






(Figure 57) Restoration and reconstruction of sculptures Cave 19 of Ajanta historic site

Before restoration (above) and after restoration (below)

The original portions cannot easily be distinguished from the restored/reconstructed portion.



(Figure 58) Restoration and reconstruction of sculptures Cave 16 of Ellora historic site

- Before restoration (left) and after restoration (right)

The original portions cannot easily be distinguished from the restored/reconstructed portions