



(Figure 1) General view of the Ajanta historic site from Viewpoint



(Figure 2) Pathway construction and repair work

Ramp that was newly constructed on the slope that runs from the entrance of the historic site to the front of the caves (right) and improved and expanded pathway that runs from the top of the hill to the front of cave 7 (left)

(Figure 3) Expanded pathway within the historic site (1)

Before expansion (left) and after expansion (right)





(Figure 4) Expanded pathway within the historic site (2)
Before expansion (left) and after expansion (right)



(Figure 5) Expanded pathway within the historic site (3)
Before expansion (left) and after expansion (right)

