Environmental and Social Monitoring Form for Construction Stage

2022Q1

Notes: Lm88 – 88km Massangulo – Lichinga in the Main road the Quarry has been deactivated

3KM - Construction of N13 Intersection to Massangulo Vila Sede we have not large scale pollution because all the material applied for this project work comes from an external quarry.

ltem	Location	Parameter/ Means of Monitoring	Result (Average / Max / Total, etc.)	Standard (Legal / International Standard)	Frequency	Remarks
	Construction site	Visual inspection of mechanical condition and exhaust gas	Equipment in good mechanical condition.		Every day before working	N/A
	Construction site	Visual observation of dust	Dust emission are minimized by regular and controled watering twice a day.		Every day	Morning 7:00am and Afternoon 17:00pm
		No. of complaint	There is no complaint.		Any time	No report of complaint during this period.
			January to March 2022 Average: 2.02 µg/m3, Max: 5 µg/m3 at Main Camp;			N/A
Air quality						
	Boundary of ROW nearest to construction site	SPM10		0.02 mg/m ³ (Japan, average 24h)	2 times in dry season and 2 times in rainy season	N/A
			On 8th of February 2022 Average: 8,5 μg/m3, Max: 12 μg/m3 at Main Camp; Average: 9,01μg/m3, Max: 14,2 μg/m3 at Massangulo main market			N/A
		SO ₂	0 ppm	0.04 mg/m ³		
		NO ₂	0 ppm	(Japan, average 24h) 0.10 mg/m ³ (Japan, average 24h)		N/A
ater Pollution	River, stream, reservoir and other public water body where construction works are executed.	VISUAI Observation	There is no record of activities with high potential for water pollution.			There is only one river in the box culvert km 1+060
	Along N-13 Boundary of land plot nearest to the construction site	No. of complaint	There is no complaint.Main Camp (February 2022)Leq(5min)MinAveMaxMinAveMax42,659,562,244.855.369.8	88dB (07:30am-05:00pm) 58dB (07:00pm - 07:00am) (Japan, Trunk Roads)	Any time Every Month	No report of complaint during this period.
			Massangulo main market (January 2022) Leq(5min) Leq(15min) Min Ave Max 62,2 55,5 78,8 65.8 69.5 79.7			
			Borrow pit 02 (March 2022) Leq(5min) Min Ave Max Min 71,02 81,1 92,1 66.8 71.1 88.2			
			Residencial areas (February to March 2022) Leq(5min) Leq(15min)			
Noise		Noise Level	Min Ave Max Min Ave Max 66.7 69.7 81.2 58.9 68.1 84.9			
			Main Camp (January 2022) Leq(5min) Leq(15min)			
			Min Ave Max Min Ave Max 49,3 55.5 68 60.1 70 76.5			
	Sensitive Area (School, Hospital)			70dB (Japan, Sensitive Area)		Due to the completion of the road, the detour is between the houses and continues to be used frequently. Reason enough to always monitor.
General waste	Waste storage at construction site, Waste Disposal Site	Store Condition	The Contractor have provided spill containment base for used oil All hazardous waste, including used oils, are storage in demarcated area and labelled to facilitate segregation. The Contractor has already sorted out all issues regarding housekeeping. The site is clean now, the waste containers are	\backslash /	Every day	Tires, filters and used oils have been stored in drums containers in the storage area of the workshop. They are reusing the remnants of metals to produce stove, roasting pans, signal board and funnel. (ongoing)
		other construction waste	empty regularly and have covers to prevent wetting. (ongoing) Recycling of metals drums			
		Way of recycle	Produce stove, roasting pans, signal board and funnel.			
		Recycling Status Way of recycle	Recycling of plastic bottles For domestic use as containers for water/juice and cooking oil. They may also be used as plant pots although in small quantity.			Empty water bottles, are collected by workers for reuse. Having observed this the Engineer arranged a bottle disinfection service.
		General Waste Way of treatment	Re-use (used by internal personal); Re-use in construction activities; Dumpsite.			Disinfection is done by use of chemicals like certeza (some drops of chloride in disinfection water). This is meant to hinder possible pathogenes from person to person.
		Location of final disposal site				General waste is separated into bio-degradable and non bio- degradable. Bio-degradable waste is disposed of in the landfill within
Ecosystem	Along N-13	Visual observation of animals (mammals, birds, reptiles, amphibians)	The presence of some Crow and Owl are observed.			the contractor's camp. Duringg the day some crows are on site and owl during the night
	Along N-13				Every Month	
Accident			Nothing to report for the review period.			
		Checking Traffic Accident Report				
						Nothing to report for the review period.
				/ \		
		A: No. of land acquired/ B: to be aquired		Progress Ratio: A/(A+B) = 1/(1+1)= 2		02 parcel of land were acquired to date, for use as borrow pits. During the reporting period, the contractor was using only one borrow pit.
				-		_

Land Acquisitio	n Along N-13	A: No. of HHs received compensation/ B: HHs to be compensated		Progress Ratio: A/(A+B) = 228/(228+1) = 0,995633	Implementation of RAP had been finalized on July 24, 2021. The total number of RAP implementation done at completion of this activity is 13 cases.
		Complaint received	Complaints only occur during explanations and signatures of compensation agreements. The construction began after the implementation of the RAP. We have no record of complaints after commencement of constraction.	In general, all affected people	All affected people have received their compensation.

1