

## Table of Contents

|     |   |     |
|-----|---|-----|
| 1.  | TREE INVENTORY DETAILS AT UGC-01 .....    | 4   |
| 2.  | TREE INVENTORY DETAILS FOR UGC-02 .....   | 42  |
| 3.  | TREE INVENTORY DETAILS FOR UGC-03 .....   | 70  |
| 4.  | TREE INVENTORY DETAILS FOR UGC-04 .....   | 133 |
| 5.  | TREE INVENTORY DETAILS FOR UGC-05 .....   | 159 |
| 6.  | TREE INVENTORY DETAILS FOR UGC-06 .....   | 182 |
| 7.  | TREE INVENTORY DETAILS FOR UGC 07 .....   | 198 |
| 8.  | AAREY PYLON SHIFTING TREE INVENTORY ..... | 242 |
| 10. | AAREY CAR SHED DEPOT TREE INVENTORY ..... | 249 |

## Tree Summary of permitted Trees

| <b>Summary of permitted trees at all stations, allied activities viz. Entry Exits, Launching shaft, Ramp, Traffic diversion, Casting Yard, Pylon etc. and Aarey Car Shed Depot at Aarey Colony Area.</b> |                                      |                |                   |                                    |                                  |                       |  |
|--|--------------------------------------|----------------|-------------------|------------------------------------|----------------------------------|-----------------------|--|
| <b>Sr. No.</b>   | <b>Station Name</b>                  | <b>Package</b> | <b>MCGM Ward</b>  | <b>To be Transplant Permission</b> | <b>Tree To be Cut Permission</b> | <b>To be Retained</b> | <b>Total Trees Cut+Transplant+Retained</b> |
| 1  | Cuffe Parade                         | UGC0 1         | A (Zone I)        | 120                                | 187                              | 19                    | 326  |
| 2  | Vidhan Bhavan                        |                | A (Zone I)        | 94                                 | 116                              | 96                    | 306  |
| 3  | Churchgate                           |                | A (Zone I)        | 47                                 | 51                               | 70                    | 168  |
| 4  | Hutatma Chowk                        |                | A (Zone I)        | 76                                 | 45                               | 11                    | 132  |
| 5  | Tunnel Operation Shaft at Churchgate |                | A (Zone I)        | 3                                  | 5                                | 0                     | 8  |
| 6  | CST                                  | UGC0 2         | A (Zone I)        | 99                                 | 93                               | 95                    | 287  |
| 7  | Kalbadevi                            |                | C (Zone I)        | 0                                  | 2                                | 32                    | 34   |
| 8  | Girgoan                              |                | C & D (Zone I)    | 9                                  | 11                               | 27                    | 47   |
| 9  | Grant Road                           |                | D (Zone I)        | 23                                 | 28                               | 56                    | 107  |
| 10   | Construction Depot (WTC plot)        |                | D (Zone I)        | 4                                  | 2                                | 82                    | 88   |
| 11   | Mumbai Central                       | UGC0 3         | E (Zone I)        | 106                                | 69                               | 2                     | 177  |
| 12   | Mahalakshmi                          |                | E (Zone I)        | 122                                | 33                               | 29                    | 184  |
| 13   | Science Museum                       |                | G South (Zone II) | 109                                | 109                              | 71                    | 289  |
| 14   | Acharya Atre                         |                | G South (Zone II) | 31                                 | 76                               | 26                    | 133  |
| 15   | Worli                                |                | G South (Zone II) | 138                                | 81                               | 6                     | 225  |
| 16   | Siddhivinayak                        | UGC0 4         | G South (Zone II) | 32                                 | 98                               | 84                    | 214  |
| 17   | Dadar                                |                | G North (Zone II) | 26                                 | 37                               | 111                   | 174  |
| 18   | Shitladevi                           |                | G North (Zone II) | 29                                 | 33                               | 14                    | 76   |
| 19   | Naya Nagar Launching Shaft           |                | G North (Zone II) | 14                                 | 1                                | 13                    | 28   |
| 20   | BKC site office                      |                | H East (Zone III) | 3                                  | 0                                | 7                     | 10   |
| 21   | Dharavi                              | UGC0 5         | G North (Zone II) | 43                                 | 5                                | 35                    | 83   |

|    |                                   |           |                               |                    |                    |                    |                    |
|----|-----------------------------------|-----------|-------------------------------|--------------------|--------------------|--------------------|--------------------|
| 22 | BKC                               |           | H East<br>(Zone III)          | 40                 | 67                 | 61                 | 168                |
| 23 | Vidyanagari                       |           | H East<br>(Zone III)          | 69                 | 47                 | 6                  | 122                |
| 24 | BKC steel Yard                    |           | H East<br>(Zone III)          | 4                  | 12                 | 116                | 132                |
| 25 | Santacruz                         |           | H East<br>(Zone III)          | 25                 | 10                 | 4                  | 39                 |
| 26 | Domestic Airport                  | UGC0<br>6 | K East<br>(Zone III)          | 112                | 3                  | 14                 | 129                |
| 27 | Sahar Road                        |           | K East<br>(Zone III)          | 226                | 4                  | 19                 | 249                |
| 28 | International<br>Airport          |           | K East<br>(Zone III)          | 4                  | 0                  | 4                  | 8                  |
| 29 | Marol Naka                        | UGC0<br>7 | K East<br>(Zone III)          | 52                 | 12                 | 19                 | 83                 |
| 30 | MIDC                              |           | K East<br>(Zone III)          | 132                | 14                 | 105                | 251                |
| 31 | Seepz                             |           | K East<br>(Zone III)          | 116                | 22                 | 100                | 238                |
| 32 | Ramp at Sariput<br>Nagar          |           | K East<br>(Zone III)          | 92                 | 238                | 47                 | 377                |
| 33 | Launching Shaft at<br>Pali ground |           | K East<br>(Zone III)          | 18                 | 1                  | 58                 | 77                 |
| 34 | Casting Yard at<br>JVLR           |           | K East<br>(Zone III)          | 48                 | 1                  | 48                 | 97                 |
| 35 | Pylon at Aarey<br>Colony          |           | K East<br>(Zone III)          | 32                 | 105                | 0                  | 137                |
| -  | -                                 | -         | <b><u>Total<br/>trees</u></b> | <b><u>2098</u></b> | <b><u>1618</u></b> | <b><u>1487</u></b> | <b><u>5203</u></b> |
| 36 | Car Shed Depot at<br>Aarey Colony | DPT       | K East<br>(Zone III)          | 461                | 2185               | 1045               | 3691               |
| -  | -                                 | -         | <b><u>Total<br/>trees</u></b> | <b><u>461</u></b>  | <b><u>2185</u></b> | <b><u>1045</u></b> | <b><u>3691</u></b> |
| -  | -                                 | -         | <b><u>Grand<br/>Total</u></b> | <b><u>2559</u></b> | <b><u>3803</u></b> | <b><u>2532</u></b> | <b><u>8894</u></b> |

- For station and allied activities total number of tree removal is 3716 (2098-Transplant + 1618-Cut).
- For station and allied activities trees to be retained is 1487.
- Total number of trees for station and allied activities is 5203.
- For Car Shed Depot at Aarey Colony, total number of trees to be removed is 2646 (461-Transplant + 2185-Cut).
- For Car Shed Depot at Aarey Colony, total number of trees to be retained is 1045.
- Total number of trees for Car Shed Depot at Aarey Colony is 3691.

**1. TREE INVENTORY DETAILS AT UGC-01**

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

| Summary of Tree Survey at Cuffe Parade Station |          |               |                                |                     |                      |                     |                                |
|--|----------|---------------|--------------------------------|---------------------|----------------------|---------------------|--------------------------------|
| Sr. no.  | Tree no. | Common Name   | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                         |
| 1  | 1        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 1                   | 20                   | To be removed       | Falling within excavation line |
| 2  | 2        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 10"                 | 10                   | To be removed       | Falling within excavation line |
| 3  | 3        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4'7"                | 35                   | To be removed       | Falling within excavation line |
| 4  | 4        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4'3"                | 35                   | To be removed       | Falling within excavation line |
| 5  | 5        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4'6"                | 35                   | To be removed       | Falling within excavation line |
| 6  | 6        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 5                   | 30                   | To be removed       | Falling within excavation line |
| 7  | 7        | Savar         | <i>Ceiba pentandra</i>         | 3                   | 25                   | To be removed       | Falling within excavation line |
| 8  | 8        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 8"                  | 10                   | To be removed       | Falling within excavation line |
| 9  | 9        | Fishtail Palm | <i>Caryota urens</i>           | 3                   | 25                   | To be removed       | Falling within excavation line |
| 10   | 10       | Fishtail Palm | <i>Caryota urens</i>           | 3                   | 25                   | To be removed       | Falling within excavation line |
| 11   | 11       | Fishtail Palm | <i>Caryota urens</i>           | 3                   | 25                   | To be removed       | Falling within excavation line |
| 12   | 12       | Sonmohar      | <i>Peltophorum pterocarpum</i> | 1                   | 20                   | To be removed       | Falling within excavation line |
| 13   | 13       | Umbrella tree | <i>Brassia actinophylla</i>    | 8"                  | 15                   | To be removed       | Falling within excavation line |
| 14   | 14       | Sonmohar      | <i>Peltophorum pterocarpum</i> | 9"                  | 15                   | To be removed       | Falling within excavation line |
| 15   | 15       | Areca palm    | <i>Areca catechu</i>           | 9"                  | 15                   | To be removed       | Falling within excavation line |
| 16   | 16       | Satwin        | <i>Alstonia scholaris</i>      | 5                   | 45                   | To be removed       | Falling within excavation line |
| 17   | 17       | Asupalav      | <i>Polyalthia longifolia</i>   | 1.5                 | 25                   | To be removed       | Falling within excavation line |
| 18   | 18       | Gulmohar      | <i>Delonix regia</i>           | 3                   | 30                   | To be removed       | Falling within excavation line |
| 19   | 19       | Naral         | <i>Cocos nucifera</i>          | 3.5                 | 25                   | To be removed       | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |               |                                |     |    |               |                                |
|----|----|---------------|--------------------------------|-----|----|---------------|--------------------------------|
| 20 | 20 | Jambhul       | <i>Syzygium cumin</i>          | 1   | 16 | To be removed | Falling within excavation line |
| 21 | 21 | Asupalav      | <i>Polyalthia longifolia</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 22 | 22 | Naral         | <i>Cocos nucifera</i>          | 2   | 10 | To be removed | Falling within excavation line |
| 23 | 23 | Deshi Badam   | <i>Terminaliacatappa</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 24 | 24 | Wad           | <i>Ficus benghalensis</i>      | 1   | 15 | To be removed | Falling within excavation line |
| 25 | 25 | Deshi Badam   | <i>Terminaliacatappa</i>       | 2   | 20 | To be removed | Falling within excavation line |
| 26 | 26 | Jannun        | <i>Syzygium cumin</i>          | 4"  | 10 | To be removed | Falling within excavation line |
| 27 | 27 | Jamun         | <i>Syzygium cumin</i>          | 5   | 30 | To be removed | Falling within excavation line |
| 28 | 28 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 6   | 30 | To be removed | Falling within excavation line |
| 29 | 29 | Areca palm    | <i>Dypsis lutescens</i>        | 9"  | 15 | To be removed | Falling within excavation line |
| 30 | 30 | Naral         | <i>Cocos nucifera</i>          | 4   | 25 | To be removed | Falling within excavation line |
| 31 | 31 | Naral         | <i>Cocos nucifera</i>          | 2   | 10 | To be removed | Falling within excavation line |
| 32 | 32 | Umbrella tree | <i>Brassia actinophylla</i>    | 6   | 25 | To be removed | Falling within excavation line |
| 33 | 33 | Pimpali       | <i>Ficus infectoria</i>        | 9"  | 15 | To be removed | Falling within excavation line |
| 34 | 34 | Naral         | <i>Cocos nucifera</i>          | 4   | 25 | To be removed | Falling within excavation line |
| 35 | 35 | Mango         | <i>Mangifera Indica</i>        | 1   | 10 | To be removed | Falling within excavation line |
| 36 | 36 | Asupalav      | <i>Polyalthia longifolia</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 37 | 37 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 6   | 30 | To be removed | Falling within excavation line |
| 38 | 38 | Asupalav      | <i>Polyalthia longifolia</i>   | 10" | 10 | To be removed | Falling within excavation line |
| 39 | 39 | Asupalav      | <i>Polyalthia longifolia</i>   | 10" | 15 | To be removed | Falling within excavation line |
| 40 | 40 | Asupalav      | <i>Polyalthia longifolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 41 | 41 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 42 | 42 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed | Falling within excavation line |
| 43 | 43 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4   | 30 | To be removed | Falling within excavation line |
| 44 | 44 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 6   | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |                    |                                |     |    |               |                                |
|----|----|--------------------|--------------------------------|-----|----|---------------|--------------------------------|
| 45 | 45 | Sonmohar           | <i>Peltophorum pterocarpum</i> | 6   | 35 | To be removed | Falling within excavation line |
| 46 | 46 | Sonmohar           | <i>Peltophorum pterocarpum</i> | 3   | 25 | To be removed | Falling within excavation line |
| 47 | 47 | Sonmohar           | <i>Peltophorum pterocarpum</i> | 6   | 30 | To be removed | Falling within excavation line |
| 48 | 48 | Sonmohar           | <i>Peltophorum pterocarpum</i> | 4   | 30 | To be removed | Falling within excavation line |
| 49 | 49 | Sonmohar           | <i>Peltophorum pterocarpum</i> | 3   | 25 | To be removed | Falling within excavation line |
| 50 | 50 | Sonmohar           | <i>Peltophorum pterocarpum</i> | 9   | 10 | To be removed | Falling within excavation line |
| 51 | 51 | Pimpal             | <i>Ficus religiosa</i>         | 8   | 25 | To be removed | Falling within excavation line |
| 52 | 52 | Sonmohar           | <i>Peltophorum pterocarpum</i> | 5   | 25 | To be removed | Falling within excavation line |
| 53 | 53 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 8   | 30 | To be removed | Falling within excavation line |
| 54 | 54 | African tulip tree | <i>Spathodea Campanulata</i>   | 1   | 20 | To be removed | Falling within excavation line |
| 55 | 55 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 1   | 20 | To be removed | Falling within excavation line |
| 56 | 56 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 9"  | 15 | To be removed | Falling within excavation line |
| 57 | 57 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 1   | 20 | To be removed | Falling within excavation line |
| 58 | 58 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 9"  | 10 | To be removed | Falling within excavation line |
| 59 | 59 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 6"  | 10 | To be removed | Falling within excavation line |
| 60 | 60 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 8"  | 10 | To be removed | Falling within excavation line |
| 61 | 61 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 10" | 10 | To be removed | Falling within excavation line |
| 62 | 62 | Pimpal             | <i>Ficus religiosa</i>         | 4   | 25 | To be removed | Falling within excavation line |
| 63 | 63 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 9"  | 10 | To be removed | Falling within excavation line |
| 64 | 64 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 65 | 65 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 66 | 66 | Sonmohar           | <i>Peltophorum pterocarpum</i> | 6   | 30 | To be removed | Falling within excavation line |
| 67 | 67 | Vilayati Chinch    | <i>Pithecellobium dulce</i>    | 9"  | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |                 |                                |     |    |               |                                |
|----|----|-----------------|--------------------------------|-----|----|---------------|--------------------------------|
| 68 | 68 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed | Falling within excavation line |
| 69 | 69 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 2   | 11 | To be removed | Falling within excavation line |
| 70 | 70 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 2   | 11 | To be removed | Falling within excavation line |
| 71 | 71 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 8   | 35 | To be removed | Falling within excavation line |
| 72 | 72 | Gulmohar        | <i>Delonix regia</i>           | 4   | 30 | To be removed | Falling within excavation line |
| 73 | 73 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 9"  | 10 | To be removed | Falling within excavation line |
| 74 | 74 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 4   | 25 | To be removed | Falling within excavation line |
| 75 | 75 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 8"  | 15 | To be removed | Falling within excavation line |
| 76 | 76 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 77 | 77 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1   | 20 | To be removed | Falling within excavation line |
| 78 | 78 | Gulmohar        | <i>Delonix regia</i>           | 4   | 30 | To be removed | Falling within excavation line |
| 79 | 79 | Pimpal          | <i>Ficus religiosa</i>         | 9"  | 20 | To be removed | Falling within excavation line |
| 80 | 80 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 9"  | 20 | To be removed | Falling within excavation line |
| 81 | 81 | Sitaphal        | <i>Annona squamosa</i>         | 4"  | 5  | To be removed | Falling within excavation line |
| 82 | 82 | Asupalav        | <i>Polyalthia longifolia</i>   | 4   | 30 | To be removed | Falling within excavation line |
| 83 | 83 | Asupalav        | <i>Polyalthia longifolia</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 84 | 84 | Asupalav        | <i>Polyalthia longifolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 85 | 85 | Asupalav        | <i>Polyalthia longifolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 86 | 86 | Asupalav        | <i>Polyalthia longifolia</i>   | 3   | 25 | To be removed | Falling within excavation line |
| 87 | 87 | Asupalav        | <i>Polyalthia longifolia</i>   | 3   | 30 | To be removed | Falling within excavation line |
| 88 | 88 | Asupalav        | <i>Polyalthia longifolia</i>   | 4   | 25 | To be removed | Falling within excavation line |
| 89 | 89 | Bhend           | <i>Thespesia populnea</i>      | 3   | 25 | To be removed | Falling within excavation line |
| 90 | 90 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 7   | 30 | To be removed | Falling within excavation line |
| 91 | 91 | Asupalav        | <i>Polyalthia longifolia</i>   | 1   | 30 | To be removed | Falling within excavation line |
| 92 | 92 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 3   | 20 | To be removed | Falling within excavation line |
| 93 | 93 | Saptaparni      | <i>Alstonia scholaris</i>      | 4   | 30 | To be removed | Falling within excavation line |
| 94 | 94 | Asupalav        | <i>Polyalthia longifolia</i>   | 5   | 30 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                                |     |    |               |                                |
|-----|-----|-------------------|--------------------------------|-----|----|---------------|--------------------------------|
| 95  | 95  | Asupalav          | <i>Polyalthia longifolia</i>   | 4   | 30 | To be removed | Falling within excavation line |
| 96  | 96  | Pimpal            | <i>Ficus religiosa</i>         | 5   | 30 | To be removed | Falling within excavation line |
| 97  | 97  | Saptaparni        | <i>Alstonia scholaris</i>      | 8   | 30 | To be removed | Falling within excavation line |
| 98  | 98  | Saptaparni        | <i>Alstonia scholaris</i>      | 5   | 30 | To be removed | Falling within excavation line |
| 99  | 99  | Saptaparni        | <i>Alstonia scholaris</i>      | 3   | 25 | To be removed | Falling within excavation line |
| 100 | 100 | Saptaparni        | <i>Alstonia scholaris</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 101 | 101 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 2   | 20 | To be removed | Falling within excavation line |
| 102 | 102 | Naral             | <i>Cocos nucifera</i>          | 3   | 10 | To be removed | Falling within excavation line |
| 103 | 103 | Naral             | <i>Cocos nucifera</i>          | 3   | 15 | To be removed | Falling within excavation line |
| 104 | 104 | Naral             | <i>Cocos nucifera</i>          | 3   | 15 | To be removed | Falling within excavation line |
| 105 | 105 | Naral             | <i>Cocos nucifera</i>          | 4   | 20 | To be removed | Falling within excavation line |
| 106 | 106 | Naral             | <i>Cocos nucifera</i>          | 3   | 10 | To be removed | Falling within excavation line |
| 107 | 107 | Australian Babhul | <i>Acacia auriculiformis</i>   | 3   | 30 | To be removed | Falling within excavation line |
| 108 | 108 | Naral             | <i>Cocos nucifera</i>          | 1.5 | 10 | To be removed | Falling within excavation line |
| 109 | 109 | Naral             | <i>Cocos nucifera</i>          | 2   | 10 | To be removed | Falling within excavation line |
| 110 | 110 | Naral             | <i>Cocos nucifera</i>          | 2   | 10 | To be removed | Falling within excavation line |
| 111 | 111 | Mosambi           | <i>Citrus limetta</i>          | 1   | 10 | To be removed | Falling within excavation line |
| 112 | 112 | Dalimb            | <i>Punica granatum</i>         | 1   | 10 | To be removed | Falling within excavation line |
| 113 | 113 | Deshi Badam       | <i>Terminalia catappa</i>      | 1   | 15 | To be removed | Falling within excavation line |
| 114 | 114 | Asupalav          | <i>Polyalthia longifolia</i>   | 1   | 15 | To be removed | Falling within excavation line |
| 115 | 115 | Tabebuia          | <i>Tabebuia pentaphylla</i>    | 4   | 20 | To be removed | Falling within excavation line |
| 116 | 116 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3   | 30 | To be removed | Falling within excavation line |
| 117 | 117 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3   | 30 | To be removed | Falling within excavation line |
| 118 | 118 | Pimpal            | <i>Ficus religiosa</i>         | 2   | 20 | To be removed | Falling within excavation line |
| 119 | 119 | Vilayati Chinch   | <i>Pithecellobium dulce</i>    | 4   | 15 | To be removed | Falling within excavation line |
| 120 | 120 | Vilayati Chinch   | <i>Pithecellobium dulce</i>    | 5   | 25 | To be removed | Falling within excavation line |
| 121 | 121 | Vilayati Chinch   | <i>Pithecellobium dulce</i>    | 4   | 15 | To be removed | Falling within excavation line |
| 122 | 122 | Vilayati Chinch   | <i>Pithecellobium dulce</i>    | 4   | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                 |                                |       |    |               |                                |
|-----|-----|-----------------|--------------------------------|-------|----|---------------|--------------------------------|
| 123 | 123 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 4'6"  | 35 | To be removed | Falling within excavation line |
| 124 | 124 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 4'6"  | 35 | To be removed | Falling within excavation line |
| 125 | 125 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 4'10" | 35 | To be removed | Falling within excavation line |
| 126 | 126 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 4'3"  | 35 | To be removed | Falling within excavation line |
| 127 | 127 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 3'3"  | 35 | To be removed | Falling within excavation line |
| 128 | 128 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 3'    | 35 | To be removed | Falling within excavation line |
| 129 | 129 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 4'    | 35 | To be removed | Falling within excavation line |
| 130 | 130 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 3'    | 30 | To be removed | Falling within excavation line |
| 131 | 131 | Gulmohar        | <i>Delonix regia</i>           | 5     | 35 | To be removed | Falling within excavation line |
| 132 | 132 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 3     | 21 | To be removed | Falling within excavation line |
| 133 | 133 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1     | 11 | To be removed | Falling within excavation line |
| 134 | 134 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1     | 11 | To be removed | Falling within excavation line |
| 135 | 135 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1     | 11 | To be removed | Falling within excavation line |
| 136 | 136 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1     | 15 | To be removed | Falling within excavation line |
| 137 | 137 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1     | 8  | To be removed | Falling within excavation line |
| 138 | 138 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1     | 20 | To be removed | Falling within excavation line |
| 139 | 139 | Karanj          | <i>Pongamia pinnata</i>        | 2     | 17 | To be removed | Falling within excavation line |
| 140 | 140 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 4     | 35 | To be removed | Falling within excavation line |
| 141 | 141 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1     | 20 | To be removed | Falling within excavation line |
| 142 | 142 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1     | 19 | To be removed | Falling within excavation line |
| 143 | 143 | Asupalav        | <i>Polyalthia longifolia</i>   | 3     | 12 | To be removed | Falling within excavation line |
| 144 | 144 | Asupalav        | <i>Polyalthia longifolia</i>   | 1     | 7  | To be removed | Falling within excavation line |
| 145 | 145 | Jamun           | <i>Syzygium cumin</i>          | 7     | 40 | To be removed | Falling within excavation line |
| 146 | 146 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1     | 22 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                 |                                |     |    |               |                                |
|-----|-----|-----------------|--------------------------------|-----|----|---------------|--------------------------------|
| 147 | 147 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1   | 22 | To be removed | Falling within excavation line |
| 148 | 148 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1   | 22 | To be removed | Falling within excavation line |
| 149 | 149 | Mango           | <i>Mangifera Indica</i>        | 1   | 6  | To be removed | Falling within excavation line |
| 150 | 150 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 3   | 25 | To be removed | Falling within excavation line |
| 151 | 151 | Sonchapha       | <i>Michelia champaca</i>       | 6"  | 10 | To be removed | Falling within excavation line |
| 152 | 152 | Supari          | <i>Areca catechu</i>           | 6"  | 10 | To be removed | Falling within excavation line |
| 153 | 153 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1'  | 19 | To be removed | Falling within excavation line |
| 154 | 154 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 2   | 26 | To be removed | Falling within excavation line |
| 155 | 155 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1   | 19 | To be removed | Falling within excavation line |
| 156 | 156 | Areca palm      | <i>Areca catechu</i>           | 6"  | 10 | To be removed | Falling within excavation line |
| 157 | 157 | Sonmohar        | <i>Peltophorum pterocarpum</i> | 6   | 30 | To be removed | Falling within excavation line |
| 158 | 158 | Tabebuia        | <i>Tabebuia pentaphylla</i>    | 5   | 30 | To be removed | Falling within excavation line |
| 159 | 159 | Sonchapha       | <i>Michelia champaca</i>       | 2   | 20 | To be removed | Falling within excavation line |
| 160 | 160 | Fan Palm        | <i>Livistonia chinensis</i>    | 2   | 30 | To be removed | Falling within excavation line |
| 161 | 161 | Vilayati Chinch | <i>Pithecellobium Dulce</i>    | 5"  | 12 | To be removed | Falling within excavation line |
| 162 | 162 | Vilayati Chinch | <i>Pithecellobium Dulce</i>    | 8"  | 12 | To be removed | Falling within excavation line |
| 163 | 163 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 8"  | 15 | To be removed | Falling within excavation line |
| 164 | 164 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 8"  | 15 | To be removed | Falling within excavation line |
| 165 | 165 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 166 | 166 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 8"  | 4  | To be removed | Falling within excavation line |
| 167 | 167 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 9"  | 20 | To be removed | Falling within excavation line |
| 168 | 168 | Sonchapha       | <i>Michelia champaca</i>       | 1.5 | 28 | To be removed | Falling within excavation line |
| 169 | 169 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 2   | 25 | To be removed | Falling within excavation line |
| 170 | 170 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 9"  | 15 | To be removed | Falling within excavation line |
| 171 | 171 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 172 | 172 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1'  | 25 | To be removed | Falling within excavation line |
| 173 | 173 | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 4"  | 10 | To be removed | Falling within excavation line |
| 174 | 174 | Pichkari        | <i>Spathodea campanulata</i>   | 1'  | 22 | To be removed | Falling within excavation line |
| 175 | 175 | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 1'  | 18 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                 |                             |     |    |                |                                 |
|-----|-----|-----------------|-----------------------------|-----|----|----------------|---------------------------------|
| 176 | 176 | Vilayati Chinch | <i>Pithecellobium dulce</i> | 6"  | 10 | To be removed  | Falling within excavation line  |
| 177 | 177 | Vilayati Chinch | <i>Pithecellobium dulce</i> | 8"  | 10 | To be removed  | Falling within excavation line  |
| 178 | 178 | Shewaga         | <i>Moringa Oleifera</i>     | 1   | 15 | To be removed  | Falling within excavation line  |
| 179 | 179 | Tecoma          | <i>Tecoma gaudichaudi</i>   | 1   | 15 | To be removed  | Falling within excavation line  |
| 180 | 180 | Tecoma          | <i>Tecoma gaudichaudi</i>   | 1   | 15 | To be removed  | Falling within excavation line  |
| 181 | 181 | Mango           | <i>Mangifera Indica</i>     | 3   | 25 | To be removed  | Falling within excavation line  |
| 182 | 182 | Royal Palm      | <i>Roystonea regia</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 183 | 183 | Royal Palm      | <i>Roystonea regia</i>      | 1.5 | 12 | To be removed  | Falling within excavation line  |
| 184 | 184 | Jamun           | <i>Syzygium cumin</i>       | 4   | 30 | To be removed  | Falling within excavation line  |
| 185 | 185 | Sonchapha       | <i>Michelia champaca</i>    | 6"  | 15 | To be removed  | Falling within excavation line  |
| 186 | 186 | Shewaga         | <i>Moringa oliefera</i>     | 2   | 20 | To be removed  | Falling within excavation line  |
| 187 | 187 | Coconut         | <i>Cocos nucifera</i>       | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 188 | 188 | Coconut         | <i>Cocos nucifera</i>       | 3.5 | 15 | To be removed  | Falling within excavation line  |
| 189 | 189 | Coconut         | <i>Cocos nucifera</i>       | 3.5 | 20 | To be removed  | Falling within excavation line  |
| 190 | 190 | Coconut         | <i>Cocos nucifera</i>       | 3.5 | 20 | To be removed  | Falling within excavation line  |
| 191 | 191 | Coconut         | <i>Cocos nucifera</i>       | 4   | 25 | To be removed  | Falling within excavation line  |
| 192 | 192 | Coconut         | <i>Cocos nucifera</i>       | 5   | 25 | To be removed  | Falling within excavation line  |
| 193 | 193 | Coconut         | <i>Cocos nucifera</i>       | 3.5 | 25 | To be removed  | Falling within excavation line  |
| 194 | 194 | Coconut         | <i>Cocos nucifera</i>       | 3   | 20 | To be removed  | Falling within excavation line  |
| 195 | 195 | Coconut         | <i>Cocos nucifera</i>       | 4   | 25 | To be removed  | Falling within excavation line  |
| 196 | 196 | Coconut         | <i>Cocos nucifera</i>       | 4   | 25 | To be removed  | Falling within excavation line  |
| 197 | 197 | Coconut         | <i>Cocos nucifera</i>       | 3.5 | 25 | To be removed  | Falling within excavation line  |
| 198 | 198 | Coconut         | <i>Cocos nucifera</i>       | 4   | 25 | To be removed  | Falling within excavation line  |
| 199 | 199 | Coconut         | <i>Cocos nucifera</i>       | 3   | 15 | To be removed  | Falling within excavation line  |
| 200 | 200 | Mango           | <i>Mangifera Indica</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 201 | 201 | Coconut         | <i>Cocos nucifera</i>       | 4   | 10 | To be removed  | Falling within excavation line  |
| 202 | 202 | Coconut         | <i>Cocos nucifera</i>       | 4   | 20 | To be removed  | Falling within excavation line  |
| 203 | 203 | Jambhul         | <i>Syzygium cumini</i>      | 2   | 22 | To be retained | Falling outside excavation line |
| 204 | 204 | Shewga          | <i>Moringa oliefera</i>     | 2   | 29 | To be retained | Falling outside excavation line |
| 205 | 205 | Amba            | <i>Mangifera indica</i>     | 2   | 19 | To be retained | Falling outside excavation line |
| 206 | 206 | Shewga          | <i>Moringa oliefera</i>     | 3   | 29 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                                |     |    |                |                                 |
|-----|-----|------------|--------------------------------|-----|----|----------------|---------------------------------|
| 207 | 207 | Naral      | <i>Cocos nucifera</i>          | 3   | 13 | To be retained | Falling outside excavation line |
| 208 | 208 | Amba       | <i>Mangifera indica</i>        | 1   | 16 | To be retained | Falling outside excavation line |
| 209 | 209 | Amba       | <i>Mangifera indica</i>        | 2   | 22 | To be retained | Falling outside excavation line |
| 210 | 210 | Ramphal    | <i>Annona reticulata</i>       | 3   | 32 | To be retained | Falling outside excavation line |
| 211 | 211 | Pimpal     | <i>Ficus religiosa</i>         | 16  | 40 | To be removed  | Falling within excavation line  |
| 212 | 212 | Coconut    | <i>Cocos nucifera</i>          | 4   | 30 | To be removed  | Falling within excavation line  |
| 213 | 213 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 7   | 35 | To be removed  | Falling within excavation line  |
| 214 | 214 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 6   | 35 | To be removed  | Falling within excavation line  |
| 215 | 215 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 6   | 35 | To be removed  | Falling within excavation line  |
| 216 | 216 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4   | 35 | To be removed  | Falling within excavation line  |
| 217 | 217 | Fan Palm   | <i>Livistonia chinensis</i>    | 2   | 22 | To be removed  | Falling within excavation line  |
| 218 | 218 | Fan Palm   | <i>Livistonia chinensis</i>    | 2   | 22 | To be removed  | Falling within excavation line  |
| 219 | 219 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4   | 30 | To be removed  | Falling within excavation line  |
| 220 | 220 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4   | 30 | To be removed  | Falling within excavation line  |
| 221 | 221 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 3.5 | 25 | To be removed  | Falling within excavation line  |
| 222 | 222 | Lychee     | <i>Litchi chinensis</i>        | 2.5 | 28 | To be removed  | Falling within excavation line  |
| 223 | 223 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 3.5 | 30 | To be removed  | Falling within excavation line  |
| 224 | 224 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 3   | 26 | To be removed  | Falling within excavation line  |
| 225 | 225 | Putranjiva | <i>Putranjiva roxburghii</i>   | 2   | 20 | To be removed  | Falling within excavation line  |
| 226 | 226 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed  | Falling within excavation line  |
| 227 | 227 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4   | 35 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                                |   |    |               |                                |
|-----|-----|-------------------|--------------------------------|---|----|---------------|--------------------------------|
| 228 | 228 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3 | 25 | To be removed | Falling within excavation line |
| 229 | 229 | Royal palm        | <i>Roystonea regia</i>         | 4 | 26 | To be removed | Falling within excavation line |
| 230 | 230 | Savar             | <i>Ceiba pentandra</i>         | 3 | 10 | To be removed | Falling within excavation line |
| 231 | 231 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 2 | 20 | To be removed | Falling within excavation line |
| 232 | 232 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 8 | 30 | To be removed | Falling within excavation line |
| 233 | 233 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 4 | 30 | To be removed | Falling within excavation line |
| 234 | 234 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 5 | 30 | To be removed | Falling within excavation line |
| 235 | 235 | Gulmohar          | <i>Delonix regia</i>           | 1 | 12 | To be removed | Falling within excavation line |
| 236 | 236 | Naral             | <i>Cocos nucifera</i>          | 1 | 14 | To be removed | Falling within excavation line |
| 237 | 237 | Naral             | <i>Cocos nucifera</i>          | 1 | 13 | To be removed | Falling within excavation line |
| 238 | 238 | Australian babhul | <i>Acacia auriculiformis</i>   | 1 | 10 | To be removed | Falling within excavation line |
| 239 | 239 | Jungli Badam      | <i>Sterculia foetida</i>       | 5 | 30 | To be removed | Falling within excavation line |
| 240 | 240 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3 | 20 | To be removed | Falling within excavation line |
| 241 | 241 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 6 | 35 | To be removed | Falling within excavation line |
| 242 | 242 | Fishtail Palm     | <i>Caryota urens</i>           | 4 | 20 | To be removed | Falling within excavation line |
| 243 | 243 | Fishtail Palm     | <i>Caryota urens</i>           | 4 | 20 | To be removed | Falling within excavation line |
| 244 | 244 | Royal palm        | <i>Roystonea regia</i>         | 3 | 26 | To be removed | Falling within excavation line |
| 245 | 245 | Son chapha        | <i>Michelia champaca</i>       | 1 | 6  | To be removed | Falling within excavation line |
| 246 | 246 | Undi              | <i>Calophyllum inophyllum</i>  | 2 | 10 | To be removed | Falling within excavation line |
| 247 | 247 | Undi              | <i>Calophyllum inophyllum</i>  | 2 | 10 | To be removed | Falling within excavation line |
| 248 | 248 | Ficus species     | <i>Ficus longifolia</i>        | 1 | 6  | To be removed | Falling within excavation line |
| 249 | 249 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 5 | 30 | To be removed | Falling within excavation line |
| 250 | 250 | Sonmohar          | <i>Peltophorum pterocarpum</i> | 5 | 30 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |              |                                |   |    |               |                                |
|-----|-----|--------------|--------------------------------|---|----|---------------|--------------------------------|
| 251 | 251 | Jungli Badam | <i>Sterculia foetida</i>       | 5 | 30 | To be removed | Falling within excavation line |
| 252 | 252 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 253 | 253 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5 | 30 | To be removed | Falling within excavation line |
| 254 | 254 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 255 | 255 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 256 | 256 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 257 | 257 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 258 | 258 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 259 | 259 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 260 | 260 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 261 | 261 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5 | 30 | To be removed | Falling within excavation line |
| 262 | 262 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 263 | 263 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5 | 30 | To be removed | Falling within excavation line |
| 264 | 264 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5 | 30 | To be removed | Falling within excavation line |
| 265 | 265 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4 | 30 | To be removed | Falling within excavation line |
| 266 | 266 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |
| 267 | 267 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6 | 30 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                                |      |    |                |                                 |
|-----|-----|------------|--------------------------------|------|----|----------------|---------------------------------|
| 268 | 268 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 6    | 30 | To be removed  | Falling within excavation line  |
| 269 | 269 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 6    | 35 | To be removed  | Falling within excavation line  |
| 270 | 270 | Amba       | <i>Mangifera indica</i>        | 1    | 12 | To be removed  | Falling within excavation line  |
| 271 | 271 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5    | 30 | To be removed  | Falling within excavation line  |
| 272 | 272 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5    | 35 | To be removed  | Falling within excavation line  |
| 273 | 273 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5    | 35 | To be removed  | Falling within excavation line  |
| 274 | 274 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 6    | 40 | To be removed  | Falling within excavation line  |
| 275 | 275 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 6    | 40 | To be removed  | Falling within excavation line  |
| 276 | 276 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4    | 40 | To be removed  | Falling within excavation line  |
| 277 | 277 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 1    | 13 | To be retained | Falling outside excavation line |
| 278 | 278 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 1    | 16 | To be removed  | Falling within excavation line  |
| 279 | 279 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 1    | 11 | To be retained | Falling outside excavation line |
| 280 | 280 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 1    | 13 | To be retained | Falling outside excavation line |
| 281 | 281 | Wad        | <i>Ficus benghalensis</i>      | 32'  | 45 | To be retained | Falling outside excavation line |
| 282 | 282 | Pimpal     | <i>Ficus religiosa</i>         | 12'  | 51 | To be retained | Falling outside excavation line |
| 283 | 283 | Pimpal     | <i>Ficus religiosa</i>         | 12'  | 45 | To be retained | Falling outside excavation line |
| 284 | 284 | Xmas tree  | <i>Araucaria columnaris</i>    | 8"   | 4  | To be removed  | Falling within excavation line  |
| 285 | 285 | Karanj     | <i>Pongamia pinnata</i>        | 1.1  | 11 | To be removed  | Falling within excavation line  |
| 286 | 286 | Desi badam | <i>Terminalia catappa</i>      | 6"   | 5  | To be removed  | Falling within excavation line  |
| 287 | 287 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 3'3" | 35 | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                |   |    |                |                                 |
|-----|-----|---------------|--------------------------------|---|----|----------------|---------------------------------|
| 288 | 288 | Lettuce tree  | <i>Pisonia alba</i>            | 1 | 9  | To be removed  | Falling within excavation line  |
| 289 | 289 | Kala umber    | <i>Ficus hispida</i>           | 1 | 9  | To be removed  | Falling within excavation line  |
| 290 | 290 | Rain Tree     | <i>Samanea saman</i>           | 4 | 33 | To be removed  | Falling within excavation line  |
| 291 | 291 | Pimpal        | <i>Ficus religiosa</i>         | 3 | 27 | To be retained | Falling outside excavation line |
| 292 | 292 | Pimpal        | <i>Ficus religiosa</i>         | 4 | 27 | To be retained | Falling outside excavation line |
| 293 | 293 | Jungli Badam  | <i>Sterculia foetida</i>       | 3 | 12 | To be retained | Falling outside excavation line |
| 294 | 294 | Vad           | <i>Ficus benghalensis</i>      | 6 | 24 | To be retained | Falling outside excavation line |
| 295 | 295 | Pimpal        | <i>Ficus religiosa</i>         | 2 | 15 | To be retained | Falling outside excavation line |
| 296 | 296 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 5 | 30 | To be removed  | Falling within excavation line  |
| 297 | 297 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4 | 30 | To be removed  | Falling within excavation line  |
| 298 | 298 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4 | 30 | To be removed  | Falling within excavation line  |
| 299 | 299 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4 | 20 | To be removed  | Falling within excavation line  |
| 300 | 300 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4 | 25 | To be removed  | Falling within excavation line  |
| 301 | 301 | Royal palm    | <i>Roystonea regia</i>         | 4 | 30 | To be removed  | Falling within excavation line  |
| 302 | 302 | Royal palm    | <i>Roystonea regia</i>         | 4 | 30 | To be removed  | Falling within excavation line  |
| 303 | 303 | Royal palm    | <i>Roystonea regia</i>         | 4 | 30 | To be removed  | Falling within excavation line  |
| 304 | 304 | Kala UMBER    | <i>Ficus hispida L.F.</i>      | 4 | 15 | To be removed  | Falling within excavation line  |
| 305 | 305 | Royal palm    | <i>Roystonea regia</i>         | 4 | 30 | To be removed  | Falling within excavation line  |
| 306 | 306 | Pimple        | <i>Ficus religiosa</i>         | 3 | 30 | To be removed  | Falling within excavation line  |
| 307 | 307 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 5 | 35 | To be removed  | Falling within excavation line  |
| 308 | 308 | Royal palm    | <i>Roystonea regia</i>         | 5 | 35 | To be removed  | Falling within excavation line  |
| 309 | 309 | Fishtail palm | <i>Caryota mitis</i>           | 5 | 30 | To be removed  | Falling within excavation line  |
| 310 | 310 | Royal palm    | <i>Roystonea regia</i>         | 4 | 30 | To be removed  | Falling within excavation line  |
| 311 | 311 | Kala UMBER    | <i>Ficus hispida L.F.</i>      | 2 | 20 | To be removed  | Falling within excavation line  |
| 312 | 312 | Pimple        | <i>Ficus religiosa</i>         | 5 | 35 | To be removed  | Falling within excavation line  |
| 313 | 313 | Royal palm    | <i>Roystonea regia</i>         | 6 | 35 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                |     |     |               |                                |
|-----|-----|---------------|--------------------------------|-----|-----|---------------|--------------------------------|
| 314 | 314 | Royal palm    | <i>Roystonea regia</i>         | 5   | 35  | To be removed | Falling within excavation line |
| 315 | 315 | Pimple        | <i>Ficus religiosa</i>         | 5   | 35  | To be removed | Falling within excavation line |
| 316 | 316 | Mango         | <i>Mangifera Indica</i>        | 8"  | 15' | To be removed | Falling within excavation line |
| 317 | 317 | Sonmohor      | <i>Peltophorum pterocarpum</i> | 4.5 | 35  | To be removed | Falling within excavation line |
| 318 | 318 | Fishtail palm | <i>Caryota mitis</i>           | 1   | 20  | To be removed | Falling within excavation line |
| 319 | 319 | Acacia        | <i>Acacia greggii</i>          | 4   | 30  | To be removed | Falling within excavation line |
| 320 | 320 | Coconut       | <i>Cocos nucifera</i>          | 3.5 | 40  | To be removed | Falling within excavation line |
| 321 | 321 | Coconut       | <i>Cocos nucifera</i>          | 3   | 30  | To be removed | Falling within excavation line |
| 322 | 322 | Mango         | <i>Mangifera Indica</i>        | 4   | 35  | To be removed | Falling within excavation line |
| 323 | 323 | Coconut       | <i>Cocos nucifera</i>          | 4   | 40  | To be removed | Falling within excavation line |
| 324 | 324 | Mango         | <i>Mangifera Indica</i>        | 3   | 30  | To be removed | Falling within excavation line |
| 325 | 325 | Coconut       | <i>Cocos nucifera</i>          | 3   | 40  | To be removed | Falling within excavation line |
| 326 | 326 | Coconut       | <i>Cocos nucifera</i>          | 3   | 40  | To be removed | Falling within excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 19         |
| Trees to be removed  | 307        |
| <b>Total Trees</b>   | <b>326</b> |

| Summary of Tree Survey at Vidhan Bhavan Station |          |             |                                 |                     |                      |                     |   |
|---|----------|-------------|---------------------------------|---------------------|----------------------|---------------------|---|
| Sr. no.   | Tree no. | Common Name | Botanical Name                  | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                                  |
| 1   | 1        | Silver oak  | <i>Grewelia robusta</i>         | 3                   | 40                   | To be removed       | Tree is Falling within excavation line  |
| 2   | 2        | Umbar       | <i>Ficus glomerata</i>          | 3                   | 16                   | To be removed       | Tree is Falling within excavation line  |
| 3   | 3        | Wad         | <i>Ficus benghalensis</i>       | 4                   | 40                   | To be removed       | Tree is Falling within excavation line  |
| 4   | 4        | Pimpal      | <i>Ficus religiosa</i>          | 16                  | 33                   | To be removed       | Tree is Falling within excavation line  |
| 5   | 5        | Gulmohar    | <i>Delonix regia</i>            | 3                   | 24                   | To be retained      | Tree is Falling outside excavation line |
| 6   | 6        | Jambhul     | <i>Syzygium cuminii</i>         | 2                   | 18                   | To be retained      | Tree is Falling outside excavation line |
| 7   | 7        | Limbu       | <i>Citrus auratifolia</i>       | 6"                  | 8                    | To be retained      | Tree is Falling outside excavation line |
| 8   | 8        | Dead        | -                               | 2                   | 20                   | To be retained      | Tree is Falling outside excavation line |
| 9   | 9        | Jambhul     | <i>Syzygium cuminii</i>         | 1                   | 18                   | To be retained      | Tree is Falling outside excavation line |
| 10  | 10       | Naral       | <i>Cocos nucifera</i>           | 2                   | 12                   | To be retained      | Tree is Falling outside excavation line |
| 11  | 11       | Gulmohar    | <i>Delonix regia</i>            | 5                   | 25                   | To be retained      | Tree is Falling outside excavation line |
| 12  | 12       | Naral       | <i>Cocos nucifera</i>           | 2                   | 10                   | To be retained      | Tree is Falling outside excavation line |
| 13  | 13       | Gulmohar    | <i>Delonix regia</i>            | 4                   | 25                   | To be retained      | Tree is Falling outside excavation line |
| 14  | 14       | Phanas      | <i>Artocarpus heterophyllus</i> | 1                   | 15                   | To be retained      | Tree is Falling outside excavation line |
| 15  | 15       | Gulmohar    | <i>Delonix regia</i>            | 4                   | 25                   | To be retained      | Tree is Falling outside excavation line |
| 16  | 16       | Naral       | <i>Cocos nucifera</i>           | 2                   | 10                   | To be retained      | Tree is Falling outside excavation line |
| 17  | 17       | Naral       | <i>Cocos nucifera</i>           | 2                   | 10                   | To be retained      | Tree is Falling outside excavation line |
| 18  | 18       | Wad         | <i>Ficus benghalensis</i>       | 12                  | 40                   | To be removed       | Tree is Falling within excavation line  |
| 19  | 19       | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 4                   | 25                   | To be retained      | Tree is Falling outside excavation line |
| 20  | 20       | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 4                   | 25                   | To be retained      | Tree is Falling outside excavation line |
| 21  | 21       | Desi Badam  | <i>Terminalia catappa</i>       | 2                   | 25                   | To be retained      | Tree is Falling outside excavation line |
| 22  | 22       | Gulmohar    | <i>Delonix regia</i>            | 2                   | 18                   | To be retained      | Tree is Falling outside excavation line |
| 23  | 23       | Wad         | <i>Ficus benghalensis</i>       | 10                  | 25                   | To be removed       | Tree is Falling within excavation line  |
| 24  | 24       | Pimpal      | <i>Ficus religiosa</i>          | 4                   | 20                   | To be removed       | Tree is Falling within excavation line  |
| 25  | 25       | Pimpal      | <i>Ficus religiosa</i>          | 5                   | 25                   | To be retained      | Tree is Falling outside excavation line |
| 26  | 26       | Pimpal      | <i>Ficus religiosa</i>          | 6                   | 25                   | To be retained      | Tree is Falling outside excavation line |
| 27  | 27       | Umber       | <i>Ficus racemosa</i>           | 4                   | 22                   | To be retained      | Tree is Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |             |                                 |    |    |                |   |
|----|----|-------------|---------------------------------|----|----|----------------|---|
| 28 | 28 | Pimpal      | <i>Ficus religiosa</i>          | 18 | 30 | To be removed  | Tree is Falling within excavation line  |
| 29 | 29 | Wad         | <i>Ficus benghalensis</i>       | 8  | 30 | To be removed  | Tree is Falling within excavation line  |
| 30 | 30 | Pimpal      | <i>Ficus religiosa</i>          | 12 | 30 | To be removed  | Tree is Falling within excavation line  |
| 31 | 31 | Saptaparni  | <i>Alstonia scholaris</i>       | 2  | 25 | To be removed  | Tree is Falling within excavation line  |
| 32 | 32 | Saptaparni  | <i>Alstonia scholaris</i>       | 2  | 21 | To be removed  | Tree is Falling within excavation line  |
| 33 | 33 | Kadamb      | <i>Neolamarkiana cadamba</i>    | 4  | 28 | To be retained | Tree is Falling outside excavation line |
| 34 | 34 | Gulmohar    | <i>Delonix regia</i>            | 3  | 24 | To be retained | Tree is Falling outside excavation line |
| 35 | 35 | Bakneem     | <i>Melia azadirach</i>          | 4  | 25 | To be retained | Tree is Falling outside excavation line |
| 36 | 36 | Saptaparni  | <i>Alstonia scholaris</i>       | 3  | 25 | To be retained | Tree is Falling outside excavation line |
| 37 | 37 | Pichkari    | <i>Spathodia campanulata</i>    | 5  | 28 | To be retained | Tree is Falling outside excavation line |
| 38 | 38 | Deshi Badam | <i>Terminalia catappa</i>       | 2  | 15 | To be removed  | Tree is Falling within excavation line  |
| 39 | 39 | Vad         | <i>Ficus benghalensis</i>       | 11 | 25 | To be removed  | Tree is Falling within excavation line  |
| 40 | 40 | Saptaparni  | <i>Alstonia scholaris</i>       | 3  | 25 | To be removed  | Tree is Falling within excavation line  |
| 41 | 41 | Kadamb      | <i>Neolamarkiana cadamba</i>    | 3  | 25 | To be removed  | Tree is Falling within excavation line  |
| 42 | 42 | Karanj      | <i>Pongamia pinnata</i>         | 4  | 30 | To be removed  | Tree is Falling within excavation line  |
| 43 | 43 | Wad         | <i>Ficus benghalensis</i>       | 10 | 40 | To be removed  | Tree is Falling within excavation line  |
| 44 | 44 | Shevga      | <i>Moringa pterigosperma</i>    | 4  | 22 | To be removed  | Tree is Falling within excavation line  |
| 45 | 45 | Jambhul     | <i>Syzygium cuminii</i>         | 4  | 25 | To be removed  | Tree is Falling within excavation line  |
| 46 | 46 | Shevga      | <i>Moringa pterigosperma</i>    | 4  | 22 | To be removed  | Tree is Falling within excavation line  |
| 47 | 47 | Amba        | <i>Mangifera indica</i>         | 8  | 15 | To be retained | Tree is Falling outside excavation line |
| 48 | 48 | Deshi Badam | <i>Terminalia catappa</i>       | 1  | 12 | To be retained | Tree is Falling outside excavation line |
| 49 | 49 | Phanas      | <i>Artocarpus heterophyllus</i> | 1  | 18 | To be retained | Tree is Falling outside excavation line |
| 50 | 50 | Phanas      | <i>Artocarpus heterophyllus</i> | 1  | 18 | To be retained | Tree is Falling outside excavation line |
| 51 | 51 | Phanas      | <i>Artocarpus heterophyllus</i> | 1  | 12 | To be retained | Tree is Falling outside excavation line |
| 52 | 52 | Amba        | <i>Mangifera indica</i>         | 2  | 18 | To be retained | Tree is Falling outside excavation line |
| 53 | 53 | Pimpal      | <i>Ficus religiosa</i>          | 5  | 25 | To be retained | Tree is Falling outside excavation line |
| 54 | 54 | Wad         | <i>Ficus benghalensis</i>       | 4  | 20 | To be retained | Tree is Falling outside excavation line |
| 55 | 55 | Peru        | <i>Psidium guajava</i>          | 1  | 15 | To be retained | Tree is Falling outside excavation line |
| 56 | 56 | Naral       | <i>Cocos nucifera</i>           | 4  | 15 | To be retained | Tree is Falling outside excavation line |
| 57 | 57 | Amba        | <i>Mangifera indica</i>         | 1  | 15 | To be retained | Tree is Falling outside excavation line |
| 58 | 58 | Phanas      | <i>Artocarpus heterophyllus</i> | 1  | 22 | To be removed  | Tree is Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |                  |   |    |    |                |   |
|----|----|------------------|---|----|----|----------------|---|
| 59 | 59 | Amba             | <i>Mangifera indica</i>                     | 1  | 15 | To be removed  | Tree is Falling within excavation line  |
| 60 | 60 | Pimpal           | <i>Ficus religiosa</i>                      | 5  | 30 | To be removed  | Tree is Falling within excavation line  |
| 61 | 61 | Pimpal           | <i>Ficus religiosa</i>                      | 5  | 30 | To be removed  | Tree is Falling within excavation line  |
| 62 | 62 | Umber            | <i>Ficus racemosa.</i>                      | 3  | 25 | To be removed  | Tree is Falling within excavation line  |
| 63 | 63 | Wad              | <i>Ficus Benghalensis</i>                   | 15 | 45 | To be removed  | Tree is Falling within excavation line  |
| 64 | 64 | Peru             | <i>Psidium guajava</i>                      | 1  | 15 | To be removed  | Tree is Falling within excavation line  |
| 65 | 65 | Asupalav         | <i>Polyalthia longifolia</i>                | 2  | 20 | To be retained | Tree is Falling outside excavation line |
| 66 | 66 | Pimpal           | <i>Ficus religiosa</i>                      | 20 | 40 | To be removed  | Tree is Falling within excavation line  |
| 67 | 67 | Mango            | <i>Mangifera indica</i>                     | 1  | 10 | To be removed  | Tree is Falling within excavation line  |
| 68 | 68 | Asupalav         | <i>Polyalthia longifolia</i>                | 2  | 16 | To be retained | Tree is Falling outside excavation line |
| 69 | 69 | Asupalav         | <i>Polyalthia longifolia</i>                | 2  | 20 | To be retained | Tree is Falling outside excavation line |
| 70 | 70 | Rain tree        | <i>Samanea saman</i>                        | 8  | 36 | To be removed  | Tree is Falling within excavation line  |
| 71 | 71 | Rain tree        | <i>Samanea saman</i>                        | 7  | 36 | To be removed  | Tree is Falling within excavation line  |
| 72 | 72 | Rain Tree        | <i>Samanea saman</i>                        | 8  | 40 | To be removed  | Tree is Falling within excavation line  |
| 73 | 73 | Rain Tree        | <i>Samanea saman</i>                        | 6  | 35 | To be retained | Tree is Falling outside excavation line |
| 74 | 74 | Rain Tree        | <i>Samanea saman</i>                        | 8  | 35 | To be retained | Tree is Falling outside excavation line |
| 75 | 75 | Rain Tree        | <i>Samanea saman</i>                        | 7  | 35 | To be retained | Tree is Falling outside excavation line |
| 76 | 76 | Rain Tree        | <i>Samanea saman</i>                        | 6  | 40 | To be retained | Tree is Falling outside excavation line |
| 77 | 77 | Rain Tree        | <i>Samanea saman</i>                        | 6  | 35 | To be retained | Tree is Falling outside excavation line |
| 78 | 78 | Asupalav         | <i>Polyalthia longifolia</i>                | 2  | 16 | To be retained | Tree is Falling outside excavation line |
| 79 | 79 | Gulmohar         | <i>Delonix regia</i>                        | 10 | 40 | To be retained | Tree is Falling outside excavation line |
| 80 | 80 | Asupalav         | <i>Polyalthia longifolia</i>                | 2  | 16 | To be retained | Tree is Falling outside excavation line |
| 81 | 81 | Date palm (Dead) | <i>Phoenix sylvestris</i>                   | 3  | 16 | To be retained | Tree is Falling outside excavation line |
| 82 | 82 | Jungli Badam     | <i>Sterculia foetida</i>                    | 2  | 30 | To be retained | Tree is Falling outside excavation line |
| 83 | 83 | J.Badam + Vad    | <i>Sterculia foetida+Ficus benghalensis</i> | 4  | 35 | To be retained | Tree is Falling outside excavation line |
| 84 | 84 | Sonmohar         | <i>Peltophorum pterocarpum</i>              | 6  | 30 | To be retained | Tree is Falling outside excavation line |
| 85 | 85 | Pimpal+ wad      | <i>Ficus religiosa+ Ficus benghalensis</i>  | 12 | 40 | To be retained | Tree is Falling outside excavation line |
| 86 | 86 | Sonmohar         | <i>Peltophorum pterocarpum</i>              | 3  | 35 | To be retained | Tree is Falling outside excavation line |
| 87 | 87 | Sonmohar         | <i>Peltophorum pterocarpum</i>              | 3  | 30 | To be retained | Tree is Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |           |                                |    |    |                |   |
|-----|-----|-----------|--------------------------------|----|----|----------------|---|
| 88  | 88  | Pimpal    | <i>Ficus religiosa</i>         | 12 | 35 | To be retained | Tree is Falling outside excavation line |
| 89  | 89  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 4  | 35 | To be retained | Tree is Falling outside excavation line |
| 90  | 90  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3  | 25 | To be retained | Tree is Falling outside excavation line |
| 91  | 91  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 7  | 35 | To be removed  | Tree is Falling within excavation line  |
| 92  | 92  | Asupalav  | <i>Polyalthia longifolia</i>   | 2  | 15 | To be removed  | Tree is Falling within excavation line  |
| 93  | 93  | Asupalav  | <i>Polyalthia longifolia</i>   | 2  | 16 | To be removed  | Tree is Falling within excavation line  |
| 94  | 94  | Asupalav  | <i>Polyalthia longifolia</i>   | 2  | 16 | To be removed  | Tree is Falling within excavation line  |
| 95  | 95  | Asupalav  | <i>Polyalthia longifolia</i>   | 2  | 16 | To be removed  | Tree is Falling within excavation line  |
| 96  | 96  | Asupalav  | <i>Polyalthia longifolia</i>   | 2  | 16 | To be removed  | Tree is Falling within excavation line  |
| 97  | 97  | Asupalav  | <i>Polyalthia longifolia</i>   | 2  | 16 | To be removed  | Tree is Falling within excavation line  |
| 98  | 98  | Bhend     | <i>Thespesia populnea</i>      | 2  | 30 | To be retained | Tree is Falling outside excavation line |
| 99  | 99  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 7  | 33 | To be removed  | Tree is Falling within excavation line  |
| 100 | 100 | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Tree is Falling within excavation line  |
| 101 | 101 | Sonmohar  | <i>Peltophorum pterocarpum</i> | 4  | 33 | To be removed  | Tree is Falling within excavation line  |
| 102 | 102 | Naral     | <i>Cocos nucifera</i>          | 3  | 15 | To be removed  | Tree is Falling within excavation line  |
| 103 | 103 | Sonmohar  | <i>Peltophorum pterocarpum</i> | 4  | 33 | To be removed  | Tree is Falling within excavation line  |
| 104 | 104 | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3  | 33 | To be removed  | Tree is Falling within excavation line  |
| 105 | 105 | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3  | 36 | To be removed  | Tree is Falling within excavation line  |
| 106 | 106 | Sonmohar  | <i>Peltophorum pterocarpum</i> | 4  | 33 | To be removed  | Tree is Falling within excavation line  |
| 107 | 107 | Asupalav  | <i>Polyalthia longifolia</i>   | 2  | 16 | To be removed  | Tree is Falling within excavation line  |
| 108 | 108 | Asupalav  | <i>Polyalthia longifolia</i>   | 2  | 16 | To be removed  | Tree is Falling within excavation line  |
| 109 | 109 | Rain Tree | <i>Samanea saman</i>           | 5  | 35 | To be removed  | Tree is Falling within excavation line  |
| 110 | 110 | Wad       | <i>Ficus benghalensis</i>      | 13 | 46 | To be removed  | Tree is Falling within excavation line  |
| 111 | 111 | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3  | 33 | To be removed  | Tree is Falling within excavation line  |
| 112 | 112 | Naral     | <i>Cocos nucifera</i>          | 2  | 25 | To be removed  | Tree is Falling within excavation line  |
| 113 | 113 | Naral     | <i>Cocos nucifera</i>          | 2  | 15 | To be removed  | Tree is Falling within excavation line  |
| 114 | 114 | Naral     | <i>Cocos nucifera</i>          | 2  | 15 | To be removed  | Tree is Falling within excavation line  |
| 115 | 115 | Rain Tree | <i>Samanea saman</i>           | 5  | 40 | To be removed  | Tree is Falling within excavation line  |
| 116 | 116 | Shevga    | <i>Moringa oleifera</i>        | 4  | 30 | To be removed  | Tree is Falling within excavation line  |
| 117 | 117 | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Tree is Falling within excavation line  |
| 118 | 118 | Bhend     | <i>Thespesia populnea</i>      | 3  | 10 | To be removed  | Tree is Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |             |                                |    |    |                |   |
|-----|-----|-------------|--------------------------------|----|----|----------------|---|
| 119 | 119 | Desi badam  | <i>Terminalia catappa</i>      | 1  | 16 | To be removed  | Tree is Falling within excavation line  |
| 120 | 120 | Naral       | <i>Cocos nucifera</i>          | 2  | 15 | To be retained | Tree is Falling outside excavation line |
| 121 | 121 | Naral       | <i>Cocos nucifera</i>          | 2  | 25 | To be retained | Tree is Falling outside excavation line |
| 122 | 122 | Umbur       | <i>Ficus racemosa</i>          | 2  | 15 | To be retained | Tree is Falling outside excavation line |
| 123 | 123 | Suru        | <i>Casuarina equisetifolia</i> | 2  | 15 | To be retained | Tree is Falling outside excavation line |
| 124 | 124 | Pimpal      | <i>Ficus religiosa</i>         | 3  | 25 | To be retained | Tree is Falling outside excavation line |
| 125 | 125 | Deshi Badam | <i>Terminalia catappa</i>      | 1  | 12 | To be retained | Tree is Falling outside excavation line |
| 126 | 126 | Badam       | <i>Terminalia catappa</i>      | 1  | 15 | To be retained | Tree is Falling outside excavation line |
| 127 | 127 | Pimpal      | <i>Ficus religiosa</i>         | 1  | 18 | To be retained | Tree is Falling outside excavation line |
| 128 | 128 | Desi Badam  | <i>Terminalia catappa</i>      | 5  | 55 | To be removed  | Tree is Falling within excavation line  |
| 129 | 129 | Kailashpati | <i>Couroupita guianensis</i>   | 4  | 40 | To be removed  | Tree is Falling within excavation line  |
| 130 | 130 | Naral       | <i>Cocos nucifera</i>          | 4  | 65 | To be removed  | Tree is Falling within excavation line  |
| 131 | 131 | Naral       | <i>Cocos nucifera</i>          | 4  | 65 | To be removed  | Tree is Falling within excavation line  |
| 132 | 132 | Naral       | <i>Cocos nucifera</i>          | 4  | 55 | To be removed  | Tree is Falling within excavation line  |
| 133 | 133 | Bhend       | <i>Thespesia populnea</i>      | 2  | 12 | To be removed  | Tree is Falling within excavation line  |
| 134 | 134 | Badam       | <i>Terminalia catappa</i>      | 1  | 15 | To be removed  | Tree is Falling within excavation line  |
| 135 | 135 | Pimple      | <i>Ficus religiosa</i>         | 1  | 20 | To be removed  | Tree is Falling within excavation line  |
| 136 | 136 | Bhend       | <i>Thespesia populnea</i>      | 2  | 10 | To be removed  | Tree is Falling within excavation line  |
| 137 | 137 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 4  | 21 | To be removed  | Tree is Falling within excavation line  |
| 138 | 138 | Royal palm  | <i>Roystonea regia</i>         | 4  | 40 | To be removed  | Tree is Falling within excavation line  |
| 139 | 139 | Kashid      | <i>Cassia siamea</i>           | 3  | 15 | To be removed  | Tree is Falling within excavation line  |
| 140 | 140 | Asupalav    | <i>Polyalthia longifolia</i>   | 1  | 25 | To be removed  | Tree is Falling within excavation line  |
| 141 | 141 | Royal palm  | <i>Roystonea regia</i>         | 4  | 40 | To be removed  | Tree is Falling within excavation line  |
| 142 | 142 | Putranjiva  | <i>Putranjiva roxburghii</i>   | 1  | 20 | To be removed  | Tree is Falling within excavation line  |
| 143 | 143 | Royal palm  | <i>Roystonea regia</i>         | 4  | 40 | To be removed  | Tree is Falling within excavation line  |
| 144 | 144 | Royal palm  | <i>Roystonea regia</i>         | 3  | 25 | To be removed  | Tree is Falling within excavation line  |
| 145 | 145 | Jamun       | <i>Syzygium cuminii</i>        | 3  | 30 | To be removed  | Tree is Falling within excavation line  |
| 146 | 146 | Royal palm  | <i>Roystonea regia</i>         | 3  | 25 | To be removed  | Tree is Falling within excavation line  |
| 147 | 147 | Sonchafa    | <i>Michelia champaca</i>       | 1  | 25 | To be removed  | Tree is Falling within excavation line  |
| 148 | 148 | Coconut     | <i>Cocos nucifera</i>          | 8" | 10 | To be removed  | Tree is Falling within excavation line  |
| 149 | 149 | Coconut     | <i>Cocos nucifera</i>          | 8" | 12 | To be removed  | Tree is Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                     |                                 |   |    |               |  |
|-----|-----|---------------------|---------------------------------|---|----|---------------|--|
| 150 | 150 | Royal palm          | <i>Roystonea regia</i>          | 3 | 25 | To be removed | Tree is Falling within excavation line |
| 151 | 151 | Gulmohar            | <i>Delonix regia</i>            | 3 | 18 | To be removed | Tree is Falling within excavation line |
| 152 | 152 | Royal palm          | <i>Roystonea regia</i>          | 3 | 25 | To be removed | Tree is Falling within excavation line |
| 153 | 153 | Gulmohar            | <i>Delonix regia</i>            | 4 | 30 | To be removed | Tree is Falling within excavation line |
| 154 | 154 | Asupalav            | <i>Polyalthia longifolia</i>    | 2 | 18 | To be removed | Tree is Falling within excavation line |
| 155 | 155 | Asupalav            | <i>Polyalthia longifolia</i>    | 2 | 20 | To be removed | Tree is Falling within excavation line |
| 156 | 156 | Parijatak           | <i>Nyctanthus arbor-tristis</i> | 2 | 26 | To be removed | Tree is Falling within excavation line |
| 157 | 157 | Shewga              | <i>Moringa oleifera</i>         | 3 | 30 | To be removed | Tree is Falling within excavation line |
| 158 | 158 | Asupalav            | <i>Polyalthia longifolia</i>    | 2 | 25 | To be removed | Tree is Falling within excavation line |
| 159 | 159 | Desi badam          | <i>Terminalia catappa</i>       | 3 | 35 | To be removed | Tree is Falling within excavation line |
| 160 | 160 | Putranjiva          | <i>Putranjiva roxburghii</i>    | 3 | 40 | To be removed | Tree is Falling within excavation line |
| 161 | 161 | Putranjiva          | <i>Putranjiva roxburghii</i>    | 4 | 45 | To be removed | Tree is Falling within excavation line |
| 162 | 162 | Desi badam          | <i>Terminalia catappa</i>       | 2 | 25 | To be removed | Tree is Falling within excavation line |
| 163 | 163 | Amba                | <i>Mangifera indica</i>         | 1 | 10 | To be removed | Tree is Falling within excavation line |
| 164 | 164 | Asupalav            | <i>Polyalthia longifolia</i>    | 2 | 26 | To be removed | Tree is Falling within excavation line |
| 165 | 165 | Asupalav            | <i>Polyalthia longifolia</i>    | 2 | 20 | To be removed | Tree is Falling within excavation line |
| 166 | 166 | Desi badam          | <i>Terminalia catappa</i>       | 3 | 30 | To be removed | Tree is Falling within excavation line |
| 167 | 167 | Asupalav            | <i>Polyalthia longifolia</i>    | 1 | 10 | To be removed | Tree is Falling within excavation line |
| 168 | 168 | Shewga              | <i>Moringa oleifera</i>         | 3 | 36 | To be removed | Tree is Falling within excavation line |
| 169 | 169 | Jungli badam (Dead) | <i>Sterculia foetida</i>        | 3 | 40 | To be removed | Tree is Falling within excavation line |
| 170 | 170 | Asupalav            | <i>Polyalthia longifolia</i>    | 3 | 30 | To be removed | Tree is Falling within excavation line |
| 171 | 171 | Peru                | <i>Psidium gujava</i>           | 2 | 16 | To be removed | Tree is Falling within excavation line |
| 172 | 172 | Desi badam          | <i>Terminalia catappa</i>       | 2 | 30 | To be removed | Tree is Falling within excavation line |
| 173 | 173 | Naral               | <i>Cocos nucifera</i>           | 3 | 16 | To be removed | Tree is Falling within excavation line |
| 174 | 174 | Naral               | <i>Cocos nucifera</i>           | 4 | 20 | To be removed | Tree is Falling within excavation line |
| 175 | 175 | Chapha              | <i>Plumeria alba</i>            | 1 | 10 | To be removed | Tree is Falling within excavation line |
| 176 | 176 | Subabhul            | <i>Leucaena leucocephala</i>    | 1 | 20 | To be removed | Tree is Falling within excavation line |
| 177 | 177 | Kala umber          | <i>Ficus hispida</i>            | 1 | 15 | To be removed | Tree is Falling within excavation line |
| 178 | 178 | Chapha              | <i>Plumeria alba</i>            | 3 | 15 | To be removed | Tree is Falling within excavation line |
| 179 | 179 | Sonmohar            | <i>Peltophorum pterocarpum</i>  | 3 | 16 | To be removed | Tree is Falling within excavation line |
| 180 | 180 | Subabhul            | <i>Leucaena leucocephala</i>    | 2 | 15 | To be removed | Tree is Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                |   |    |                |   |
|-----|-----|----------------|--------------------------------|---|----|----------------|---|
| 181 | 181 | Subabhul       | <i>Leucaena leucocephala</i>   | 2 | 20 | To be removed  | Tree is Falling within excavation line  |
| 182 | 182 | Chapha         | <i>Plumeria alba</i>           | 3 | 12 | To be retained | Tree is Falling outside excavation line |
| 183 | 183 | Chapha         | <i>Plumeria alba</i>           | 1 | 15 | To be retained | Tree is Falling outside excavation line |
| 184 | 184 | Kala umber     | <i>Ficus hispida</i>           | 1 | 15 | To be removed  | Tree is Falling within excavation line  |
| 185 | 185 | Chapha         | <i>Plumeria alba</i>           | 3 | 15 | To be retained | Tree is Falling outside excavation line |
| 186 | 186 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 6 | 35 | To be retained | Tree is Falling outside excavation line |
| 187 | 187 | Gulmohar       | <i>Delonix regia</i>           | 3 | 25 | To be retained | Tree is Falling outside excavation line |
| 188 | 188 | Gulmohar       | <i>Delonix regia</i>           | 5 | 25 | To be retained | Tree is Falling outside excavation line |
| 189 | 189 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 2 | 25 | To be retained | Tree is Falling outside excavation line |
| 190 | 190 | Gulmohar       | <i>Delonix regia</i>           | 2 | 25 | To be retained | Tree is Falling outside excavation line |
| 191 | 191 | Gulmohar       | <i>Delonix regia</i>           | 4 | 25 | To be retained | Tree is Falling outside excavation line |
| 192 | 192 | Chenduphul     | <i>Parkia biglandulosa</i>     | 5 | 25 | To be retained | Tree is Falling outside excavation line |
| 193 | 193 | Tabebuia       | <i>Tabebuia pentaphylla</i>    | 2 | 15 | To be retained | Tree is Falling outside excavation line |
| 194 | 194 | Pimpal         | <i>Ficus religiosa</i>         | 8 | 25 | To be retained | Tree is Falling outside excavation line |
| 195 | 195 | Naral          | <i>Cocos nucifera</i>          | 2 | 15 | To be retained | Tree is Falling outside excavation line |
| 196 | 196 | Pimpal         | <i>Ficus religiosa</i>         | 7 | 25 | To be retained | Tree is Falling outside excavation line |
| 197 | 197 | Pimpal         | <i>Ficus religiosa</i>         | 4 | 22 | To be retained | Tree is Falling outside excavation line |
| 198 | 198 | Pimpal         | <i>Ficus religiosa</i>         | 5 | 25 | To be retained | Tree is Falling outside excavation line |
| 199 | 199 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 3 | 22 | To be retained | Tree is Falling outside excavation line |
| 200 | 200 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 4 | 25 | To be retained | Tree is Falling outside excavation line |
| 201 | 201 | Scarlet cordia | <i>Cordia sebestina</i>        | 2 | 22 | To be retained | Tree is Falling outside excavation line |
| 202 | 202 | Naral          | <i>Cocos nucifera</i>          | 2 | 20 | To be retained | Tree is Falling outside excavation line |
| 203 | 203 | Naral          | <i>Cocos nucifera</i>          | 2 | 15 | To be retained | Tree is Falling outside excavation line |
| 204 | 204 | Amba           | <i>Mangifera indica</i>        | 2 | 18 | To be retained | Tree is Falling outside excavation line |
| 205 | 205 | Peru           | <i>Psidium guajava</i>         | 1 | 12 | To be retained | Tree is Falling outside excavation line |
| 206 | 206 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 3 | 30 | To be removed  | Tree is Falling within excavation line  |
| 207 | 207 | Amba           | <i>Mangifera indica</i>        | 2 | 16 | To be removed  | Tree is Falling within excavation line  |
| 208 | 208 | Phanas         | <i>Atrocarpus integrifolia</i> | 2 | 35 | To be removed  | Tree is Falling within excavation line  |
| 209 | 209 | Nandaruk       | <i>Ficus benjamina</i>         | 3 | 10 | To be removed  | Tree is Falling within excavation line  |
| 210 | 210 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 1 | 15 | To be removed  | Tree is Falling within excavation line  |
| 211 | 211 | Amba           | <i>Mangifera indica</i>        | 7 | 36 | To be removed  | Tree is Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |             |                                 |    |    |                |   |
|-----|-----|-------------|---------------------------------|----|----|----------------|---|
| 212 | 212 | Amba        | <i>Mangifera indica</i>         | 1  | 15 | To be removed  | Tree is Falling within excavation line  |
| 213 | 213 | Naral       | <i>Cocos nucifera</i>           | 3  | 15 | To be removed  | Tree is Falling within excavation line  |
| 214 | 214 | Naral       | <i>Cocos nucifera</i>           | 2  | 15 | To be removed  | Tree is Falling within excavation line  |
| 215 | 215 | Gulmohar    | <i>Delonix regia</i>            | 4  | 30 | To be removed  | Tree is Falling within excavation line  |
| 216 | 216 | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 3  | 20 | To be removed  | Tree is Falling within excavation line  |
| 217 | 217 | Taman       | <i>Lagerstroemia speciosa</i>   | 4  | 30 | To be removed  | Tree is Falling within excavation line  |
| 218 | 218 | Taman       | <i>Lagerstroemia speciosa</i>   | 3  | 25 | To be removed  | Tree is Falling within excavation line  |
| 219 | 219 | Pimpal      | <i>Ficus religiosa</i>          | 2  | 15 | To be removed  | Tree is Falling within excavation line  |
| 220 | 220 | Umber       | <i>Ficus glomerata</i>          | 1  | 10 | To be removed  | Tree is Falling within excavation line  |
| 221 | 221 | Amba        | <i>Mangifera indica</i>         | 3  | 30 | To be removed  | Tree is Falling within excavation line  |
| 222 | 222 | Asupalav    | <i>Polyalthia longifolia</i>    | 1  | 16 | To be removed  | Tree is Falling within excavation line  |
| 223 | 223 | Umber       | <i>Ficus glomerata</i>          | 7  | 36 | To be removed  | Tree is Falling within excavation line  |
| 224 | 224 | Amba        | <i>Mangifera indica</i>         | 1  | 16 | To be removed  | Tree is Falling within excavation line  |
| 225 | 225 | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 1  | 20 | To be removed  | Tree is Falling within excavation line  |
| 226 | 226 | Nandaruk    | <i>Ficus benjamina</i>          | 3  | 15 | To be removed  | Tree is Falling within excavation line  |
| 227 | 227 | Phanas      | <i>Artocarpus heterophyllus</i> | 2  | 15 | To be removed  | Tree is Falling within excavation line  |
| 228 | 228 | Phanas      | <i>Artocarpus heterophyllus</i> | 1  | 10 | To be removed  | Tree is Falling within excavation line  |
| 229 | 229 | Peru        | <i>Psidium guajava</i>          | 9" | 8  | To be removed  | Tree is Falling within excavation line  |
| 230 | 230 | Naral       | <i>Cocos nucifera</i>           | 3  | 12 | To be removed  | Tree is Falling within excavation line  |
| 231 | 231 | Rain tree   | <i>Samanea saman</i>            | 7  | 35 | To be removed  | Tree is Falling within excavation line  |
| 232 | 232 | Naral       | <i>Cocos nucifera</i>           | 3  | 40 | To be removed  | Tree is Falling within excavation line  |
| 233 | 233 | Fan palm    | <i>Washingtonia robusta</i>     | 2  | 25 | To be removed  | Tree is Falling within excavation line  |
| 234 | 234 | Naral       | <i>Cocos nucifera</i>           | 3  | 46 | To be removed  | Tree is Falling within excavation line  |
| 235 | 235 | Amba        | <i>Mangifera indica</i>         | 3  | 38 | To be removed  | Tree is Falling within excavation line  |
| 236 | 236 | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 8  | 35 | To be retained | Tree is Falling outside excavation line |
| 237 | 237 | Gulmohar    | <i>Delonix regia</i>            | 6  | 40 | To be removed  | Tree is Falling within excavation line  |
| 238 | 238 | Royal Palm  | <i>Roystonea regia</i>          | 2  | 15 | To be removed  | Tree is Falling within excavation line  |
| 239 | 239 | Naral       | <i>Cocos nucifera</i>           | 4  | 10 | To be removed  | Tree is Falling within excavation line  |
| 240 | 240 | Amba        | <i>Mangifera indica</i>         | 1  | 8  | To be removed  | Tree is Falling within excavation line  |
| 241 | 241 | Royal Palm  | <i>Roystonea regia</i>          | 4  | 15 | To be removed  | Tree is Falling within excavation line  |
| 242 | 242 | Deshi Badam | <i>Terminalia catappa</i>       | 2  | 22 | To be removed  | Tree is Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                                |    |    |                |   |
|-----|-----|------------|--------------------------------|----|----|----------------|---|
| 243 | 243 | Royal Palm | <i>Roystonea regia</i>         | 3  | 12 | To be removed  | Tree is Falling within excavation line  |
| 244 | 244 | Sita Ashok | <i>Saraca indica</i>           | 1  | 8  | To be removed  | Tree is Falling within excavation line  |
| 245 | 245 | Naral      | <i>Cocos nucifera</i>          | 3  | 8  | To be removed  | Tree is Falling within excavation line  |
| 246 | 246 | Amba       | <i>Mangifera indica</i>        | 1  | 10 | To be removed  | Tree is Falling within excavation line  |
| 247 | 247 | Royal Palm | <i>Roystonea regia</i>         | 3  | 15 | To be removed  | Tree is Falling within excavation line  |
| 248 | 248 | Royal Palm | <i>Roystonea regia</i>         | 2  | 10 | To be removed  | Tree is Falling within excavation line  |
| 249 | 249 | Royal Palm | <i>Roystonea regia</i>         | 2  | 10 | To be removed  | Tree is Falling within excavation line  |
| 250 | 250 | Royal Palm | <i>Roystonea regia</i>         | 2  | 10 | To be removed  | Tree is Falling within excavation line  |
| 251 | 251 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Tree is Falling within excavation line  |
| 252 | 252 | Pimpal     | <i>Ficus religiosa</i>         | 13 | 52 | To be removed  | Tree is Falling within excavation line  |
| 253 | 253 | Giripushpa | <i>Gliricidia sepium</i>       | 5  | 30 | To be removed  | Tree is Falling within excavation line  |
| 254 | 254 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 7  | 35 | To be removed  | Tree is Falling within excavation line  |
| 255 | 255 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5  | 35 | To be removed  | Tree is Falling within excavation line  |
| 256 | 256 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 38 | To be removed  | Tree is Falling within excavation line  |
| 257 | 257 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5  | 38 | To be removed  | Tree is Falling within excavation line  |
| 258 | 258 | Rain tree  | <i>Samanea saman</i>           | 7  | 50 | To be retained | Tree is Falling outside excavation line |
| 259 | 259 | Gulmohar   | <i>Delonix regia</i>           | 4  | 35 | To be removed  | Tree is Falling within excavation line  |
| 260 | 260 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 25 | To be removed  | Tree is Falling within excavation line  |
| 261 | 261 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 38 | To be removed  | Tree is Falling within excavation line  |
| 262 | 262 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 40 | To be removed  | Tree is Falling within excavation line  |
| 263 | 263 | Pimpal     | <i>Ficus religiosa</i>         | 4  | 25 | To be removed  | Tree is Falling within excavation line  |
| 264 | 264 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 3  | 38 | To be removed  | Tree is Falling within excavation line  |
| 265 | 265 | Vad        | <i>Ficus benghalensis</i>      | 1  | 15 | To be removed  | Tree is Falling within excavation line  |
| 266 | 266 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 40 | To be removed  | Tree is Falling within excavation line  |
| 267 | 267 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 25 | To be removed  | Tree is Falling within excavation line  |
| 268 | 268 | Gulmohar   | <i>Delonix regia</i>           | 8  | 45 | To be retained | Tree is Falling outside excavation line |
| 269 | 269 | Pimpal     | <i>Ficus religiosa</i>         | 18 | 45 | To be removed  | Tree is Falling within excavation line  |
| 270 | 270 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 25 | To be removed  | Tree is Falling within excavation line  |
| 271 | 271 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5  | 25 | To be retained | Tree is Falling outside excavation line |
| 272 | 272 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 25 | To be retained | Tree is Falling outside excavation line |
| 273 | 273 | Bhend      | <i>Thespesia populnea</i>      | 2  | 12 | To be retained | Tree is Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |              |                                |     |    |                |   |
|-----|-----|--------------|--------------------------------|-----|----|----------------|---|
| 274 | 274 | Giripushpa   | <i>Gliricidia sepium</i>       | 2   | 15 | To be removed  | Tree is Falling within excavation line  |
| 275 | 275 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3   | 35 | To be removed  | Tree is Falling within excavation line  |
| 276 | 276 | Desi Badam   | <i>Terminalia catappa</i>      | 2   | 20 | To be removed  | Tree is Falling within excavation line  |
| 277 | 277 | Pimpal       | <i>Ficus religiosa</i>         | 6   | 45 | To be removed  | Tree is Falling within excavation line  |
| 278 | 278 | Jungli badam | <i>Sterculia foetida</i>       | 1   | 25 | To be removed  | Tree is Falling within excavation line  |
| 279 | 279 | Tabebuia     | <i>Tabebuia pentaphylla</i>    | 3   | 30 | To be removed  | Tree is Falling within excavation line  |
| 280 | 280 | Tabebuia     | <i>Tabebuia pentaphylla</i>    | 3   | 30 | To be removed  | Tree is Falling within excavation line  |
| 281 | 281 | Rain tree    | <i>Samanea saman</i>           | 7   | 30 | To be removed  | Tree is Falling within excavation line  |
| 282 | 282 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3   | 40 | To be removed  | Tree is Falling within excavation line  |
| 283 | 283 | Giripushpa   | <i>Gliricidia sepium</i>       | 6   | 40 | To be removed  | Tree is Falling within excavation line  |
| 284 | 284 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3   | 40 | To be removed  | Tree is Falling within excavation line  |
| 285 | 285 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4   | 40 | To be removed  | Tree is Falling within excavation line  |
| 286 | 286 | Giripushpa   | <i>Gliricidia sepium</i>       | 6   | 35 | To be removed  | Tree is Falling within excavation line  |
| 287 | 287 | Giripushpa   | <i>Gliricidia sepium</i>       | 3   | 45 | To be removed  | Tree is Falling within excavation line  |
| 288 | 288 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3   | 43 | To be removed  | Tree is Falling within excavation line  |
| 289 | 289 | Rain tree    | <i>Samanea saman</i>           | 3   | 50 | To be removed  | Tree is Falling within excavation line  |
| 290 | 290 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3   | 45 | To be removed  | Tree is Falling within excavation line  |
| 291 | 291 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3   | 45 | To be removed  | Tree is Falling within excavation line  |
| 292 | 292 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2   | 35 | To be removed  | Tree is Falling within excavation line  |
| 293 | 293 | Rain tree    | <i>Samanea saman</i>           | 7   | 50 | To be removed  | Tree is Falling within excavation line  |
| 294 | 294 | Rain Tree    | <i>Samanea saman</i>           | 7   | 40 | To be removed  | Tree is Falling within excavation line  |
| 295 | 295 | Gulmohar     | <i>Delonix regia</i>           | 1   | 20 | To be retained | Tree is Falling outside excavation line |
| 296 | 296 | Pissonia     | <i>Pissonia alba</i>           | 3   | 20 | To be removed  | Tree is Falling within excavation line  |
| 297 | 297 | Naral        | <i>Cocos Nucifera</i>          | 3.5 | 20 | To be removed  | Tree is Falling within excavation line  |
| 298 | 298 | Jamun        | <i>Syzygium cuminii</i>        | 3   | 30 | To be removed  | Tree is Falling within excavation line  |
| 299 | 299 | Rain Tree    | <i>Samanea saman</i>           | 4.5 | 35 | To be removed  | Tree is Falling within excavation line  |
| 300 | 300 | Gliricidia   | <i>Gliricidia sepium</i>       | 4.5 | 40 | To be removed  | Tree is Falling within excavation line  |
| 301 | 301 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 1   | 15 | To be removed  | Tree is Falling within excavation line  |
| 302 | 302 | Rain tree    | <i>Samanea saman</i>           | 12  | 50 | To be removed  | Tree is Falling within excavation line  |
| 303 | 303 | Gliricidia   | <i>Gliricidia sepium</i>       | 4   | 30 | To be removed  | Tree is Falling within excavation line  |
| 304 | 304 | Sonmohor     | <i>Peltophorum pterocarpum</i> | 5   | 50 | To be removed  | Tree is Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |          |                                |   |    |               |  |
|-----|-----|----------|--------------------------------|---|----|---------------|--|
| 305 | 305 | Sonmohor | <i>Peltophorum pterocarpum</i> | 4 | 35 | To be removed | Tree is Falling within excavation line |
| 306 | 306 | Sonmohor | <i>Peltophorum pterocarpum</i> | 4 | 30 | To be removed | Tree is Falling within excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 96         |
| Trees to be removed  | 210        |
| <b>Total Trees</b>   | <b>306</b> |

| Summary of Tree Survey at Churchgate Station |          |             |                                 |                     |                      |                     |  |
|--|----------|-------------|---------------------------------|---------------------|----------------------|---------------------|--|
| Sr. no.                                      | Tree no. | Common Name | Botanical Name                  | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                                 |
| 1  | 1        | Karanj      | <i>Pongamia pinnata</i>         | 4                   | 33                   | To be removed       | Tree is Falling within excavation line |
| 2  | 2        | Karanj      | <i>Pongamia pinnata</i>         | 3                   | 26                   | To be removed       | Tree is Falling within excavation line |
| 3  | 3        | Karanj      | <i>Pongamia pinnata</i>         | 3                   | 33                   | To be removed       | Tree is Falling within excavation line |
| 4  | 4        | Gulmohar    | <i>Delonix regia</i>            | 3                   | 33                   | To be removed       | Tree is Falling within excavation line |
| 5  | 5        | Karanj      | <i>Pongamia pinnata</i>         | 3                   | 39                   | To be removed       | Tree is Falling within excavation line |
| 6  | 6        | Umber       | <i>Ficus glomerata</i>          | 4"                  | 8                    | To be removed       | Tree is Falling within excavation line |
| 7  | 7        | Pimpal      | <i>Ficus religiosa</i>          | 6                   | 33                   | To be removed       | Tree is Falling within excavation line |
| 8  | 8        | Karanj      | <i>Pongamia pinnata</i>         | 10                  | 26                   | To be removed       | Tree is Falling within excavation line |
| 9  | 9        | Wad         | <i>Ficus benghalensis</i>       | 12                  | 39                   | To be removed       | Tree is Falling within excavation line |
| 10   | 10       | Karanj      | <i>Pongamia pinnata</i>         | 8                   | 33                   | To be removed       | Tree is Falling within excavation line |
| 11   | 11       | Wad         | <i>Ficus benghalensis</i>       | 20                  | 36                   | To be removed       | Tree is Falling within excavation line |
| 12   | 12       | Jackfruit   | <i>Artocarpus heterophyllus</i> | 4                   | 33                   | To be removed       | Tree is Falling within excavation line |
| 13   | 13       | Pimpal      | <i>Ficus religiosa</i>          | 12                  | 39                   | To be removed       | Tree is Falling within excavation line |
| 14   | 14       | Pimpal      | <i>Ficus religiosa</i>          | 12                  | 39                   | To be removed       | Tree is Falling within excavation line |
| 15   | 15       | Wad (Dead)  | <i>Ficus benghalensis</i>       | 5                   | 12                   | To be removed       | Tree is Falling within excavation line |
| 16   | 16       | Wad         | <i>Ficus benghalensis</i>       | 5                   | 39                   | To be removed       | Tree is Falling within excavation line |
| 17   | 17       | Pimpal      | <i>Ficus religiosa</i>          | 10                  | 36                   | To be removed       | Tree is Falling within excavation line |
| 18   | 18       | Wad         | <i>Ficus benghalensis</i>       | 8                   | 46                   | To be removed       | Tree is Falling within excavation line |
| 19   | 19       | Kashid      | <i>Cassia siamea</i>            | 3                   | 25                   | To be removed       | Tree is Falling within excavation line |
| 20   | 20       | Wad         | <i>Ficus benghalensis</i>       | 18                  | 43                   | To be removed       | Tree is Falling within excavation line |
| 21   | 21       | Kashid      | <i>Cassia siamea</i>            | 3                   | 33                   | To be removed       | Tree is Falling within excavation line |
| 22   | 22       | Pimpal      | <i>Ficus religiosa</i>          | 16                  | 46                   | To be removed       | Tree is Falling within excavation line |
| 23   | 23       | Karanj      | <i>Pongamia pinnata</i>         | 7                   | 34                   | To be removed       | Tree is Falling within excavation line |
| 24   | 24       | Umber       | <i>Ficus glomerata</i>          | 5                   | 30                   | To be removed       | Tree is Falling within excavation line |
| 25   | 25       | Sitaphal    | <i>Annona squamosa</i>          | 1                   | 12                   | To be removed       | Tree is Falling within excavation line |
| 26   | 26       | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 1                   | 23                   | To be removed       | Tree is Falling within excavation line |
| 27   | 27       | Amba        | <i>Mangifera indica</i>         | 6"                  | 9                    | To be removed       | Tree is Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |             |                              |    |    |               |  |
|----|----|-------------|------------------------------|----|----|---------------|--|
| 28 | 28 | Sitaphal    | <i>Annona squamosa</i>       | 2  | 13 | To be removed | Tree is Falling within excavation line |
| 29 | 29 | Kala umber  | <i>Ficus hispida</i>         | 2  | 10 | To be removed | Tree is Falling within excavation line |
| 30 | 30 | Gulmohar    | <i>Delonix regia</i>         | 8  | 26 | To be removed | Tree is Falling within excavation line |
| 31 | 31 | Wad         | <i>Ficus benghalensis</i>    | 3  | 33 | To be removed | Tree is Falling within excavation line |
| 32 | 32 | Umbur       | <i>Ficus glomerata</i>       | 2  | 33 | To be removed | Tree is Falling within excavation line |
| 33 | 33 | Putranjiva  | <i>Putranjiva roxburghii</i> | 3  | 39 | To be removed | Tree is Falling within excavation line |
| 34 | 34 | Amba        | <i>Mangifera indica</i>      | 8  | 33 | To be removed | Tree is Falling within excavation line |
| 35 | 35 | Desi badam  | <i>Terminalia catappa</i>    | 2  | 23 | To be removed | Tree is Falling within excavation line |
| 36 | 36 | Pimpal      | <i>Ficus religiosa</i>       | 2  | 23 | To be removed | Tree is Falling within excavation line |
| 37 | 37 | Pimpal      | <i>Ficus religiosa</i>       | 11 | 43 | To be removed | Tree is Falling within excavation line |
| 38 | 38 | Naral       | <i>Cocos nucifera</i>        | 2  | 30 | To be removed | Tree is Falling within excavation line |
| 39 | 39 | Kadamb      | <i>Neolamarckia cadamba</i>  | 2  | 33 | To be removed | Tree is Falling within excavation line |
| 40 | 40 | Pimpal      | <i>Ficus religiosa</i>       | 3  | 39 | To be removed | Tree is Falling within excavation line |
| 41 | 41 | Wad         | <i>Ficus benghalensis</i>    | 2  | 30 | To be removed | Tree is Falling within excavation line |
| 42 | 42 | Kaduneem    | <i>Azadirachta indica</i>    | 2  | 30 | To be removed | Tree is Falling within excavation line |
| 43 | 43 | Nandarukh   | <i>Ficus benjamina</i>       | 2  | 9  | To be removed | Tree is Falling within excavation line |
| 44 | 44 | Desi badam  | <i>Terminalia catappa</i>    | 3  | 30 | To be removed | Tree is Falling within excavation line |
| 45 | 45 | Wad         | <i>Ficus benghalensis</i>    | 28 | 33 | To be removed | Tree is Falling within excavation line |
| 46 | 46 | Desi badam  | <i>Terminalia catappa</i>    | 1  | 26 | To be removed | Tree is Falling within excavation line |
| 47 | 47 | Taman       | <i>Lagerstroemia sps.</i>    | 3  | 20 | To be removed | Tree is Falling within excavation line |
| 48 | 48 | Jambhul     | <i>Syzygium cumini</i>       | 3  | 31 | To be removed | Tree is Falling within excavation line |
| 49 | 49 | Nandarukh   | <i>Ficus benjamina</i>       | 2  | 10 | To be removed | Tree is Falling within excavation line |
| 50 | 50 | Taman       | <i>Lagerstroemia sps.</i>    | 3  | 23 | To be removed | Tree is Falling within excavation line |
| 51 | 51 | Chapha      | <i>Plumeria alba</i>         | 2  | 7  | To be removed | Tree is Falling within excavation line |
| 52 | 52 | Chapha      | <i>Plumeria alba</i>         | 2  | 7  | To be removed | Tree is Falling within excavation line |
| 53 | 53 | Chapha      | <i>Plumeria alba</i>         | 2  | 7  | To be removed | Tree is Falling within excavation line |
| 54 | 54 | Chapha      | <i>Plumeria alba</i>         | 2  | 7  | To be removed | Tree is Falling within excavation line |
| 55 | 55 | Chapha      | <i>Plumeria alba</i>         | 2  | 7  | To be removed | Tree is Falling within excavation line |
| 56 | 56 | Asupalav    | <i>Polyalthia longifolia</i> | 2  | 16 | To be removed | Tree is Falling within excavation line |
| 57 | 57 | Asupalav    | <i>Polyalthia longifolia</i> | 3  | 30 | To be removed | Tree is Falling within excavation line |
| 58 | 58 | Bottle palm | <i>Roystonea regia</i>       | 5  | 39 | To be removed | Tree is Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |             |                                |    |    |                |   |
|----|----|-------------|--------------------------------|----|----|----------------|---|
| 59 | 59 | Desi badam  | <i>Terminalia catappa</i>      | 4  | 30 | To be removed  | Tree is Falling within excavation line  |
| 60 | 60 | Amba        | <i>Mangifera indica</i>        | 3  | 36 | To be removed  | Tree is Falling within excavation line  |
| 61 | 61 | Desi badam  | <i>Terminalia catappa</i>      | 3  | 26 | To be removed  | Tree is Falling within excavation line  |
| 62 | 62 | Desi badam  | <i>Terminalia catappa</i>      | 2  | 20 | To be removed  | Tree is Falling within excavation line  |
| 63 | 63 | Pimpal      | <i>Ficus religiosa</i>         | 16 | 39 | To be removed  | Tree is Falling within excavation line  |
| 64 | 64 | Wad         | <i>Ficus benghalensis</i>      | 11 | 30 | To be removed  | Tree is Falling within excavation line  |
| 65 | 65 | Umber       | <i>Ficus glomerata</i>         | 8  | 30 | To be removed  | Tree is Falling within excavation line  |
| 66 | 66 | Umber       | <i>Ficus glomerata</i>         | 10 | 40 | To be removed  | Tree is Falling within excavation line  |
| 67 | 67 | Umber       | <i>Ficus glomerata</i>         | 8  | 30 | To be removed  | Tree is Falling within excavation line  |
| 68 | 68 | Umbar       | <i>Ficus racemosa</i>          | 3  | 33 | To be retained | Tree is Falling outside excavation line |
| 69 | 69 | Wad         | <i>Ficus benghalensis</i>      | 7  | 33 | To be removed  | Tree is Falling within excavation line  |
| 70 | 70 | Karanj      | <i>Pongamia pinnata</i>        | 2  | 23 | To be removed  | Tree is Falling within excavation line  |
| 71 | 71 | Amba        | <i>Mangifera indica</i>        | 3  | 23 | To be removed  | Tree is Falling within excavation line  |
| 72 | 72 | Suru        | <i>Casurina equisetifolia</i>  | 5  | 43 | To be removed  | Tree is Falling within excavation line  |
| 73 | 73 | Asupalav    | <i>Polyalthia longifolia</i>   | 2  | 23 | To be removed  | Tree is Falling within excavation line  |
| 74 | 74 | Wad         | <i>Ficus benghalensis</i>      | 14 | 39 | To be removed  | Tree is Falling within excavation line  |
| 75 | 75 | Karanj      | <i>Pongamia pinnata</i>        | 3  | 30 | To be removed  | Tree is Falling within excavation line  |
| 76 | 76 | Pimpal      | <i>Ficus religiosa</i>         | 8  | 36 | To be removed  | Tree is Falling within excavation line  |
| 77 | 77 | Wad         | <i>Ficus benghalensis</i>      | 11 | 36 | To be removed  | Tree is Falling within excavation line  |
| 78 | 78 | Pimpal      | <i>Ficus religiosa</i>         | 15 | 36 | To be removed  | Tree is Falling within excavation line  |
| 79 | 79 | Samudraphal | <i>Barringtonia asiatica</i>   | 6  | 26 | To be removed  | Tree is Falling within excavation line  |
| 80 | 80 | Pimpal      | <i>Ficus religiosa</i>         | 20 | 33 | To be removed  | Tree is Falling within excavation line  |
| 81 | 81 | Wad         | <i>Ficus benghalensis</i>      | 7  | 33 | To be removed  | Tree is Falling within excavation line  |
| 82 | 82 | Gulmohar    | <i>Delonix regia</i>           | 2  | 20 | To be removed  | Tree is Falling within excavation line  |
| 83 | 83 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 4  | 36 | To be removed  | Tree is Falling within excavation line  |
| 84 | 84 | Amba        | <i>Mangifera indica</i>        | 2  | 20 | To be removed  | Tree is Falling within excavation line  |
| 85 | 85 | Amba        | <i>Mangifera indica</i>        | 6" | 8  | To be removed  | Tree is Falling within excavation line  |
| 86 | 86 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3  | 36 | To be removed  | Tree is Falling within excavation line  |
| 87 | 87 | Gulmohar    | <i>Delonix regia</i>           | 5  | 25 | To be removed  | Tree is Falling within excavation line  |
| 88 | 88 | Wad         | <i>Ficus benghalensis</i>      | 10 | 8  | To be removed  | Tree is Falling within excavation line  |
| 89 | 89 | Gulmohar    | <i>Delonix regia</i>           | 4  | 33 | To be removed  | Tree is Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                |    |      |                |   |
|-----|-----|---------------|--------------------------------|----|------|----------------|---|
| 90  | 90  | Wad           | <i>Ficus benghalensis</i>      | 8  | 36   | To be removed  | Tree is Falling within excavation line  |
| 91  | 91  | Samudraphal   | <i>Parkia biglandulosa</i>     | 6" | 8    | To be removed  | Tree is Falling within excavation line  |
| 92  | 92  | Karanj        | <i>Pongamia pinnata</i>        | 3  | 23   | To be removed  | Tree is Falling within excavation line  |
| 93  | 93  | Gulmohar      | <i>Delonix regia</i>           | 3  | 23   | To be removed  | Tree is Falling within excavation line  |
| 94  | 94  | Karanj        | <i>Pongamia pinnata</i>        | 3  | 33   | To be removed  | Tree is Falling within excavation line  |
| 95  | 95  | Pimpal        | <i>Ficus religiosa</i>         | 10 | 39   | To be removed  | Tree is Falling within excavation line  |
| 96  | 96  | Amba          | <i>Mangifera indica</i>        | 3  | 23   | To be removed  | Tree is Falling within excavation line  |
| 97  | 97  | Mango         | <i>Mangifera indica</i>        | 3  | 36   | To be removed  | Tree is Falling within excavation line  |
| 98  | 98  | Sonmohar      | <i>Peltophorum pterocarpum</i> | 10 | 39   | To be removed  | Tree is Falling within excavation line  |
| 99  | 99  | Naral         | <i>Cocos nucifera</i>          | 3  | 18   | To be retained | Tree is Falling outside excavation line |
| 100 | 100 | Royal Palm    | <i>Roystonea regia</i>         | 6  | 27   | To be retained | Tree is Falling outside excavation line |
| 101 | 101 | Jungali Badam | <i>Sterculia foetida</i>       | 6  | 24   | To be retained | Tree is Falling outside excavation line |
| 102 | 102 | Royal Palm    | <i>Roystonea regia</i>         | 6  | 21   | To be retained | Tree is Falling outside excavation line |
| 103 | 103 | Jungali Badam | <i>Sterculia foetida</i>       | 6  | 30   | To be retained | Tree is Falling outside excavation line |
| 104 | 104 | Jungali Badam | <i>Sterculia foetida</i>       | 6  | 30   | To be retained | Tree is Falling outside excavation line |
| 105 | 105 | Royal Palm    | <i>Roystonea regia</i>         | 8  | 21   | To be retained | Tree is Falling outside excavation line |
| 106 | 106 | Royal Palm    | <i>Roystonea regia</i>         | 8  | 21   | To be retained | Tree is Falling outside excavation line |
| 107 | 107 | Royal Palm    | <i>Roystonea regia</i>         | 9  | 36   | To be retained | Tree is Falling outside excavation line |
| 108 | 108 | Naral         | <i>Cocos nucifera</i>          | 3  | 18   | To be retained | Tree is Falling outside excavation line |
| 109 | 109 | Naral         | <i>Cocos nucifera</i>          | 7  | 45   | To be retained | Tree is Falling outside excavation line |
| 110 | 110 | Naral         | <i>Cocos nucifera</i>          | 3  | 18   | To be retained | Tree is Falling outside excavation line |
| 111 | 111 | Asupalav      | <i>Polyalthia longifolia</i>   | 1  | 10.5 | To be retained | Tree is Falling outside excavation line |
| 112 | 112 | Naral         | <i>Cocos nucifera</i>          | 6  | 24   | To be retained | Tree is Falling outside excavation line |
| 113 | 113 | Royal Palm    | <i>Roystonea regia</i>         | 8  | 30   | To be retained | Tree is Falling outside excavation line |
| 114 | 114 | Royal Palm    | <i>Roystonea regia</i>         | 8  | 30   | To be retained | Tree is Falling outside excavation line |
| 115 | 115 | Naral         | <i>Cocos nucifera</i>          | 5  | 21   | To be retained | Tree is Falling outside excavation line |
| 116 | 116 | Royal Palm    | <i>Roystonea regia</i>         | 8  | 24   | To be retained | Tree is Falling outside excavation line |
| 117 | 117 | Naral         | <i>Cocos nucifera</i>          | 4  | 18   | To be retained | Tree is Falling outside excavation line |
| 118 | 118 | Royal Palm    | <i>Roystonea regia</i>         | 7  | 24   | To be retained | Tree is Falling outside excavation line |
| 119 | 119 | Naral         | <i>Cocos nucifera</i>          | 5  | 27   | To be retained | Tree is Falling outside excavation line |
| 120 | 120 | Royal Palm    | <i>Roystonea regia</i>         | 7  | 27   | To be retained | Tree is Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                              |    |    |                |   |
|-----|-----|---------------|------------------------------|----|----|----------------|---|
| 121 | 121 | Royal Palm    | <i>Roystonea regia</i>       | 7  | 27 | To be retained | Tree is Falling outside excavation line |
| 122 | 122 | Royal Palm    | <i>Roystonea regia</i>       | 7  | 24 | To be retained | Tree is Falling outside excavation line |
| 123 | 123 | Royal Palm    | <i>Roystonea regia</i>       | 5  | 18 | To be retained | Tree is Falling outside excavation line |
| 124 | 124 | Royal Palm    | <i>Roystonea regia</i>       | 7  | 24 | To be retained | Tree is Falling outside excavation line |
| 125 | 125 | Naral         | <i>Cocos nucifera</i>        | 6  | 36 | To be retained | Tree is Falling outside excavation line |
| 126 | 126 | Royal Palm    | <i>Roystonea regia</i>       | 8  | 30 | To be retained | Tree is Falling outside excavation line |
| 127 | 127 | Naral         | <i>Cocos nucifera</i>        | 5  | 36 | To be retained | Tree is Falling outside excavation line |
| 128 | 128 | Royal Palm    | <i>Roystonea regia</i>       | 6  | 21 | To be retained | Tree is Falling outside excavation line |
| 129 | 129 | Jambhul       | <i>Syzigium cumini</i>       | 9  | 36 | To be retained | Tree is Falling outside excavation line |
| 130 | 130 | Deshi Badam   | <i>Terminalia catappa</i>    | 9  | 30 | To be retained | Tree is Falling outside excavation line |
| 131 | 131 | Naral         | <i>Cocos nucifera</i>        | 3  | 18 | To be retained | Tree is Falling outside excavation line |
| 132 | 132 | Royal Palm    | <i>Roystonea regia</i>       | 8  | 27 | To be retained | Tree is Falling outside excavation line |
| 133 | 133 | Amba          | <i>Mangifera indica</i>      | 6  | 27 | To be retained | Tree is Falling outside excavation line |
| 134 | 134 | Royal Palm    | <i>Roystonea regia</i>       | 2  | 12 | To be retained | Tree is Falling outside excavation line |
| 135 | 135 | Royal Palm    | <i>Roystonea regia</i>       | 7  | 30 | To be retained | Tree is Falling outside excavation line |
| 136 | 136 | Royal Palm    | <i>Roystonea regia</i>       | 8  | 36 | To be retained | Tree is Falling outside excavation line |
| 137 | 137 | Deshi Badam   | <i>Terminalia catappa</i>    | 6  | 30 | To be retained | Tree is Falling outside excavation line |
| 138 | 138 | Jungali Badam | <i>Sterculia foetida</i>     | 8  | 36 | To be retained | Tree is Falling outside excavation line |
| 139 | 139 | Naral         | <i>Cocos nucifera</i>        | 5  | 27 | To be retained | Tree is Falling outside excavation line |
| 140 | 140 | Amba          | <i>Mangifera indica</i>      | 13 | 36 | To be retained | Tree is Falling outside excavation line |
| 141 | 141 | Asupalav      | <i>Polyalthia longifolia</i> | 3  | 18 | To be retained | Tree is Falling outside excavation line |
| 142 | 142 | Shevaga       | <i>Moringa oleifera</i>      | 3  | 30 | To be retained | Tree is Falling outside excavation line |
| 143 | 143 | Royal Palm    | <i>Roystonea regia</i>       | 7  | 36 | To be retained | Tree is Falling outside excavation line |
| 144 | 144 | Naral         | <i>Cocos nucifera</i>        | 6  | 30 | To be retained | Tree is Falling outside excavation line |
| 145 | 145 | Naral         | <i>Cocos nucifera</i>        | 7  | 39 | To be retained | Tree is Falling outside excavation line |
| 146 | 146 | Naral         | <i>Cocos nucifera</i>        | 6  | 27 | To be retained | Tree is Falling outside excavation line |
| 147 | 147 | Naral         | <i>Cocos nucifera</i>        | 4  | 54 | To be retained | Tree is Falling outside excavation line |
| 148 | 148 | Royal Palm    | <i>Roystonea regia</i>       | 2  | 15 | To be retained | Tree is Falling outside excavation line |
| 149 | 149 | Amba          | <i>Mangifera indica</i>      | 5  | 30 | To be retained | Tree is Falling outside excavation line |
| 150 | 150 | Amba          | <i>Mangifera indica</i>      | 12 | 36 | To be retained | Tree is Falling outside excavation line |
| 151 | 151 | Karanj        | <i>Pongamia pinnata</i>      | 9  | 42 | To be retained | Tree is Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                                |    |    |                |   |
|-----|-----|------------|--------------------------------|----|----|----------------|---|
| 152 | 152 | Naral      | <i>Cocos nucifera</i>          | 8  | 54 | To be retained | Tree is Falling outside excavation line |
| 153 | 153 | Shindi     | <i>Phoenix sylvestris</i>      | 3  | 36 | To be retained | Tree is Falling outside excavation line |
| 154 | 154 | Asupalav   | <i>Polyalthia longifolia</i>   | 3  | 30 | To be retained | Tree is Falling outside excavation line |
| 155 | 155 | Wad        | <i>Ficus benghalensis</i>      | 24 | 45 | To be retained | Tree is Falling outside excavation line |
| 156 | 156 | Asupalav   | <i>Polyalthia longifolia</i>   | 1  | 12 | To be retained | Tree is Falling outside excavation line |
| 157 | 157 | Asupalav   | <i>Polyalthia longifolia</i>   | 6  | 36 | To be removed  | Tree is Falling within excavation line  |
| 158 | 158 | Amba       | <i>Mangifera indica</i>        | 1  | 12 | To be retained | Tree is Falling outside excavation line |
| 159 | 159 | Kaduneem   | <i>Azadirachta indica</i>      | 1  | 18 | To be retained | Tree is Falling outside excavation line |
| 160 | 160 | Asupalav   | <i>Polyalthia longifolia</i>   | 7  | 30 | To be retained | Tree is Falling outside excavation line |
| 161 | 161 | Naral      | <i>Cocos nucifera</i>          | 6  | 42 | To be retained | Tree is Falling outside excavation line |
| 162 | 162 | Pimpal     | <i>Ficus religiosa</i>         | 3  | 30 | To be retained | Tree is Falling outside excavation line |
| 163 | 163 | Umbar      | <i>Ficus glomerata</i>         | 8  | 36 | To be retained | Tree is Falling outside excavation line |
| 164 | 164 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5  | 30 | To be retained | Tree is Falling outside excavation line |
| 165 | 165 | Naral      | <i>Cocos nucifera</i>          | 3  | 18 | To be retained | Tree is Falling outside excavation line |
| 166 | 166 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 6" | 12 | To be retained | Tree is Falling outside excavation line |
| 167 | 167 | Royal Palm | <i>Roystonea regia</i>         | 9  | 36 | To be retained | Tree is Falling outside excavation line |
| 168 | 168 | Asupalav   | <i>Polyalthia longifolia</i>   | 2  | 18 | To be retained | Tree is Falling outside excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 70         |
| Trees to be removed  | 98         |
| <b>Total Trees</b>   | <b>168</b> |

| Summary of Tree Survey at Hutatma Chowk Station |          |              |                                |                     |                      |                     |                                      |
|---|----------|--------------|--------------------------------|---------------------|----------------------|---------------------|--------------------------------------|
| Sr. no.   | Tree no. | Common Name  | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                               |
| 1   | 1        | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4                   | 30                   | To be retained      | Tree Falling outside excavation line |
| 2   | 2        | Mahogany     | <i>Swietenia mahagoni</i>      | 6"                  | 11                   | To be retained      | Tree Falling outside excavation line |
| 3   | 3        | Aus. Babhul  | <i>Acacia auriculiformis</i>   | 10"                 | 12                   | To be retained      | Tree Falling outside excavation line |
| 4   | 4        | Mahogani     | <i>Sweitenia mahogoni</i>      | 6"                  | 10                   | To be retained      | Tree Falling outside excavation line |
| 5   | 5        | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3                   | 30                   | To be retained      | Tree Falling outside excavation line |
| 6   | 6        | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2                   | 30                   | To be retained      | Tree Falling outside excavation line |
| 7   | 7        | Sonmohar     | <i>Peltophorum pterocarpum</i> | 10"                 | 20                   | To be removed       | Tree Falling within excavation line  |
| 8   | 8        | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2                   | 30                   | To be removed       | Tree Falling within excavation line  |
| 9   | 9        | Karanj       | <i>Pongamia pinnata</i>        | 5                   | 30                   | To be removed       | Tree Falling within excavation line  |
| 10  | 10       | Sonmohar     | <i>Peltophorum pterocarpum</i> | 1                   | 15                   | To be removed       | Tree Falling within excavation line  |
| 11  | 11       | Karanj       | <i>Pongamia pinnata</i>        | 10"                 | 12                   | To be removed       | Tree Falling within excavation line  |
| 12  | 12       | Markhamia    | <i>Markhamia platycalyx</i>    | 10"                 | 12                   | To be removed       | Tree Falling within excavation line  |
| 13  | 13       | Markhamia    | <i>Markhamia platycalyx</i>    | 10"                 | 12                   | To be removed       | Tree Falling within excavation line  |
| 14  | 14       | Karanj       | <i>Pongamia pinnata</i>        | 8"                  | 10                   | To be removed       | Tree Falling within excavation line  |
| 15  | 15       | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5                   | 40                   | To be removed       | Tree Falling within excavation line  |
| 16  | 16       | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3                   | 25                   | To be removed       | Tree Falling within excavation line  |
| 17  | 17       | Markhamia    | <i>Markhamia platycalyx</i>    | 10"                 | 12                   | To be removed       | Tree Falling within excavation line  |
| 18  | 18       | Markhamia    | <i>Markhamia platycalyx</i>    | 10"                 | 12                   | To be removed       | Tree Falling within excavation line  |
| 19  | 19       | Markhamia    | <i>Markhamia platycalyx</i>    | 6"                  | 8                    | To be removed       | Tree Falling within excavation line  |
| 20  | 20       | Markhamia    | <i>Markhamia platycalyx</i>    | 4"                  | 8                    | To be removed       | Tree Falling within excavation line  |
| 21  | 21       | Markhamia    | <i>Markhamia platycalyx</i>    | 8"                  | 8                    | To be removed       | Tree Falling within excavation line  |
| 22  | 22       | Markhamia    | <i>Markhamia platycalyx</i>    | 8"                  | 10                   | To be removed       | Tree Falling within excavation line  |
| 23  | 23       | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6                   | 30                   | To be removed       | Tree Falling within excavation line  |
| 24  | 24       | Mahogani     | <i>Sweitenia mahogoni</i>      | 5"                  | 6                    | To be removed       | Tree Falling within excavation line  |
| 25  | 25       | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5                   | 35                   | To be removed       | Tree Falling within excavation line  |
| 26  | 26       | Jungli Badam | <i>Terminalia cattapa</i>      | 3                   | 35                   | To be removed       | Tree Falling within excavation line  |
| 27  | 27       | Saptaparni   | <i>Alstonia scholaris</i>      | 1                   | 10                   | To be removed       | Tree Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |                  |                                |     |    |               |                                     |
|----|----|------------------|--------------------------------|-----|----|---------------|-------------------------------------|
| 28 | 28 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 6   | 30 | To be removed | Tree Falling within excavation line |
| 29 | 29 | Wad              | <i>Ficus benghalensis</i>      | 2   | 25 | To be removed | Tree Falling within excavation line |
| 30 | 30 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 1   | 15 | To be removed | Tree Falling within excavation line |
| 31 | 31 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 3   | 28 | To be removed | Tree Falling within excavation line |
| 32 | 32 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 6   | 40 | To be removed | Tree Falling within excavation line |
| 33 | 33 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed | Tree Falling within excavation line |
| 34 | 34 | Pimpal           | <i>Ficus religiosa</i>         | 6   | 40 | To be removed | Tree Falling within excavation line |
| 35 | 35 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 4   | 40 | To be removed | Tree Falling within excavation line |
| 36 | 36 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 4   | 40 | To be removed | Tree Falling within excavation line |
| 37 | 37 | Jungli badam     | <i>Sterculia foetida</i>       | 3   | 30 | To be removed | Tree Falling within excavation line |
| 38 | 38 | Gulmohar         | <i>Delonix regia</i>           | 6   | 40 | To be removed | Tree Falling within excavation line |
| 39 | 39 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 2.5 | 23 | To be removed | Tree Falling within excavation line |
| 40 | 40 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 3   | 25 | To be removed | Tree Falling within excavation line |
| 41 | 41 | Jungli Badam     | <i>Sterculia foetida</i>       | 2   | 30 | To be removed | Tree Falling within excavation line |
| 42 | 42 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 6"  | 10 | To be removed | Tree Falling within excavation line |
| 43 | 43 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 3   | 25 | To be removed | Tree Falling within excavation line |
| 44 | 44 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 3   | 30 | To be removed | Tree Falling within excavation line |
| 45 | 45 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 1.5 | 20 | To be removed | Tree Falling within excavation line |
| 46 | 46 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 1   | 5  | To be removed | Tree Falling within excavation line |
| 47 | 47 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 3   | 30 | To be removed | Tree Falling within excavation line |
| 48 | 48 | Australian Babul | <i>Acacia auriculiformis</i>   | 6"  | 10 | To be removed | Tree Falling within excavation line |
| 49 | 49 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 2   | 25 | To be removed | Tree Falling within excavation line |
| 50 | 50 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 2   | 25 | To be removed | Tree Falling within excavation line |
| 51 | 51 | Rain Tree        | <i>Samanea saman</i>           | 2   | 15 | To be removed | Tree Falling within excavation line |
| 52 | 52 | Gulmohar         | <i>Delonix regia</i>           | 1.5 | 15 | To be removed | Tree Falling within excavation line |
| 53 | 53 | Wad              | <i>Ficus benghalensis</i>      | 20  | 43 | To be removed | Tree Falling within excavation line |
| 54 | 54 | Asupalav         | <i>Peltophorum pterocarpum</i> | 3   | 23 | To be removed | Tree Falling within excavation line |
| 55 | 55 | Pimpal           | <i>Ficus religiosa</i>         | 8   | 50 | To be removed | Tree Falling within excavation line |
| 56 | 56 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 6   | 25 | To be removed | Tree Falling within excavation line |
| 57 | 57 | Gulmohar         | <i>Delonix Regia</i>           | 6"  | 20 | To be removed | Tree Falling within excavation line |
| 58 | 58 | Sonmohar         | <i>Peltophorum pterocarpum</i> | 5   | 25 | To be removed | Tree Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |              |                                   |    |    |                |                                      |
|----|----|--------------|-----------------------------------|----|----|----------------|--------------------------------------|
| 59 | 59 | Wad          | <i>Ficus benghalensis</i>         | 10 | 36 | To be removed  | Tree Falling within excavation line  |
| 60 | 60 | Lettuce tree | <i>Pisonia alba</i>               | 3  | 20 | To be removed  | Tree Falling within excavation line  |
| 61 | 61 | Nandarukh    | <i>Ficus benjamina</i>            | 1  | 10 | To be removed  | Tree Falling within excavation line  |
| 62 | 62 | Lettuce tree | <i>Pisonia alba</i>               | 1  | 13 | To be removed  | Tree Falling within excavation line  |
| 63 | 63 | Asupalav     | <i>Polyalthia longifolia</i>      | 1  | 10 | To be removed  | Tree Falling within excavation line  |
| 64 | 64 | Nandarukh    | <i>Ficus benjamina</i>            | 1  | 10 | To be removed  | Tree Falling within excavation line  |
| 65 | 65 | Nandarukh    | <i>Ficus benjamina</i>            | 2  | 16 | To be removed  | Tree Falling within excavation line  |
| 66 | 66 | Phanas       | <i>Atrocarpus integrifolia</i>    | 3  | 36 | To be removed  | Tree Falling within excavation line  |
| 67 | 67 | X-mas tree   | <i>Aruacaria columnaris</i>       | 6" | 10 | To be removed  | Tree Falling within excavation line  |
| 68 | 68 | Fan palm     | <i>Washingtonia filifera</i>      | 3  | 10 | To be removed  | Tree Falling within excavation line  |
| 69 | 69 | Fan palm     | <i>Washingtonia filifera</i>      | 3  | 10 | To be removed  | Tree Falling within excavation line  |
| 70 | 70 | Nandarukh    | <i>Ficus benjamina</i>            | 1  | 14 | To be removed  | Tree Falling within excavation line  |
| 71 | 71 | Asupalav     | <i>Polyalthia longifolia</i>      | 1  | 13 | To be removed  | Tree Falling within excavation line  |
| 72 | 72 | Areca palm   | <i>Chrysalidocarpus lutescens</i> | 6" | 16 | To be removed  | Tree Falling within excavation line  |
| 73 | 73 | Jambhul      | <i>Syzygium cumini</i>            | 4" | 10 | To be removed  | Tree Falling within excavation line  |
| 74 | 74 | Pimpal       | <i>Ficus religiosa</i>            | 15 | 40 | To be retained | Tree Falling outside excavation line |
| 75 | 75 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 3  | 35 | To be retained | Tree Falling outside excavation line |
| 76 | 76 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 4  | 35 | To be retained | Tree Falling outside excavation line |
| 77 | 77 | Wad          | <i>Ficus benghalensis</i>         | 8  | 35 | To be retained | Tree Falling outside excavation line |
| 78 | 78 | Motiphoh     |                                   | 5  | 35 | To be removed  | Tree Falling within excavation line  |
| 79 | 79 | Wad          | <i>Ficus benghalensis</i>         | 18 | 40 | To be removed  | Tree Falling within excavation line  |
| 80 | 80 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 6  | 35 | To be removed  | Tree Falling within excavation line  |
| 81 | 81 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 4  | 35 | To be removed  | Tree Falling within excavation line  |
| 82 | 82 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 3  | 35 | To be removed  | Tree Falling within excavation line  |
| 83 | 83 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 3  | 35 | To be removed  | Tree Falling within excavation line  |
| 84 | 84 | Wad ( dead)  | <i>Ficus benghalensis</i>         | 4  | 12 | To be removed  | Tree Falling within excavation line  |
| 85 | 85 | Bhend        | <i>Thespesia populnea</i>         | 4  | 30 | To be removed  | Tree Falling within excavation line  |
| 86 | 86 | Bhend        | <i>Thespesia populnea</i>         | 3  | 30 | To be removed  | Tree Falling within excavation line  |
| 87 | 87 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 3  | 26 | To be removed  | Tree Falling within excavation line  |
| 88 | 88 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 3  | 26 | To be removed  | Tree Falling within excavation line  |
| 89 | 89 | Sonmohar     | <i>Peltophorum pterocarpum</i>    | 4  | 33 | To be removed  | Tree Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                                 |    |    |               |                                     |
|-----|-----|------------|---------------------------------|----|----|---------------|-------------------------------------|
| 90  | 90  | Wad        | <i>Ficus benghalensis</i>       | 18 | 43 | To be removed | Tree Falling within excavation line |
| 91  | 91  | Bhend      | <i>Thespesia populnea</i>       | 3  | 15 | To be removed | Tree Falling within excavation line |
| 92  | 92  | Royal palm | <i>Roystonea regia</i>          | 5  | 30 | To be removed | Tree Falling within excavation line |
| 93  | 93  | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 3  | 26 | To be removed | Tree Falling within excavation line |
| 94  | 94  | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 3  | 33 | To be removed | Tree Falling within excavation line |
| 95  | 95  | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 3  | 30 | To be removed | Tree Falling within excavation line |
| 96  | 96  | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 3  | 30 | To be removed | Tree Falling within excavation line |
| 97  | 97  | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 4  | 30 | To be removed | Tree Falling within excavation line |
| 98  | 98  | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 4  | 33 | To be removed | Tree Falling within excavation line |
| 99  | 99  | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 5  | 30 | To be removed | Tree Falling within excavation line |
| 100 | 100 | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 3  | 30 | To be removed | Tree Falling within excavation line |
| 101 | 101 | Royal palm | <i>Roystonea regia</i>          | 3  | 16 | To be removed | Tree Falling within excavation line |
| 102 | 102 | Royal palm | <i>Roystonea regia</i>          | 3  | 23 | To be removed | Tree Falling within excavation line |
| 103 | 103 | Royal palm | <i>Roystonea regia</i>          | 4  | 33 | To be removed | Tree Falling within excavation line |
| 104 | 104 | Suru       | <i>Casuarina equisetifolia</i>  | 1  | 5  | To be removed | Tree Falling within excavation line |
| 105 | 105 | Royal palm | <i>Roystonea regia</i>          | 3  | 26 | To be removed | Tree Falling within excavation line |
| 106 | 106 | Suru       | <i>Casuarina equisetifolia</i>  | 1  | 5  | To be removed | Tree Falling within excavation line |
| 107 | 107 | Royal palm | <i>Roystonea regia</i>          | 3  | 26 | To be removed | Tree Falling within excavation line |
| 108 | 108 | Royal palm | <i>Roystonea regia</i>          | 3  | 23 | To be removed | Tree Falling within excavation line |
| 109 | 109 | Royal palm | <i>Roystonea regia</i>          | 4  | 23 | To be removed | Tree Falling within excavation line |
| 110 | 110 | Royal palm | <i>Roystonea regia</i>          | 3  | 25 | To be removed | Tree Falling within excavation line |
| 111 | 111 | Royal palm | <i>Roystonea regia</i>          | 4  | 30 | To be removed | Tree Falling within excavation line |
| 112 | 112 | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 1  | 30 | To be removed | Tree Falling within excavation line |
| 113 | 113 | Royal palm | <i>Roystonea regia</i>          | 4  | 52 | To be removed | Tree Falling within excavation line |
| 114 | 114 | Pimpal     | <i>Ficus religiosa</i>          | 6  | 39 | To be removed | Tree Falling within excavation line |
| 115 | 115 | Asupalav   | <i>Polyalthia longifolia</i>    | 3  | 30 | To be removed | Tree Falling within excavation line |
| 116 | 116 | Royal palm | <i>Roystonea regia</i>          | 5  | 52 | To be removed | Tree Falling within excavation line |
| 117 | 117 | Phanas     | <i>Artocarpus heterophyllus</i> | 3  | 36 | To be removed | Tree Falling within excavation line |
| 118 | 118 | Sonmohar   | <i>Peltophorum pterocarpum</i>  | 6  | 36 | To be removed | Tree Falling within excavation line |
| 119 | 119 | Pisonia    | <i>Pisonia alba</i>             | 1  | 15 | To be removed | Tree Falling within excavation line |
| 120 | 120 | Wad(Dead)  | <i>Ficus benghalensis</i>       | 2  | 26 | To be removed | Tree Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |             |                                |    |    |                |                                      |
|-----|-----|-------------|--------------------------------|----|----|----------------|--------------------------------------|
| 121 | 121 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 4  | 30 | To be removed  | Tree Falling within excavation line  |
| 122 | 122 | Pimpal      | <i>Ficus religiosa</i>         | 12 | 46 | To be removed  | Tree Falling within excavation line  |
| 123 | 123 | Pichkari    | <i>Spathodea campanulata</i>   | 1  | 20 | To be removed  | Tree Falling within excavation line  |
| 124 | 124 | Mahogani    | <i>Sweitenia mahogoni</i>      | 1  | 20 | To be removed  | Tree Falling within excavation line  |
| 125 | 125 | Gulmohar    | <i>Delonix regia</i>           | 3  | 33 | To be removed  | Tree Falling within excavation line  |
| 126 | 126 | Deshi badam | <i>Terminalia cattapa</i>      | 1  | 20 | To be removed  | Tree Falling within excavation line  |
| 127 | 127 | Putranjiva  | <i>Putranjiva roxburghii</i>   | 3  | 39 | To be removed  | Tree Falling within excavation line  |
| 128 | 128 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 2  | 30 | To be removed  | Tree Falling within excavation line  |
| 129 | 129 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Tree Falling within excavation line  |
| 130 | 130 | Deshi badam | <i>Terminalia cattapa</i>      | 1  | 15 | To be removed  | Tree Falling within excavation line  |
| 131 | 131 | Giripushpa  | <i>Gliricidia sepium</i>       | 10 | 15 | To be retained | Tree Falling outside excavation line |
| 132 | 132 | Rain Tree   | <i>Samanea saman</i>           | 4  | 30 | To be removed  | Tree Falling within excavation line  |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 11         |
| Trees to be removed  | 121        |
| <b>Total Trees</b>   | <b>132</b> |



| Summary of Tree Survey at Tunnel Operation Shaft |          |             |                            |                     |                      |                     |                                     |
|--|----------|-------------|----------------------------|---------------------|----------------------|---------------------|-------------------------------------|
| Sr. no.  | Tree no. | Common Name | Botanical Name             | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                              |
| 1  | 1        | Pimpal      | <i>Ficus religiosa</i>     | 3'5"                | 25'-30'              | To be removed       | Tree Falling within excavation line |
| 2  | 2        | Bor         | <i>Ziziphus mauritiana</i> | 4'                  | 30'-35'              | To be removed       | Tree Falling within excavation line |
| 3  | 3        | Mango       | <i>Mangifera indica</i>    | 2'5"                | 30'-35'              | To be removed       | Tree Falling within excavation line |
| 4  | 4        | Pimpal      | <i>Ficus religiosa</i>     | 7'5"                | 35'-40'              | To be removed       | Tree Falling within excavation line |
| 5  | 5        | Pimpal      | <i>Ficus religiosa</i>     | 4'                  | 35'-40'              | To be removed       | Tree Falling within excavation line |
| 6  | 6        | Pimpal      | <i>Ficus religiosa</i>     | 8'5"                | 35'-40'              | To be removed       | Tree Falling within excavation line |
| 7  | 7        | Pimpal      | <i>Ficus religiosa</i>     | 4'5"                | 35'-40'              | To be removed       | Tree Falling within excavation line |
| 8  | 8        | Wad         | <i>Ficus benghalensis</i>  | 18'                 | 35'-40'              | To be removed       | Tree Falling within excavation line |

|                      |          |
|----------------------|----------|
| Trees to be Retained | 0        |
| Trees to be removed  | 8        |
| <b>Total Trees</b>   | <b>8</b> |

**2. TREE INVENTORY DETAILS AT UGC-02**

| Summary of Tree Survey at CST Station |          |              |                              |                     |                      |                     |                                |
|---------------------------------------|----------|--------------|------------------------------|---------------------|----------------------|---------------------|--------------------------------|
| Sr. no.                               | Tree no. | Common Name  | Botanical Name               | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                         |
| 1                                     | 1        | Pichkari     | <i>Spathodea campanulata</i> | 4'-6'               | 20'-22'              | To be removed       | Falling within Excavation area |
| 2                                     | 2        | Karanj       | <i>Pongamia Pinnata</i>      | 4"-6"               | 10'-12'              | To be removed       | Falling within Excavation area |
| 3                                     | 3        | Umbar        | <i>Ficus Racemosa</i>        | 6"-8"               | 8'-10'               | To be removed       | Falling within Excavation area |
| 4                                     | 4        | Jungli Badam | <i>Sterculia foetida</i>     | 9"-12"              | 15'-17'              | To be removed       | Falling within Excavation area |
| 5                                     | 5        | Jungli Badam | <i>Sterculia foetida</i>     | 9"-12"              | 12'-14'              | To be removed       | Falling within Excavation area |
| 6                                     | 6        | Subabhul     | <i>Leucaena Leucocephala</i> | 4"-6"               | 9'-12'               | To be removed       | Falling within Excavation area |
| 7                                     | 7        | Jungli Badam | <i>Sterculia foetida</i>     | 1'-2'               | 15'-20'              | To be removed       | Falling within Excavation area |
| 8                                     | 8        | Jungli Badam | <i>Sterculia foetida</i>     | 1'-2'               | 15'-20'              | To be removed       | Falling within Excavation area |
| 9                                     | 9        | Jungli Badam | <i>Sterculia foetida</i>     | 6"-8"               | 10'-12'              | To be removed       | Falling within Excavation area |
| 10                                    | 10       | Subabhul     | <i>Leucaena Leucocephala</i> | 1'-2'               | 12'-14'              | To be removed       | Falling within Excavation area |
| 11                                    | 11       | Jungli Badam | <i>Sterculia foetida</i>     | 1'-2'               | 15'-20'              | To be removed       | Falling within Excavation area |
| 12                                    | 12       | Asupalav     | <i>Polyalthia longifolia</i> | 1'-2'               | 12'-14'              | To be removed       | Falling within Excavation area |
| 13                                    | 13       | Asupalav     | <i>Polyalthia longifolia</i> | 6'-8'               | 10'-12'              | To be removed       | Falling within Excavation area |
| 14                                    | 14       | Anant        | <i>Gardenia jasminoides</i>  | 6"-8"               | 8'-10'               | To be removed       | Falling within Excavation area |
| 15                                    | 15       | Lettuce tree | <i>Pisonia alba</i>          | 6"-8"               | 6'-8'                | To be removed       | Falling within Excavation area |
| 16                                    | 15A      | Asupalav     | <i>Polyalthia longifolia</i> | 6"                  | 10                   | To be removed       | Falling within Excavation area |
| 17                                    | 16       | Mango        | <i>Mangifera Indica</i>      | 3'-4'               | 20'-22'              | To be removed       | Falling within Excavation area |
| 18                                    | 17       | Peru(Dead)   | <i>Psidium guajava</i>       | 1'-2'               | 12'-14'              | To be removed       | Falling within Excavation area |
| 19                                    | 18       | Mango        | <i>Mangifera Indica</i>      | 1'-2'               | 15'-18'              | To be removed       | Falling within Excavation area |
| 20                                    | 19       | Peru         | <i>Psidium guajava</i>       | 6"-8"               | 7'-9'                | To be removed       | Falling within Excavation area |
| 21                                    | 20       | Peru         | <i>Psidium guajava</i>       | 6"-8"               | 7'-9'                | To be removed       | Falling within Excavation area |
| 22                                    | 21       | Peru         | <i>Psidium guajava</i>       | 1'-2'               | 14-16'               | To be removed       | Falling within Excavation area |
| 23                                    | 22       | Neem         | <i>Azadirachta indica</i>    | 6"-8"               | 10'-12'              | To be removed       | Falling within Excavation area |
| 24                                    | 23       | Naral        | <i>Cocos nucifera</i>        | 4'-6'               | 25'-25'              | To be removed       | Falling within Excavation area |
| 25                                    | 24       | Deshi Badam  | <i>Terminalia cattapa</i>    | 3'-5'               | 20'-22'              | To be removed       | Falling within Excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |                       |                                    |         |         |                |                                 |
|----|----|-----------------------|------------------------------------|---------|---------|----------------|---------------------------------|
| 26 | 25 | Deshi Badam           | <i>Terminalia cattapa</i>          | 2'-3'   | 20'-22' | To be removed  | Falling within Excavation area  |
| 27 | 26 | Peru                  | <i>Psidium guajava</i>             | 9"-11"  | 8'-10'  | To be removed  | Falling within Excavation area  |
| 28 | 27 | Pimpal                | <i>Ficus religiosa</i>             | 3'-5'   | 25'-27' | To be removed  | Falling within Excavation area  |
| 29 | 28 | Deshi Badam           | <i>Terminalia cattapa</i>          | 2'-3'   | 20'-22' | To be removed  | Falling within Excavation area  |
| 30 | 29 | Deshi Badam           | <i>Terminalia cattapa</i>          | 3'-4'   | 20'-22' | To be removed  | Falling within Excavation area  |
| 31 | 30 | Asupalav              | <i>Polyalthia longifolia</i>       | 2'-4'   | 25'-27' | To be retained | Falling outside Excavation area |
| 32 | 31 | Asupalav              | <i>Polyalthia longifolia</i>       | 3'-5'   | 25'-27' | To be retained | Falling outside Excavation area |
| 33 | 32 | Asupalav              | <i>Polyalthia longifolia</i>       | 4'-6'   | 25'-27' | To be retained | Falling outside Excavation area |
| 34 | 33 | Subabul               | <i>Leucaena<br/>Leucocephala</i>   | 6"-8"   | 15'-18' | To be removed  | Falling within Excavation area  |
| 35 | 34 | Subabul               | <i>Leucaena<br/>Leucocephala</i>   | 2'-3'   | 20'-22' | To be removed  | Falling within Excavation area  |
| 36 | 35 | Subabul               | <i>Leucaena<br/>Leucocephala</i>   | 4'-6'   | 20'-22' | To be removed  | Falling within Excavation area  |
| 37 | 36 | Putranjiva            | <i>Putranjiva roxburghii</i>       | 4"-6"   | 7'-9'   | To be removed  | Falling within Excavation area  |
| 38 | 37 | Putranjiva            | <i>Putranjiva roxburghii</i>       | 9"-11"  | 12'-14' | To be removed  | Falling within Excavation area  |
| 39 | 38 | Putranjiva            | <i>Putranjiva roxburghii</i>       | 1'-2'   | 15'-18' | To be removed  | Falling within Excavation area  |
| 40 | 39 | Putranjiva            | <i>Putranjiva roxburghii</i>       | 1'-2'   | 15'-18' | To be removed  | Falling within Excavation area  |
| 41 | 40 | Naral                 | <i>Cocos nucifera</i>              | 4'-6'   | 25'-27' | To be retained | Falling outside Excavation area |
| 42 | 41 | Shewaga               | <i>Moringa oliefera</i>            | 1'-2'   | 12'-14' | To be retained | Falling outside Excavation area |
| 43 | 42 | Putranjiva            | <i>Putranjiva roxburghii</i>       | 1'-2'   | 12'-14' | To be removed  | Falling within Excavation area  |
| 44 | 43 | Naral                 | <i>Cocos nucifera</i>              | 5'-6'   | 25'-27' | To be retained | Falling outside Excavation area |
| 45 | 44 | Gulmohar(Dead)        | <i>Delonix regia</i>               | 2'-3'   | 15'-17' | To be removed  | Falling within Excavation area  |
| 46 | 45 | Sonmohar              | <i>Peltophorum<br/>Pterocarpum</i> | 9"-11"  | 10'-12' | To be removed  | Falling within Excavation area  |
| 47 | 46 | Karanj                | <i>Pongamia Pinnata</i>            | 3"-5"   | 10'-12' | To be removed  | Falling within Excavation area  |
| 48 | 47 | Jungli<br>Badam(Dead) | <i>Terminalia cattapa</i>          | 3"-5"   | 12'-14' | To be removed  | Falling within Excavation area  |
| 49 | 48 | Pimpal                | <i>Ficus religiosa</i>             | 20'-22' | 35'-38' | To be removed  | Falling within Excavation area  |
| 50 | 49 | Asupalav              | <i>Polyalthia longifolia</i>       | 1'-2'   | 15'-18' | To be removed  | Falling within Excavation area  |
| 51 | 50 | Asupalav              | <i>Polyalthia longifolia</i>       | 6"-8"   | 6'-8'   | To be removed  | Falling within Excavation area  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |               |                                    |         |         |               |                                |
|----|----|---------------|------------------------------------|---------|---------|---------------|--------------------------------|
| 52 | 51 | Asupalav      | <i>Polyalthia longifolia</i>       | 6"-8"   | 6'-8'   | To be removed | Falling within Excavation area |
| 53 | 52 | Karanj        | <i>Pongamia Pinnata</i>            | 9"-11"  | 5'-7'   | To be removed | Falling within Excavation area |
| 54 | 53 | Subabhul      | <i>Peltophorum<br/>Pterocarpum</i> | 9"-11"  | 12'-14' | To be removed | Falling within Excavation area |
| 55 | 54 | Gulmohar      | <i>Delonix Regia</i>               | 3'-5'   | 20'-22' | To be removed | Falling within Excavation area |
| 56 | 55 | Naral         | <i>Cocos nucifera</i>              | 4'-5'   | 15'-20' | To be removed | Falling within Excavation area |
| 57 | 56 | Fishtail Palm | <i>Caryota urens</i>               | 5'-8'   | 20'-25' | To be removed | Falling within Excavation area |
| 58 | 57 | Subabul       | <i>Leucaena<br/>Leucocephala</i>   | 1'-2'   | 20'-22' | To be removed | Falling within Excavation area |
| 59 | 58 | Shewaga       | <i>Moringa oliefera</i>            | 4'-6'   | 20'-22' | To be removed | Falling within Excavation area |
| 60 | 59 | Naral         | <i>Cocos nucifera</i>              | 2'-4'   | 10'-12' | To be removed | Falling within Excavation area |
| 61 | 60 | Pimpal        | <i>Ficus religiosa</i>             | 9"-11"  | 20'-22' | To be removed | Falling within Excavation area |
| 62 | 61 | Peru          | <i>Psidium guajava</i>             | 6"-8"   | 4'-6'   | To be removed | Falling within Excavation area |
| 63 | 62 | Mango         | <i>Mangifera indica</i>            | 10"-12" | 12'-14' | To be removed | Falling within Excavation area |
| 64 | 63 | Neem          | <i>Azadirachta indica</i>          | 2'-4'   | 20'-22' | To be removed | Falling within Excavation area |
| 65 | 64 | Jambhul       | <i>Syzigium cumini</i>             | 9"-11"  | 12"-14" | To be removed | Falling within Excavation area |
| 66 | 65 | Subabhul      | <i>Leucaena<br/>leucocephala</i>   | 4'-6'   | 20'-22' | To be removed | Falling within Excavation area |
| 67 | 66 | Subabhul      | <i>Leucaena<br/>leucocephala</i>   | 4'-6'   | 20'-22' | To be removed | Falling within Excavation area |
| 68 | 67 | Pimpal        | <i>Ficus religiosa</i>             | 5'-8'   | 20'-22' | To be removed | Falling within Excavation area |
| 69 | 68 | Mango         | <i>Mangifera Indica</i>            | 4'-6'   | 15'-17' | To be removed | Falling within Excavation area |
| 70 | 69 | Subabhul      | <i>Leuceana<br/>leucocephala</i>   | 1'-2'   | 42'-46' | To be removed | Falling within Excavation area |
| 71 | 70 | Bhend         | <i>Thespesia populnea</i>          | 3'-5'   | 15'-17' | To be removed | Falling within Excavation area |
| 72 | 71 | Naral         | <i>Cocos nucifera</i>              | 4'-6'   | 18'-20' | To be removed | Falling within Excavation area |
| 73 | 72 | Raiwala       | <i>Cicca acida</i>                 | 9"-10"  | 10'-12' | To be removed | Falling within Excavation area |
| 74 | 73 | Peru          | <i>Psidium guajava</i>             | 1'-2'   | 15'-18' | To be removed | Falling within Excavation area |
| 75 | 74 | Subabul       | <i>Leucaena<br/>Leucocephala</i>   | 2'-4'   | 15'-18' | To be removed | Falling within Excavation area |
| 76 | 75 | Subabul       | <i>Leucaena<br/>Leucocephala</i>   | 2'-4'   | 15'-18' | To be removed | Falling within Excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |    |              |                                    |         |         |                |                                 |
|-----|----|--------------|------------------------------------|---------|---------|----------------|---------------------------------|
| 77  | 76 | Subabul      | <i>Leucaena<br/>Leucocephala</i>   | 2'-4'   | 15'-18' | To be removed  | Falling within Excavation area  |
| 78  | 77 | Subabul      | <i>Leucaena<br/>Leucocephala</i>   | 2'-4'   | 15'-18' | To be removed  | Falling within Excavation area  |
| 79  | 78 | Pimpal       | <i>Ficus religiosa</i>             | 2'-4'   | 30'-32' | To be retained | Falling outside Excavation area |
| 80  | 79 | Pimpal       | <i>Ficus religiosa</i>             | 3'-5'   | 35'-38' | To be retained | Falling outside Excavation area |
| 81  | 80 | Pimpal       | <i>Ficus religiosa</i>             | 2'-4'   | 15'-18' | To be retained | Falling outside Excavation area |
| 82  | 81 | Wad          | <i>Ficus benghalensis</i>          | 4'-6'   | 30'-35' | To be removed  | Falling within Excavation area  |
| 83  | 82 | Wad          | <i>Ficus benghalensis</i>          | 4'-6'   | 30'-35' | To be removed  | Falling within Excavation area  |
| 84  | 83 | Royal palm   | <i>Roystonea regia</i>             | 2'-4'   | 8'-10'  | To be retained | Falling outside Excavation area |
| 85  | 84 | Pimpal       | <i>Ficus religiosa</i>             | 8'-9'   | 30'-32' | To be removed  | Falling within Excavation area  |
| 86  | 85 | Pimpal       | <i>Ficus religiosa</i>             | 5'-6'   | 35'-38' | To be retained | Falling outside Excavation area |
| 87  | 86 | Deshi Badam  | <i>Terminalia cattapa</i>          | 2'-3'   | 22'-24' | To be removed  | Falling within Excavation area  |
| 88  | 87 | Wad          | <i>Ficus benalensis</i>            | 8'-9'   | 45'-48' | To be removed  | Falling within Excavation area  |
| 89  | 88 | Wad          | <i>Ficus benalensis</i>            | 18'-19' | 45'-48' | To be removed  | Falling within Excavation area  |
| 90  | 89 | Kala umber   | <i>Ficus hispida</i>               | 1'-2'   | 10'-12' | To be removed  | Falling within Excavation area  |
| 91  | 90 | Shewaga      | <i>Moringa oliefera</i>            | 2'-3'   | 25'-28' | To be removed  | Falling within Excavation area  |
| 92  | 91 | Sonmohar     | <i>Peltophorum<br/>Pterocarpum</i> | 2'-3'   | 35'-38' | To be removed  | Falling within Excavation area  |
| 93  | 92 | Sonmohar     | <i>Peltophorum<br/>Pterocarpum</i> | 1'-2'   | 35'-38' | To be removed  | Falling within Excavation area  |
| 94  | 93 | Sonmohar     | <i>Peltophorum<br/>Pterocarpum</i> | 2'-3'   | 35'-38' | To be removed  | Falling within Excavation area  |
| 95  | 94 | Sonmohar     | <i>Peltophorum<br/>Pterocarpum</i> | 5'-6'   | 35'-38' | To be retained | Falling outside Excavation area |
| 96  | 95 | Sonmohar     | <i>Peltophorum<br/>pterocarpum</i> | 2'-3'   | 43-45'  | To be removed  | Falling within Excavation area  |
| 97  | 96 | Jungli badam | <i>Sterculia foetida</i>           | 2'-3'   | 52'-54' | To be removed  | Falling within Excavation area  |
| 98  | 97 | Sonmohar     | <i>Peltophorum<br/>pterocarpum</i> | 6'-7'   | 42'-44' | To be retained | Falling outside Excavation area |
| 99  | 98 | Jungli badam | <i>Sterculia foetida</i>           | 4'-5'   | 52'-54' | To be retained | Falling outside Excavation area |
| 100 | 99 | Jungli badam | <i>Sterculia foetida</i>           | 3'-4'   | 52'-54' | To be retained | Falling outside Excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                     |         |         |                |                                 |
|-----|-----|----------------|-------------------------------------|---------|---------|----------------|---------------------------------|
| 101 | 100 | Deshi Badam    | <i>Terminalia cattapa</i>           | 4'-5'   | 26'-28' | To be retained | Falling outside Excavation area |
| 102 | 101 | Undi           | <i>Callophyllum<br/>innophyllum</i> | 4'-5'   | 30'-32' | To be retained | Falling outside Excavation area |
| 103 | 102 | Vilayti chinch | <i>Pithecellobium dulce</i>         | 2'-3'   | 30'-32' | To be removed  | Falling within Excavation area  |
| 104 | 103 | Vilayti chinch | <i>Pithecellobium dulce</i>         | 1'-2'   | 36'-38' | To be removed  | Falling within Excavation area  |
| 105 | 104 | Amba           | <i>Mangifera indica</i>             | 1'-2'   | 50'-52' | To be removed  | Falling within Excavation area  |
| 106 | 105 | Asupalav       | <i>Polyalthia longifolia</i>        | 8"-12"  | 10'-12' | To be removed  | Falling within Excavation area  |
| 107 | 106 | Akashneem      | <i>Millingtonia hortensis</i>       | 8"-12"  | 23'-25' | To be removed  | Falling within Excavation area  |
| 108 | 107 | Akashneem      | <i>Millingtonia hortensis</i>       | 1'-2'   | 33'-35' | To be removed  | Falling within Excavation area  |
| 109 | 108 | Akashneem      | <i>Millingtonia hortensis</i>       | 1'-2'   | 33'-35' | To be removed  | Falling within Excavation area  |
| 110 | 109 | Deshi Badam    | <i>Terminalia cattapa</i>           | 19'-20' | 34'-36' | To be removed  | Falling within Excavation area  |
| 111 | 110 | Asupalav(Dead) | <i>Polyalthia longifolia</i>        | 1'-2'   | 12'-14' | To be removed  | Falling within Excavation area  |
| 112 | 111 | Jambhul        | <i>Syzygium cumini</i>              | 5'-6'   | 46      | To be removed  | Falling within Excavation area  |
| 113 | 112 | Mahuva         | <i>Madhuca indica</i>               | 3'-4'   | 13'-15' | To be removed  | Falling within Excavation area  |
| 114 | 113 | Fishtail Palm  | <i>Caryota urens</i>                | 14'-15' | 33'-35' | To be removed  | Falling within Excavation area  |
| 115 | 114 | Amba           | <i>Mangifera indica</i>             | 3'-4'   | 15'-20' | To be removed  | Falling within Excavation area  |
| 116 | 115 | Rain tree      | <i>Samanea saman</i>                | 1'-2'   | 62'-65' | To be removed  | Falling within Excavation area  |
| 117 | 116 | Fishtail Palm  | <i>Caryota urens</i>                | 1'-2'   | 50'-54' | To be removed  | Falling within Excavation area  |
| 118 | 117 | Asupalav       | <i>Polyalthia longifolia</i>        | 19'-20' | 10'-15' | To be retained | Falling outside Excavation area |
| 119 | 118 | Asupalav       | <i>Polyalthia longifolia</i>        | 15'-16' | 10'-15' | To be retained | Falling outside Excavation area |
| 120 | 119 | Asupalav       | <i>Polyalthia longifolia</i>        | 3'-4'   | 10'-15' | To be retained | Falling outside Excavation area |
| 121 | 120 | Asupalav       | <i>Polyalthia longifolia</i>        | 1'-2'   | 26'-30' | To be retained | Falling outside Excavation area |
| 122 | 121 | Asupalav       | <i>Polyalthia longifolia</i>        | 3'-4'   | 13'-15' | To be retained | Falling outside Excavation area |
| 123 | 122 | Asupalav       | <i>Polyalthia longifolia</i>        | 1'-2'   | 26'-30' | To be retained | Falling outside Excavation area |
| 124 | 123 | Deshi Badam    | <i>Terminalia cattapa</i>           | 2'-3'   | 36'-40' | To be retained | Falling outside Excavation area |
| 125 | 124 | Asupalav       | <i>Polyalthia longifolia</i>        | 2'-3'   | 36'-40' | To be retained | Falling outside Excavation area |
| 126 | 125 | Asupalav       | <i>Polyalthia longifolia</i>        | 3'-4'   | 30'-32' | To be retained | Falling outside Excavation area |
| 127 | 126 | Asupalav       | <i>Polyalthia longifolia</i>        | 3'-4'   | 30'-32' | To be retained | Falling outside Excavation area |
| 128 | 127 | Asupalav       | <i>Polyalthia longifolia</i>        | 7'-8'   | 30'-32' | To be retained | Falling outside Excavation area |
| 129 | 128 | Rain tree      | <i>Samanea saman</i>                | 3'-4'   | 50'-55' | To be removed  | Falling within Excavation area  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                |           |         |                |                                 |
|-----|-----|---------------|--------------------------------|-----------|---------|----------------|---------------------------------|
| 130 | 129 | Rain tree     | <i>Samanea saman</i>           | 10' - 11' | 50'-55' | To be removed  | Falling within Excavation area  |
| 131 | 130 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 45'-50' | To be retained | Falling outside Excavation area |
| 132 | 131 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 5'-6'     | 48'-50' | To be retained | Falling outside Excavation area |
| 133 | 132 | Asupalav      | <i>Polyalthia longifolia</i>   | 4'-5'     | 48'-50' | To be retained | Falling outside Excavation area |
| 134 | 133 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-4'     | 40'-42' | To be retained | Falling outside Excavation area |
| 135 | 134 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-4'     | 35'-40' | To be retained | Falling outside Excavation area |
| 136 | 135 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-4'     | 35'-40' | To be retained | Falling outside Excavation area |
| 137 | 136 | Asupalav      | <i>Polyalthia longifolia</i>   | 1'-2'     | 33'-35' | To be retained | Falling outside Excavation area |
| 138 | 137 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-4'     | 35'-40' | To be retained | Falling outside Excavation area |
| 139 | 138 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-4'     | 35'-40' | To be retained | Falling outside Excavation area |
| 140 | 139 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-4'     | 35'-40' | To be retained | Falling outside Excavation area |
| 141 | 140 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 142 | 141 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 143 | 142 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 144 | 143 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 145 | 144 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 146 | 145 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 147 | 146 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 148 | 147 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 149 | 148 | Naral         | <i>Cocos nucifera</i>          | 3'-4'     | 56'58'  | To be retained | Falling outside Excavation area |
| 150 | 149 | Naral         | <i>Cocos nucifera</i>          | 3'-4'     | 62'-64' | To be retained | Falling outside Excavation area |
| 151 | 150 | Naral         | <i>Cocos nucifera</i>          | 2'-3'     | 13'-15' | To be retained | Falling outside Excavation area |
| 152 | 151 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'     | 56'-60' | To be retained | Falling outside Excavation area |
| 153 | 152 | Amba          | <i>Mangifera indica</i>        | 4'-5'     | 50'-52' | To be retained | Falling outside Excavation area |
| 154 | 153 | Amba          | <i>Mangifera indica</i>        | 4'-5'     | 50'-52' | To be retained | Falling outside Excavation area |
| 155 | 154 | Fishtail Palm | <i>Caryota urens</i>           | 2'-3'     | 42'-44' | To be retained | Falling outside Excavation area |
| 156 | 155 | Fishtail Palm | <i>Caryota urens</i>           | 2'-3'     | 42'-44' | To be retained | Falling outside Excavation area |
| 157 | 156 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-3'     | 42'-44' | To be retained | Falling outside Excavation area |
| 158 | 157 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-3'     | 42'-44' | To be retained | Falling outside Excavation area |
| 159 | 158 | Deshi Badam   | <i>Terminalia cattapa</i>      | 6"-8"     | 16'-18' | To be retained | Falling outside Excavation area |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                |         |         |                |                                 |
|-----|-----|---------------|--------------------------------|---------|---------|----------------|---------------------------------|
| 160 | 159 | Amba          | <i>Mangifera indica</i>        | 5'-6'   | 46'-48' | To be retained | Falling outside Excavation area |
| 161 | 160 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'   | 49'-50' | To be retained | Falling outside Excavation area |
| 162 | 161 | Karanj        | <i>Pongamia pinnata</i>        | 3'-4'   | 41'-42' | To be retained | Falling outside Excavation area |
| 163 | 162 | Karanj        | <i>Pongamia pinnata</i>        | 3'-4'   | 41'-42' | To be retained | Falling outside Excavation area |
| 164 | 163 | Karanj        | <i>Pongamia pinnata</i>        | 2'-3'   | 36'-38' | To be retained | Falling outside Excavation area |
| 165 | 164 | Saptaparni    | <i>Alstonia scholaris</i>      | 8'-10'  | 46'-48' | To be retained | Falling outside Excavation area |
| 166 | 165 | Chapha        | <i>Plumeria sps.</i>           | 2'-3'   | 33'-34' | To be retained | Falling outside Excavation area |
| 167 | 166 | Sitaphal      | <i>Annona squamosa</i>         | 1'-2'   | 13'-14' | To be retained | Falling outside Excavation area |
| 168 | 167 | Amba          | <i>Mangifera indica</i>        | 1'-2'   | 13'-14' | To be removed  | Falling within Excavation area  |
| 169 | 168 | Deshi Badam   | <i>Terminalia cattapa</i>      | 2'-3'   | 26'-28' | To be removed  | Falling within Excavation area  |
| 170 | 169 | Karanj        | <i>Pongamia pinnata</i>        | 4'-6'   | 36'-38' | To be removed  | Falling within Excavation area  |
| 171 | 170 | Chinch        | <i>Tamarin spp.</i>            | 1'-2'   | 23'-25' | To be removed  | Falling within Excavation area  |
| 172 | 171 | Fishtail Palm | <i>Caryota urens</i>           | 2'-3'   | 42'-44' | To be retained | Falling outside Excavation area |
| 173 | 172 | Deshi Badam   | <i>Terminalia cattapa</i>      | 5'-7'   | 38'-40' | To be retained | Falling outside Excavation area |
| 174 | 173 | Naral         | <i>Cocos nucifera</i>          | 2'-3'   | 42'-44' | To be retained | Falling outside Excavation area |
| 175 | 174 | Asupalav      | <i>Polyalthia longifolia</i>   | 2'-3'   | 36'-39' | To be retained | Falling outside Excavation area |
| 176 | 175 | Naral         | <i>Cocos nucifera</i>          | 2'-3'   | 36'-39' | To be retained | Falling outside Excavation area |
| 177 | 176 | Bhend         | <i>Thespesia populnea</i>      | 1'-2'   | 23'-25' | To be retained | Falling outside Excavation area |
| 178 | 177 | Bhend         | <i>Thespesia populnea</i>      | 13'-15' | 30'-32' | To be retained | Falling outside Excavation area |
| 179 | 178 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 2'-3'   | 26'-28' | To be retained | Falling outside Excavation area |
| 180 | 179 | Gulmohar      | <i>Delonix regia</i>           | 2'-3'   | 22'-24' | To be retained | Falling outside Excavation area |
| 181 | 180 | Jungli badam  | <i>Sterculia foetida</i>       | 3'-4'   | 33'-35' | To be retained | Falling outside Excavation area |
| 182 | 181 | Kashid        | <i>Cassia siamea</i>           | 2'-3'   | 23'-24' | To be removed  | Falling within Excavation area  |
| 183 | 182 | Naral         | <i>Cocos nucifera</i>          | 3'-4'   | 42'-44' | To be removed  | Falling within Excavation area  |
| 184 | 183 | Naral         | <i>Cocos nucifera</i>          | 3'-4'   | 36'-38' | To be retained | Falling outside Excavation area |
| 185 | 184 | Asupalav      | <i>Polyalthia longifolia</i>   | 3'-4'   | 38'-40' | To be retained | Falling outside Excavation area |
| 186 | 185 | Naral         | <i>Cocos nucifera</i>          | 2'-3'   | 32'-35' | To be retained | Falling outside Excavation area |
| 187 | 186 | Wad           | <i>Ficus bengalensis</i>       | 14'-15' | 46'-48' | To be removed  | Falling within Excavation area  |
| 188 | 187 | Chapha        | <i>Plumeria sps.</i>           | 2'-3'   | 30'-32' | To be removed  | Falling within Excavation area  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                 |        |         |                |                                 |
|-----|-----|----------------|---------------------------------|--------|---------|----------------|---------------------------------|
| 189 | 188 | Phanas         | <i>Atrocarpus heterophyllus</i> | 6'-8'  | 44'-46' | To be removed  | Falling within Excavation area  |
| 190 | 189 | Royal palm     | <i>Roystonea regia</i>          | 3'-5'  | 44'-46' | To be retained | Falling outside Excavation area |
| 191 | 190 | Asupalav       | <i>Polyalthia longifolia</i>    | 2'-3'  | 22'-25' | To be retained | Falling outside Excavation area |
| 192 | 191 | Royal palm     | <i>Roystonea regia</i>          | 3'-4'  | 30'-32' | To be retained | Falling outside Excavation area |
| 193 | 192 | Jambhul        | <i>Syzygium cumini</i>          | 5'-6'  | 40'-42' | To be retained | Falling outside Excavation area |
| 194 | 193 | Naral          | <i>cocos nucifera</i>           | 2'-3'  | 32'-35' | To be retained | Falling outside Excavation area |
| 195 | 194 | Asupalav       | <i>Polyalthia longifolia</i>    | 3'-4'  | 32'-35' | To be retained | Falling outside Excavation area |
| 196 | 195 | Naral          | <i>cocos nucifera</i>           | 2'-3'  | 16'-18' | To be retained | Falling outside Excavation area |
| 197 | 196 | Naral          | <i>Cocos nucifera</i>           | 1'-2'  | 12'-14' | To be retained | Falling outside Excavation area |
| 198 | 197 | Pichkari       | <i>Spathodia companulata</i>    | 1'-2'  | 13'-14' | To be retained | Falling outside Excavation area |
| 199 | 198 | Taman          | <i>Lagerstroemia speciosa</i>   | 2'-3'  | 10'-14' | To be removed  | Falling within Excavation area  |
| 200 | 199 | Asupalav       | <i>Polyalthia longifolia</i>    | 2'-3'  | 10'-14' | To be removed  | Falling within Excavation area  |
| 201 | 200 | Asupalav       | <i>Polyalthia longifolia</i>    | 1'-2'  | 10'-14' | To be removed  | Falling within Excavation area  |
| 202 | 201 | Asupalav       | <i>Polyalthia longifolia</i>    | 2'-3'  | 20'-22' | To be removed  | Falling within Excavation area  |
| 203 | 202 | Asupalav       | <i>Polyalthia longifolia</i>    | 5'-6'  | 36'-40' | To be removed  | Falling within Excavation area  |
| 204 | 203 | Asupalav       | <i>Polyalthia longifolia</i>    | 2'-3'  | 30'-35' | To be removed  | Falling within Excavation area  |
| 205 | 204 | Sonmohar       | <i>Peltophorum pterocarpum</i>  | 2'-3'  | 13'-15' | To be removed  | Falling within Excavation area  |
| 206 | 205 | Asupalav(Dead) | <i>Polyalthia longifolia</i>    | 6'-7'  | 13'-15' | To be removed  | Falling within Excavation area  |
| 207 | 206 | Satvin         | <i>Alstonia scholaris</i>       | 4'-5'  | 12'-14' | To be retained | Falling outside Excavation area |
| 208 | 207 | Asupalav       | <i>Polyalthia longifolia</i>    | 6'-7'  | 43'-45' | To be removed  | Falling within Excavation area  |
| 209 | 208 | Asupalav       | <i>Polyalthia longifolia</i>    | 4'-5'  | 43'-45' | To be removed  | Falling within Excavation area  |
| 210 | 209 | Asupalav       | <i>Polyalthia longifolia</i>    | 3'-4'  | 22'-25' | To be removed  | Falling within Excavation area  |
| 211 | 210 | Asupalav       | <i>Polyalthia longifolia</i>    | 4'-5'  | 22'-25' | To be removed  | Falling within Excavation area  |
| 212 | 211 | Asupalav       | <i>Polyalthia longifolia</i>    | 1'-2'  | 20'-22' | To be retained | Falling outside Excavation area |
| 213 | 212 | Asupalav       | <i>Polyalthia longifolia</i>    | 1'-2'  | 20'-22' | To be retained | Falling outside Excavation area |
| 214 | 213 | Sonmohar       | <i>Peltophorum pterocarpum</i>  | 8"-12" | 36'-40' | To be retained | Falling outside Excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |              |                                |         |         |                |                                 |
|-----|-----|--------------|--------------------------------|---------|---------|----------------|---------------------------------|
| 215 | 214 | Bhokar       | <i>Cordia dichotoma</i>        | 8"-12"  | 36'-40' | To be removed  | Falling within Excavation area  |
| 216 | 215 | Jambhul      | <i>Syzigium cumini</i>         | 1'-2'   | 50'-52' | To be retained | Falling outside Excavation area |
| 217 | 216 | Amba         | <i>Mangifera indica</i>        | 4'-5'   | 40'-42' | To be removed  | Falling within Excavation area  |
| 218 | 217 | Amba         | <i>Mangifera indica</i>        | 2'-3'   | 40'-42' | To be removed  | Falling within Excavation area  |
| 219 | 218 | Tuti         | <i>Morus alba</i>              | 1'-2'   | 15'20'  | To be removed  | Falling within Excavation area  |
| 220 | 219 | Chenduphul   | <i>Parkia biglandulosa</i>     | 1'-2'   | 30'-32' | To be removed  | Falling within Excavation area  |
| 221 | 220 | Amba         | <i>Mangifera indica</i>        | 1'-2'   | 11'-12' | To be removed  | Falling within Excavation area  |
| 222 | 221 | Chenduphul   | <i>Parkia biglandulosa</i>     | 1'-2'   | 25'-30' | To be removed  | Falling within Excavation area  |
| 223 | 222 | Kadu Neem    | <i>Azadirachta indica</i>      | 1'-2'   | 15'-20' | To be retained | Falling outside Excavation area |
| 224 | 223 | Amba         | <i>Mangifera indica</i>        | 1'-2'   | 30'-32' | To be removed  | Falling within Excavation area  |
| 225 | 224 | Amba         | <i>Mangifera indica</i>        | 1'-2'   | 20'-22' | To be removed  | Falling within Excavation area  |
| 226 | 225 | Naral        | <i>Cocos nucifera</i>          | 1'-2'   | 8'-12'  | To be retained | Falling outside Excavation area |
| 227 | 226 | Bakul        | <i>Mimusops elengi</i>         | 3'-4'   | 40'-42' | To be retained | Falling outside Excavation area |
| 228 | 227 | Pimpal       | <i>Ficus religiosa</i>         | 19'-20' | 45'-45' | To be removed  | Falling within Excavation area  |
| 229 | 228 | Karanj       | <i>Pongamia pinnata</i>        | 1'-2'   | 13'-15' | To be removed  | Falling within Excavation area  |
| 230 | 229 | kashid       | <i>Cassia siamea</i>           | 5'-6'   | 30'-32' | To be removed  | Falling within Excavation area  |
| 231 | 230 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3'-4'   | 38'-40' | To be removed  | Falling within Excavation area  |
| 232 | 231 | Pimpal       | <i>Ficus religiosa</i>         | 14'-15' | 42'-44' | To be removed  | Falling within Excavation area  |
| 233 | 232 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3'-4'   | 62'-64' | To be removed  | Falling within Excavation area  |
| 234 | 233 | Jungli badam | <i>Sterculia foetida</i>       | 1'-2'   | 22'-24' | To be removed  | Falling within Excavation area  |
| 235 | 234 | Jungli badam | <i>Sterculia foetida</i>       | 1'-2'   | 22'-24' | To be removed  | Falling within Excavation area  |
| 236 | 235 | Wad          | <i>Ficus bengalensis</i>       | 19'-20' | 45'-50' | To be removed  | Falling within Excavation area  |
| 237 | 236 | Wad          | <i>Ficus bengalensis</i>       | 15'-16' | 45'-50' | To be removed  | Falling within Excavation area  |
| 238 | 237 | Jungli badam | <i>Sterculia foetida</i>       | 3'-4'   | 38'-40' | To be removed  | Falling within Excavation area  |
| 239 | 238 | Amba         | <i>Mangifera indica</i>        | 1'-2'   | 22'-24' | To be removed  | Falling within Excavation area  |
| 240 | 239 | Putranjiva   | <i>Putranjiva roxburghii</i>   | 3'-4'   | 40'-42' | To be removed  | Falling within Excavation area  |
| 241 | 240 | Karanj       | <i>Pongamia pinnata</i>        | 1'-2'   | 25'-30' | To be removed  | Falling within Excavation area  |
| 242 | 241 | Naral        | <i>Cocos nucifera</i>          | 2'-4'   | 10'-12' | To be removed  | Falling within Excavation area  |
| 243 | 242 | Naral        | <i>Cocos nucifera</i>          | 2'-3'   | 5'-8'   | To be removed  | Falling within Excavation area  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                |                              |         |         |               |                                |
|-----|------|----------------|------------------------------|---------|---------|---------------|--------------------------------|
| 244 | 243  | Naral          | <i>Cocos nucifera</i>        | 3'-4'   | 36'-40' | To be removed | Falling within Excavation area |
| 245 | 244  | Pimpal         | <i>Ficus religiosa</i>       | 7'-8'   | 40'-45' | To be removed | Falling within Excavation area |
| 246 | 245  | Naral          | <i>Cocos nucifera</i>        | 3'-4'   | 35'-38' | To be removed | Falling within Excavation area |
| 247 | 246  | Bimbli         | <i>Averrhoa bilimbi</i>      | 8"-12"  | 10'-12' | To be removed | Falling within Excavation area |
| 248 | 246A | Jambhul        | <i>Syzigium cumini</i>       | 1'-2'   | 20'-22' | To be removed | Falling within Excavation area |
| 249 | 246B | Jambhul        | <i>Syzigium cumini</i>       | 2'-3'   | 20'-22' | To be removed | Falling within Excavation area |
| 250 | 246C | Deshi Badam    | <i>Terminalia cattapa</i>    | 8"-10"  | 10'-12' | To be removed | Falling within Excavation area |
| 251 | 246D | Lettuce tree   | <i>Pisonia alba</i>          | 6"-8"   | 9'-12'  | To be removed | Falling within Excavation area |
| 252 | 246E | Naral          | <i>Cocos nucifera</i>        | 1'-2'   | 8'-10'  | To be removed | Falling within Excavation area |
| 253 | 247  | Amba           | <i>Mangifera indica</i>      | 1'-2'   | 20'-25' | To be removed | Falling within Excavation area |
| 254 | 248  | Wad            | <i>Ficus bengalensis</i>     | 15'-18' | 40'-42' | To be removed | Falling within Excavation area |
| 255 | 249  | Naral          | <i>Cocos nucifera</i>        | 3'-4'   | 10'-12' | To be removed | Falling within Excavation area |
| 256 | 250  | Fishtail Palm  | <i>Caryota urens</i>         | 3'-4'   | 35'-40' | To be removed | Falling within Excavation area |
| 257 | 251  | Fishtail Palm  | <i>Caryota urens</i>         | 3'-4'   | 35'-40' | To be removed | Falling within Excavation area |
| 258 | 252  | Subabhul       | <i>Leuceana leucocephala</i> | 3'-4'   | 35'-40' | To be removed | Falling within Excavation area |
| 259 | 253  | Umber          | <i>Ficus glomerata</i>       | 6'-8'   | 30'-32' | To be removed | Falling within Excavation area |
| 260 | 254  | Deshi Badam    | <i>Terminalia cattapa</i>    | 3'-4'   | 32'-34' | To be removed | Falling within Excavation area |
| 261 | 255  | Umber          | <i>Ficus glomerata</i>       | 7'-8'   | 32'-34' | To be removed | Falling within Excavation area |
| 262 | 256  | Fishtail Palm  | <i>Caryota urens</i>         | 3'-4'   | 10'-15' | To be removed | Falling within Excavation area |
| 263 | 257  | Fishtail Palm  | <i>Caryota urens</i>         | 3'-4'   | 45'-50' | To be removed | Falling within Excavation area |
| 264 | 258  | Umber          | <i>Ficus glomerata</i>       | 6'-7'   | 30'-32' | To be removed | Falling within Excavation area |
| 265 | 259  | Amba           | <i>Mangifera indica</i>      | 6'-7'   | 45'-50' | To be removed | Falling within Excavation area |
| 266 | 260  | Naral          | <i>Cocos nucifera</i>        | 4'-5'   | 30'-32' | To be removed | Falling within Excavation area |
| 267 | 261  | Mango          | <i>Mangifera indica</i>      | 7'-8'   | 30'-32' | To be removed | Falling within Excavation area |
| 268 | 262  | Gulmohar       | <i>Delonix regia</i>         | 5'-6'   | 30'-32' | To be removed | Falling within Excavation area |
| 269 | 263  | Asupalav       | <i>Polyalthia longifolia</i> | 3'-4'   | 20'-22' | To be removed | Falling within Excavation area |
| 270 | 264  | Asupalav       | <i>Polyalthia longifolia</i> | 4'-5'   | 30'-32' | To be removed | Falling within Excavation area |
| 271 | 265  | Naral (Dead)   | <i>Cocos nucifera</i>        | 4'-5'   | 30'-32' | To be removed | Falling within Excavation area |
| 272 | 266  | Christmas tree | <i>Auracaria columnaris</i>  | 4"-5"   | 6'-8'   | To be removed | Falling within Excavation area |
| 273 | 267  | Neem(Dead)     | <i>Azadirachta indica</i>    | 4"-5"   | 8'-9'   | To be removed | Falling within Excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |          |                                |            |         |               |                                |
|-----|-----|----------|--------------------------------|------------|---------|---------------|--------------------------------|
| 274 | 268 | Naral    | <i>Cocos nucifera</i>          | 4'-5'      | 35'-38' | To be removed | Falling within Excavation area |
| 275 | 269 | Naral    | <i>Cocos nucifera</i>          | 4'-5'      | 35'-38' | To be removed | Falling within Excavation area |
| 276 | 270 | Naral    | <i>Cocos nucifera</i>          | 5'-6'      | 40'-45' | To be removed | Falling within Excavation area |
| 277 | 271 | Naral    | <i>Cocos nucifera</i>          | 5'-6'      | 40'-45' | To be removed | Falling within Excavation area |
| 278 | 272 | Asupalav | <i>Polyalthia longifolia</i>   | 3'-4'      | 20'-22' | To be removed | Falling within Excavation area |
| 279 | 273 | Pimpal   | <i>Ficus religiosa</i>         | 10'-12'    | 35'-40' | To be removed | Falling within Excavation area |
| 280 | 274 | Sonmohar | <i>Peltophorum pterocarpum</i> | 10' - 11'  | 40'-45' | To be removed | Falling within Excavation area |
| 281 | 275 | Gulmohar | <i>Delonix regia</i>           | 3'-4'      | 20'-22' | To be removed | Falling within Excavation area |
| 282 | 276 | Pimpal   | <i>Ficus religiosa</i>         | 5'-6'      | 25'-28' | To be removed | Falling within Excavation area |
| 283 | 277 | Gulmohar | <i>Delonix regia</i>           | 4'-5'      | 20'-22' | To be removed | Falling within Excavation area |
| 284 | 278 | Vad      | <i>Ficus bengalensis</i>       | 1'-2'      | 15'-20' | To be removed | Falling within Excavation area |
| 285 | 279 | Pimpal   | <i>Ficus religiosa</i>         | 1'-2'      | 15'-20' | To be removed | Falling within Excavation area |
| 286 | 280 | Peepal   | <i>Ficus religiosa</i>         | 5' - 6'    | 16'-19' | To be removed | Falling within Excavation area |
| 287 | 281 | Nirgundi | <i>Vitex negundo</i>           | 1' -2'     | 9' -12' | To be removed | Falling within Excavation area |
|     |     |          |                                |            |         |               |                                |
|     |     |          | Trees to be Retained           | 95         |         |               |                                |
|     |     |          | Trees to be removed            | 192        |         |               |                                |
|     |     |          | <b>Total Trees</b>             | <b>287</b> |         |               |                                |

| Summary of Tree Survey at Kalbadevi Station |          |             |                                |                     |                      |                     |                                 |
|---|----------|-------------|--------------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.                                     | Tree no. | Common Name | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1   | SG18     | Asupalav    | <i>Polyalthia longifolia</i>   | 5                   | 32                   | To be retained      | Falling outside excavation line |
| 2   | SG19     | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3                   | 25                   | To be retained      | Falling outside excavation line |
| 3   | SG20     | Bhend       | <i>Thespesia populnea</i>      | 3                   | 18                   | To be retained      | Falling outside excavation line |
| 4   | SG21     | Asupalav    | <i>Polyalthia longifolia</i>   | 4                   | 30                   | To be retained      | Falling outside excavation line |
| 5   | SG22     | Savar       | <i>Ceiba pentandra</i>         | 4                   | 30                   | To be retained      | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |         |             |                                |    |    |                |                                 |
|----|---------|-------------|--------------------------------|----|----|----------------|---------------------------------|
| 6  | SG23    | Savar       | <i>Ceiba pentandra</i>         | 4  | 30 | To be retained | Falling outside excavation line |
| 7  | JSS 21D | Wad         | <i>Ficus benghalensis</i>      | 10 | 40 | To be removed  | Falling within excavation line  |
| 8  | X1      | Pimpal      | <i>Ficus religiosa</i>         | 2  | 10 | To be retained | Falling outside excavation line |
| 9  | X2      | Wad         | <i>Ficus benghalensis</i>      | 3  | 13 | To be retained | Falling outside excavation line |
| 10 | X3      | Pimpal      | <i>Ficus religiosa</i>         | 2  | 13 | To be retained | Falling outside excavation line |
| 11 | X4      | Wad         | <i>Ficus benghalensis</i>      | 16 | 39 | To be retained | Falling outside excavation line |
| 12 | X5      | Pimpal      | <i>Ficus religiosa</i>         | 25 | 46 | To be retained | Falling outside excavation line |
| 13 | CW18    | Bhend       | <i>Thespesia populnea</i>      | 3  | 22 | To be retained | Falling outside excavation line |
| 14 | CW19    | Putranjiva  | <i>Putranjiva roxburghii</i>   | 3  | 15 | To be retained | Falling outside excavation line |
| 15 | JSS 20  | Jamun       | <i>Syzygium cumini</i>         | 2  | 45 | To be removed  | Falling within excavation line  |
| 16 | JSS20A  | Wad         | <i>Ficus benghalensis</i>      | 23 | 43 | To be retained | Falling outside excavation line |
| 17 | JSS20B  | Amba        | <i>Mangifera indica</i>        | 10 | 46 | To be retained | Falling outside excavation line |
| 18 | JSS20C  | Chapha      | <i>Plumeria alba</i>           | 7  | 32 | To be retained | Falling outside excavation line |
| 19 | JSS20D  | Pimpal      | <i>Ficus religiosa</i>         | 10 | 43 | To be retained | Falling outside excavation line |
| 20 | JSS20E  | Wad         | <i>Ficus benghalensis</i>      | 21 | 43 | To be retained | Falling outside excavation line |
| 21 | JSS20F  | Pimpal      | <i>Ficus religiosa</i>         | 17 | 49 | To be retained | Falling outside excavation line |
| 22 | JSS20G  | Wad         | <i>Ficus benghalensis</i>      | 15 | 42 | To be retained | Falling outside excavation line |
| 23 | JSS 21  | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3  | 50 | To be retained | Falling outside excavation line |
| 24 | JSS21A  | Shevga      | <i>Moringa oleifera</i>        | 2  | 20 | To be retained | Falling outside excavation line |
| 25 | JSS21B  | Naral       | <i>Cocos nucifera</i>          | 2  | 20 | To be retained | Falling outside excavation line |
| 26 | JSS21C  | Naral       | <i>Cocos nucifera</i>          | 3  | 16 | To be retained | Falling outside excavation line |
| 27 | JSS 22  | Samudraphal | <i>Barringtonia asiatica</i>   | 1  | 30 | To be retained | Falling outside excavation line |
| 28 | JSS22A  | Asupalav    | <i>Polyalthia longifolia</i>   | 2  | 10 | To be retained | Falling outside excavation line |
| 29 | JSS22B  | Gulmohar    | <i>Delonix regia</i>           | 10 | 30 | To be retained | Falling outside excavation line |
| 30 | JSS 23  | Samudraphal | <i>Barringtonia asiatica</i>   | 1  | 30 | To be retained | Falling outside excavation line |
| 31 | JSS 24  | Deshi Badam | <i>Terminalia catappa</i>      | 2  | 40 | To be retained | Falling outside excavation line |
| 32 | JSS 25  | Samudraphal | <i>Barringtonia asiatica</i>   | 2  | 30 | To be retained | Falling outside excavation line |
| 33 | JSS 26  | Samudraphal | <i>Barringtonia asiatica</i>   | 2  | 30 | To be retained | Falling outside excavation line |
| 34 | JSS 27  | Samudraphal | <i>Barringtonia asiatica</i>   | 3  | 40 | To be retained | Falling outside excavation line |

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 32        |
| Trees to be removed  | 2         |
| <b>Total Trees</b>   | <b>34</b> |

| Summary of Tree Survey at Girgaon Station |          |              |                                |                     |                      |                     |                                 |
|---|----------|--------------|--------------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.                                   | Tree no. | Common Name  | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1   | JSS 22   | Pimpal       | <i>Ficus religiosa</i>         | 5                   | 30                   | To be retained      | Falling outside excavation line |
| 2   | JSS 22A  | Asupalav     | <i>Polyalthia longifolia</i>   | 1                   | 20                   | To be retained      | Falling outside excavation line |
| 3   | JSS22B   | Asupalav     | <i>Polyalthia longifolia</i>   | 9"                  | 18                   | To be retained      | Falling outside excavation line |
| 4   | JSS22C   | Asupalav     | <i>Polyalthia longifolia</i>   | 6"                  | 15                   | To be retained      | Falling outside excavation line |
| 5   | JSS22D   | Asupalav     | <i>Polyalthia longifolia</i>   | 6"                  | 15                   | To be retained      | Falling outside excavation line |
| 6   | JSS 23   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3                   | 25                   | To be removed       | Falling within excavation line  |
| 7   | JSS 23A  | Narikel      | <i>Pterygota alata</i>         | 16"                 | 18                   | To be removed       | Falling within excavation line  |
| 8   | JSS 23B  | Narikel      | <i>Pterygota alata</i>         | 6"                  | 10                   | To be removed       | Falling within excavation line  |
| 9   | JSS 23C  | Pimpal       | <i>ficus religiosa</i>         | 8"                  | 10                   | To be removed       | Falling within excavation line  |
| 10  | JSS 24   | Saptarni     | <i>Alstonia scholaris</i>      | 1                   | 12                   | To be removed       | Falling within excavation line  |
| 11  | JSS 24 A | Wad          | <i>Ficus benghalensis</i>      | 1                   | 12                   | To be removed       | Falling within excavation line  |
| 12  | JSS 25   | Asupalav     | <i>Polyalthia longifolia</i>   | 1                   | 12                   | To be removed       | Falling within excavation line  |
| 13  | JSS 26   | Jungli Badam | <i>Sterculia foetida</i>       | 2.5                 | 40                   | To be removed       | Falling within excavation line  |
| 14  | JSS 27   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2.5                 | 30                   | To be removed       | Falling within excavation line  |
| 15  | JSS 28   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2.5                 | 30                   | To be removed       | Falling within excavation line  |
| 16  | JSS 29   | Jungli Badam | <i>Sterculia foetida</i>       | 2                   | 33                   | To be removed       | Falling within excavation line  |
| 17  | JSS 30   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3                   | 30                   | To be removed       | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |        |              |                                |     |    |                |                                 |
|----|--------|--------------|--------------------------------|-----|----|----------------|---------------------------------|
| 18 | JSS 31 | Neem         | <i>Azadirachta indica</i>      | 8"  | 12 | To be removed  | Falling within excavation line  |
| 19 | JSS 32 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2.5 | 35 | To be removed  | Falling within excavation line  |
| 20 | JSS 33 | Jungli Badam | <i>Sterculia foetida</i>       | 2.5 | 35 | To be removed  | Falling within excavation line  |
| 21 | JSS34  | Jungli Badam | <i>Sterculia foetida</i>       | 5   | 40 | To be retained | Falling outside excavation line |
| 22 | JSS35  | Bhend        | <i>Thespesia populnea</i>      | 2.5 | 25 | To be retained | Falling outside excavation line |
| 23 | JSS37  | Gulmohar     | <i>Delonix regia</i>           | 6   | 40 | To be removed  | Falling within excavation line  |
| 24 | JSS 38 | Bhend        | <i>Thespesia populnea</i>      | 1   | 20 | To be retained | Falling outside excavation line |
| 25 | JSS 39 | Bhend        | <i>Thespesia populnea</i>      | 2   | 25 | To be retained | Falling outside excavation line |
| 26 | JSS 40 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be retained | Falling outside excavation line |
| 27 | JSS 41 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4   | 30 | To be retained | Falling outside excavation line |
| 28 | JSS 42 | Jambul       | <i>Syzygium cumini</i>         | 3   | 25 | To be retained | Falling outside excavation line |
| 29 | JSS 43 | Taman        | <i>Lagerstroemia indica</i>    | 2.5 | 20 | To be retained | Falling outside excavation line |
| 30 | JSS 44 | Taman        | <i>Lagerstroemia indica</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 31 | JSS44A | Desi badam   | <i>Terminalia catappa</i>      | 3   | 46 | To be retained | Falling outside excavation line |
| 32 | JSS44B | Asupalav     | <i>Polyalthia longifolia</i>   | 4   | 35 | To be retained | Falling outside excavation line |
| 33 | JSS44C | Asupalav     | <i>Polyalthia longifolia</i>   | 3   | 25 | To be retained | Falling outside excavation line |
| 34 | JSS44D | Asupalav     | <i>Polyalthia longifolia</i>   | 4   | 35 | To be retained | Falling outside excavation line |
| 35 | JSS44E | Sitaphal     | <i>Annona squamosa</i>         | 2   | 25 | To be retained | Falling outside excavation line |
| 36 | JSS44F | Peru         | <i>Psidium gujava</i>          | 2   | 22 | To be retained | Falling outside excavation line |
| 37 | JSS44G | Peru         | <i>Psidium gujava</i>          | 1   | 22 | To be retained | Falling outside excavation line |
| 38 | JSS44H | Chiku        | <i>Manilkara zapota</i>        | 3   | 30 | To be retained | Falling outside excavation line |
| 39 | JSS 45 | Asupalav     | <i>Polyalthia longifolia</i>   | 1   | 20 | To be removed  | Falling within excavation line  |
| 40 | JSS45A | Umber        | <i>Ficus glomerata</i>         | 3   | 33 | To be retained | Falling outside excavation line |
| 41 | JSS45B | Asupalav     | <i>Polyalthia longifolia</i>   | 4   | 40 | To be retained | Falling outside excavation line |
| 42 | JSS45C | Asupalav     | <i>Polyalthia longifolia</i>   | 4   | 35 | To be retained | Falling outside excavation line |
| 43 | JSS 46 | Wad          | <i>Ficus benghalensis</i>      | 6"  | 8  | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |        |          |                                |     |    |                |                                 |
|----|--------|----------|--------------------------------|-----|----|----------------|---------------------------------|
| 44 | JSS 47 | Jambul   | <i>Syzygium cumini</i>         | 10" | 15 | To be removed  | Falling within excavation line  |
| 45 | JSS 48 | Sonmohar | <i>Peltophorum pterocarpum</i> | 4   | 25 | To be removed  | Falling within excavation line  |
| 46 | JSS 49 | Sonmohar | <i>Peltophorum pterocarpum</i> | 3   | 25 | To be removed  | Falling within excavation line  |
| 47 | BJ24   | Sonmohar | <i>Peltophorum pterocarpum</i> | 4   | 40 | To be retained | Falling outside excavation line |

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 27        |
| Trees to be removed  | 20        |
| <b>Total Trees</b>   | <b>47</b> |

| Summary of Tree Survey at Grant Road Station |          |              |                                |                     |                      |                     |                                 |
|--|----------|--------------|--------------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.                                      | Tree no. | Common Name  | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1  | APM 4    | Sonmohar     | <i>Peltophorum pterocarpum</i> | 7                   | 50                   | To be retained      | Falling outside excavation line |
| 2  | APM5     | Kadu neem    | <i>Azadirachta indica</i>      | 2                   | 20                   | To be retained      | Falling outside excavation line |
| 3  | APM6     | Jungli badam | <i>Sterculia foetida</i>       | 3                   | 46                   | To be retained      | Falling outside excavation line |
| 4  | DBM 51   | Jambul       | <i>Syzygium cumini</i>         | 1                   | 20                   | To be removed       | Falling within excavation line  |
| 5  | DBM 51A  | Wad          | <i>Ficus benghalensis</i>      | 10"                 | 15                   | To be removed       | Falling within excavation line  |
| 6  | DBM 52   | Wad          | <i>Ficus benghalensis</i>      | 10"                 | 15                   | To be removed       | Falling within excavation line  |
| 7  | DBM 53   | Umber        | <i>Ficus racemosa</i>          | 8"                  | 10                   | To be removed       | Falling within excavation line  |
| 8  | DBM 54   | Asupalav     | <i>Polyalthia longifolia</i>   | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 9  | DBM 55   | Asupalav     | <i>Polyalthia longifolia</i>   | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 10   | DBM 56   | Asupalav     | <i>Polyalthia longifolia</i>   | 10"                 | 15                   | To be removed       | Falling within excavation line  |
| 11   | DBM 57   | Asupalav     | <i>Polyalthia longifolia</i>   | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 12   | DBM 58   | Asupalav     | <i>Polyalthia longifolia</i>   | 10"                 | 15                   | To be removed       | Falling within excavation line  |
| 13   | DBM 59   | Sonmohar     | <i>Samanea saman</i>           | 12                  | 60                   | To be removed       | Falling within excavation line  |
| 14   | DBM 60   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 1.5                 | 20                   | To be removed       | Falling within excavation line  |
| 15   | DBM 61   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2                   | 20                   | To be removed       | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |         |             |                                |     |    |               |                                |
|----|---------|-------------|--------------------------------|-----|----|---------------|--------------------------------|
| 16 | DBM 62  | Sonmohar    | <i>Peltophorum pterocarpum</i> | 1   | 15 | To be removed | Falling within excavation line |
| 17 | DBM 63  | Rain Tree   | <i>Samanea saman</i>           | 8   | 60 | To be removed | Falling within excavation line |
| 18 | DBM 64  | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3   | 10 | To be removed | Falling within excavation line |
| 19 | DBM 65  | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3   | 10 | To be removed | Falling within excavation line |
| 20 | DBM 66  | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3   | 9  | To be removed | Falling within excavation line |
| 21 | DBM 67  | Deshi Badam | <i>Terminalia catappa</i>      | 10" | 12 | To be removed | Falling within excavation line |
| 22 | DBM 146 | Rain Tree   | <i>Samanea saman</i>           | 6   | 50 | To be removed | Falling within excavation line |
| 23 | DBM146A | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3   | 33 | To be removed | Falling within excavation line |
| 24 | DBM 148 | Jambul      | <i>Syzygium cumini</i>         | 2.5 | 7  | To be removed | Falling within excavation line |
| 25 | DBM 149 | Rain tree   | <i>Samanea saman</i>           | 4"  | 9  | To be removed | Falling within excavation line |
| 26 | DBM 150 | Royal Palm  | <i>Roystonea regia</i>         | 3.5 | 50 | To be removed | Falling within excavation line |
| 27 | DBM 151 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3   | 35 | To be removed | Falling within excavation line |
| 28 | DBM 152 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3   | 30 | To be removed | Falling within excavation line |
| 29 | DBM 154 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 2   | 30 | To be removed | Falling within excavation line |
| 30 | DBM 155 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3.4 | 25 | To be removed | Falling within excavation line |
| 31 | DBM 156 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 4   | 35 | To be removed | Falling within excavation line |
| 32 | DBM 157 | Royal Palm  | <i>Roystonea regia</i>         | 4   | 50 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |          |            |                                |     |    |                |                                 |
|----|----------|------------|--------------------------------|-----|----|----------------|---------------------------------|
| 33 | DBM 158  | Royal Palm | <i>Roystonea regia</i>         | 4   | 50 | To be removed  | Falling within excavation line  |
| 34 | DBM 159  | Putranjiva | <i>Putranjiva roxburghii</i>   | 10" | 15 | To be removed  | Falling within excavation line  |
| 35 | DBM 160  | Sonmohar   | <i>Peltophorum pterocarpum</i> | 2   | 25 | To be removed  | Falling within excavation line  |
| 36 | DBM 161  | Sonmohar   | <i>Peltophorum pterocarpum</i> | 2   | 25 | To be removed  | Falling within excavation line  |
| 37 | DBM 162  | Rain tree  | <i>Samanea saman</i>           | 1   | 15 | To be removed  | Falling within excavation line  |
| 38 | DBM 163  | Rain tree  | <i>Samanea saman</i>           | 1   | 15 | To be removed  | Falling within excavation line  |
| 39 | DBM 164  | Wad        | <i>Ficus benghalensis</i>      | 3   | 45 | To be removed  | Falling within excavation line  |
| 40 | DBM 164A | Sonmohar   | <i>Peltophorum pterocarpum</i> | 2   | 25 | To be removed  | Falling within excavation line  |
| 41 | DBM 165  | Pimpal     | <i>Ficus religiosa</i>         | 6"  | 10 | To be removed  | Falling within excavation line  |
| 42 | DBM 167  | Jambul     | <i>Syzygium cumini</i>         | 3   | 40 | To be retained | Falling outside excavation line |
| 43 | DBM 168  | Jambul     | <i>Syzygium cumini</i>         | 2   | 35 | To be retained | Falling outside excavation line |
| 44 | GTM 1    | Umber      | <i>Ficus glomerata</i>         | 2   | 23 | To be removed  | Falling within excavation line  |
| 45 | GTM 2    | Pimpal     | <i>Ficus religiosa</i>         | 13  | 49 | To be retained | Falling outside excavation line |
| 46 | GTM 3    | Rain tree  | <i>Samanea saman</i>           | 10  | 56 | To be retained | Falling outside excavation line |
| 47 | GTM 4    | Asupalav   | <i>Polyalthia longifolia</i>   | 5   | 49 | To be retained | Falling outside excavation line |
| 48 | GTM 5    | Kala umber | <i>Ficus hispida</i>           | 3   | 33 | To be retained | Falling outside excavation line |
| 49 | GTM 6    | Kala umber | <i>Ficus hispida</i>           | 3   | 33 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |        |            |                              |   |    |                |                                 |
|----|--------|------------|------------------------------|---|----|----------------|---------------------------------|
| 50 | GTM 7  | Dead       | -                            | 3 | 13 | To be retained | Falling outside excavation line |
| 51 | GTM 8  | Naral      | <i>Cocos nucifera</i>        | 3 | 13 | To be retained | Falling outside excavation line |
| 52 | GTM 9  | Naral      | <i>Cocos nucifera</i>        | 4 | 26 | To be retained | Falling outside excavation line |
| 53 | GTM 10 | Naral      | <i>Cocos nucifera</i>        | 4 | 20 | To be retained | Falling outside excavation line |
| 54 | GTM 11 | Naral      | <i>Cocos nucifera</i>        | 4 | 30 | To be retained | Falling outside excavation line |
| 55 | GTM 12 | Asupalav   | <i>Polyalthia longifolia</i> | 1 | 13 | To be retained | Falling outside excavation line |
| 56 | GTM 13 | Jambhul    | <i>Syzygium cumini</i>       | 3 | 43 | To be retained | Falling outside excavation line |
| 57 | GTM 14 | Asupalav   | <i>Polyalthia longifolia</i> | 1 | 13 | To be retained | Falling outside excavation line |
| 58 | GTM 15 | Naral      | <i>Cocos nucifera</i>        | 2 | 5  | To be retained | Falling outside excavation line |
| 59 | GTM 16 | Naral      | <i>Cocos nucifera</i>        | 2 | 10 | To be retained | Falling outside excavation line |
| 60 | GTM 17 | Jambhul    | <i>Syzygium cumini</i>       | 2 | 30 | To be retained | Falling outside excavation line |
| 61 | GTM 18 | Naral      | <i>Cocos nucifera</i>        | 3 | 33 | To be retained | Falling outside excavation line |
| 62 | GTM 19 | Asupalav   | <i>Polyalthia longifolia</i> | 2 | 26 | To be retained | Falling outside excavation line |
| 63 | GTM 20 | Asupalav   | <i>Polyalthia longifolia</i> | 2 | 23 | To be retained | Falling outside excavation line |
| 64 | GTM 21 | Dead       | -                            | 1 | 16 | To be retained | Falling outside excavation line |
| 65 | GTM 22 | Saptaparni | <i>Alstonia scholaris</i>    | 2 | 33 | To be retained | Falling outside excavation line |
| 66 | GTM 23 | Saptaparni | <i>Alstonia scholaris</i>    | 3 | 43 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |        |            |                                |       |       |                |                                 |
|----|--------|------------|--------------------------------|-------|-------|----------------|---------------------------------|
| 67 | GTM 24 | Saptaparni | <i>Alstonia scholaris</i>      | 3     | 43    | To be retained | Falling outside excavation line |
| 68 | GTM 25 | Saptaparni | <i>Alstonia scholaris</i>      | 2     | 43    | To be retained | Falling outside excavation line |
| 69 | GTM 26 | Putranjiva | <i>Putranjiva roxburghii</i>   | 7     | 43    | To be retained | Falling outside excavation line |
| 70 | GTM 27 | Putranjiva | <i>Putranjiva roxburghii</i>   | 5     | 46    | To be retained | Falling outside excavation line |
| 71 | GTM 28 | Pimpal     | <i>Ficus religiosa</i>         | 16.4  | 52.48 | To be removed  | Falling within excavation line  |
| 72 | GTM 29 | Putranjiva | <i>Putranjiva roxburghii</i>   | 13.12 | 42.64 | To be removed  | Falling within excavation line  |
| 73 | GTM 30 | Royal Palm | <i>Roystonea regia</i>         | 3     | 16    | To be retained | Falling outside excavation line |
| 74 | GTM 31 | Amba       | <i>Mangifera indica</i>        | 2     | 26    | To be retained | Falling outside excavation line |
| 75 | GTM 32 | Saptaparni | <i>Alstonia scholaris</i>      | 1     | 13    | To be retained | Falling outside excavation line |
| 76 | GTM 33 | Nandarukh  | <i>Ficus benjamina</i>         | 2     | 16    | To be retained | Falling outside excavation line |
| 77 | GTM 34 | Saptaparni | <i>Alstonia scholaris</i>      | 1     | 13    | To be retained | Falling outside excavation line |
| 78 | GTM 35 | Shevga     | <i>Moringa oliefera</i>        | 8     | 36    | To be retained | Falling outside excavation line |
| 79 | GTM 36 | Amba       | <i>Mangifera indica</i>        | 1     | 23    | To be retained | Falling outside excavation line |
| 80 | GTM 37 | Saptaparni | <i>Alstonia scholaris</i>      | 3     | 16    | To be retained | Falling outside excavation line |
| 81 | GTM 38 | Umber      | <i>Ficus glomerata</i>         | 3     | 33    | To be retained | Falling outside excavation line |
| 82 | GTM 39 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 7     | 13    | To be retained | Falling outside excavation line |
| 83 | GTM 40 | Pimpal     | <i>Ficus religiosa</i>         | 7     | 16    | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |        |                |                                |      |       |                |                                 |
|-----|--------|----------------|--------------------------------|------|-------|----------------|---------------------------------|
| 84  | GTM 41 | Jambhul        | <i>Syzygium cumini</i>         | 10   | 66    | To be retained | Falling outside excavation line |
| 85  | GTM 42 | Dead           | -                              | 3    | 23    | To be retained | Falling outside excavation line |
| 86  | GTM 43 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 8    | 36    | To be retained | Falling outside excavation line |
| 87  | GTM 44 | Dead           | -                              | 2    | 10    | To be retained | Falling outside excavation line |
| 88  | GTM 45 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 8    | 33    | To be retained | Falling outside excavation line |
| 89  | GTM 46 | Sita Ashok     | <i>Saraca indica</i>           | 7    | 43    | To be retained | Falling outside excavation line |
| 90  | GTM 47 | Kashid         | <i>Cassia siamea</i>           | 7    | 39    | To be retained | Falling outside excavation line |
| 91  | GTM 48 | Pimpal         | <i>Ficus religiosa</i>         | 5    | 23    | To be retained | Falling outside excavation line |
| 92  | GTM 49 | Jambhul        | <i>Syzygium cumini</i>         | 11   | 66    | To be retained | Falling outside excavation line |
| 93  | GTM 50 | Dead           | -                              | 7    | 16    | To be retained | Falling outside excavation line |
| 94  | GTM 51 | Saptaparni     | <i>Alstonia scholaris</i>      | 2    | 26    | To be removed  | Falling within excavation line  |
| 95  | GTM 52 | Gulmohar       | <i>Delonix regia</i>           | 3    | 39    | To be removed  | Falling within excavation line  |
| 96  | GTM 53 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 4    | 33    | To be removed  | Falling within excavation line  |
| 97  | GTM 54 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 4    | 33    | To be removed  | Falling within excavation line  |
| 98  | GTM 55 | Gulmohar       | <i>Delonix regia</i>           | 7    | 39    | To be removed  | Falling within excavation line  |
| 99  | GTM 56 | Vilayti chinch | <i>Pithecellobium dulce</i>    | 9.84 | 26.24 | To be removed  | Falling within excavation line  |
| 100 | GTM 57 | Asupalav       | <i>Polyalthia longifolia</i>   | 7    | 49    | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |        |          |                                |   |    |                |                                 |
|-----|--------|----------|--------------------------------|---|----|----------------|---------------------------------|
| 101 | GTM 58 | Asupalav | <i>Polyalthia longifolia</i>   | 7 | 43 | To be removed  | Falling within excavation line  |
| 102 | GTM 59 | Asupalav | <i>Polyalthia longifolia</i>   | 7 | 36 | To be removed  | Falling within excavation line  |
| 103 | GTM 60 | Sonmohar | <i>Peltophorum pterocarpum</i> | 5 | 23 | To be removed  | Falling within excavation line  |
| 104 | GTM 61 | Asupalav | <i>Polyalthia longifolia</i>   | 8 | 36 | To be retained | Falling outside excavation line |
| 105 | GTM 62 | Asupalav | <i>Polyalthia longifolia</i>   | 5 | 36 | To be retained | Falling outside excavation line |
| 106 | GTM 63 | Asupalav | <i>Polyalthia longifolia</i>   | 5 | 39 | To be retained | Falling outside excavation line |
| 107 | GTM 64 | Asupalav | <i>Polyalthia longifolia</i>   | 5 | 39 | To be retained | Falling outside excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 56         |
| Trees to be removed  | 51         |
| <b>Total Trees</b>   | <b>107</b> |

| Summary of Tree Survey at WTC Construction Storage Yard Station |          |                 |                              |                     |                      |                     |                                 |
|---|----------|-----------------|------------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.   | Tree no. | Common Name     | Botanical Name               | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1   | 1        | Pimpal          | <i>Flcus religiosa</i>       | 2                   | 20                   | To be Retain        | Falling outside excavation line |
| 2   | 2        | Gulomar         | <i>Deloris regia</i>         | 2                   | 18                   | To be Retain        | Falling outside excavation line |
| 3   | 3        | Limbu           | <i>Citrus aurantifolia</i>   | 6"                  | 6                    | To be removed       | Falling within excavation line  |
| 4   | 4        | Dalimb          | <i>Punica granatum</i>       | 6"                  | 6                    | To be removed       | Falling within excavation line  |
| 5   | 5        | Pimpal          | <i>Flcus religiosa</i>       | 4"                  | 22                   | To be Retain        | Falling outside excavation line |
| 6   | 6        | Kaduneem        | <i>Azadirachta indica</i>    | 1                   | 8                    | To be Retain        | Falling outside excavation line |
| 7   | 7        | Vad             | <i>Ficus benghalensis</i>    | 4                   | 9                    | To be Retain        | Falling outside excavation line |
| 8   | 8        | Pimpal          | <i>Flcus religiosa</i>       | 1                   | 12                   | To be Retain        | Falling outside excavation line |
| 9   | 9        | Subabhul        | <i>Leucaena leucocephala</i> | 1                   | 14                   | To be Retain        | Falling outside excavation line |
| 10  | 10       | Pimpal          | <i>Leucaena leucocephala</i> | 2                   | 9                    | To be Retain        | Falling outside excavation line |
| 11  | 11       | Subabhul        | <i>Leucaena leucocephala</i> | 6"                  | 16                   | To be Retain        | Falling outside excavation line |
| 12  | 12       | gulmohar        | <i>Delonix regia</i>         | 6"                  | 9                    | To be Retain        | Falling outside excavation line |
| 13  | 13       | chinch          | <i>Tamarindus indica</i>     | 7"                  | 9                    | To be Retain        | Falling outside excavation line |
| 14  | 14       | Pimpal          | <i>Flcus religiosa</i>       | 8"                  | 11                   | To be Retain        | Falling outside excavation line |
| 15  | 15       | Subabhul        | <i>Leucaena leucocephala</i> | 9"                  | 9                    | To be Retain        | Falling outside excavation line |
| 16  | 16       | Pimpal          | <i>Flcus religiosa</i>       | 1                   | 12                   | To be Retain        | Falling outside excavation line |
| 17  | 17       | Vad             | <i>Ficus benghalensis</i>    | 3                   | 12                   | To be Retain        | Falling outside excavation line |
| 18  | 18       | Vilayati Chinch | <i>Pithecellobium dulce</i>  | 1                   | 11                   | To be Retain        | Falling outside excavation line |
| 19  | 19       | Bor             | <i>Ziziphus mauritiana</i>   | 1                   | 15                   | To be Retain        | Falling outside excavation line |
| 20  | 20       | Bor             | <i>Ziziphus mauritiana</i>   | 1                   | 15                   | To be Retain        | Falling outside excavation line |
| 21  | 21       | Bor             | <i>Ziziphus mauritiana</i>   | 1                   | 15                   | To be Retain        | Falling outside excavation line |
| 22  | 22       | Bor             | <i>Ziziphus mauritiana</i>   | 1                   | 12                   | To be Retain        | Falling outside excavation line |
| 23  | 23       | Pimpal          | <i>Flcus religiosa</i>       | 3                   | 18                   | To be Retain        | Falling outside excavation line |
| 24  | 24       | Pimpal          | <i>Flcus religiosa</i>       | 2                   | 16                   | To be Retain        | Falling outside excavation line |
| 25  | 25       | Pimpal          | <i>Flcus religiosa</i>       | 3                   | 18                   | To be Retain        | Falling outside excavation line |
| 26  | 26       | Vad(Payer)      | <i>Ficus benghalensis</i>    | 6                   | 24                   | To be Retain        | Falling outside excavation line |
| 27  | 27       | Umbar           | <i>Ficus racemosa</i>        | 10'                 | 10                   | To be Retain        | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |          |                              |    |    |               |                                 |
|----|----|----------|------------------------------|----|----|---------------|---------------------------------|
| 28 | 28 | gulmohar | <i>Delonix regia</i>         | 6" | 10 | To be Retain  | Falling outside excavation line |
| 29 | 29 | vad      | <i>Ficus benghalensis</i>    | 6" | 8  | To be Retain  | Falling outside excavation line |
| 30 | 30 | Pimpal   | <i>Ficus religiosa</i>       | 1  | 20 | To be Retain  | Falling outside excavation line |
| 31 | 31 | Subabhul | <i>Leucaena leucocephala</i> | 2  | 20 | To be Retain  | Falling outside excavation line |
| 32 | 32 | Gulmohar | <i>Delonix regia</i>         | 1  | 20 | To be Retain  | Falling outside excavation line |
| 33 | 33 | Gulmohar | <i>Delonix regia</i>         | 1  | 20 | To be Retain  | Falling outside excavation line |
| 34 | 34 | Gulmohar | <i>Delonix regia</i>         | 2  | 25 | To be Retain  | Falling outside excavation line |
| 35 | 35 | chinch   | <i>Tamarindus indica</i>     | 1  | 20 | To be Retain  | Falling outside excavation line |
| 36 | 36 | Gulmohar | <i>Delonix regia</i>         | 1  | 20 | To be Retain  | Falling outside excavation line |
| 37 | 37 | Gulmohar | <i>Delonix regia</i>         | 1  | 12 | To be Retain  | Falling outside excavation line |
| 38 | 38 | Gulmohar | <i>Delonix regia</i>         | 3  | 20 | To be Retain  | Falling outside excavation line |
| 39 | 39 | Gulmohar | <i>Delonix regia</i>         | 2  | 20 | To be Retain  | Falling outside excavation line |
| 40 | 40 | Gulmohar | <i>Delonix regia</i>         | 1  | 20 | To be Retain  | Falling outside excavation line |
| 41 | 41 | Bor      | <i>Ziziphus mauritiana</i>   | 1  | 15 | To be Retain  | Falling outside excavation line |
| 42 | 42 | Bor      | <i>Ziziphus mauritiana</i>   | 1  | 16 | To be Retain  | Falling outside excavation line |
| 43 | 43 | Bor      | <i>Ziziphus mauritiana</i>   | 1  | 16 | To be Retain  | Falling outside excavation line |
| 44 | 44 | Bor      | <i>Ziziphus mauritiana</i>   | 1  | 16 | To be Retain  | Falling outside excavation line |
| 45 | 45 | Gulmohar | <i>Delonix regia</i>         | 1  | 15 | To be Retain  | Falling outside excavation line |
| 46 | 46 | Gulmohar | <i>Delonix regia</i>         | 8" | 14 | To be Retain  | Falling outside excavation line |
| 47 | 47 | Subabhul | <i>Leucaena leucocephala</i> | 3  | 25 | To be Retain  | Falling outside excavation line |
| 48 | 48 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 20 | To be removed | Falling within excavation line  |
| 49 | 49 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 20 | To be removed | Falling within excavation line  |
| 50 | 50 | Gulmohar | <i>Delonix regia</i>         | 1  | 20 | To be Retain  | Falling outside excavation line |
| 51 | 51 | Bor      | <i>Ziziphus mauritiana</i>   | 1  | 15 | To be Retain  | Falling outside excavation line |
| 52 | 52 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 12 | To be Retain  | Falling outside excavation line |
| 53 | 53 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 15 | To be Retain  | Falling outside excavation line |
| 54 | 54 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 14 | To be Retain  | Falling outside excavation line |
| 55 | 55 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 20 | To be Retain  | Falling outside excavation line |
| 56 | 56 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 5  | To be Retain  | Falling outside excavation line |
| 57 | 57 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 12 | To be Retain  | Falling outside excavation line |
| 58 | 58 | badam    | <i>Ficus religiosa</i>       | 1  | 1  | To be Retain  | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |          |                              |    |    |               |                                 |
|----|----|----------|------------------------------|----|----|---------------|---------------------------------|
| 59 | 59 | Shevga   | <i>Moringa pterigosperma</i> | 3  | 14 | To be Retain  | Falling outside excavation line |
| 60 | 60 | Shevga   | <i>Moringa pterigosperma</i> | 1  | 15 | To be Retain  | Falling outside excavation line |
| 61 | 61 | Shevga   | <i>Moringa pterigosperma</i> | 8" | 10 | To be Retain  | Falling outside excavation line |
| 62 | 62 | Bor      | <i>Ziziphus mauritiana</i>   | 1  | 12 | To be Retain  | Falling outside excavation line |
| 63 | 63 | Bor      | <i>Ziziphus mauritiana</i>   | 1  | 15 | To be Retain  | Falling outside excavation line |
| 64 | 64 | Bor      | <i>Ziziphus mauritiana</i>   | 3  | 20 | To be Retain  | Falling outside excavation line |
| 65 | 65 | Umbar    | <i>Ficus racemosa</i>        | 1  | 15 | To be Retain  | Falling outside excavation line |
| 66 | 66 | Umbar    | <i>Ficus racemosa</i>        | 2  | 15 | To be Retain  | Falling outside excavation line |
| 67 | 67 | Bor      | <i>Ziziphus mauritiana</i>   | 2  | 15 | To be Retain  | Falling outside excavation line |
| 68 | 68 | Umbar    | <i>Ficus racemosa</i>        | 2  | 15 | To be Retain  | Falling outside excavation line |
| 69 | 69 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 18 | To be Retain  | Falling outside excavation line |
| 70 | 70 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 12 | To be Retain  | Falling outside excavation line |
| 71 | 71 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 12 | To be Retain  | Falling outside excavation line |
| 72 | 72 | Subabhul | <i>Leucaena leucocephala</i> | 1  | 12 | To be Retain  | Falling outside excavation line |
| 73 | 73 | Subabhul | <i>Leucaena leucocephala</i> | 3  | 20 | To be Retain  | Falling outside excavation line |
| 74 | 74 | Subabhul | <i>Leucaena leucocephala</i> | 4  | 20 | To be Retain  | Falling outside excavation line |
| 75 | 75 | Subabhul | <i>Leucaena leucocephala</i> | 4  | 20 | To be Retain  | Falling outside excavation line |
| 76 | 76 | Subabhul | <i>Leucaena leucocephala</i> | 4  | 20 | To be Retain  | Falling outside excavation line |
| 77 | 77 | Subabhul | <i>Leucaena leucocephala</i> | 4  | 20 | To be Retain  | Falling outside excavation line |
| 78 | 78 | Subabhul | <i>Leucaena leucocephala</i> | 3  | 20 | To be Retain  | Falling outside excavation line |
| 79 | 79 | Subabhul | <i>Leucaena leucocephala</i> | 3  | 25 | To be Retain  | Falling outside excavation line |
| 80 | 80 | Subabhul | <i>Leucaena leucocephala</i> | 2  | 25 | To be Retain  | Falling outside excavation line |
| 81 | 81 | Pimpal   | <i>Flcus religiosa</i>       | 1  | 15 | To be Retain  | Falling outside excavation line |
| 82 | 82 | Bor      | <i>Ziziphus mauritiana</i>   | 1  | 12 | To be Retain  | Falling outside excavation line |
| 83 | 83 | Subabhul | <i>Leucaena leucocephala</i> | 2  | 25 | To be Retain  | Falling outside excavation line |
| 84 | 84 | Subabhul | <i>Leucaena leucocephala</i> | 3  | 30 | To be Retain  | Falling outside excavation line |
| 85 | 85 | Pimpal   | <i>Flcus religiosa</i>       | 5  | 8  | To be Retain  | Falling outside excavation line |
| 86 | 86 | Pimpal   | <i>Flcus religiosa</i>       | 2  | 24 | To be Retain  | Falling outside excavation line |
| 87 | 87 | pimpal   | <i>Flcus religiosa</i>       | 1  | 18 | To be removed | Falling within excavation line  |
| 88 | 88 | Pimpal   | <i>Flcus religiosa</i>       | 2  | 20 | To be removed | Falling within excavation line  |

**PART-II: TREE INVENTORY DETAILS**

**GENERAL CONSULTANT FOR MUMBAI METRO LINE 3**

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 82        |
| Trees to be removed  | 6         |
| <b>Total Trees</b>   | <b>88</b> |

**3. TREE INVENTORY DETAILS AT UGC-03**

| Summary of Tree Survey at Mumbai Central Station |          |             |                                |                     |                      |                     |                                |
|--|----------|-------------|--------------------------------|---------------------|----------------------|---------------------|--------------------------------|
| Sr. no.  | Tree no. | Common Name | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                         |
| 1  | MC-01    | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 7'                  | 15'                  | To be removed       | Falling within excavation line |
| 2  | Mc-02    | Wad         | <i>Ficus Benghalensis</i>      | 8'                  | 14'                  | To be removed       | Falling within excavation line |
| 3  | MC-03    | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 6'                  | 12'                  | To be removed       | Falling within excavation line |
| 4  | MC-04    | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 4'                  | 7'                   | To be removed       | Falling within excavation line |
| 5  | MC-05    | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 4'                  | 8'                   | To be removed       | Falling within excavation line |
| 6  | MC-06    | Pimpal      | <i>Ficus Religiosa</i>         | 3'                  | 12'                  | To be removed       | Falling within excavation line |
| 7  | MC-07    | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 3'                  | 9'                   | To be removed       | Falling within excavation line |
| 8  | MC-08    | Asupalav    | <i>polyalthia longifolia</i>   | 5'                  | 27'                  | To be removed       | Falling within excavation line |
| 9  | MC-09    | Asupalav    | <i>polyalthia longifolia</i>   | 4'                  | 39'                  | To be removed       | Falling within excavation line |
| 10   | MC-10    | Pimpal      | <i>Ficus Religiosa</i>         | 4'                  | 33'                  | To be removed       | Falling within excavation line |
| 11   | MC-11    | Asupalav    | <i>polyalthia longifolia</i>   | 4'                  | 39'                  | To be removed       | Falling within excavation line |
| 12   | MC-12    | Putranjiva  | <i>Putranjiva</i>              | 6''                 | 8'                   | To be removed       | Falling within excavation line |
| 13   | MC-13    | Bael        | <i>Aegle Marmelos</i>          | 5''                 | 6'                   | To be removed       | Falling within excavation line |
| 14   | MC-14    | Wad         | <i>Ficus Benghalensis</i>      | 2'                  | 7'                   | To be removed       | Falling within excavation line |
| 15   | MC-15    | Pimpal      | <i>Ficus Religiosa</i>         | 6''                 | 8'                   | To be removed       | Falling within excavation line |
| 16   | MC-16    | Bhend       | <i>Thespesia Populnea</i>      | 6'                  | 9'                   | To be removed       | Falling within excavation line |
| 17   | MC-17    | Deshi badam | <i>Terminalia Catappa</i>      | 2'                  | 5'                   | To be removed       | Falling within excavation line |
| 18   | MC-18    | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 4'                  | 11'                  | To be removed       | Falling within excavation line |
| 19   | MC-19    | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 3'                  | 8'                   | To be removed       | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |       |             |                                   |    |     |               |                                |
|----|-------|-------------|-----------------------------------|----|-----|---------------|--------------------------------|
| 20 | MC-20 | Sonmohar    | <i>Peltophorum Pterocarpum</i>    | 4' | 10' | To be removed | Falling within excavation line |
| 21 | MC-21 | Sonmohar    | <i>Peltophorum Pterocarpum</i>    | 5' | 11' | To be removed | Falling within excavation line |
| 22 | MC-22 | Akashneem   | <i>Millingtonia Hortensis</i>     | 1' | 15' | To be removed | Falling within excavation line |
| 23 | MC-23 | Tuti        | <i>Morus Alba</i>                 | 2' | 4'  | To be removed | Falling within excavation line |
| 24 | MC-24 | Akashneem   | <i>Millingtonia Hortensis</i>     | 2' | 4'  | To be removed | Falling within excavation line |
| 25 | MC-25 | Akashneem   | <i>Millingtonia Hortensis</i>     | 1' | 5'  | To be removed | Falling within excavation line |
| 26 | MC-26 | Karanj      | <i>Pongamia Pinnata</i>           | 4' | 7'  | To be removed | Falling within excavation line |
| 27 | MC-27 | Neem        | <i>Azadiracta Indica</i>          | 2' | 6'  | To be removed | Falling within excavation line |
| 28 | MC-28 | Deshi badam | <i>Terminalia Catappa</i>         | 2' | 5'  | To be removed | Falling within excavation line |
| 29 | MC-29 | Asupalav    | <i>polyalthia longifolia</i>      | 4' | 6'  | To be removed | Falling within excavation line |
| 30 | MC-30 | Areca Palm  | <i>Chrysalidocarpus Lutescens</i> | 1' | 5'  | To be removed | Falling within excavation line |
| 31 | MC-31 | Sonmohar    | <i>Peltophorum Pterocarpum</i>    | 3' | 7'  | To be removed | Falling within excavation line |
| 32 | MC-32 | Sonmohar    | <i>Peltophorum Pterocarpum</i>    | 2' | 27' | To be removed | Falling within excavation line |
| 33 | MC-33 | Sonmohar    | <i>Peltophorum Pterocarpum</i>    | 6' | 14' | To be removed | Falling within excavation line |
| 34 | MC-34 | Asupalav    | <i>polyalthia longifolia</i>      | 2' | 33' | To be removed | Falling within excavation line |
| 35 | MC-35 | Sonmohar    | <i>Peltophorum Pterocarpum</i>    | 8' | 12' | To be removed | Falling within excavation line |
| 36 | MC-36 | Bhend       | <i>Thespesia Populnea</i>         | 3' | 9'  | To be removed | Falling within excavation line |
| 37 | MC-37 | Tetu        | <i>Oroxylum Indicum</i>           | 1' | 20' | To be removed | Falling within excavation line |
| 38 | MC-38 | Amba        | <i>Mangifera Indica</i>           | 1' | 12' | To be removed | Falling within excavation line |
| 39 | MC-39 | Royal palm  | <i>Roystonea Regia</i>            | 3' | 39' | To be removed | Falling within excavation line |
| 40 | MC-40 | Royal palm  | <i>Roystonea Regia</i>            | 3' | 39' | To be removed | Falling within excavation line |
| 41 | MC-41 | Royal palm  | <i>Roystonea Regia</i>            | 3' | 39' | To be removed | Falling within excavation line |
| 42 | MC-42 | Royal palm  | <i>Roystonea Regia</i>            | 3' | 39' | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |       |                   |                                    |     |     |               |                                |
|----|-------|-------------------|------------------------------------|-----|-----|---------------|--------------------------------|
| 43 | MC-43 | Asupalav          | <i>polyalthia longifolia</i>       | 3'  | 33' | To be removed | Falling within excavation line |
| 44 | MC-44 | Kala umber        | <i>Ficus Hispida</i>               | 10" | 12' | To be removed | Falling within excavation line |
| 45 | MC-45 | Asupalav          | <i>polyalthia longifolia</i>       | 3'  | 30' | To be removed | Falling within excavation line |
| 46 | MC-46 | Kala umber        | <i>Ficus Hispida</i>               | 10" | 15' | To be removed | Falling within excavation line |
| 47 | MC-47 | Kala umber        | <i>Ficus Hispida</i>               | 10" | 9'  | To be removed | Falling within excavation line |
| 48 | MC-48 | Sonmohar          | <i>Peltophorum<br/>Pterocarpum</i> | 10" | 20' | To be removed | Falling within excavation line |
| 49 | MC-49 | Amba              | <i>Mangifera Indica</i>            | 3'  | 27' | To be removed | Falling within excavation line |
| 50 | MC-50 | Jambhul           | <i>Syzygium Cumini</i>             | 9'  | 51' | To be removed | Falling within excavation line |
| 51 | MC-51 | Asupalav          | <i>polyalthia longifolia</i>       | 2'  | 18' | To be removed | Falling within excavation line |
| 52 | MC-52 | Jambhul           | <i>Syzygium Cumini</i>             | 8'  | 45' | To be removed | Falling within excavation line |
| 53 | MC-53 | Sonmohar          | <i>Peltophorum<br/>Pterocarpum</i> | 2'  | 27' | To be removed | Falling within excavation line |
| 54 | MC-54 | Peru (Dead)       | <i>Psidium Guajava</i>             | 1'  | 18' | To be removed | Falling within excavation line |
| 55 | MC-55 | Naral             | <i>Cocos Nucifera</i>              | 3'  | 30' | To be removed | Falling within excavation line |
| 56 | MC-56 | Asupalav          | <i>polyalthia longifolia</i>       | 2'  | 24' | To be removed | Falling within excavation line |
| 57 | MC-57 | Jambhul           | <i>Syzygium Cumini</i>             | 1'  | 18' | To be removed | Falling within excavation line |
| 58 | MC-58 | Kadamba           | <i>Anthocephalus<br/>Cadamba</i>   | 2'  | 36' | To be removed | Falling within excavation line |
| 59 | MC-59 | Amba              | <i>Mangifera Indica</i>            | 2'  | 30' | To be removed | Falling within excavation line |
| 60 | MC-60 | Sonmohar          | <i>Peltophorum<br/>Pterocarpum</i> | 5'  | 42' | To be removed | Falling within excavation line |
| 61 | MC-61 | Saptparni         | <i>Alstonia Scholaris</i>          | 2'  | 48' | To be removed | Falling within excavation line |
| 62 | MC-62 | Asupalav          | <i>polyalthia longifolia</i>       | 2'  | 21' | To be removed | Falling within excavation line |
| 63 | MC-63 | Sonmohar          | <i>Peltophorum<br/>Pterocarpum</i> | 2'  | 15' | To be removed | Falling within excavation line |
| 64 | MC-64 | Sonmohar          | <i>Peltophorum<br/>Pterocarpum</i> | 8'  | 12' | To be removed | Falling within excavation line |
| 65 | MC-65 | Pandhara<br>Savar | <i>Ceiba Pentandra</i>             | 3'  | 12' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |         |                     |                              |       |     |               |                                |
|----|---------|---------------------|------------------------------|-------|-----|---------------|--------------------------------|
| 66 | MC-66   | Rain Tree<br>(Dead) | <i>Samanea Saman</i>         | 6'    | 14' | To be removed | Falling within excavation line |
| 67 | MC-67   | Deshi badam         | <i>Terminalia Catappa</i>    | 1'    | 3'  | To be removed | Falling within excavation line |
| 68 | MC-68   | Pandhara<br>Savar   | <i>Ceiba Pentandra</i>       | 10'   | 22' | To be removed | Falling within excavation line |
| 69 | MC-69   | Gulmohar            | <i>Delonix Regia</i>         | 3'    | 12' | To be removed | Falling within excavation line |
| 70 | MC-70   | Umber               | <i>Ficus Glomerata</i>       | 3'    | 11' | To be removed | Falling within excavation line |
| 71 | MC-71   | Jamun               | <i>Syzygium Cumini</i>       | 3'    | 9'  | To be removed | Falling within excavation line |
| 72 | MC-72   | Pimpal              | <i>Ficus Religiosa</i>       | 5'    | 11' | To be removed | Falling within excavation line |
| 73 | MC-73   | Bhend               | <i>Thespesia Populnea</i>    | 3'    | 9'  | To be removed | Falling within excavation line |
| 74 | MC-74   | Pimpal              | <i>Ficus Religiosa</i>       | 3'    | 9'  | To be removed | Falling within excavation line |
| 75 | MC-75   | Pimpal              | <i>Ficus Religiosa</i>       | 1'    | 7'  | To be removed | Falling within excavation line |
| 76 | MC-76   | Rain Tree           | <i>Samanea Saman</i>         | 4'    | 8'  | To be removed | Falling within excavation line |
| 77 | E/MC-77 | Asupalav            | <i>polyalthia longifolia</i> | 1'3"  | 25' | To be removed | Falling within excavation line |
| 78 | E/MC-78 | Madhumalti          | <i>Quisqualis Indica</i>     | 1'8"  | 23' | To be removed | Falling within excavation line |
| 79 | E/MC-79 | Royal palm          | <i>Roystonea Regia</i>       | 5'    | 30' | To be removed | Falling within excavation line |
| 80 | E/MC-80 | Asupalav            | <i>polyalthia longifolia</i> | 1'4"  | 23' | To be removed | Falling within excavation line |
| 81 | E/MC-81 | Asupalav            | <i>polyalthia longifolia</i> | 9"    | 23' | To be removed | Falling within excavation line |
| 82 | E/MC-82 | Bhend               | <i>Thespesia Populnea</i>    | 3'    | 25' | To be removed | Falling within excavation line |
| 83 | E/MC-83 | Kalaumber           | <i>Ficus Hispida</i>         | 2'2"  | 13' | To be removed | Falling within excavation line |
| 84 | E/MC-84 | Royal palm          | <i>Roystonea Regia</i>       | 7'    | 30' | To be removed | Falling within excavation line |
| 85 | E/MC-85 | JANGLI BADAM        | <i>Sterculiafoetida</i>      | 3'1"  | 26' | To be removed | Falling within excavation line |
| 86 | E/MC-86 | Asupalav            | <i>polyalthia longifolia</i> | 1'9"  | 23' | To be removed | Falling within excavation line |
| 87 | E/MC-87 | JANGLI BADAM        | <i>Sterculiafoetida</i>      | 3'1"  | 30' | To be removed | Falling within excavation line |
| 88 | E/MC-88 | Royal palm          | <i>Roystonea Regia</i>       | 5'    | 30' | To be removed | Falling within excavation line |
| 89 | E/MC-89 | Nilgiri             | <i>Eucalyptus Citridora</i>  | 7'    | 40' | To be removed | Falling within excavation line |
| 90 | E/MC-90 | JANGLI BADAM        | <i>Sterculiafoetida</i>      | 3'1"  | 30' | To be removed | Falling within excavation line |
| 91 | E/MC-91 | JANGLI BADAM        | <i>Sterculiafoetida</i>      | 2'9"  | 23' | To be removed | Falling within excavation line |
| 92 | E/MC-92 | Asupalav            | <i>polyalthia longifolia</i> | 1'10" | 20' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |          |               |                                    |       |     |                |                                    |
|-----|----------|---------------|------------------------------------|-------|-----|----------------|------------------------------------|
| 93  | E/MC-93  | Chafa         | <i>Plumeria alba</i>               | 1'6"  | 10' | To be removed  | Falling within excavation line     |
| 94  | E/MC-94  | Chafa         | <i>Plumeria alba</i>               | 1'1"  | 7'  | To be removed  | Falling within excavation line     |
| 95  | E/MC-95  | Chafa         | <i>Plumeria alba</i>               | 1'4"  | 8'  | To be removed  | Falling within excavation line     |
| 96  | E/MC-96  | Gulmohar      | <i>Delonix Regia</i>               | 4'    | 28' | To be removed  | Falling within excavation line     |
| 97  | E/MC-97  | Naral         | <i>Cocos Nucifera</i>              | 3'10" | 28' | To be removed  | Falling within excavation line     |
| 98  | E/MC-98  | Sonmohar      | <i>Peltophorum<br/>Pterocarpum</i> | 2'11" | 20' | To be retained | Falling outside of excavation area |
| 99  | E/MC-99  | Cherry        | <i>Prunus Avium</i>                | 1'3"  | 17' | To be retained | Falling outside of excavation area |
| 100 | E/MC-100 | Xmax Tree     | <i>Auroucarla<br/>Columnarls</i>   | 3'1"  | 30' | To be removed  | Falling within excavation line     |
| 101 | E/MC-101 | Jamun         | <i>Syzygium Cumini</i>             | 2'    | 22' | To be removed  | Falling within excavation line     |
| 102 | E/MC-98  | Sonmohar      | <i>Peltophorum<br/>Pterocarpum</i> | 2'11" | 20' | To be removed  | Falling within excavation line     |
| 103 | E/MC-99  | Cherry        | <i>Prunus Avium</i>                | 1'3"  | 17' | To be removed  | Falling within excavation line     |
| 104 | E/MC-102 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 15' | To be removed  | Falling within excavation line     |
| 105 | E/MC-103 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 15' | To be removed  | Falling within excavation line     |
| 106 | E/MC-104 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 13' | To be removed  | Falling within excavation line     |
| 107 | E/MC-105 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 13' | To be removed  | Falling within excavation line     |
| 108 | E/MC-106 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 13' | To be removed  | Falling within excavation line     |
| 109 | E/MC-107 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 15' | To be removed  | Falling within excavation line     |
| 110 | E/MC-108 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 13' | To be removed  | Falling within excavation line     |
| 111 | E/MC-109 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 13' | To be removed  | Falling within excavation line     |
| 112 | E/MC-110 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 13' | To be removed  | Falling within excavation line     |
| 113 | E/MC-111 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 13' | To be removed  | Falling within excavation line     |
| 114 | E/MC-112 | Khajur        | <i>Phoenix dactylifera</i>         | 3'    | 13' | To be removed  | Falling within excavation line     |
| 115 | E/MC-113 | Khajur (dead) | <i>Phoenix dactylifera</i>         | 2.5,  | 6'  | To be removed  | Falling within excavation line     |
| 116 | E/MC-114 | Palm tree     | <i>Chamaerops</i>                  | 2,    | 23' | To be removed  | Falling within excavation line     |
| 117 | E/MC-115 | Rubber Tree   | <i>Ficus Elastica</i>              | 2'    | 25' | To be removed  | Falling within excavation line     |
| 118 | E/MC-116 | Deshi badam   | <i>Terminalia catappa</i>          | 2'3"  | 23' | To be removed  | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |          |                       |                                   |      |     |               |                                |
|-----|----------|-----------------------|-----------------------------------|------|-----|---------------|--------------------------------|
| 119 | E/MC-117 | Asupalav              | <i>polyalthia longifolia</i>      | 2'9" | 28' | To be removed | Falling within excavation line |
| 120 | E/MC-118 | Palm Tree             | <i>Chamaerops</i>                 | 1'   | 25' | To be removed | Falling within excavation line |
| 121 | E/MC-119 | Asupalav              | <i>polyalthia longifolia</i>      | 2'5" | 21' | To be removed | Falling within excavation line |
| 122 | E/MC-120 | Asupalav              | <i>polyalthia longifolia</i>      | 1'9" | 20' | To be removed | Falling within excavation line |
| 123 | E/MC-121 | Kanchan               | <i>Bauhinia variegata</i>         | 1'7" | 13' | To be removed | Falling within excavation line |
| 124 | E/MC-122 | Kanchan               | <i>Bauhinia variegata</i>         | 1'7" | 13' | To be removed | Falling within excavation line |
| 125 | E/MC-123 | Asupalav              | <i>polyalthia longifolia</i>      | 2'6" | 26' | To be removed | Falling within excavation line |
| 126 | E/MC-124 | Indian Cherry         |                                   | 2'   | 10' | To be removed | Falling within excavation line |
| 127 | E/MC-125 | Ficus                 | <i>Ficus benjamina</i>            | 6"   | 5'  | To be removed | Falling within excavation line |
| 128 | E/MC-126 | Kala umber            | <i>Ficus Hispida</i>              | 3'   | 15' | To be removed | Falling within excavation line |
| 129 | E/MC-127 | Kala umber            | <i>Ficus Hispida</i>              | 1'   | 12' | To be removed | Falling within excavation line |
| 130 | E/MC-128 | Pisonia               | <i>Pisonia Alba</i>               | 1'   | 10' | To be removed | Falling within excavation line |
| 131 | E/MC-129 | Ficus                 | <i>Ficus benjamina</i>            | 6"   | 6'  | To be removed | Falling within excavation line |
| 132 | E/MC-130 | Ficus                 | <i>Ficus benjamina</i>            | 6"   | 6'  | To be removed | Falling within excavation line |
| 133 | E/MC-131 | Ficus                 | <i>Ficus benjamina</i>            | 6"   | 6'  | To be removed | Falling within excavation line |
| 134 | E/MC-132 | Amba                  | <i>Mangifera Indica</i>           | 4'   | 40' | To be removed | Falling within excavation line |
| 135 | E/MC-133 | Amba                  | <i>Mangifera Indica</i>           | 3'   | 35' | To be removed | Falling within excavation line |
| 136 | E/MC-134 | Bottel Palm<br>(Dead) | <i>Hyophorbe<br/>lagenicaulis</i> | 6'   | 20' | To be removed | Falling within excavation line |
| 137 | E/MC-135 | Bottel Palm           | <i>Hyophorbe<br/>lagenicaulis</i> | 4'   | 25' | To be removed | Falling within excavation line |
| 138 | E/MC-136 | Bottel Palm           | <i>Hyophorbe<br/>lagenicaulis</i> | 8'   | 40' | To be removed | Falling within excavation line |
| 139 | E/MC-137 | Bottel Palm           | <i>Hyophorbe<br/>lagenicaulis</i> | 5'   | 35' | To be removed | Falling within excavation line |
| 140 | E/MC-138 | Naral                 | <i>Cocos Nucifera</i>             | 4'   | 50' | To be removed | Falling within excavation line |
| 141 | /MC-139  | Bottel Palm           | <i>Hyophorbe<br/>lagenicaulis</i> | 6'   | 40' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |          |                     |                               |      |     |               |                                |
|-----|----------|---------------------|-------------------------------|------|-----|---------------|--------------------------------|
| 142 | E/MC-140 | Bottel Palm         | <i>Hyophorbe lagenicaulis</i> | 5'   | 35' | To be removed | Falling within excavation line |
| 143 | E/MC-141 | Naral               | <i>Cocos Nucifera</i>         | 2'5" | 45' | To be removed | Falling within excavation line |
| 144 | E/MC-142 | Putranjiva          | <i>Putranjiva</i>             | 8'   | 60' | To be removed | Falling within excavation line |
| 145 | E/MC-143 | Putranjiva          | <i>Putranjiva</i>             | 1'   | 20' | To be removed | Falling within excavation line |
| 146 | E/MC-144 | Jangali Badam       | <i>Sterculia foetida</i>      | 2'   | 45' | To be removed | Falling within excavation line |
| 147 | E/MC-145 | Bottel Palm         | <i>Hyophorbe lagenicaulis</i> | 4'   | 40' | To be removed | Falling within excavation line |
| 148 | E/MC-146 | Jangali Badam       | <i>Sterculia foetida</i>      | 2'   | 25' | To be removed | Falling within excavation line |
| 149 | E/MC-147 | Jangali Badam       | <i>Sterculia foetida</i>      | 3'   | 45' | To be removed | Falling within excavation line |
| 150 | E/MC-148 | Asupalav            | <i>polyalthia longifolia</i>  | 10"  | 20' | To be removed | Falling within excavation line |
| 151 | E/MC-149 | Jangali Badam       | <i>Sterculia foetida</i>      | 8'   | 45' | To be removed | Falling within excavation line |
| 152 | E/MC-150 | Asupalav            | <i>polyalthia longifolia</i>  | 10"  | 20' | To be removed | Falling within excavation line |
| 153 | E/MC-151 | Asupalav            | <i>polyalthia longifolia</i>  | 10"  | 20' | To be removed | Falling within excavation line |
| 154 | E/MC-152 | Bottel Palm         | <i>Hyophorbe lagenicaulis</i> | 6'   | 25' | To be removed | Falling within excavation line |
| 155 | E/MC-153 | Asupalav            | <i>polyalthia longifolia</i>  | 1'7" | 25' | To be removed | Falling within excavation line |
| 156 | E/MC-154 | Asupalav            | <i>polyalthia longifolia</i>  | 1'8" | 25' | To be removed | Falling within excavation line |
| 157 | E/MC-155 | Asupalav            | <i>polyalthia longifolia</i>  | 1'8" | 17' | To be removed | Falling within excavation line |
| 158 | E/MC-156 | Crismas Tree (Dead) | <i>Araucaria columnaris</i>   | 2'2" | 20' | To be removed | Falling within excavation line |
| 159 | E/MC-157 | Asupalav            | <i>polyalthia longifolia</i>  | 2'4" | 22' | To be removed | Falling within excavation line |
| 160 | E/MC-158 | Asupalav            | <i>polyalthia longifolia</i>  | 2'3" | 21' | To be removed | Falling within excavation line |
| 161 | E/MC-159 | Asupalav            | <i>polyalthia longifolia</i>  | 2'5" | 23' | To be removed | Falling within excavation line |
| 162 | E/MC-160 | Asupalav            | <i>polyalthia longifolia</i>  | 2'3" | 35' | To be removed | Falling within excavation line |
| 163 | E/MC-161 | Asupalav            | <i>polyalthia longifolia</i>  | 2'2" | 30' | To be removed | Falling within excavation line |
| 164 | E/MC-162 | Indian rubber tree  | <i>Hevea brasiliensis</i>     | 1'9" | 20' | To be removed | Falling within excavation line |
| 165 | E/MC-163 | Asupalav            | <i>polyalthia longifolia</i>  | 6"   | 15' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |          |          |                              |      |     |               |                                |
|-----|----------|----------|------------------------------|------|-----|---------------|--------------------------------|
| 166 | E/MC-164 | Asupalav | <i>polyalthia longifolia</i> | 1'2" | 18" | To be removed | Falling within excavation line |
| 167 | E/MC-165 | umber    | <i>Ficus Glomerata</i>       | 6'   | 23' | To be removed | Falling within excavation line |
| 168 | E/MC-166 | Gulmohar | <i>Delonix Regia</i>         | 5'9" | 28' | To be removed | Falling within excavation line |
| 169 | E/MC-167 | Pimpal   | <i>Ficus Religiosa</i>       | 8'   | 26' | To be removed | Falling within excavation line |
| 170 | E/MC-168 | Jambhul  | <i>Syzygium Cumini</i>       | 2'1" | 23' | To be removed | Falling within excavation line |
| 171 | E/MC-169 | Asupalav | <i>polyalthia longifolia</i> | 3'6" | 22' | To be removed | Falling within excavation line |
| 172 | E/MC-170 | Asupalav | <i>polyalthia longifolia</i> | 3'8" | 23' | To be removed | Falling within excavation line |
| 173 | E/MC-171 | Asupalav | <i>polyalthia longifolia</i> | 3'3" | 20' | To be removed | Falling within excavation line |
| 174 | E/MC-172 | Asupalav | <i>polyalthia longifolia</i> | 2'9" | 20' | To be removed | Falling within excavation line |
| 175 | E/MC-173 | umber    | <i>Ficus Glomerata</i>       | 3'9" | 30' | To be removed | Falling within excavation line |
| 176 | E/MC-174 | Pimpal   | <i>Ficus Religiosa</i>       | 5'2" | 40' | To be removed | Falling within excavation line |
| 177 | E/MC-175 | Amba     | <i>Mangifera Indica</i>      | 4'9" | 35' | To be removed | Falling within excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 2          |
| Trees to be removed  | 175        |
| <b>Total Trees</b>   | <b>177</b> |

| Summary of Tree Survey at Mahalakshmi Station |             |             |                                |                     |                      |                     |                                    |
|---|-------------|-------------|--------------------------------|---------------------|----------------------|---------------------|------------------------------------|
| Sr. no.                                       | Tree no.    | Common Name | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                             |
| 1   | M-3/E/MS-01 | Gulmohar    | <i>Delonix regia</i>           | 3'                  | 5'                   | To be reatined      | Falling outside of excavation area |
| 2   | M-3/E/MS-02 | Umbar       | <i>Ficus glomerata</i>         | 1'                  | 4'                   | To be reatined      | Falling outside of excavation area |
| 3   | M-3/E/MS-03 | Umbar       | <i>Ficus glomerata</i>         | 1'                  | 5'                   | To be reatined      | Falling outside of excavation area |
| 4   | M-3/E/MS-04 | Gulmohar    | <i>Delonix regia</i>           | 3'                  | 7'                   | To be reatined      | Falling outside of excavation area |
| 5   | M-3/E/MS-05 | Rain Tree   | <i>Samanea saman</i>           | 2'                  | 8'                   | To be reatined      | Falling outside of excavation area |
| 6   | M-3/E/MS-06 | Kala Umber  | <i>Ficus hispida</i>           | 1'                  | 10'                  | To be reatined      | Falling outside of excavation area |
| 7   | M-3/E/MS-07 | Jambhul     | <i>Syzygium cumini</i>         | 3'                  | 9'                   | To be reatined      | Falling outside of excavation area |
| 8   | M-3/E/MS-08 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3'                  | 9'                   | To be reatined      | Falling outside of excavation area |
| 9   | M-3/E/MS-09 | Pimpal      | <i>Ficus religiosa</i>         | 5'6"                | 55'                  | To be reatined      | Falling outside of excavation area |
| 10  | M-3/E/MS-10 | Pimpal      | <i>Ficus religiosa</i>         | 6'6"                | 55'                  | To be reatined      | Falling outside of excavation area |
| 11  | M-3/E/MS-11 | Karanj      | <i>Pongamia pinnata</i>        | 2'                  | 5'                   | To be removed       | Falling within excavation line     |
| 12  | M-3/E/MS-12 | Umber       | <i>Ficus glomerata</i>         | 4"                  | 7'                   | To be removed       | Falling within excavation line     |
| 13  | M-3/E/MS-13 | Pimpal      | <i>Ficus religiosa</i>         | 1'                  | 7'                   | To be removed       | Falling within excavation line     |
| 14  | M-3/E/MS-14 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 2'                  | 5'                   | To be removed       | Falling within excavation line     |
| 15  | M-3/E/MS-15 | Jambhul     | <i>Syzygium cumini</i>         | 1'                  | 12'                  | To be removed       | Falling within excavation line     |
| 16  | M-3/E/MS-16 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3'                  | 5'                   | To be removed       | Falling within excavation line     |
| 17  | M-3/E/MS-17 | Naral       | <i>cocos nucifera</i>          | 2'                  | 5'                   | To be removed       | Falling within excavation line     |
| 18  | M-3/E/MS-18 | Asupalav    | <i>Polyalthia longifolia</i>   | 2'                  | 5'                   | To be removed       | Falling within excavation line     |
| 19  | M-3/E/MS-19 | Wad         | <i>Ficus Benghalensis</i>      | 3'                  | 7'                   | To be removed       | Falling within excavation line     |
| 20  | M-3/E/MS-20 | Gulmohar    | <i>Delonix regia</i>           | 7'                  | 13'                  | To be removed       | Falling within excavation line     |
| 21  | M-3/E/MS-21 | Rain Tree   | <i>Samanea saman</i>           | 8'                  | 12'                  | To be removed       | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |             |                     |                                    |     |     |               |                                |
|----|-------------|---------------------|------------------------------------|-----|-----|---------------|--------------------------------|
| 22 | M-3/E/MS-22 | Tabebuia            | <i>tabeula pentaphyl</i>           | 7"  | 10' | To be removed | Falling within excavation line |
| 23 | M-3/E/MS-23 | Rain Tree<br>(Dead) | <i>Samanea saman</i>               | 7'  | 8'  | To be removed | Falling within excavation line |
| 24 | M-3/E/MS-24 | Sonmohar            | <i>Peltophorum<br/>pterocarpum</i> | 3'  | 8'  | To be removed | Falling within excavation line |
| 25 | M-3/E/MS-25 | Sonmohar            | <i>Peltophorum<br/>pterocarpum</i> | 3'  | 8'  | To be removed | Falling within excavation line |
| 26 | M-3/E/MS-26 | Sonmohar            | <i>Peltophorum<br/>pterocarpum</i> | 3'  | 8'  | To be removed | Falling within excavation line |
| 27 | M-3/E/MS-27 | Sonmohar            | <i>Peltophorum<br/>pterocarpum</i> | 3'  | 8'  | To be removed | Falling within excavation line |
| 28 | M-3/E/MS-28 | Pimpal              | <i>Ficus religiosa</i>             | 1'  | 7'  | To be removed | Falling within excavation line |
| 29 | M-3/E/MS-29 | Sonmohar            | <i>Peltophorum<br/>pterocarpum</i> | 3'  | 11' | To be removed | Falling within excavation line |
| 30 | M-3/E/MS-30 | Bhend               | <i>Thespesia populnea</i>          | 4'  | 12' | To be removed | Falling within excavation line |
| 31 | M-3/E/MS-31 | Pimpal              | <i>Ficus religiosa</i>             | 10' | 13' | To be removed | Falling within excavation line |
| 32 | M-3/E/MS-32 | Wad                 | <i>Ficus Benghalensis</i>          | 10' | 12' | To be removed | Falling within excavation line |
| 33 | M-3/E/MS-33 | Sonmohar            | <i>Sonmohar</i>                    | 3'  | 7'  | To be removed | Falling within excavation line |
| 34 | M-3/E/MS-34 | Pimpal              | <i>Ficus religiosa</i>             | 5'  | 12' | To be removed | Falling within excavation line |
| 35 | M-3/E/MS-35 | Pimpal              | <i>Ficus religiosa</i>             | 2'  | 12' | To be removed | Falling within excavation line |
| 36 | M-3/E/MS-36 | Umber               | <i>Ficus glomerata</i>             | 5'  | 24' | To be removed | Falling within excavation line |
| 37 | M-3/E/MS-37 | Asupalav            | <i>Polyalthia longifolia</i>       | 2'  | 21' | To be removed | Falling within excavation line |
| 38 | M-3/E/MS-38 | Kala Umber          | <i>Ficus hispida</i>               | 2'  | 5'  | To be removed | Falling within excavation line |
| 39 | M-3/E/MS-39 | Sonmohar            | <i>Sonmohar</i>                    | 1'  | 9'  | To be removed | Falling within excavation line |
| 40 | M-3/E/MS-40 | Sonmohar            | <i>Peltophorum<br/>pterocarpum</i> | 8"  | 4'  | To be removed | Falling within excavation line |
| 41 | M-3/E/MS-41 | Karanj              | <i>Pongamia pinnata</i>            | 1'  | 8'  | To be removed | Falling within excavation line |
| 42 | M-3/E/MS-42 | Rain Tree           | <i>Samanea saman</i>               | 8'  | 15' | To be removed | Falling within excavation line |
| 43 | M-3/E/MS-43 | Amba                | <i>Mangifera indica</i>            | 3'  | 39' | To be removed | Falling within excavation line |
| 44 | M-3/E/MS-44 | Naral               | <i>cocus nucifera</i>              | 2'  | 9'  | To be removed | Falling within excavation line |
| 45 | M-3/E/MS-45 | Asupalav            | <i>Polyalthia longifolia</i>       | 4'  | 45' | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |             |            |                                |      |     |                |                                    |
|----|-------------|------------|--------------------------------|------|-----|----------------|------------------------------------|
| 46 | M-3/E/MS-46 | Asupalav   | <i>Polyalthia longifolia</i>   | 4'   | 45' | To be removed  | Falling within excavation line     |
| 47 | M-3/E/MS-47 | Amba       | <i>Mangifera indica</i>        | 8'   | 51' | To be removed  | Falling within excavation line     |
| 48 | M-3/E/MS-48 | Pimpal     | <i>Ficus religiosa</i>         | 12'  | 51' | To be removed  | Falling within excavation line     |
| 49 | M-3/E/MS-49 | Umber      | <i>Ficus glomerata</i>         | 2    | 18' | To be removed  | Falling within excavation line     |
| 50 | M-3/E/MS-50 | Asupalav   | <i>Polyalthia longifolia</i>   | 2'   | 36' | To be removed  | Falling within excavation line     |
| 51 | M-3/E/MS-51 | Umber      | <i>Ficus glomerata</i>         | 12   | 36' | To be removed  | Falling within excavation line     |
| 52 | M-3/E/MS-52 | Naral      | <i>cocos nucifera</i>          | 2'   | 12' | To be removed  | Falling within excavation line     |
| 53 | M-3/E/MS-53 | Naral      | <i>cocos nucifera</i>          | 2'   | 12' | To be removed  | Falling within excavation line     |
| 54 | M-3/E/MS-54 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 2'   | 7'  | To be removed  | Falling within excavation line     |
| 55 | M-3/E/MS-55 | Amba       | <i>Mangifera indica</i>        | 1'   | 12' | To be removed  | Falling within excavation line     |
| 56 | M-3/E/MS-56 | kashid     | <i>cassia slamea</i>           | 2'   | 5'  | To be removed  | Falling within excavation line     |
| 57 | M-3/E/MS-57 | Pimpal     | <i>Ficus religiosa</i>         | 9'   | 9'  | To be removed  | Falling within excavation line     |
| 58 | M-3/E/MS-58 | Naral      | <i>cocos nucifera</i>          | 2'   | 40' | To be removed  | Falling within excavation line     |
| 59 | M-3/E/MS-59 | Neem       | <i>Azadiracta indica</i>       | 10"  | 10' | To be removed  | Falling within excavation line     |
| 60 | M-3/E/MS-60 | Ficus      | <i>ficus panda</i>             | 10"  | 10' | To be removed  | Falling within excavation line     |
| 61 | M-3/E/MS-61 | Gulmohar   | <i>Delonix regia</i>           | 3'   | 25' | To be removed  | Falling within excavation line     |
| 62 | M-3/E/MS-62 | Ficus      | <i>ficus panda</i>             | 10"  | 10' | To be removed  | Falling within excavation line     |
| 63 | M-3/E/MS-63 | Gulmohar   | <i>Delonix regia</i>           | 4'   | 9'  | To be removed  | Falling within excavation line     |
| 64 | M-3/E/MS-64 | Gulmohar   | <i>Delonix regia</i>           | 4'   | 10' | To be removed  | Falling within excavation line     |
| 65 | M-3/E/MS-65 | Gulmohar   | <i>Delonix regia</i>           | 3'   | 9'  | To be removed  | Falling within excavation line     |
| 66 | M-3/E/MS-66 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 7'4" | 50' | To be reatined | Falling outside of excavation area |
| 67 | M-3/E/MS-67 | Gulmohar   | <i>Delonix regia</i>           | 2'   | 10' | To be removed  | Falling within excavation line     |
| 68 | M-3/E/MS-68 | Gulmohar   | <i>Delonix regia</i>           | 4'   | 42' | To be removed  | Falling within excavation line     |
| 69 | M-3/E/MS-69 | Gulmohar   | <i>Delonix regia</i>           | 2'   | 9'  | To be removed  | Falling within excavation line     |
| 70 | M-3/E/MS-70 | Pimpal     | <i>Ficus religiosa</i>         | 8'   | 48' | To be removed  | Falling within excavation line     |
| 71 | M-3/E/MS-71 | Jambhul    | <i>Syzygium cumini</i>         | 6'   | 42' | To be removed  | Falling within excavation line     |
| 72 | M-3/E/MS-72 | Putranjiva | <i>Putranjiva roxburghli</i>   | 3'   | 9'  | To be removed  | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |             |             |                                |    |     |               |                                |
|----|-------------|-------------|--------------------------------|----|-----|---------------|--------------------------------|
| 73 | M-3/E/MS-73 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 4' | 39' | To be removed | Falling within excavation line |
| 74 | M-3/E/MS-74 | Bhend       | <i>Thespesia populnea</i>      | 2' | 25' | To be removed | Falling within excavation line |
| 75 | M-3/E/MS-75 | Putranjiva  | <i>Putranjiva roxburghli</i>   | 5' | 9'  | To be removed | Falling within excavation line |
| 76 | M-3/E/MS-76 | Asupalav    | <i>Polyalthia longifolia</i>   | 2' | 6'  | To be removed | Falling within excavation line |
| 77 | M-3/E/MS-77 | Asupalav    | <i>Polyalthia longifolia</i>   | 2' | 6'  | To be removed | Falling within excavation line |
| 78 | M-3/E/MS-78 | Asupalav    | <i>Polyalthia longifolia</i>   | 2' | 6'  | To be removed | Falling within excavation line |
| 79 | M-3/E/MS-79 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 5' | 39' | To be removed | Falling within excavation line |
| 80 | M-3/E/MS-80 | Phanas      | <i>Artocarpus heterop</i>      | 1' | 9'  | To be removed | Falling within excavation line |
| 81 | M-3/E/MS-81 | Chapha      | <i>Plumeria alba</i>           | 2' | 9'  | To be removed | Falling within excavation line |
| 82 | M-3/E/MS-82 | Bhend       | <i>Thespesia populnea</i>      | 2' | 21' | To be removed | Falling within excavation line |
| 83 | M-3/E/MS-83 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 2' | 36' | To be removed | Falling within excavation line |
| 84 | M-3/E/MS-84 | Karanj      | <i>Pongamia pinnata</i>        | 3' | 33' | To be removed | Falling within excavation line |
| 85 | M-3/E/MS-85 | Umber       | <i>Ficus glomerata</i>         | 2' | 21' | To be removed | Falling within excavation line |
| 86 | M-3/E/MS-86 | Shewga      | <i>Moringa Oliefera</i>        | 3' | 27' | To be removed | Falling within excavation line |
| 87 | M-3/E/MS-87 | Chafa       | <i>Plumeria alba</i>           | 3' | 15' | To be removed | Falling within excavation line |
| 88 | M-3/E/MS-88 | Kailashpati | <i>Kailashpati</i>             | 2' | 9'  | To be removed | Falling within excavation line |
| 89 | M-3/E/MS-89 | X mas tree  | <i>Auroucaria columnaris</i>   | 2' | 30' | To be removed | Falling within excavation line |
| 90 | M-3/E/MS-90 | Chapha      | <i>Plumeria alba</i>           | 2' | 9'  | To be removed | Falling within excavation line |
| 91 | M-3/E/MS-91 | Aus. Babhul | <i>Acacia Auriculiform</i>     | 2' | 30' | To be removed | Falling within excavation line |
| 92 | M-3/E/MS-92 | Chapha      | <i>Plumeria alba</i>           | 2' | 9'  | To be removed | Falling within excavation line |
| 93 | M-3/E/MS-93 | Apta        | <i>Bauhinia Racemosa</i>       | 3' | 24' | To be removed | Falling within excavation line |
| 94 | M-3/E/MS-94 | Aus. Babhul | <i>Acacia Auriculiform</i>     | 2' | 36' | To be removed | Falling within excavation line |
| 95 | M-3/E/MS-95 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 1' | 18' | To be removed | Falling within excavation line |
| 96 | M-3/E/MS-96 | Sonmohar    | <i>Peltophorum pterocarpum</i> | 1' | 24' | To be removed | Falling within excavation line |
| 97 | M-3/E/MS-97 | Pimpal      | <i>Ficus religiosa</i>         | 8' | 54' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |              |                              |                                |    |     |               |                                |
|-----|--------------|------------------------------|--------------------------------|----|-----|---------------|--------------------------------|
| 98  | M-3/E/MS-98  | Nandarukh                    | <i>Ficus benjamina</i>         | 5' | 36' | To be removed | Falling within excavation line |
| 99  | M-3/E/MS-99  | Aus. Babhul                  | <i>Acacia Auriculiform</i>     | 2' | 39' | To be removed | Falling within excavation line |
| 100 | M-3/E/MS-100 | Sonmohar                     | <i>Peltophorum pterocarpum</i> | 2' | 27' | To be removed | Falling within excavation line |
| 101 | M-3/E/MS-101 | Sonmohar                     | <i>Peltophorum pterocarpum</i> | 1' | 27' | To be removed | Falling within excavation line |
| 102 | M-3/E/MS-102 | Rubber Tree                  | <i>Ficus elastica</i>          | 6' | 24' | To be removed | Falling within excavation line |
| 103 | M-3/E/MS-103 | Jambhul                      | <i>Syzygium cumini</i>         | 1' | 9'  | To be removed | Falling within excavation line |
| 104 | M-3/E/MS-104 | Sonmohar<br>(Dead)           | <i>Peltophorum pterocarpum</i> | 1' | 15' | To be removed | Falling within excavation line |
| 105 | M-3/E/MS-105 | Sonmohar                     | <i>Peltophorum pterocarpum</i> | 3' | 21' | To be removed | Falling within excavation line |
| 106 | M-3/E/MS-106 | Sonmohar                     | <i>Peltophorum pterocarpum</i> | 7' | 45' | To be removed | Falling within excavation line |
| 107 | M-3/E/MS-107 | Sonmohar                     | <i>Peltophorum pterocarpum</i> | 1' | 15' | To be removed | Falling within excavation line |
| 108 | M-3/E/MS-108 | Asupalav                     | <i>Polyalthia longifolia</i>   | 1' | 12' | To be removed | Falling within excavation line |
| 109 | M-3/E/MS-109 | Sonmohar                     | <i>Peltophorum pterocarpum</i> | 8' | 45' | To be removed | Falling within excavation line |
| 110 | M-3/E/MS-110 | Nandarukh                    | <i>Ficus benjamina</i>         | 2' | 27' | To be removed | Falling within excavation line |
| 111 | M-3/E/MS-111 | Asupalav                     | <i>Polyalthia longifolia</i>   | 2' | 15' | To be removed | Falling within excavation line |
| 112 | M-3/E/MS-112 | Bhend                        | <i>Thespesia populnea</i>      | 2' | 7'  | To be removed | Falling within excavation line |
| 113 | M-3/E/MS-113 | Chapha                       | <i>Plumeria alba</i>           | 2' | 12' | To be removed | Falling within excavation line |
| 114 | M-3/E/MS-114 | Pimpal                       | <i>Ficus religiosa</i>         | 4' | 11' | To be removed | Falling within excavation line |
| 115 | M-3/E/MS-115 | Nandarukh                    | <i>Ficus benjamina</i>         | 9' | 33' | To be removed | Falling within excavation line |
| 116 | M-3/E/MS-116 | Amba                         | <i>Mangifera indica</i>        | 1' | 9'  | To be removed | Falling within excavation line |
| 117 | M-3/E/MS-117 | Bhend                        | <i>Thespesia populnea</i>      | 2' | 24' | To be removed | Falling within excavation line |
| 118 | M-3/E/MS-118 | Amba                         | <i>Mangifera indica</i>        | 1' | 12' | To be removed | Falling within excavation line |
| 119 | M-3/E/MS-119 | Jambhul                      | <i>Syzygium cumini</i>         | 2' | 27' | To be removed | Falling within excavation line |
| 120 | M-3/E/MS-120 | Charcoal tree<br>(Dead tree) | <i>Trema Orientalis</i>        | 2' | 24' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |              |              |                                |      |     |                |                                    |
|-----|--------------|--------------|--------------------------------|------|-----|----------------|------------------------------------|
| 121 | M-3/E/MS-121 | Naral        | <i>cocus nucifera</i>          | 3'   | 33' | To be removed  | Falling within excavation line     |
| 122 | M-3/E/MS-122 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 1'   | 9'  | To be removed  | Falling within excavation line     |
| 123 | M-3/E/MS-123 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3'   | 10' | To be removed  | Falling within excavation line     |
| 124 | M-3/E/MS-124 | Umber        | <i>Ficus glomerata</i>         | 3'   | 48' | To be removed  | Falling within excavation line     |
| 125 | M-3/E/MS-125 | Chapha       | <i>Plumeria alba</i>           | 2'   | 12' | To be removed  | Falling within excavation line     |
| 126 | M-3/E/MS-126 | Chapha       | <i>Plumeria alba</i>           | 2'   | 12' | To be removed  | Falling within excavation line     |
| 127 | M-3/E/MS-127 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 1'   | 9'  | To be removed  | Falling within excavation line     |
| 128 | M-3/E/MS-128 | Chapha       | <i>Plumeria alba</i>           | 2'   | 12' | To be removed  | Falling within excavation line     |
| 129 | M-3/E/MS-129 | Jungli badam | <i>Sterculi foetida</i>        | 2'   | 21' | To be removed  | Falling within excavation line     |
| 130 | M-3/E/MS-130 | Raiawala     | <i>Cicca acida</i>             | 2'   | 15' | To be removed  | Falling within excavation line     |
| 131 | M-3/E/MS-131 | Chafa        | <i>Plumeria alba</i>           | 1'   | 10' | To be removed  | Falling within excavation line     |
| 132 | M-3/E/MS-132 | khair        | <i>Acacla catechu</i>          | 1'   | 12' | To be removed  | Falling within excavation line     |
| 133 | M-3/E/MS-133 | Dead tree    | <i>Dead tree</i>               | 0.10 | 20' | To be removed  | Falling within excavation line     |
| 134 | M-3/E/MS-134 | Pimpal       | <i>Ficus religiosa</i>         | 14'  | 51' | To be reatined | Falling outside of excavation area |
| 135 | M-3/E/MS-135 | Amba         | <i>Mangifera indica</i>        | 9"   | 6'  | To be reatined | Falling outside of excavation area |
| 136 | M-3/E/MS-136 | Dead tree    | <i>Dead tree</i>               | -    | -   | To be removed  | Falling within excavation line     |
| 137 | M-3/E/MS-137 | Amba         | <i>Mangifera indica</i>        | 10"  | 15' | To be reatined | Falling outside of excavation area |
| 138 | M-3/E/MS-138 | Asupalav     | <i>Polyalthia longifolia</i>   | 6"   | 12' | To be reatined | Falling outside of excavation area |
| 139 | M-3/E/MS-139 | Amba         | <i>Mangifera indica</i>        | 10"  | 12' | To be reatined | Falling outside of excavation area |
| 140 | M-3/E/MS-140 | Amba         | <i>Mangifera indica</i>        | 7"   | 10' | To be reatined | Falling outside of excavation area |
| 141 | M-3/E/MS-141 | Amba         | <i>Mangifera indica</i>        | 1'6" | 15' | To be reatined | Falling outside of excavation area |
| 142 | M-3/E/MS-142 | Amba         | <i>Mangifera indica</i>        | 1'6" | 20' | To be reatined | Falling outside of excavation area |
| 143 | M-3/E/MS-143 | Chapha       | <i>Plumeria alba</i>           | 9"   | 9'  | To be reatined | Falling outside of excavation area |
| 144 | M-3/E/MS-144 | Peru         | <i>Psidium guajaya</i>         | 1'4" | 10' | To be reatined | Falling outside of excavation area |
| 145 | M-3/E/MS-145 | Amba         | <i>Mangifera indica</i>        | 1'   | 15' | To be removed  | Falling within excavation line     |
| 146 | M-3/E/MS-146 | Chapha       | <i>Plumeria alba</i>           | 1'   | 6'  | To be removed  | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |              |            |                                |      |     |                |                                    |
|-----|--------------|------------|--------------------------------|------|-----|----------------|------------------------------------|
| 147 | M-3/E/MS-147 | Chapha     | <i>Plumeria alba</i>           | 1'   | 6'  | To be removed  | Falling within excavation line     |
| 148 | M-3/E/MS-148 | Umber      | <i>Ficus glomerata</i>         | 2'   | 12' | To be removed  | Falling within excavation line     |
| 149 | M-3/E/MS-149 | Kala Umber | <i>Ficus hispida</i>           | 1'   | 15' | To be removed  | Falling within excavation line     |
| 150 | M-3/E/MS-150 | Pimpal     | <i>Ficus religiosa</i>         | 1'   | 15' | To be removed  | Falling within excavation line     |
| 151 | M-3/E/MS-151 | Pimpal     | <i>Ficus religiosa</i>         | 1'   | 15' | To be removed  | Falling within excavation line     |
| 152 | M-3/E/MS-152 | Pimpal     | <i>Ficus religiosa</i>         | 3'   | 25' | To be removed  | Falling within excavation line     |
| 153 | M-3/E/MS-01  | Gulmohar   | <i>Delonix regia</i>           | 3'   | 5'  | To be retained | Falling outside of excavation area |
| 154 | M-3/E/MS-02  | Umbar      | <i>Ficus glomerata</i>         | 1'   | 4'  | To be retained | Falling outside of excavation area |
| 155 | M-3/E/MS-03  | Umbar      | <i>Ficus glomerata</i>         | 1'   | 5'  | To be retained | Falling outside of excavation area |
| 156 | M-3/E/MS-04  | Gulmohar   | <i>Delonix regia</i>           | 3'   | 7'  | To be retained | Falling outside of excavation area |
| 157 | M-3/E/MS-05  | Rain Tree  | <i>Samanea saman</i>           | 2'   | 8'  | To be retained | Falling outside of excavation area |
| 158 | M-3/E/MS-06  | Kala Umber | <i>Ficus hispida</i>           | 1'   | 10' | To be retained | Falling outside of excavation area |
| 159 | M-3/E/MS-07  | Jambhul    | <i>Syzygium cumini</i>         | 3'   | 9'  | To be retained | Falling outside of excavation area |
| 160 | M-3/E/MS-08  | Sonmohar   | <i>Peltophorum pterocarpum</i> | 3'   | 9'  | To be retained | Falling outside of excavation area |
| 161 | M-3/E/MS-09  | Pimpal     | <i>Ficus religiosa</i>         | 5'6" | 55' | To be removed  | Falling within excavation line     |
| 162 | M-3/E/MS-10  | Pimpal     | <i>Ficus religiosa</i>         | 6'6" | 55' | To be removed  | Falling within excavation line     |
| 163 | M-3/E/MS-66  | Sonmohar   | <i>Peltophorum pterocarpum</i> | 7'4" | 50' | To be removed  | Falling within excavation line     |
| 164 | M-3/E/MS-134 | Pimpal     | <i>Ficus religiosa</i>         | 14'  | 51' | To be removed  | Falling within excavation line     |
| 165 | M-3/E/MS-135 | Amba       | <i>Mangifera indica</i>        | 9"   | 6'  | To be removed  | Falling within excavation line     |
| 166 | M-3/E/MS-137 | Amba       | <i>Mangifera indica</i>        | 10"  | 15' | To be removed  | Falling within excavation line     |
| 167 | M-3/E/MS-138 | Asupalav   | <i>Polyalthia longifolia</i>   | 6"   | 12' | To be removed  | Falling within excavation line     |
| 168 | M-3/E/MS-139 | Amba       | <i>Mangifera indica</i>        | 10"  | 12' | To be removed  | Falling within excavation line     |
| 169 | M-3/E/MS-140 | Amba       | <i>Mangifera indica</i>        | 7"   | 10' | To be removed  | Falling within excavation line     |
| 170 | M-3/E/MS-141 | Amba       | <i>Mangifera indica</i>        | 1'6" | 15' | To be removed  | Falling within excavation line     |
| 171 | M-3/E/MS-142 | Amba       | <i>Mangifera indica</i>        | 1'6" | 20' | To be removed  | Falling within excavation line     |
| 172 | M-3/E/MS-143 | Chapha     | <i>Plumeria alba</i>           | 9"   | 9'  | To be removed  | Falling within excavation line     |
| 173 | M-3/E/MS-144 | Peru       | <i>Psidium guajaya</i>         | 1'4" | 10' | To be removed  | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |              |            |                                |       |     |               |                                |
|-----|--------------|------------|--------------------------------|-------|-----|---------------|--------------------------------|
| 174 | M-3/E/MS-153 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 2'10" | 35' | To be removed | Falling within excavation line |
| 175 | M-3/E/MS-154 | Rain tree  | <i>Samanea saman</i>           | 3'6"  | 35' | To be removed | Falling within excavation line |
| 176 | M-3/E/MS-155 | Rain tree  | <i>Samanea saman</i>           | 3'    | 35' | To be removed | Falling within excavation line |
| 177 | M-3/E/MS-156 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 8'    | 40' | To be removed | Falling within excavation line |
| 178 | M-3/E/MS-157 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 5'7"  | 35' | To be removed | Falling within excavation line |
| 179 | M-3/E/MS-158 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 7'5"  | 35' | To be removed | Falling within excavation line |
| 180 | M-3/E/MS-159 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 6'6"  | 35' | To be removed | Falling within excavation line |
| 181 | M-3/E/MS-160 | Palm tree  | <i>Areaceae</i>                | 5'6"  | 30' | To be removed | Falling within excavation line |
| 182 | M-3/E/MS-161 | Royal Palm | <i>Roystonea Regia</i>         | 5'4"  | 55' | To be removed | Falling within excavation line |
| 183 | M-3/E/MS-162 | Pimpal     | <i>Ficus religiosa</i>         | 2'3"  | 28' | To be removed | Falling within excavation line |
| 184 | M-3/E/MS-163 | Pimpal     | <i>Ficus religiosa</i>         | 10'4" | 50' | To be removed | Falling within excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 29         |
| Trees to be removed  | 155        |
| <b>Total Trees</b>   | <b>184</b> |

| Summary of Tree Survey at Science Museum Station |               |             |                         |                     |                      |                     |                                |
|--|---------------|-------------|-------------------------|---------------------|----------------------|---------------------|--------------------------------|
| Sr. no.  | Tree no.      | Common Name | Botanical Name          | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                         |
| 1  | M-3/GS/SSM-1  | Neem        | Azadiracta Indica       | 2'5"                | 35'                  | To be removed       | Falling within excavation line |
| 2  | M-3/GS/SSM-2  | Umber       | Ficus Glomerata         | 3'5"                | 40'                  | To be removed       | Falling within excavation line |
| 3  | M-3/GS/SSM-3  | Sonmohar    | Peltophorum pterocarpun | 2'5"                | 42'                  | To be removed       | Falling within excavation line |
| 4  | M-3/GS/SSM-4  | Bhend       | Thespesia Populnea      | 7'                  | 55'                  | To be removed       | Falling within excavation line |
| 5  | M-3/GS/SSM-5  | Asupalav    | Polyalthia Longifolia   | 3'5"                | 55'                  | To be removed       | Falling within excavation line |
| 6  | M-3/GS/SSM-6  | Asupalav    | Polyalthia Longifolia   | 3'5"                | 40'                  | To be removed       | Falling within excavation line |
| 7  | M-3/GS/SSM-7  | Asupalav    | Polyalthia Longifolia   | 4'5"                | 40'                  | To be removed       | Falling within excavation line |
| 8  | M-3/GS/SSM-8  | Asupalav    | Polyalthia Longifolia   | 4'5"                | 35'                  | To be removed       | Falling within excavation line |
| 9  | M-3/GS/SSM-9  | Asupalav    | Polyalthia Longifolia   | 4'5"                | 40'                  | To be removed       | Falling within excavation line |
| 10   | M-3/GS/SSM-10 | Asupalav    | Polyalthia Longifolia   | 3'5"                | 45'                  | To be removed       | Falling within excavation line |
| 11   | M-3/GS/SSM-11 | Asupalav    | Polyalthia Longifolia   | 4'5"                | 50'                  | To be removed       | Falling within excavation line |
| 12   | M-3/GS/SSM-12 | Asupalav    | Polyalthia Longifolia   | 2'5"                | 35'                  | To be removed       | Falling within excavation line |
| 13   | M-3/GS/SSM-13 | Asupalav    | Polyalthia Longifolia   | 4'5"                | 35'                  | To be removed       | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |               |            |                         |      |     |               |                                |
|----|---------------|------------|-------------------------|------|-----|---------------|--------------------------------|
| 14 | M-3/GS/SSM-14 | Asupalav   | Polyalthia Longifolia   | 3'5" | 35' | To be removed | Falling within excavation line |
| 15 | M-3/GS/SSM-15 | Rain Tree  | Samanea Saman           | 5'5" | 45' | To be removed | Falling within excavation line |
| 16 | M-3/GS/SSM-16 | Asupalav   | Polyalthia Longifolia   | 3'   | 42' | To be removed | Falling within excavation line |
| 17 | M-3/GS/SSM-17 | Asupalav   | Polyalthia Longifolia   | 3'   | 35' | To be removed | Falling within excavation line |
| 18 | M-3/GS/SSM-18 | Asupalav   | Polyalthia Longifolia   | 4'5" | 30' | To be removed | Falling within excavation line |
| 19 | M-3/GS/SSM-19 | Asupalav   | Polyalthia Longifolia   | 3'5" | 42' | To be removed | Falling within excavation line |
| 20 | M-3/GS/SSM-20 | Suru       | Casuarina Equisetifolia | 2'5" | 35' | To be removed | Falling within excavation line |
| 21 | M-3/GS/SSM-21 | Suru       | Casuarina Equisetifolia | 2'5" | 35' | To be removed | Falling within excavation line |
| 22 | M-3/GS/SSM-22 | Asupalav   | Polyalthia Longifolia   | 3'   | 35' | To be removed | Falling within excavation line |
| 23 | M-3/GS/SSM-23 | Asupalav   | Polyalthia Longifolia   | 2'5" | 15' | To be removed | Falling within excavation line |
| 24 | M-3/GS/SSM-24 | Chenduphul | Parkia Biglandulosa     | 6'   | 45' | To be removed | Falling within excavation line |
| 25 | M-3/GS/SSM-25 | Sonmohar   | Peltophorum pterocarpun | 4'5" | 30' | To be removed | Falling within excavation line |
| 26 | M-3/GS/SSM-26 | Sonmohar   | Peltophorum pterocarpun | 5'   | 35' | To be removed | Falling within excavation line |
| 27 | M-3/GS/SSM-27 | Chenduphul | Parkia Biglandulosa     | 7'   | 50' | To be removed | Falling within excavation line |
| 28 | M-3/GS/SSM-28 | Chenduphul | Parkia Biglandulosa     | 6'   | 40' | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |               |            |                       |      |     |               |                                |
|----|---------------|------------|-----------------------|------|-----|---------------|--------------------------------|
| 29 | M-3/GS/SSM-29 | Bor        | Zizithus Mauritian    | 4'   | 15' | To be removed | Falling within excavation line |
| 30 | M-3/GS/SSM-30 | Pimpal     | Ficus Raligiosa       | 2'5" | 20' | To be removed | Falling within excavation line |
| 31 | M-3/GS/SSM-31 | Pimpal     | Ficus Raligiosa       | 2'5" | 18' | To be removed | Falling within excavation line |
| 32 | M-3/GS/SSM-32 | Asupalav   | Polyalthia Longifolia | 2'   | 25' | To be removed | Falling within excavation line |
| 33 | M-3/GS/SSM-33 | Pimpal     | Ficus Raligiosa       | 4'   | 40' | To be removed | Falling within excavation line |
| 34 | M-3/GS/SSM-34 | Desi Badam | Terminalia Catappa    | 4'   | 40' | To be removed | Falling within excavation line |
| 35 | M-3/GS/SSM-35 | Asupalav   | Polyalthia Longifolia | 3'5" | 30' | To be removed | Falling within excavation line |
| 36 | M-3/GS/SSM-36 | Pimpal     | Ficus Raligiosa       | 6'   | 40' | To be removed | Falling within excavation line |
| 37 | M-3/GS/SSM-37 | Bor        | Zizithus Mauritian    | 3'   | 18' | To be removed | Falling within excavation line |
| 38 | M-3/GS/SSM-38 | Shevga     | Moringa Oliefera      | 2'5" | 22' | To be removed | Falling within excavation line |
| 39 | M-3/GS/SSM-39 | Asupalav   | Polyalthia Longifolia | 4'   | 35' | To be removed | Falling within excavation line |
| 40 | M-3/GS/SSM-40 | Asupalav   | Polyalthia Longifolia | 4'   | 22' | To be removed | Falling within excavation line |
| 41 | M-3/GS/SSM-41 | Payar      | Ficus Amottiana       | 4'   | 22' | To be removed | Falling within excavation line |
| 42 | M-3/GS/SSM-42 | Asupalav   | Polyalthia Longifolia | 2'   | 20' | To be removed | Falling within excavation line |
| 43 | M-3/GS/SSM-43 | Pimpal     | Ficus Raligiosa       | 10'  | 45' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |               |            |                       |    |     |               |                                |
|----|---------------|------------|-----------------------|----|-----|---------------|--------------------------------|
| 44 | M-3/GS/SSM-44 | Rain Tree  | Samanea Saman         | 4' | 50' | To be removed | Falling within excavation line |
| 45 | M-3/GS/SSM-45 | Asupalav   | Polyalthia Longifolia | 4' | 30' | To be removed | Falling within excavation line |
| 46 | M-3/GS/SSM-46 | Asupalav   | Polyalthia Longifolia | 4' | 35' | To be removed | Falling within excavation line |
| 47 | M-3/GS/SSM-47 | Desi Badam | Terminalia Catappa    | 4' | 40' | To be removed | Falling within excavation line |
| 48 | M-3/GS/SSM-48 | Desi Badam | Terminalia Catappa    | 3' | 45' | To be removed | Falling within excavation line |
| 49 | M-3/GS/SSM-49 | Asupalav   | Polyalthia Longifolia | 4' | 45' | To be removed | Falling within excavation line |
| 50 | M-3/GS/SSM-50 | Asupalav   | Polyalthia Longifolia | 4' | 45' | To be removed | Falling within excavation line |
| 51 | M-3/GS/SSM-51 | Umber      | Ficus Glomerata       | 2  | 15' | To be removed | Falling within excavation line |
| 52 | M-3/GS/SSM-52 | Asupalav   | Polyalthia Longifolia | 3  | 40' | To be removed | Falling within excavation line |
| 53 | M-3/GS/SSM-53 | Asupalav   | Polyalthia Longifolia | 3' | 35' | To be removed | Falling within excavation line |
| 54 | M-3/GS/SSM-54 | Asupalav   | Polyalthia Longifolia | 4' | 40' | To be removed | Falling within excavation line |
| 55 | M-3/GS/SSM-55 | Asupalav   | Polyalthia Longifolia | 3' | 35' | To be removed | Falling within excavation line |
| 56 | M-3/GS/SSM-56 | Asupalav   | Polyalthia Longifolia | 3' | 35' | To be removed | Falling within excavation line |
| 57 | M-3/GS/SSM-57 | Asupalav   | Polyalthia Longifolia | 4' | 40' | To be removed | Falling within excavation line |
| 58 | M-3/GS/SSM-58 | Asupalav   | Polyalthia Longifolia | 3' | 35' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |               |            |                       |      |     |               |                                |
|----|---------------|------------|-----------------------|------|-----|---------------|--------------------------------|
| 59 | M-3/GS/SSM-59 | Asupalav   | Polyalthia Longifolia | 4'   | 40' | To be removed | Falling within excavation line |
| 60 | M-3/GS/SSM-60 | Asupalav   | Polyalthia Longifolia | 4'   | 40' | To be removed | Falling within excavation line |
| 61 | M-3/GS/SSM-61 | Asupalav   | Polyalthia Longifolia | 3'5" | 40' | To be removed | Falling within excavation line |
| 62 | M-3/GS/SSM-62 | Desi Badam | Terminalia Catappa    | 3'   | 40' | To be removed | Falling within excavation line |
| 63 | M-3/GS/SSM-63 | Asupalav   | Polyalthia Longifolia | 3'5" | 40' | To be removed | Falling within excavation line |
| 64 | M-3/GS/SSM-64 | Asupalav   | Polyalthia Longifolia | 3'   | 35' | To be removed | Falling within excavation line |
| 65 | M-3/GS/SSM-65 | Asupalav   | Polyalthia Longifolia | 3'5" | 30' | To be removed | Falling within excavation line |
| 66 | M-3/GS/SSM-66 | Asupalav   | Polyalthia Longifolia | 3'5" | 35' | To be removed | Falling within excavation line |
| 67 | M-3/GS/SSM-67 | Asupalav   | Polyalthia Longifolia | 3'   | 35' | To be removed | Falling within excavation line |
| 68 | M-3/GS/SSM-68 | Asupalav   | Polyalthia Longifolia | 3'5" | 35' | To be removed | Falling within excavation line |
| 69 | M-3/GS/SSM-69 | Desi Badam | Terminalia Catappa    | 4'   | 40' | To be removed | Falling within excavation line |
| 70 | M-3/GS/SSM-70 | Asupalav   | Polyalthia Longifolia | 3'   | 35' | To be removed | Falling within excavation line |
| 71 | M-3/GS/SSM-71 | Pimpal     | Ficus Raligiosa       | 4'   | 35' | To be removed | Falling within excavation line |
| 72 | M-3/GS/SSM-72 | Asupalav   | Polyalthia Longifolia | 3'   | 30' | To be removed | Falling within excavation line |
| 73 | M-3/GS/SSM-73 | Desi Badam | Terminalia Catappa    | 2'   | 18' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |               |            |                        |      |     |                |                                    |
|----|---------------|------------|------------------------|------|-----|----------------|------------------------------------|
| 74 | M-3/GS/SSM-74 | Asupalav   | Polyalthia Longifolia  | 4'   | 35' | To be removed  | Falling within excavation line     |
| 75 | M-3/GS/SSM-75 | Asupalav   | Polyalthia Longifolia  | 4'   | 38' | To be removed  | Falling within excavation line     |
| 76 | M-3/GS/SSM-76 | Asupalav   | Polyalthia Longifolia  | 3'5" | 20' | To be removed  | Falling within excavation line     |
| 77 | M-3/GS/SSM-77 | Asupalav   | Polyalthia Longifolia  | 3'   | 18' | To be retained | Falling outside of excavation area |
| 78 | M-3/GS/SSM-78 | Asupalav   | Polyalthia Longifolia  | 3'   | 15' | To be retained | Falling outside of excavation area |
| 79 | M-3/GS/SSM-79 | Asupalav   | Polyalthia Longifolia  | 3'   | 35' | To be retained | Falling outside of excavation area |
| 80 | M-3/GS/SSM-80 | Asupalav   | Polyalthia Longifolia  | 3'   | 40' | To be retained | Falling outside of excavation area |
| 81 | M-3/GS/SSM-81 | Asupalav   | Polyalthia Longifolia  | 3'   | 35' | To be retained | Falling outside of excavation area |
| 82 | M-3/GS/SSM-82 | Asupalav   | Polyalthia Longifolia  | 3'   | 20' | To be retained | Falling outside of excavation area |
| 83 | M-3/GS/SSM-83 | Dead       | -                      | 3'   | 20' | To be retained | Falling outside of excavation area |
| 84 | M-3/GS/SSM-84 | Asupalav   | Polyalthia Longifolia  | 4'   | 35' | To be retained | Falling outside of excavation area |
| 85 | M-3/GS/SSM-85 | Tamhan     | Lagerstroemia Speciosa | 4'   | 25' | To be retained | Falling outside of excavation area |
| 86 | M-3/GS/SSM-86 | Kala Umber | Ficus hispida          | 2'   | 20' | To be retained | Falling outside of excavation area |
| 87 | M-3/GS/SSM-87 | Tamhan     | Lagerstroemia Speciosa | 3'   | 22' | To be retained | Falling outside of excavation area |
| 88 | M-3/GS/SSM-88 | Tamhan     | Lagerstroemia Speciosa | 3'   | 18' | To be retained | Falling outside of excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |            |                         |    |     |                |                                    |
|-----|----------------|------------|-------------------------|----|-----|----------------|------------------------------------|
| 89  | M-3/GS/SSM-89  | Kala UMBER | Ficus hispida           | 2' | 18' | To be retained | Falling outside of excavation area |
| 90  | M-3/GS/SSM-90  | Kala UMBER | Ficus hispida           | 1' | 15' | To be retained | Falling outside of excavation area |
| 91  | M-3/GS/SSM-91  | Bakul      | Mimusops Elengi         | 2' | 25' | To be retained | Falling outside of excavation area |
| 92  | M-3/GS/SSM-92  | Jambhul    | Syzygium Cumini         | 3' | 30' | To be retained | Falling outside of excavation area |
| 93  | M-3/GS/SSM-93  | Bakul      | Mimusops Elengi         | 2' | 18' | To be retained | Falling outside of excavation area |
| 94  | M-3/GS/SSM-94  | Kala UMBER | Ficus hispida           | 2' | 20' | To be retained | Falling outside of excavation area |
| 95  | M-3/GS/SSM-95  | Pimpal     | Ficus Raligiosa         | 5' | 45' | To be retained | Falling outside of excavation area |
| 96  | M-3/GS/SSM-96  | Bakul      | Mimusops Elengi         | 2' | 18' | To be retained | Falling outside of excavation area |
| 97  | M-3/GS/SSM-97  | Kala UMBER | Ficus hispida           | 2' | 20' | To be retained | Falling outside of excavation area |
| 98  | M-3/GS/SSM-98  | Bakul      | Mimusops Elengi         | 2' | 25' | To be removed  | Falling within excavation line     |
| 99  | M-3/GS/SSM-99  | Desi Badam | Terminalia Catappa      | 4' | 50' | To be removed  | Falling within excavation line     |
| 100 | M-3/GS/SSM-100 | Sonmohar   | Peltophorum pterocarpun | 5' | 40' | To be removed  | Falling within excavation line     |
| 101 | M-3/GS/SSM-101 | Sonmohar   | Peltophorum pterocarpun | 5' | 45' | To be removed  | Falling within excavation line     |
| 102 | M-3/GS/SSM-102 | Desi Badam | Terminalia Catappa      | 4' | 40' | To be removed  | Falling within excavation line     |
| 103 | M-3/GS/SSM-103 | Desi Badam | Terminalia Catappa      | 2' | 18' | To be removed  | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |             |                       |    |     |               |                                |
|-----|----------------|-------------|-----------------------|----|-----|---------------|--------------------------------|
| 104 | M-3/GS/SSM-104 | Desi Badam  | Terminalia Catappa    | 5' | 40' | To be removed | Falling within excavation line |
| 105 | M-3/GS/SSM-105 | Satvin      | Alstonia Scholaris    | 4' | 40' | To be removed | Falling within excavation line |
| 106 | M-3/GS/SSM-106 | Powder puff | Calliandra Emarginata | 2' | 20' | To be removed | Falling within excavation line |
| 107 | M-3/GS/SSM-107 | Powder puff | Calliandra Emarginata | 2' | 22' | To be removed | Falling within excavation line |
| 108 | M-3/GS/SSM-108 | Powder puff | Calliandra Emarginata | 1' | 10' | To be removed | Falling within excavation line |
| 109 | M-3/GS/SSM-109 | Shevga      | Moringa Oliefera      | 2' | 15' | To be removed | Falling within excavation line |
| 110 | M-3/GS/SSM-110 | Powder puff | Calliandra Emarginata | 2' | 12' | To be removed | Falling within excavation line |
| 111 | M-3/GS/SSM-111 | Powder puff | Calliandra Emarginata | 1' | 10' | To be removed | Falling within excavation line |
| 112 | M-3/GS/SSM-112 | Powder puff | Calliandra Emarginata | 1' | 10' | To be removed | Falling within excavation line |
| 113 | M-3/GS/SSM-113 | Kala Umber  | Ficus hispida         | 3' | 20' | To be removed | Falling within excavation line |
| 114 | M-3/GS/SSM-114 | Karanj      | pongamia Pinnata      | 2' | 22' | To be removed | Falling within excavation line |
| 115 | M-3/GS/SSM-115 | Bhend       | Thespesia Populnea    | 4' | 40' | To be removed | Falling within excavation line |
| 116 | M-3/GS/SSM-116 | Bhend       | Thespesia Populnea    | 5' | 45' | To be removed | Falling within excavation line |
| 117 | M-3/GS/SSM-117 | Bhend       | Thespesia Populnea    | 5' | 45' | To be removed | Falling within excavation line |
| 118 | M-3/GS/SSM-118 | Bhend       | Thespesia Populnea    | 5' | 40' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |          |                         |      |     |                |                                    |
|-----|----------------|----------|-------------------------|------|-----|----------------|------------------------------------|
| 119 | M-3/GS/SSM-119 | Bhend    | Thespesia Populnea      | 4'   | 40' | To be removed  | Falling within excavation line     |
| 120 | M-3/GS/SSM-120 | Bhend    | Thespesia Populnea      | 5'   | 25' | To be removed  | Falling within excavation line     |
| 121 | M-3/GS/SSM-121 | Bhend    | Thespesia Populnea      | 4'   | 35' | To be removed  | Falling within excavation line     |
| 122 | M-3/GS/SSM-122 | Bhend    | Thespesia Populnea      | 5'   | 40' | To be removed  | Falling within excavation line     |
| 123 | M-3/GS/SSM-123 | Bhend    | Thespesia Populnea      | 6'   | 50' | To be removed  | Falling within excavation line     |
| 124 | M-3/GS/SSM-124 | Bhend    | Thespesia Populnea      | 4'   | 35' | To be removed  | Falling within excavation line     |
| 125 | M-3/GS/SSM-125 | Bhend    | Thespesia Populnea      | 4'   | 35' | To be removed  | Falling within excavation line     |
| 126 | M-3/GS/SSM-126 | Bhend    | Thespesia Populnea      | 4'   | 40' | To be retained | Falling outside of excavation area |
| 127 | M-3/GS/SSM-127 | Bhend    | Thespesia Populnea      | 3'   | 40' | To be retained | Falling outside of excavation area |
| 128 | M-3/GS/SSM-128 | Bhend    | Thespesia Populnea      | 3'   | 20' | To be retained | Falling outside of excavation area |
| 129 | M-3/GS/SSM-129 | Sonmohar | Peltophorum pterocarpun | 3'   | 30' | To be retained | Falling outside of excavation area |
| 130 | M-3/GS/SSM-130 | Sonmohar | Peltophorum pterocarpun | 6'5" | 35' | To be retained | Falling outside of excavation area |
| 131 | M-3/GS/SSM-131 | Sonmohar | Peltophorum pterocarpun | 4'8" | 40' | To be retained | Falling outside of excavation area |
| 132 | M-3/GS/SSM-132 | Sonmohar | Peltophorum pterocarpun | 4    | 40' | To be retained | Falling outside of excavation area |
| 133 | M-3/GS/SSM-133 | Sonmohar | Peltophorum pterocarpun | 5'1" | 35' | To be retained | Falling outside of excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |               |                         |      |     |                |                                    |
|-----|----------------|---------------|-------------------------|------|-----|----------------|------------------------------------|
| 134 | M-3/GS/SSM-134 | Sonmohar      | Peltophorum pterocarpun | 4'8" | 40  | To be retained | Falling outside of excavation area |
| 135 | M-3/GS/SSM-135 | Rain Tree     | Samanea Saman           | 7'8" | 45' | To be retained | Falling outside of excavation area |
| 136 | M-3/GS/SSM-136 | Rain Tree     | Samanea Saman           | 7'6" | 50' | To be retained | Falling outside of excavation area |
| 137 | M-3/GS/SSM-137 | Kashid        | Cassia siamea           | 2'   | 18' | To be retained | Falling outside of excavation area |
| 138 | M-3/GS/SSM-138 | Bhend         | Thespesia Populnea      | 7'   | 30' | To be retained | Falling outside of excavation area |
| 139 | M-3/GS/SSM-139 | Rain Tree     | Samanea Saman           | 7'   | 55' | To be removed  | Falling within excavation line     |
| 140 | M-3/GS/SSM-140 | Sonmohar      | Peltophorum pterocarpun | 4'   | 50' | To be removed  | Falling within excavation line     |
| 141 | M-3/GS/SSM-141 | Rain Tree     | Samanea Saman           | 6'   | 55' | To be removed  | Falling within excavation line     |
| 142 | M-3/GS/SSM-142 | Jungali badam | Sterculia foetida       | 4'   | 45' | To be removed  | Falling within excavation line     |
| 143 | M-3/GS/SSM-143 | Rain Tree     | Samanea Saman           | 6'   | 55' | To be removed  | Falling within excavation line     |
| 144 | M-3/GS/SSM-144 | Chenduphul    | Parkia Biglandulosa     | 4'   | 45' | To be removed  | Falling within excavation line     |
| 145 | M-3/GS/SSM-145 | Chenduphul    | Parkia Biglandulosa     | 5'   | 12' | To be removed  | Falling within excavation line     |
| 146 | M-3/GS/SSM-146 | Sonmohar      | Peltophorum pterocarpun | 3'   | 30' | To be removed  | Falling within excavation line     |
| 147 | M-3/GS/SSM-147 | Bhend         | Thespesia Populnea      | 3'   | 30' | To be removed  | Falling within excavation line     |
| 148 | M-3/GS/SSM-148 | Bhend         | Thespesia Populnea      | 4'   | 30' | To be removed  | Falling within excavation line     |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |            |                    |    |     |               |                                |
|-----|----------------|------------|--------------------|----|-----|---------------|--------------------------------|
| 149 | M-3/GS/SSM-149 | Wad        | Ficus Benghalensis | 3' | 25' | To be removed | Falling within excavation line |
| 150 | M-3/GS/SSM-150 | Bhend      | Thespesia Populnea | 4' | 25' | To be removed | Falling within excavation line |
| 151 | M-3/GS/SSM-151 | Bhend      | Thespesia Populnea | 4' | 30' | To be removed | Falling within excavation line |
| 152 | M-3/GS/SSM-152 | Wad        | Ficus Benghalensis | 9' | 40' | To be removed | Falling within excavation line |
| 153 | M-3/GS/SSM-153 | Kala Umber | Ficus hispida      | 4' | 35' | To be removed | Falling within excavation line |
| 154 | M-3/GS/SSM-154 | Coconut    | Cocos nucifera     | 2' | 25' | To be removed | Falling within excavation line |
| 155 | M-3/GS/SSM-155 | Chafa      | Plumpria Alba      | 4' | 30' | To be removed | Falling within excavation line |
| 156 | M-3/GS/SSM-156 | Chinch     | Tamarindus Indica  | 3' | 30' | To be removed | Falling within excavation line |
| 157 | M-3/GS/SSM-157 | Chafa      | Plumpria Alba      | 4' | 25' | To be removed | Falling within excavation line |
| 158 | M-3/GS/SSM-158 | Coconut    | Cocos nucifera     | 5' | 40' | To be removed | Falling within excavation line |
| 159 | M-3/GS/SSM-159 | Amba       | Mangifera Indica   | 3' | 25' | To be removed | Falling within excavation line |
| 160 | M-3/GS/SSM-160 | Savor      | Ceiba Pentandra    | 3' | 45' | To be removed | Falling within excavation line |
| 161 | M-3/GS/SSM-161 | Amba       | Mangifera Indica   | 2' | 25' | To be removed | Falling within excavation line |
| 162 | M-3/GS/SSM-162 | Coconut    | Cocos nucifera     | 5' | 50' | To be removed | Falling within excavation line |
| 163 | M-3/GS/SSM-163 | Savor      | Ceiba Pentandra    | 4' | 35' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |               |                        |     |     |               |                                |
|-----|----------------|---------------|------------------------|-----|-----|---------------|--------------------------------|
| 164 | M-3/GS/SSM-164 | Tamhan        | Lagerstroemia Speciosa | 3'  | 25' | To be removed | Falling within excavation line |
| 165 | M-3/GS/SSM-165 | Fan Palm      | Livistona Chinensis    | 2'  | 25' | To be removed | Falling within excavation line |
| 166 | M-3/GS/SSM-166 | Jambhul       | Syzygium Cumini        | 6'  | 45' | To be removed | Falling within excavation line |
| 167 | M-3/GS/SSM-167 | Amba          | Mangifera Indica       | 4'  | 45' | To be removed | Falling within excavation line |
| 168 | M-3/GS/SSM-168 | Giripushpa    | Gilricidia Sepium      | 5'  | 45' | To be removed | Falling within excavation line |
| 169 | M-3/GS/SSM-169 | Fan Palm      | Livistona Chinensis    | 2'  | 30' | To be removed | Falling within excavation line |
| 170 | M-3/GS/SSM-170 | Pimpal        | Ficus Raligiosa        | 10' | 45' | To be removed | Falling within excavation line |
| 171 | M-3/GS/SSM-171 | Asupalav      | Polyalthia Longifolia  | 3'  | 40' | To be removed | Falling within excavation line |
| 172 | M-3/GS/SSM-172 | Rain tree     | Samanea Saman          | 9'  | 55' | To be removed | Falling within excavation line |
| 173 | M-3/GS/SSM-173 | Powder puff   | Calliandra Emarginata  | 2'  | 10' | To be removed | Falling within excavation line |
| 174 | M-3/GS/SSM-174 | Powder puff   | Calliandra Emarginata  | 2'  | 10' | To be removed | Falling within excavation line |
| 175 | M-3/GS/SSM-175 | Jungali badam | Sterculia foetida      | 3'  | 30' | To be removed | Falling within excavation line |
| 176 | M-3/GS/SSM-176 | Powder puff   | Calliandra Emarginata  | 2'  | 10' | To be removed | Falling within excavation line |
| 177 | M-3/GS/SSM-177 | Karanj        | pongamia Pinnata       | 2'  | 25' | To be removed | Falling within excavation line |
| 178 | M-3/GS/SSM-178 | Rain tree     | Samanea Saman          | 5'  | 45' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |                   |                            |      |     |                   |                                       |
|-----|----------------|-------------------|----------------------------|------|-----|-------------------|---------------------------------------|
| 179 | M-3/GS/SSM-179 | Subhabul          | Leucena<br>Leucocephala    | 2'   | 40' | To be<br>removed  | Falling within excavation<br>line     |
| 180 | M-3/GS/SSM-180 | Powder puff       | Calliandra<br>Emarginata   | 1'   | 15' | To be<br>removed  | Falling within excavation<br>line     |
| 181 | M-3/GS/SSM-181 | Giripushpa        | Gilricidia Sepium          | 4'   | 30' | To be<br>removed  | Falling within excavation<br>line     |
| 182 | M-3/GS/SSM-182 | Powder puff       | Calliandra<br>Emarginata   | 1'   | 15' | To be<br>removed  | Falling within excavation<br>line     |
| 183 | M-3/GS/SSM-183 | Giripushpa        | Gilricidia Sepium          | 1'   | 15' | To be<br>removed  | Falling within excavation<br>line     |
| 184 | M-3/GS/SSM-184 | Pimpal            | Ficus Raligiosa            | 7'   | 60' | To be<br>removed  | Falling within excavation<br>line     |
| 185 | M-3/GS/SSM-185 | Australian Bhabul | Acacia<br>Auriculiformis   | 3'   | 40' | To be<br>removed  | Falling within excavation<br>line     |
| 186 | M-3/GS/SSM-186 | Bhend             | Thespesia Populnea         | 5'   | 45' | To be<br>removed  | Falling within excavation<br>line     |
| 187 | M-3/GS/SSM-187 | Sonmohar          | Peltophorum<br>pterocarpun | 3'   | 40' | To be<br>retained | Falling outside of excavation<br>area |
| 188 | M-3/GS/SSM-188 | Wad               | Ficus Benghalensis         | 10'  | 55' | To be<br>retained | Falling outside of excavation<br>area |
| 189 | M-3/GS/SSM-189 | Savor             | Ceiba Pentandra            | 3'   | 35' | To be<br>retained | Falling outside of excavation<br>area |
| 190 | M-3/GS/SSM-190 | Bismarkia Palm    | Bismarkia Nobilis          | 2'6" | 10' | To be<br>removed  | Falling within excavation<br>line     |
| 191 | M-3/GS/SSM-191 | Bismarkia Palm    | Bismarkia Nobilis          | 2'6" | 10' | To be<br>removed  | Falling within excavation<br>line     |
| 192 | M-3/GS/SSM-192 | Bismarkia Palm    | Bismarkia Nobilis          | 2'6" | 10' | To be<br>removed  | Falling within excavation<br>line     |
| 193 | M-3/GS/SSM-193 | Bismarkia Palm    | Bismarkia Nobilis          | 2'6" | 10' | To be<br>removed  | Falling within excavation<br>line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |                |                   |      |     |               |                                |
|-----|----------------|----------------|-------------------|------|-----|---------------|--------------------------------|
| 194 | M-3/GS/SSM-194 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 195 | M-3/GS/SSM-195 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 196 | M-3/GS/SSM-196 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 197 | M-3/GS/SSM-197 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 198 | M-3/GS/SSM-198 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 199 | M-3/GS/SSM-199 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 200 | M-3/GS/SSM-200 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 201 | M-3/GS/SSM-201 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 202 | M-3/GS/SSM-202 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 203 | M-3/GS/SSM-203 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 204 | M-3/GS/SSM-204 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 205 | M-3/GS/SSM-205 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 206 | M-3/GS/SSM-206 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 207 | M-3/GS/SSM-207 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 208 | M-3/GS/SSM-208 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |

**PART-II: TREE INVENTORY DETAILS**

**GENERAL CONSULTANT FOR MUMBAI METRO LINE 3**

|     |                |                |                   |      |     |               |                                |
|-----|----------------|----------------|-------------------|------|-----|---------------|--------------------------------|
| 209 | M-3/GS/SSM-209 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 210 | M-3/GS/SSM-210 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 211 | M-3/GS/SSM-211 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 212 | M-3/GS/SSM-212 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 213 | M-3/GS/SSM-213 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 214 | M-3/GS/SSM-214 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 215 | M-3/GS/SSM-215 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 216 | M-3/GS/SSM-216 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 217 | M-3/GS/SSM-217 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 218 | M-3/GS/SSM-218 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 219 | M-3/GS/SSM-219 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 220 | M-3/GS/SSM-220 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 221 | M-3/GS/SSM-221 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 222 | M-3/GS/SSM-222 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |
| 223 | M-3/GS/SSM-223 | Bismarkia Palm | Bismarkia Nobilis | 2'6" | 10' | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |            |                        |    |     |                |                                    |
|-----|---------------|------------|------------------------|----|-----|----------------|------------------------------------|
| 224 | M-3/GS/SSM-77 | Asupalav   | Polyalthia Longifolia  | 3' | 18' | To be retained | Falling outside of excavation area |
| 225 | M-3/GS/SSM-78 | Asupalav   | Polyalthia Longifolia  | 3' | 15' | To be retained | Falling outside of excavation area |
| 226 | M-3/GS/SSM-79 | Asupalav   | Polyalthia Longifolia  | 3' | 35' | To be retained | Falling outside of excavation area |
| 227 | M-3/GS/SSM-80 | Asupalav   | Polyalthia Longifolia  | 3' | 40' | To be retained | Falling outside of excavation area |
| 228 | M-3/GS/SSM-81 | Asupalav   | Polyalthia Longifolia  | 3' | 35' | To be retained | Falling outside of excavation area |
| 229 | M-3/GS/SSM-82 | Asupalav   | Polyalthia Longifolia  | 3' | 20' | To be retained | Falling outside of excavation area |
| 230 | M-3/GS/SSM-83 | Dead       |                        | 3' | 20' | To be retained | Falling outside of excavation area |
| 231 | M-3/GS/SSM-84 | Asupalav   | Polyalthia Longifolia  | 4' | 35' | To be retained | Falling outside of excavation area |
| 232 | M-3/GS/SSM-85 | Tamhan     | Lagerstroemia Speciosa | 4' | 25' | To be retained | Falling outside of excavation area |
| 233 | M-3/GS/SSM-86 | Kala Umber | Ficus hispida          | 2' | 20' | To be retained | Falling outside of excavation area |
| 234 | M-3/GS/SSM-87 | Tamhan     | Lagerstroemia Speciosa | 3' | 22' | To be retained | Falling outside of excavation area |
| 235 | M-3/GS/SSM-88 | Tamhan     | Lagerstroemia Speciosa | 3' | 18' | To be retained | Falling outside of excavation area |
| 236 | M-3/GS/SSM-89 | Kala Umber | Ficus hispida          | 2' | 18' | To be retained | Falling outside of excavation area |
| 237 | M-3/GS/SSM-90 | Kala Umber | Ficus hispida          | 1' | 15' | To be retained | Falling outside of excavation area |
| 238 | M-3/GS/SSM-91 | Bakul      | Mimusops Elengi        | 2' | 25' | To be retained | Falling outside of excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |            |                         |      |     |                |                                    |
|-----|----------------|------------|-------------------------|------|-----|----------------|------------------------------------|
| 239 | M-3/GS/SSM-92  | Jambhul    | Syzygium Cumini         | 3'   | 30' | To be retained | Falling outside of excavation area |
| 240 | M-3/GS/SSM-93  | Bakul      | Mimusops Elengi         | 2'   | 18' | To be retained | Falling outside of excavation area |
| 241 | M-3/GS/SSM-94  | Kala Umber | Ficus hispida           | 2'   | 20' | To be retained | Falling outside of excavation area |
| 242 | M-3/GS/SSM-95  | Pimpal     | Ficus Raligiosa         | 5'   | 45' | To be retained | Falling outside of excavation area |
| 243 | M-3/GS/SSM-96  | Bakul      | Mimusops Elengi         | 2'   | 18' | To be retained | Falling outside of excavation area |
| 244 | M-3/GS/SSM-97  | Kala Umber | Ficus hispida           | 2'   | 20' | To be retained | Falling outside of excavation area |
| 245 | M-3/GS/SSM-126 | Bhend      | Thespesia Populnea      | 4'   | 40' | To be retained | Falling outside of excavation area |
| 246 | M-3/GS/SSM-127 | Bhend      | Thespesia Populnea      | 3'   | 40' | To be retained | Falling outside of excavation area |
| 247 | M-3/GS/SSM-128 | Bhend      | Thespesia Populnea      | 3'   | 20' | To be retained | Falling outside of excavation area |
| 248 | M-3/GS/SSM-129 | Sonmohar   | Peltophorum pterocarpun | 3'   | 30' | To be retained | Falling outside of excavation area |
| 249 | M-3/GS/SSM-130 | Sonmohar   | Peltophorum pterocarpun | 6'5" | 35' | To be removed  | Falling within excavation line     |
| 250 | M-3/GS/SSM-131 | Sonmohar   | Peltophorum pterocarpun | 4'8" | 40' | To be removed  | Falling within excavation line     |
| 251 | M-3/GS/SSM-133 | Sonmohar   | Peltophorum pterocarpun | 5'1" | 35' | To be removed  | Falling within excavation line     |
| 252 | M-3/GS/SSM-134 | Sonmohar   | Peltophorum pterocarpun | 4'8" | 40' | To be removed  | Falling within excavation line     |
| 253 | M-3/GS/SSM-135 | Rain Tree  | Samanea Saman           | 7'8" | 45' | To be removed  | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                |              |                         |      |     |                |                                    |
|-----|----------------|--------------|-------------------------|------|-----|----------------|------------------------------------|
| 254 | M-3/GS/SSM-136 | Rain Tree    | Samanea Saman           | 7'6" | 50' | To be removed  | Falling within excavation line     |
| 255 | M-3/GS/SSM-137 | Kashid       | Cassia siamea           | 2'   | 18' | To be removed  | Falling within excavation line     |
| 256 | M-3/GS/SSM-138 | Bhend        | Thespesia Populnea      | 7'   | 30' | To be removed  | Falling within excavation line     |
| 257 | M-3/GS/SSM-187 | Sonmohar     | Peltophorum pterocarpun | 3'   | 40' | To be retained | Falling outside of excavation area |
| 258 | M-3/GS/SSM-188 | Wad          | Ficus Benghalensis      | 10'  | 55' | To be retained | Falling outside of excavation area |
| 259 | M-3/GS/SSM-189 | Savor        | Ceiba Pentandra         | 3'   | 35' | To be retained | Falling outside of excavation area |
| 260 | M-3/GS/SSM-01  | Coconut      | Cocos nucifera          | 2'   | 45' | To be retained | Falling outside of excavation area |
| 261 | M-3/GS/SSM-02  | Coconut      | Cocos nucifera          | 1.5' | 30' | To be retained | Falling outside of excavation area |
| 262 | M-3/GS/SSM-03  | Jangli Badam | Terminalia catappa      | 0.5' | 10' | To be retained | Falling outside of excavation area |
| 263 | M-3/GS/SSM-04  | Kadamba      | Neolamarckia cadamba    | 0.5' | 15' | To be retained | Falling outside of excavation area |
| 264 | M-3/GS/SSM-05  | Shevar       | Sesbania bispinosa,     | 2'   | 30' | To be removed  | Falling within excavation line     |
| 265 | M-3/GS/SSM-06  | Coconut      | Cocos nucifera          | 4'   | 42' | To be removed  | Falling within excavation line     |
| 266 | M-3/GS/SSM-07  | Bhabul       | Vachellia nilotica      | 1'7" | 15' | To be removed  | Falling within excavation line     |
| 267 | M-3/GS/SSM-08  | Kala Umber   | Ficus racemosa          | 2'4" | 20' | To be removed  | Falling within excavation line     |
| 268 | M-3/GS/SSM-09  | Kadu Neem    | Azadirachta indica      | 10"  | 20' | To be removed  | Falling within excavation line     |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |            |                        |      |     |                |                                    |
|-----|---------------|------------|------------------------|------|-----|----------------|------------------------------------|
| 269 | M-3/GS/SSM-10 | Coconut    | Cocos nucifera         | 4'   | 20' | To be removed  | Falling within excavation line     |
| 270 | M-3/GS/SSM-11 | Tamhan     | Lagerstroemia speciosa | 1'3" | 15' | To be removed  | Falling within excavation line     |
| 271 | M-3/GS/SSM-12 | Amba       | Mangifera indica       | 2'   | 45' | To be retained | Falling outside of excavation area |
| 272 | M-3/GS/SSM-13 | Asupalav   | Polyalthia             | 1'1" | 15' | To be removed  | Falling within excavation line     |
| 273 | M-3/GS/SSM-14 | Asupalav   | Polyalthia             | 1'2" | 18' | To be removed  | Falling within excavation line     |
| 274 | M-3/GS/SSM-15 | Asupalav   | Polyalthia             | 1'2" | 18' | To be removed  | Falling within excavation line     |
| 275 | M-3/GS/SSM-16 | Undi       | Guttiferae             | 3'9" | 35' | To be removed  | Falling within excavation line     |
| 276 | M-3/GS/SSM-17 | Asupalav   | Polyalthia             | 11"  | 9'  | To be removed  | Falling within excavation line     |
| 277 | M-3/GS/SSM-18 | Coconut    | Cocos nucifera         | 3'4" | 10' | To be removed  | Falling within excavation line     |
| 278 | M-3/GS/SSM-19 | Desi Badam | Terminalia catappa     | 3'2" | 28' | To be removed  | Falling within excavation line     |
| 279 | M-3/GS/SSM-20 | Asupalav   | Polyalthia             | 10"  | 9'  | To be removed  | Falling within excavation line     |
| 280 | M-3/GS/SSM-21 | Asupalav   | Polyalthia             | 11"  | 9'  | To be removed  | Falling within excavation line     |
| 281 | M-3/GS/SSM-22 | Asupalav   | Polyalthia             | 1'6" | 20' | To be removed  | Falling within excavation line     |
| 282 | M-3/GS/SSM-23 | Asupalav   | Polyalthia             | 1'2" | 18' | To be removed  | Falling within excavation line     |
| 283 | M-3/GS/SSM-24 | Asupalav   | Polyalthia             | 1'   | 12' | To be removed  | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |                  |                  |       |     |                |                                    |
|-----|---------------|------------------|------------------|-------|-----|----------------|------------------------------------|
| 284 | M-3/GS/SSM-25 | Coconut          | Cocos nucifera   | 2'8"  | 28' | To be removed  | Falling within excavation line     |
| 285 | M-3/GS/SSM-26 | Chafa            | Plumeria         | 1'11" | 15' | To be removed  | Falling within excavation line     |
| 286 | M-3/GS/SSM-27 | Asupalav         | Polyalthia       | 2'3"  | 22' | To be removed  | Falling within excavation line     |
| 287 | M-3/GS/SSM-28 | Chafa            | Plumeria         | 2'    | 15' | To be removed  | Falling within excavation line     |
| 288 | M-3/GS/SSM-29 | Bhokar           | Cordia dichotoma | 1'4"  | 16' | To be removed  | Falling within excavation line     |
| 289 | M-3/GS/SSM-30 | Singapore Cherry | -                | 1'4"  | 16' | To be retained | Falling outside of excavation area |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 71         |
| Trees to be removed  | 218        |
| <b>Total Trees</b>   | <b>289</b> |

| Summary of Tree Survey at Acharya Aatre Station |              |              |                                 |                      |                       |                     |  |
|---|--------------|--------------|---------------------------------|----------------------|-----------------------|---------------------|--|
| Sr. no.   | Tree no.     | Common Name  | Botanical Name                  | Appro x. Girth (ft.) | Appro x. Height (ft.) | Proposed suggestion | Remark                                     |
| 1   | M-3/GS/AC/01 | Bhend        | <i>Thespesia populnea</i>       | 5'                   | 40'                   | To be retained      | Falling outside of excavation line         |
| 2   | M-3/GS/AC/02 | Sonmohar     | <i>Peltophorum pterocarpum</i>  | 2'                   | 28'                   | To be removed       | Falling within Station Box excavation area |
| 3   | M-3/GS/AC/03 | Sonmohar     | <i>Peltophorum pterocarpum</i>  | 4'                   | 40'                   | To be removed       | Falling within Station Box excavation area |
| 4   | M-3/GS/AC/04 | Sonmohar     | <i>Peltophorum pterocarpum</i>  | 5'                   | 40'                   | To be removed       | Falling within Station Box excavation area |
| 5   | M-3/GS/AC/05 | Phanas       | <i>Artocarpus heterophyllus</i> | 3'                   | 25'                   | To be removed       | Falling within Station Box excavation area |
| 6   | M-3/GS/AC/06 | Coconut      | <i>Cocos nucifera</i>           | 4'                   | 30'                   | To be removed       | Falling within Station Box excavation area |
| 7   | M-3/GS/AC/07 | Pimpal       | <i>Ficus religiosa</i>          | 11'                  | 50'                   | To be removed       | Falling within Station Box excavation area |
| 8   | M-3/GS/AC/08 | Rain Tree    | <i>Samanea saman</i>            | 5'                   | 40'                   | To be removed       | Falling within Station Box excavation area |
| 9   | M-3/GS/AC/09 | Pimpal       | <i>Ficus religiosa</i>          | 5'                   | 30'                   | To be removed       | Falling within Station Box excavation area |
| 10  | M-3/GS/AC/10 | Pimpal       | <i>Ficus religiosa</i>          | 10'                  | 35'                   | To be removed       | Falling within Station Box excavation area |
| 11  | M-3/GS/AC/11 | Lettuce tree | <i>Pisonia alba</i>             | 2'                   | 20'                   | To be retained      | Falling outside of excavation line         |
| 12  | M-3/GS/AC/12 | Chafa        | <i>Plumeria alba</i>            | 2'                   | 20'                   | To be retained      | Falling outside of excavation line         |
| 13  | M-3/GS/AC/13 | Lettuce tree | <i>Pisonia alba</i>             | 2'                   | 20'                   | To be retained      | Falling outside of excavation line         |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |                   |              |                              |     |     |                |  |
|----|-------------------|--------------|------------------------------|-----|-----|----------------|--|
| 14 | M -<br>3/GS/AC/14 | Asupalav     | <i>Polyalthia longifolia</i> | 10" | 20' | To be retained | Falling outside of excavation line         |
| 15 | M -<br>3/GS/AC/15 | Asupalav     | <i>Polyalthia longifolia</i> | 10" | 20' | To be retained | Falling outside of excavation line         |
| 16 | M -<br>3/GS/AC/16 | Asupalav     | <i>Polyalthia longifolia</i> | 10" | 20' | To be retained | Falling outside of excavation line         |
| 17 | M -<br>3/GS/AC/17 | Asupalav     | <i>Polyalthia longifolia</i> | 10" | 20' | To be retained | Falling outside of excavation line         |
| 18 | M -<br>3/GS/AC/18 | Lettuce tree | <i>Pisonia alba</i>          | 2'  | 20' | To be retained | Falling outside of excavation line         |
| 19 | M -<br>3/GS/AC/19 | Bhend        | <i>Thespesia populnea</i>    | 2'  | 20' | To be removed  | Falling within Station Box excavation area |
| 20 | M -<br>3/GS/AC/20 | Desi Badam   | <i>Terminalia catappa</i>    | 2'  | 25' | To be removed  | Falling within Station Box excavation area |
| 21 | M -<br>3/GS/AC/21 | Pimpal       | <i>Ficus religiosa</i>       | 11' | 40' | To be removed  | Falling within Station Box excavation area |
| 22 | M -<br>3/GS/AC/22 | Jambhul      | <i>Syzygium cumini</i>       | 4'  | 50' | To be removed  | Falling within Station Box excavation area |
| 23 | M -<br>3/GS/AC/23 | Peru         | <i>Psidium guajaya</i>       | 2'  | 18' | To be removed  | Falling within Station Box excavation area |
| 24 | M -<br>3/GS/AC/24 | Bhend        | <i>Thespesia populnea</i>    | 6'  | 30' | To be removed  | Falling within Station Box excavation area |
| 25 | M -<br>3/GS/AC/25 | Pimpal       | <i>Ficus religiosa</i>       | 11' | 40' | To be removed  | Falling within Station Box excavation area |
| 26 | M -<br>3/GS/AC/26 | Jambhul      | <i>Syzygium cumini</i>       | 2'  | 15' | To be removed  | Falling within Station Box excavation area |
| 27 | M -<br>3/GS/AC/27 | Jambhul      | <i>Syzygium cumini</i>       | 2'  | 10' | To be removed  | Falling within Station Box excavation area |
| 28 | M -<br>3/GS/AC/28 | Wad          | <i>Ficus benghalensis</i>    | 10' | 40' | To be removed  | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |                   |                   |  |     |     |               |  |
|----|-------------------|-------------------|--|-----|-----|---------------|--|
| 29 | M -<br>3/GS/AC/29 | Bhend             | <i>Thespesia populnea</i>                | 6'  | 35' | To be removed | Falling within Station Box excavation area |
| 30 | M -<br>3/GS/AC/30 | Wad+kala<br>umber | <i>Ficus benghalensis +<br/>hispidia</i> | 4'  | 30' | To be removed | Falling within Station Box excavation area |
| 31 | M -<br>3/GS/AC/31 | Bhend             | <i>Thespesia populnea</i>                | 3'  | 20' | To be removed | Falling within Station Box excavation area |
| 32 | M -<br>3/GS/AC/32 | Pimpal            | <i>Ficus religiosa</i>                   | 4'  | 50' | To be removed | Falling within Station Box excavation area |
| 33 | M -<br>3/GS/AC/33 | Wad               | <i>Ficus benghalensis</i>                | 9'  | 40' | To be removed | Falling within Station Box excavation area |
| 34 | M -<br>3/GS/AC/34 | Pimpal            | <i>Ficus religiosa</i>                   | 11' | 40' | To be removed | Falling within Station Box excavation area |
| 35 | M -<br>3/GS/AC/35 | Coconut           | <i>Cocos nucifera</i>                    | 4'  | 30' | To be removed | Falling within Station Box excavation area |
| 36 | M -<br>3/GS/AC/36 | Sonmohar          | <i>Peltophorum<br/>pterocarpum</i>       | 7'  | 40' | To be removed | Falling within Station Box excavation area |
| 37 | M -<br>3/GS/AC/37 | Peru              | <i>Psidium guajaya</i>                   | 2'  | 20' | To be removed | Falling within Station Box excavation area |
| 38 | M -<br>3/GS/AC/38 | Pimpal            | <i>Ficus religiosa</i>                   | 3'  | 30' | To be removed | Falling within Station Box excavation area |
| 39 | M -<br>3/GS/AC/39 | Pimpal            | <i>Ficus religiosa</i>                   | 10' | 35' | To be removed | Falling within Station Box excavation area |
| 40 | M -<br>3/GS/AC/40 | Mango             | <i>Mangifera indica</i>                  | 3'  | 40' | To be removed | Falling within Station Box excavation area |
| 41 | M -<br>3/GS/AC/41 | Bhend             | <i>Thespesia populnea</i>                | 2'  | 30' | To be removed | Falling within Station Box excavation area |
| 42 | M -<br>3/GS/AC/42 | Bhend             | <i>Thespesia populnea</i>                | 6'  | 40' | To be removed | Falling within Station Box excavation area |
| 43 | M -<br>3/GS/AC/43 | Bhend             | <i>Thespesia populnea</i>                | 3'  | 35' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |                   |            |                                |     |     |                |  |
|----|-------------------|------------|--------------------------------|-----|-----|----------------|--|
| 44 | M -<br>3/GS/AC/44 | Wad        | <i>Ficus benghalensis</i>      | 4'  | 40' | To be removed  | Falling within Station Box excavation area |
| 45 | M -<br>3/GS/AC/45 | Jambhul    | <i>Syzygium cumini</i>         | 4'  | 55' | To be removed  | Falling within Station Box excavation area |
| 46 | M -<br>3/GS/AC/46 | Pimpal     | <i>Ficus religiosa</i>         | 5'  | 50' | To be removed  | Falling within Station Box excavation area |
| 47 | M -<br>3/GS/AC/47 | Badam      | <i>Terminalia catappa</i>      | 3'  | 20' | To be removed  | Falling within Station Box excavation area |
| 48 | M -<br>3/GS/AC/48 | Pimpal     | <i>Ficus religiosa</i>         | 12' | 60' | To be retained | Falling outside of excavation line         |
| 49 | M -<br>3/GS/AC/49 | Putranjiva | <i>Putranjiva roxburghli</i>   | 4'  | 55' | To be retained | Falling outside of excavation line         |
| 50 | M -<br>3/GS/AC/50 | Suru       | <i>Casuarina equisetifolia</i> | 2'  | 45' | To be retained | Falling outside of excavation line         |
| 51 | M -<br>3/GS/AC/51 | Suru       | <i>Casuarina equisetifolia</i> | 4'  | 45' | To be retained | Falling outside of excavation line         |
| 52 | M -<br>3/GS/AC/52 | Suru       | <i>Casuarina equisetifolia</i> | 2'  | 40' | To be retained | Falling outside of excavation line         |
| 53 | M -<br>3/GS/AC/53 | Pimpal     | <i>Ficus religiosa</i>         | 5'  | 60' | To be retained | Falling outside of excavation line         |
| 54 | M -<br>3/GS/AC/54 | Kala umber | <i>Ficus hispida</i>           | 3'  | 30' | To be retained | Falling outside of excavation line         |
| 55 | M -<br>3/GS/AC/55 | Kala umber | <i>Ficus hispida</i>           | 2'  | 30' | To be retained | Falling outside of excavation line         |
| 56 | M -<br>3/GS/AC/56 | Suru       | <i>Casuarina equisetifolia</i> | 2'  | 40' | To be retained | Falling outside of excavation line         |
| 57 | M -<br>3/GS/AC/57 | Suru       | <i>Casuarina equisetifolia</i> | 3'  | 40' | To be retained | Falling outside of excavation line         |
| 58 | M -<br>3/GS/AC/58 | Suru       | <i>Casuarina equisetifolia</i> | 2'  | 40' | To be retained | Falling outside of excavation line         |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |                   |            |                                |     |     |                |  |
|----|-------------------|------------|--------------------------------|-----|-----|----------------|--|
| 59 | M -<br>3/GS/AC/59 | Pimpal     | <i>Ficus religiosa</i>         | 3'  | 30' | To be retained | Falling outside of excavation line         |
| 60 | M -<br>3/GS/AC/60 | Suru       | <i>Casuarina equisetifolia</i> | 6'  | 50' | To be retained | Falling outside of excavation line         |
| 61 | M -<br>3/GS/AC/61 | Umber      | <i>Ficus glomerata</i>         | 7'  | 45' | To be retained | Falling outside of excavation line         |
| 62 | M -<br>3/GS/AC/62 | Suru(Dead) | <i>Casuarina equisetifolia</i> | 3'  | 15' | To be retained | Falling outside of excavation line         |
| 63 | M -<br>3/GS/AC/63 | Suru       | <i>Casuarina equisetifolia</i> | 4'  | 40' | To be retained | Falling outside of excavation line         |
| 64 | M -<br>3/GS/AC/64 | Suru       | <i>Casuarina equisetifolia</i> | 3'  | 45' | To be retained | Falling outside of excavation line         |
| 65 | M -<br>3/GS/AC/65 | Pimpal     | <i>Ficus religiosa</i>         | 8'  | 50' | To be removed  | Falling within Station Box excavation area |
| 66 | M -<br>3/GS/AC/66 | Badam      | <i>Terminalia catappa</i>      | 5'  | 55' | To be removed  | Falling within Station Box excavation area |
| 67 | M -<br>3/GS/AC/67 | Mango      | <i>Mangifera indica</i>        | 6'  | 50' | To be removed  | Falling within Station Box excavation area |
| 68 | M -<br>3/GS/AC/68 | Coconut    | <i>Cocos nucifera</i>          | 4'  | 55' | To be removed  | Falling within Station Box excavation area |
| 69 | M -<br>3/GS/AC/69 | Coconut    | <i>Cocos nucifera</i>          | 3'  | 45' | To be removed  | Falling within Station Box excavation area |
| 70 | M -<br>3/GS/AC/70 | Karanj     | <i>Pongamia pinnata</i>        | 5'  | 55' | To be removed  | Falling within Station Box excavation area |
| 71 | M -<br>3/GS/AC/71 | Coconut    | <i>Cocos nucifera</i>          | 4'  | 60' | To be removed  | Falling within Station Box excavation area |
| 72 | M -<br>3/GS/AC/72 | Parijatak  | <i>Nyctanthes arbortristis</i> | 2'  | 15' | To be removed  | Falling within Station Box excavation area |
| 73 | M -<br>3/GS/AC/73 | Jambhul    | <i>Syzygium cumini</i>         | 10' | 20' | To be removed  | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |                   |          |                                 |     |     |               |  |
|----|-------------------|----------|---------------------------------|-----|-----|---------------|--|
| 74 | M -<br>3/GS/AC/74 | Sonmohar | <i>Peltophorum pterocarpum</i>  | 4'  | 30' | To be removed | Falling within Station Box excavation area |
| 75 | M -<br>3/GS/AC/75 | Pimpal   | <i>Ficus religiosa</i>          | 13' | 40' | To be removed | Falling within Station Box excavation area |
| 76 | M -<br>3/GS/AC/76 | Asupalav | <i>Polyalthia longifolia</i>    | 3'  | 30' | To be removed | Falling within Station Box excavation area |
| 77 | M -<br>3/GS/AC/77 | Asupalav | <i>Polyalthia longifolia</i>    | 5'  | 30' | To be removed | Falling within Station Box excavation area |
| 78 | M -<br>3/GS/AC/78 | Pimpal   | <i>Ficus religiosa</i>          | 10' | 40' | To be removed | Falling within Station Box excavation area |
| 79 | M -<br>3/GS/AC/79 | Gulmohor | <i>Delonix regia</i>            | 6'  | 30' | To be removed | Falling within Station Box excavation area |
| 80 | M -<br>3/GS/AC/80 | Wad      | <i>Ficus benghalensis</i>       | 1'  | 20' | To be removed | Falling within Station Box excavation area |
| 81 | M -<br>3/GS/AC/81 | Raiawala | <i>Cicca acida</i>              | 2'  | 10' | To be removed | Falling within Station Box excavation area |
| 82 | M -<br>3/GS/AC/82 | Coconut  | <i>Cocos nucifera</i>           | 6'  | 50' | To be removed | Falling within Station Box excavation area |
| 83 | M -<br>3/GS/AC/83 | Phanas   | <i>Artocarpus heterophyllus</i> | 6'  | 50' | To be removed | Falling within Station Box excavation area |
| 84 | M -<br>3/GS/AC/84 | Coconut  | <i>Cocos nucifera</i>           | 6'  | 40' | To be removed | Falling within Station Box excavation area |
| 85 | M -<br>3/GS/AC/85 | Phanas   | <i>Artocarpus heterophyllus</i> | 8'  | 30' | To be removed | Falling within Station Box excavation area |
| 86 | M -<br>3/GS/AC/86 | Sonmohar | <i>Peltophorum pterocarpum</i>  | 9'  | 35' | To be removed | Falling within Station Box excavation area |
| 87 | M -<br>3/GS/AC/87 | Sonmohar | <i>Peltophorum pterocarpum</i>  | 6'  | 30' | To be removed | Falling within Station Box excavation area |
| 88 | M -<br>3/GS/AC/88 | Jambhul  | <i>Syzygium cumini</i>          | 6'  | 25' | To be removed | Falling within Station Box excavation area |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                    |               |                           |      |      |               |  |
|-----|--------------------|---------------|---------------------------|------|------|---------------|--|
| 89  | M -<br>3/GS/AC/89  | Jangali Badam | <i>Sterculia foetida</i>  | 4'   | 20'  | To be removed | Falling within Station Box excavation area |
| 90  | M -<br>3/GS/AC/90  | Pimpal        | <i>Ficus religiosa</i>    | 2'   | 20'  | To be removed | Falling within Station Box excavation area |
| 91  | M -<br>3/GS/AC/91  | Jambhul       | <i>Syzygium cumini</i>    | 10'  | 50'  | To be removed | Falling within Station Box excavation area |
| 92  | M -<br>3/GS/AC/92  | Mango         | <i>Mangifera indica</i>   | 10'  | 50'  | To be removed | Falling within Station Box excavation area |
| 93  | M -<br>3/GS/AC/93  | Jangali Badam | <i>Sterculia foetida</i>  | 4'   | 30'  | To be removed | Falling within Station Box excavation area |
| 94  | M -<br>3/GS/AC/94  | Pimpal        | <i>Ficus religiosa</i>    | 4'   | 30'  | To be removed | Falling within Station Box excavation area |
| 95  | M -<br>3/GS/AC/95  | Ramphal       | <i>Annona reticulata</i>  | 2'   | 30'  | To be removed | Falling within Station Box excavation area |
| 96  | M -<br>3/GS/AC/96  | Coconut       | <i>Cocos nucifera</i>     | 4'   | 15'  | To be removed | Falling within Station Box excavation area |
| 97  | M -<br>3/GS/AC/97  | Jambhul       | <i>Syzygium cumini</i>    | 8'   | 44'  | To be removed | Falling within Station Box excavation area |
| 98  | M -<br>3/GS/AC/98  | Kala umber    | <i>Ficus hispida</i>      | 1'   | 12'  | To be removed | Falling within Station Box excavation area |
| 99  | M -<br>3/GS/AC/99  | Jambhul       | <i>Syzygium cumini</i>    | 2'   | 18'  | To be removed | Falling within Station Box excavation area |
| 100 | M -<br>3/GS/AC/100 | Pimpal        | <i>Ficus religiosa</i>    | 3'4" | 18'  | To be removed | Falling within Station Box excavation area |
| 101 | M -<br>3/GS/AC/101 | Desi Badam    | <i>Terminalia catappa</i> | 5'   | 35'  | To be removed | Falling within Station Box excavation area |
| 102 | M -<br>3/GS/AC/102 | Coconut       | <i>Cocos nucifera</i>     | 4'   | 20'  | To be removed | Falling within Station Box excavation area |
| 103 | 1                  | Badam         | <i>Terminalia catappa</i> | 43'  | 6'9" | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                   |              |                                |     |     |               |  |
|-----|-------------------|--------------|--------------------------------|-----|-----|---------------|--|
| 104 | M -<br>3/GS/AC/11 | Lettuce tree | <i>Pisonia alba</i>            | 2'  | 20' | To be removed | Falling within Station Box excavation area |
| 105 | M -<br>3/GS/AC/12 | Chafa        | <i>Plumeria alba</i>           | 2'  | 20' | To be removed | Falling within Station Box excavation area |
| 106 | M -<br>3/GS/AC/13 | Lettuce tree | <i>Pisonia alba</i>            | 2'  | 20' | To be removed | Falling within Station Box excavation area |
| 107 | M -<br>3/GS/AC/14 | Asupalav     | <i>Polyalthia longifolia</i>   | 10" | 20' | To be removed | Falling within Station Box excavation area |
| 108 | M -<br>3/GS/AC/15 | Asupalav     | <i>Polyalthia longifolia</i>   | 10" | 20' | To be removed | Falling within Station Box excavation area |
| 109 | M -<br>3/GS/AC/16 | Asupalav     | <i>Polyalthia longifolia</i>   | 10" | 20' | To be removed | Falling within Station Box excavation area |
| 110 | M -<br>3/GS/AC/17 | Asupalav     | <i>Polyalthia longifolia</i>   | 10" | 20' | To be removed | Falling within Station Box excavation area |
| 111 | M -<br>3/GS/AC/18 | Lettuce tree | <i>Pisonia alba</i>            | 2'  | 20' | To be removed | Falling within Station Box excavation area |
| 112 | M -<br>3/GS/AC/50 | Suru         | <i>Casuarina equisetifolia</i> | 2'  | 45' | To be removed | Falling within Station Box excavation area |
| 113 | M -<br>3/GS/AC/51 | Suru         | <i>Casuarina equisetifolia</i> | 4'  | 45' | To be removed | Falling within Station Box excavation area |
| 114 | M -<br>3/GS/AC/52 | Suru         | <i>Casuarina equisetifolia</i> | 2'  | 40' | To be removed | Falling within Station Box excavation area |
| 115 | M -<br>3/GS/AC/53 | Pimpal       | <i>Ficus religiosa</i>         | 5'  | 60' | To be removed | Falling within Station Box excavation area |
| 116 | M -<br>3/GS/AC/54 | Kala umber   | <i>Ficus hispida</i>           | 3'  | 30' | To be removed | Falling within Station Box excavation area |
| 117 | M -<br>3/GS/AC/55 | Kala umber   | <i>Ficus hispida</i>           | 2'  | 30' | To be removed | Falling within Station Box excavation area |
| 118 | M -<br>3/GS/AC/56 | Suru         | <i>Casuarina equisetifolia</i> | 2'  | 40' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                   |                  |                                |     |      |               |  |
|-----|-------------------|------------------|--------------------------------|-----|------|---------------|--|
| 119 | M -<br>3/GS/AC/57 | Suru             | <i>Casuarina equisetifolia</i> | 3'  | 40'  | To be removed | Falling within Station Box excavation area |
| 120 | M -<br>3/GS/AC/58 | Suru             | <i>Casuarina equisetifolia</i> | 2'  | 40'  | To be removed | Falling within Station Box excavation area |
| 121 | M -<br>3/GS/AC/59 | Pimpal           | <i>Ficus religiosa</i>         | 3'  | 30'  | To be removed | Falling within Station Box excavation area |
| 122 | M -<br>3/GS/AC/60 | Suru             | <i>Casuarina equisetifolia</i> | 6'  | 50'  | To be removed | Falling within Station Box excavation area |
| 123 | M -<br>3/GS/AC/61 | Umber            | <i>Ficus glomerata</i>         | 7'  | 45'  | To be removed | Falling within Station Box excavation area |
| 124 | M -<br>3/GS/AC/62 | Suru(Dead)       | <i>Casuarina equisetifolia</i> | 3'  | 15'  | To be removed | Falling within Station Box excavation area |
| 125 | M -<br>3/GS/AC/63 | Suru             | <i>Casuarina equisetifolia</i> | 4'  | 40'  | To be removed | Falling within Station Box excavation area |
| 126 | 1                 | Singapore Cherry | <i>Muntingicalabura</i>        | 12' | 1'2" | To be removed | Falling within Station Box excavation area |
| 127 | 2                 | Singapore Cherry | <i>Muntingicalabura</i>        | 10' | 1'5" | To be removed | Falling within Station Box excavation area |
| 128 | 3                 | Singapore Cherry | <i>Muntingicalabura</i>        | 8'  | 1'1" | To be removed | Falling within Station Box excavation area |
| 129 | 4                 | Singapore Cherry | <i>Muntingicalabura</i>        | 5'  | 1'3" | To be removed | Falling within Station Box excavation area |
| 130 | 5                 | Singapore Cherry | <i>Muntingicalabura</i>        | 15' | 1'5" | To be removed | Falling within Station Box excavation area |
| 131 | 6                 | Singapore Cherry | <i>Muntingicalabura</i>        | 10' | 11"  | To be removed | Falling within Station Box excavation area |
| 132 | 7                 | Singapore Cherry | <i>Muntingicalabura</i>        | 13' | 1'3" | To be removed | Falling within Station Box excavation area |
| 133 | 8                 | Singapore Cherry | <i>Muntingicalabura</i>        | 12' | 1'3" | To be removed | Falling within Station Box excavation area |

**PART-II: TREE INVENTORY DETAILS**

**GENERAL CONSULTANT FOR MUMBAI METRO LINE 3**

|                      |            |
|----------------------|------------|
| Trees to be Retained | 26         |
| Trees to be removed  | 107        |
| <b>Total Trees</b>   | <b>133</b> |

| Summary of Tree Survey at Worli Station |              |             |                                |                      |                       |                     |  |
|---|--------------|-------------|--------------------------------|----------------------|-----------------------|---------------------|--|
| Sr. no.                                 | Tree no.     | Common Name | Botanical Name                 | Appro x. Girth (ft.) | Appro x. Height (ft.) | Proposed suggestion | Remark                                     |
| 1                                       | M-3/GS/WS-01 | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 4'                   | 27'                   | To be removed       | Falling within Station Box excavation area |
| 2                                       | M-3/GS/WS-02 | Rain tree   | <i>Samanea saman</i>           | 7'                   | 39'                   | To be removed       | Falling within Station Box excavation area |
| 3                                       | M-3/GS/WS-03 | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 2'                   | 24'                   | To be removed       | Falling within Station Box excavation area |
| 4                                       | M-3/GS/WS-04 | Neem        | <i>Azadirachta indica</i>      | 3'                   | 23'                   | To be removed       | Falling within Station Box excavation area |
| 5                                       | M-3/GS/WS-05 | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 4'                   | 27'                   | To be removed       | Falling within Station Box excavation area |
| 6                                       | M-3/GS/WS-06 | Neem        | <i>Azadirachta indica</i>      | 3'                   | 23'                   | To be removed       | Falling within Station Box excavation area |
| 7                                       | M-3/GS/WS-07 | Neem        | <i>Azadirachta indica</i>      | 3'                   | 23'                   | To be removed       | Falling within Station Box excavation area |
| 8                                       | M-3/GS/WS-08 | Asupalav    | <i>polyalthia longifolia</i>   | 3'                   | 33'                   | To be removed       | Falling within Station Box excavation area |
| 9                                       | M-3/GS/WS-09 | Neem        | <i>Azadirachta indica</i>      | 4'                   | 26'                   | To be removed       | Falling within Station Box excavation area |
| 10                                      | M-3/GS/WS-10 | Asupalav    | <i>polyalthia longifolia</i>   | 3'                   | 33'                   | To be removed       | Falling within Station Box excavation area |
| 11                                      | M-3/GS/WS-11 | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 5'                   | 35'                   | To be removed       | Falling within Station Box excavation area |
| 12                                      | M-3/GS/WS-12 | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 3'                   | 20'                   | To be removed       | Falling within Station Box excavation area |
| 13                                      | M-3/GS/WS-13 | Sonmohar    | <i>Peltophorum Pterocarpum</i> | 4'                   | 37'                   | To be removed       | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |              |              |                                |    |     |               |  |
|----|--------------|--------------|--------------------------------|----|-----|---------------|--|
| 14 | M-3/GS/WS-14 | Sonmohar     | <i>Peltophorum Pterocarpum</i> | 4' | 27' | To be removed | Falling within Station Box excavation area |
| 15 | M-3/GS/WS-15 | Sonmohar     | <i>Peltophorum Pterocarpum</i> | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 16 | M-3/GS/WS-16 | Sonmohar     | <i>Peltophorum Pterocarpum</i> | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 17 | M-3/GS/WS-17 | Bhend        | <i>Thespesia populnea</i>      | 3' | 35' | To be removed | Falling within Station Box excavation area |
| 18 | M-3/GS/WS-18 | Asupalav     | <i>polyalthia longifolia</i>   | 3' | 26' | To be removed | Falling within Station Box excavation area |
| 19 | M-3/GS/WS-19 | Shevga       | <i>moringa oliefera</i>        | 1' | 20' | To be removed | Falling within Station Box excavation area |
| 20 | M-3/GS/WS-20 | Jangli Badam | <i>Sterculia foetida</i>       | 3' | 50' | To be removed | Falling within Station Box excavation area |
| 21 | M-3/GS/WS-21 | Amba         | <i>mangifera indica</i>        | 1' | 20' | To be removed | Falling within Station Box excavation area |
| 22 | M-3/GS/WS-22 | Umber        | <i>Ficus glomerata</i>         | 6' | 33' | To be removed | Falling within Station Box excavation area |
| 23 | M-3/GS/WS-23 | Naral        | <i>cocus nucifera</i>          | 3' | 13' | To be removed | Falling within Station Box excavation area |
| 24 | M-3/GS/WS-24 | Jangli Badam | <i>Sterculia foetida</i>       | 5' | 27' | To be removed | Falling within Station Box excavation area |
| 25 | M-3/GS/WS-25 | Putranjiva   | <i>Putranjiva roxburghii</i>   | 4' | 36' | To be removed | Falling within Station Box excavation area |
| 26 | M-3/GS/WS-26 | Pichkari     | <i>spathodea campanulata</i>   | 2' | 24' | To be removed | Falling within Station Box excavation area |
| 27 | M-3/GS/WS-27 | Putranjiva   | <i>Putranjiva roxburghii</i>   | 2' | 17' | To be removed | Falling within Station Box excavation area |
| 28 | M-3/GS/WS-28 | Desi badam   | <i>Terminalia catappa</i>      | 7' | 33' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |              |          |                                |    |     |               |  |
|----|--------------|----------|--------------------------------|----|-----|---------------|--|
| 29 | M-3/GS/WS-29 | Shevga   | <i>Moringa oliefera</i>        | 6' | 20' | To be removed | Falling within Station Box excavation area |
| 30 | M-3/GS/WS-30 | pimpal   | <i>ficus religiosa</i>         | 7' | 27' | To be removed | Falling within Station Box excavation area |
| 31 | M-3/GS/WS-31 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 32 | M-3/GS/WS-32 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 33 | M-3/GS/WS-33 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 34 | M-3/GS/WS-34 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 30' | To be removed | Falling within Station Box excavation area |
| 35 | M-3/GS/WS-35 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 30' | To be removed | Falling within Station Box excavation area |
| 36 | M-3/GS/WS-36 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 30' | To be removed | Falling within Station Box excavation area |
| 37 | M-3/GS/WS-37 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 30' | To be removed | Falling within Station Box excavation area |
| 38 | M-3/GS/WS-38 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 4' | 20' | To be removed | Falling within Station Box excavation area |
| 39 | M-3/GS/WS-39 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 40 | M-3/GS/WS-40 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 41 | M-3/GS/WS-41 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 42 | M-3/GS/WS-42 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 43 | M-3/GS/WS-43 | Asupalav | <i>polyalthia longifolia</i>   | 2' | 27' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |              |          |                                |    |     |                |  |
|----|--------------|----------|--------------------------------|----|-----|----------------|--|
| 44 | M-3/GS/WS-44 | Saptarni | <i>Alstonia scholaris</i>      | 6' | 15' | To be removed  | Falling within Station Box excavation area |
| 45 | M-3/GS/WS-45 | Amba     | <i>mangifera indica</i>        | 8' | 40' | To be removed  | Falling within Station Box excavation area |
| 46 | M-3/GS/WS-46 | Gulmohar | <i>Delonix regia</i>           | 4' | 35' | To be removed  | Falling within Station Box excavation area |
| 47 | M-3/GS/WS-47 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 5' | 27' | To be removed  | Falling within Station Box excavation area |
| 48 | M-3/GS/WS-48 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 7' | 46' | To be removed  | Falling within Station Box excavation area |
| 49 | M-3/GS/WS-49 | Naral    | <i>cocus nucifera</i>          | 5' | 52' | To be removed  | Falling within Station Box excavation area |
| 50 | M-3/GS/WS-50 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 26' | To be removed  | Falling within Station Box excavation area |
| 51 | M-3/GS/WS-51 | Asupalav | <i>polyalthia longifolia</i>   | 3' | 26' | To be removed  | Falling within Station Box excavation area |
| 52 | M-3/GS/WS-52 | Naral    | <i>cocus nucifera</i>          | 5' | 49' | To be removed  | Falling within Station Box excavation area |
| 53 | M-3/GS/WS-53 | Pichkari | <i>spathodea campanulata</i>   | 3' | 26' | To be retained | Falling outside of excavation line         |
| 54 | M-3/GS/WS-54 | Pichkari | <i>spathodea campanulata</i>   | 3' | 26' | To be retained | Falling outside of excavation line         |
| 55 | M-3/GS/WS-55 | Umber    | <i>Ficus glomerata</i>         | 1' | 10' | To be retained | Falling outside of excavation line         |
| 56 | M-3/GS/WS-56 | Pichkari | <i>spathodea campanulata</i>   | 3' | 26' | To be retained | Falling outside of excavation line         |
| 57 | M-3/GS/WS-57 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 4' | 30' | To be removed  | Falling within Station Box excavation area |
| 58 | M-3/GS/WS-58 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 4' | 27' | To be removed  | Falling within Station Box excavation area |
| 59 | M-3/GS/WS-59 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 4' | 27' | To be removed  | Falling within Station Box excavation area |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |              |          |                                |     |     |               |  |
|----|--------------|----------|--------------------------------|-----|-----|---------------|--|
| 60 | M-3/GS/WS-60 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 4'  | 27' | To be removed | Falling within Station Box excavation area |
| 61 | M-3/GS/WS-61 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 4'  | 30' | To be removed | Falling within Station Box excavation area |
| 62 | M-3/GS/WS-62 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 7'  | 37' | To be removed | Falling within Station Box excavation area |
| 63 | M-3/GS/WS-63 | pimpal   | <i>ficus religiosa</i>         | 4'  | 33' | To be removed | Falling within Station Box excavation area |
| 64 | M-3/GS/WS-64 | pimpal   | <i>ficus religiosa</i>         | 10' | 39' | To be removed | Falling within Station Box excavation area |
| 65 | M-3/GS/WS-65 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3'  | 30' | To be removed | Falling within Station Box excavation area |
| 66 | M-3/GS/WS-66 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 4'  | 27' | To be removed | Falling within Station Box excavation area |
| 67 | M-3/GS/WS-67 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 6'  | 35' | To be removed | Falling within Station Box excavation area |
| 68 | M-3/GS/WS-68 | Taman    | <i>Lagerstroemia speciosa</i>  | 3'  | 23' | To be removed | Falling within Station Box excavation area |
| 69 | M-3/GS/WS-69 | Gulmohar | <i>Delonix regia</i>           | 5'  | 27' | To be removed | Falling within Station Box excavation area |
| 70 | M-3/GS/WS-70 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 6'  | 30' | To be removed | Falling within Station Box excavation area |
| 71 | M-3/GS/WS-71 | Peru     | <i>psidium guajava</i>         | 2'  | 23' | To be removed | Falling within Station Box excavation area |
| 72 | M-3/GS/WS-72 | Sitaphal | <i>Annona squamosa</i>         | 3'  | 16' | To be removed | Falling within Station Box excavation area |
| 73 | M-3/GS/WS-73 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 6'  | 37' | To be removed | Falling within Station Box excavation area |
| 74 | M-3/GS/WS-74 | Bahava   | <i>cassia fistula</i>          | 3'  | 23' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |              |               |                                |     |     |                |  |
|----|--------------|---------------|--------------------------------|-----|-----|----------------|--|
| 75 | M-3/GS/WS-75 | Sonmohar      | <i>Peltophorum Pterocarpum</i> | 11' | 10' | To be removed  | Falling within Station Box excavation area |
| 76 | M-3/GS/WS-76 | Umbrella Tree | <i>Brassia actinophylla</i>    | 3'  | 26' | To be retained | Falling outside of excavation line         |
| 77 | M-3/GS/WS-77 | Jangli Badam  | <i>Sterculia foetida</i>       | 4'  | 33' | To be retained | Falling outside of excavation line         |
| 78 | M-3/GS/WS-78 | Sonmohar      | <i>Peltophorum Pterocarpum</i> | 3'  | 26' | To be removed  | Falling within Station Box excavation area |
| 79 | M-3/GS/WS-79 | Sonmohar      | <i>Peltophorum Pterocarpum</i> | 2'  | 20' | To be removed  | Falling within Station Box excavation area |
| 80 | M-3/GS/WS-80 | Sonmohar      | <i>Peltophorum Pterocarpum</i> | 3'  | 25' | To be removed  | Falling within Station Box excavation area |
| 81 | M-3/GS/WS-81 | Bhend         | <i>Thespesia populnea</i>      | 2'  | 25' | To be removed  | Falling within Station Box excavation area |
| 82 | M-3/GS/WS-82 | Bhend         | <i>Thespesia populnea</i>      | 6'  | 33' | To be removed  | Falling within Station Box excavation area |
| 83 | M-3/GS/WS-83 | Sonmohar      | <i>Peltophorum Pterocarpum</i> | 5'  | 40' | To be removed  | Falling within Station Box excavation area |
| 84 | M-3/GS/WS-84 | Naral         | <i>cocus nucifera</i>          | 3'  | 23' | To be removed  | Falling within Station Box excavation area |
| 85 | M-3/GS/WS-85 | Rain tree     | <i>Samanea saman</i>           | 7'  | 37' | To be removed  | Falling within Station Box excavation area |
| 86 | M-3/GS/WS-86 | Gulmohar      | <i>Delonix regia</i>           | 3'  | 40' | To be removed  | Falling within Station Box excavation area |
| 87 | M-3/GS/WS-87 | Subabhul      | <i>leucena leucocephala</i>    | 1'  | 23' | To be removed  | Falling within Station Box excavation area |
| 88 | M-3/GS/WS-88 | Subabhul      | <i>leucena leucocephala</i>    | 1'  | 30' | To be removed  | Falling within Station Box excavation area |
| 89 | M-3/GS/WS-89 | Sonmohar      | <i>Peltophorum Pterocarpum</i> | 3'  | 33' | To be removed  | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |            |                                |    |     |               |  |
|-----|---------------|------------|--------------------------------|----|-----|---------------|--|
| 90  | M-3/GS/WS-90  | Subabhul   | <i>leucena leucocephela</i>    | 2' | 27' | To be removed | Falling within Station Box excavation area |
| 91  | M-3/GS/WS-91  | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 1' | 27' | To be removed | Falling within Station Box excavation area |
| 92  | M-3/GS/WS-92  | Subabhul   | <i>leucena leucocephela</i>    | 1' | 17' | To be removed | Falling within Station Box excavation area |
| 93  | M-3/GS/WS-93  | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 94  | M-3/GS/WS-94  | Gulmohar   | <i>Delonix regia</i>           | 2' | 23' | To be removed | Falling within Station Box excavation area |
| 95  | M-3/GS/WS-95  | Rain tree  | <i>Samanea saman</i>           | 3' | 23' | To be removed | Falling within Station Box excavation area |
| 96  | M-3/GS/WS-96  | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 97  | M-3/GS/WS-97  | Subabhul   | <i>leucena leucocephela</i>    | 2' | 23' | To be removed | Falling within Station Box excavation area |
| 98  | M-3/GS/WS-98  | Subabhul   | <i>leucena leucocephela</i>    | 2' | 30' | To be removed | Falling within Station Box excavation area |
| 99  | M-3/GS/WS-99  | Kala Umber | <i>Ficus hispida</i>           | 2' | 23' | To be removed | Falling within Station Box excavation area |
| 100 | M-3/GS/WS-100 | Gulmohar   | <i>Delonix regia</i>           | 3' | 40' | To be removed | Falling within Station Box excavation area |
| 101 | M-3/GS/WS-101 | Gulmohar   | <i>Delonix regia</i>           | 1' | 33' | To be removed | Falling within Station Box excavation area |
| 102 | M-3/GS/WS-102 | Kadu Neem  | <i>Azadirachta indica</i>      | 1' | 45' | To be removed | Falling within Station Box excavation area |
| 103 | M-3/GS/WS-103 | Subabhul   | <i>leucena leucocephela</i>    | 1' | 40' | To be removed | Falling within Station Box excavation area |
| 104 | M-3/GS/WS-104 | Subabhul   | <i>leucena leucocephela</i>    | 1' | 27' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |          |                                |    |     |               |  |
|-----|---------------|----------|--------------------------------|----|-----|---------------|--|
| 105 | M-3/GS/WS-105 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 1' | 14' | To be removed | Falling within Station Box excavation area |
| 106 | M-3/GS/WS-106 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 1' | 40' | To be removed | Falling within Station Box excavation area |
| 107 | M-3/GS/WS-107 | Gulmohar | <i>Delonix regia</i>           | 1' | 43' | To be removed | Falling within Station Box excavation area |
| 108 | M-3/GS/WS-108 | Subabhul | <i>leucena leucocephela</i>    | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 109 | M-3/GS/WS-109 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 1' | 14' | To be removed | Falling within Station Box excavation area |
| 110 | M-3/GS/WS-110 | Subabhul | <i>leucena leucocephela</i>    | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 111 | M-3/GS/WS-111 | Gulmohar | <i>Delonix regia</i>           | 3' | 30' | To be removed | Falling within Station Box excavation area |
| 112 | M-3/GS/WS-112 | Subabhul | <i>leucena leucocephela</i>    | 3' | 40' | To be removed | Falling within Station Box excavation area |
| 113 | M-3/GS/WS-113 | Subabhul | <i>leucena leucocephela</i>    | 2' | 14' | To be removed | Falling within Station Box excavation area |
| 114 | M-3/GS/WS-114 | Subabhul | <i>leucena leucocephela</i>    | 3' | 45' | To be removed | Falling within Station Box excavation area |
| 115 | M-3/GS/WS-115 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 2' | 30' | To be removed | Falling within Station Box excavation area |
| 116 | M-3/GS/WS-116 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 117 | M-3/GS/WS-117 | Subabhul | <i>leucena leucocephela</i>    | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 118 | M-3/GS/WS-118 | Subabhul | <i>leucena leucocephela</i>    | 2' | 33' | To be removed | Falling within Station Box excavation area |
| 119 | M-3/GS/WS-119 | Subabhul | <i>leucena leucocephela</i>    | 3' | 33' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |          |                                |    |     |               |  |
|-----|---------------|----------|--------------------------------|----|-----|---------------|--|
| 120 | M-3/GS/WS-120 | Subabhul | <i>leucena leucocephala</i>    | 2' | 33' | To be removed | Falling within Station Box excavation area |
| 121 | M-3/GS/WS-121 | Umber    | <i>Ficus glomerata</i>         | 6' | 40' | To be removed | Falling within Station Box excavation area |
| 122 | M-3/GS/WS-122 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3' | 40' | To be removed | Falling within Station Box excavation area |
| 123 | M-3/GS/WS-123 | Subabhul | <i>leucena leucocephala</i>    | 2' | 33' | To be removed | Falling within Station Box excavation area |
| 124 | M-3/GS/WS-124 | Subabhul | <i>leucena leucocephala</i>    | 2' | 33' | To be removed | Falling within Station Box excavation area |
| 125 | M-3/GS/WS-125 | Subabhul | <i>leucena leucocephala</i>    | 1' | 14' | To be removed | Falling within Station Box excavation area |
| 126 | M-3/GS/WS-126 | Gulmohar | <i>Delonix regia</i>           | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 127 | M-3/GS/WS-127 | Subabhul | <i>leucena leucocephala</i>    | 3' | 36' | To be removed | Falling within Station Box excavation area |
| 128 | M-3/GS/WS-128 | Subabhul | <i>leucena leucocephala</i>    | 1' | 14' | To be removed | Falling within Station Box excavation area |
| 129 | M-3/GS/WS-129 | Subabhul | <i>leucena leucocephala</i>    | 1' | 14' | To be removed | Falling within Station Box excavation area |
| 130 | M-3/GS/WS-130 | Subabhul | <i>leucena leucocephala</i>    | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 131 | M-3/GS/WS-131 | Subabhul | <i>leucena leucocephala</i>    | 1' | 8'  | To be removed | Falling within Station Box excavation area |
| 132 | M-3/GS/WS-132 | Subabhul | <i>leucena leucocephala</i>    | 2' | 17' | To be removed | Falling within Station Box excavation area |
| 133 | M-3/GS/WS-133 | Subabhul | <i>leucena leucocephala</i>    | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 134 | M-3/GS/WS-134 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 2' | 20' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |            |                                |    |     |               |  |
|-----|---------------|------------|--------------------------------|----|-----|---------------|--|
| 135 | M-3/GS/WS-135 | Subabhul   | <i>leucena leucocephela</i>    | 2' | 13' | To be removed | Falling within Station Box excavation area |
| 136 | M-3/GS/WS-136 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 137 | M-3/GS/WS-137 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 138 | M-3/GS/WS-138 | karanj     | <i>Pongamia pinnata</i>        | 2' | 23' | To be removed | Falling within Station Box excavation area |
| 139 | M-3/GS/WS-139 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 40' | To be removed | Falling within Station Box excavation area |
| 140 | M-3/GS/WS-140 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 1' | 33' | To be removed | Falling within Station Box excavation area |
| 141 | M-3/GS/WS-141 | Subabhul   | <i>leucena leucocephela</i>    | 1' | 27' | To be removed | Falling within Station Box excavation area |
| 142 | M-3/GS/WS-142 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 1' | 25' | To be removed | Falling within Station Box excavation area |
| 143 | M-3/GS/WS-143 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 1' | 27' | To be removed | Falling within Station Box excavation area |
| 144 | M-3/GS/WS-144 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 25' | To be removed | Falling within Station Box excavation area |
| 145 | M-3/GS/WS-145 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 25' | To be removed | Falling within Station Box excavation area |
| 146 | M-3/GS/WS-146 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 25' | To be removed | Falling within Station Box excavation area |
| 147 | M-3/GS/WS-147 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 25' | To be removed | Falling within Station Box excavation area |
| 148 | M-3/GS/WS-148 | Giripushpa | <i>Gliricidia sepium</i>       | 3' | 25' | To be removed | Falling within Station Box excavation area |
| 149 | M-3/GS/WS-149 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 3' | 25' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |            |                                |    |     |               |  |
|-----|---------------|------------|--------------------------------|----|-----|---------------|--|
| 150 | M-3/GS/WS-150 | Giripushpa | <i>Gliricidia sepium</i>       | 3' | 45' | To be removed | Falling within Station Box excavation area |
| 151 | M-3/GS/WS-151 | Giripushpa | <i>Gliricidia sepium</i>       | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 152 | M-3/GS/WS-152 | Giripushpa | <i>Gliricidia sepium</i>       | 2' | 17' | To be removed | Falling within Station Box excavation area |
| 153 | M-3/GS/WS-153 | pimpal     | <i>ficus religiosa</i>         | 8' | 50' | To be removed | Falling within Station Box excavation area |
| 154 | M-3/GS/WS-154 | Subabhul   | <i>leucena leucocephala</i>    | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 155 | M-3/GS/WS-155 | Sonmohar   | <i>Peltophorum Pterocarpum</i> | 6' | 40' | To be removed | Falling within Station Box excavation area |
| 156 | M-3/GS/WS-156 | karanj     | <i>Pongamia pinnata</i>        | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 157 | M-3/GS/WS-157 | Unknown    | <i>Unknown</i>                 | 3' | 20' | To be removed | Falling within Station Box excavation area |
| 158 | M-3/GS/WS-158 | Subabhul   | <i>leucena leucocephala</i>    | 1' | 23' | To be removed | Falling within Station Box excavation area |
| 159 | M-3/GS/WS-159 | Subabhul   | <i>leucena leucocephala</i>    | 1' | 20' | To be removed | Falling within Station Box excavation area |
| 160 | M-3/GS/WS-160 | Subabhul   | <i>leucena leucocephala</i>    | 1' | 23' | To be removed | Falling within Station Box excavation area |
| 161 | M-3/GS/WS-161 | Subabhul   | <i>leucena leucocephala</i>    | 1' | 27' | To be removed | Falling within Station Box excavation area |
| 162 | M-3/GS/WS-162 | Subabhul   | <i>leucena leucocephala</i>    | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 163 | M-3/GS/WS-163 | Subabhul   | <i>leucena leucocephala</i>    | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 164 | M-3/GS/WS-164 | Subabhul   | <i>leucena leucocephala</i>    | 1' | 27' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |          |                                |    |     |               |  |
|-----|---------------|----------|--------------------------------|----|-----|---------------|--|
| 165 | M-3/GS/WS-165 | Subabhul | <i>leucena leucocephela</i>    | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 166 | M-3/GS/WS-166 | Subabhul | <i>leucena leucocephela</i>    | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 167 | M-3/GS/WS-167 | Subabhul | <i>leucena leucocephela</i>    | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 168 | M-3/GS/WS-168 | Subabhul | <i>leucena leucocephela</i>    | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 169 | M-3/GS/WS-169 | Subabhul | <i>leucena leucocephela</i>    | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 170 | M-3/GS/WS-170 | Subabhul | <i>leucena leucocephela</i>    | 3' | 27' | To be removed | Falling within Station Box excavation area |
| 171 | M-3/GS/WS-171 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3' | 40' | To be removed | Falling within Station Box excavation area |
| 172 | M-3/GS/WS-172 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3' | 40' | To be removed | Falling within Station Box excavation area |
| 173 | M-3/GS/WS-173 | Subabhul | <i>leucena leucocephela</i>    | 4' | 40' | To be removed | Falling within Station Box excavation area |
| 174 | M-3/GS/WS-174 | Subabhul | <i>leucena leucocephela</i>    | 3' | 23' | To be removed | Falling within Station Box excavation area |
| 175 | M-3/GS/WS-175 | Subabhul | <i>leucena leucocephela</i>    | 3' | 23' | To be removed | Falling within Station Box excavation area |
| 176 | M-3/GS/WS-176 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 177 | M-3/GS/WS-177 | Sonmohar | <i>Peltophorum Pterocarpum</i> | 3' | 33' | To be removed | Falling within Station Box excavation area |
| 178 | M-3/GS/WS-178 | Subabhul | <i>leucena leucocephela</i>    | 2' | 27' | To be removed | Falling within Station Box excavation area |
| 179 | M-3/GS/WS-179 | Subabhul | <i>leucena leucocephela</i>    | 1' | 27' | To be removed | Falling within Station Box excavation area |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |               |                                 |      |     |               |  |
|-----|---------------|---------------|---------------------------------|------|-----|---------------|--|
| 180 | M-3/GS/WS-180 | Subabhul      | <i>leucena leucocephala</i>     | 2'   | 27' | To be removed | Falling within Station Box excavation area |
| 181 | M-3/GS/WS-181 | Subabhul      | <i>leucena leucocephala</i>     | 2'   | 25' | To be removed | Falling within Station Box excavation area |
| 182 | 1             | Neem          | <i>Azadirachta indica</i>       | 7"   | 8'  | To be removed | Falling within Station Box excavation area |
| 183 | 2             | Asupalav      | <i>polyalthia longifolia</i>    | 2'9" | 30' | To be removed | Falling within Station Box excavation area |
| 184 | 3             | Naral         | <i>cocus nucifera</i>           | 3'6" | 48' | To be removed | Falling within Station Box excavation area |
| 185 | 4             | Desibadam     | <i>Terminalia catappa</i>       | 3'   | 35' | To be removed | Falling within Station Box excavation area |
| 186 | 5             | Amba          | <i>mangifera indica</i>         | 8"   | 10' | To be removed | Falling within Station Box excavation area |
| 187 | 6             | Phanas        | <i>Artocarpus heterophyllus</i> | 6'4" | 35' | To be removed | Falling within Station Box excavation area |
| 188 | 7             | Phanas        | <i>Artocarpus heterophyllus</i> | 5'6" | 35' | To be removed | Falling within Station Box excavation area |
| 189 | 8             | puthranjiva   | <i>Putranjiva roxburghli</i>    | 1'6" | 24' | To be removed | Falling within Station Box excavation area |
| 190 | 9             | Ashoka        | <i>Saraca asoca</i>             | 2'   | 32' | To be removed | Falling within Station Box excavation area |
| 191 | 10            | Jambhul       | <i>Syzygium cumini.</i>         | 7'6" | 50' | To be removed | Falling within Station Box excavation area |
| 192 | 11            | Amba          | <i>mangifera indica</i>         | 5'5" | 40' | To be removed | Falling within Station Box excavation area |
| 193 | 12            | Phanas        | <i>Artocarpus heterophyllus</i> | 3'9" | 30' | To be removed | Falling within Station Box excavation area |
| 194 | 13            | Phanas (dead) | <i>Artocarpus heterophyllus</i> |      | 15' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |              |               |                                |       |     |               |  |
|-----|--------------|---------------|--------------------------------|-------|-----|---------------|--|
| 195 | 4            | Naral         | <i>Cocus Nucifera</i>          | 1'7"  | 9'  | To be removed | Falling within Station Box excavation area |
| 196 | 23           | Jambhul       | <i>Syzygium cumini.</i>        | 2'    | 25' | To be removed | Falling within Station Box excavation area |
| 197 | 24           | Seetaphal     | <i>Annona squamosa</i>         | 1'    | 12' | To be removed | Falling within Station Box excavation area |
| 198 | 25           | Badam         | <i>Terminalia catappa</i>      | 2'5"  | 15' | To be removed | Falling within Station Box excavation area |
| 199 | 43           | Pimpal        | <i>ficus religiosa</i>         | 9'2"  | 40' | To be removed | Falling within Station Box excavation area |
| 200 | 44           | Sonmohar      | <i>Peltophorum Pterocarpum</i> | 3'    | 30' | To be removed | Falling within Station Box excavation area |
| 201 | 45           | Jungli badam  | <i>Sterculia foetida</i>       | 3'11" | 30' | To be removed | Falling within Station Box excavation area |
| 202 | 46           | Asupalav      | <i>polyalthia longifolia</i>   | 2'6"  | 30' | To be removed | Falling within Station Box excavation area |
| 203 | 82           | Rain tree     | <i>Samanea saman</i>           | 5'3"  | 40' | To be removed | Falling within Station Box excavation area |
| 204 | 95           | Kaduneem      | <i>Azadirachta indica</i>      | 3'    | 50' | To be removed | Falling within Station Box excavation area |
| 205 | M-3/GS/WS-53 | Pichkari      | <i>spathodea campanulata</i>   | 3'    | 26' | To be removed | Falling within Station Box excavation area |
| 206 | M-3/GS/WS-55 | Umber         | <i>Ficus glomerata</i>         | 1'    | 10' | To be removed | Falling within Station Box excavation area |
| 207 | M-3/GS/WS-56 | Pichkari      | <i>spathodea campanulata</i>   | 3'    | 26' | To be removed | Falling within Station Box excavation area |
| 208 | M-3/GS/WS-76 | Umbrella Tree | <i>Brassia actinophylla</i>    | 3'    | 26' | To be removed | Falling within Station Box excavation area |
| 209 | M-3/GS/WS-77 | Jangli Badam  | <i>Sterculia foetida</i>       | 4'    | 33' | To be removed | Falling within Station Box excavation area |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |        |                  |                              |      |     |               |  |
|-----|--------|------------------|------------------------------|------|-----|---------------|--|
| 210 | 1      | Naral            | <i>cocus nucifera</i>        | 3'8" | 28' | To be removed | Falling within Station Box excavation area |
| 211 | 1      | Pichkari         | <i>spathodea campanulata</i> | 3'7" | 25' | To be removed | Falling within Station Box excavation area |
| 212 | 2      | Pichkari         | <i>Spathodea campanulata</i> | 2"   | 6'  | To be removed | Falling within Station Box excavation area |
| 213 | 3      | Nirgundi         | <i>Vitex negundo</i>         | 2'3" | 7'  | To be removed | Falling within Station Box excavation area |
| 214 | 4      | Wield tree(Dead) | <i>Wild tree</i>             | 3'6" | 5'  | To be removed | Falling within Station Box excavation area |
| 215 | 1      | Pimpal           | <i>ficus religiosa</i>       | 10'  | 40' | To be removed | Falling within Station Box excavation area |
| 216 | 2      | wild Tree(Dead)  | <i>wild Tree(Dead)</i>       | 2'   | 20' | To be removed | Falling within Station Box excavation area |
| 217 | 3      | Amba             | <i>mangifera indica</i>      | 6"   | 10' | To be removed | Falling within Station Box excavation area |
| 218 | 4      | Naral            | <i>cocus nucifera</i>        | 3'8" | 45' | To be removed | Falling within Station Box excavation area |
| 219 | WS-182 | Bor              | <i>Ziziphus mauritiana</i>   | 2'   | 23' | To be removed | Falling within Station Box excavation area |
| 220 | WS-183 | Amba             | <i>Mangifera indica</i>      | 6"   | 5'  | To be removed | Falling within Station Box excavation area |
| 221 | WS-184 | Bor              | <i>Ziziphus mauritiana</i>   | 2'   | 24' | To be removed | Falling within Station Box excavation area |
| 222 | WS-185 | Amba             | <i>Mangifera indica</i>      | 2'   | 26' | To be removed | Falling within Station Box excavation area |
| 223 | WS-186 | Asupalav         | <i>polyalthia longifolia</i> | 1'   | 15' | To be removed | Falling within Station Box excavation area |
| 224 | WS-187 | Bor              | <i>Ziziphus mauritiana</i>   | 2'5" | 23' | To be removed | Falling within Station Box excavation area |

**PART-II: TREE INVENTORY DETAILS**

**GENERAL CONSULTANT FOR MUMBAI METRO LINE 3**

|         |        |     |                            |      |    |               |  |
|---------|--------|-----|----------------------------|------|----|---------------|--|
| 22<br>5 | WS-188 | Bor | <i>Ziziphus mauritiana</i> | 1'2" | 4' | To be removed | Falling within Station Box excavation area |
|---------|--------|-----|----------------------------|------|----|---------------|--|

|                      |            |
|----------------------|------------|
| Trees to be Retained | 6          |
| Trees to be removed  | 219        |
| <b>Total Trees</b>   | <b>225</b> |

**4. TREE INVENTORY DETAILS AT UGC-04**

| Summary of Tree Survey at Siddhivinayak Station |             |             |                                |                      |                       |               |                                |
|---|-------------|-------------|--------------------------------|----------------------|-----------------------|---------------|--------------------------------|
| Sr. no.   | Tree no.    | Common Name | Botanical Name                 | Approx . Girth (ft.) | Approx . Height (ft.) | Remark        | Proposed suggestion            |
| 1   | M3/GS/SV 1  | Gulmohar    | <i>Delonix regia</i>           | 4                    | 27                    | To be removed | Falling within excavation line |
| 2   | M3/GS/SV 2  | Neem        | <i>Azadirachta indica</i>      | 2                    | 14                    | To be removed | Falling within excavation line |
| 3   | M3/GS/SV 3  | Suru        | <i>Casuarina equisetifolia</i> | 6                    | 50                    | To be removed | Falling within excavation line |
| 4   | M3/GS/SV 4  | Badam       | <i>Terminalia catappa</i>      | 4                    | 25                    | To be removed | Falling within excavation line |
| 5   | M3/GS/SV 5  | Suru        | <i>Casuarina equisetifolia</i> | 3                    | 25                    | To be removed | Falling within excavation line |
| 6   | M3/GS/SV 6  | Suru        | <i>Casuarina equisetifolia</i> | 3                    | 30                    | To be removed | Falling within excavation line |
| 7   | M3/GS/SV 7  | Naral       | <i>Cocos nucifera</i>          | 4                    | 25                    | To be removed | Falling within excavation line |
| 8   | M3/GS/SV 8  | Naral       | <i>Cocos nucifera</i>          | 3                    | 25                    | To be removed | Falling within excavation line |
| 9   | M3/GS/SV 9  | Naral       | <i>Cocos nucifera</i>          | 4                    | 30                    | To be removed | Falling within excavation line |
| 10  | M3/GS/SV 10 | Naral       | <i>Cocos nucifera</i>          | 4                    | 25                    | To be removed | Falling within excavation line |
| 11  | M3/GS/SV 11 | Asupalav    | <i>Polyalthia longifolia</i>   | 8"                   | 12                    | To be removed | Falling within excavation line |
| 12  | M3/GS/SV 12 | Royal Palm  | <i>Roystonea regia</i>         | 3                    | 25                    | To be removed | Falling within excavation line |
| 13  | M3/GS/SV 13 | Suru        | <i>Casuarina equisetifolia</i> | 2                    | 30                    | To be removed | Falling within excavation line |
| 14  | M3/GS/SV 14 | Supari      | <i>Areca catechu</i>           | 1                    | 12                    | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |             |            |                              |    |    |                |                                 |
|----|-------------|------------|------------------------------|----|----|----------------|---------------------------------|
| 15 | M3/GS/SV 15 | Supari     | <i>Areca catechu</i>         | 1  | 12 | To be removed  | Falling within excavation line  |
| 16 | M3/GS/SV 16 | Supari     | <i>Areca catechu</i>         | 1  | 18 | To be retained | Falling outside excavation line |
| 17 | M3/GS/SV 17 | Supari     | <i>Areca catechu</i>         | 1  | 18 | To be retained | Falling outside excavation line |
| 18 | M3/GS/SV 18 | Asupalav   | <i>Polyalthia longifolia</i> | 2  | 27 | To be removed  | Falling within excavation line  |
| 19 | M3/GS/SV 19 | Pimpal     | <i>Ficus religiosa</i>       | 2  | 25 | To be retained | Falling outside excavation line |
| 20 | M3/GS/SV 20 | Asupalav   | <i>Polyalthia longifolia</i> | 3  | 15 | To be retained | Falling outside excavation line |
| 21 | M3/GS/SV 21 | Asupalav   | <i>Polyalthia longifolia</i> | 3  | 18 | To be retained | Falling outside excavation line |
| 22 | M3/GS/SV 22 | Asupalav   | <i>Polyalthia longifolia</i> | 2  | 25 | To be retained | Falling outside excavation line |
| 23 | M3/GS/SV 23 | Naral      | <i>Cocos nucifera</i>        | 3  | 27 | To be retained | Falling outside excavation line |
| 24 | M3/GS/SV 24 | Naral      | <i>Cocos nucifera</i>        | 3  | 27 | To be retained | Falling outside excavation line |
| 25 | M3/GS/SV 25 | Naral      | <i>Cocos nucifera</i>        | 3  | 27 | To be retained | Falling outside excavation line |
| 26 | M3/GS/SV 26 | Royal palm | <i>Roystonea regia</i>       | 3  | 45 | To be retained | Falling outside excavation line |
| 27 | M3/GS/SV 27 | Naral      | <i>Cocos nucifera</i>        | 3  | 24 | To be retained | Falling outside excavation line |
| 28 | M3/GS/SV 28 | Naral      | <i>Cocos nucifera</i>        | 3  | 30 | To be retained | Falling outside excavation line |
| 29 | M3/GS/SV 29 | Royal palm | <i>Roystonea regia</i>       | 3  | 39 | To be retained | Falling outside excavation line |
| 30 | M3/GS/SV 30 | Asupalav   | <i>Polyalthia longifolia</i> | 10 | 10 | To be retained | Falling outside excavation line |
| 31 | M3/GS/SV 31 | Asupalav   | <i>Polyalthia longifolia</i> | 1  | 9  | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |             |            |                                |    |    |                |                                 |
|----|-------------|------------|--------------------------------|----|----|----------------|---------------------------------|
| 32 | M3/GS/SV 32 | Royal palm | <i>Roystonea regia</i>         | 5  | 39 | To be retained | Falling outside excavation line |
| 33 | M3/GS/SV 33 | Royal palm | <i>Roystonea regia</i>         | 4  | 33 | To be retained | Falling outside excavation line |
| 34 | M3/GS/SV 34 | Royal palm | <i>Roystonea regia</i>         | 4  | 33 | To be retained | Falling outside excavation line |
| 35 | M3/GS/SV 35 | Naral      | <i>Cocos nucifera</i>          | 3  | 45 | To be retained | Falling outside excavation line |
| 36 | M3/GS/SV 36 | Royal palm | <i>Roystonea regia</i>         | 4  | 45 | To be retained | Falling outside excavation line |
| 37 | M3/GS/SV 37 | Naral      | <i>Cocos nucifera</i>          | 3  | 45 | To be retained | Falling outside excavation line |
| 38 | M3/GS/SV 38 | Royal palm | <i>Roystonea regia</i>         | 4  | 45 | To be retained | Falling outside excavation line |
| 39 | M3/GS/SV 39 | Asupalav   | <i>Polyalthia longifolia</i>   | 1  | 9  | To be retained | Falling outside excavation line |
| 40 | M3/GS/SV 40 | Royal palm | <i>Roystonea regia</i>         | 5  | 45 | To be retained | Falling outside excavation line |
| 41 | M3/GS/SV 41 | Naral      | <i>Cocos nucifera</i>          | 3  | 48 | To be removed  | Falling within excavation line  |
| 42 | M3/GS/SV 42 | Pimpal     | <i>Ficus religiosa</i>         | 12 | 60 | To be retained | Falling outside excavation line |
| 43 | M3/GS/SV 43 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4  | 45 | To be retained | Falling outside excavation line |
| 44 | M3/GS/SV 44 | Suru       | <i>Casurina equisetifolia</i>  | 2  | 24 | To be retained | Falling outside excavation line |
| 45 | M3/GS/SV 45 | Jambhul    | <i>Syzygium cumini</i>         | 4  | 42 | To be retained | Falling outside excavation line |
| 46 | M3/GS/SV 46 | Putranjiva | <i>Putranjiva roxburghii</i>   | 3  | 36 | To be retained | Falling outside excavation line |
| 47 | M3/GS/SV 47 | Asupalav   | <i>Polyalthia longifolia</i>   | 1  | 9  | To be retained | Falling outside excavation line |
| 48 | M3/GS/SV 48 | Royal palm | <i>Roystonea regia</i>         | 4  | 36 | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |             |               |                                |    |    |                |                                 |
|----|-------------|---------------|--------------------------------|----|----|----------------|---------------------------------|
| 49 | M3/GS/SV 49 | Suru          | <i>Casuarina equisetifolia</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 50 | M3/GS/SV 50 | Lemon         | <i>Citrus limon</i>            | 2  | 15 | To be removed  | Falling within excavation line  |
| 51 | M3/GS/SV 51 | Suru          | <i>Casuarina equisetifolia</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 52 | M3/GS/SV 52 | Naral         | <i>Cocos nucifera</i>          | 2  | 33 | To be removed  | Falling within excavation line  |
| 53 | M3/GS/SV 53 | Asupalav      | <i>Polyalthia longifolia</i>   | 1  | 9  | To be removed  | Falling within excavation line  |
| 54 | M3/GS/SV 54 | Chapha        | <i>Plumeria alba</i>           | 2  | 18 | To be removed  | Falling within excavation line  |
| 55 | M3/GS/SV 55 | X-mas tree    | <i>Aurocaria columnaris</i>    | 2  | 24 | To be removed  | Falling within excavation line  |
| 56 | M3/GS/SV 56 | Suru          | <i>Casuarina equisetifolia</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 57 | M3/GS/SV 57 | Suru          | <i>Casuarina equisetifolia</i> | 4  | 30 | To be removed  | Falling within excavation line  |
| 58 | M3/GS/SV 58 | Savar         | <i>Ceiba pentandra</i>         | 4  | 22 | To be removed  | Falling within excavation line  |
| 59 | M3/GS/SV 59 | Savar         | <i>Ceiba pentandra</i>         | 4  | 25 | To be removed  | Falling within excavation line  |
| 60 | M3/GS/SV 60 | Neem          | <i>Azadirachta indica</i>      | 1  | 10 | To be retained | Falling outside excavation line |
| 61 | M3/GS/SV 61 | Saptaparni    | <i>Alstonia scholaris</i>      | 3  | 30 | To be retained | Falling outside excavation line |
| 62 | M3/GS/SV 62 | Dhuli chandan |                                | 1  | 15 | To be retained | Falling outside excavation line |
| 63 | M3/GS/SV 63 | Rain Tree     | <i>Samanea saman</i>           | 12 | 45 | To be removed  | Falling within excavation line  |
| 64 | M3/GS/SV 64 | Royal palm    | <i>Roystonea regia</i>         | 4  | 30 | To be removed  | Falling within excavation line  |
| 65 | M3/GS/SV 65 | Royal palm    | <i>Roystonea regia</i>         | 4  | 30 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |             |                 |                              |    |    |                |                                 |
|----|-------------|-----------------|------------------------------|----|----|----------------|---------------------------------|
| 66 | M3/GS/SV 66 | Royal palm      | <i>Roystonea regia</i>       | 4  | 30 | To be removed  | Falling within excavation line  |
| 67 | M3/GS/SV 67 | Rain Tree       | <i>Samanea saman</i>         | 18 | 70 | To be removed  | Falling within excavation line  |
| 68 | M3/GS/SV 68 | Vilayati Chinch | <i>Pithecellobium dulce</i>  | 3  | 25 | To be removed  | Falling within excavation line  |
| 69 | M3/GS/SV 69 | Jamun           | <i>Syzygium cumini</i>       | 4  | 35 | To be removed  | Falling within excavation line  |
| 70 | M3/GS/SV 70 | Putranjiva      | <i>Putranjiva roxburghii</i> | 4  | 30 | To be removed  | Falling within excavation line  |
| 71 | M3/GS/SV 71 | Savar           | <i>Ceiba pentandra</i>       | 5  | 35 | To be removed  | Falling within excavation line  |
| 72 | M3/GS/SV 72 | Putranjiva      | <i>Putranjiva roxburghii</i> | 4  | 20 | To be removed  | Falling within excavation line  |
| 73 | M3/GS/SV 73 | Asupalav        | <i>Polyalthia longifolia</i> | 9" | 15 | To be removed  | Falling within excavation line  |
| 74 | M3/GS/SV 74 | Shewga          | <i>Moringa oleifera</i>      | 3  | 30 | To be removed  | Falling within excavation line  |
| 75 | M3/GS/SV 75 | Mango           | <i>Mangifera indica</i>      | 8" | 20 | To be removed  | Falling within excavation line  |
| 76 | M3/GS/SV 76 | Son chafa       | <i>Michelia champaca</i>     | 2  | 25 | To be removed  | Falling within excavation line  |
| 77 | M3/GS/SV 77 | Putranjiva      | <i>Putranjiva roxburghii</i> | 4  | 22 | To be removed  | Falling within excavation line  |
| 78 | M3/GS/SV 78 | Gulmohar        | <i>Delonix regia</i>         | 4  | 40 | To be removed  | Falling within excavation line  |
| 79 | M3/GS/SV 79 | Shewga          | <i>Moringa oleifera</i>      | 1  | 18 | To be removed  | Falling within excavation line  |
| 80 | M3/GS/SV 80 | Asupalav        | <i>Polyalthia longifolia</i> | 8" | 15 | To be removed  | Falling within excavation line  |
| 81 | M3/GS/SV 81 | Putranjiva      | <i>Putranjiva roxburghii</i> | 8  | 45 | To be removed  | Falling within excavation line  |
| 82 | M3/GS/SV 82 | Umber           | <i>Ficus glomerata</i>       | 8  | 39 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |             |            |                                 |    |    |                |                                 |
|----|-------------|------------|---------------------------------|----|----|----------------|---------------------------------|
| 83 | M3/GS/SV 83 | Naral      | <i>Cocos nucifera</i>           | 3  | 50 | To be retained | Falling outside excavation line |
| 84 | M3/GS/SV 84 | Bhend      | <i>Thespesia populnea</i>       | 9  | 33 | To be retained | Falling outside excavation line |
| 85 | M3/GS/SV 85 | Royal palm | <i>Roystonea regia</i>          | 6  | 30 | To be removed  | Falling within excavation line  |
| 86 | M3/GS/SV 86 | Naral      | <i>Cocos nucifera</i>           | 2  | 20 | To be retained | Falling outside excavation line |
| 87 | M3/GS/SV 87 | Peru       | <i>Psidium gujava</i>           | 1  | 9  | To be retained | Falling outside excavation line |
| 88 | M3/GS/SV 88 | Royal palm | <i>Roystonea regia</i>          | 4  | 36 | To be retained | Falling outside excavation line |
| 89 | M3/GS/SV 89 | Wad        | <i>Ficus benghalensis</i>       | 9  | 60 | To be retained | Falling outside excavation line |
| 90 | M3/GS/SV 90 | Shivan     | <i>Gmelina arborea</i>          | 5  | 36 | To be retained | Falling outside excavation line |
| 91 | M3/GS/SV 91 | Phanas     | <i>Artocarpus heterophyllus</i> | 2  | 27 | To be retained | Falling outside excavation line |
| 92 | M3/GS/SV 92 | Naral      | <i>Cocos nucifera</i>           | 3  | 45 | To be retained | Falling outside excavation line |
| 93 | M3/GS/SV 93 | Royal palm | <i>Roystonea regia</i>          | 6  | 30 | To be removed  | Falling within excavation line  |
| 94 | M3/GS/SV 94 | Royal palm | <i>Roystonea regia</i>          | 4  | 30 | To be removed  | Falling within excavation line  |
| 95 | M3/GS/SV 95 | Umbar      | <i>Ficus racemosa</i>           | 4  | 40 | To be removed  | Falling within excavation line  |
| 96 | M3/GS/SV 96 | Ritha      | <i>Sapindus mukorossi</i>       | 8" | 20 | To be removed  | Falling within excavation line  |
| 97 | M3/GS/SV 97 | Royal Palm | <i>Roystonea regia</i>          | 8  | 30 | To be removed  | Falling within excavation line  |
| 98 | M3/GS/SV 98 | Phanas     | <i>Artocarpus heterophyllus</i> | 6  | 30 | To be removed  | Falling within excavation line  |
| 99 | M3/GS/SV 99 | Chafa      | <i>Plumeria alba</i>            | 1  | 12 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                 |            |                              |   |     |                |                                 |
|-----|-----------------|------------|------------------------------|---|-----|----------------|---------------------------------|
| 100 | M3/GS/SV<br>100 | Supari     | <i>Areca catechu</i>         | 1 | 15  | To be removed  | Falling within excavation line  |
| 101 | M3/GS/SV<br>101 | Supari     | <i>Areca catechu</i>         | 1 | 15  | To be removed  | Falling within excavation line  |
| 102 | M3/GS/SV<br>102 | Supari     | <i>Areca catechu</i>         | 1 | 27  | To be retained | Falling outside excavation line |
| 103 | M3/GS/SV<br>103 | Supari     | <i>Areca catechu</i>         | 1 | 27  | To be retained | Falling outside excavation line |
| 104 | M3/GS/SV<br>104 | Supari     | <i>Areca catechu</i>         | 1 | 27  | To be retained | Falling outside excavation line |
| 105 | M3/GS/SV<br>105 | Amba       | <i>Mangifera indica</i>      | 3 | 27  | To be retained | Falling outside excavation line |
| 106 | M3/GS/SV<br>106 | Royal palm | <i>Roystonea regia</i>       | 4 | 30  | To be retained | Falling outside excavation line |
| 107 | M3/GS/SV<br>107 | Asupalav   | <i>Polyalthia longifolia</i> | 1 | 9   | To be retained | Falling outside excavation line |
| 108 | M3/GS/SV<br>108 | Royal palm | <i>Roystonea regia</i>       | 4 | 33  | To be retained | Falling outside excavation line |
| 109 | M3/GS/SV<br>109 | Naral      | <i>Cocos nucifera</i>        | 3 | 45  | To be removed  | Falling within excavation line  |
| 110 | M3/GS/SV<br>110 | Asupalav   | <i>Polyalthia longifolia</i> | 2 | 15  | To be removed  | Falling within excavation line  |
| 111 | M3/GS/SV<br>111 | Asupalav   | <i>Polyalthia longifolia</i> | 2 | 15  | To be removed  | Falling within excavation line  |
| 112 | M3/GS/SV<br>112 | Royal palm | <i>Roystonea regia</i>       | 4 | 3.9 | To be removed  | Falling within excavation line  |
| 113 | M3/GS/SV<br>113 | Chafa      | <i>Plumeria alba</i>         | 1 | 20  | To be removed  | Falling within excavation line  |
| 114 | M3/GS/SV<br>114 | Asupalav   | <i>Polyalthia longifolia</i> | 3 | 25  | To be removed  | Falling within excavation line  |
| 115 | M3/GS/SV<br>115 | Royal Palm | <i>Roystonea regia</i>       | 5 | 40  | To be removed  | Falling within excavation line  |
| 116 | M3/GS/SV<br>116 | Naral      | <i>Cocos nucifera</i>        | 5 | 40  | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                 |              |                                |   |    |               |                                |
|-----|-----------------|--------------|--------------------------------|---|----|---------------|--------------------------------|
| 117 | M3/GS/SV<br>117 | Naral        | <i>Cocos nucifera</i>          | 3 | 54 | To be removed | Falling within excavation line |
| 118 | M3/GS/SV<br>118 | Naral        | <i>Cocos nucifera</i>          | 4 | 45 | To be removed | Falling within excavation line |
| 119 | M3/GS/SV<br>119 | Royal palm   | <i>Roystonea regia</i>         | 5 | 35 | To be removed | Falling within excavation line |
| 120 | M3/GS/SV<br>120 | Naral        | <i>Cocos nucifera</i>          | 4 | 40 | To be removed | Falling within excavation line |
| 121 | M3/GS/SV<br>121 | Asupalav     | <i>Polyalthia longifolia</i>   | 1 | 15 | To be removed | Falling within excavation line |
| 122 | M3/GS/SV<br>122 | Suru         | <i>Casuarina equisetifolia</i> | 1 | 15 | To be removed | Falling within excavation line |
| 123 | M3/GS/SV<br>123 | Suru         | <i>Casuarina equisetifolia</i> | 4 | 22 | To be removed | Falling within excavation line |
| 124 | M3/GS/SV<br>124 | Asupalav     | <i>Polyalthia longifolia</i>   | 2 | 22 | To be removed | Falling within excavation line |
| 125 | M3/GS/SV<br>125 | Naral        | <i>Cocos nucifera</i>          | 4 | 30 | To be removed | Falling within excavation line |
| 126 | M3/GS/SV<br>126 | Naral        | <i>Cocos nucifera</i>          | 5 | 40 | To be removed | Falling within excavation line |
| 127 | M3/GS/SV<br>127 | Naral        | <i>Cocos nucifera</i>          | 5 | 45 | To be removed | Falling within excavation line |
| 128 | M3/GS/SV<br>128 | Suru         | <i>Casuarina equisetifolia</i> | 4 | 25 | To be removed | Falling within excavation line |
| 129 | M3/GS/SV<br>129 | Suru         | <i>Casuarina equisetifolia</i> | 3 | 25 | To be removed | Falling within excavation line |
| 130 | M3/GS/SV<br>130 | Jamun        | <i>Syzygium cumini</i>         | 6 | 30 | To be removed | Falling within excavation line |
| 131 | M3/GS/SV<br>131 | Jungli badam | <i>Sterculia foetida</i>       | 3 | 35 | To be removed | Falling within excavation line |
| 132 | M3/GS/SV<br>132 | Savar        | <i>Ceiba pentandra</i>         | 3 | 25 | To be removed | Falling within excavation line |
| 133 | M3/GS/SV<br>133 | Jungli badam | <i>Sterculia foetida</i>       | 2 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|         |                 |              |                                |    |    |                |                                 |
|---------|-----------------|--------------|--------------------------------|----|----|----------------|---------------------------------|
| 13<br>4 | M3/GS/SV<br>134 | Jungli badam | <i>Sterculia foetida</i>       | 3  | 25 | To be removed  | Falling within excavation line  |
| 13<br>5 | M3/GS/SV<br>135 | Savar        | <i>Ceiba pentandra</i>         | 3  | 25 | To be removed  | Falling within excavation line  |
| 13<br>6 | M3/GS/SV<br>136 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4  | 20 | To be removed  | Falling within excavation line  |
| 13<br>7 | M3/GS/SV<br>137 | Savar        | <i>Ceiba pentandra</i>         | 6  | 30 | To be removed  | Falling within excavation line  |
| 13<br>8 | M3/GS/SV<br>138 | Jungli badam | <i>Sterculia foetida</i>       | 1  | 20 | To be removed  | Falling within excavation line  |
| 13<br>9 | M3/GS/SV<br>139 | Pimpal       | <i>Ficus religiosa</i>         | 6  | 20 | To be removed  | Falling within excavation line  |
| 14<br>0 | M3/GS/SV<br>140 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2  | 40 | To be removed  | Falling within excavation line  |
| 14<br>1 | M3/GS/SV<br>141 | Rain Tree    | <i>Samanea saman</i>           | 6  | 49 | To be removed  | Falling within excavation line  |
| 14<br>2 | M3/GS/SV<br>142 | Pimpal       | <i>Ficus religiosa</i>         | 5  | 39 | To be retained | Falling outside excavation line |
| 14<br>3 | M3/GS/SV<br>143 | Umber        | <i>Ficus glomerata</i>         | 2  | 24 | To be retained | Falling outside excavation line |
| 14<br>4 | M3/GS/SV<br>144 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5  | 45 | To be retained | Falling outside excavation line |
| 14<br>5 | M3/GS/SV<br>145 | Umber        | <i>Ficus glomerata</i>         | 3  | 39 | To be retained | Falling outside excavation line |
| 14<br>6 | M3/GS/SV<br>146 | Pimpal       | <i>Ficus religiosa</i>         | 12 | 54 | To be retained | Falling outside excavation line |
| 14<br>7 | M3/GS/SV<br>147 | Pimpal       | <i>Ficus religiosa</i>         | 21 | 54 | To be retained | Falling outside excavation line |
| 14<br>8 | M3/GS/SV<br>148 | Jungli badam | <i>Sterculia foetida</i>       | 3  | 45 | To be retained | Falling outside excavation line |
| 14<br>9 | M3/GS/SV<br>149 | Bhend        | <i>Thespesia populnea</i>      | 5  | 30 | To be retained | Falling outside excavation line |
| 15<br>0 | M3/GS/SV<br>150 | Giripushp    | <i>Gliricidia sepium</i>       | 6  | 36 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|         |                 |              |                                |   |    |                |                                 |
|---------|-----------------|--------------|--------------------------------|---|----|----------------|---------------------------------|
| 15<br>1 | M3/GS/SV<br>151 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 7 | 40 | To be retained | Falling outside excavation line |
| 15<br>2 | M3/GS/SV<br>152 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3 | 30 | To be removed  | Falling within excavation line  |
| 15<br>3 | M3/GS/SV<br>153 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 7 | 35 | To be removed  | Falling within excavation line  |
| 15<br>4 | M3/GS/SV<br>154 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2 | 20 | To be removed  | Falling within excavation line  |
| 15<br>5 | M3/GS/SV<br>155 | Jungli badam | <i>Sterculia foetida</i>       | 5 | 40 | To be removed  | Falling within excavation line  |
| 15<br>6 | M3/GS/SV<br>156 | Jungli badam | <i>Sterculia foetida</i>       | 6 | 39 | To be removed  | Falling within excavation line  |
| 15<br>7 | M3/GS/SV<br>157 | Jungli badam | <i>Sterculia foetida</i>       | 7 | 39 | To be removed  | Falling within excavation line  |
| 15<br>8 | M3/GS/SV<br>158 | Jungli badam | <i>Sterculia foetida</i>       | 7 | 39 | To be removed  | Falling within excavation line  |
| 15<br>9 | M3/GS/SV<br>159 | Bhend        | <i>Thespesia populnea</i>      | 2 | 35 | To be removed  | Falling within excavation line  |
| 16<br>0 | M3/GS/SV<br>160 | Deshi Badam  | <i>Terminalia catappa</i>      | 2 | 25 | To be removed  | Falling within excavation line  |
| 16<br>1 | M3/GS/SV<br>161 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4 | 40 | To be removed  | Falling within excavation line  |
| 16<br>2 | M3/GS/SV<br>162 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4 | 35 | To be removed  | Falling within excavation line  |
| 16<br>3 | M3/GS/SV<br>163 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5 | 45 | To be removed  | Falling within excavation line  |
| 16<br>4 | M3/GS/SV<br>164 | Jungli badam | <i>Sterculia foetida</i>       | 2 | 21 | To be removed  | Falling within excavation line  |
| 16<br>5 | M3/GS/SV<br>165 | Jungli badam | <i>Sterculia foetida</i>       | 3 | 36 | To be removed  | Falling within excavation line  |
| 16<br>6 | M3/GS/SV<br>166 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3 | 33 | To be removed  | Falling within excavation line  |
| 16<br>7 | M3/GS/SV<br>167 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 5 | 50 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                 |              |   |    |    |                |                                 |
|-----|-----------------|--------------|---|----|----|----------------|---------------------------------|
| 168 | M3/GS/SV<br>168 | Sonmohar     | <i>Peltophorum pterocarpum</i>              | 2  | 27 | To be removed  | Falling within excavation line  |
| 169 | M3/GS/SV<br>169 | Sonmohar     | <i>Peltophorum pterocarpum</i>              | 4  | 40 | To be retained | Falling outside excavation line |
| 170 | M3/GS/SV<br>170 | Bhend        | <i>Thespesia populnea</i>                   | 3  | 27 | To be removed  | Falling within excavation line  |
| 171 | M3/GS/SV<br>171 | Umber        | <i>Ficus glomerata</i>                      | 4  | 30 | To be removed  | Falling within excavation line  |
| 172 | M3/GS/SV<br>172 | Shewga       | <i>Moringa oliefera</i>                     | 3  | 27 | To be removed  | Falling within excavation line  |
| 173 | M3/GS/SV<br>173 | Gulmohar     | <i>Delonix regia</i>                        | 3  | 27 | To be removed  | Falling within excavation line  |
| 174 | M3/GS/SV<br>174 | Gulmohar     | <i>Delonix regia</i>                        | 3  | 27 | To be removed  | Falling within excavation line  |
| 175 | M3/GS/SV<br>175 | Sonmohar     | <i>Peltophorum pterocarpum</i>              | 4  | 36 | To be retained | Falling outside excavation line |
| 176 | M3/GS/SV<br>176 | Sonmohar     | <i>Peltophorum pterocarpum</i>              | 4  | 36 | To be retained | Falling outside excavation line |
| 177 | M3/GS/SV<br>177 | Bhend        | <i>Thespesia populnea</i>                   | 4  | 35 | To be removed  | Falling within excavation line  |
| 178 | M3/GS/SV<br>178 | Bhend        | <i>Thespesia populnea</i>                   | 5  | 25 | To be removed  | Falling within excavation line  |
| 179 | M3/GS/SV<br>179 | Sonmohar     | <i>Peltophorum pterocarpum</i>              | 12 | 30 | To be removed  | Falling within excavation line  |
| 180 | M3/GS/SV<br>180 | Asupalav     | <i>Polyalthia longifolia</i>                | 3  | 15 | To be removed  | Falling within excavation line  |
| 181 | M3/GS/SV<br>181 | Asupalav     | <i>Polyalthia longifolia</i>                | 4" | 10 | To be removed  | Falling within excavation line  |
| 182 | M3/GS/SV<br>182 | Wad + Pimpal | <i>Ficus benghalensis + Ficus religiosa</i> | 2  | 12 | To be removed  | Falling within excavation line  |
| 183 | M3/GS/SV<br>183 | Jackfruit    | <i>Artocarpus heterophyllus</i>             | 3  | 15 | To be removed  | Falling within excavation line  |
| 184 | M3/GS/SV<br>184 | Mango        | <i>Mangifera indica</i>                     | 1  | 18 | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                 |              |                                |     |    |                |                                 |
|-----|-----------------|--------------|--------------------------------|-----|----|----------------|---------------------------------|
| 185 | M3/GS/SV<br>185 | Bhend        | <i>Thespesia populnea</i>      | 2.7 | 33 | To be retained | Falling outside excavation line |
| 186 | M3/GS/SV<br>186 | Umber        | <i>Ficus glomerata</i>         | 1   | 9  | To be retained | Falling outside excavation line |
| 187 | M3/GS/SV<br>187 | Asupalav     | <i>Polyalthia longifolia</i>   | 3   | 27 | To be retained | Falling outside excavation line |
| 188 | M3/GS/SV<br>188 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4   | 33 | To be retained | Falling outside excavation line |
| 189 | M3/GS/SV<br>189 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4   | 39 | To be retained | Falling outside excavation line |
| 190 | M3/GS/SV<br>190 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3   | 36 | To be retained | Falling outside excavation line |
| 191 | M3/GS/SV<br>191 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3   | 9  | To be retained | Falling outside excavation line |
| 192 | M3/GS/SV<br>192 | Savar        | <i>Ceiba pentandra</i>         | 5   | 42 | To be retained | Falling outside excavation line |
| 193 | M3/GS/SV<br>193 | Savar        | <i>Ceiba pentandra</i>         | 4   | 36 | To be retained | Falling outside excavation line |
| 194 | M3/GS/SV<br>194 | Savar        | <i>Ceiba pentandra</i>         | 5   | 39 | To be retained | Falling outside excavation line |
| 195 | M3/GS/SV<br>195 | Savar        | <i>Ceiba pentandra</i>         | 5   | 30 | To be retained | Falling outside excavation line |
| 196 | M3/GS/SV<br>196 | Gulmohar     | <i>Delonix regia</i>           | 4   | 27 | To be removed  | Falling within excavation line  |
| 197 | M3/GS/SV<br>197 | Jungli badam | <i>Sterculia foetida</i>       | 4   | 36 | To be retained | Falling outside excavation line |
| 198 | M3/GS/SV<br>198 | Asupalav     | <i>Polyalthia longifolia</i>   | 5   | 33 | To be retained | Falling outside excavation line |
| 199 | M3/GS/SV<br>199 | Saptaparni   | <i>Alstonia scholaris</i>      | 3   | 27 | To be retained | Falling outside excavation line |
| 200 | M3/GS/SV<br>200 | Pichkari     | <i>Spathodea campanulata</i>   | 2   | 27 | To be retained | Falling outside excavation line |
| 201 | M3/GS/SV<br>201 | Saptaparni   | <i>Alstonia scholaris</i>      | 3   | 18 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                 |              |                              |     |    |                |                                 |
|-----|-----------------|--------------|------------------------------|-----|----|----------------|---------------------------------|
| 202 | M3/GS/SV<br>202 | Jambhul      | <i>Syzygium cumini</i>       | 3   | 27 | To be retained | Falling outside excavation line |
| 203 | M3/GS/SV<br>203 | Jungli badam | <i>Sterculia foetida</i>     | 2   | 48 | To be retained | Falling outside excavation line |
| 204 | M3/GS/SV<br>204 | Asupalav     | <i>Polyalthia longifolia</i> | 1   | 12 | To be retained | Falling outside excavation line |
| 205 | M3/GS/SV<br>205 | Rain tree    | <i>Samanea saman</i>         | 12  | 48 | To be retained | Falling outside excavation line |
| 206 | M3/GS/SV<br>206 | Umber        | <i>Ficus glomerata</i>       | 1.5 | 12 | To be removed  | Falling within excavation line  |
| 207 | M3/GS/SV<br>207 | Asupalav     | <i>Polyalthia longifolia</i> | 1   | 20 | To be removed  | Falling within excavation line  |
| 208 | M3/GS/SV<br>208 | Wad+Sonmohar | <i>Ficus benghalensis</i>    | 21  | 45 | To be removed  | Falling within excavation line  |
| 209 | M3/GS/SV<br>209 | Jungli badam | <i>Sterculia foetida</i>     | 1   | 15 | To be removed  | Falling within excavation line  |
| 210 | M3/GS/SV<br>210 | Rain tree    | <i>Samanea saman</i>         | 6   | 48 | To be removed  | Falling within excavation line  |
| 211 | M3/GS/SV<br>211 | Pimpal       | <i>Ficus religiosa</i>       | 11  | 45 | To be removed  | Falling within excavation line  |
| 212 | M3/GS/SV<br>212 | Pimpal       | <i>Ficus religiosa</i>       | 4   | 35 | To be removed  | Falling within excavation line  |
| 213 | M3/GS/SV<br>213 | Pimpal       | <i>Ficus religiosa</i>       | 1   | 20 | To be removed  | Falling within excavation line  |
| 214 | M3/GS/SV<br>214 | Pimpal       | <i>Ficus religiosa</i>       | 4   | 30 | To be retained | Falling outside excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 84         |
| Trees to be removed  | 130        |
| <b>Total Trees</b>   | <b>214</b> |

| summary of Tree Survey at Dadar Station |          |                  |                                |                     |                      |               |                                |
|---|----------|------------------|--------------------------------|---------------------|----------------------|---------------|--------------------------------|
| Sr. no.                                 | Tree no. | Common Name      | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Remark        | Proposed suggestion            |
| 1                                       | NGR76    | Rain Tree        | <i>Samanea saman</i>           | 4                   | 30                   | To be removed | Falling within excavation line |
| 2                                       | NGR77    | Sonmohar         | <i>Peltophorum pterocarpum</i> | 3                   | 30                   | To be removed | Falling within excavation line |
| 3                                       | NGR78    | Wad              | <i>Ficus benghalensis</i>      | 1                   | 15                   | To be removed | Falling within excavation line |
| 4                                       | NGR78 A  | Rain Tree        | <i>Samanea saman</i>           | 4                   | 30                   | To be removed | Falling within excavation line |
| 5                                       | NGR79    | Rain Tree (Dead) | <i>Samanea saman</i>           | 3                   | 32                   | To be removed | Falling within excavation line |
| 6                                       | NGR79 A  | Umber            | <i>Ficus Racemosa</i>          | 1                   | 10                   | To be removed | Falling within excavation line |
| 7                                       | NGR80    | Rain Tree (Dead) | <i>Samanea saman</i>           | 3                   | 30                   | To be removed | Falling within excavation line |
| 8                                       | NGR80 A  | Desi Badam       | <i>Terminalia catappa</i>      | 8"                  | 6                    | To be removed | Falling within excavation line |
| 9                                       | NGR81    | Rain Tree (Dead) | <i>Samanea saman</i>           | 4                   | 30                   | To be removed | Falling within excavation line |
| 10                                      | NGR82    | Pichkari (New)   | <i>Spathodea campanulata</i>   | 10cm                | 8                    | To be removed | Falling within excavation line |
| 11                                      | NGR83    | Rain Tree        | <i>Samanea saman</i>           | 5                   | 35                   | To be removed | Falling within excavation line |
| 12                                      | NGR84    | Jamun            | <i>Syzygium cumini</i>         | 5                   | 32                   | To be removed | Falling within excavation line |
| 13                                      | NGR85    | Gulmohar (New)   | <i>Delonix regia</i>           | 10cm                | 8                    | To be removed | Falling within excavation line |
| 14                                      | NGR86    | Kashid           | <i>Cassia siamea</i>           | 4                   | 30                   | To be removed | Falling within excavation line |
| 15                                      | NGR87    | Pichkari (New)   | <i>Spathodea campanulata</i>   | 10cm                | 8                    | To be removed | Falling within excavation line |
| 16                                      | NGR88    | Sonmohar         | <i>Peltophorum pterocarpum</i> | 6                   | 35                   | To be removed | Falling within excavation line |
| 17                                      | NGR89    | Chapha (New)     | <i>Plumeria alba</i>           | 10cm                | 5                    | To be removed | Falling within excavation line |
| 18                                      | NGR90    | Kaduneem (New)   | <i>Azadirachta indica</i>      | 10cm                | 15                   | To be removed | Falling within excavation line |
| 19                                      | NGR91    | Karanj           | <i>Pongamia Pinata</i>         | 5                   | 43                   | To be removed | Falling within excavation line |
| 20                                      | NGR92    | Rain Tree (Dead) | <i>Samanea saman</i>           | 5                   | 30                   | To be removed | Falling within excavation line |
| 21                                      | NGR93    | Pimpal           | <i>Ficus religiosa</i>         | 8                   | 40                   | To be removed | Falling within excavation line |
| 22                                      | NGR94    | Pichkari (New)   | <i>Spathodea campanulata</i>   | 10cm                | 7                    | To be removed | Falling within excavation line |
| 23                                      | NGR95    | Bhend            | <i>Thespesia populnea</i>      | 8                   | 45                   | To be removed | Falling within excavation line |
| 24                                      | NGR95 A  | Suru             | <i>Casuarina equisetifolia</i> | 3                   | 10                   | To be removed | Falling within excavation line |
| 25                                      | 1A       | Asupalav         | <i>Polyalthia longifolia</i>   | 4                   | 30                   | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |           |             |                                 |     |    |                |                                 |
|----|-----------|-------------|---------------------------------|-----|----|----------------|---------------------------------|
| 26 | 1B        | Asupalav    | <i>Polyalthia longifolia</i>    | 4   | 30 | To be removed  | Falling within excavation line  |
| 27 | 1C        | Peru        | <i>Psidium guajava</i>          | 1   | 6  | To be retained | Falling outside excavation line |
| 28 | 1D        | Deshi Badam | <i>Terminalia catappa</i>       | 2   | 15 | To be retained | Falling outside excavation line |
| 29 | 1E        | Suru        | <i>Casuarina equisetifolia</i>  | 1   | 15 | To be retained | Falling outside excavation line |
| 30 | NGR 100   | Rain Tree   | <i>Samanea saman</i>            | 8   | 36 | To be removed  | Falling within excavation line  |
| 31 | NGR 101   | Pimpal      | <i>Ficus religiosa</i>          | 5   | 33 | To be removed  | Falling within excavation line  |
| 32 | NGR102    | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 3   | 32 | To be removed  | Falling within excavation line  |
| 33 | NGR103    | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 3   | 32 | To be removed  | Falling within excavation line  |
| 34 | NGR104    | Asupalav    | <i>Polyalthia longifolia</i>    | 3   | 30 | To be removed  | Falling within excavation line  |
| 35 | NGR105    | Bhend       | <i>Thespesia populnea</i>       | 3   | 30 | To be removed  | Falling within excavation line  |
| 36 | NGR106    | Bhend       | <i>Thespesia populnea</i>       | 3   | 30 | To be removed  | Falling within excavation line  |
| 37 | NGR107    | Asupalav    | <i>Polyalthia longifolia</i>    | 3   | 30 | To be removed  | Falling within excavation line  |
| 38 | NGR108    | Bhend       | <i>Thespesia populnea</i>       | 4   | 30 | To be removed  | Falling within excavation line  |
| 39 | NGR109    | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 10" | 20 | To be removed  | Falling within excavation line  |
| 40 | NGR110    | Kashid      | <i>Cassia siamea</i>            | 1   | 20 | To be removed  | Falling within excavation line  |
| 41 | NGR111    | Jack Fruit  | <i>Artocarpus heterophyllus</i> | 10" | 12 | To be removed  | Falling within excavation line  |
| 42 | NGR112    | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 3   | 30 | To be removed  | Falling within excavation line  |
| 43 | NGR113    | Rain Tree   | <i>Samanea saman</i>            | 4   | 53 | To be removed  | Falling within excavation line  |
| 44 | NGR114    | Kashid      | <i>Cassia siamea</i>            | 3   | 32 | To be removed  | Falling within excavation line  |
| 45 | NGR115    | Pimpal      | <i>Ficus religiosa</i>          | 4   | 40 | To be removed  | Falling within excavation line  |
| 46 | NGR116    | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 3   | 28 | To be removed  | Falling within excavation line  |
| 47 | NGR117    | Kashid      | <i>Cassia siamea</i>            | 3   | 28 | To be removed  | Falling within excavation line  |
| 48 | NGR118    | Umber       | <i>Ficus racemosa</i>           | 2   | 30 | To be removed  | Falling within excavation line  |
| 49 | NGR118 A  | Putranjiva  | <i>Putranjiva roxburghii</i>    | 10" | 10 | To be removed  | Falling within excavation line  |
| 50 | NGR118 B  | Bhend       | <i>Thespesia populnea</i>       | 10" | 8  | To be removed  | Falling within excavation line  |
| 51 | NGR119    | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 3   | 32 | To be removed  | Falling within excavation line  |
| 52 | NGR120    | Umber       | <i>Ficus racemosa</i>           | 3   | 28 | To be removed  | Falling within excavation line  |
| 53 | NGR 120 A | Sonmohar    | <i>Peltophorum pterocarpum</i>  | 7   | 30 | To be removed  | Falling within excavation line  |
| 54 | NGR 120 B | Bhend       | <i>Thespesia populnea</i>       | 2   | 7  | To be removed  | Falling within excavation line  |
| 55 | 1         | Naral       | <i>Cocos nucifera</i>           | 3   | 24 | To be retained | Falling outside excavation line |
| 56 | 2         | Jambhul     | <i>Syzigium cumini</i>          | 2   | 11 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |      |                |                                 |   |    |                |                                 |
|----|------|----------------|---------------------------------|---|----|----------------|---------------------------------|
| 57 | 3    | Jambhul        | <i>Syzigium cumini</i>          | 3 | 18 | To be retained | Falling outside excavation line |
| 58 | 4    | Asupalav       | <i>Polyalthia longifolia</i>    | 5 | 36 | To be retained | Falling outside excavation line |
| 59 | 5    | Jungli Badam   | <i>Sterculia foetida</i>        | 4 | 45 | To be retained | Falling outside excavation line |
| 60 | 6    | Fanas          | <i>Artocarpus heterophyllus</i> | 3 | 15 | To be retained | Falling outside excavation line |
| 61 | 7    | Deshi Badam    | <i>Terminalia catappa</i>       | 2 | 21 | To be retained | Falling outside excavation line |
| 62 | 8    | Wad            | <i>Ficus benghalensis</i>       | 2 | 18 | To be retained | Falling outside excavation line |
| 63 | 9    | Jambhul        | <i>Syzigium cumini</i>          | 2 | 21 | To be retained | Falling outside excavation line |
| 64 | 10   | Peru           | <i>Psidium gujava</i>           | 2 | 21 | To be retained | Falling outside excavation line |
| 65 | 11   | Umbar          | <i>Ficus glomerata</i>          | 2 | 9  | To be retained | Falling outside excavation line |
| 66 | 12   | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 2 | 24 | To be retained | Falling outside excavation line |
| 67 | 13   | Umbar          | <i>Ficus glomerata</i>          | 4 | 42 | To be retained | Falling outside excavation line |
| 68 | 14   | Jambhul        | <i>Syzigium cumini</i>          | 2 | 30 | To be retained | Falling outside excavation line |
| 69 | 15   | Naral          | <i>Cocus nucifera</i>           | 3 | 27 | To be retained | Falling outside excavation line |
| 70 | 16   | Naral          | <i>Cocus nucifera</i>           | 3 | 27 | To be retained | Falling outside excavation line |
| 71 | 17   | Asupalav       | <i>Polyalthia longifolia</i>    | 3 | 30 | To be retained | Falling outside excavation line |
| 72 | 18   | Jungli Badam   | <i>Sterculia foetida</i>        | 5 | 45 | To be retained | Falling outside excavation line |
| 73 | 18 A | Ratangunj      | <i>Adenanthera pavonina</i>     | 3 | 24 | To be retained | Falling outside excavation line |
| 74 | 19   | Jambhul        | <i>Syzigium cumini</i>          | 3 | 24 | To be retained | Falling outside excavation line |
| 75 | 20   | Asupalav       | <i>Polyalthia longifolia</i>    | 3 | 24 | To be retained | Falling outside excavation line |
| 76 | 21   | Badam          | <i>Terminalia catappa</i>       | 3 | 27 | To be retained | Falling outside excavation line |
| 77 | 22   | Jungli Badam   | <i>Sterculia foetida</i>        | 4 | 18 | To be retained | Falling outside excavation line |
| 78 | 23   | Jungli Badam   | <i>Sterculia foetida</i>        | 2 | 30 | To be retained | Falling outside excavation line |
| 79 | 24   | Badam          | <i>Terminalia catappa</i>       | 1 | 21 | To be retained | Falling outside excavation line |
| 80 | 25   | Jungli Badam   | <i>Sterculia foetida</i>        | 3 | 24 | To be retained | Falling outside excavation line |
| 81 | 26   | Jungli Badam   | <i>Sterculia foetida</i>        | 3 | 21 | To be removed  | Falling within excavation line  |
| 82 | 27   | Sonmohar       | <i>Peltophorum pterocarpum</i>  | 3 | 36 | To be retained | Falling outside excavation line |
| 83 | 28   | Karanj         | <i>Pongamia pinnata</i>         | 2 | 39 | To be retained | Falling outside excavation line |
| 84 | 29   | Sonmohar       | <i>Peltophorum pterocarpum</i>  | 3 | 36 | To be retained | Falling outside excavation line |
| 85 | 30   | Sonmohar       | <i>Peltophorum pterocarpum</i>  | 4 | 36 | To be retained | Falling outside excavation line |
| 86 | 31   | Karanj         | <i>Pongamia pinnata</i>         | 6 | 24 | To be retained | Falling outside excavation line |
| 87 | 32   | Badam          | <i>Terminalia catappa</i>       | 3 | 21 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |             |                                |    |    |                |                                 |
|-----|------|-------------|--------------------------------|----|----|----------------|---------------------------------|
| 88  | 33   | Badam       | <i>Terminalia catappa</i>      | 3  | 21 | To be retained | Falling outside excavation line |
| 89  | 34   | Badam       | <i>Terminalia catappa</i>      | 3  | 21 | To be retained | Falling outside excavation line |
| 90  | 35   | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3  | 36 | To be retained | Falling outside excavation line |
| 91  | 36   | Badam       | <i>Terminalia catappa</i>      | 3  | 27 | To be retained | Falling outside excavation line |
| 92  | 37   | Asupalav    | <i>Polyalthia longifolia</i>   | 3  | 21 | To be retained | Falling outside excavation line |
| 93  | 38   | Badam       | <i>Terminalia catappa</i>      | 2  | 30 | To be retained | Falling outside excavation line |
| 94  | 39   | Jambhul     | <i>Syzigium cumini</i>         | 4  | 42 | To be retained | Falling outside excavation line |
| 95  | 40   | Wad         | <i>Ficus benghalensis</i>      | 4  | 39 | To be retained | Falling outside excavation line |
| 96  | 41   | Asupalav    | <i>Polyalthia longifolia</i>   | 5  | 30 | To be retained | Falling outside excavation line |
| 97  | 42   | Wad         | <i>Ficus benghalensis</i>      | 11 | 54 | To be retained | Falling outside excavation line |
| 98  | 42 A | Umbar       | <i>Ficus glomerata</i>         | 5  | 36 | To be retained | Falling outside excavation line |
| 99  | 42 B | Pimpal      | <i>Ficus religiosa</i>         | 7  | 42 | To be retained | Falling outside excavation line |
| 100 | 42 C | Coconut     | <i>Cocos nucifera</i>          | 3  | 36 | To be retained | Falling outside excavation line |
| 101 | 43   | Pimpal      | <i>Ficus religiosa</i>         | 9  | 54 | To be retained | Falling outside excavation line |
| 102 | 44   | Asupalav    | <i>Polyalthia longifolia</i>   | 3  | 30 | To be retained | Falling outside excavation line |
| 103 | 45   | Bhend       | <i>Thespesia polunea</i>       | 3  | 27 | To be retained | Falling outside excavation line |
| 104 | 46   | Umbar       | <i>Ficus glomerata</i>         | 2  | 30 | To be retained | Falling outside excavation line |
| 105 | 47   | Pimpal      | <i>Ficus religiosa</i>         | 2  | 15 | To be retained | Falling outside excavation line |
| 106 | 48   | Kadipatta   | <i>Murraya koenigii</i>        | 2  | 11 | To be retained | Falling outside excavation line |
| 107 | 49   | Ramphal     | <i>Annona reticulata</i>       | 2  | 18 | To be retained | Falling outside excavation line |
| 108 | 50   | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3  | 36 | To be retained | Falling outside excavation line |
| 109 | 51   | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3  | 36 | To be retained | Falling outside excavation line |
| 110 | 52   | Gulmohar    | <i>Delonix regia</i>           | 3  | 33 | To be retained | Falling outside excavation line |
| 111 | 53   | Putranjiva  | <i>Putranjiva roxburghii</i>   | 4  | 40 | To be retained | Falling outside excavation line |
| 112 | 54   | Sonchapha   | <i>Michelia champaca</i>       | 3  | 40 | To be removed  | Falling within excavation line  |
| 113 | 55   | Putranjiva  | <i>Putranjiva roxburghii</i>   | 3  | 33 | To be removed  | Falling within excavation line  |
| 114 | 56   | Sonchapha   | <i>Michelia champaca</i>       | 3  | 40 | To be removed  | Falling within excavation line  |
| 115 | 57   | Umbar       | <i>Ficus glomerata</i>         | 3  | 36 | To be removed  | Falling within excavation line  |
| 116 | 58   | Karanj      | <i>Pongamia pinnata</i>        | 3  | 9  | To be removed  | Falling within excavation line  |
| 117 | 59   | Deshi Badam | <i>Terminalia catappa</i>      | 3  | 54 | To be removed  | Falling within excavation line  |
| 118 | 60   | Asupalav    | <i>Polyalthia longifolia</i>   | 2  | 30 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                    |                              |    |    |                |                                 |
|-----|------|--------------------|------------------------------|----|----|----------------|---------------------------------|
| 119 | 61   | Asupalav           | <i>Polyalthia longifolia</i> | 2  | 36 | To be removed  | Falling within excavation line  |
| 120 | 62   | Badam              | <i>Terminalia catappa</i>    | 3  | 36 | To be retained | Falling outside excavation line |
| 121 | 63   | Sitaphal           | <i>Annona squamosa</i>       | 2  | 30 | To be retained | Falling outside excavation line |
| 122 | 64   | Indian rubber tree | <i>Ficus elastica</i>        | 2  | 11 | To be retained | Falling outside excavation line |
| 123 | 65   | Badam              | <i>Terminalia catappa</i>    | 3  | 36 | To be retained | Falling outside excavation line |
| 124 | 66   | Coconut            | <i>Cocos nucifera</i>        | 2  | 12 | To be retained | Falling outside excavation line |
| 125 | 67   | Peru               | <i>Psidium gujava</i>        | 2  | 6  | To be retained | Falling outside excavation line |
| 126 | 68   | Asupalav           | <i>Polyalthia longifolia</i> | 3  | 42 | To be retained | Falling outside excavation line |
| 127 | 69   | Asupalav           | <i>Polyalthia longifolia</i> | 3  | 15 | To be retained | Falling outside excavation line |
| 128 | 70   | Royal Palm         | <i>Roystonea regia</i>       | 7  | 54 | To be retained | Falling outside excavation line |
| 129 | 71   | Putranjiva         | <i>Putranjiva roxburghii</i> | 3  | 24 | To be retained | Falling outside excavation line |
| 130 | 72   | Sitaphal           | <i>Annona squamosa</i>       | 3  | 15 | To be retained | Falling outside excavation line |
| 131 | 73   | Peru               | <i>Psidium gujava</i>        | 3  | 12 | To be retained | Falling outside excavation line |
| 132 | 74   | Peru               | <i>Psidium gujava</i>        | 3  | 12 | To be retained | Falling outside excavation line |
| 133 | 75   | Coconut            | <i>Cocos nucifera</i>        | 5  | 21 | To be retained | Falling outside excavation line |
| 134 | 76   | Jungli Badam       | <i>Sterculia foetida</i>     | 3  | 30 | To be retained | Falling outside excavation line |
| 135 | 77   | Jambhul            | <i>Syzigium cumini</i>       | 3  | 30 | To be retained | Falling outside excavation line |
| 136 | 78   | Umbar              | <i>Ficus glomerata</i>       | 8  | 39 | To be retained | Falling outside excavation line |
| 137 | 79   | Umbar              | <i>Ficus glomerata</i>       | 3  | 42 | To be retained | Falling outside excavation line |
| 138 | 80   | Umbar              | <i>Ficus glomerata</i>       | 4  | 36 | To be retained | Falling outside excavation line |
| 139 | 81   | Tecoma stans       | <i>Tecoma stans</i>          | 4  | 18 | To be retained | Falling outside excavation line |
| 140 | 82   | Khair              | <i>Acacia catechu</i>        | 4  | 12 | To be retained | Falling outside excavation line |
| 141 | 83   | Tecoma stans       | <i>Tecoma stans</i>          | 4  | 15 | To be retained | Falling outside excavation line |
| 142 | 84   | Pimpal             | <i>Ficus religiosa</i>       | 9  | 36 | To be retained | Falling outside excavation line |
| 143 | 84 A | Pimpal             | <i>Ficus religiosa</i>       | 6  | 45 | To be retained | Falling outside excavation line |
| 144 | 85   | Kashid             | <i>Cassia siamea</i>         | 2  | 36 | To be retained | Falling outside excavation line |
| 145 | 86   | Karanj             | <i>Pongamia pinnata</i>      | 7  | 42 | To be retained | Falling outside excavation line |
| 146 | 87   | Pimpal             | <i>Ficus religiosa</i>       | 3  | 30 | To be retained | Falling outside excavation line |
| 147 | 88   | Pimpal             | <i>Ficus religiosa</i>       | 11 | 45 | To be retained | Falling outside excavation line |
| 148 | 89   | Umbar              | <i>Ficus glomerata</i>       | 4  | 30 | To be retained | Falling outside excavation line |
| 149 | 90   | Umbar              | <i>Ficus glomerata</i>       | 3  | 36 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |               |            |                                |   |    |                |                                 |
|-----|---------------|------------|--------------------------------|---|----|----------------|---------------------------------|
| 150 | 91            | Asupalav   | <i>Polyalthia longifolia</i>   | 2 | 30 | To be retained | Falling outside excavation line |
| 151 | 92            | Asupalav   | <i>Polyalthia longifolia</i>   | 2 | 27 | To be retained | Falling outside excavation line |
| 152 | 92 A          | Asupalav   | <i>Polyalthia longifolia</i>   | 3 | 24 | To be retained | Falling outside excavation line |
| 153 | 93            | Rain tree  | <i>Samanea saman</i>           | 3 | 30 | To be retained | Falling outside excavation line |
| 154 | 94            | Asupalav   | <i>Polyalthia longifolia</i>   | 3 | 33 | To be retained | Falling outside excavation line |
| 155 | 95            | Asupalav   | <i>Polyalthia longifolia</i>   | 5 | 45 | To be retained | Falling outside excavation line |
| 156 | 96            | Royal Palm | <i>Roystonea regia</i>         | 4 | 45 | To be retained | Falling outside excavation line |
| 157 | 97            | Chapha     | <i>Plumeria alba</i>           | 3 | 20 | To be retained | Falling outside excavation line |
| 158 | 98            | Umbar      | <i>Ficus glomerata</i>         | 2 | 18 | To be retained | Falling outside excavation line |
| 159 | 99            | Asupalav   | <i>Polyalthia longifolia</i>   | 2 | 15 | To be retained | Falling outside excavation line |
| 160 | 100           | Peru       | <i>Psidium gujava</i>          | 2 | 9  | To be retained | Falling outside excavation line |
| 161 | 101           | Peru       | <i>Psidium gujava</i>          | 2 | 10 | To be retained | Falling outside excavation line |
| 162 | 102           | Peru       | <i>Psidium gujava</i>          | 2 | 21 | To be retained | Falling outside excavation line |
| 163 | 103           | Bael       | <i>Aegle marmelos</i>          | 2 | 11 | To be retained | Falling outside excavation line |
| 164 | 104           | Amba       | <i>Mangifera indica</i>        | 4 | 36 | To be retained | Falling outside excavation line |
| 165 | Additional-1  | Pimpal     | <i>Ficus religiosa</i>         | 7 | 50 | To be removed  | Falling within excavation line  |
| 166 | Additional-2  | Desi Badam | <i>Terminalia catappa</i>      | 2 | 25 | To be removed  | Falling within excavation line  |
| 167 | Additional-3  | Umber      | <i>Ficus racemosa</i>          | 2 | 20 | To be removed  | Falling within excavation line  |
| 168 | Additional-4  | Bhendi     | <i>Thespesia populnea</i>      | 3 | 30 | To be retained | Falling outside excavation line |
| 169 | Additional-5  | Bhendi     | <i>Thespesia populnea</i>      | 4 | 45 | To be retained | Falling outside excavation line |
| 170 | Additional-6  | Pimpal     | <i>Ficus religiosa</i>         | 6 | 50 | To be retained | Falling outside excavation line |
| 171 | Additional-7  | Sonmohar   | <i>Peltophorum pterocarpum</i> | 3 | 35 | To be retained | Falling outside excavation line |
| 172 | Additional-8  | Pimpal     | <i>Ficus religiosa</i>         | 8 | 60 | To be retained | Falling outside excavation line |
| 173 | Additional-9  | Sonmohar   | <i>Peltophorum pterocarpum</i> | 4 | 50 | To be retained | Falling outside excavation line |
| 174 | Additional-10 | Bhendi     | <i>Thespesia populnea</i>      | 2 | 20 | To be retained | Falling outside excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 111        |
| Trees to be removed  | 63         |
| <b>Total Trees</b>   | <b>174</b> |



| Summary of Tree Survey at Shitaladevi Station |          |              |                                |                     |                      |                |                                 |
|---|----------|--------------|--------------------------------|---------------------|----------------------|----------------|---------------------------------|
| Sr. no.                                       | Tree no. | Common Name  | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Remark         | Proposed suggestion             |
| 1   | LJ96     | Jangli Badam | <i>Sterculia foetida</i>       | 3                   | 30                   | To be retained | Falling outside excavation line |
| 2   | LJ 97    | Wad          | <i>Ficus benghalensis</i>      | 7                   | 53                   | To be retained | Falling outside excavation line |
| 3   | LJ 98    | Bhend        | <i>Thespesia populnea</i>      | 1                   | 10                   | To be removed  | Falling within excavation line  |
| 4   | LJ 98A   | Markhamiya   | <i>Markhamia platycalyx</i>    | 1                   | 10                   | To be removed  | Falling within excavation line  |
| 5   | LJ 99    | Gulmohar     | <i>Delonix regia</i>           | 2                   | 15                   | To be removed  | Falling within excavation line  |
| 6   | LJ 100   | Gulmohar     | <i>Delonix regia</i>           | 3                   | 22                   | To be removed  | Falling within excavation line  |
| 7   | LJ 101   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3                   | 25                   | To be removed  | Falling within excavation line  |
| 8   | LJ 103   | Gulmohar     | <i>Delonix Regia</i>           | 1                   | 20                   | To be removed  | Falling within excavation line  |
| 9   | LJ 104   | Jangli Badam | <i>Sterculia foetida</i>       | 1                   | 20                   | To be removed  | Falling within excavation line  |
| 10  | LJ 106   | Jangli Badam | <i>Sterculia foetida</i>       | 1                   | 22                   | To be removed  | Falling within excavation line  |
| 11  | LJ 107   | Karanj       | <i>Pongamia pinnata</i>        | 1                   | 8                    | To be removed  | Falling within excavation line  |
| 12  | LJ 109   | Karanj       | <i>Pongamia pinnata</i>        | 1                   | 20                   | To be removed  | Falling within excavation line  |
| 13  | LJ 110   | Rain Tree    | <i>Samanea saman</i>           | 3                   | 40                   | To be removed  | Falling within excavation line  |
| 14  | LJ 111   | Karanj       | <i>Pongamia Pinata</i>         | 1                   | 15                   | To be removed  | Falling within excavation line  |
| 15  | LJ 112   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 10"                 | 10                   | To be removed  | Falling within excavation line  |
| 16  | LJ 113   | Bhend        | <i>Thespesia populnea</i>      | 3                   | 30                   | To be removed  | Falling within excavation line  |
| 17  | LJ 114   | Kashid       | <i>Cassia siamea</i>           | 3                   | 23                   | To be removed  | Falling within excavation line  |
| 18  | LJ 114 A | Kaduneem     | <i>Azadirachta indica</i>      | 1                   | 12                   | To be removed  | Falling within excavation line  |
| 19  | LJ 115   | Putranjiva   | <i>Putranjiva roxburghii</i>   | 2                   | 15                   | To be removed  | Falling within excavation line  |
| 20  | LJ 116   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3                   | 18                   | To be removed  | Falling within excavation line  |
| 21  | LJ 117   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3                   | 21                   | To be removed  | Falling within excavation line  |
| 22  | LJ 118   | Karanj       | <i>Pongamia pinnata</i>        | 1                   | 15                   | To be removed  | Falling within excavation line  |
| 23  | LJ 118 A | Pimpal       | <i>Ficus religiosa</i>         | 8                   | 21                   | To be removed  | Falling within excavation line  |
| 24  | LJ 118 B | Savar        | <i>Ceiba pentandra</i>         | 1                   | 12                   | To be removed  | Falling within excavation line  |
| 25  | LJ 118 C | Amba         | <i>Mangifera indica</i>        | 5                   | 24                   | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |          |              |                                |    |    |                |                                 |
|----|----------|--------------|--------------------------------|----|----|----------------|---------------------------------|
| 26 | LJ 118 D | Shevga       | <i>Moringa oliefera</i>        | 1  | 9  | To be retained | Falling outside excavation line |
| 27 | LJ 118 E | Asupalav     | <i>Polyalthia longifolia</i>   | 1  | 9  | To be retained | Falling outside excavation line |
| 28 | LJ 118 F | Asupalav     | <i>Polyalthia longifolia</i>   | 1  | 9  | To be retained | Falling outside excavation line |
| 29 | LJ 118 G | Asupalav     | <i>Polyalthia longifolia</i>   | 1  | 9  | To be retained | Falling outside excavation line |
| 30 | LJ 118 H | Asupalav     | <i>Polyalthia longifolia</i>   | 1  | 12 | To be retained | Falling outside excavation line |
| 31 | LJ 118 I | Amba         | <i>Mangifera indica</i>        | 1  | 15 | To be retained | Falling outside excavation line |
| 32 | LJ 118 J | Chinch       | <i>Tamarindus indica</i>       | 5  | 24 | To be removed  | Falling within excavation line  |
| 33 | LJ 118 K | Kaduneem     | <i>Azadirachta indica</i>      | 5  | 24 | To be retained | Falling outside excavation line |
| 34 | LJ 118 L | Asupalav     | <i>Polyalthia longifolia</i>   | 1  | 18 | To be retained | Falling outside excavation line |
| 35 | LJ 118 M | Asupalav     | <i>Polyalthia longifolia</i>   | 2  | 24 | To be retained | Falling outside excavation line |
| 36 | LJ 118 N | Asupalav     | <i>Polyalthia longifolia</i>   | 2  | 21 | To be retained | Falling outside excavation line |
| 37 | LJ 118 O | Narul        | <i>Cocus nucifera</i>          | 3  | 24 | To be retained | Falling outside excavation line |
| 38 | LJ 118 P | Royal palm   | <i>Roystonea regia</i>         | 5  | 27 | To be removed  | Falling within excavation line  |
| 39 | LJ 118 Q | Royal palm   | <i>Roystonea regia</i>         | 5  | 27 | To be removed  | Falling within excavation line  |
| 40 | LJ 122   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4  | 35 | To be removed  | Falling within excavation line  |
| 41 | LJ 123   | Kadamba      | <i>Neolamarckia cadamba</i>    | 2  | 30 | To be removed  | Falling within excavation line  |
| 42 | LJ 174   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 43 | LJ 174 A | Sonmohar     | <i>Peltophorum pterocarpum</i> | 4  | 21 | To be removed  | Falling within excavation line  |
| 44 | LJ 174 B | Markhamiya   | <i>Markhamia platycalyx</i>    | 1  | 9  | To be removed  | Falling within excavation line  |
| 45 | LJ 174 C | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2  | 15 | To be removed  | Falling within excavation line  |
| 46 | LJ 174 D | Markhamiya   | <i>Markhamia platycalyx</i>    | 1  | 12 | To be removed  | Falling within excavation line  |
| 47 | LJ 174 E | Wad          | <i>Ficus benghalensis</i>      | 2  | 20 | To be removed  | Falling within excavation line  |
| 48 | LJ 175   | Putranjiva   | <i>Putranjiva roxburghii</i>   | 3  | 30 | To be removed  | Falling within excavation line  |
| 49 | LJ 176   | Jangli Badam | <i>Sterculia foetida</i>       | 3  | 32 | To be removed  | Falling within excavation line  |
| 50 | LJ 177   | Bhend        | <i>Thespesia populnea</i>      | 1  | 10 | To be removed  | Falling within excavation line  |
| 51 | LJ 178   | Jangli Badam | <i>Sterculia foetida</i>       | 1  | 20 | To be removed  | Falling within excavation line  |
| 52 | LJ 179   | Wad          | <i>Ficus benghalensis</i>      | 1  | 12 | To be removed  | Falling within excavation line  |
| 53 | LJ 180   | Bhend        | <i>Thespesia populnea</i>      | 2  | 18 | To be removed  | Falling within excavation line  |
| 54 | LJ 181   | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3  | 18 | To be removed  | Falling within excavation line  |
| 55 | LJ 182   | Jangli Badam | <i>Sterculia foetida</i>       | 1  | 28 | To be removed  | Falling within excavation line  |
| 56 | LJ 183   | Jangli Badam | <i>Sterculia foetida</i>       | 10 | 30 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |          |                 |                                |    |    |               |                                |
|----|----------|-----------------|--------------------------------|----|----|---------------|--------------------------------|
| 57 | LJ 184   | Jangli Badam    | <i>Sterculia foetida</i>       | 10 | 30 | To be removed | Falling within excavation line |
| 58 | LJ 185   | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1  | 25 | To be removed | Falling within excavation line |
| 59 | LJ 186   | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1  | 30 | To be removed | Falling within excavation line |
| 60 | LJ 188   | Rain Tree       | <i>Samanea saman</i>           | 4  | 30 | To be removed | Falling within excavation line |
| 61 | LJ 189   | Wad             | <i>Ficus benghalensis</i>      | 10 | 12 | To be removed | Falling within excavation line |
| 62 | LJ 190   | Jangli Badam    | <i>Sterculia foetida</i>       | 3  | 30 | To be removed | Falling within excavation line |
| 63 | LJ 191   | Mahogani        | <i>Swetenia macrophylla</i>    | 4  | 35 | To be removed | Falling within excavation line |
| 64 | LJ 192   | Jangli Badam    | <i>Sterculia foetida</i>       | 3  | 32 | To be removed | Falling within excavation line |
| 65 | LJ 192 A | Kaduneem (Dead) | <i>Azadirachta indica</i>      | 1  | 12 | To be removed | Falling within excavation line |
| 66 | LJ 192 B | Sonmohar        | <i>Peltophorum pterocarpum</i> | 5  | 24 | To be removed | Falling within excavation line |
| 67 | LJ 192 C | Sonmohar        | <i>Peltophorum pterocarpum</i> | 5  | 21 | To be removed | Falling within excavation line |
| 68 | LJ 192 D | Pimpal          | <i>Ficus religiosa</i>         | 12 | 21 | To be removed | Falling within excavation line |
| 69 | LJ 193   | Pimpal          | <i>Ficus Religiosa</i>         | 4  | 40 | To be removed | Falling within excavation line |
| 70 | LJ 194   | Jangli Badam    | <i>Sterculia foetida</i>       | 3  | 40 | To be removed | Falling within excavation line |
| 71 | LJ 195   | Jangli Badam    | <i>Sterculia foetida</i>       | 3  | 45 | To be removed | Falling within excavation line |
| 72 | LJ 196   | Sonmohar        | <i>Peltophorum pterocarpum</i> | 2  | 40 | To be removed | Falling within excavation line |
| 73 | LJ 197   | Sonmohar        | <i>Peltophorum pterocarpum</i> | 2  | 40 | To be removed | Falling within excavation line |
| 74 | LJ 198   | Jangli Badam    | <i>Sterculia foetida</i>       | 2  | 35 | To be removed | Falling within excavation line |
| 75 | LJ 199   | Chafa           | <i>Plumeria alba</i>           | 1  | 5  | To be removed | Falling within excavation line |
| 76 | LJ 200   | Chafa           | <i>Plumeria alba</i>           | 1  | 5  | To be removed | Falling within excavation line |

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 14        |
| Trees to be removed  | 62        |
| <b>Total Trees</b>   | <b>76</b> |

| Summary of Tree Survey at Naya-Nagar Station |          |             |                            |                     |                      |                |                                 |
|--|----------|-------------|----------------------------|---------------------|----------------------|----------------|---------------------------------|
| Sr. no.                                      | Tree no. | Common Name | Botanical Name             | Approx. Girth (ft.) | Approx. Height (ft.) | Remark         | Proposed suggestion             |
| 1  | 1        | Desi Badam  | <i>Terminalia catappa</i>  | 1                   | 30                   | To be retained | Falling outside excavation line |
| 2  | 2        | Mango       | <i>Mangifera indica</i>    | 2                   | 30                   | To be retained | Falling outside excavation line |
| 3  | 3        | Jambhul     | <i>Syzygium cumini</i>     | 1                   | 30                   | To be retained | Falling outside excavation line |
| 4  | 4        | Mango       | <i>Mangifera indica</i>    | 1                   | 10                   | To be retained | Falling outside excavation line |
| 5  | 5        | Bor         | <i>Ziziphus mauritiana</i> | 1                   | 10                   | To be retained | Falling outside excavation line |
| 6  | 6        | Shewga      | <i>Moringa oliefera</i>    | 1                   | 15                   | To be retained | Falling outside excavation line |
| 7  | 7        | Shewga      | <i>Moringa oliefera</i>    | 1                   | 15                   | To be retained | Falling outside excavation line |
| 8  | 8        | Shewga      | <i>Moringa oliefera</i>    | 1                   | 15                   | To be retained | Falling outside excavation line |
| 9  | 9        | Shewga      | <i>Moringa oliefera</i>    | 2                   | 20                   | To be removed  | Falling within excavation line  |
| 10   | 10       | Shewga      | <i>Moringa oliefera</i>    | 2                   | 20                   | To be removed  | Falling within excavation line  |
| 11   | 11       | Neem        | <i>Azadirachta indica</i>  | 6                   | 10                   | To be removed  | Falling within excavation line  |
| 12   | 12       | Shewga      | <i>Moringa oliefera</i>    | 2                   | 25                   | To be removed  | Falling within excavation line  |
| 13   | 13       | Mango       | <i>Mangifera indica</i>    | 1                   | 30                   | To be removed  | Falling within excavation line  |
| 14   | 14       | Shewga      | <i>Moringa oliefera</i>    | 2                   | 25                   | To be removed  | Falling within excavation line  |
| 15   | 15       | Shewga      | <i>Moringa oliefera</i>    | 3                   | 35                   | To be removed  | Falling within excavation line  |
| 16   | 16       | Desi Badam  | <i>Terminalia catappa</i>  | 1                   | 30                   | To be removed  | Falling within excavation line  |
| 17   | 17       | Shewga      | <i>Moringa oliefera</i>    | 4                   | 15                   | To be removed  | Falling within excavation line  |
| 18   | 18       | Shewga      | <i>Moringa oliefera</i>    | 1                   | 25                   | To be removed  | Falling within excavation line  |
| 19   | 19       | Shewga      | <i>Moringa oliefera</i>    | 3                   | 25                   | To be removed  | Falling within excavation line  |
| 20   | 20       | Shewga      | <i>Moringa oliefera</i>    | 2                   | 25                   | To be removed  | Falling within excavation line  |
| 21   | 21       | Bhendi      | <i>Thespesia populnea</i>  | 2                   | 25                   | To be removed  | Falling within excavation line  |
| 22   | 22       | Shewga      | <i>Moringa oliefera</i>    | 2                   | 20                   | To be removed  | Falling within excavation line  |
| 23   | 23       | Bhendi      | <i>Thespesia populnea</i>  | 2                   | 20                   | To be removed  | Falling within excavation line  |
| 24   | 24       | Shewga      | <i>Moringa oliefera</i>    | 1                   | 15                   | To be retained | Falling outside excavation line |
| 25   | 25       | Desi Badam  | <i>Terminalia catappa</i>  | 6"                  | 15                   | To be retained | Falling outside excavation line |
| 26   | 26       | Gulmohar    | <i>Delonix regia</i>       | 2                   | 20                   | To be retained | Falling outside excavation line |
| 27   | 27       | Bhendi      | <i>Thespesia populnea</i>  | 2                   | 15                   | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |        |                           |   |    |                |                                 |
|----|----|--------|---------------------------|---|----|----------------|---------------------------------|
| 28 | 28 | Bhendi | <i>Thespesia populnea</i> | 2 | 20 | To be retained | Falling outside excavation line |
|----|----|--------|---------------------------|---|----|----------------|---------------------------------|

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 13        |
| Trees to be removed  | 15        |
| <b>Total Trees</b>   | <b>28</b> |

| Summary of Tree Survey at BKC site office |          |                        |                                |                     |                      |                |                                 |
|---|----------|------------------------|--------------------------------|---------------------|----------------------|----------------|---------------------------------|
| Sr. no.                                   | Tree no. | Common Name            | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Remark         | Proposed suggestion             |
| 1   | 1        | Trema ( charcoal-tree) | <i>Trema orientalis</i>        | 2"                  | 20'                  | To be retained | Falling outside excavation line |
| 2   | 2        | Jangli Badam           | <i>Sterculia foetida</i>       | 2"                  | 15'                  | To be retained | Falling outside excavation line |
| 3   | 3        | Jangli Badam           | <i>Sterculia foetida</i>       | 2"                  | 15'                  | To be retained | Falling outside excavation line |
| 4   | 4        | Jangli Badam           | <i>Sterculia foetida</i>       | 2"                  | 15'                  | To be retained | Falling outside excavation line |
| 5   | 5        | Subhabhul              | <i>Leucaena leucocephala</i>   | 6"                  | 8'                   | To be removed  | Falling within excavation line  |
| 6   | 6        | Subhabhul              | <i>Leucaena leucocephala</i>   | 8"                  | 15'                  | To be retained | Falling outside excavation line |
| 7   | 7        | Subhabhul              | <i>Leucaena leucocephala</i>   | -                   | -                    | To be retained | Falling outside excavation line |
| 8   | 8        | Sonmohar               | <i>Peltophorum pterocarpum</i> | 3'                  | 30'                  | To be retained | Falling outside excavation line |
| 9   | 9        | Royal palm             | <i>Roystonea regia</i>         | 3'                  | 15'                  | To be removed  | Falling within excavation line  |
| 10  | 10       | Royal palm             | <i>Roystonea regia</i>         | 3'                  | 15'                  | To be removed  | Falling within excavation line  |

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 7         |
| Trees to be removed  | 3         |
| <b>Total Trees</b>   | <b>10</b> |

**5. TREE INVENTORY DETAILS AT UGC-05**

| Summary of Tree Survey at Dharavi Station |          |              |                                |                     |                      |                     |                                     |
|---|----------|--------------|--------------------------------|---------------------|----------------------|---------------------|-------------------------------------|
| Sr. no.                                   | Tree no. | Common Name  | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                              |
| 1   | 1        | Jangli Badam | <i>Sterculia foetida</i>       | 2'                  | 30'                  | To be removed       | Falling within excavation line      |
| 2   | 1A       | Neem         | <i>Azadirachta indica</i>      | 10"                 | 15'                  | To be removed       | Falling within excavation line      |
| 3   | 2        | Pimpal       | <i>Ficus religiosa</i>         | 5'                  | 30'                  | To be removed       | Falling within excavation line      |
| 4   | 3        | Bhend        | <i>Thespesia populnea</i>      | 5'                  | 30'                  | To be removed       | Falling within excavation line      |
| 5   | 4        | Pimpal       | <i>Ficus religiosa</i>         | 9'                  | 35'                  | To be removed       | Falling within excavation line      |
| 6   | 5        | Jangli Badam | <i>Sterculia foetida</i>       | 1'                  | 35'                  | To be retained      | Falling out side of excavation line |
| 7   | 6        | Jangli Badam | <i>Sterculia foetida</i>       | 3'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 8   | 7        | Pimpal       | <i>Ficus religiosa</i>         | 1'                  | 30'                  | To be retained      | Falling out side of excavation line |
| 9   | 8        | Katesavar    | <i>Bombax ceiba</i>            | 3'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 10  | 9        | Jangli Badam | <i>Sterculia foetida</i>       | 3'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 11  | 10       | Jangli Badam | <i>Sterculia foetida</i>       | 3'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 12  | 11       | Wad          | <i>Ficus benghalensis</i>      | 10"                 | 15'                  | To be retained      | Falling out side of excavation line |
| 13  | 12       | Jangli Badam | <i>Sterculia foetida</i>       | 1'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 14  | 13       | Jangli Badam | <i>Sterculia foetida</i>       | 1'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 15  | 14       | Jangli Badam | <i>Sterculia foetida</i>       | 1'                  | 30'                  | To be retained      | Falling out side of excavation line |
| 16  | 15       | Mango (Dead) | <i>Mangifera Indica</i>        | 2'                  | 25'                  | To be removed       | Falling within excavation line      |
| 17  | 16       | Jangli Badam | <i>Sterculia foetida</i>       | 1'                  | 30'                  | To be retained      | Falling out side of excavation line |
| 18  | 17       | Sonmohar     | <i>Peltophorum pterocarpum</i> | 1'                  | 30'                  | To be retained      | Falling out side of excavation line |
| 19  | 18       | Jangli Badam | <i>Sterculia foetida</i>       | 2'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 20  | 19       | Karanj       | <i>Pongamia pinnata</i>        | 1'                  | 15'                  | To be retained      | Falling out side of excavation line |
| 21  | 20       | Jangli Badam | <i>Sterculia foetida</i>       | 2'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 22  | 21       | Deshi Badam  | <i>Terminalia catappa</i>      | 10"                 | 15'                  | To be retained      | Falling out side of excavation line |
| 23  | 22       | Jangli Badam | <i>Sterculia foetida</i>       | 1'                  | 55'                  | To be retained      | Falling out side of excavation line |
| 24  | 23       | Jangli Badam | <i>Sterculia foetida</i>       | 1'                  | 50'                  | To be retained      | Falling out side of excavation line |
| 25  | 24       | Umber        | <i>Ficus racemosa</i>          | 3'                  | 40'                  | To be retained      | Falling out side of excavation line |
| 26  | 25       | Jangli Badam | <i>Sterculia foetida</i>       | 2'                  | 30'                  | To be retained      | Falling out side of excavation line |
| 27  | 26       | Deshi Badam  | <i>Terminalia catappa</i>      | 1'                  | 25'                  | To be retained      | Falling out side of excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                        |                                |      |     |                |                                     |
|----|-----|------------------------|--------------------------------|------|-----|----------------|-------------------------------------|
| 28 | 27  | Jangli Badam           | <i>Sterculia foetida</i>       | 3'   | 52' | To be retained | Falling out side of excavation line |
| 29 | 28  | Jangli Badam           | <i>Sterculia foetida</i>       | 3'   | 52' | To be retained | Falling out side of excavation line |
| 30 | 29  | Jangli Badam           | <i>Sterculia foetida</i>       | 3'   | 52' | To be retained | Falling out side of excavation line |
| 31 | 30  | Bhend                  | <i>Thespesia populnea</i>      | 1'   | 30' | To be retained | Falling out side of excavation line |
| 32 | 31  | Jangli Badam           | <i>Sterculia foetida</i>       | 2'   | 55' | To be retained | Falling out side of excavation line |
| 33 | 32  | Karanj                 | <i>Pongamia pinnata</i>        | 10"  | 25' | To be retained | Falling out side of excavation line |
| 34 | 33  | Jangli Badam           | <i>Sterculia foetida</i>       | 2'   | 50' | To be retained | Falling out side of excavation line |
| 35 | 34  | Jangli Badam           | <i>Sterculia foetida</i>       | 2'   | 50' | To be retained | Falling out side of excavation line |
| 36 | 35  | Pimpal                 | <i>Ficus religiosa</i>         | 3'   | 30' | To be retained | Falling out side of excavation line |
| 37 | 36  | Jangli Badam<br>(Dead) | <i>Sterculia foetida</i>       | 1'   | 22' | To be removed  | Falling within excavation line      |
| 38 | 36A | Pimpal                 | <i>Ficus religiosa</i>         | 2'   | 26' | To be removed  | Falling within excavation line      |
| 39 | 36B | Naral                  | <i>Cocos nucifera</i>          | 3'   | 23' | To be removed  | Falling within excavation line      |
| 40 | 36C | Neem                   | <i>Azadirachta indica</i>      | 6"   | 15' | To be removed  | Falling within excavation line      |
| 41 | 36D | Neem                   | <i>Azadirachta indica</i>      | 6"   | 12' | To be removed  | Falling within excavation line      |
| 42 | 36E | Neem                   | <i>Azadirachta indica</i>      | 6"   | 10' | To be removed  | Falling within excavation line      |
| 43 | 37  | Pimpal                 | <i>Ficus religiosa</i>         | 6"   | 12' | To be removed  | Falling within excavation line      |
| 44 | 38  | Neem                   | <i>Azadirachta indica</i>      | 1'   | 13' | To be removed  | Falling within excavation line      |
| 45 | 39  | Gulmohar               | <i>Delonix regia</i>           | 2'   | 16' | To be removed  | Falling within excavation line      |
| 46 | 40  | Desi Badam             | <i>Terminalia catappa</i>      | 1'2" | 20' | To be removed  | Falling within excavation line      |
| 47 | 41  | Naral                  | <i>Cocos nucifera</i>          | 1'3" | 10' | To be removed  | Falling within excavation line      |
| 48 | 42  | Desi Badam             | <i>Terminalia catappa</i>      | 1'   | 10' | To be removed  | Falling within excavation line      |
| 49 | 43  | Neem                   | <i>Azadirachta indica</i>      | 1'   | 7'  | To be removed  | Falling within excavation line      |
| 50 | 44  | Gulmohar               | <i>Delonix regia</i>           | 1'   | 23' | To be removed  | Falling within excavation line      |
| 51 | 45  | Desi Badam             | <i>Terminalia catappa</i>      | 1'2" | 16' | To be removed  | Falling within excavation line      |
| 52 | 46  | Wad                    | <i>Ficus benghalensis</i>      | 3'   | 25' | To be retained | Falling out side of excavation line |
| 53 | 47  | Bhend                  | <i>Thespesia populnea</i>      | 1'   | 20' | To be retained | Falling out side of excavation line |
| 54 | 48  | Bhend                  | <i>Thespesia populnea</i>      | 1'   | 15' | To be retained | Falling out side of excavation line |
| 55 | 49  | Pimpal                 | <i>Ficus religiosa</i>         | 1'5" | 26' | To be removed  | Falling within excavation line      |
| 56 | 50  | Nandarukh              | <i>Ficus benjamina</i>         | 2'6" | 26' | To be removed  | Falling within excavation line      |
| 57 | 51  | Sonmohar               | <i>Peltophorum pterocarpum</i> | 3'   | 26' | To be removed  | Falling within excavation line      |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |              |                                |      |     |                |                                     |
|----|-----|--------------|--------------------------------|------|-----|----------------|-------------------------------------|
| 58 | 52  | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3'   | 26' | To be removed  | Falling within excavation line      |
| 59 | 53  | Nandarukh    | <i>Ficus benjamina</i>         | 2'3" | 26' | To be removed  | Falling within excavation line      |
| 60 | 54  | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2'6" | 23' | To be removed  | Falling within excavation line      |
| 61 | 54A | Pimpal       | <i>Ficus religiosa</i>         | 1'3" | 16' | To be removed  | Falling within excavation line      |
| 62 | 55  | Nandarukh    | <i>Ficus benjamina</i>         | 2'   | 16' | To be removed  | Falling within excavation line      |
| 63 | 56  | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2'   | 20' | To be removed  | Falling within excavation line      |
| 64 | 57  | Nandarukh    | <i>Ficus benjamina</i>         | 1'3" | 10' | To be removed  | Falling within excavation line      |
| 65 | 58  | Sonmohar     | <i>Peltophorum pterocarpum</i> | 1'3" | 20' | To be removed  | Falling within excavation line      |
| 66 | 59  | Nandarukh    | <i>Ficus benjamina</i>         | 1'7" | 10' | To be removed  | Falling within excavation line      |
| 67 | 60  | Nandarukh    | <i>Ficus benjamina</i>         | 1'6" | 10' | To be removed  | Falling within excavation line      |
| 68 | 61  | Desi badam   | <i>Terminalia catappa</i>      | 1'   | 11' | To be removed  | Falling within excavation line      |
| 69 | 62  | Chapha       | <i>Plumeria alba</i>           | 1'2" | 10' | To be removed  | Falling within excavation line      |
| 70 | 63  | Asupalav     | <i>Polyalthia longifolia</i>   | 1'   | 10' | To be removed  | Falling within excavation line      |
| 71 | 64  | Desi badam   | <i>Terminalia catappa</i>      | 1'2" | 11' | To be retained | Falling out side of excavation line |
| 72 | 65  | Desi badam   | <i>Terminalia catappa</i>      | 1'2" | 11' | To be retained | Falling out side of excavation line |
| 73 | 66  | Pimpal       | <i>ficus religiosa</i>         | 1'2" | 18' | To be removed  | Falling within excavation line      |
| 74 | 67  | desi badam   | <i>terminalia catappa</i>      | 2'8" | 30' | To be removed  | Falling within excavation line      |
| 75 | 68  | Bhend (Dead) | <i>thespesia populnea</i>      | 10"  | 12' | To be removed  | Falling within excavation line      |
| 76 | 69  | Bhend        | <i>thespesia populnea</i>      | 3'3" | 33' | To be removed  | Falling within excavation line      |
| 77 | 70  | desi badam   | <i>terminalia catappa</i>      | 2'4" | 35' | To be removed  | Falling within excavation line      |
| 78 | 71  | desi badam   | <i>terminalia catappa</i>      | 1'9" | 35' | To be removed  | Falling within excavation line      |
| 79 | 72  | jungle badam | <i>sterculia foetida</i>       | 3'9" | 35' | To be removed  | Falling within excavation line      |
| 80 | 73  | desi badam   | <i>terminalia catappa</i>      | 2'2" | 30' | To be removed  | Falling within excavation line      |
| 81 | 74  | Aawala       | <i>Emblica officindis</i>      | 5"   | 10' | To be removed  | Falling within excavation line      |
| 82 | 75  | Mango        | <i>mangifera indica</i>        | 6"   | 12' | To be removed  | Falling within excavation line      |
| 83 | 76  | Pimpal       | <i>ficus religiosa</i>         | 6"   | 12' | To be removed  | Falling within excavation line      |

**PART-II: TREE INVENTORY DETAILS**

**GENERAL CONSULTANT FOR MUMBAI METRO LINE 3**

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 35        |
| Trees to be removed  | 48        |
| <b>Total Trees</b>   | <b>83</b> |

| Summary of Tree Survey at BKC Station |          |               |                                |                     |                      |                     |                                     |
|---------------------------------------|----------|---------------|--------------------------------|---------------------|----------------------|---------------------|-------------------------------------|
| Sr. no.                               | Tree no. | Common Name   | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                              |
| 1                                     | 1        | Desi badam    | <i>Terminalia catappa</i>      | 1                   | 30                   | To be removed       | Falling within excavation line      |
| 2                                     | 2        | Asupalav      | <i>Polyalthia longifolia</i>   | 1                   | 23                   | To be removed       | Falling within excavation line      |
| 3                                     | 3        | Asupalav      | <i>Polyalthia longifolia</i>   | 1                   | 23                   | To be removed       | Falling within excavation line      |
| 4                                     | 4        | Asupalav      | <i>Polyalthia longifolia</i>   | 1                   | 30                   | To be removed       | Falling within excavation line      |
| 5                                     | 5        | Asupalav      | <i>Polyalthia longifolia</i>   | 1                   | 16                   | To be removed       | Falling within excavation line      |
| 6                                     | 6        | Naral         | <i>Cocos nucifera</i>          | 3                   | 39                   | To be removed       | Falling within excavation line      |
| 7                                     | 7        | Asupalav      | <i>Polyalthia longifolia</i>   | 1                   | 30                   | To be removed       | Falling within excavation line      |
| 8                                     | 8        | Umber         | <i>Ficus racemosa</i>          | 2                   | 33                   | To be removed       | Falling within excavation line      |
| 9                                     | 9        | Asupalav      | <i>Polyalthia longifolia</i>   | 1'4"                | 20                   | To be removed       | Falling within excavation line      |
| 10                                    | 10       | Naral         | <i>Cocos nucifera</i>          | 3                   | 39                   | To be removed       | Falling within excavation line      |
| 11                                    | 11       | Jamun         | <i>Syzygium cumini</i>         | 1                   | 23                   | To be removed       | Falling within excavation line      |
| 12                                    | 12       | Asupalav      | <i>Polyalthia longifolia</i>   | 1                   | 20                   | To be removed       | Falling within excavation line      |
| 13                                    | 13       | Asupalav      | <i>Polyalthia longifolia</i>   | 1.3                 | 22                   | To be retained      | Falling out side of excavation line |
| 14                                    | 14       | Desi badam    | <i>Terminalia catappa</i>      | 2                   | 30                   | To be retained      | Falling out side of excavation line |
| 15                                    | 15       | Wad           | <i>Ficus benghalensis</i>      | 7                   | 30                   | To be retained      | Falling out side of excavation line |
| 16                                    | 16       | Sonmohar      | <i>Peltophorum pterocarpum</i> | 3                   | 33                   | To be removed       | Falling within excavation line      |
| 17                                    | 17       | Wad           | <i>Ficus religiosa</i>         | 20                  | 33                   | To be retained      | Falling out side of excavation line |
| 18                                    | 18       | Desi badam    | <i>Terminalia catappa</i>      | 1                   | 16                   | To be retained      | Falling out side of excavation line |
| 19                                    | 19       | Desi badam    | <i>Terminalia catappa</i>      | 2                   | 23                   | To be retained      | Falling out side of excavation line |
| 20                                    | 20       | Charcoal tree | <i>Trema orientalis</i>        | 1                   | 16                   | To be retained      | Falling out side of excavation line |
| 21                                    | 21       | Pimpal        | <i>Ficus religiosa</i>         | 1                   | 16                   | To be retained      | Falling out side of excavation line |
| 22                                    | 22       | Kala umber    | <i>Ficus hispida</i>           | 1                   | 18                   | To be removed       | Falling within excavation line      |
| 23                                    | 23       | Kala umber    | <i>Ficus hispida</i>           | 8                   | 18                   | To be removed       | Falling within excavation line      |
| 24                                    | 24       | Kala umber    | <i>Ficus hispida</i>           | 2                   | 18                   | To be removed       | Falling within excavation line      |
| 25                                    | 25       | Kala umber    | <i>Ficus hispida</i>           | 3                   | 20                   | To be removed       | Falling within excavation line      |
| 26                                    | 26       | Pimpal        | <i>Ficus religiosa</i>         | 6                   | 40                   | To be removed       | Falling within excavation line      |
| 27                                    | 27       | Saptaparni    | <i>Alstonia scholaris</i>      | 5                   | 33                   | To be removed       | Falling within excavation line      |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |      |            |                                 |    |    |                |                                     |
|----|------|------------|---------------------------------|----|----|----------------|-------------------------------------|
| 28 | 28   | Asupalav   | <i>Polyalthia longifolia</i>    | 1  | 20 | To be removed  | Falling within excavation line      |
| 29 | 29   | Pichkari   | <i>Spathodea campanulata</i>    | 6  | 39 | To be removed  | Falling within excavation line      |
| 30 | 30   | Pichkari   | <i>Spathodea campanulata</i>    | 6  | 39 | To be removed  | Falling within excavation line      |
| 31 | 31   | Pichkari   | <i>Spathodea campanulata</i>    | 5  | 39 | To be retained | Falling out side of excavation line |
| 32 | 32   | Pangara    | <i>Erythrina indica</i>         | 4  | 30 | To be removed  | Falling within excavation line      |
| 33 | 33   | Pimpal     | <i>Ficus religiosa</i>          | 7  | 33 | To be removed  | Falling within excavation line      |
| 34 | 34   | Rain tree  | <i>Samanea saman</i>            | 1  | 13 | To be removed  | Falling within excavation line      |
| 35 | 35   | Amba       | <i>Mangifera indica</i>         | 8" | 6  | To be retained | Falling out side of excavation line |
| 36 | 36   | Naral      | <i>Cocos nucifera</i>           | 1  | 12 | To be retained | Falling out side of excavation line |
| 37 | 37   | Naral      | <i>Cocos nucifera</i>           | 2  | 36 | To be removed  | Falling within excavation line      |
| 38 | 38   | Asupalav   | <i>Polyalthia longifolia</i>    | 4  | 8  | To be removed  | Falling within excavation line      |
| 39 | 39   | Naral      | <i>Cocos nucifera</i>           | 2  | 43 | To be removed  | Falling within excavation line      |
| 40 | 40   | Naral      | <i>Cocos nucifera</i>           | 4  | 50 | To be removed  | Falling within excavation line      |
| 41 | 41   | Naral      | <i>Cocos nucifera</i>           | 4  | 50 | To be retained | Falling out side of excavation line |
| 42 | 42   | Rain Tree  | <i>Samanea saman</i>            | 6  | 28 | To be removed  | Falling within excavation line      |
| 43 | 43   | Rain Tree  | <i>Samanea saman</i>            | 7  | 25 | To be removed  | Falling within excavation line      |
| 44 | 44   | Asupalav   | <i>Polyalthia longifolia</i>    | 2  | 20 | To be retained | Falling out side of excavation line |
| 45 | 44 A | Asupalav   | <i>Polyalthia longifolia</i>    | 2  | 20 | To be retained | Falling out side of excavation line |
| 46 | 44 B | Asupalav   | <i>Polyalthia longifolia</i>    | 2  | 20 | To be retained | Falling out side of excavation line |
| 47 | 44 C | Phanas     | <i>Artocarpus heterophyllus</i> | 1  | 21 | To be retained | Falling out side of excavation line |
| 48 | 45   | Desi Badam | <i>Terminalia catappa</i>       | 6  | 50 | To be retained | Falling out side of excavation line |
| 49 | 45 A | Supari     | <i>Areca catechu</i>            | 1  | 20 | To be retained | Falling out side of excavation line |
| 50 | 45 B | Asupalav   | <i>Polyalthia longifolia</i>    | 1  | 20 | To be retained | Falling out side of excavation line |
| 51 | 45 C | Areca palm | <i>Dyopsis lutescens</i>        | 1  | 18 | To be retained | Falling out side of excavation line |
| 52 | 46   | Asupalav   | <i>Polyalthia longifolia</i>    | 1  | 18 | To be retained | Falling out side of excavation line |
| 53 | 46 A | Asupalav   | <i>Polyalthia longifolia</i>    | 2  | 18 | To be retained | Falling out side of excavation line |
| 54 | 46 B | Asupalav   | <i>Polyalthia longifolia</i>    | 2  | 18 | To be retained | Falling out side of excavation line |
| 55 | 46 C | Chafa      | <i>Plumeria alba</i>            | 2  | 18 | To be retained | Falling out side of excavation line |
| 56 | 47   | Asupalav   | <i>Polyalthia longifolia</i>    | 2  | 16 | To be retained | Falling out side of excavation line |
| 57 | 47 A | Amba       | <i>Mangifera indica</i>         | 1  | 16 | To be retained | Falling out side of excavation line |
| 58 | 47 B | Asupalav   | <i>Polyalthia longifolia</i>    | 2  | 15 | To be retained | Falling out side of excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |      |            |                                  |   |    |                |                                     |
|----|------|------------|----------------------------------|---|----|----------------|-------------------------------------|
| 59 | 47 C | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 15 | To be retained | Falling out side of excavation line |
| 60 | 48   | Peru       | <i>Psidium guajava</i>           | 2 | 10 | To be retained | Falling out side of excavation line |
| 61 | 48 A | Kadi Patta | <i>Murraya koenigii</i>          | 1 | 10 | To be retained | Falling out side of excavation line |
| 62 | 48 B | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 16 | To be retained | Falling out side of excavation line |
| 63 | 48 C | Naral      | <i>Cocos nucifera</i>            | 4 | 14 | To be retained | Falling out side of excavation line |
| 64 | 49   | Asupalav   | <i>Polyalthia longifolia</i>     | 3 | 14 | To be retained | Falling out side of excavation line |
| 65 | 49 A | Amba       | <i>Mangifera indica</i>          | 1 | 10 | To be retained | Falling out side of excavation line |
| 66 | 49 B | Asupalav   | <i>Polyalthia longifolia</i>     | 4 | 13 | To be retained | Falling out side of excavation line |
| 67 | 49 C | Naral      | <i>Cocos nucifera</i>            | 4 | 28 | To be retained | Falling out side of excavation line |
| 68 | 50   | Amba       | <i>Mangifera indica</i>          | 1 | 10 | To be retained | Falling out side of excavation line |
| 69 | 50 A | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 13 | To be retained | Falling out side of excavation line |
| 70 | 50 B | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 15 | To be retained | Falling out side of excavation line |
| 71 | 50 C | Amba       | <i>Mangifera indica</i>          | 4 | 20 | To be retained | Falling out side of excavation line |
| 72 | 51   | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 18 | To be retained | Falling out side of excavation line |
| 73 | 51 A | Asupalav   | <i>Polyalthia longifolia</i>     | 3 | 18 | To be retained | Falling out side of excavation line |
| 74 | 51 B | Naral      | <i>Cocos nucifera</i>            | 6 | 12 | To be retained | Falling out side of excavation line |
| 75 | 51 C | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 18 | To be retained | Falling out side of excavation line |
| 76 | 52   | Phanas     | <i>Artocarpus heterophyullus</i> | 1 | 7  | To be retained | Falling out side of excavation line |
| 77 | 52 A | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 12 | To be retained | Falling out side of excavation line |
| 78 | 52 B | Asupalav   | <i>Polyalthia longifolia</i>     | 3 | 15 | To be retained | Falling out side of excavation line |
| 79 | 53   | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 15 | To be retained | Falling out side of excavation line |
| 80 | 53 A | Phanas     | <i>Artocarpus heterophyullus</i> | 1 | 15 | To be retained | Falling out side of excavation line |
| 81 | 53 B | Naral      | <i>Cocos nucifera</i>            | 5 | 20 | To be retained | Falling out side of excavation line |
| 82 | 54   | Peru       | <i>Psidium guajava</i>           | 1 | 6  | To be retained | Falling out side of excavation line |
| 83 | 54 A | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 15 | To be retained | Falling out side of excavation line |
| 84 | 54 B | Naral      | <i>Cocos nucifera</i>            | 5 | 50 | To be retained | Falling out side of excavation line |
| 85 | 55   | Asupalav   | <i>Polyalthia longifolia</i>     | 2 | 20 | To be retained | Falling out side of excavation line |
| 86 | 56   | Rain Tree  | <i>Samanea saman</i>             | 3 | 20 | To be removed  | Falling within excavation line      |
| 87 | 57   | Royal palm | <i>Roystonea regia</i>           | 1 | 10 | To be removed  | Falling within excavation line      |
| 88 | 58   | Royal palm | <i>Roystonea regia</i>           | 2 | 16 | To be removed  | Falling within excavation line      |
| 89 | 59   | Royal palm | <i>Roystonea regia</i>           | 4 | 30 | To be removed  | Falling within excavation line      |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                  |                                |   |    |                |                                     |
|-----|------|------------------|--------------------------------|---|----|----------------|-------------------------------------|
| 90  | 60   | Areca palm       | <i>Dypsis lutescens</i>        | 1 | 15 | To be removed  | Falling within excavation line      |
| 91  | 61   | Royal palm       | <i>Roystonea regia</i>         | 4 | 33 | To be removed  | Falling within excavation line      |
| 92  | 62   | Royal palm       | <i>Roystonea regia</i>         | 4 | 43 | To be retained | Falling out side of excavation line |
| 93  | 63   | Royal palm       | <i>Roystonea regia</i>         | 4 | 33 | To be retained | Falling out side of excavation line |
| 94  | 64   | Royal palm       | <i>Roystonea regia</i>         | 3 | 20 | To be retained | Falling out side of excavation line |
| 95  | 65   | Naral            | <i>Cocos nucifera</i>          | 2 | 25 | To be removed  | Falling within excavation line      |
| 96  | 66   | Naral            | <i>Cocos nucifera</i>          | 3 | 36 | To be removed  | Falling within excavation line      |
| 97  | 67   | Desi badam       | <i>Terminalia catappa</i>      | 4 | 36 | To be removed  | Falling within excavation line      |
| 98  | 68   | Naral            | <i>Cocos nucifera</i>          | 4 | 25 | To be removed  | Falling within excavation line      |
| 99  | 69   | Pimpal           | <i>Ficus religiosa</i>         | 3 | 20 | To be removed  | Falling within excavation line      |
| 100 | 70   | Pimpal           | <i>Ficus religiosa</i>         | 3 | 36 | To be removed  | Falling within excavation line      |
| 101 | 71   | Asupalav         | <i>Polyalthia longifolia</i>   | 1 | 20 | To be removed  | Falling within excavation line      |
| 102 | 72   | Naral            | <i>Cocos nucifera</i>          | 2 | 30 | To be removed  | Falling within excavation line      |
| 103 | 73   | Pimpal           | <i>Ficus religiosa</i>         | 7 | 25 | To be removed  | Falling within excavation line      |
| 104 | 74   | Karanj           | <i>Pongamia pinnata</i>        | 2 | 12 | To be removed  | Falling within excavation line      |
| 105 | 75   | Naral            | <i>Cocos nucifera</i>          | 2 | 7  | To be removed  | Falling within excavation line      |
| 106 | 76   | Amba             | <i>Mangifera indica</i>        | 2 | 26 | To be removed  | Falling within excavation line      |
| 107 | 77   | Desi badam       | <i>Terminalia catappa</i>      | 2 | 26 | To be retained | Falling out side of excavation line |
| 108 | 78   | Naral            | <i>Cocos nucifera</i>          | 2 | 26 | To be retained | Falling out side of excavation line |
| 109 | 79   | Naral            | <i>Cocos nucifera</i>          | 2 | 30 | To be retained | Falling out side of excavation line |
| 110 | 80   | Supari           | <i>Areca catechu</i>           | 1 | 23 | To be retained | Falling out side of excavation line |
| 111 | 81   | Rain Tree        | <i>Samanea saman</i>           | 7 | 30 | To be removed  | Falling within excavation line      |
| 112 | 82   | Rain Tree        | <i>Samanea saman</i>           | 4 | 30 | To be removed  | Falling within excavation line      |
| 113 | 83   | Rain Tree        | <i>Samanea saman</i>           | 4 | 30 | To be removed  | Falling within excavation line      |
| 114 | 84   | Rain Tree        | <i>Samanea saman</i>           | 6 | 30 | To be removed  | Falling within excavation line      |
| 115 | 85   | Rain Tree        | <i>Samanea saman</i>           | 6 | 30 | To be removed  | Falling within excavation line      |
| 116 | 86   | Pimpal           | <i>Ficus religiosa</i>         | 7 | 30 | To be removed  | Falling within excavation line      |
| 117 | 87   | Rain Tree        | <i>Samanea saman</i>           | 6 | 25 | To be removed  | Falling within excavation line      |
| 118 | 88   | Rain Tree (Dead) | <i>Samanea saman</i>           | 6 | 30 | To be removed  | Falling within excavation line      |
| 119 | 89   | Sonmohar         | <i>Peltophorum pterocarpum</i> | 1 | 25 | To be removed  | Falling within excavation line      |
| 120 | 89 A | Rain Tree        | <i>Samanea saman</i>           | 1 | 20 | To be removed  | Falling within excavation line      |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                  |                              |    |    |               |                                |
|-----|------|------------------|------------------------------|----|----|---------------|--------------------------------|
| 121 | 89 B | Rain Tree        | <i>Samanea saman</i>         | 1  | 20 | To be removed | Falling within excavation line |
| 122 | 90   | Rain Tree        | <i>Samanea saman</i>         | 1  | 20 | To be removed | Falling within excavation line |
| 123 | 91   | Rain Tree        | <i>Samanea saman</i>         | 2  | 20 | To be removed | Falling within excavation line |
| 124 | 92   | Rain Tree (Dead) | <i>Samanea saman</i>         | 6  | 30 | To be removed | Falling within excavation line |
| 125 | 93   | Foxtail palm     | <i>Wodyetia bifurcata</i>    | 1  | 20 | To be removed | Falling within excavation line |
| 126 | 94   | Foxtail palm     | <i>Wodyetia bifurcata</i>    | 1  | 18 | To be removed | Falling within excavation line |
| 127 | 95   | Foxtail palm     | <i>Wodyetia bifurcata</i>    | 1  | 15 | To be removed | Falling within excavation line |
| 128 | 96   | Vilayti Chinch   | <i>Pithecellobium dulce</i>  | 3  | 20 | To be removed | Falling within excavation line |
| 129 | 97   | Pimpal           | <i>Ficus religiosa</i>       | 8  | 34 | To be removed | Falling within excavation line |
| 130 | 98   | Rain tree        | <i>Samanea saman</i>         | 7  | 30 | To be removed | Falling within excavation line |
| 131 | 99   | Asupalav         | <i>Polyalthia longifolia</i> | 3  | 30 | To be removed | Falling within excavation line |
| 132 | 100  | Asupalav         | <i>Polyalthia longifolia</i> | 3  | 30 | To be removed | Falling within excavation line |
| 133 | 101  | Rain tree        | <i>Samanea saman</i>         | 10 | 35 | To be removed | Falling within excavation line |
| 134 | 102  | Putranjiva       | <i>Putranjiva roxburghii</i> | 8  | 36 | To be removed | Falling within excavation line |
| 135 | 103  | Asupalav         | <i>Polyalthia longifolia</i> | 2  | 25 | To be removed | Falling within excavation line |
| 136 | 104  | Gulmohar         | <i>Delonix regia</i>         | 3  | 24 | To be removed | Falling within excavation line |
| 137 | 105  | Rain tree        | <i>Samanea saman</i>         | 1  | 14 | To be removed | Falling within excavation line |
| 138 | 106  | Kashid           | <i>Cassia siamea</i>         | 3  | 25 | To be removed | Falling within excavation line |
| 139 | 107  | Pimpal           | <i>Ficus religiosa</i>       | 6  | 30 | To be removed | Falling within excavation line |
| 140 | 108  | Gulmohar         | <i>Delonix regia</i>         | 8  | 40 | To be removed | Falling within excavation line |
| 141 | 109  | Pimpal           | <i>Ficus religiosa</i>       | 10 | 36 | To be removed | Falling within excavation line |
| 142 | 110  | Pimpal           | <i>Ficus religiosa</i>       | 6  | 30 | To be removed | Falling within excavation line |
| 143 | 111  | Dhaman           | <i>Grewia tiliaefolia</i>    | 2  | 24 | To be removed | Falling within excavation line |
| 144 | 112  | Vilayti Chinch   | <i>Pithecellobium dulce</i>  | 2  | 25 | To be removed | Falling within excavation line |
| 145 | 113  | Rain tree        | <i>Samanea saman</i>         | 1  | 20 | To be removed | Falling within excavation line |
| 146 | 114  | Bor              | <i>Ziziphus mauritiana</i>   | 3  | 25 | To be removed | Falling within excavation line |
| 147 | 115  | Vilayti Chinch   | <i>Pithecellobium dulce</i>  | 6  | 30 | To be removed | Falling within excavation line |
| 148 | 116  | Pimpal           | <i>Ficus religiosa</i>       | 10 | 40 | To be removed | Falling within excavation line |
| 149 | 117  | Bor              | <i>Ziziphus mauritiana</i>   | 5  | 28 | To be removed | Falling within excavation line |
| 150 | 118  | Pimpal           | <i>Ficus religiosa</i>       | 9  | 45 | To be removed | Falling within excavation line |
| 151 | 119  | Chinch           | <i>Tamarindus indica</i>     | 2  | 20 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                |                             |   |    |               |                                |
|-----|------|----------------|-----------------------------|---|----|---------------|--------------------------------|
| 152 | 120  | Bor            | <i>Ziziphus mauritiana</i>  | 2 | 20 | To be removed | Falling within excavation line |
| 153 | 121  | Vilayti Chinch | <i>Pithecellobium dulce</i> | 6 | 20 | To be removed | Falling within excavation line |
| 154 | 122  | Karanj         | <i>Pongamia pinnata</i>     | 6 | 30 | To be removed | Falling within excavation line |
| 155 | 123  | Date palm      | <i>Phoenix sylvestris</i>   | 2 | 10 | To be removed | Falling within excavation line |
| 156 | 124  | Bor            | <i>Ziziphus mauritiana</i>  | 4 | 20 | To be removed | Falling within excavation line |
| 157 | 125  | Bor            | <i>Ziziphus mauritiana</i>  | 2 | 15 | To be removed | Falling within excavation line |
| 158 | 126  | Bor            | <i>Ziziphus mauritiana</i>  | 2 | 25 | To be removed | Falling within excavation line |
| 159 | 127  | Vilayti Chinch | <i>Pithecellobium dulce</i> | 4 | 25 | To be removed | Falling within excavation line |
| 160 | 128  | Bhokar         | <i>Cordia dichotoma</i>     | 2 | 15 | To be removed | Falling within excavation line |
| 161 | 129  | Bor            | <i>Ziziphus mauritiana</i>  | 5 | 28 | To be removed | Falling within excavation line |
| 162 | 130  | Bor            | <i>Ziziphus mauritiana</i>  | 1 | 15 | To be removed | Falling within excavation line |
| 163 | 131  | Babool         | <i>Acacia nilotica</i>      | 2 | 22 | To be removed | Falling within excavation line |
| 164 | 131A | Rain tree      | <i>Samanea saman</i>        | 9 | 20 | To be removed | Falling within excavation line |
| 165 | 132  | Bor            | <i>Ziziphus mauritiana</i>  | 2 | 22 | To be removed | Falling within excavation line |
| 166 | 133  | Rain tree      | <i>Samanea saman</i>        | 3 | 25 | To be removed | Falling within excavation line |
| 167 | 134  | Bhokar         | <i>Cordia dichotoma</i>     | 4 | 25 | To be removed | Falling within excavation line |
| 168 | 135  | Bor            | <i>Ziziphus mauritiana</i>  | 2 | 18 | To be removed | Falling within excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 61         |
| Trees to be removed  | 107        |
| <b>Total Trees</b>   | <b>168</b> |

| Summary of Tree Survey at Vidyanagari Station |          |               |                                |                     |                      |                     |                                |
|---|----------|---------------|--------------------------------|---------------------|----------------------|---------------------|--------------------------------|
| Sr. no.                                       | Tree no. | Common Name   | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                         |
| 1   | 1        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 4                   | 30                   | To be removed       | Falling within excavation line |
| 2   | 2        | Mango         | <i>Mangifera indica</i>        | 2                   | 18                   | To be removed       | Falling within excavation line |
| 3   | 3        | Shewga        | <i>Moringa oleifera</i>        | 2                   | 18                   | To be removed       | Falling within excavation line |
| 4   | 4        | Rain Tree     | <i>Samanea saman</i>           | 2                   | 15                   | To be removed       | Falling within excavation line |
| 5   | 5        | Rain Tree     | <i>Samanea saman</i>           | 6                   | 30                   | To be removed       | Falling within excavation line |
| 6   | 6        | Rain Tree     | <i>Samanea saman</i>           | 2                   | 22                   | To be removed       | Falling within excavation line |
| 7   | 7        | Subabhul      | <i>Leucaena leucocephala</i>   | 3                   | 20                   | To be removed       | Falling within excavation line |
| 8   | 8        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 3                   | 25                   | To be removed       | Falling within excavation line |
| 9   | 9        | Sonmohar      | <i>Peltophorum pterocarpum</i> | 2                   | 22                   | To be removed       | Falling within excavation line |
| 10  | 10       | Gulmohar      | <i>Delonix regia</i>           | 4                   | 20                   | To be removed       | Falling within excavation line |
| 11  | 11       | Pimpal        | <i>Ficus religiosa</i>         | 6"                  | 8                    | To be removed       | Falling within excavation line |
| 12  | 12       | Naral         | <i>Cocos nucifera</i>          | 4                   | 25                   | To be removed       | Falling within excavation line |
| 13  | 13       | Naral         | <i>Cocos nucifera</i>          | 4                   | 25                   | To be removed       | Falling within excavation line |
| 14  | 14       | Naral         | <i>Cocos nucifera</i>          | 4                   | 25                   | To be removed       | Falling within excavation line |
| 15  | 15       | Naral         | <i>Cocos nucifera</i>          | 3                   | 12                   | To be removed       | Falling within excavation line |
| 16  | 16       | Naral         | <i>Cocos nucifera</i>          | 4                   | 12                   | To be removed       | Falling within excavation line |
| 17  | 17       | Naral         | <i>Cocos nucifera</i>          | 4                   | 20                   | To be removed       | Falling within excavation line |
| 18  | 18       | Supari (Dead) | <i>Areca Catechu</i>           | 2                   | 25                   | To be removed       | Falling within excavation line |
| 19  | 19       | Naral         | <i>Cocos nucifera</i>          | 4                   | 25                   | To be removed       | Falling within excavation line |
| 20  | 20       | Naral         | <i>Cocos nucifera</i>          | 4                   | 30                   | To be removed       | Falling within excavation line |
| 21  | 21       | Naral         | <i>Cocos nucifera</i>          | 4                   | 30                   | To be removed       | Falling within excavation line |
| 22  | 22       | Sonmohar      | <i>Peltophorum pterocarpum</i> | 2                   | 18                   | To be removed       | Falling within excavation line |
| 23  | 23       | Naral         | <i>Cocos nucifera</i>          | 3                   | 28                   | To be removed       | Falling within excavation line |
| 24  | 24       | Naral         | <i>Cocos nucifera</i>          | 3                   | 28                   | To be removed       | Falling within excavation line |
| 25  | 25       | Naral         | <i>Cocos nucifera</i>          | 3                   | 28                   | To be removed       | Falling within excavation line |
| 26  | 26       | Naral         | <i>Cocos nucifera</i>          | 4                   | 22                   | To be removed       | Falling within excavation line |
| 27  | 27       | Naral         | <i>Cocos nucifera</i>          | 3                   | 20                   | To be removed       | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |          |                           |     |    |                |                                 |
|----|-----|----------|---------------------------|-----|----|----------------|---------------------------------|
| 28 | 28  | Naral    | <i>Cocos nucifera</i>     | 2.5 | 20 | To be removed  | Falling within excavation line  |
| 29 | 29  | Naral    | <i>Cocos nucifera</i>     | 3   | 20 | To be removed  | Falling within excavation line  |
| 30 | 30  | Naral    | <i>Cocos nucifera</i>     | 4   | 25 | To be removed  | Falling within excavation line  |
| 31 | 31  | Naral    | <i>Cocos nucifera</i>     | 5   | 25 | To be removed  | Falling within excavation line  |
| 32 | 32  | Naral    | <i>Cocos nucifera</i>     | 3   | 15 | To be removed  | Falling within excavation line  |
| 33 | 33  | Naral    | <i>Cocos nucifera</i>     | 4   | 25 | To be removed  | Falling within excavation line  |
| 34 | 34  | Naral    | <i>Cocos nucifera</i>     | 3   | 20 | To be removed  | Falling within excavation line  |
| 35 | 35  | Naral    | <i>Cocos nucifera</i>     | 5   | 25 | To be removed  | Falling within excavation line  |
| 36 | 36  | Naral    | <i>Cocos nucifera</i>     | 2   | 15 | To be removed  | Falling within excavation line  |
| 37 | 37  | Naral    | <i>Cocos nucifera</i>     | 3   | 15 | To be removed  | Falling within excavation line  |
| 38 | 38  | Naral    | <i>Cocos nucifera</i>     | 4   | 15 | To be removed  | Falling within excavation line  |
| 39 | 39  | Naral    | <i>Cocos nucifera</i>     | 4   | 25 | To be removed  | Falling within excavation line  |
| 40 | 40  | Naral    | <i>Cocos nucifera</i>     | 3   | 20 | To be removed  | Falling within excavation line  |
| 41 | 41  | Naral    | <i>Cocos nucifera</i>     | 3   | 15 | To be removed  | Falling within excavation line  |
| 42 | 42  | Naral    | <i>Cocos nucifera</i>     | 3   | 18 | To be removed  | Falling within excavation line  |
| 43 | 42A | Pimpal   | <i>Ficus religiosa</i>    | 5   | 43 | To be retained | Falling outside excavation line |
| 44 | 43  | Naral    | <i>Cocos nucifera</i>     | 3   | 20 | To be removed  | Falling within excavation line  |
| 45 | 44  | Naral    | <i>Cocos nucifera</i>     | 5   | 25 | To be removed  | Falling within excavation line  |
| 46 | 45  | Naral    | <i>Cocos nucifera</i>     | 5   | 25 | To be removed  | Falling within excavation line  |
| 47 | 46  | Naral    | <i>Cocos nucifera</i>     | 4   | 20 | To be removed  | Falling within excavation line  |
| 48 | 47  | Naral    | <i>Cocos nucifera</i>     | 3   | 20 | To be removed  | Falling within excavation line  |
| 49 | 48  | Naral    | <i>Cocos nucifera</i>     | 5   | 25 | To be removed  | Falling within excavation line  |
| 50 | 49  | Pimpal   | <i>Ficus religiosa</i>    | 3   | 20 | To be removed  | Falling within excavation line  |
| 51 | 50  | Wad      | <i>Ficus benghalensis</i> | 8   | 20 | To be removed  | Falling within excavation line  |
| 52 | 51  | Wad      | <i>Ficus benghalensis</i> | 3   | 15 | To be removed  | Falling within excavation line  |
| 53 | 52  | Naral    | <i>Cocos nucifera</i>     | 5   | 20 | To be removed  | Falling within excavation line  |
| 54 | 53  | Badam    | <i>Terminala catappa</i>  | 3   | 22 | To be removed  | Falling within excavation line  |
| 55 | 54  | Peru     | <i>Psidium gujava</i>     | 1   | 18 | To be removed  | Falling within excavation line  |
| 56 | 55  | Mango    | <i>Mangifera indica</i>   | 6"  | 10 | To be removed  | Falling within excavation line  |
| 57 | 56  | Gulmohar | <i>Delonix regia</i>      | 4   | 22 | To be removed  | Falling within excavation line  |
| 58 | 57  | Badam    | <i>Terminala catappa</i>  | 2   | 22 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |      |                   |                                |    |    |               |                                |
|----|------|-------------------|--------------------------------|----|----|---------------|--------------------------------|
| 59 | 58   | Badam             | <i>Terminala catappa</i>       | 1  | 20 | To be removed | Falling within excavation line |
| 60 | 59   | Neem              | <i>Azadirachta indica</i>      | 2  | 10 | To be removed | Falling within excavation line |
| 61 | 60   | Wad               | <i>Ficus benghalensis</i>      | 4  | 22 | To be removed | Falling within excavation line |
| 62 | 60 A | Wad               | <i>Ficus benghalensis</i>      | 3  | 30 | To be removed | Falling within excavation line |
| 63 | 61   | Wad               | <i>Ficus benghalensis</i>      | 5  | 22 | To be removed | Falling within excavation line |
| 64 | 62   | Pimpal            | <i>Ficus religiosa</i>         | 12 | 25 | To be removed | Falling within excavation line |
| 65 | 63   | Mango             | <i>Mangifera Indica</i>        | 1  | 12 | To be removed | Falling within excavation line |
| 66 | 64   | Naral             | <i>Cocos nucifera</i>          | 6  | 25 | To be removed | Falling within excavation line |
| 67 | 65   | Umber             | <i>Ficus racemosa</i>          | 5  | 25 | To be removed | Falling within excavation line |
| 68 | 66   | Naral             | <i>Cocos nucifera</i>          | 4  | 20 | To be removed | Falling within excavation line |
| 69 | 67   | Naral             | <i>Cocos nucifera</i>          | 6  | 20 | To be removed | Falling within excavation line |
| 70 | 68   | Naral             | <i>Cocos nucifera</i>          | 6  | 25 | To be removed | Falling within excavation line |
| 71 | 69   | Sonmohar          | <i>Peltophorum pterocarpum</i> | 2  | 20 | To be removed | Falling within excavation line |
| 72 | 69A  | Naral             | <i>Cocos nucifera</i>          | 3  | 36 | To be removed | Falling within excavation line |
| 73 | 69B  | Amba              | <i>Mangifera indica</i>        | 2  | 25 | To be removed | Falling within excavation line |
| 74 | 69C  | Chapha            | <i>Plumeria alba</i>           | 1  | 13 | To be removed | Falling within excavation line |
| 75 | 69D  | Naral             | <i>Cocos nucifera</i>          | 3  | 26 | To be removed | Falling within excavation line |
| 76 | 69E  | Saptaparni        | <i>Alstonia scholaris</i>      | 2  | 23 | To be removed | Falling within excavation line |
| 77 | 69F  | Saptaparni (Dead) | <i>Alstonia scholaris</i>      | 2  | 23 | To be removed | Falling within excavation line |
| 78 | 70   | Sonmohar          | <i>Peltophorum pterocarpum</i> | 4  | 25 | To be removed | Falling within excavation line |
| 79 | 71   | Rain Tree         | <i>Samanea saman</i>           | 5  | 25 | To be removed | Falling within excavation line |
| 80 | 72   | Gulmohar          | <i>Delonix regia</i>           | 6  | 25 | To be removed | Falling within excavation line |
| 81 | 73   | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3  | 18 | To be removed | Falling within excavation line |
| 82 | 74   | Sonmohar          | <i>Peltophorum pterocarpum</i> | 2  | 20 | To be removed | Falling within excavation line |
| 83 | 75   | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3  | 22 | To be removed | Falling within excavation line |
| 84 | 76   | Sonmohar          | <i>Peltophorum pterocarpum</i> | 4  | 22 | To be removed | Falling within excavation line |
| 85 | 77   | Rain Tree         | <i>Samanea saman</i>           | 3  | 20 | To be removed | Falling within excavation line |
| 86 | 78   | Rain Tree         | <i>Samanea saman</i>           | 5  | 28 | To be removed | Falling within excavation line |
| 87 | 79   | Rain Tree         | <i>Samanea saman</i>           | 4  | 35 | To be removed | Falling within excavation line |
| 88 | 80   | Rain Tree         | <i>Samanea saman</i>           | 4  | 25 | To be removed | Falling within excavation line |
| 89 | 81   | Rain Tree         | <i>Samanea saman</i>           | 7  | 30 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                                |    |    |                |                                 |
|-----|-----|------------|--------------------------------|----|----|----------------|---------------------------------|
| 90  | 82  | Guimohar   | <i>Delonix regia</i>           | 7  | 25 | To be removed  | Falling within excavation line  |
| 91  | 82A | Rain tree  | <i>Samanea saman</i>           | 3  | 13 | To be removed  | Falling within excavation line  |
| 92  | 82B | Shewga     | <i>Moringa oleifera</i>        | 3  | 30 | To be removed  | Falling within excavation line  |
| 93  | 82C | Peru       | <i>Psidium guajava</i>         | 4" | 10 | To be removed  | Falling within excavation line  |
| 94  | 82D | Suru       | <i>Casuarina equisetifolia</i> | 8" | 6  | To be removed  | Falling within excavation line  |
| 95  | 82E | Pimpal     | <i>Ficus religiosa</i>         | 1  | 20 | To be retained | Falling outside excavation line |
| 96  | 82F | Subabhul   | <i>polyalthia longifolia</i>   | 1  | 20 | To be retained | Falling outside excavation line |
| 97  | 83  | Rain Tree  | <i>Samanea saman</i>           | 3  | 20 | To be removed  | Falling within excavation line  |
| 98  | 84  | Rain Tree  | <i>Samanea saman</i>           | 3  | 20 | To be removed  | Falling within excavation line  |
| 99  | 84A | Amba       | <i>Mangifera indica</i>        | 1  | 6  | To be removed  | Falling within excavation line  |
| 100 | 85  | Rain Tree  | <i>Samanea saman</i>           | 3  | 20 | To be removed  | Falling within excavation line  |
| 101 | 86  | Rain tree  | <i>Samanea saman</i>           | 5  | 21 | To be removed  | Falling within excavation line  |
| 102 | 87  | Rain tree  | <i>Samanea saman</i>           | 4  | 20 | To be removed  | Falling within excavation line  |
| 103 | 88  | Pimpal     | <i>Spathodea campanulata</i>   | 3  | 33 | To be removed  | Falling within excavation line  |
| 104 | 89  | Pichkari   | <i>Spathodea campanulata</i>   | 2  | 39 | To be removed  | Falling within excavation line  |
| 105 | 90  | Pichkari   | <i>Spathodea campanulata</i>   | 1  | 16 | To be removed  | Falling within excavation line  |
| 106 | 91  | Jambhul    | <i>Syzygium cumini</i>         | 2  | 30 | To be removed  | Falling within excavation line  |
| 107 | 92  | Jambhul    | <i>Syzygium cumini</i>         | 3  | 36 | To be removed  | Falling within excavation line  |
| 108 | 93  | Shewga     | <i>Moringa oleifera</i>        | 2  | 28 | To be removed  | Falling within excavation line  |
| 109 | 94  | Kaduneem   | <i>Azadirachta indica</i>      | 2  | 30 | To be removed  | Falling within excavation line  |
| 110 | 95  | Desi badam | <i>Terminalia catappa</i>      | 3  | 31 | To be removed  | Falling within excavation line  |
| 111 | 96  | Pimpal     | <i>Ficus religiosa</i>         | 3  | 39 | To be removed  | Falling within excavation line  |
| 112 | 97  | Wad        | <i>Ficus benghalensis</i>      | 4  | 43 | To be removed  | Falling within excavation line  |
| 113 | 98  | Asupalav   | <i>Polyalthia lingifolia</i>   | 3  | 36 | To be removed  | Falling within excavation line  |
| 114 | 99  | Sonmohar   | <i>Peltophorum pterocarpum</i> | 2  | 26 | To be retained | Falling outside excavation line |
| 115 | 100 | Kala umber | <i>Ficus hispida</i>           | 2  | 23 | To be removed  | Falling within excavation line  |
| 116 | 101 | Kala umber | <i>Ficus hispida</i>           | 2  | 23 | To be removed  | Falling within excavation line  |
| 117 | 102 | Kala umber | <i>Ficus hispida</i>           | 1  | 20 | To be removed  | Falling within excavation line  |
| 118 | 103 | Kala umber | <i>Ficus hispida</i>           | 2  | 23 | To be removed  | Falling within excavation line  |
| 119 | 104 | Pimpal     | <i>Ficus religiosa</i>         | 7  | 46 | To be removed  | Falling within excavation line  |
| 120 | 105 | Asupalav   | <i>Polyalthia lingifolia</i>   | 3  | 26 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                      |   |    |                |                                 |
|-----|-----|------------|----------------------|---|----|----------------|---------------------------------|
| 121 | 106 | Kala umber | <i>Ficus hispida</i> | 3 | 23 | To be retained | Falling outside excavation line |
| 122 | 107 | Kala umber | <i>Ficus hispida</i> | 3 | 23 | To be retained | Falling outside excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 6          |
| Trees to be removed  | 116        |
| <b>Total Trees</b>   | <b>122</b> |

| Summary of Tree Survey at Santacruz Station |          |             |                           |                     |                      |                     |                                 |
|---|----------|-------------|---------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.                                     | Tree no. | Common Name | Botanical Name            | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1   | 2        | Gulmohar    | <i>Delonix regia</i>      | 6                   | 30                   | To be retained      | Falling outside excavation line |
| 2   | 4        | Naral       | <i>Cocos nucifera</i>     | 4                   | 30                   | To be retained      | Falling outside excavation line |
| 3   | 5        | Naral       | <i>Cocos nucifera</i>     | 3                   | 30                   | To be retained      | Falling outside excavation line |
| 4   | 6        | Desi badam  | <i>Terminalia catappa</i> | 8"                  | 10                   | To be removed       | Falling within excavation line  |
| 5   | 7        | Wad         | <i>Ficus benghalensis</i> | 8"                  | 10                   | To be removed       | Falling within excavation line  |
| 6   | 8        | Kaduneem    | <i>Azadirachta indica</i> | 8"                  | 11                   | To be removed       | Falling within excavation line  |
| 7   | 9        | Desi badam  | <i>Terminalia catappa</i> | 8"                  | 13                   | To be removed       | Falling within excavation line  |
| 8   | 10       | Desi badam  | <i>Terminalia catappa</i> | 8"                  | 10                   | To be removed       | Falling within excavation line  |
| 9   | 11       | Desi badam  | <i>Terminalia catappa</i> | 8"                  | 10                   | To be removed       | Falling within excavation line  |
| 10  | 12       | Desi badam  | <i>Terminalia catappa</i> | 8"                  | 20                   | To be removed       | Falling within excavation line  |
| 11  | 12A      | Naral       | <i>Cocos nucifera</i>     | 4"                  | 5                    | To be removed       | Falling within excavation line  |
| 12  | 13       | Desi badam  | <i>Terminalia catappa</i> | 1                   | 16                   | To be removed       | Falling within excavation line  |
| 13  | 14       | Desi badam  | <i>Terminalia catappa</i> | 2                   | 30                   | To be removed       | Falling within excavation line  |
| 14  | 15       | Desi badam  | <i>Terminalia catappa</i> | 2                   | 20                   | To be removed       | Falling within excavation line  |
| 15  | 16       | Desi badam  | <i>Terminalia catappa</i> | 2                   | 26                   | To be removed       | Falling within excavation line  |
| 16  | 17       | Desi badam  | <i>Terminalia catappa</i> | 2                   | 30                   | To be removed       | Falling within excavation line  |
| 17  | 18       | Naral       | <i>Cocos nucifera</i>     | 2                   | 13                   | To be removed       | Falling within excavation line  |
| 18  | 19       | Shewga      | <i>Moringa oliefera</i>   | 1                   | 30                   | To be removed       | Falling within excavation line  |
| 19  | 19A      | Neem        | <i>Azadirachta indica</i> | 4"                  | 10                   | To be removed       | Falling within excavation line  |
| 20  | 19B      | Neem        | <i>Azadirachta indica</i> | 4"                  | 5                    | To be removed       | Falling within excavation line  |
| 21  | 20       | Desi badam  | <i>Terminalia catappa</i> | 1                   | 10                   | To be removed       | Falling within excavation line  |
| 22  | 21       | Desi badam  | <i>Terminalia catappa</i> | 2                   | 8                    | To be removed       | Falling within excavation line  |
| 23  | 22       | Desi badam  | <i>Terminalia catappa</i> | 1                   | 23                   | To be removed       | Falling within excavation line  |
| 24  | 23       | Desi badam  | <i>Terminalia catappa</i> | 8"                  | 8                    | To be removed       | Falling within excavation line  |
| 25  | 24       | Wad         | <i>Ficus benghalensis</i> | 5                   | 36                   | To be removed       | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                |                                |    |    |                |                                 |
|----|-----|----------------|--------------------------------|----|----|----------------|---------------------------------|
| 26 | 25  | Wad            | <i>Ficus benghalensis</i>      | 3  | 33 | To be removed  | Falling within excavation line  |
| 27 | 26  | Desi badam     | <i>Terminalia catappa</i>      | 8" | 6  | To be removed  | Falling within excavation line  |
| 28 | 26A | Vilayti chinch | <i>Pithecellobium dulce</i>    | 5" | 5  | To be removed  | Falling within excavation line  |
| 29 | 27  | Jungli badam   | <i>Sterculia foetida</i>       | 4  | 39 | To be removed  | Falling within excavation line  |
| 30 | 28  | Pimpal         | <i>Ficus religiosa</i>         | 8" | 10 | To be removed  | Falling within excavation line  |
| 31 | 29  | Rain tree      | <i>Samanea saman</i>           | 2  | 20 | To be removed  | Falling within excavation line  |
| 32 | 29A | Pimpal         | <i>Ficus religiosa</i>         | 4" | 5  | To be removed  | Falling within excavation line  |
| 33 | 29B | Pimpal         | <i>Ficus religiosa</i>         | 4" | 6  | To be removed  | Falling within excavation line  |
| 34 | 29C | Naral          | <i>Cocos nucifera</i>          | 8" | 6  | To be removed  | Falling within excavation line  |
| 35 | 29D | Karanj         | <i>Pongamia pinnata</i>        | 4" | 8  | To be removed  | Falling within excavation line  |
| 36 | 30  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 2  | 20 | To be retained | Falling outside excavation line |
| 37 | 31  | Pichkari       | <i>Spathodea campanulata</i>   | 2  | 23 | To be removed  | Falling within excavation line  |
| 38 | 32  | Pichkari       | <i>Spathodea campanulata</i>   | 2  | 30 | To be removed  | Falling within excavation line  |
| 39 | 33  | Bhend          | <i>Thespesia populnea</i>      | 1  | 16 | To be removed  | Falling within excavation line  |

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 4         |
| Trees to be removed  | 35        |
| <b>Total Trees</b>   | <b>39</b> |



| Summary of Tree Survey at BKC Steel Yard |          |              |                                |                     |                      |                     |                                 |
|--|----------|--------------|--------------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.                                  | Tree no. | Common Name  | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1  | 1        | Bhendi       | <i>Thespesia populnea</i>      | 7'                  | 30'                  | To be retained      | Falling outside excavation line |
| 2  | 2        | Peltophoram  | <i>Peltophorum pterocarpum</i> | 5.2'                | 20'                  | To be retained      | Falling outside excavation line |
| 3  | 3        | Sausage Tree | <i>Kigelia Pinnata</i>         | 2.1'                | 18'                  | To be retained      | Falling outside excavation line |
| 4  | 4        | Peltophorum  | <i>Peltophorum pterocarpum</i> | 3.7'                | 20'                  | To be retained      | Falling outside excavation line |
| 5  | 5        | Peltophorum  | <i>Peltophorum pterocarpum</i> | 3'                  | 22'                  | To be removed       | Falling within excavation line  |
| 6  | 6        | Peltophorum  | <i>Peltophorum pterocarpum</i> | 2.8'                | 20'                  | To be removed       | Falling within excavation line  |
| 7  | 7        | Peltophorum  | <i>Peltophorum pterocarpum</i> | 2.7'                | 20'                  | To be removed       | Falling within excavation line  |
| 8  | 8        | Gulmohar     | <i>Delonix regia</i>           | 3'                  | 22'                  | To be removed       | Falling within excavation line  |
| 9  | 9        | Gulmohar     | <i>Delonix regia</i>           | 3'                  | 20'                  | To be retained      | Falling outside excavation line |
| 10                                       | 10       | Gulmohar     | <i>Delonix regia</i>           | 3.3'                | 20'                  | To be retained      | Falling outside excavation line |
| 11                                       | 11       | Gulmohar     | <i>Delonix regia</i>           | 3'                  | 18'                  | To be retained      | Falling outside excavation line |
| 12                                       | 12       | Peltophorum  | <i>Peltophorum pterocarpum</i> | 2'                  | 15'                  | To be retained      | Falling outside excavation line |
| 13                                       | 13       | subabul      | <i>Laucaena leucocephala</i>   | 1'                  | 16'                  | To be retained      | Falling outside excavation line |
| 14                                       | 14       | Peltophorum  | <i>Peltophorum pterocarpum</i> | 3.8'                | 12'                  | To be removed       | Falling within excavation line  |
| 15                                       | 15       | Peltophorum  | <i>Peltophorum pterocarpum</i> | 4.3'                | 12'                  | To be retained      | Falling outside excavation line |
| 16                                       | 16       | Peltophorum  | <i>Peltophorum pterocarpum</i> | 5.2'                | 15'                  | To be removed       | Falling within excavation line  |
| 17                                       | 17       | subabul      | <i>Laucaena leucocephala</i>   | 2.8'                | 20'                  | To be removed       | Falling within excavation line  |
| 18                                       | 18       | subabul      | <i>Laucaena leucocephala</i>   | 1.2'                | 15'                  | To be removed       | Falling within excavation line  |
| 19                                       | 19       | Coconut      | <i>Cocos nicifera</i>          | 2.2'                | 20'                  | To be retained      | Falling outside excavation line |
| 20                                       | 20       | Subabul      | <i>Laucaena leucocephala</i>   | 2'                  | 15'                  | To be removed       | Falling within excavation line  |
| 21                                       | 21       | Pimpal       | <i>Ficus religiosa</i>         | 1.5'                | 12'                  | To be retained      | Falling outside excavation line |
| 22                                       | 22       | Peltophorum  | <i>Peltophorum pterocarpum</i> | 3.5'                | 15'                  | To be retained      | Falling outside excavation line |
| 23                                       | 23       | subabul      | <i>Laucaena leucocephala</i>   | 1.9'                | 12'                  | To be removed       | Falling within excavation line  |
| 24                                       | 24       | subabul      | <i>Laucaena leucocephala</i>   | 2.4'                | 15'                  | To be removed       | Falling within excavation line  |
| 25                                       | 25       | subabul      | <i>Laucaena leucocephala</i>   | 3'                  | 20'                  | To be removed       | Falling within excavation line  |
| 26                                       | 25A      | subabul      | <i>Laucaena leucocephala</i>   | 3'                  | 20'                  | To be retained      | Falling outside excavation line |
| 27                                       | 25B      | subabul      | <i>Laucaena leucocephala</i>   | 2.6'                | 15'                  | To be retained      | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                 |                                |      |     |                |                                 |
|----|-----|-----------------|--------------------------------|------|-----|----------------|---------------------------------|
| 28 | 25C | subabul         | <i>Laucaena leucocephala</i>   | 3'   | 15' | To be retained | Falling outside excavation line |
| 29 | 25D | subabul         | <i>Laucaena leucocephala</i>   | 3'   | 15' | To be retained | Falling outside excavation line |
| 30 | 26  | subabul         | <i>Laucaena leucocephala</i>   | 9'   | 10' | To be retained | Falling outside excavation line |
| 31 | 27  | subabul         | <i>Laucaena leucocephala</i>   | 1'   | 12' | To be retained | Falling outside excavation line |
| 32 | 28  | subabul         | <i>Laucaena leucocephala</i>   | 3'   | 18' | To be removed  | Falling within excavation line  |
| 33 | 29  | subabul         | <i>Laucaena leucocephala</i>   | 3.9' | 15' | To be removed  | Falling within excavation line  |
| 34 | 30  | subabul         | <i>Laucaena leucocephala</i>   | 9'   | 18' | To be retained | Falling outside excavation line |
| 35 | 30A | subabul         | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 36 | 31  | Wilayati Chinch | <i>Pithecellobium dulce</i>    | 3.8' | 15' | To be removed  | Falling within excavation line  |
| 37 | 31A | Subabul         | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 38 | 31B | Subabul         | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 39 | 31C | Subabul         | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 40 | 31D | Subabul         | <i>Laucaena leucocephala</i>   | 9'   | 15' | To be retained | Falling outside excavation line |
| 41 | 31E | Subabul         | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 42 | 32  | Subabul         | <i>Laucaena leucocephala</i>   | 1.2' | 18' | To be retained | Falling outside excavation line |
| 43 | 33  | Subabul         | <i>Laucaena leucocephala</i>   | 8'   | 15' | To be retained | Falling outside excavation line |
| 44 | 34  | Subabul         | <i>Laucaena leucocephala</i>   | 9'   | 18' | To be retained | Falling outside excavation line |
| 45 | 35  | Peltophorum     | <i>Peltophorum pterocarpum</i> | 2.7' | 20' | To be retained | Falling outside excavation line |
| 46 | 36  | Peltophorum     | <i>Peltophorum pterocarpum</i> | 4.6' | 25' | To be retained | Falling outside excavation line |
| 47 | 37  | Gulmohar        | <i>Delonix regia</i>           | 3'   | 22' | To be retained | Falling outside excavation line |
| 48 | 38  | Gulmohar        | <i>Delonix regia</i>           | 3.8' | 25' | To be retained | Falling outside excavation line |
| 49 | 39  | Gulmohar        | <i>Delonix regia</i>           | 3.8' | 30' | To be retained | Falling outside excavation line |
| 50 | 40  | Gulmohar        | <i>Delonix regia</i>           | 2.5' | 20' | To be retained | Falling outside excavation line |
| 51 | 41  | Rain Tree       | <i>Samanea Saman</i>           | 2'   | 12' | To be retained | Falling outside excavation line |
| 52 | 42  | Peltophorum     | <i>Peltophorum pterocarpum</i> | 2.5' | 18' | To be retained | Falling outside excavation line |
| 53 | 43  | Peltophorum     | <i>Peltophorum pterocarpum</i> | 2.9' | 20' | To be retained | Falling outside excavation line |
| 54 | 44  | Peltophorum     | <i>Peltophorum pterocarpum</i> | 1'6" | 20' | To be retained | Falling outside excavation line |
| 55 | 44A | Peltophorum     | <i>Peltophorum pterocarpum</i> | 1'   | 15' | To be retained | Falling outside excavation line |
| 56 | 45  | Peltophorum     | <i>Peltophorum pterocarpum</i> | 1.7' | 20' | To be retained | Falling outside excavation line |
| 57 | 46  | Peltophorum     | <i>Peltophorum pterocarpum</i> | 1.2' | 18' | To be retained | Falling outside excavation line |
| 58 | 47  | Peltophorum     | <i>Peltophorum pterocarpum</i> | 1.4' | 18' | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |               |                                |      |     |                |                                 |
|----|-----|---------------|--------------------------------|------|-----|----------------|---------------------------------|
| 59 | 48  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 3.2' | 20' | To be retained | Falling outside excavation line |
| 60 | 49  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2'   | 20' | To be retained | Falling outside excavation line |
| 61 | 50  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2.5' | 20' | To be retained | Falling outside excavation line |
| 62 | 51  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2.2' | 20' | To be retained | Falling outside excavation line |
| 63 | 52  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 1.9' | 20' | To be retained | Falling outside excavation line |
| 64 | 53  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 1.8' | 18' | To be retained | Falling outside excavation line |
| 65 | 54  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 3.7' | 22' | To be retained | Falling outside excavation line |
| 66 | 54A | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 8'   | 12' | To be retained | Falling outside excavation line |
| 67 | 54B | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 6'   | 12' | To be retained | Falling outside excavation line |
| 68 | 55  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 3.8' | 25' | To be retained | Falling outside excavation line |
| 69 | 56  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2.9' | 20' | To be retained | Falling outside excavation line |
| 70 | 57  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2.8' | 18' | To be retained | Falling outside excavation line |
| 71 | 57A | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 8'   | 14' | To be removed  | Falling within excavation line  |
| 72 | 58  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 1.3' | 15' | To be retained | Falling outside excavation line |
| 73 | 59  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2'   | 15' | To be retained | Falling outside excavation line |
| 74 | 60  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2'   | 15' | To be retained | Falling outside excavation line |
| 75 | 61  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2'   | 15' | To be retained | Falling outside excavation line |
| 76 | 62  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 1.3' | 18' | To be retained | Falling outside excavation line |
| 77 | 63  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2'   | 18' | To be retained | Falling outside excavation line |
| 78 | 64  | Peltophoprum  | <i>Peltophorum pterocarpum</i> | 2.3' | 20' | To be retained | Falling outside excavation line |
| 79 | 65  | Cassia        | <i>Cassia biflora</i>          | 1.6' | 20' | To be retained | Falling outside excavation line |
| 80 | 66  | Bhendi        | <i>Thespesia populnea</i>      | 4'   | 18' | To be retained | Falling outside excavation line |
| 81 | 67  | Subabul       | <i>Laucaena leucocephala</i>   | 2.8' | 18' | To be retained | Falling outside excavation line |
| 82 | 68  | Subabul       | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 83 | 69  | Subabul       | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 84 | 70  | Subabul       | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 85 | 71  | Subabul       | <i>Laucaena leucocephala</i>   | 1.3' | 18' | To be retained | Falling outside excavation line |
| 86 | 72  | Subabul       | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 87 | 73  | Subabul       | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 88 | 74  | Subabul       | <i>Laucaena leucocephala</i>   | 1'   | 15' | To be retained | Falling outside excavation line |
| 89 | 75  | Jangali Badam | <i>Sterculia foetida</i>       | 1.6' | 18' | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                |      |     |                |                                 |
|-----|-----|---------------|--------------------------------|------|-----|----------------|---------------------------------|
| 90  | 76  | Jangali Badam | <i>Sterculia foetida</i>       | 2.6' | 20' | To be retained | Falling outside excavation line |
| 91  | 77  | Gulmohar      | <i>Delonix regia</i>           | 3'   | 20' | To be retained | Falling outside excavation line |
| 92  | 78  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 1.9' | 20' | To be retained | Falling outside excavation line |
| 93  | 79  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 3.7' | 25' | To be retained | Falling outside excavation line |
| 94  | 80  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 3'   | 25' | To be retained | Falling outside excavation line |
| 95  | 81  | Gulmohar      | <i>Delonix regia</i>           | 2.3' | 18' | To be retained | Falling outside excavation line |
| 96  | 82  | Gulmohar      | <i>Delonix regia</i>           | 2'   | 20' | To be retained | Falling outside excavation line |
| 97  | 83  | Gulmohar      | <i>Delonix regia</i>           | 2.4' | 20' | To be retained | Falling outside excavation line |
| 98  | 84  | Gulmohar      | <i>Delonix regia</i>           | 2.5' | 25' | To be retained | Falling outside excavation line |
| 99  | 85  | Gulmohar      | <i>Delonix regia</i>           | 2.2' | 22' | To be retained | Falling outside excavation line |
| 100 | 86  | Gulmohar      | <i>Delonix regia</i>           | 2.2' | 20' | To be retained | Falling outside excavation line |
| 101 | 87  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 3.2' | 20' | To be retained | Falling outside excavation line |
| 102 | 88  | Gulmohar      | <i>Delonix regia</i>           | 3.7' | 25' | To be retained | Falling outside excavation line |
| 103 | 89  | Gulmohar      | <i>Delonix regia</i>           | 2.2' | 25' | To be retained | Falling outside excavation line |
| 104 | 90  | Gulmohar      | <i>Delonix regia</i>           | 2.6' | 25' | To be retained | Falling outside excavation line |
| 105 | 91  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 2.9' | 22' | To be retained | Falling outside excavation line |
| 106 | 92  | Gulmohar      | <i>Delonix regia</i>           | 2.6' | 25' | To be retained | Falling outside excavation line |
| 107 | 93  | Gulmohar      | <i>Delonix regia</i>           | 3'   | 25' | To be retained | Falling outside excavation line |
| 108 | 94  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 3.2' | 25' | To be retained | Falling outside excavation line |
| 109 | 95  | Rain Tree     | <i>Samanea Saman</i>           | 4.2' | 30' | To be retained | Falling outside excavation line |
| 110 | 96  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 4'   | 25' | To be retained | Falling outside excavation line |
| 111 | 97  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 2'   | 25' | To be retained | Falling outside excavation line |
| 112 | 98  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 2.2' | 25' | To be retained | Falling outside excavation line |
| 113 | 99  | Peltophorum   | <i>Peltophorum pterocarpum</i> | 2'   | 20' | To be retained | Falling outside excavation line |
| 114 | 100 | Peltophorum   | <i>Peltophorum pterocarpum</i> | 3.7' | 25' | To be retained | Falling outside excavation line |
| 115 | 101 | Gulmohar      | <i>Delonix regia</i>           | 2.7' | 25' | To be retained | Falling outside excavation line |
| 116 | 102 | Peltophorum   | <i>Peltophorum pterocarpum</i> | 1.3' | 20' | To be retained | Falling outside excavation line |
| 117 | 103 | Peltophorum   | <i>Peltophorum pterocarpum</i> | 2'   | 18' | To be retained | Falling outside excavation line |
| 118 | 104 | Peltophorum   | <i>Peltophorum pterocarpum</i> | 2.9' | 20' | To be retained | Falling outside excavation line |
| 119 | 105 | Rain Tree     | <i>Samanea Saman</i>           | 4.9' | 30' | To be retained | Falling outside excavation line |
| 120 | 106 | Peltophorum   | <i>Peltophorum pterocarpum</i> | 2'   | 18' | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                |      |     |                |                                 |
|-----|-----|----------------|--------------------------------|------|-----|----------------|---------------------------------|
| 121 | 107 | Rain Tree      | <i>Samanea Saman</i>           | 3.3' | 30' | To be retained | Falling outside excavation line |
| 122 | 108 | Peltophorum    | <i>Peltophorum pterocarpum</i> | 2.2' | 18' | To be retained | Falling outside excavation line |
| 123 | 109 | Peltophorum    | <i>Peltophorum pterocarpum</i> | 2.4' | 20' | To be retained | Falling outside excavation line |
| 124 | 110 | Rain Tree      | <i>Samanea Saman</i>           | 2.9' | 20' | To be retained | Falling outside excavation line |
| 125 | 111 | Peltophorum    | <i>Peltophorum pterocarpum</i> | 2'   | 18' | To be retained | Falling outside excavation line |
| 126 | 112 | Subabul        | <i>Laucaena leucocephala</i>   | 1.2' | 15' | To be retained | Falling outside excavation line |
| 127 | 113 | Kate Savar     | <i>Bombax ceiba</i>            | 2.9' | 30' | To be retained | Falling outside excavation line |
| 128 | 114 | Peltophorum    | <i>Peltophorum pterocarpum</i> | 2.9' | 30' | To be retained | Falling outside excavation line |
| 129 | 115 | Peltophorum    | <i>Peltophorum pterocarpum</i> | 2.9' | 30' | To be retained | Falling outside excavation line |
| 130 | 116 | Peltophorum    | <i>Peltophorum pterocarpum</i> | 2.2' | 22' | To be retained | Falling outside excavation line |
| 131 | 117 | Jangali Cherri | <i>Prunus avium</i>            | 2.2' | 15' | To be retained | Falling outside excavation line |
| 132 | 118 | Jangali Cherri | <i>Prunus avium</i>            | 2.9' | 18' | To be retained | Falling outside excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 116        |
| Trees to be removed  | 16         |
| <b>Total Trees</b>   | <b>132</b> |

**6. TREE INVENTORY DETAILS AT UGC-06**

| Summary of Tree Survey at Domestic Airport Station |          |                 |                                |                     |                      |                     |                                |
|--|----------|-----------------|--------------------------------|---------------------|----------------------|---------------------|--------------------------------|
| Sr. no.  | Tree no. | Common Name     | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                         |
| 1  | 1        | Wad             | <i>Ficus benghalensis</i>      | 4                   | 45                   | To be removed       | Falling within excavation line |
| 2  | 2        | Naral           | <i>Cocos nucifera</i>          | 2.5                 | 12                   | To be removed       | Falling within excavation line |
| 3  | 3        | Naral           | <i>Cocos nucifera</i>          | 3                   | 30                   | To be removed       | Falling within excavation line |
| 4  | 4        | Naral           | <i>Cocos nucifera</i>          | 6                   | 15                   | To be removed       | Falling within excavation line |
| 5  | 5        | Mango           | <i>Mangifera indica</i>        | 3                   | 30                   | To be removed       | Falling within excavation line |
| 6  | 6        | Suru            | <i>Casurina equisetifolia</i>  | 6                   | 30                   | To be removed       | Falling within excavation line |
| 7  | 7        | Nilgiri         | <i>Eucalyptus citridora</i>    | 6                   | 30                   | To be removed       | Falling within excavation line |
| 8  | 7A       | Pimpal          | <i>Ficus religiosa</i>         | 3                   | 30                   | To be removed       | Falling within excavation line |
| 9  | 7B       | Umber           | <i>Ficus racemosa</i>          | 3                   | 15                   | To be removed       | Falling within excavation line |
| 10   | 8        | Subabul         | <i>Leucaena leucocephala</i>   | 4                   | 30                   | To be removed       | Falling within excavation line |
| 11   | 8A       | Lettuce tree    | <i>Pisonia alba</i>            | 2                   | 12                   | To be removed       | Falling within excavation line |
| 12   | 9        | Naral           | <i>Cocos nucifera</i>          | 3                   | 35                   | To be removed       | Falling within excavation line |
| 13   | 10       | Sonmohar        | <i>Peltophorum pterocarpum</i> | 10                  | 35                   | To be removed       | Falling within excavation line |
| 14   | 11       | Pimpal          | <i>Ficus religiosa</i>         | 10                  | 35                   | To be removed       | Falling within excavation line |
| 15   | 12       | Desi Badam      | <i>Terminalia catappa</i>      | 3                   | 35                   | To be removed       | Falling within excavation line |
| 16   | 13       | Desi Badam      | <i>Terminalia catappa</i>      | 3                   | 30                   | To be removed       | Falling within excavation line |
| 17   | 14       | Naral           | <i>Cocos nucifera</i>          | 5                   | 22                   | To be removed       | Falling within excavation line |
| 18   | 17       | Mango (Dead)    | <i>Mangifera indica</i>        | 3.5                 | 20                   | To be removed       | Falling within excavation line |
| 19   | 19       | Pimpal          | <i>Ficus religiosa</i>         | 12                  | 25                   | To be removed       | Falling within excavation line |
| 20   | 20       | Pimpal          | <i>Ficus religiosa</i>         | 6                   | 25                   | To be removed       | Falling within excavation line |
| 21   | 21       | Wad             | <i>Ficus benghalensis</i>      | 2                   | 20                   | To be removed       | Falling within excavation line |
| 22   | 22       | Pimpal          | <i>Ficus religiosa</i>         | 2                   | 20                   | To be removed       | Falling within excavation line |
| 23   | 23       | Umber           | <i>Ficus racemosa</i>          | 9"                  | 15                   | To be removed       | Falling within excavation line |
| 24   | 24       | Bor             | <i>Zizyphus mauritiana</i>     | 9"                  | 12                   | To be removed       | Falling within excavation line |
| 25   | 25       | Aus. Babhul     | <i>Acacia auriculiformis</i>   | 5                   | 12                   | To be removed       | Falling within excavation line |
| 26   | 26       | Pimpal          | <i>Ficus religiosa</i>         | 6"                  | 12                   | To be removed       | Falling within excavation line |
| 27   | 27       | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 12                  | 35                   | To be removed       | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |               |                              |     |    |               |                                |
|----|-----|---------------|------------------------------|-----|----|---------------|--------------------------------|
| 28 | 28  | Fishtail Palm | <i>Caryota urens</i>         | 3   | 15 | To be removed | Falling within excavation line |
| 29 | 29  | Chafa         | <i>Plumeria alba</i>         | 2   | 12 | To be removed | Falling within excavation line |
| 30 | 30  | Mango         | <i>Mangifera indica</i>      | 1   | 12 | To be removed | Falling within excavation line |
| 31 | 31  | Badam         | <i>Terminalia catappa</i>    | 2   | 15 | To be removed | Falling within excavation line |
| 32 | 31A | Desi Badam    | <i>Terminalia catappa</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 33 | 32  | Acasia        | <i>Acacia auriculiformis</i> | 8   | 30 | To be removed | Falling within excavation line |
| 34 | 33  | Badam         | <i>Terminalia catappa</i>    | 1   | 12 | To be removed | Falling within excavation line |
| 35 | 34  | Umber         | <i>Ficus racemosa</i>        | 6   | 30 | To be removed | Falling within excavation line |
| 36 | 35  | Aus. Babhul   | <i>Acacia auriculiformis</i> | 6   | 35 | To be removed | Falling within excavation line |
| 37 | 36  | Umber         | <i>Ficus racemosa</i>        | 10  | 35 | To be removed | Falling within excavation line |
| 38 | 37  | Umber         | <i>Ficus racemosa</i>        | 8   | 35 | To be removed | Falling within excavation line |
| 39 | 38  | Bor           | <i>Zizyphus mauritiana</i>   | 8   | 35 | To be removed | Falling within excavation line |
| 40 | 39  | Aus. Babhul   | <i>Acacia auriculiformis</i> | 8   | 35 | To be removed | Falling within excavation line |
| 41 | 40  | Mango         | <i>Mangifera indica</i>      | 2.5 | 25 | To be removed | Falling within excavation line |
| 42 | 41  | Umber         | <i>Ficus racemosa</i>        | 8   | 35 | To be removed | Falling within excavation line |
| 43 | 41A | Subabul       | <i>Polyalthia longifolia</i> | 1   | 20 | To be removed | Falling within excavation line |
| 44 | 41B | Subabul       | <i>Polyalthia longifolia</i> | 1   | 25 | To be removed | Falling within excavation line |
| 45 | 41C | Subabul       | <i>Polyalthia longifolia</i> | 1   | 25 | To be removed | Falling within excavation line |
| 46 | 41D | Aus. Babhul   | <i>Acacia auriculiformis</i> | 2   | 30 | To be removed | Falling within excavation line |
| 47 | 41E | Pimpal        | <i>Ficus religiosa</i>       | 6   | 25 | To be removed | Falling within excavation line |
| 48 | 41F | Subabul       | <i>Polyalthia longifolia</i> | 1   | 20 | To be removed | Falling within excavation line |
| 49 | 41G | Subabul       | <i>Polyalthia longifolia</i> | 1   | 20 | To be removed | Falling within excavation line |
| 50 | 41H | Subabul       | <i>Polyalthia longifolia</i> | 8   | 20 | To be removed | Falling within excavation line |
| 51 | 41I | Subabul       | <i>Polyalthia longifolia</i> | 2   | 25 | To be removed | Falling within excavation line |
| 52 | 41J | Subabul       | <i>Polyalthia longifolia</i> | 2   | 20 | To be removed | Falling within excavation line |
| 53 | 41K | Charcoal tree | <i>Trema orientalis</i>      | 2   | 30 | To be removed | Falling within excavation line |
| 54 | 41L | Subabul       | <i>Polyalthia longifolia</i> | 1   | 10 | To be removed | Falling within excavation line |
| 55 | 42  | Aus. Babhul   | <i>Acacia auriculiformis</i> | 8   | 35 | To be removed | Falling within excavation line |
| 56 | 42A | Subabul       | <i>Leucaena leucocephala</i> | 1   | 12 | To be removed | Falling within excavation line |
| 57 | 42B | Foxtail Palm  | <i>Wodyetia bifurcata</i>    | 2   | 20 | To be removed | Falling within excavation line |
| 58 | 42C | Foxtail Palm  | <i>Wodyetia bifurcata</i>    | 2   | 20 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                 |                                |    |    |                |                                 |
|----|-----|-----------------|--------------------------------|----|----|----------------|---------------------------------|
| 59 | 42D | Foxtail Palm    | <i>Wodyetia bifurcata</i>      | 2  | 20 | To be removed  | Falling within excavation line  |
| 60 | 42E | Foxtail Palm    | <i>Wodyetia bifurcata</i>      | 2  | 20 | To be removed  | Falling within excavation line  |
| 61 | 42F | Foxtail Palm    | <i>Wodyetia bifurcata</i>      | 2  | 20 | To be removed  | Falling within excavation line  |
| 62 | 42G | Foxtail Palm    | <i>Wodyetia bifurcata</i>      | 2  | 20 | To be removed  | Falling within excavation line  |
| 63 | 42H | Aus. Babhul     | <i>Acacia auriculiformis</i>   | 4  | 32 | To be removed  | Falling within excavation line  |
| 64 | 42I | Umber           | <i>Ficus racemosa</i>          | 1  | 18 | To be removed  | Falling within excavation line  |
| 65 | 43  | Asupalav        | <i>Polyalthia longifolia</i>   | 2  | 8  | To be removed  | Falling within excavation line  |
| 66 | 43A | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1  | 10 | To be removed  | Falling within excavation line  |
| 67 | 43B | Subabul         | <i>Polyalthia longifolia</i>   | 1  | 12 | To be removed  | Falling within excavation line  |
| 68 | 43C | Date palm       | <i>Phoenix sylvestris</i>      | 3  | 12 | To be retained | Falling outside excavation line |
| 69 | 43D | Date palm       | <i>Phoenix sylvestris</i>      | 3  | 12 | To be retained | Falling outside excavation line |
| 70 | 43E | Date palm       | <i>Phoenix sylvestris</i>      | 3  | 12 | To be retained | Falling outside excavation line |
| 71 | 44  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 3  | 9  | To be removed  | Falling within excavation line  |
| 72 | 45  | Umber           | <i>Ficus racemosa</i>          | 3  | 20 | To be removed  | Falling within excavation line  |
| 73 | 46  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 2  | 10 | To be removed  | Falling within excavation line  |
| 74 | 47  | Pimpal          | <i>Ficus religiosa</i>         | 3  | 12 | To be removed  | Falling within excavation line  |
| 75 | 48  | Foxtail Palm    | <i>Wodyetia bifurcata</i>      | 1  | 6  | To be removed  | Falling within excavation line  |
| 76 | 49  | Foxtail Palm    | <i>Wodyetia bifurcata</i>      | 1  | 5  | To be removed  | Falling within excavation line  |
| 77 | 50  | Umber           | <i>Ficus racemosa</i>          | 1  | 5  | To be removed  | Falling within excavation line  |
| 78 | 51  | Foxtail Palm    | <i>Wodyetia bifurcata</i>      | 1  | 5  | To be retained | Falling outside excavation line |
| 79 | 52  | Desi Badam      | <i>Terminalia catappa</i>      | 8  | 34 | To be removed  | Falling within excavation line  |
| 80 | 52A | Amba            | <i>Mangifera indica</i>        | 2  | 20 | To be removed  | Falling within excavation line  |
| 81 | 52B | Vilayati Chinch | <i>Pithecellobium dulce</i>    | 5  | 30 | To be removed  | Falling within excavation line  |
| 82 | 52C | Jambhul         | <i>Syzygium cuminii</i>        | 9  | 35 | To be removed  | Falling within excavation line  |
| 83 | 53  | Jambhul         | <i>Syzygium cuminii</i>        | 5  | 10 | To be retained | Falling outside excavation line |
| 84 | 54  | Jambhul         | <i>Syzygium cuminii</i>        | 4  | 12 | To be removed  | Falling within excavation line  |
| 85 | 54A | Bakul           | <i>Mimusops enengi</i>         | 1  | 15 | To be removed  | Falling within excavation line  |
| 86 | 54B | Bakul           | <i>Mimusops enengi</i>         | 1  | 15 | To be removed  | Falling within excavation line  |
| 87 | 54C | Licula palm     | <i>Licula grandis</i>          | 6" | 6  | To be removed  | Falling within excavation line  |
| 88 | 54D | Bakul           | <i>Mimusops enengi</i>         | 1  | 15 | To be retained | Falling outside excavation line |
| 89 | 54E | Bakul           | <i>Mimusops enengi</i>         | 2  | 18 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                                |    |    |                |                                 |
|-----|-----|-------------------|--------------------------------|----|----|----------------|---------------------------------|
| 90  | 54F | Madagascar almond | <i>Terminalia mantaly</i>      | 2  | 25 | To be retained | Falling outside excavation line |
| 91  | 54G | Madagascar almond | <i>Terminalia mantaly</i>      | 2  | 25 | To be retained | Falling outside excavation line |
| 92  | 54H | Madagascar almond | <i>Terminalia mantaly</i>      | 2  | 30 | To be removed  | Falling within excavation line  |
| 93  | 54I | Madagascar almond | <i>Terminalia mantaly</i>      | 2  | 25 | To be removed  | Falling within excavation line  |
| 94  | 54J | Madagascar almond | <i>Terminalia mantaly</i>      | 2  | 25 | To be removed  | Falling within excavation line  |
| 95  | 54K | Madagascar almond | <i>Terminalia mantaly</i>      | 1  | 20 | To be removed  | Falling within excavation line  |
| 96  | 54L | Madagascar almond | <i>Terminalia mantaly</i>      | 2  | 25 | To be removed  | Falling within excavation line  |
| 97  | 54M | Madagascar almond | <i>Terminalia mantaly</i>      | 2  | 25 | To be removed  | Falling within excavation line  |
| 98  | 54N | Madagascar almond | <i>Terminalia mantaly</i>      | 3  | 20 | To be removed  | Falling within excavation line  |
| 99  | 55  | Amba              | <i>Mangifera indica</i>        | 1  | 8  | To be removed  | Falling within excavation line  |
| 100 | 55A | Pimpal            | <i>Ficus religiosa</i>         | 12 | 35 | To be removed  | Falling within excavation line  |
| 101 | 56  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 1  | 9  | To be retained | Falling outside excavation line |
| 102 | 57  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 1  | 9  | To be retained | Falling outside excavation line |
| 103 | 58  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 1  | 9  | To be retained | Falling outside excavation line |
| 104 | 83  | Pimpal            | <i>Ficus religiosa</i>         | 2  | 8  | To be removed  | Falling within excavation line  |
| 105 | 84  | Umber             | <i>Ficus racemosa</i>          | 2  | 8  | To be removed  | Falling within excavation line  |
| 106 | A1  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 2  | 30 | To be removed  | Falling within excavation line  |
| 107 | A2  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 108 | A3  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 109 | A4  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 110 | A5  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 111 | A6  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 112 | A7  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be removed  | Falling within excavation line  |
| 113 | 1   | Rain tree         | <i>Samanea saman</i>           | 1  | 6  | To be removed  | Falling within excavation line  |
| 114 | 1A  | Vilayti Chinch    | <i>Pithecellobium dulce</i>    | 1  | 15 | To be removed  | Falling within excavation line  |
| 115 | 2   | Umber             | <i>Ficus racemosa</i>          | 1  | 7  | To be removed  | Falling within excavation line  |
| 116 | 3   | Ficus Black       | <i>Ficus elastica</i>          | 9" | 4  | To be removed  | Falling within excavation line  |
| 117 | 4   | Areca Palm        | <i>Dyopsis lutescens</i>       | 8" | 6  | To be removed  | Falling within excavation line  |
| 118 | 5   | Areca Palm        | <i>Dyopsis lutescens</i>       | 8" | 6  | To be removed  | Falling within excavation line  |
| 119 | 6   | Rain tree         | <i>Samanea saman</i>           | 2  | 10 | To be retained | Falling outside excavation line |
| 120 | 7   | Chapha            | <i>Plumeria alba</i>           | 1  | 6  | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |    |            |                           |    |     |                |                                 |
|-----|----|------------|---------------------------|----|-----|----------------|---------------------------------|
| 121 | 8  | Chapha     | <i>Plumeria alba</i>      | 1  | 6   | To be removed  | Falling within excavation line  |
| 122 | 9  | Chapha     | <i>Plumeria alba</i>      | 1  | 6   | To be removed  | Falling within excavation line  |
| 123 | 10 | Chapha     | <i>Plumeria alba</i>      | 1  | 6   | To be removed  | Falling within excavation line  |
| 124 | 11 | Naral      | <i>Cocos nucifera</i>     | 2  | 7   | To be removed  | Falling within excavation line  |
| 125 | 12 | Pimpal     | <i>Ficus religiosa</i>    | 1  | 8   | To be removed  | Falling within excavation line  |
| 126 | 13 | Peru       | <i>Psidium guajava</i>    | 8" | 3.5 | To be removed  | Falling within excavation line  |
| 127 | 14 | Vad        | <i>Ficus benghalensis</i> | 6  | 15  | To be retained | Falling outside excavation line |
| 128 | 15 | Areca Palm | <i>Dyopsis lutescens</i>  | 8" | 3   | To be removed  | Falling within excavation line  |
| 129 | 16 | Areca Palm | <i>Dyopsis lutescens</i>  | 8" | 3   | To be removed  | Falling within excavation line  |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 14         |
| Trees to be removed  | 115        |
| <b>Total Trees</b>   | <b>129</b> |

| Summary of Tree Survey at Sahar Road Station |          |               |                             |                      |                       |                     |                                 |
|--|----------|---------------|-----------------------------|----------------------|-----------------------|---------------------|---------------------------------|
| Sr. no.                                      | Tree no. | Common Name   | Botanical Name              | Approx . Girth (ft.) | Approx . Height (ft.) | Proposed suggestion | Remark                          |
| 1  | 1        | Rain Tree     | <i>Samanea saman</i>        | 3                    | 20                    | To be removed       | Falling within excavation line  |
| 2  | 1A       | Rain tree     | <i>Samanea saman</i>        | 3                    | 33                    | To be removed       | Falling within excavation line  |
| 3  | 1B       | Ficus black   | <i>Ficus benjamina</i>      | 2                    | 16                    | To be removed       | Falling within excavation line  |
| 4  | 1C       | Supari        | <i>Areca catechu</i>        | 2                    | 16                    | To be removed       | Falling within excavation line  |
| 5  | 1D       | Fishtail palm | <i>Caryota urens</i>        | 4                    | 20                    | To be removed       | Falling within excavation line  |
| 6  | 1E       | Jamun         | <i>Syzygium cumini</i>      | 2                    | 20                    | To be removed       | Falling within excavation line  |
| 7  | 1F       | Fishtail palm | <i>Caryota urens</i>        | 3                    | 20                    | To be removed       | Falling within excavation line  |
| 8  | 1G       | Fishtail palm | <i>Caryota urens</i>        | 3                    | 20                    | To be removed       | Falling within excavation line  |
| 9  | 1H       | Fishtail palm | <i>Caryota urens</i>        | 3                    | 20                    | To be removed       | Falling within excavation line  |
| 10   | 2        | Naral         | <i>Cocos nucifera</i>       | 4                    | 30                    | To be removed       | Falling within excavation line  |
| 11   | 2A       | Naral         | <i>Cocos nucifera</i>       | 3                    | 21                    | To be removed       | Falling within excavation line  |
| 12   | 2B       | Royal palm    | <i>Roystonea regia</i>      | 2                    | 8                     | To be removed       | Falling within excavation line  |
| 13   | 2C       | Naral         | <i>Cocos nucifera</i>       | 1                    | 8                     | To be removed       | Falling within excavation line  |
| 14   | 2D       | Royal Palm    | <i>Roystonea regia</i>      | 4                    | 26                    | To be removed       | Falling within excavation line  |
| 15   | 3        | Deshi badam   | <i>Terminalia catappa</i>   | 1                    | 8                     | To be retained      | Falling outside excavation line |
| 16   | 4        | Rain Tree     | <i>Samanea saman</i>        | 6                    | 25                    | To be removed       | Falling within excavation line  |
| 17   | 5        | Naral         | <i>Cocos nucifera</i>       | 5                    | 35                    | To be removed       | Falling within excavation line  |
| 18   | 6        | Rain Tree     | <i>Samanea saman</i>        | 4                    | 30                    | To be removed       | Falling within excavation line  |
| 19   | 7        | Gulmohar      | <i>Delonix regia</i>        | 3                    | 20                    | To be removed       | Falling within excavation line  |
| 20   | 8        | Chinch        | <i>Pithecellobium dulce</i> | 1                    | 15                    | To be removed       | Falling within excavation line  |
| 21   | 9        | Naral         | <i>Cocos nucifera</i>       | 3                    | 30                    | To be removed       | Falling within excavation line  |
| 22   | 10       | Chafa         | <i>Plumeria alba</i>        | 2                    | 20                    | To be removed       | Falling within excavation line  |
| 23   | 11       | Chafa         | <i>Plumeria alba</i>        | 2                    | 20                    | To be removed       | Falling within excavation line  |
| 24   | 12       | Pimpal        | <i>Ficus religiosa</i>      | 2                    | 20                    | To be removed       | Falling within excavation line  |
| 25   | 13       | Bherli mad    | <i>Caryota urens</i>        | 3                    | 20                    | To be removed       | Falling within excavation line  |
| 26   | 13A      | Shevga        | <i>Moringa oliefera</i>     | 1                    | 15                    | To be removed       | Falling within excavation line  |
| 27   | 14       | Naral         | <i>Cocos nucifera</i>       | 4                    | 20                    | To be removed       | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |             |                           |   |    |               |                                |
|----|-----|-------------|---------------------------|---|----|---------------|--------------------------------|
| 28 | 15  | Royal Palm  | <i>Roystonea regia</i>    | 6 | 20 | To be removed | Falling within excavation line |
| 29 | 16  | Bherli mad  | <i>Caryota urens</i>      | 6 | 20 | To be removed | Falling within excavation line |
| 30 | 17  | Mango       | <i>Mangifera indica</i>   | 1 | 10 | To be removed | Falling within excavation line |
| 31 | 18  | Bherli mad  | <i>Caryota urens</i>      | 5 | 10 | To be removed | Falling within excavation line |
| 32 | 18A | Deshi Badam | <i>Terminalia catappa</i> | 3 | 13 | To be removed | Falling within excavation line |
| 33 | 18B | Naral       | <i>Cocos nucifera</i>     | 3 | 26 | To be removed | Falling within excavation line |
| 34 | 18C | Mango       | <i>Mangifera indica</i>   | 2 | 25 | To be removed | Falling within excavation line |
| 35 | 19  | Bherli mad  | <i>Caryota urens</i>      | 4 | 20 | To be removed | Falling within excavation line |
| 36 | 19A | Shevga      | <i>Moringa oliefera</i>   | 3 | 23 | To be removed | Falling within excavation line |
| 37 | 19B | Dead tree   | -                         | 3 | 23 | To be removed | Falling within excavation line |
| 38 | 19C | Jamun       | <i>Syzygium cumini</i>    | 3 | 26 | To be removed | Falling within excavation line |
| 39 | 19D | Jamun       | <i>Syzygium cumini</i>    | 3 | 26 | To be removed | Falling within excavation line |
| 40 | 19E | Peru        | <i>Psidium gujava</i>     | 1 | 13 | To be removed | Falling within excavation line |
| 41 | 19F | Naral       | <i>Cocos nucifera</i>     | 3 | 26 | To be removed | Falling within excavation line |
| 42 | 20  | Chafa       | <i>Plumeria alba</i>      | 1 | 20 | To be removed | Falling within excavation line |
| 43 | 21  | Chafa       | <i>Plumeria alba</i>      | 2 | 20 | To be removed | Falling within excavation line |
| 44 | 22  | Naral       | <i>Cocos nucifera</i>     | 4 | 25 | To be removed | Falling within excavation line |
| 45 | 23  | Dead tree   | -                         | 3 | 6  | To be removed | Falling within excavation line |
| 46 | 24  | Chafa       | <i>Plumeria alba</i>      | 1 | 15 | To be removed | Falling within excavation line |
| 47 | 25  | Bherli mad  | <i>Caryota urens</i>      | 4 | 20 | To be removed | Falling within excavation line |
| 48 | 26  | Naral       | <i>Cocos nucifera</i>     | 4 | 20 | To be removed | Falling within excavation line |
| 49 | 27  | Royal palm  | <i>Roystonea regia</i>    | 5 | 25 | To be removed | Falling within excavation line |
| 50 | 28  | Bherli mad  | <i>Caryota urens</i>      | 3 | 20 | To be removed | Falling within excavation line |
| 51 | 28A | Mango       | <i>Mangifera indica</i>   | 3 | 20 | To be removed | Falling within excavation line |
| 52 | 28B | Mango       | <i>Mangifera indica</i>   | 3 | 20 | To be removed | Falling within excavation line |
| 53 | 28C | Mango       | <i>Mangifera indica</i>   | 3 | 23 | To be removed | Falling within excavation line |
| 54 | 29  | Ficus black | <i>Ficus benjamina</i>    | 8 | 25 | To be removed | Falling within excavation line |
| 55 | 30  | Bherli mad  | <i>Caryota urens</i>      | 5 | 20 | To be removed | Falling within excavation line |
| 56 | 30A | Jamun       | <i>Syzygium cumini</i>    | 1 | 10 | To be removed | Falling within excavation line |
| 57 | 30B | Jamun       | <i>Syzygium cumini</i>    | 3 | 23 | To be removed | Falling within excavation line |
| 58 | 30C | Jamun       | <i>Syzygium cumini</i>    | 3 | 16 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                        |                              |    |    |               |                                |
|----|-----|------------------------|------------------------------|----|----|---------------|--------------------------------|
| 59 | 30D | Shevga                 | <i>Moringa oliefera</i>      | 4  | 23 | To be removed | Falling within excavation line |
| 60 | 30E | Naral                  | <i>Cocos nucifera</i>        | 5  | 20 | To be removed | Falling within excavation line |
| 61 | 31  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 10 | To be removed | Falling within excavation line |
| 62 | 31A | Ficus black            | <i>Ficus benjamina</i>       | 13 | 33 | To be removed | Falling within excavation line |
| 63 | 31B | Chafa                  | <i>Plumeria alba</i>         | 3  | 13 | To be removed | Falling within excavation line |
| 64 | 31C | Royal Palm             | <i>Roystonea regia</i>       | 7  | 33 | To be removed | Falling within excavation line |
| 65 | 31D | Vilayti chinch         | <i>Pithecellobium dulce</i>  | 2  | 18 | To be removed | Falling within excavation line |
| 66 | 32  | Asupalav               | <i>Polyalthia longifolia</i> | 1  | 20 | To be removed | Falling within excavation line |
| 67 | 33  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 8  | To be removed | Falling within excavation line |
| 68 | 34  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 69 | 35  | Foxtail palm<br>(dead) | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 70 | 36  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 71 | 37  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 72 | 38  | Asupalav               | <i>Polyalthia longifolia</i> | 1  | 20 | To be removed | Falling within excavation line |
| 73 | 39  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 6" | 6  | To be removed | Falling within excavation line |
| 74 | 40  | Asupalav               | <i>Polyalthia longifolia</i> | 1  | 15 | To be removed | Falling within excavation line |
| 75 | 41  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 76 | 42  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 77 | 43  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 78 | 44  | Asupalav               | <i>Polyalthia longifolia</i> | 1  | 25 | To be removed | Falling within excavation line |
| 79 | 45  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 80 | 46  | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 81 | 46A | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 6  | To be removed | Falling within excavation line |
| 82 | 47  | Asupalav               | <i>Polyalthia longifolia</i> | 1  | 25 | To be removed | Falling within excavation line |
| 83 | 47A | Foxtail palm           | <i>Wodetia bifurcata</i>     | 1  | 12 | To be removed | Falling within excavation line |
| 84 | 47B | Asupalav               | <i>Polyalthia longifolia</i> | 1  | 20 | To be removed | Falling within excavation line |
| 85 | 47C | Foxtail palm           | <i>Wodetia bifurcata</i>     | 2  | 10 | To be removed | Falling within excavation line |
| 86 | 47D | Asupalav               | <i>Polyalthia longifolia</i> | 8" | 15 | To be removed | Falling within excavation line |
| 87 | 48  | Naral                  | <i>Cocos nucifera</i>        | 3  | 20 | To be removed | Falling within excavation line |
| 88 | 49  | Gulmohar               | <i>Delonix regia</i>         | 5  | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                    |                                |    |    |                |                                 |
|-----|-----|--------------------|--------------------------------|----|----|----------------|---------------------------------|
| 89  | 50  | Naral              | <i>Cocos nucifera</i>          | 6  | 20 | To be removed  | Falling within excavation line  |
| 90  | 51  | Naral              | <i>Cocos nucifera</i>          | 4  | 25 | To be removed  | Falling within excavation line  |
| 91  | 52  | Gulmohar           | <i>Delonix regia</i>           | 6  | 20 | To be removed  | Falling within excavation line  |
| 92  | 53  | Naral              | <i>Cocos nucifera</i>          | 4  | 25 | To be removed  | Falling within excavation line  |
| 93  | 54  | Gulmohar<br>(Dead) | <i>Delonix regia</i>           | 8  | 30 | To be removed  | Falling within excavation line  |
| 94  | 55  | Subabhul           | <i>Leucaena leucocephala</i>   | 9" | 14 | To be retained | Falling outside excavation line |
| 95  | 56  | Umbar              | <i>Ficus glomerata</i>         | 1  | 13 | To be retained | Falling outside excavation line |
| 96  | 57  | Pimpal             | <i>Ficus religiosa</i>         | 1  | 7  | To be retained | Falling outside excavation line |
| 97  | 58  | Kaduneem           | <i>Azadirachta indica</i>      | 1  | 12 | To be retained | Falling outside excavation line |
| 98  | 59  | Peru               | <i>Psidium guajava</i>         | 1  | 7  | To be retained | Falling outside excavation line |
| 99  | 60  | Jambhul            | <i>Syzigium cumini</i>         | 1  | 20 | To be retained | Falling outside excavation line |
| 100 | 61  | Amba               | <i>Mangifera indica</i>        | 1  | 14 | To be retained | Falling outside excavation line |
| 101 | 62  | Chafa              | <i>Plumeria alba</i>           | 2  | 8  | To be retained | Falling outside excavation line |
| 102 | 63  | Chafa              | <i>Plumeria alba</i>           | 2  | 8  | To be retained | Falling outside excavation line |
| 103 | 64  | Peru               | <i>Psidium guajava</i>         | 1  | 8  | To be retained | Falling outside excavation line |
| 104 | 65  | Peru               | <i>Psidium guajava</i>         | 1  | 9  | To be retained | Falling outside excavation line |
| 105 | 66  | Amba               | <i>Mangifera indica</i>        | 1  | 12 | To be retained | Falling outside excavation line |
| 106 | 67  | Chafa              | <i>Plumeria alba</i>           | 1  | 7  | To be removed  | Falling within excavation line  |
| 107 | 68  | Pimpal             | <i>Ficus religiosa</i>         | 2  | 26 | To be removed  | Falling within excavation line  |
| 108 | 69  | Amba               | <i>Mangifera indica</i>        | 2  | 22 | To be removed  | Falling within excavation line  |
| 109 | 70  | Wad                | <i>Ficus benghalensis</i>      | 1  | 15 | To be removed  | Falling within excavation line  |
| 110 | 71  | Deshi Badam        | <i>Terminalia catappa</i>      | 1  | 15 | To be removed  | Falling within excavation line  |
| 111 | 72  | Deshi Badam        | <i>Terminalia catappa</i>      | 1  | 15 | To be removed  | Falling within excavation line  |
| 112 | 73  | Subabhul           | <i>Leucaena leucocephala</i>   | 1  | 14 | To be removed  | Falling within excavation line  |
| 113 | 74  | Amba               | <i>Mangifera indica</i>        | 3  | 18 | To be removed  | Falling within excavation line  |
| 114 | 75  | Pimpal             | <i>Ficus religiosa</i>         | 2  | 20 | To be removed  | Falling within excavation line  |
| 115 | 76  | Pimpal             | <i>Ficus religiosa</i>         | 2  | 20 | To be removed  | Falling within excavation line  |
| 116 | 77  | Amba               | <i>Mangifera indica</i>        | 1  | 13 | To be removed  | Falling within excavation line  |
| 117 | 78  | Sonmohor           | <i>Peltophorum pterocarpum</i> | 2  | 30 | To be removed  | Falling within excavation line  |
| 118 | 78A | Sonmohor           | <i>Peltophorum pterocarpum</i> | 1  | 18 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                |    |    |                |                                 |
|-----|-----|----------------|--------------------------------|----|----|----------------|---------------------------------|
| 119 | 78B | Sonmohor       | <i>Peltophorum pterocarpum</i> | 1  | 20 | To be removed  | Falling within excavation line  |
| 120 | 78C | Sonmohor       | <i>Peltophorum pterocarpum</i> | 1  | 20 | To be removed  | Falling within excavation line  |
| 121 | 79  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 4  | 30 | To be removed  | Falling within excavation line  |
| 122 | 80  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 3  | 26 | To be removed  | Falling within excavation line  |
| 123 | 81  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 3  | 25 | To be retained | Falling outside excavation line |
| 124 | 82  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 3  | 25 | To be removed  | Falling within excavation line  |
| 125 | 83  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 4  | 30 | To be removed  | Falling within excavation line  |
| 126 | 84  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 4  | 25 | To be removed  | Falling within excavation line  |
| 127 | 85  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 5  | 30 | To be removed  | Falling within excavation line  |
| 128 | 86  | Umbar          | <i>Ficus glomerata</i>         | 3  | 26 | To be removed  | Falling within excavation line  |
| 129 | 87  | Pimpal         | <i>Ficus religiosa</i>         | 2  | 26 | To be removed  | Falling within excavation line  |
| 130 | 88  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 3  | 28 | To be removed  | Falling within excavation line  |
| 131 | 89  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 3  | 26 | To be removed  | Falling within excavation line  |
| 132 | 90  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 4  | 26 | To be removed  | Falling within excavation line  |
| 133 | 91  | Subabhul       | <i>Leucaena leucocephala</i>   | 4  | 18 | To be removed  | Falling within excavation line  |
| 134 | 92  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 4  | 28 | To be removed  | Falling within excavation line  |
| 135 | 92A | Subabhul       | <i>Leucaena leucocephala</i>   | 2  | 25 | To be removed  | Falling within excavation line  |
| 136 | 92B | Subabhul       | <i>Leucaena leucocephala</i>   | 3  | 25 | To be removed  | Falling within excavation line  |
| 137 | 92C | Umbar          | <i>Ficus glomerata</i>         | 4  | 30 | To be removed  | Falling within excavation line  |
| 138 | 92D | Pimpal         | <i>Ficus religiosa</i>         | 2  | 25 | To be removed  | Falling within excavation line  |
| 139 | 92E | Pandhara Savar | <i>Ceiba pentandra</i>         | 3  | 30 | To be removed  | Falling within excavation line  |
| 140 | 93  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 4  | 26 | To be removed  | Falling within excavation line  |
| 141 | 94  | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 4  | 24 | To be removed  | Falling within excavation line  |
| 142 | 95  | Subabhul       | <i>Leucaena leucocephala</i>   | 2  | 16 | To be removed  | Falling within excavation line  |
| 143 | 96  | Subabhul       | <i>Leucaena leucocephala</i>   | 1  | 9  | To be removed  | Falling within excavation line  |
| 144 | 97  | Subabhul       | <i>Leucaena leucocephala</i>   | 8" | 9  | To be removed  | Falling within excavation line  |
| 145 | 98  | Sonmohor       | <i>Peltophorum pterocarpum</i> | 2  | 24 | To be removed  | Falling within excavation line  |
| 146 | 99  | Subabhul       | <i>Leucaena leucocephala</i>   | 3  | 28 | To be removed  | Falling within excavation line  |
| 147 | 100 | Sonmohor       | <i>Peltophorum pterocarpum</i> | 6" | 9  | To be removed  | Falling within excavation line  |
| 148 | 101 | Sonmohor       | <i>Peltophorum pterocarpum</i> | 2  | 20 | To be removed  | Falling within excavation line  |
| 149 | 102 | Subabhul       | <i>Leucaena leucocephala</i>   | 2  | 22 | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                   |                                |   |    |               |                                |
|-----|------|-------------------|--------------------------------|---|----|---------------|--------------------------------|
| 150 | 102A | Subabhul          | <i>Leucaena leucocephala</i>   | 1 | 20 | To be removed | Falling within excavation line |
| 151 | 102B | Subabhul          | <i>Leucaena leucocephala</i>   | 1 | 20 | To be removed | Falling within excavation line |
| 152 | 102C | Subabhul          | <i>Leucaena leucocephala</i>   | 1 | 20 | To be removed | Falling within excavation line |
| 153 | 102D | Subabhul          | <i>Leucaena leucocephala</i>   | 1 | 15 | To be removed | Falling within excavation line |
| 154 | 102E | Subabhul          | <i>Leucaena leucocephala</i>   | 1 | 20 | To be removed | Falling within excavation line |
| 155 | 102F | Subabhul          | <i>Leucaena leucocephala</i>   | 1 | 25 | To be removed | Falling within excavation line |
| 156 | 102G | Subabhul          | <i>Leucaena leucocephala</i>   | 2 | 25 | To be removed | Falling within excavation line |
| 157 | 102H | Subabhul          | <i>Leucaena leucocephala</i>   | 2 | 20 | To be removed | Falling within excavation line |
| 158 | 103  | Subabhul          | <i>Leucaena leucocephala</i>   | 1 | 12 | To be removed | Falling within excavation line |
| 159 | 104  | Vilayti Chinch    | <i>Pithecellobium dulce</i>    | 2 | 18 | To be removed | Falling within excavation line |
| 160 | 105  | Sonmohor          | <i>Peltophorum pterocarpum</i> | 9 | 30 | To be removed | Falling within excavation line |
| 161 | 106  | Subabhul          | <i>Leucaena leucocephala</i>   | 2 | 25 | To be removed | Falling within excavation line |
| 162 | 107  | Subabhul          | <i>Leucaena leucocephala</i>   | 2 | 25 | To be removed | Falling within excavation line |
| 163 | 108  | Vilayti Chinch    | <i>Pithecellobium dulce</i>    | 3 | 18 | To be removed | Falling within excavation line |
| 164 | 109  | Sonmohor          | <i>Peltophorum pterocarpum</i> | 5 | 22 | To be removed | Falling within excavation line |
| 165 | 110  | Sonmohor          | <i>Peltophorum pterocarpum</i> | 5 | 24 | To be removed | Falling within excavation line |
| 166 | 111  | Subabhul          | <i>Leucaena leucocephala</i>   | 2 | 28 | To be removed | Falling within excavation line |
| 167 | 112  | Umbar             | <i>Ficus glomerata</i>         | 2 | 18 | To be removed | Falling within excavation line |
| 168 | 113  | Subabhul          | <i>Leucaena leucocephala</i>   | 3 | 25 | To be removed | Falling within excavation line |
| 169 | 114  | Sonmohor          | <i>Peltophorum pterocarpum</i> | 1 | 18 | To be removed | Falling within excavation line |
| 170 | 115  | Australian Babhul | <i>Acacia auriculiformis</i>   | 6 | 38 | To be removed | Falling within excavation line |
| 171 | 116  | Asupalav          | <i>Polyalthia longifolia</i>   | 2 | 25 | To be removed | Falling within excavation line |
| 172 | 117  | Australian Babhul | <i>Acacia auriculiformis</i>   | 7 | 40 | To be removed | Falling within excavation line |
| 173 | 118  | Asupalav          | <i>Polyalthia longifolia</i>   | 2 | 20 | To be removed | Falling within excavation line |
| 174 | 119  | Subabhul          | <i>Leucaena leucocephala</i>   | 2 | 8  | To be removed | Falling within excavation line |
| 175 | 120  | Asupalav          | <i>Polyalthia longifolia</i>   | 3 | 23 | To be removed | Falling within excavation line |
| 176 | 121  | Subabhul          | <i>Leucaena leucocephala</i>   | 2 | 18 | To be removed | Falling within excavation line |
| 177 | 122  | Subabhul          | <i>Leucaena leucocephala</i>   | 2 | 18 | To be removed | Falling within excavation line |
| 178 | 123  | Subabhul          | <i>Leucaena leucocephala</i>   | 3 | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |             |                              |    |    |               |                                |
|-----|-----|-------------|------------------------------|----|----|---------------|--------------------------------|
| 179 | 124 | Asupalav    | <i>Polyalthia longifolia</i> | 3  | 15 | To be removed | Falling within excavation line |
| 180 | 125 | Subabhul    | <i>Leucaena leucocephala</i> | 2  | 18 | To be removed | Falling within excavation line |
| 181 | 126 | Asupalav    | <i>Polyalthia longifolia</i> | 1  | 12 | To be removed | Falling within excavation line |
| 182 | 127 | Umbar       | <i>Ficus glomerata</i>       | 4  | 16 | To be removed | Falling within excavation line |
| 183 | 128 | Asupalav    | <i>Polyalthia longifolia</i> | 1  | 12 | To be removed | Falling within excavation line |
| 184 | 129 | Subabhul    | <i>Leucaena leucocephala</i> | 1  | 20 | To be removed | Falling within excavation line |
| 185 | 130 | Asupalav    | <i>Polyalthia longifolia</i> | 3  | 13 | To be removed | Falling within excavation line |
| 186 | 131 | Subabhul    | <i>Leucaena leucocephala</i> | 2  | 18 | To be removed | Falling within excavation line |
| 187 | 132 | Asupalav    | <i>Polyalthia longifolia</i> | 3  | 13 | To be removed | Falling within excavation line |
| 188 | 133 | Bitti       | <i>Thevetia peruviana</i>    | 1  | 7  | To be removed | Falling within excavation line |
| 189 | 134 | Bitti       | <i>Thevetia peruviana</i>    | 1  | 7  | To be removed | Falling within excavation line |
| 190 | 135 | Asupalav    | <i>Polyalthia longifolia</i> | 2  | 18 | To be removed | Falling within excavation line |
| 191 | 136 | Pimpal      | <i>Ficus religiosa</i>       | 2  | 14 | To be removed | Falling within excavation line |
| 192 | 137 | Subabhul    | <i>Leucaena leucocephala</i> | 2  | 16 | To be removed | Falling within excavation line |
| 193 | 138 | Subabhul    | <i>Leucaena leucocephala</i> | 2  | 16 | To be removed | Falling within excavation line |
| 194 | 139 | Asupalav    | <i>Polyalthia longifolia</i> | 2  | 14 | To be removed | Falling within excavation line |
| 195 | 140 | Wad         | <i>Ficus benghalensis</i>    | 2  | 14 | To be removed | Falling within excavation line |
| 196 | 141 | Asupalav    | <i>Polyalthia longifolia</i> | 1  | 14 | To be removed | Falling within excavation line |
| 197 | 142 | Wad         | <i>Ficus benghalensis</i>    | 4  | 25 | To be removed | Falling within excavation line |
| 198 | 143 | Asupalav    | <i>Polyalthia longifolia</i> | 1  | 14 | To be removed | Falling within excavation line |
| 199 | 144 | Subabhul    | <i>Leucaena leucocephala</i> | 2  | 14 | To be removed | Falling within excavation line |
| 200 | 145 | Asupalav    | <i>Polyalthia longifolia</i> | 1  | 11 | To be removed | Falling within excavation line |
| 201 | 146 | Subabhul    | <i>Leucaena leucocephala</i> | 8" | 10 | To be removed | Falling within excavation line |
| 202 | 147 | Subabhul    | <i>Leucaena leucocephala</i> | 2  | 17 | To be removed | Falling within excavation line |
| 203 | 148 | Asupalav    | <i>Polyalthia longifolia</i> | 3  | 18 | To be removed | Falling within excavation line |
| 204 | 149 | Asupalav    | <i>Polyalthia longifolia</i> | 3  | 18 | To be removed | Falling within excavation line |
| 205 | 150 | Subabhul    | <i>Leucaena leucocephala</i> | 3  | 25 | To be removed | Falling within excavation line |
| 206 | 151 | Subabhul    | <i>Leucaena leucocephala</i> | 2  | 18 | To be removed | Falling within excavation line |
| 207 | 152 | Asupalav    | <i>Polyalthia longifolia</i> | 2  | 17 | To be removed | Falling within excavation line |
| 208 | 153 | Asupalav    | <i>Polyalthia longifolia</i> | 2  | 17 | To be removed | Falling within excavation line |
| 209 | 154 | Deshi Badam | <i>Terminalia catappa</i>    | 2  | 33 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                                |    |    |                |                                 |
|-----|-----|-------------------|--------------------------------|----|----|----------------|---------------------------------|
| 210 | 155 | Deshi Badam       | <i>Terminalia catappa</i>      | 1  | 18 | To be removed  | Falling within excavation line  |
| 211 | 156 | Sonmohor          | <i>Peltophorum pterocarpum</i> | 3  | 30 | To be retained | Falling outside excavation line |
| 212 | 157 | Australian Babbul | <i>Acacia auriculiformis</i>   | 3  | 26 | To be removed  | Falling within excavation line  |
| 213 | 158 | Australian Babbul | <i>Acacia auriculiformis</i>   | 5  | 30 | To be removed  | Falling within excavation line  |
| 214 | 159 | Australian Babbul | <i>Acacia auriculiformis</i>   | 3  | 27 | To be retained | Falling outside excavation line |
| 215 | 160 | Sonmohor          | <i>Peltophorum pterocarpum</i> | 3  | 28 | To be retained | Falling outside excavation line |
| 216 | 161 | Sonmohor          | <i>Peltophorum pterocarpum</i> | 4  | 28 | To be retained | Falling outside excavation line |
| 217 | 162 | Sonmohor          | <i>Peltophorum pterocarpum</i> | 6  | 30 | To be retained | Falling outside excavation line |
| 218 | 163 | Deshi Badam       | <i>Terminalia catappa</i>      | 1  | 18 | To be removed  | Falling within excavation line  |
| 219 | 164 | Umbar             | <i>Ficus glomerata</i>         | 2  | 20 | To be removed  | Falling within excavation line  |
| 220 | 165 | Pimpal            | <i>Ficus religiosa</i>         | 1  | 18 | To be removed  | Falling within excavation line  |
| 221 | 166 | Charcoal          | <i>Trema orientalis</i>        | 10 | 14 | To be removed  | Falling within excavation line  |
| 222 | 167 | Charcoal          | <i>Trema orientalis</i>        | 8  | 12 | To be removed  | Falling within excavation line  |
| 223 | 168 | Charcoal          | <i>Trema orientalis</i>        | 10 | 12 | To be removed  | Falling within excavation line  |
| 224 | 169 | Charcoal          | <i>Trema orientalis</i>        | 3  | 25 | To be removed  | Falling within excavation line  |
| 225 | 170 | Asupalav          | <i>Polyalthia longifolia</i>   | 3  | 22 | To be removed  | Falling within excavation line  |
| 226 | 171 | Foxtail           | <i>Wodyetia bifurcata</i>      | 1  | 14 | To be removed  | Falling within excavation line  |
| 227 | 172 | Foxtail           | <i>Wodyetia bifurcata</i>      | 2  | 15 | To be removed  | Falling within excavation line  |
| 228 | 173 | Foxtail           | <i>Wodyetia bifurcata</i>      | 2  | 15 | To be removed  | Falling within excavation line  |
| 229 | 174 | Umbar             | <i>Ficus racemosa</i>          | 4  | 28 | To be removed  | Falling within excavation line  |
| 230 | 175 | Pimpal            | <i>Ficus religiosa</i>         | 4  | 30 | To be removed  | Falling within excavation line  |
| 231 | 176 | Pimpal            | <i>Ficus religiosa</i>         | 6  | 35 | To be removed  | Falling within excavation line  |
| 232 | 177 | Kaduneem          | <i>Azadirachta indica</i>      | 2  | 22 | To be removed  | Falling within excavation line  |
| 233 | 178 | Naral             | <i>Cocos nucifera</i>          | 3  | 18 | To be removed  | Falling within excavation line  |
| 234 | 179 | Vilayti Chinch    | <i>Pithecellobium dulce</i>    | 4  | 30 | To be removed  | Falling within excavation line  |
| 235 | 180 | Naral             | <i>Cocos nucifera</i>          | 4  | 40 | To be removed  | Falling within excavation line  |
| 236 | 181 | Deshi Badam       | <i>Terminalia catappa</i>      | 4  | 40 | To be removed  | Falling within excavation line  |
| 237 | 182 | Amba              | <i>Mangifera indica</i>        | 6  | 14 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                              |   |    |               |                                |
|-----|-----|---------------|------------------------------|---|----|---------------|--------------------------------|
| 238 | 183 | Deshi Badam   | <i>Terminalia catappa</i>    | 3 | 40 | To be removed | Falling within excavation line |
| 239 | 184 | Sitaphal      | <i>Annona squamosa</i>       | 6 | 10 | To be removed | Falling within excavation line |
| 240 | 185 | Jambhul       | <i>Syzigium cumini</i>       | 3 | 25 | To be removed | Falling within excavation line |
| 241 | 186 | Deshi Badam   | <i>Terminalia catappa</i>    | 2 | 15 | To be removed | Falling within excavation line |
| 242 | 187 | Naral         | <i>Cocos nucifera</i>        | 3 | 35 | To be removed | Falling within excavation line |
| 243 | 188 | Fishtail palm | <i>Caryota urens</i>         | 3 | 25 | To be removed | Falling within excavation line |
| 244 | 189 | Dombeya       | <i>Dombeya spectabilis</i>   | 1 | 25 | To be removed | Falling within excavation line |
| 245 | 190 | Subabhul      | <i>Leucaena leucocephala</i> | 3 | 35 | To be removed | Falling within excavation line |
| 246 | 191 | Dombeya       | <i>Dombeya spectabilis</i>   | 1 | 25 | To be removed | Falling within excavation line |
| 247 | 192 | Chafa         | <i>Plumeria rubra</i>        | 2 | 25 | To be removed | Falling within excavation line |
| 248 | 193 | Ramphal       | <i>Anona reticulata</i>      | 1 | 15 | To be removed | Falling within excavation line |
| 249 | 194 | Neem          | <i>Azadirachta indica</i>    | 1 | 15 | To be removed | Falling within excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 19         |
| Trees to be removed  | 230        |
| <b>Total Trees</b>   | <b>249</b> |

| Summary of Tree Survey at International Airport Station |          |             |                           |                     |                      |                     |                                 |
|---|----------|-------------|---------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.   | Tree no. | Common Name | Botanical Name            | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1   | 1        | Naral       | <i>Cocos nucifera</i>     | 3                   | 23                   | To be retained      | Falling outside excavation line |
| 2   | 2        | Pimpal      | <i>Ficus religiosa</i>    | 3                   | 16                   | To be removed       | Falling within excavation line  |
| 3   | 3        | Pimpal      | <i>Ficus religiosa</i>    | 2                   | 16                   | To be removed       | Falling within excavation line  |
| 4   | 4        | Wad         | <i>Ficus benghalensis</i> | 1                   | 13                   | To be removed       | Falling within excavation line  |
| 5   | 5        | Pimpal      | <i>Ficus religiosa</i>    | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 6   | 6        | Naral       | <i>Cocos nucifera</i>     | 3                   | 40                   | To be retained      | Falling outside excavation line |
| 7   | 7        | Pimpal      | <i>Ficus religiosa</i>    | 5                   | 40                   | To be retained      | Falling outside excavation line |
| 8   | 8        | Wad         | <i>Ficus benghalensis</i> | 16                  | 40                   | To be retained      | Falling outside excavation line |

|                      |          |
|----------------------|----------|
| Trees to be Retained | 4        |
| Trees to be removed  | 4        |
| <b>Total Trees</b>   | <b>8</b> |

**7. TREE INVENTORY DETAILS AT UGC-07**

| Summary of Tree Survey at Marol Station |          |                 |                                 |                     |                      |                     |                                    |
|---|----------|-----------------|---------------------------------|---------------------|----------------------|---------------------|------------------------------------|
| Sr. no.                                 | Tree no. | Common Name     | Botanical Name                  | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                             |
| 1                                       | 1        | Jambul          | <i>Syzygium cumini</i>          | 4                   | 30                   | To be removed       | Falling within excavation line     |
| 2                                       | 1A       | Deshi Badam     | <i>Terminalia catappa</i>       | 5                   | 25                   | To be Retain        | Falling outside of excavation line |
| 3                                       | 1B       | Naral           | <i>Cocos nucifera</i>           | 4                   | 35                   | To be Retain        | Falling outside of excavation line |
| 4                                       | 1 C      | Asupalav        | <i>Polyalthia longifolia</i>    | 1                   | 22                   | To be Retain        | Falling outside of excavation line |
| 5                                       | 1 D      | Naral           | <i>Cocos nucifera</i>           | 2                   | 23                   | To be Retain        | Falling outside of excavation line |
| 6                                       | 1E       | Naral           | <i>Cocos nucifera</i>           | 3                   | 35                   | To be removed       | Falling within excavation line     |
| 7                                       | 1F       | Naral           | <i>Cocos nucifera</i>           | 3                   | 35                   | To be removed       | Falling within excavation line     |
| 8                                       | 2        | Jambul          | <i>Syzygium cumini</i>          | 7                   | 30                   | To be removed       | Falling within excavation line     |
| 9                                       | 3        | Naral           | <i>Cocos nucifera</i>           | 6                   | 30                   | To be removed       | Falling within excavation line     |
| 10                                      | 4        | Deshi Badam     | <i>Terminalia catappa</i>       | 5                   | 30                   | To be removed       | Falling within excavation line     |
| 11                                      | 5        | Deshi Badam     | <i>Terminalia catappa</i>       | 2.5                 | 25                   | To be removed       | Falling within excavation line     |
| 12                                      | 6        | Naral           | <i>Cocos nucifera</i>           | 1                   | 10                   | To be removed       | Falling within excavation line     |
| 13                                      | 6A       | Asupalav        | <i>Polyalthia longifolia</i>    | 2                   | 20                   | To be removed       | Falling within excavation line     |
| 14                                      | 6B       | Asupalav        | <i>Polyalthia longifolia</i>    | 3                   | 20                   | To be removed       | Falling within excavation line     |
| 15                                      | 6C       | Singapur Cherry | dead                            | 1                   | 12                   | To be removed       | Falling within excavation line     |
| 16                                      | 6D       | Deshi Badam     | <i>Terminalia catappa</i>       | 3.5                 | 40                   | To be Retain        | Falling outside of excavation line |
| 17                                      | 6E       | Raan Chiku      | <i>Manilkara zapota</i>         | 2.5                 | 15                   | To be Retain        | Falling outside of excavation line |
| 18                                      | 6F       | Naral           | <i>Cocos nucifera</i>           | 2.5                 | 25                   | To be Retain        | Falling outside of excavation line |
| 19                                      | 6G       | Jambul          | <i>Syzygium cumini</i>          | 2                   | 25                   | To be removed       | Falling within excavation line     |
| 20                                      | 6H       | Jackfruit       | <i>Artocarpus heterophyllus</i> | 1                   | 25                   | To be removed       | Falling within excavation line     |
| 21                                      | 7        | Naral           | <i>Cocos nucifera</i>           | 5                   | 30                   | To be removed       | Falling within excavation line     |
| 22                                      | 7A       | Asupalav        | <i>Polyalthia longifolia</i>    | 2                   | 30                   | To be removed       | Falling within excavation line     |
| 23                                      | 7B       | Asupalav        | <i>Polyalthia longifolia</i>    | 2                   | 30                   | To be removed       | Falling within excavation line     |
| 24                                      | 8        | Pimpal          | <i>Ficus religiosa</i>          | 5                   | 30                   | To be removed       | Falling within excavation line     |
| 25                                      | 9        | Naral           | <i>Cocos nucifera</i>           | 4                   | 30                   | To be removed       | Falling within excavation line     |
| 26                                      | 9A       | Asupalav        | <i>Polyalthia longifolia</i>    | 2                   | 30                   | To be removed       | Falling within excavation line     |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |             |                                |     |    |               |                                    |
|----|-----|-------------|--------------------------------|-----|----|---------------|------------------------------------|
| 27 | 9B  | Mango       | <i>Mangifera indica</i>        | 1   | 20 | To be removed | Falling within excavation line     |
| 28 | 10  | Asupalav    | <i>Polyalthia longifolia</i>   | 2   | 20 | To be removed | Falling within excavation line     |
| 29 | 10A | Asupalav    | <i>Polyalthia longifolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line     |
| 30 | 11  | Pimpal      | <i>Ficus religiosa</i>         | 1   | 20 | To be removed | Falling within excavation line     |
| 31 | 12  | Naral       | <i>Cocos nucifera</i>          | 3   | 10 | To be removed | Falling within excavation line     |
| 32 | 12A | Deshi Badam | <i>Terminalia catappa</i>      | 2   | 25 | To be Retain  | Falling outside of excavation line |
| 33 | 12B | Peru        | <i>Citrus spp</i>              | 6"  | 8  | To be Retain  | Falling outside of excavation line |
| 34 | 12C | Sitaphal    | <i>Annona squamosa</i>         | 1   | 8  | To be Retain  | Falling outside of excavation line |
| 35 | 12D | Jambul      | <i>Syzygium cumini</i>         | 2   | 25 | To be Retain  | Falling outside of excavation line |
| 36 | 12E | Deshi Badam | <i>Terminalia catappa</i>      | 2   | 25 | To be Retain  | Falling outside of excavation line |
| 37 | 12F | Umber       | <i>Ficus glomerata</i>         | 2   | 30 | To be Retain  | Falling outside of excavation line |
| 38 | 12G | Mango       | <i>Mangifera Indica</i>        | 2   | 30 | To be removed | Falling within excavation line     |
| 39 | 13  | Mango       | <i>Mangifera Indica</i>        | 5   | 30 | To be removed | Falling within excavation line     |
| 40 | 14  | Pimpal      | <i>Ficus religiosa</i>         | 10  | 35 | To be removed | Falling within excavation line     |
| 41 | 15  | Pimpal      | <i>Ficus religiosa</i>         | 8   | 55 | To be removed | Falling within excavation line     |
| 42 | 15A | Sitaphal    | <i>Annona squamosa</i>         | 8"  | 15 | To be removed | Falling within excavation line     |
| 43 | 15B | Umber       | <i>Ficus glomerata</i>         | 3   | 30 | To be removed | Falling within excavation line     |
| 44 | 16  | Pimpal      | <i>Ficus religiosa</i>         | 4   | 36 | To be removed | Falling within excavation line     |
| 45 | 16A | Peru        | <i>Psidium gujava</i>          | 1   | 10 | To be removed | Falling within excavation line     |
| 46 | 16B | Phanas      | <i>Artocarpus hetrophyllus</i> | 2   | 23 | To be Retain  | Falling outside of excavation line |
| 47 | 17  | Asupalav    | <i>Polyalthia longifolia</i>   | 2   | 20 | To be removed | Falling within excavation line     |
| 48 | 18  | Pimpal      | <i>Ficus religiosa</i>         | 5   | 46 | To be Retain  | Falling outside of excavation line |
| 49 | 19  | Asupalav    | <i>Polyalthia longifolia</i>   | 7   | 59 | To be removed | Falling within excavation line     |
| 50 | 19A | Naral       | <i>Cocos nucifera</i>          | 2   | 23 | To be removed | Falling within excavation line     |
| 51 | 20  | Pimpal      | <i>Ficus religiosa</i>         | 8   | 46 | To be removed | Falling within excavation line     |
| 52 | 21  | Asupalav    | <i>Polyalthia longifolia</i>   | 4   | 52 | To be removed | Falling within excavation line     |
| 53 | 22  | Asupalav    | <i>Polyalthia longifolia</i>   | 4   | 46 | To be removed | Falling within excavation line     |
| 54 | 23  | Asupalav    | <i>Polyalthia longifolia</i>   | 4   | 43 | To be removed | Falling within excavation line     |
| 55 | 24  | Kaduneem    | <i>Azadirachta indica</i>      | 6"  | 10 | To be removed | Falling within excavation line     |
| 56 | 24A | Asupalav    | <i>Polyalthia longifolia</i>   | 6"  | 10 | To be removed | Falling within excavation line     |
| 57 | 25  | Pimpal      | <i>Ficus religiosa</i>         | 3   | 49 | To be removed | Falling within excavation line     |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |              |                                 |    |    |               |                                    |
|----|-----|--------------|---------------------------------|----|----|---------------|------------------------------------|
| 58 | 26  | Asupalav     | <i>Polyalthia longifolia</i>    | 6  | 56 | To be removed | Falling within excavation line     |
| 59 | 27  | Asupalav     | <i>Polyalthia longifolia</i>    | 1  | 13 | To be removed | Falling within excavation line     |
| 60 | 27A | Supari       | <i>Areca catechu</i>            | 8" | 10 | To be removed | Falling within excavation line     |
| 61 | 27B | Asupalav     | <i>Polyalthia longifolia</i>    | 6" | 8  | To be removed | Falling within excavation line     |
| 62 | 28  | Umber        | <i>Ficus glomerata</i>          | 3  | 33 | To be removed | Falling within excavation line     |
| 63 | 28A | Asupalav     | <i>Polyalthia longifolia</i>    | 6" | 12 | To be removed | Falling within excavation line     |
| 64 | 28B | Supari       | <i>Areca catechu</i>            | 8" | 12 | To be removed | Falling within excavation line     |
| 65 | 29  | Umber        | <i>Ficus glomerata</i>          | 2  | 30 | To be removed | Falling within excavation line     |
| 66 | 30  | Naral        | <i>Cocos nucifera</i>           | 3  | 59 | To be removed | Falling within excavation line     |
| 67 | 30A | Naral        | <i>Cocos nucifera</i>           | 3  | 59 | To be removed | Falling within excavation line     |
| 68 | 31  | Karanj       | <i>Pongamia pinnata</i>         | 3  | 40 | To be removed | Falling within excavation line     |
| 69 | 32  | Savar        | <i>Ceiba pentandra</i>          | 2  | 15 | To be removed | Falling within excavation line     |
| 70 | 32A | Bakul        | <i>Mimusops elengi</i>          | 4  | 50 | To be Retain  | Falling outside of excavation line |
| 71 | 32B | Naral        | <i>Cocos nucifera</i>           | 3  | 62 | To be Retain  | Falling outside of excavation line |
| 72 | 33  | Asupalav     | <i>Polyalthia longifolia</i>    | 1  | 23 | To be removed | Falling within excavation line     |
| 73 | 34  | Naral        | <i>Cocos nucifera</i>           | 3  | 33 | To be removed | Falling within excavation line     |
| 74 | 35  | Bael         | <i>Aegle marmelos</i>           | 2  | 20 | To be removed | Falling within excavation line     |
| 75 | 36  | Phanas       | <i>Artocarpus heterophyllus</i> | 1  | 20 | To be removed | Falling within excavation line     |
| 76 | 37  | Umber        | <i>Ficus glomerata</i>          | 4  | 30 | To be removed | Falling within excavation line     |
| 77 | 38  | Jungli badam | <i>Sterculia foetida</i>        | 3  | 40 | To be Retain  | Falling outside of excavation line |
| 78 | 38A | Desi badam   | <i>Terminalia cattapa</i>       | 3  | 36 | To be removed | Falling within excavation line     |
| 79 | 39  | Umber        | <i>Ficus glomerata</i>          | 4  | 35 | To be Retain  | Falling outside of excavation line |
| 80 | 40  | Asupalav     | <i>Polyalthia longifolia</i>    | 4  | 50 | To be removed | Falling within excavation line     |
| 81 | 41  | Rain Tree    | <i>Samanea saman</i>            | 3  | 40 | To be removed | Falling within excavation line     |
| 82 | 42  | Gulmohar     | <i>Delonix regia</i>            | 4  | 50 | To be removed | Falling within excavation line     |
| 83 | 43  | Dead         | -                               | 3  | 40 | To be removed | Falling within excavation line     |

**PART-II: TREE INVENTORY DETAILS**

**GENERAL CONSULTANT FOR MUMBAI METRO LINE 3**

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 19        |
| Trees to be removed  | 64        |
| <b>Total Trees</b>   | <b>83</b> |

| Summary of Tree Survey at MIDC Station |          |                    |                              |                     |                      |                     |                                 |
|--|----------|--------------------|------------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.                                | Tree no. | Common Name        | Botanical Name               | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1                                      | 1        | Shevar             | <i>Ceiba pentandra</i>       | 6                   | 22                   | To be removed       | Falling within excavation line  |
| 2                                      | 2        | Mango              | <i>Mangifera Indica</i>      | 2                   | 10                   | To be removed       | Falling within excavation line  |
| 3                                      | 3        | Jambul             | <i>Syzygium cumini</i>       | 1                   | 10                   | To be removed       | Falling within excavation line  |
| 4                                      | 4        | Asupalav           | <i>Polyalthia longifolia</i> | 2                   | 20                   | To be removed       | Falling within excavation line  |
| 5                                      | 5        | Indian Rubber tree | <i>Ficus elastica</i>        | 2                   | 20                   | To be removed       | Falling within excavation line  |
| 6                                      | 6        | Mango              | <i>Mangifera Indica</i>      | 6"                  | 10                   | To be retained      | Falling outside excavation line |
| 7                                      | 7        | Mango              | <i>Mangifera Indica</i>      | 9"                  | 10                   | To be retained      | Falling outside excavation line |
| 8                                      | 8        | Asupalav           | <i>Polyalthia longifolia</i> | 2                   | 22                   | To be retained      | Falling outside excavation line |
| 9                                      | 9        | Asupalav           | <i>Polyalthia longifolia</i> | 2                   | 25                   | To be removed       | Falling within excavation line  |
| 10                                     | 10       | Deshi Badam        | <i>Terminalia catappa</i>    | 1                   | 15                   | To be retained      | Falling outside excavation line |
| 11                                     | 11       | Karanj             | <i>Pongamia pinnata</i>      | 2                   | 25                   | To be removed       | Falling within excavation line  |
| 12                                     | 12       | Dead               | -                            | 9"                  | 10                   | To be removed       | Falling within excavation line  |
| 13                                     | 13       | Naral              | <i>Cocos nucifera</i>        | 3                   | 10                   | To be removed       | Falling within excavation line  |
| 14                                     | 14       | Naral              | <i>Cocos nucifera</i>        | 3                   | 10                   | To be removed       | Falling within excavation line  |
| 15                                     | 15       | Peru               | <i>Citrus spp</i>            | 1                   | 10                   | To be removed       | Falling within excavation line  |
| 16                                     | 16       | Naral              | <i>Cocos nucifera</i>        | 3                   | 10                   | To be removed       | Falling within excavation line  |
| 17                                     | 17       | Naral              | <i>Cocos nucifera</i>        | 3                   | 10                   | To be removed       | Falling within excavation line  |
| 18                                     | 18       | Asupalav           | <i>Polyalthia longifolia</i> | 1                   | 20                   | To be removed       | Falling within excavation line  |
| 19                                     | 19       | Asupalav           | <i>Polyalthia longifolia</i> | 2                   | 36                   | To be removed       | Falling within excavation line  |
| 20                                     | 20       | Neem               | <i>Azadirachta indica</i>    | 8"                  | 12                   | To be removed       | Falling within excavation line  |
| 21                                     | 21       | Asupalav           | <i>Polyalthia longifolia</i> | 1                   | 25                   | To be removed       | Falling within excavation line  |
| 22                                     | 21 A     | Bakneem            | <i>Melia azadirach</i>       | 4                   | 38                   | To be removed       | Falling within excavation line  |
| 23                                     | 21 B     | Subabul            | <i>Leucaena leucocephala</i> | 4                   | 35                   | To be removed       | Falling within excavation line  |
| 24                                     | 21 C     | Subabul            | <i>Leucaena leucocephala</i> | 3                   | 30                   | To be removed       | Falling within excavation line  |
| 25                                     | 21 D     | Subabul            | <i>Leucaena leucocephala</i> | 3                   | 30                   | To be removed       | Falling within excavation line  |
| 26                                     | 21 E     | Pimpal             | <i>Ficus religiosa</i>       | 2                   | 25                   | To be removed       | Falling within excavation line  |
| 27                                     | 21 F     | Amba               | <i>Mangifera Indica</i>      | 1                   | 20                   | To be removed       | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                    |                                 |     |    |                |                                 |
|----|-----|--------------------|---------------------------------|-----|----|----------------|---------------------------------|
| 28 | 22  | Asupalav           | <i>Polyalthia longifolia</i>    | 1   | 20 | To be removed  | Falling within excavation line  |
| 29 | 23  | Asupalav           | <i>Polyalthia longifolia</i>    | 2   | 25 | To be removed  | Falling within excavation line  |
| 30 | 23A | Asupalav           | <i>Polyalthia longifolia</i>    | 3   | 30 | To be removed  | Falling within excavation line  |
| 31 | 23B | Karanj             | <i>Pongamia pinnata</i>         | 4   | 35 | To be removed  | Falling within excavation line  |
| 32 | 24  | Mango              | <i>Mangifera indica</i>         | 3"  | 10 | To be removed  | Falling within excavation line  |
| 33 | 25  | Shewaga            | <i>Moringa oleifera</i>         | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 34 | 26  | Asupalav           | <i>Polyalthia longifolia</i>    | 2   | 25 | To be removed  | Falling within excavation line  |
| 35 | 27  | Asupalav           | <i>Polyalthia longifolia</i>    | 2   | 25 | To be removed  | Falling within excavation line  |
| 36 | 28  | Mango (Dead)       | <i>Mangifera indica</i>         | 2   | 20 | To be removed  | Falling within excavation line  |
| 37 | 29  | Asupalav           | <i>Polyalthia longifolia</i>    | 1   | 20 | To be removed  | Falling within excavation line  |
| 38 | 30  | Asupalav           | <i>Polyalthia longifolia</i>    | 1   | 30 | To be removed  | Falling within excavation line  |
| 39 | 31  | Gulmohar           | <i>Delonix regia</i>            | 3   | 25 | To be removed  | Falling within excavation line  |
| 40 | 32  | Gulmohar           | <i>Delonix regia</i>            | 3   | 25 | To be removed  | Falling within excavation line  |
| 41 | 32A | Mango              | <i>Mangifera indica</i>         | 6"  | 9  | To be removed  | Falling within excavation line  |
| 42 | 33  | Indian Rubber tree | <i>Ficus elastica</i>           | 3   | 30 | To be removed  | Falling within excavation line  |
| 43 | 34  | Desi Badam         | <i>Terminalia catappa</i>       | 3   | 30 | To be removed  | Falling within excavation line  |
| 44 | 35  | Asupalav           | <i>Polyalthia longifolia</i>    | 3   | 30 | To be removed  | Falling within excavation line  |
| 45 | 35A | Naral              | <i>Cocos nucifera</i>           | 3   | 30 | To be retained | Falling outside excavation line |
| 46 | 35B | Asupalav           | <i>Polyalthia longifolia</i>    | 2   | 30 | To be retained | Falling outside excavation line |
| 47 | 35C | Shewaga            | <i>Moringa oleifera</i>         | 2.5 | 20 | To be retained | Falling outside excavation line |
| 48 | 35D | Asupalav           | <i>Polyalthia longifolia</i>    | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 49 | 35E | Naral              | <i>Cocos nucifera</i>           | 2   | 30 | To be removed  | Falling within excavation line  |
| 50 | 35F | Jackfruit          | <i>Artocarpus heterophyllus</i> | 6"  | 18 | To be removed  | Falling within excavation line  |
| 51 | 35G | Asupalav           | <i>Polyalthia longifolia</i>    | 1   | 20 | To be removed  | Falling within excavation line  |
| 52 | 35H | Asupalav           | <i>Polyalthia longifolia</i>    | 2.5 | 30 | To be removed  | Falling within excavation line  |
| 53 | 35I | Supari             | <i>Areca catechu</i>            | 10" | 15 | To be removed  | Falling within excavation line  |
| 54 | 35J | Jamun              | <i>Syzygium cumini</i>          | 7"  | 12 | To be removed  | Falling within excavation line  |
| 55 | 35K | Jangali Tree       | <i>Jangali Tree</i>             | 6"  | 10 | To be removed  | Falling within excavation line  |
| 56 | 36  | Royal palm         | <i>Roystonea regia</i>          | 4   | 35 | To be removed  | Falling within excavation line  |
| 57 | 36A | Asupalav           | <i>Polyalthia longifolia</i>    | 2   | 12 | To be removed  | Falling within excavation line  |
| 58 | 36B | Lettuce tree       | <i>Pisonia alba</i>             | 1.5 | 3  | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                 |                              |     |    |               |                                |
|----|-----|-----------------|------------------------------|-----|----|---------------|--------------------------------|
| 59 | 36C | Asupalav        | <i>Polyalthia longifolia</i> | 1.5 | 12 | To be removed | Falling within excavation line |
| 60 | 36D | Asupalav        | <i>Polyalthia longifolia</i> | 2   | 12 | To be removed | Falling within excavation line |
| 61 | 37  | Asupalav        | <i>Polyalthia longifolia</i> | 4   | 30 | To be removed | Falling within excavation line |
| 62 | 38  | Asupalav        | <i>Polyalthia longifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 63 | 38A | Lettuce tree    | <i>Pisonia alba</i>          | 2   | 15 | To be removed | Falling within excavation line |
| 64 | 39  | Naral           | <i>Cocos nucifera</i>        | 3   | 10 | To be removed | Falling within excavation line |
| 65 | 40  | Naral           | <i>Cocos nucifera</i>        | 3   | 10 | To be removed | Falling within excavation line |
| 66 | 41  | Royal palm      | <i>Roystonea regia</i>       | 4   | 25 | To be removed | Falling within excavation line |
| 67 | 42  | Royal palm      | <i>Roystonea regia</i>       | 6   | 25 | To be removed | Falling within excavation line |
| 68 | 43  | Asupalav        | <i>Polyalthia longifolia</i> | 2   | 20 | To be removed | Falling within excavation line |
| 69 | 44  | Royal palm      | <i>Roystonea regia</i>       | 6   | 25 | To be removed | Falling within excavation line |
| 70 | 45  | Royal palm      | <i>Roystonea regia</i>       | 6   | 25 | To be removed | Falling within excavation line |
| 71 | 46  | Asupalav        | <i>Polyalthia longifolia</i> | 6   | 25 | To be removed | Falling within excavation line |
| 72 | 47  | Royal palm      | <i>Roystonea regia</i>       | 6   | 30 | To be removed | Falling within excavation line |
| 73 | 48  | Deshi Badam     | <i>Terminalia catappa</i>    | 2   | 25 | To be removed | Falling within excavation line |
| 74 | 49  | Son Chafa       | <i>Michelia champaca</i>     | 6"  | 12 | To be removed | Falling within excavation line |
| 75 | 50  | Asupalav        | <i>Polyalthia longifolia</i> | 1   | 20 | To be removed | Falling within excavation line |
| 76 | 51  | Asupalav        | <i>Polyalthia longifolia</i> | 1   | 25 | To be removed | Falling within excavation line |
| 77 | 52  | Asupalav        | <i>Polyalthia longifolia</i> | 1   | 15 | To be removed | Falling within excavation line |
| 78 | 53  | Asupalav        | <i>Polyalthia longifolia</i> | 1   | 20 | To be removed | Falling within excavation line |
| 79 | 54  | Asupalav        | <i>Polyalthia longifolia</i> | 2   | 25 | To be removed | Falling within excavation line |
| 80 | 55  | Nilgiri         | <i>Eucalyptus citridora</i>  | 10  | 35 | To be removed | Falling within excavation line |
| 81 | 56  | Naral           | <i>Cocos nucifera</i>        | 4   | 40 | To be removed | Falling within excavation line |
| 82 | 57  | Lettuce tree    | <i>Pisonia alba</i>          | 1   | 15 | To be removed | Falling within excavation line |
| 83 | 57A | Asupalav        | <i>Polyalthia longifolia</i> | 1   | 15 | To be removed | Falling within excavation line |
| 84 | 58  | Nilgiri         | <i>Eucalyptus citridora</i>  | 1   | 25 | To be removed | Falling within excavation line |
| 85 | 59  | Asupalav (Dead) | <i>Polyalthia longifolia</i> | 1   | 25 | To be removed | Falling within excavation line |
| 86 | 60  | Asupalav        | <i>Polyalthia longifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 87 | 61  | Nilgiri         | <i>Eucalyptus citridora</i>  | 10  | 35 | To be removed | Falling within excavation line |
| 88 | 62  | Bakneem         | <i>Melia azadirach</i>       | 3   | 20 | To be removed | Falling within excavation line |
| 89 | 63  | Asupalav        | <i>Polyalthia longifolia</i> | 9"  | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                 |                                 |    |     |                |                                 |
|-----|-----|-----------------|---------------------------------|----|-----|----------------|---------------------------------|
| 90  | 64  | Asupalav        | <i>Polyalthia longifolia</i>    | 2  | 25  | To be removed  | Falling within excavation line  |
| 91  | 64A | Chapha          | <i>Plumeria alba</i>            | 8" | 2.5 | To be removed  | Falling within excavation line  |
| 92  | 64B | Deshi badam     | <i>Terminalia cattapa</i>       | 6" | 13  | To be removed  | Falling within excavation line  |
| 93  | 64C | Asupalav        | <i>Polyalthia longifolia</i>    | 5" | 4   | To be removed  | Falling within excavation line  |
| 94  | 64D | Asupalav (Dead) | <i>Polyalthia longifolia</i>    | 5" | 3   | To be removed  | Falling within excavation line  |
| 95  | 64E | Deshi badam     | <i>Terminalia cattapa</i>       | 6" | 10  | To be removed  | Falling within excavation line  |
| 96  | 64F | Deshi badam     | <i>Terminalia cattapa</i>       | 1  | 15  | To be retained | Falling outside excavation line |
| 97  | 64G | Asupalav        | <i>Polyalthia longifolia</i>    | 6" | 17  | To be removed  | Falling within excavation line  |
| 98  | 64H | Asupalav        | <i>Polyalthia longifolia</i>    | 2  | 25  | To be removed  | Falling within excavation line  |
| 99  | 64I | Deshi badam     | <i>Terminalia cattapa</i>       | 1  | 15  | To be retained | Falling outside excavation line |
| 100 | 64J | Asupalav        | <i>Polyalthia longifolia</i>    | 2  | 25  | To be retained | Falling outside excavation line |
| 101 | 64K | Asupalav        | <i>Polyalthia longifolia</i>    | 2  | 25  | To be retained | Falling outside excavation line |
| 102 | 64L | Deshi badam     | <i>Terminalia cattapa</i>       | 1  | 15  | To be retained | Falling outside excavation line |
| 103 | 64M | Asupalav        | <i>Polyalthia longifolia</i>    | 2  | 25  | To be retained | Falling outside excavation line |
| 104 | 64N | Amba            | <i>Mangifera Indica</i>         | 1  | 15  | To be retained | Falling outside excavation line |
| 105 | 64O | Deshi badam     | <i>Terminalia cattapa</i>       | 1  | 25  | To be retained | Falling outside excavation line |
| 106 | 65  | Pimpal          | <i>Ficus religiosa</i>          | 8  | 30  | To be removed  | Falling within excavation line  |
| 107 | 66  | Pimpal          | <i>Ficus religiosa</i>          | 8  | 30  | To be removed  | Falling within excavation line  |
| 108 | 67  | Pimpal          | <i>Ficus religiosa</i>          | 10 | 30  | To be removed  | Falling within excavation line  |
| 109 | 68  | Asupalav        | <i>Polyalthia longifolia</i>    | 3  | 30  | To be removed  | Falling within excavation line  |
| 110 | 69  | Rain Tree       | <i>Samanea saman</i>            | 8  | 20  | To be removed  | Falling within excavation line  |
| 111 | 69A | Bakul           | <i>Mimusops elengi</i>          | 1  | 14  | To be removed  | Falling within excavation line  |
| 112 | 70  | Naral           | <i>Cocos nucifera</i>           | 8  | 15  | To be removed  | Falling within excavation line  |
| 113 | 71  | Mango           | <i>Mangifera indica</i>         | 1  | 10  | To be removed  | Falling within excavation line  |
| 114 | 72  | Sitaphal        | <i>Annona squamosa</i>          | 1  | 10  | To be removed  | Falling within excavation line  |
| 115 | 73  | Naral           | <i>Cocos nucifera</i>           | 6  | 30  | To be removed  | Falling within excavation line  |
| 116 | 74  | Naral           | <i>Cocos nucifera</i>           | 4  | 40  | To be removed  | Falling within excavation line  |
| 117 | 75  | Jackfruit       | <i>Artocarpus heterophyllus</i> | 4  | 30  | To be removed  | Falling within excavation line  |
| 118 | 76  | Jamun           | <i>Syzygium cumini</i>          | 3  | 30  | To be removed  | Falling within excavation line  |
| 119 | 77  | Peru            | <i>Psidium guajava</i>          | 1  | 10  | To be removed  | Falling within excavation line  |
| 120 | 78  | Naral           | <i>Cocos nucifera</i>           | 4  | 30  | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |             |                              |     |    |                |                                 |
|-----|-----|-------------|------------------------------|-----|----|----------------|---------------------------------|
| 121 | 79  | Peru        | <i>Psidium guajava</i>       | 9"  | 10 | To be removed  | Falling within excavation line  |
| 122 | 80  | Jamun       | <i>Syzygium cumini</i>       | 2   | 30 | To be removed  | Falling within excavation line  |
| 123 | 81  | Gulmohar    | <i>Delonix regia</i>         | 8   | 30 | To be removed  | Falling within excavation line  |
| 124 | 82  | Naral       | <i>Cocos nucifera</i>        | 5   | 40 | To be removed  | Falling within excavation line  |
| 125 | 83  | Naral       | <i>Cocos nucifera</i>        | 5   | 40 | To be removed  | Falling within excavation line  |
| 126 | 84  | Wad         | <i>Ficus Benghalensis</i>    | 2   | 25 | To be removed  | Falling within excavation line  |
| 127 | 85  | Neem        | <i>Azadirachta indica</i>    | 6"  | 10 | To be removed  | Falling within excavation line  |
| 128 | 86  | Umbar       | <i>Ficus racemosa</i>        | 3   | 30 | To be removed  | Falling within excavation line  |
| 129 | 87  | Umbar       | <i>Ficus racemosa</i>        | 6   | 30 | To be removed  | Falling within excavation line  |
| 130 | 88  | Naral       | <i>Cocos nucifera</i>        | 6   | 35 | To be removed  | Falling within excavation line  |
| 131 | 89  | Dead        |                              | 1   | 20 | To be removed  | Falling within excavation line  |
| 132 | 90  | Jamun       | <i>Syzygium cumini</i>       | 9"  | 10 | To be removed  | Falling within excavation line  |
| 133 | 91  | Jamun       | <i>Syzygium cumini</i>       | 3   | 30 | To be removed  | Falling within excavation line  |
| 134 | 92  | Deshi Badam | <i>Terminalia catappa</i>    | 8   | 30 | To be removed  | Falling within excavation line  |
| 135 | 93  | Naral       | <i>Cocos nucifera</i>        | 7   | 40 | To be removed  | Falling within excavation line  |
| 136 | 93A | Mango       | <i>Mangifera indica</i>      | 10  | 15 | To be removed  | Falling within excavation line  |
| 137 | 93B | Mango       | <i>Mangifera indica</i>      | 9   | 12 | To be removed  | Falling within excavation line  |
| 138 | 94  | Jamun       | <i>Syzygium cumini</i>       | 6   | 40 | To be removed  | Falling within excavation line  |
| 139 | 95  | Asupalav    | <i>Polyalthia longifolia</i> | 6"  | 12 | To be removed  | Falling within excavation line  |
| 140 | 96  | Naral       | <i>Cocos nucifera</i>        | 8   | 30 | To be removed  | Falling within excavation line  |
| 141 | 97  | Mango       | <i>Mangifera indica</i>      | 3   | 30 | To be removed  | Falling within excavation line  |
| 142 | 98  | Peru        | <i>Psidium guajava</i>       | 6"  | 10 | To be removed  | Falling within excavation line  |
| 143 | 99  | Mango       | <i>Mangifera indica</i>      | 4"  | 10 | To be removed  | Falling within excavation line  |
| 144 | 100 | Naral       | <i>Cocos nucifera</i>        | 3   | 10 | To be removed  | Falling within excavation line  |
| 145 | 101 | Jamun       | <i>Syzygium cumini</i>       | 4   | 35 | To be retained | Falling outside excavation line |
| 146 | 102 | Peru        | <i>Psidium guajava</i>       | 8"  | 12 | To be retained | Falling outside excavation line |
| 147 | 103 | Deshi Badam | <i>Terminalia catappa</i>    | 4   | 25 | To be retained | Falling outside excavation line |
| 148 | 104 | Royal Palm  | <i>Roystonea regia</i>       | 1.5 | 10 | To be retained | Falling outside excavation line |
| 149 | 105 | Sag         | <i>Tectona grandis</i>       | 8"  | 10 | To be retained | Falling outside excavation line |
| 150 | 106 | Shewaga     | <i>Moringa Oleifera</i>      | 4   | 25 | To be retained | Falling outside excavation line |
| 151 | 107 | Naral       | <i>Cocos nucifera</i>        | 3   | 10 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                  |                                 |     |    |                |                                 |
|-----|-----|------------------|---------------------------------|-----|----|----------------|---------------------------------|
| 152 | 108 | Naral            | <i>Cocos nucifera</i>           | 3   | 10 | To be retained | Falling outside excavation line |
| 153 | 109 | Naral            | <i>Cocos nucifera</i>           | 5   | 25 | To be retained | Falling outside excavation line |
| 154 | 110 | Royal Palm       | <i>Roystonea regia</i>          | 1   | 10 | To be retained | Falling outside excavation line |
| 155 | 111 | Mango            | <i>Mangifera indica</i>         | 9"  | 10 | To be retained | Falling outside excavation line |
| 156 | 112 | Chafa            | <i>Plumeria alba</i>            | 1   | 15 | To be retained | Falling outside excavation line |
| 157 | 113 | Singapore Cherry | <i>Muntingia calabura</i>       | 1   | 9  | To be retained | Falling outside excavation line |
| 158 | 114 | Jamun            | <i>Syzygium cumini</i>          | 5   | 30 | To be retained | Falling outside excavation line |
| 159 | 115 | Umbar            | <i>Ficus racemosa</i>           | 8   | 35 | To be retained | Falling outside excavation line |
| 160 | 116 | Bhend            | <i>Thespesia populnea</i>       | 4   | 25 | To be removed  | Falling within excavation line  |
| 161 | 117 | Desi Badam       | <i>Terminalia catappa</i>       | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 162 | 118 | Phanas           | <i>Artocarpus heterophyllus</i> | 9"  | 15 | To be removed  | Falling within excavation line  |
| 163 | 119 | Umbar            | <i>Ficus racemosa</i>           | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 164 | 120 | Mango            | <i>Mangifera indica</i>         | 3   | 30 | To be removed  | Falling within excavation line  |
| 165 | 121 | Gulmohar         | <i>Delonix regia</i>            | 4   | 25 | To be removed  | Falling within excavation line  |
| 166 | 122 | Gulmohar         | <i>Delonix regia</i>            | 5   | 25 | To be removed  | Falling within excavation line  |
| 167 | 123 | Rain Tree (Dead) | <i>Samanea saman</i>            | 7   | 10 | To be removed  | Falling within excavation line  |
| 168 | 124 | Desi Badam       | <i>Terminalia catappa</i>       | 3   | 20 | To be retained | Falling outside excavation line |
| 169 | 125 | Naral            | <i>Cocos nucifera</i>           | 6   | 35 | To be retained | Falling outside excavation line |
| 170 | 126 | Naral            | <i>Cocos nucifera</i>           | 7   | 40 | To be removed  | Falling within excavation line  |
| 171 | 127 | Desi Badam       | <i>Terminalia catappa</i>       | 8   | 35 | To be removed  | Falling within excavation line  |
| 172 | 128 | Desi Badam       | <i>Terminalia catappa</i>       | 4   | 45 | To be removed  | Falling within excavation line  |
| 173 | 129 | Amba             | <i>Mangifera indica</i>         | 8   | 30 | To be removed  | Falling within excavation line  |
| 174 | 130 | Pimpal           | <i>Ficus religiosa</i>          | 12  | 40 | To be removed  | Falling within excavation line  |
| 175 | 131 | Shevga           | <i>Moringa Oleifera</i>         | 2   | 30 | To be removed  | Falling within excavation line  |
| 176 | 132 | Desi Badam       | <i>Terminalia catappa</i>       | 2   | 35 | To be removed  | Falling within excavation line  |
| 177 | 133 | Desi Badam       | <i>Terminalia catappa</i>       | 5   | 35 | To be retained | Falling outside excavation line |
| 178 | 134 | Amba             | <i>Mangifera indica</i>         | 3   | 45 | To be retained | Falling outside excavation line |
| 179 | 135 | Desi Badam       | <i>Terminalia catappa</i>       | 3   | 30 | To be retained | Falling outside excavation line |
| 180 | 136 | Mango            | <i>Mangifera indica</i>         | 1   | 15 | To be retained | Falling outside excavation line |
| 181 | 137 | Vilayti Chinch   | <i>Pithecellobium dulce</i>     | 6   | 20 | To be retained | Falling outside excavation line |
| 182 | 138 | Jamun            | <i>Syzygium cumini</i>          | 4   | 30 | To be retained | Falling outside excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |              |                                |    |       |                |                                 |
|-----|-----|--------------|--------------------------------|----|-------|----------------|---------------------------------|
| 183 | 139 | Mango        | <i>Mangifera indica</i>        | 9" | 15    | To be retained | Falling outside excavation line |
| 184 | 140 | Mango        | <i>Mangifera indica</i>        | 9" | 10    | To be retained | Falling outside excavation line |
| 185 | 141 | Jamb         | <i>Syzygium samarangens</i>    | 6" | 10    | To be retained | Falling outside excavation line |
| 186 | 142 | Deshi Badam  | <i>Terminalia catappa</i>      | 5  | 25    | To be retained | Falling outside excavation line |
| 187 | 143 | Jamun        | <i>Syzygium Cumini</i>         | 3  | 25    | To be retained | Falling outside excavation line |
| 188 | 144 | Deshi Badam  | <i>Terminalia catappa</i>      | 4  | 25    | To be removed  | Falling within excavation line  |
| 189 | 145 | Kadamba      | <i>Neolemarckia cadamba</i>    | 3  | 19.68 | To be retained | Falling outside excavation line |
| 190 | 146 | Subabhul     | <i>Leucaena leucocephala</i>   | 3  | 16.4  | To be retained | Falling outside excavation line |
| 191 | 147 | Raintree     | <i>Samanea saman</i>           | 7  | 39.36 | To be retained | Falling outside excavation line |
| 192 | 148 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 6  | 32.8  | To be retained | Falling outside excavation line |
| 193 | 149 | Kaduneem     | <i>Azadirachta indica</i>      | 3  | 26.24 | To be retained | Falling outside excavation line |
| 194 | 150 | Naral        | <i>Cocos nucifera</i>          | 3  | 32.8  | To be retained | Falling outside excavation line |
| 195 | 151 | Sausage tree | <i>Kiegelia pinnata</i>        | 3  | 29.52 | To be retained | Falling outside excavation line |
| 196 | 152 | Sonmohar     | <i>Polyalthia longifolia</i>   | 1  | 32.8  | To be retained | Falling outside excavation line |
| 197 | 153 | Naral        | <i>Cocos nucifera</i>          | 3  | 32.8  | To be retained | Falling outside excavation line |
| 198 | 154 | Sausage tree | <i>Kiegelia pinnata</i>        | 2  | 29.52 | To be retained | Falling outside excavation line |
| 199 | 155 | Jambhul      | <i>Syzygium cumini</i>         | 2  | 13.12 | To be retained | Falling outside excavation line |
| 200 | 156 | Naral        | <i>Cocos nucifera</i>          | 2  | 32.8  | To be retained | Falling outside excavation line |
| 201 | 157 | Gulmohar     | <i>Delonix regia</i>           | 1  | 26.24 | To be retained | Falling outside excavation line |
| 202 | 158 | Lettuce tree | <i>Pisonia alba</i>            | 1  | 13.12 | To be retained | Falling outside excavation line |
| 203 | 159 | Deshi badam  | <i>Terminalia cattapa</i>      | 2  | 29.52 | To be retained | Falling outside excavation line |
| 204 | 160 | Asupalav     | <i>Polyalthia longifolia</i>   | 1  | 13.12 | To be retained | Falling outside excavation line |
| 205 | 161 | Rain tree    | <i>Samanea saman</i>           | 2  | 16    | To be removed  | Falling within excavation line  |
| 206 | 162 | Areca palm   | <i>Areca palm</i>              | 1  | 19.68 | To be retained | Falling outside excavation line |
| 207 | 163 | Areca palm   | <i>Areca palm</i>              | 2  | 19.68 | To be retained | Falling outside excavation line |
| 208 | 164 | Chapha       | <i>Plumeria alba</i>           | 4  | 22.96 | To be retained | Falling outside excavation line |
| 209 | 165 | Naral        | <i>Cocos nucifera</i>          | 3  | 36.08 | To be retained | Falling outside excavation line |
| 210 | 166 | Rain tree    | <i>Samanea saman</i>           | 4  | 49.2  | To be retained | Falling outside excavation line |
| 211 | 167 | Chapha       | <i>Plumeria alba</i>           | 2  | 13.12 | To be retained | Falling outside excavation line |
| 212 | 168 | Chapha       | <i>Plumeria alba</i>           | 2  | 13.12 | To be retained | Falling outside excavation line |
| 213 | 169 | Fan palm     | <i>Washingtonia filifera</i>   | 3  | 29.52 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                 |                                 |    |       |                |                                 |
|-----|-----|-----------------|---------------------------------|----|-------|----------------|---------------------------------|
| 214 | 170 | Lettuce tree    | <i>Pisonia alba</i>             | 2  | 13.12 | To be retained | Falling outside excavation line |
| 215 | 171 | Rain tree       | <i>Samanea saman</i>            | 18 | 39.36 | To be retained | Falling outside excavation line |
| 216 | 172 | Desi badam      | <i>Terminalia cattapa</i>       | 3  | 32.8  | To be retained | Falling outside excavation line |
| 217 | 173 | Pimpal          | <i>Ficus religiosa</i>          | 7  | 39.36 | To be retained | Falling outside excavation line |
| 218 | 174 | Shevga          | <i>Moringa oleifera</i>         | 3  | 16.4  | To be retained | Falling outside excavation line |
| 219 | 175 | Shevga          | <i>Moringa oleifera</i>         | 1  | 9.84  | To be retained | Falling outside excavation line |
| 220 | 176 | Umber           | <i>Ficus glomerata</i>          | 2  | 32.8  | To be retained | Falling outside excavation line |
| 221 | 177 | Pimpal          | <i>Ficus religiosa</i>          | 3  | 42.64 | To be retained | Falling outside excavation line |
| 222 | 178 | Pimpal          | <i>Ficus religiosa</i>          | 8  | 52.48 | To be retained | Falling outside excavation line |
| 223 | 179 | Amba            | <i>Mangifera indica</i>         | 2  | 22.96 | To be retained | Falling outside excavation line |
| 224 | 180 | Amba            | <i>Mangifera indica</i>         | 2  | 19.68 | To be retained | Falling outside excavation line |
| 225 | 181 | Pimpal          | <i>Ficus religiosa</i>          | 3  | 29.52 | To be retained | Falling outside excavation line |
| 226 | 182 | Pimpal          | <i>Ficus religiosa</i>          | 3  | 39.36 | To be retained | Falling outside excavation line |
| 227 | 183 | Wad             | <i>Ficus benghalensis</i>       | 10 | 32.8  | To be retained | Falling outside excavation line |
| 228 | 184 | Jambhul         | <i>Syzygium cumini</i>          | 1  | 16.4  | To be retained | Falling outside excavation line |
| 229 | 185 | Wad             | <i>Ficus benghalensis</i>       | 13 | 32.8  | To be retained | Falling outside excavation line |
| 230 | 186 | Wad             | <i>Ficus benghalensis</i>       | 10 | 32.8  | To be retained | Falling outside excavation line |
| 231 | 187 | Peru            | <i>Psidium gujava</i>           | 2  | 19.68 | To be retained | Falling outside excavation line |
| 232 | 188 | Wad             | <i>Ficus benghalensis</i>       | 10 | 26.24 | To be retained | Falling outside excavation line |
| 233 | 189 | Wad             | <i>Ficus benghalensis</i>       | 23 | 39.36 | To be retained | Falling outside excavation line |
| 234 | 190 | Pangara         | <i>Erythrina variegata</i>      | 10 | 32.8  | To be retained | Falling outside excavation line |
| 235 | 191 | Pimpal          | <i>Ficus religiosa</i>          | 25 | 36.08 | To be retained | Falling outside excavation line |
| 236 | 192 | Desi badam      | <i>Terminalia cattapa</i>       | 2  | 16.4  | To be retained | Falling outside excavation line |
| 237 | 193 | Wad             | <i>Ficus benghalensis</i>       | 3  | 16.4  | To be retained | Falling outside excavation line |
| 238 | 194 | Pimpal          | <i>Ficus religiosa</i>          | 7  | 29.52 | To be retained | Falling outside excavation line |
| 239 | 195 | Karanj          | <i>Pongamia pinnata</i>         | 4  | 39.36 | To be retained | Falling outside excavation line |
| 240 | 196 | Vilayati chinch | <i>Pithecellobium dulce</i>     | 8  | 32.8  | To be retained | Falling outside excavation line |
| 241 | 197 | Desi badam      | <i>Terminalia cattapa</i>       | 4  | 26.24 | To be retained | Falling outside excavation line |
| 242 | 198 | Naral           | <i>Cocos nucifera</i>           | 3  | 32.8  | To be retained | Falling outside excavation line |
| 243 | 199 | Jambhul         | <i>Syzygium cumini</i>          | 3  | 32.8  | To be retained | Falling outside excavation line |
| 244 | 200 | Phanas          | <i>Atrocarpus heterophyllus</i> | 2  | 22.96 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |             |                           |   |       |                |                                 |
|-----|-----|-------------|---------------------------|---|-------|----------------|---------------------------------|
| 245 | 201 | Supari      | <i>Areca catechu</i>      | 3 | 36.08 | To be retained | Falling outside excavation line |
| 246 | 202 | Peru        | <i>Psidium gujava</i>     | 2 | 13.12 | To be retained | Falling outside excavation line |
| 247 | 203 | Amba        | <i>Mangifera indica</i>   | 2 | 32.8  | To be retained | Falling outside excavation line |
| 248 | 204 | Naral       | <i>cocos nucifera</i>     | 3 | 32.8  | To be retained | Falling outside excavation line |
| 249 | 205 | Deshi badam | <i>Terminalia cattapa</i> | 2 | 22.96 | To be retained | Falling outside excavation line |
| 250 | 206 | Jambhul     | <i>Syzygium cumini</i>    | 2 | 26.24 | To be retained | Falling outside excavation line |
| 251 | 207 | Naral       | <i>Cocos nucifera</i>     | 3 | 32.8  | To be retained | Falling outside excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 105        |
| Trees to be removed  | 146        |
| <b>Total Trees</b>   | <b>251</b> |

| Summary of Tree Survey at SEEPZ Station |          |                |                              |                     |                      |                     |                                |
|---|----------|----------------|------------------------------|---------------------|----------------------|---------------------|--------------------------------|
| Sr. no.                                 | Tree no. | Common Name    | Botanical Name               | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                         |
| 1                                       | 1        | Deshi Badam    | <i>Terminalia catappa</i>    | 1                   | 20                   | To be removed       | Falling within excavation line |
| 2                                       | 2        | Jambhul        | <i>Syzygium cumini</i>       | 1                   | 18                   | To be removed       | Falling within excavation line |
| 3                                       | 3        | Naral          | <i>Cocos nucifera</i>        | 2                   | 15                   | To be removed       | Falling within excavation line |
| 4                                       | 4        | Jungli Badam   | <i>Sterculia foetida</i>     | 2                   | 20                   | To be removed       | Falling within excavation line |
| 5                                       | 4A       | Asupalav       | <i>Polyalthia longifolia</i> | 7"                  | 10                   | To be retained      | Falling within excavation line |
| 6                                       | 5        | Peru           | <i>Psidium guajava</i>       | 1                   | 20                   | To be removed       | Falling within excavation line |
| 7                                       | 6        | Naral          | <i>Cocos nucifera</i>        | 5                   | 40                   | To be removed       | Falling within excavation line |
| 8                                       | 7        | Shewaga        | <i>Moringa oleifera</i>      | 2                   | 10                   | To be removed       | Falling within excavation line |
| 9                                       | 8        | Deshi Badam    | <i>Terminalia catappa</i>    | 3                   | 30                   | To be removed       | Falling within excavation line |
| 10                                      | 9        | Peru           | <i>Psidium guajava</i>       | 8"                  | 15                   | To be removed       | Falling within excavation line |
| 11                                      | 10       | Naral          | <i>Cocos nucifera</i>        | 4                   | 20                   | To be removed       | Falling within excavation line |
| 12                                      | 11       | Naral          | <i>Cocos nucifera</i>        | 2                   | 10                   | To be removed       | Falling within excavation line |
| 13                                      | 12       | Naral          | <i>Cocos nucifera</i>        | 3                   | 15                   | To be removed       | Falling within excavation line |
| 14                                      | 13       | Deshi Badam    | <i>Terminalia catappa</i>    | 2                   | 25                   | To be removed       | Falling within excavation line |
| 15                                      | 14       | Charcoal       | <i>Trema orientalis</i>      | 8"                  | 20                   | To be removed       | Falling within excavation line |
| 16                                      | 15       | Date palm      | <i>Phoenix dactylifera</i>   | 2                   | 25                   | To be removed       | Falling within excavation line |
| 17                                      | 16       | Naral          | <i>Cocos nucifera</i>        | 2                   | 30                   | To be removed       | Falling within excavation line |
| 18                                      | 17       | Naral          | <i>Cocos nucifera</i>        | 2                   | 35                   | To be removed       | Falling within excavation line |
| 19                                      | 18       | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1                   | 13                   | To be removed       | Falling within excavation line |
| 20                                      | 18A      | Jamun          | <i>Syzygium cumini</i>       | 1                   | 20                   | To be removed       | Falling within excavation line |
| 21                                      | 19       | Peru           | <i>Psidium guajava</i>       | 8"                  | 8                    | To be removed       | Falling within excavation line |
| 22                                      | 20       | Shewaga        | <i>Moringa oleifera</i>      | 3                   | 23                   | To be removed       | Falling within excavation line |
| 23                                      | 21       | Amba           | <i>Mangifera indica</i>      | 1                   | 25                   | To be removed       | Falling within excavation line |
| 24                                      | 22       | Shewaga        | <i>Moringa oleifera</i>      | 1                   | 15                   | To be removed       | Falling within excavation line |
| 25                                      | 22A      | Asupalav       | <i>Polyalthia longifolia</i> | 1.312               | 26.24                | To be retained      | Falling within excavation line |
| 26                                      | 22B      | Naral          | <i>Cocos nucifera</i>        | 0.984               | 19.68                | To be retained      | Falling within excavation line |
| 27                                      | 23       | Pimpal         | <i>Ficus religiosa</i>       | 8"                  | 17                   | To be removed       | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |           |                                 |       |       |                |                                |
|----|-----|-----------|---------------------------------|-------|-------|----------------|--------------------------------|
| 28 | 23A | Asupalav  | <i>Polyalthia longifolia</i>    | 1.312 | 26.24 | To be retained | Falling within excavation line |
| 29 | 23B | Asupalav  | <i>Polyalthia longifolia</i>    | 1.64  | 29.52 | To be retained | Falling within excavation line |
| 30 | 24  | Naral     | <i>Cocos nucifera</i>           | 4     | 25    | To be removed  | Falling within excavation line |
| 31 | 24A | Asupalav  | <i>Polyalthia longifolia</i>    | 0.984 | 19.68 | To be removed  | Falling within excavation line |
| 32 | 24B | Asupalav  | <i>Polyalthia longifolia</i>    | 2     | 26    | To be removed  | Falling within excavation line |
| 33 | 24C | Naral     | <i>Cocos nucifera</i>           | 2     | 23    | To be removed  | Falling within excavation line |
| 34 | 24D | Asupalav  | <i>Polyalthia longifolia</i>    | 2     | 26    | To be removed  | Falling within excavation line |
| 35 | 24E | Asupalav  | <i>Polyalthia longifolia</i>    | 1     | 23    | To be removed  | Falling within excavation line |
| 36 | 25  | Phanas    | <i>Artocarpus heterophyllus</i> | 3     | 23    | To be removed  | Falling within excavation line |
| 37 | 25A | Asupalav  | <i>Polyalthia longifolia</i>    | 1     | 20    | To be removed  | Falling within excavation line |
| 38 | 26  | Phanas    | <i>Artocarpus heterophyllus</i> | 3     | 18    | To be removed  | Falling within excavation line |
| 39 | 26A | Asupalav  | <i>Polyalthia longifolia</i>    | 1     | 20    | To be retained | Falling within excavation line |
| 40 | 26B | Asupalav  | <i>Polyalthia longifolia</i>    | 1     | 20    | To be removed  | Falling within excavation line |
| 41 | 27  | Bakul     | <i>Mimusops elengi</i>          | 5     | 28    | To be removed  | Falling within excavation line |
| 42 | 28  | Amba      | <i>Mangifera indica</i>         | 8"    | 15    | To be removed  | Falling within excavation line |
| 43 | 29  | Peru      | <i>Psidium guajava</i>          | 1     | 10    | To be removed  | Falling within excavation line |
| 44 | 30  | Peru      | <i>Psidium guajava</i>          | 8"    | 8     | To be removed  | Falling within excavation line |
| 45 | 31  | Amba      | <i>Mangifera indica</i>         | 8"    | 8     | To be removed  | Falling within excavation line |
| 46 | 32  | Shewaga   | <i>Moringa oleifera</i>         | 1     | 7     | To be removed  | Falling within excavation line |
| 47 | 33  | Peru      | <i>Psidium guajava</i>          | 8"    | 10    | To be removed  | Falling within excavation line |
| 48 | 34  | Peru      | <i>Psidium guajava</i>          | 8"    | 10    | To be removed  | Falling within excavation line |
| 49 | 35  | Shewaga   | <i>Moringa oleifera</i>         | 1     | 13    | To be removed  | Falling within excavation line |
| 50 | 36  | Amba      | <i>Mangifera indica</i>         | 1     | 15    | To be removed  | Falling within excavation line |
| 51 | 37  | Amba      | <i>Mangifera indica</i>         | 8"    | 10    | To be removed  | Falling within excavation line |
| 52 | 38  | Shewaga   | <i>Moringa oleifera</i>         | 1     | 18    | To be removed  | Falling within excavation line |
| 53 | 39  | Naral     | <i>Cocos nucifera</i>           | 1     | 10    | To be removed  | Falling within excavation line |
| 54 | 40  | Amba      | <i>Mangifera indica</i>         | 8"    | 10    | To be removed  | Falling within excavation line |
| 55 | 41  | Amba      | <i>Mangifera indica</i>         | 1     | 14    | To be removed  | Falling within excavation line |
| 56 | 42  | Peru      | <i>Psidium guajava</i>          | 8"    | 12    | To be removed  | Falling within excavation line |
| 57 | 43  | Naral     | <i>Cocos nucifera</i>           | 3     | 15    | To be removed  | Falling within excavation line |
| 58 | 44  | Giripushp | <i>Gliricidia sepium</i>        | 2     | 15    | To be removed  | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |      |                 |                                 |    |    |                |                                |
|----|------|-----------------|---------------------------------|----|----|----------------|--------------------------------|
| 59 | 45   | Kala Umber      | <i>Ficus hispida</i>            | 2  | 15 | To be removed  | Falling within excavation line |
| 60 | 46   | Umber           | <i>Ficus racemosa</i>           | 2  | 25 | To be removed  | Falling within excavation line |
| 61 | 47   | Naral           | <i>Cocos nucifera</i>           | 3  | 10 | To be removed  | Falling within excavation line |
| 62 | 48   | Peru            | <i>Psidium guajava</i>          | 1  | 15 | To be removed  | Falling within excavation line |
| 63 | 49   | Subabul         | <i>Leucaena leucocephala</i>    | 1  | 25 | To be removed  | Falling within excavation line |
| 64 | 50   | Jambhul         | <i>Syzygium cumini</i>          | 3  | 30 | To be removed  | Falling within excavation line |
| 65 | 50A  | Vilayati Chinch | <i>Pithecellobium dulce</i>     | 2  | 20 | To be removed  | Falling within excavation line |
| 66 | 51   | Kakad           | <i>Garuga pinnata</i>           | 2  | 25 | To be removed  | Falling within excavation line |
| 67 | 52   | Deshi Badam     | <i>Terminalia catappa</i>       | 1  | 25 | To be removed  | Falling within excavation line |
| 68 | 52A  | Vilayati Chinch | <i>Pithecellobium dulce</i>     | 4  | 30 | To be removed  | Falling within excavation line |
| 69 | 52B  | Vilayati Chinch | <i>Pithecellobium dulce</i>     | 4  | 30 | To be removed  | Falling within excavation line |
| 70 | 53   | Bor             | <i>Zizyphus mauritiana</i>      | 1  | 18 | To be removed  | Falling within excavation line |
| 71 | 54   | Deshi Badam     | <i>Terminalia catappa</i>       | 2  | 25 | To be removed  | Falling within excavation line |
| 72 | 55   | Bhokar          | <i>Cordia dichotoma</i>         | 3  | 23 | To be removed  | Falling within excavation line |
| 73 | 56   | Amba            | <i>Mangifera indica</i>         | 1  | 13 | To be removed  | Falling within excavation line |
| 74 | 57   | Deshi Badam     | <i>Terminalia catappa</i>       | 1  | 20 | To be removed  | Falling within excavation line |
| 75 | 58   | Umber           | <i>Ficus racemosa</i>           | 1  | 15 | To be removed  | Falling within excavation line |
| 76 | 59   | Phanas          | <i>Artocarpus heterophyllus</i> | 8" | 17 | To be removed  | Falling within excavation line |
| 77 | 60   | Peru            | <i>Psidium guajava</i>          | 1  | 17 | To be removed  | Falling within excavation line |
| 78 | 61   | Shewaga         | <i>Moringa oleifera</i>         | 2  | 30 | To be removed  | Falling within excavation line |
| 79 | 62   | Naral           | <i>Cocos nucifera</i>           | 4  | 20 | To be removed  | Falling within excavation line |
| 80 | 63   | Deshi Badam     | <i>Terminalia catappa</i>       | 2  | 30 | To be removed  | Falling within excavation line |
| 81 | 63-A | Mango           | <i>Mangifera indica</i>         | 2  | 10 | To be removed  | Falling within excavation line |
| 82 | 63-B | Chinch          | <i>Tamarindus indica</i>        | 5  | 30 | To be removed  | Falling within excavation line |
| 83 | 63-C | Wad             | <i>Ficus bengalensis</i>        | 7  | 35 | To be removed  | Falling within excavation line |
| 84 | 63-D | Pimpal          | <i>Ficus religiosa</i>          | 7  | 35 | To be removed  | Falling within excavation line |
| 85 | 64   | Subabul         | <i>Leucaena leucocephala</i>    | 1  | 15 | To be removed  | Falling within excavation line |
| 86 | 64A  | Gulmohar        | <i>Delonix regia</i>            | 5  | 33 | To be removed  | Falling within excavation line |
| 87 | 64B  | Saptparni       | <i>Alstonia scholaris</i>       | 1  | 10 | To be removed  | Falling within excavation line |
| 88 | 64C  | Phanas          | <i>Artocarpus heterophyllus</i> | 4  | 30 | To be retained | Falling within excavation line |
| 89 | 65   | Peru            | <i>Psidium guajava</i>          | 1  | 20 | To be removed  | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |                  |             |                                |     |    |                |                                |
|-----|------------------|-------------|--------------------------------|-----|----|----------------|--------------------------------|
| 90  | 66               | Jambhul     | <i>Syzygium cumini</i>         | 2   | 30 | To be removed  | Falling within excavation line |
| 91  | 67               | Dead        | -                              | 8"  | 13 | To be removed  | Falling within excavation line |
| 92  | 67A              | Gulmohar    | <i>Delonix regia</i>           | 6   | 36 | To be retained | Falling within excavation line |
| 93  | 67B              | Lokhandi    | <i>Samadera indica</i>         | 1   | 13 | To be retained | Falling within excavation line |
| 94  | 68               | Deshi Badam | <i>Terminalia catappa</i>      | 2   | 20 | To be removed  | Falling within excavation line |
| 95  | 69               | Deshi Badam | <i>Terminalia catappa</i>      | 1   | 25 | To be removed  | Falling within excavation line |
| 96  | 69B              | Kashid      | <i>Cassia siamea</i>           | 2   | 26 | To be removed  | Falling within excavation line |
| 97  | 69A              | Suru        | <i>Chusquea</i>                | 3   | 30 | To be retained | Falling within excavation line |
| 98  | 69C              | Kashid      | <i>Cassia siamea</i>           | 2   | 23 | To be removed  | Falling within excavation line |
| 99  | 69D              | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3   | 30 | To be retained | Falling within excavation line |
| 100 | 69E              | Sonmohar    | <i>Peltophorum pterocarpum</i> | 4   | 30 | To be retained | Falling within excavation line |
| 101 | 70               | Katesavar   | <i>Bombax cieba</i>            | 3   | 25 | To be removed  | Falling within excavation line |
| 102 | 70A              | Chenduphul  |                                | 8   | 33 | To be removed  | Falling within excavation line |
| 103 | 70B              | Gulmohar    | <i>Delonix regia</i>           | 5   | 30 | To be removed  | Falling within excavation line |
| 104 | 70C              | Gulmohar    | <i>Delonix regia</i>           | 1   | 16 | To be removed  | Falling within excavation line |
| 105 | 71               | Kakad       | <i>Garuga pinnata</i>          | 1   | 20 | To be removed  | Falling within excavation line |
| 106 | 72               | Umber       | <i>Ficus racemosa</i>          | 7   | 25 | To be removed  | Falling within excavation line |
| 107 | 72-A(Near to 72) | Tad         | <i>Borassus flabellifer</i>    | 2   | 35 | To be removed  | Falling within excavation line |
| 108 | 72-B(Near to 72) | Asupalav    | <i>Polyalthia longifolia</i>   | 1.5 | 18 | To be removed  | Falling within excavation line |
| 109 | 72-C(Near to 72) | Sitaphal    | <i>Annona squamosa</i>         | 1   | 15 | To be removed  | Falling within excavation line |
| 110 | 72-D(Near to 72) | Asupalav    | <i>Polyalthia longifolia</i>   | 1.5 | 30 | To be removed  | Falling within excavation line |
| 111 | 73               | Amba        | <i>Mangifera indica</i>        | 8"  | 15 | To be removed  | Falling within excavation line |
| 112 | 74               | Subabul     | <i>Leucaena leucocephala</i>   | 8"  | 10 | To be removed  | Falling within excavation line |
| 113 | 75               | Deshi Badam | <i>Terminalia catappa</i>      | 2   | 15 | To be removed  | Falling within excavation line |
| 114 | 76               | Giripushp   | <i>Gliricidia sepium</i>       | 1   | 10 | To be removed  | Falling within excavation line |
| 115 | 77               | Giripushp   | <i>Gliricidia sepium</i>       | 1   | 15 | To be retained | Falling within excavation line |
| 116 | 78               | Giripushp   | <i>Gliricidia sepium</i>       | 1   | 15 | To be retained | Falling within excavation line |
| 117 | 79               | Bor         | <i>Zizyphus mauritiana</i>     | 1   | 15 | To be retained | Falling within excavation line |
| 118 | 80               | Giripushp   | <i>Gliricidia sepium</i>       | 1   | 15 | To be retained | Falling within excavation line |
| 119 | 81               | Giripushp   | <i>Gliricidia sepium</i>       | 1   | 15 | To be retained | Falling within excavation line |
| 120 | 82               | Giripushp   | <i>Gliricidia sepium</i>       | 1   | 15 | To be retained | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                 |                              |    |    |                |                                |
|-----|-----|-----------------|------------------------------|----|----|----------------|--------------------------------|
| 121 | 83  | Giripushp       | <i>Gliricidia sepium</i>     | 1  | 15 | To be retained | Falling within excavation line |
| 122 | 84  | Giripushp       | <i>Gliricidia sepium</i>     | 1  | 15 | To be retained | Falling within excavation line |
| 123 | 85  | Subabul         | <i>Leucaena leucocephala</i> | 1  | 15 | To be retained | Falling within excavation line |
| 124 | 86  | Apta            | <i>Bauhinia racemosa</i>     | 1  | 15 | To be retained | Falling within excavation line |
| 125 | 87  | Apta            | <i>Bauhinia racemosa</i>     | 8" | 12 | To be retained | Falling within excavation line |
| 126 | 88  | Umber           | <i>Ficus racemosa</i>        | 2  | 23 | To be retained | Falling within excavation line |
| 127 | 89  | Singapur Cherry | <i>Muntingia calabura</i>    | 8" | 15 | To be retained | Falling within excavation line |
| 128 | 90  | Naral           | <i>Cocos nucifera</i>        | 3  | 30 | To be retained | Falling within excavation line |
| 129 | 91  | Naral           | <i>Cocos nucifera</i>        | 2  | 20 | To be retained | Falling within excavation line |
| 130 | 92  | Pichkari        | <i>Spathodea campanulata</i> | 2  | 25 | To be retained | Falling within excavation line |
| 131 | 93  | Supari          | <i>Areca catechu</i>         | 1  | 23 | To be retained | Falling within excavation line |
| 132 | 94  | Chinch          | <i>Tamarindus indica</i>     | 4  | 25 | To be retained | Falling within excavation line |
| 133 | 95  | Naral           | <i>Cocos nucifera</i>        | 2  | 15 | To be retained | Falling within excavation line |
| 134 | 96  | Deshi Badam     | <i>Terminalia catappa</i>    | 2  | 30 | To be retained | Falling within excavation line |
| 135 | 97  | Jambhul         | <i>Syzygium cumini</i>       | 8" | 20 | To be retained | Falling within excavation line |
| 136 | 98  | Dead            | -                            | 8" | 15 | To be retained | Falling within excavation line |
| 137 | 99  | Naral           | <i>Cocos nucifera</i>        | 2  | 20 | To be retained | Falling within excavation line |
| 138 | 100 | Bhend           | <i>Thespesia populnea</i>    | 2  | 25 | To be retained | Falling within excavation line |
| 139 | 101 | Bhend           | <i>Thespesia populnea</i>    | 8" | 15 | To be retained | Falling within excavation line |
| 140 | 102 | Bhend           | <i>Thespesia populnea</i>    | 2  | 20 | To be retained | Falling within excavation line |
| 141 | 103 | Shewaga         | <i>Moringa oleifera</i>      | 1  | 18 | To be retained | Falling within excavation line |
| 142 | 104 | Peru            | <i>Psidium guajava</i>       | 8" | 20 | To be retained | Falling within excavation line |
| 143 | 105 | Bhend           | <i>Thespesia populnea</i>    | 1  | 15 | To be retained | Falling within excavation line |
| 144 | 106 | Karanj          | <i>Pongamia pinnata</i>      | 8" | 20 | To be retained | Falling within excavation line |
| 145 | 107 | Subabul         | <i>Leucaena leucocephala</i> | 8" | 15 | To be retained | Falling within excavation line |
| 146 | 108 | Subabul         | <i>Leucaena leucocephala</i> | 1  | 25 | To be retained | Falling within excavation line |
| 147 | 109 | Peru            | <i>Psidium guajava</i>       | 8" | 20 | To be retained | Falling within excavation line |
| 148 | 110 | Subabul         | <i>Leucaena leucocephala</i> | 1  | 27 | To be retained | Falling within excavation line |
| 149 | 111 | Deshi Badam     | <i>Terminalia catappa</i>    | 1  | 10 | To be retained | Falling within excavation line |
| 150 | 112 | Umber           | <i>Ficus racemosa</i>        | 1  | 25 | To be retained | Falling within excavation line |
| 151 | 113 | Giripushp       | <i>Gliricidia sepium</i>     | 1  | 15 | To be retained | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                |                                 |     |      |                |                                |
|-----|------|----------------|---------------------------------|-----|------|----------------|--------------------------------|
| 152 | 114  | Giripushp      | <i>Gliricidia sepium</i>        | 1   | 15   | To be retained | Falling within excavation line |
| 153 | 115  | Bhend          | <i>Thespesia populnea</i>       | 1   | 15   | To be removed  | Falling within excavation line |
| 154 | 116  | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 1   | 15   | To be removed  | Falling within excavation line |
| 155 | 117  | Bhend          | <i>Thespesia populnea</i>       | 1   | 10   | To be retained | Falling within excavation line |
| 156 | 118  | Deshi Badam    | <i>Terminalia catappa</i>       | 1   | 25   | To be retained | Falling within excavation line |
| 157 | 119  | Peru           | <i>Psidium guajava</i>          | 8"  | 18   | To be retained | Falling within excavation line |
| 158 | 120  | Bhend          | <i>Thespesia populnea</i>       | 2   | 15   | To be retained | Falling within excavation line |
| 159 | 120A | Mango          | <i>Mangifera indica</i>         | 1   | 8    | To be retained | Falling within excavation line |
| 160 | 121  | Amba           | <i>Mangifera indica</i>         | 8"  | 10   | To be retained | Falling within excavation line |
| 161 | 122  | Bhend          | <i>Thespesia populnea</i>       | 1   | 10   | To be retained | Falling within excavation line |
| 162 | 123  | Amba           | <i>Mangifera indica</i>         | 1   | 18   | To be retained | Falling within excavation line |
| 163 | 124  | Bhend          | <i>Thespesia populnea</i>       | 8"  | 10   | To be removed  | Falling within excavation line |
| 164 | 125  | Bhend          | <i>Thespesia populnea</i>       | 8"  | 10   | To be retained | Falling within excavation line |
| 165 | 126  | Deshi Badam    | <i>Terminalia catappa</i>       | 2   | 30   | To be retained | Falling within excavation line |
| 166 | 127  | Umber          | <i>Ficus racemosa</i>           | 2   | 25   | To be retained | Falling within excavation line |
| 167 | 127A | Asupalav       | <i>Polyalthia longifolia</i>    | 3   | 26   | To be retained | Falling within excavation line |
| 168 | 128  | Kakad          | <i>Garuga pinnata</i>           | 4   | 25   | To be retained | Falling within excavation line |
| 169 | 129  | Kakad          | <i>Garuga pinnata</i>           | 3   | 25   | To be removed  | Falling within excavation line |
| 170 | 130  | Naral          | <i>Cocos nucifera</i>           | 3   | 35   | To be retained | Falling within excavation line |
| 171 | 131  | Peru           | <i>Psidium guajava</i>          | 8"  | 20   | To be removed  | Falling within excavation line |
| 172 | 132  | Kaduneem       | <i>Azadirachta indica</i>       | 8"  | 15   | To be retained | Falling within excavation line |
| 173 | 133  | Naral          | <i>Cocos nucifera</i>           | 2   | 15   | To be retained | Falling within excavation line |
| 174 | 134  | Phanas         | <i>Artocarpus heterophyllus</i> | 1   | 15   | To be retained | Falling within excavation line |
| 175 | 135  | Pimpal         | <i>Ficus religiosa</i>          | 10  | 30   | To be retained | Falling within excavation line |
| 176 | 136  | Kakad          | <i>Garuga pinnata</i>           | 3   | 30   | To be retained | Falling within excavation line |
| 177 | 137  | Chinch         | <i>Tamarindus indica</i>        | 3   | 25   | To be retained | Falling within excavation line |
| 178 | 138  | Chafa          | <i>Plumeria alba</i>            | 1   | 20   | To be retained | Falling within excavation line |
| 179 | 139  | Bhend          | <i>Thespesia populnea</i>       | 1   | 15   | To be retained | Falling within excavation line |
| 180 | 140  | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 3   | 20   | To be retained | Falling within excavation line |
| 181 | 141  | Deshi Badam    | <i>Terminalia catappa</i>       | 2   | 25   | To be retained | Falling within excavation line |
| 182 | 142  | Umbar          | <i>Ficus racemosa</i>           | 7.9 | 26.2 | To be retained | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                   |                               |     |      |                |                                |
|-----|------|-------------------|-------------------------------|-----|------|----------------|--------------------------------|
| 183 | 143  | Amba              | <i>Mangifera indica</i>       | 2.0 | 19.7 | To be retained | Falling within excavation line |
| 184 | 144  | Asupalav          | <i>Polyalthia longifolia</i>  | 4.0 | 32.8 | To be retained | Falling within excavation line |
| 185 | 145  | Asupalav          | <i>Polyalthia longifolia</i>  | 3.9 | 29.5 | To be retained | Falling within excavation line |
| 186 | 146  | Asupalav          | <i>Polyalthia longifolia</i>  | 1.7 | 26.2 | To be retained | Falling within excavation line |
| 187 | 147  | Asupalav          | <i>Polyalthia longifolia</i>  | 3.0 | 32.8 | To be retained | Falling within excavation line |
| 188 | 148  | Asupalav          | <i>Polyalthia longifolia</i>  | 4.2 | 29.5 | To be retained | Falling within excavation line |
| 189 | 149  | Asupalav          | <i>Polyalthia longifolia</i>  | 3.9 | 32.8 | To be retained | Falling within excavation line |
| 190 | 150  | Katesavar         | <i>Bombax cieba</i>           | 3.6 | 26.2 | To be removed  | Falling within excavation line |
| 191 | 151  | Khirni            | <i>Manilkara hexandra</i>     | 4.8 | 29.5 | To be removed  | Falling within excavation line |
| 192 | 152  | Amba              | <i>Mangifera indica</i>       | 0.6 | 9.8  | To be retained | Falling within excavation line |
| 193 | 153  | Kaju              | <i>Anacardium occidentale</i> | 3.0 | 19.7 | To be retained | Falling within excavation line |
| 194 | 154  | Katesavar         | <i>Bombax cieba</i>           | 3.5 | 26.2 | To be retained | Falling within excavation line |
| 195 | 155  | Lettuce tree      | <i>Pisonia alba</i>           | 7"  | 6.6  | To be retained | Falling within excavation line |
| 196 | 156  | Pichkari          | <i>Spathodia campanulata</i>  | 5.4 | 29.5 | To be retained | Falling within excavation line |
| 197 | 157  | Amba              | <i>Mangifera indica</i>       | 4.5 | 26.2 | To be retained | Falling within excavation line |
| 198 | 158  | Asupalav          | <i>Polyalthia longifolia</i>  | 3.9 | 29.5 | To be retained | Falling within excavation line |
| 199 | 158A | Chinch            | <i>Tamarindus indica</i>      | 5.2 | 32.8 | To be retained | Falling within excavation line |
| 200 | 159  | Chinch            | <i>Tamarindus indica</i>      | 5.0 | 26.2 | To be retained | Falling within excavation line |
| 201 | 160  | Chinch            | <i>Tamarindus indica</i>      | 5.0 | 26.0 | To be removed  | Falling within excavation line |
| 202 | 161  | Umber             | <i>Ficus racemosa</i>         | 4.0 | 26.0 | To be removed  | Falling within excavation line |
| 203 | 162  | Asupalav          | <i>Polyalthia longifolia</i>  | 1.0 | 20.0 | To be removed  | Falling within excavation line |
| 204 | 163  | Asupalav          | <i>Polyalthia longifolia</i>  | 1.0 | 23.0 | To be removed  | Falling within excavation line |
| 205 | 164  | Asupalav          | <i>Polyalthia longifolia</i>  | 2.0 | 30.0 | To be removed  | Falling within excavation line |
| 206 | 165  | Asupalav          | <i>Polyalthia longifolia</i>  | 1.0 | 30.0 | To be removed  | Falling within excavation line |
| 207 | 166  | Dhaman            | <i>tiliifolia</i>             | 1.0 | 20.0 | To be removed  | Falling within excavation line |
| 208 | 167  | Gulmohar          | <i>Delonix regia</i>          | 2.6 | 39.4 | To be retained | Falling within excavation line |
| 209 | 168  | Kashid            | <i>Cassia siamea</i>          | 3.9 | 42.6 | To be retained | Falling within excavation line |
| 210 | 169  | Rain tree         | <i>Samanea saman</i>          | 4.4 | 45.9 | To be retained | Falling within excavation line |
| 211 | 170  | Wad               | <i>Ficus benghalensis</i>     | 7   | 39   | To be removed  | Falling within excavation line |
| 212 | 171  | Australian babool |                               | 3   | 43   | To be removed  | Falling within excavation line |
| 213 | 172  | Naral             | <i>Cocos nucifera</i>         | 1   | 26   | To be removed  | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                |     |      |                |                                |
|-----|-----|---------------|--------------------------------|-----|------|----------------|--------------------------------|
| 214 | 173 | Shewaga       | <i>Moringa oleifera</i>        | 3   | 26   | To be removed  | Falling within excavation line |
| 215 | 174 | Kala Umber    | <i>Ficus racemosa</i>          | 1   | 21   | To be removed  | Falling within excavation line |
| 216 | 175 | Amba          | <i>Mangifera indica</i>        | 3   | 20   | To be removed  | Falling within excavation line |
| 217 | 176 | Jamun         | <i>Syzygium cumini</i>         | 5   | 43   | To be removed  | Falling within excavation line |
| 218 | 177 | Saptparni     | <i>Alstonia scholaris</i>      | 18  | 21   | To be removed  | Falling within excavation line |
| 219 | 178 | Charcoal tree | <i>Trema orientalis</i>        | 1   | 8    | To be removed  | Falling within excavation line |
| 220 | 179 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 3.3 | 32.8 | To be retained | Falling within excavation line |
| 221 | 180 | Rain tree     | <i>Samanea saman</i>           | 7.0 | 52.0 | To be removed  | Falling within excavation line |
| 222 | 181 | Rain tree     | <i>Samanea saman</i>           | 8.0 | 56.0 | To be removed  | Falling within excavation line |
| 223 | 182 | Gulmohar      | <i>Delonix regia</i>           | 3.0 | 30.0 | To be removed  | Falling within excavation line |
| 224 | 183 | Gulmohar      | <i>Delonix regia</i>           | 3.0 | 30.0 | To be removed  | Falling within excavation line |
| 225 | 184 | Raan chiku    |                                | 1.0 | 20.0 | To be removed  | Falling within excavation line |
| 226 | 185 | Dhaman        | <i>Grewia tilifolia</i>        | 1.0 | 19.7 | To be retained | Falling within excavation line |
| 227 | 186 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 1.3 | 36.1 | To be retained | Falling within excavation line |
| 228 | 187 | Amba          | <i>Mangifera indica</i>        | 2.0 | 39.4 | To be retained | Falling within excavation line |
| 229 | 188 | Rain tree     | <i>Samanea saman</i>           | 4.9 | 42.6 | To be retained | Falling within excavation line |
| 230 | 189 | Taad          | <i>Borassus flabellifer</i>    | 3.0 | 39.4 | To be retained | Falling within excavation line |
| 231 | 190 | Asupalav      | <i>Polyalthia longifolia</i>   | 1   | 23   | To be removed  | Falling within excavation line |
| 232 | 191 | Asupalav      | <i>Polyalthia longifolia</i>   | 2   | 33   | To be removed  | Falling within excavation line |
| 233 | 192 | Naral         | <i>Cocos nucifera</i>          | 1   | 16   | To be removed  | Falling within excavation line |
| 234 | 193 | Naral         | <i>Cocos nucifera</i>          | 1   | 13   | To be removed  | Falling within excavation line |
| 235 | 194 | Asupalav      | <i>Polyalthia longifolia</i>   | 1   | 33   | To be removed  | Falling within excavation line |
| 236 | 195 | Asupalav      | <i>Polyalthia longifolia</i>   | 1   | 30   | To be removed  | Falling within excavation line |
| 237 | 196 | Asupalav      | <i>Polyalthia longifolia</i>   | 1   | 26   | To be removed  | Falling within excavation line |
| 238 | 197 | Asupalav      | <i>Polyalthia longifolia</i>   | 1   | 26   | To be removed  | Falling within excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 100        |
| Trees to be removed  | 138        |
| <b>Total Trees</b>   | <b>238</b> |

| Summary of Tree Survey at Ramp Area, Sariput Nagar |          |                |                                 |                     |                      |                     |                                |
|--|----------|----------------|---------------------------------|---------------------|----------------------|---------------------|--------------------------------|
| Sr. no.  | Tree no. | Common Name    | Botanical Name                  | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                         |
| 1  | 1        | Naral          | <i>Cocos nucifera</i>           | 3-4                 | 20-25                | To be Removed       | Falling within excavation line |
| 2  | 1 A      | Jambhul        | <i>Syzygium cumini</i>          | 1-2                 | 10-15                | To be Removed       | Falling within excavation line |
| 3  | 1 B      | Desi Badam     | <i>Terminalia catappa</i>       | 1-2                 | 15-20                | To be Removed       | Falling within excavation line |
| 4  | 1 C      | Naral          | <i>Cocos nucifera</i>           | 2-3                 | 10-15                | To be Removed       | Falling within excavation line |
| 5  | 2        | Peru           | <i>Psidium guajava</i>          | 7"-1                | 10-15                | To be Removed       | Falling within excavation line |
| 6  | 3        | Kala Umber     | <i>bombax ceiba</i>             | 7"-1                | 10-15                | To be Removed       | Falling within excavation line |
| 7  | 4        | Rain Tree      | <i>Samanea saman</i>            | 7"-1                | 10-15                | To be Removed       | Falling within excavation line |
| 8  | 5        | Umber          | <i>Ficus racemosa</i>           | 7"-1                | 10-12                | To be Removed       | Falling within excavation line |
| 9  | 6        | Phanas         | <i>Artocarpus heterophyllus</i> | 7"-1                | 10-15                | To be Removed       | Falling within excavation line |
| 10   | 7        | Kala Umber     | <i>Ficus hispida</i>            | 7"-1                | 10-15                | To be Removed       | Falling within excavation line |
| 11   | 8        | Desi Badam     | <i>Terminalia catappa</i>       | 1-2                 | 15-20                | To be Removed       | Falling within excavation line |
| 12   | 9        | Desi Badam     | <i>Terminalia catappa</i>       | 1-2                 | 15-20                | To be Removed       | Falling within excavation line |
| 13   | 10       | Rai awala      | <i>Phyllanthus emblica</i>      | 1-2                 | 20-25                | To be Removed       | Falling within excavation line |
| 14   | 11       | Ramphal        | <i>Annona reticulata</i>        | 1-2                 | 15-20                | To be Removed       | Falling within excavation line |
| 15   | 12       | Peru           | <i>Psidium guajava</i>          | 7"-1                | 10-12                | To be Removed       | Falling within excavation line |
| 16   | 13       | Naral          | <i>Cocos nucifera</i>           | 2-3                 | 25-30                | To be Removed       | Falling within excavation line |
| 17   | 14       | Desi Badam     | <i>Terminalia catappa</i>       | 3-4                 | 25-30                | To be Removed       | Falling within excavation line |
| 18   | 15       | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 5-6                 | 25-30                | To be Removed       | Falling within excavation line |
| 19   | 16       | Jambhul        | <i>Syzygium cumini</i>          | 5-6                 | 30-35                | To be Removed       | Falling within excavation line |
| 20   | 17       | Jambhul        | <i>Syzygium cumini</i>          | 3-4                 | 30-35                | To be Removed       | Falling within excavation line |
| 21   | 18       | Peru           | <i>Psidium guajava</i>          | 1-2                 | 10-12                | To be Removed       | Falling within excavation line |
| 22   | 19       | Desi Badam     | <i>Terminalia catappa</i>       | 1-2                 | 10-15                | To be Removed       | Falling within excavation line |
| 23   | 20       | Naral          | <i>Cocos nucifera</i>           | 3-4                 | 20-25                | To be Removed       | Falling within excavation line |
| 24   | 21       | Jangli Badam   | <i>Sterculia foetida Inn</i>    | 5-6                 | 25-30                | To be Removed       | Falling within excavation line |
| 25   | 22       | Desi Badam     | <i>Terminalia catappa</i>       | 1-2                 | 15-20                | To be Removed       | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |      |                |                                 |      |       |               |                                |
|----|------|----------------|---------------------------------|------|-------|---------------|--------------------------------|
| 26 | 23   | Shemat         | <i>Lannea coromandelica</i>     | 5-6  | 25-30 | To be Removed | Falling within excavation line |
| 27 | 23-A | Pimpal         | <i>Ficus religiosa</i>          | 3-4  | 30-35 | To be Removed | Falling within excavation line |
| 28 | 23-B | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 1-2  | 18-22 | To be Removed | Falling within excavation line |
| 29 | 24   | Desi Badam     | <i>Terminalia catappa</i>       | 2-3  | 20-25 | To be Removed | Falling within excavation line |
| 30 | 25   | Kakad          | <i>Garuga pinnata</i>           | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 31 | 26   | Tad            | <i>Borassus flabellifer</i>     | 2-3  | 25-30 | To be Removed | Falling within excavation line |
| 32 | 27   | Peru           | <i>Psidium guajava</i>          | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 33 | 28   | Kakad          | <i>Garuga pinnata</i>           | 2-3  | 15-20 | To be Removed | Falling within excavation line |
| 34 | 29   | Desi Badam     | <i>Terminalia catappa</i>       | 1-2  | 20-25 | To be Removed | Falling within excavation line |
| 35 | 30   | Peru           | <i>Psidium guajava</i>          | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 36 | 31   | Shewga         | <i>Moringa oleifera</i>         | 2-3  | 20-30 | To be Removed | Falling within excavation line |
| 37 | 32   | Naral          | <i>Cocos nucifera</i>           | 4-5  | 15-20 | To be Removed | Falling within excavation line |
| 38 | 33   | Umber          | <i>Ficus racemosa</i>           | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 39 | 34   | Bor            | <i>Zizyphus mauritiana</i>      | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 40 | 35   | Desi Badam     | <i>Terminalia catappa</i>       | 1-2  | 20-25 | To be Removed | Falling within excavation line |
| 41 | 36   | Bhokar         | <i>Cordia dichotoma</i>         | 1-2  | 20-25 | To be Removed | Falling within excavation line |
| 42 | 37   | Desi Badam     | <i>Terminalia catappa</i>       | 2-3  | 25-30 | To be Removed | Falling within excavation line |
| 43 | 38   | Phanas         | <i>Artocarpus heterophyllus</i> | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 44 | 39   | Amba           | <i>Mangifera indica</i>         | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 45 | 40   | Umber          | <i>Ficus racemosa</i>           | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 46 | 41   | Umber          | <i>Ficus racemosa</i>           | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 47 | 42   | Pimpal         | <i>Ficus religiosa</i>          | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 48 | 43   | Umber          | <i>Ficus racemosa</i>           | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 49 | 44   | Umber          | <i>Ficus racemosa</i>           | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 50 | 45   | Naral (Dead)   | <i>Cocos nucifera</i>           | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 51 | 46   | Shewga         | <i>Moringa oleifera</i>         | 2-3  | 10-15 | To be Removed | Falling within excavation line |
| 52 | 47   | Desi Badam     | <i>Terminalia catappa</i>       | 2-3  | 25-30 | To be Removed | Falling within excavation line |
| 53 | 48   | Desi Badam     | <i>Terminalia catappa</i>       | 1-2  | 20-25 | To be Removed | Falling within excavation line |
| 54 | 49   | Desi Badam     | <i>Terminalia catappa</i>       | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 55 | 50   | Naral          | <i>Cocos nucifera</i>           | 2-3  | 20-25 | To be Removed | Falling within excavation line |
| 56 | 51   | Peru           | <i>Psidium guajava</i>          | 7"-1 | 10-12 | To be Removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |                      |                              |      |       |               |                                 |
|----|----|----------------------|------------------------------|------|-------|---------------|---------------------------------|
| 57 | 52 | Naral                | <i>Cocos nucifera</i>        | 3-4  | 25-30 | To be Removed | Falling within excavation line  |
| 58 | 53 | Naral                | <i>Cocos nucifera</i>        | 2-3  | 10-15 | To be Removed | Falling within excavation line  |
| 59 | 54 | Deshi Badam          | <i>Terminalia catappa</i>    | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 60 | 55 | Deshi Badam          | <i>Terminalia catappa</i>    | 1-2  | 20-25 | To be Removed | Falling within excavation line  |
| 61 | 56 | Kate Savar           | <i>Bombax ceiba</i>          | 2-3  | 25-35 | To be Removed | Falling within excavation line  |
| 62 | 57 | Chinch               | <i>Tamarindus indica</i>     | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 63 | 58 | Charcoal Tree (Dead) | <i>Trema orientalis</i>      | 1-2  | 20-25 | To be Removed | Falling within excavation line  |
| 64 | 59 | Amba                 | <i>Mangifera indica</i>      | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 65 | 60 | Subabul              | <i>Leucaena leucocephala</i> | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 66 | 61 | Subabul              | <i>Leucaena leucocephala</i> | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 67 | 62 | Limbu                | <i>Citrus limonium</i>       | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 68 | 63 | Bor                  | <i>Zizyphus mauritiana</i>   | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 69 | 64 | Giripushpa           | <i>Gliricidia sepium</i>     | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 70 | 65 | Vilayti Chinch       | <i>Pithecellobium dulce</i>  | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 71 | 66 | Giripushpa           | <i>Gliricidia sepium</i>     | 7"-1 | 15-20 | To be Removed | Falling within excavation line  |
| 72 | 67 | Giripushpa           | <i>Gliricidia sepium</i>     | 7"-1 | 15-20 | To be Removed | Falling within excavation line  |
| 73 | 68 | Giripushpa           | <i>Gliricidia sepium</i>     | 7"-1 | 15-20 | To be Removed | Falling within excavation line  |
| 74 | 69 | Subabul              | <i>Leucaena leucocephala</i> | 7"-1 | 15-20 | To be Removed | Falling within excavation line  |
| 75 | 70 | Giripushpa           | <i>Gliricidia sepium</i>     | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 76 | 71 | Giripushpa           | <i>Gliricidia sepium</i>     | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 77 | 72 | Deshi Badam          | <i>Terminalia catappa</i>    | 3-4  | 15-20 | To be Removed | Falling within excavation line  |
| 78 | 73 | Peru                 | <i>Psidium guajava</i>       | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 79 | 74 | Jambhul              | <i>Syzygium cumini</i>       | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 80 | 75 | Umber                | <i>Ficus racemosa</i>        | 2-3  | 15-20 | To be Removed | Falling within excavation line  |
| 81 | 76 | Naral                | <i>Cocos nucifera</i>        | 3-4  | 25-30 | To be Removed | Falling within excavation line  |
| 82 | 77 | Naral                | <i>Cocos nucifera</i>        | 3-4  | 25-30 | To be Removed | Falling within excavation line  |
| 83 | 78 | Umber                | <i>Ficus racemosa</i>        | 2-3  | 15-20 | To be Removed | Falling within excavation line  |
| 84 | 79 | Deshi Badam          | <i>Terminalia catappa</i>    | 2-3  | 25-30 | To be Removed | Falling within excavation line  |
| 85 | 80 | Kakad                | <i>Garuga pinnata</i>        | 5-6  | 25-30 | To be Retaine | Falling outside excavation line |
| 86 | 81 | Pimpal               | <i>Ficus religiosa</i>       | 1-2  | 10-15 | To be Retaine | Falling outside excavation line |
| 87 | 82 | Umber                | <i>Ficus racemosa</i>        | 1-2  | 10-15 | To be Retaine | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |              |                                 |      |       |               |                                 |
|-----|-----|--------------|---------------------------------|------|-------|---------------|---------------------------------|
| 88  | 83  | Pimpal       | <i>Ficus religiosa</i>          | 1-2  | 15-20 | To be Retaine | Falling outside excavation line |
| 89  | 84  | Kakad        | <i>Garuga pinnata</i>           | 4-5  | 25-30 | To be Retaine | Falling outside excavation line |
| 90  | 85  | Naral        | <i>Cocos nucifera</i>           | 2-3  | 30-35 | To be Retaine | Falling outside excavation line |
| 91  | 86  | Naral        | <i>Cocos nucifera</i>           | 2-3  | 20-25 | To be Retaine | Falling outside excavation line |
| 92  | 87  | Phanas       | <i>Artocarpus heterophyllus</i> | 1-2  | 10-12 | To be Retaine | Falling outside excavation line |
| 93  | 88  | Kaduneem     | <i>Azadirachta indica</i>       | 7"-1 | 10-12 | To be Removed | Falling within excavation line  |
| 94  | 89  | Pimpal       | <i>Ficus religiosa</i>          | 5-6  | 15-18 | To be Retaine | Falling outside excavation line |
| 95  | 90  | Chinch       | <i>Tamarindus indica</i>        | 2-3  | 25-30 | To be Retaine | Falling outside excavation line |
| 96  | 91  | Supari       | <i>Areca catechu</i>            | 7"-1 | 15-20 | To be Removed | Falling within excavation line  |
| 97  | 92  | Kakad        | <i>Garuga pinnata</i>           | 3-4  | 15-20 | To be Removed | Falling within excavation line  |
| 98  | 93  | Naral        | <i>Cocos nucifera</i>           | 2-3  | 20-25 | To be Removed | Falling within excavation line  |
| 99  | 94  | Limbu (Dead) | <i>Citrus limonium</i>          | 7"-1 | 10-12 | To be Removed | Falling within excavation line  |
| 100 | 95  | Jambhul      | <i>Syzygium cumini</i>          | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 101 | 96  | Subabul      | <i>Leucaena leucocephala</i>    | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 102 | 97  | Peru         | <i>Psidium guajava</i>          | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 103 | 98  | Bhend        | <i>Cordia dichotoma</i>         | 7"-1 | 12-15 | To be Removed | Falling within excavation line  |
| 104 | 99  | Shewga       | <i>Moringa oleifera</i>         | 2-3  | 25-30 | To be Removed | Falling within excavation line  |
| 105 | 100 | Bhend        | <i>Cordia dichotoma</i>         | 1-2  | 25-30 | To be Removed | Falling within excavation line  |
| 106 | 101 | Apta         | <i>Cordia dichotoma</i>         | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 107 | 102 | Bhend        | <i>Cordia dichotoma</i>         | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 108 | 103 | Bhend        | <i>Cordia dichotoma</i>         | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 109 | 104 | Bor          | <i>Zizyphus mauritiana</i>      | 7"-1 | 10-12 | To be Removed | Falling within excavation line  |
| 110 | 105 | Tuti         | <i>Morus alba</i>               | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 111 | 106 | Shewga       | <i>Moringa oleifera</i>         | 1-2  | 10-12 | To be Removed | Falling within excavation line  |
| 112 | 107 | Bhend        | <i>Cordia dichotoma</i>         | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 113 | 108 | Bhend        | <i>Cordia dichotoma</i>         | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 114 | 109 | Bhend        | <i>Cordia dichotoma</i>         | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 115 | 110 | Tuti         | <i>Morus alba</i>               | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 116 | 111 | Peru         | <i>Psidium guajava</i>          | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 117 | 112 | Naral        | <i>Cocos nucifera</i>           | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 118 | 113 | Chafa        | <i>Plumeria alba</i>            | 1-2  | 15-20 | To be Retaine | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                 |      |       |               |                                 |
|-----|-----|----------------|---------------------------------|------|-------|---------------|---------------------------------|
| 119 | 114 | Chinch         | <i>Tamarindus indica</i>        | 2-3  | 25-30 | To be Retaine | Falling outside excavation line |
| 120 | 115 | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 2-3  | 10-15 | To be Removed | Falling within excavation line  |
| 121 | 116 | Deshi Badam    | <i>Terminalia catappa</i>       | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 122 | 117 | Deshi Badam    | <i>Terminalia catappa</i>       | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 123 | 118 | Kadamb         | <i>Neolamarckia cadamba</i>     | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 124 | 119 | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 7"-1 | 10-12 | To be Removed | Falling within excavation line  |
| 125 | 120 | Bhend          | <i>Cordia dichotoma</i>         | 7"-1 | 10-12 | To be Removed | Falling within excavation line  |
| 126 | 121 | Bhend          | <i>Cordia dichotoma</i>         | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 127 | 122 | Peru           | <i>Psidium guajava</i>          | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 128 | 123 | Peru           | <i>Psidium guajava</i>          | 1-2  | 10-12 | To be Removed | Falling within excavation line  |
| 129 | 124 | Amba           | <i>Cordia dichotoma</i>         | 1-2  | 10-12 | To be Removed | Falling within excavation line  |
| 130 | 125 | Peru           | <i>Psidium guajava</i>          | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 131 | 126 | Bhend          | <i>Cordia dichotoma</i>         | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 132 | 127 | Amba           | <i>Cordia dichotoma</i>         | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 133 | 128 | Bhend          | <i>Cordia dichotoma</i>         | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 134 | 129 | Bhend          | <i>Cordia dichotoma</i>         | 1-2  | 10-12 | To be Removed | Falling within excavation line  |
| 135 | 130 | Bhend          | <i>Cordia dichotoma</i>         | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 136 | 131 | Bhend          | <i>Cordia dichotoma</i>         | 1-2  | 10-15 | To be Retaine | Falling outside excavation line |
| 137 | 132 | Shemat         | <i>Lannea coromandelica</i>     | 3-4  | 20-25 | To be Retaine | Falling outside excavation line |
| 138 | 133 | Deshi Badam    | <i>Terminalia catappa</i>       | 3-4  | 25-30 | To be Removed | Falling within excavation line  |
| 139 | 134 | Giripushpa     | <i>Gliricidia sepium</i>        | 3-4  | 25-30 | To be Removed | Falling within excavation line  |
| 140 | 135 | Deshi Badam    | <i>Terminalia catappa</i>       | 1-2  | 20-25 | To be Removed | Falling within excavation line  |
| 141 | 136 | Deshi Badam    | <i>Terminalia catappa</i>       | 1-2  | 20-25 | To be Removed | Falling within excavation line  |
| 142 | 137 | Phanas         | <i>Artocarpus heterophyllus</i> | 7"-1 | 10-15 | To be Retaine | Falling outside excavation line |
| 143 | 138 | Naral          | <i>Cocos nucifera</i>           | 3-4  | 10-15 | To be Retaine | Falling outside excavation line |
| 144 | 139 | Vad            | <i>Ficus benghalensis</i>       | 2-3  | 15-20 | To be Retaine | Falling outside excavation line |
| 145 | 140 | Umber          | <i>Ficus racemosa</i>           | 3-5  | 15-20 | To be Retaine | Falling outside excavation line |
| 146 | 141 | Amba           | <i>Mangifera indica</i>         | 7"-1 | 10-15 | To be Retaine | Falling outside excavation line |
| 147 | 142 | Kaduneem       | <i>Azadirachta indica</i>       | 1-2  | 15-20 | To be Retaine | Falling outside excavation line |
| 148 | 143 | Deshi Badam    | <i>Terminalia catappa</i>       | 1-2  | 15-20 | To be Retaine | Falling outside excavation line |
| 149 | 144 | Subabul        | <i>Leucaena leucocephala</i>    | 1-2  | 15-20 | To be Retaine | Falling outside excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |       |                |                                 |      |       |               |                                 |
|-----|-------|----------------|---------------------------------|------|-------|---------------|---------------------------------|
| 150 | 145   | Amba           | <i>Mangifera indica</i>         | 7"-1 | 10-12 | To be Retaine | Falling outside excavation line |
| 151 | 146   | Peru           | <i>Psidium guajava</i>          | 7"-1 | 10-12 | To be Retaine | Falling outside excavation line |
| 152 | 147   | Phanas         | <i>Artocarpus heterophyllus</i> | 1-2  | 15-20 | To be Retaine | Falling outside excavation line |
| 153 | 148   | Jambhul        | <i>Syzygium cumini</i>          | 3-4  | 20-25 | To be Retaine | Falling outside excavation line |
| 154 | 149   | Shewga         | <i>Moringa oleifera</i>         | 1-2  | 15-20 | To be Retaine | Falling outside excavation line |
| 155 | 150   | Shewga         | <i>Moringa oleifera</i>         | 1-2  | 20-25 | To be Retaine | Falling outside excavation line |
| 156 | 151   | Shewga         | <i>Moringa oleifera</i>         | 1-2  | 15-20 | To be Retaine | Falling outside excavation line |
| 157 | 152   | Umber          | <i>Ficus racemosa</i>           | 1-2  | 20-25 | To be Retaine | Falling outside excavation line |
| 158 | 153   | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 159 | 154   | Deshi Badam    | <i>Terminalia catappa</i>       | 1-2  | 20-25 | To be Removed | Falling within excavation line  |
| 160 | 155   | Subabul        | <i>Leucaena leucocephala</i>    | 1-2  | 10-12 | To be Removed | Falling within excavation line  |
| 161 | 156   | Shewga         | <i>Moringa oleifera</i>         | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 162 | 157   | Sag            | <i>Tectona grandis</i>          | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 163 | 158   | Sag            | <i>Tectona grandis</i>          | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 164 | 159   | Subabul        | <i>Leucaena leucocephala</i>    | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 165 | 160   | Naral          | <i>Cocos nucifera</i>           | 2-3  | 10-12 | To be Removed | Falling within excavation line  |
| 166 | 161   | Amba           | <i>Mangifera indica</i>         | 7"-1 | 10-12 | To be Removed | Falling within excavation line  |
| 167 | 162   | Subabul        | <i>Leucaena leucocephala</i>    | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 168 | 163   | Naral          | <i>Cocos nucifera</i>           | 1-2  | 10-12 | To be Removed | Falling within excavation line  |
| 169 | 164   | Subabul        | <i>Leucaena leucocephala</i>    | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 170 | 165   | Pimpal         | <i>Ficus religiosa</i>          | 5-6  | 20-25 | To be Removed | Falling within excavation line  |
| 171 | 166   | Subabul        | <i>Leucaena leucocephala</i>    | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 172 | 166 A | Subabul        | <i>Leucaena leucocephala</i>    | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 173 | 167   | Subabul        | <i>Leucaena leucocephala</i>    | 1-2  | 15-20 | To be Removed | Falling within excavation line  |
| 174 | 168   | Kala Umber     | <i>Ficus hispida</i>            | 7"-1 | 10-12 | To be Removed | Falling within excavation line  |
| 175 | 169   | Rai awala      | <i>Phyllanthus emblica</i>      | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 176 | 170   | Peru           | <i>Psidium guajava</i>          | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 177 | 171   | Naral          | <i>Cocos nucifera</i>           | 1-2  | 10-12 | To be Removed | Falling within excavation line  |
| 178 | 172   | Subabul        | <i>Leucaena leucocephala</i>    | 7"-1 | 10-12 | To be Removed | Falling within excavation line  |
| 179 | 173   | Giripushpa     | <i>Gliricidia sepium</i>        | 7"-1 | 15-20 | To be Removed | Falling within excavation line  |
| 180 | 174   | Subabul        | <i>Leucaena leucocephala</i>    | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                 |      |       |               |                                |
|-----|-----|----------------|---------------------------------|------|-------|---------------|--------------------------------|
| 181 | 175 | Umber          | <i>Ficus racemosa</i>           | 2-3  | 25-30 | To be Removed | Falling within excavation line |
| 182 | 176 | Giripushpa     | <i>Gliricidia sepium</i>        | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 183 | 177 | Giripushpa     | <i>Gliricidia sepium</i>        | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 184 | 178 | Giripushpa     | <i>Gliricidia sepium</i>        | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 185 | 179 | Kala Umber     | <i>Ficus hispida</i>            | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 186 | 180 | Deshi Badam    | <i>Terminalia catappa</i>       | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 187 | 181 | Naral          | <i>Cocos nucifera</i>           | 2-3  | 10-12 | To be Removed | Falling within excavation line |
| 188 | 182 | Peru           | <i>Psidium guajava</i>          | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 189 | 183 | Amba           | <i>Mangifera indica</i>         | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 190 | 184 | Amba           | <i>Mangifera indica</i>         | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 191 | 185 | Shewga         | <i>Moringa oleifera</i>         | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 192 | 186 | Jambhul        | <i>Syzygium cumini</i>          | 5-6  | 25-30 | To be Removed | Falling within excavation line |
| 193 | 187 | Phanas         | <i>Artocarpus heterophyllus</i> | 2-3  | 15-20 | To be Removed | Falling within excavation line |
| 194 | 188 | Jambhul        | <i>Syzygium cumini</i>          | 3-4  | 30-35 | To be Removed | Falling within excavation line |
| 195 | 189 | Naral          | <i>Cocos nucifera</i>           | 4-5  | 25-30 | To be Removed | Falling within excavation line |
| 196 | 190 | Charcoal Tree  | <i>Trema orientalis</i>         | 7"-1 | 15-20 | To be Removed | Falling within excavation line |
| 197 | 191 | Amba           | <i>Mangifera indica</i>         | 2-3  | 25-30 | To be Removed | Falling within excavation line |
| 198 | 192 | Jambhul        | <i>Syzygium cumini</i>          | 3-4  | 25-30 | To be Removed | Falling within excavation line |
| 199 | 193 | Shewga         | <i>Moringa oleifera</i>         | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 200 | 194 | Pimpal         | <i>Ficus religiosa</i>          | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 201 | 195 | Amba           | <i>Mangifera indica</i>         | 7"-1 | 15-20 | To be Removed | Falling within excavation line |
| 202 | 196 | Shewga         | <i>Moringa oleifera</i>         | 3-4  | 25-30 | To be Removed | Falling within excavation line |
| 203 | 197 | Shewga         | <i>Moringa oleifera</i>         | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 204 | 198 | Peru           | <i>Psidium guajava</i>          | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 205 | 199 | Subabul        | <i>Leucaena leucocephala</i>    | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 206 | 200 | Peru           | <i>Psidium guajava</i>          | 7"-1 | 12-15 | To be Removed | Falling within excavation line |
| 207 | 201 | Shewga         | <i>Moringa oleifera</i>         | 2-3  | 20-25 | To be Removed | Falling within excavation line |
| 208 | 202 | Kala Umber     | <i>Ficus hispida</i>            | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 209 | 203 | Kakad          | <i>Garuga pinnata</i>           | 1-2  | 10-12 | To be Removed | Falling within excavation line |
| 210 | 204 | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 211 | 205 | Deshi Badam    | <i>Terminalia catappa</i>       | 1-2  | 10-15 | To be Removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |       |                |                                |      |       |               |                                |
|-----|-------|----------------|--------------------------------|------|-------|---------------|--------------------------------|
| 212 | 206   | Naral          | <i>Cocos nucifera</i>          | 2-3  | 25-30 | To be Removed | Falling within excavation line |
| 213 | 207   | Naral          | <i>Cocos nucifera</i>          | 2-3  | 25-30 | To be Removed | Falling within excavation line |
| 214 | 208   | Shindhi        | <i>Phoenix sylvestris</i>      | 2-3  | 15-20 | To be Removed | Falling within excavation line |
| 215 | 209   | Peru           | <i>Psidium guajava</i>         | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 216 | 210   | Peru           | <i>Psidium guajava</i>         | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 217 | 211   | Amba           | <i>Mangifera indica</i>        | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 218 | 212   | Peru           | <i>Psidium guajava</i>         | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 219 | 213   | Shewga         | <i>Moringa oleifera</i>        | 7"-1 | 15-20 | To be Removed | Falling within excavation line |
| 220 | 214   | Amba           | <i>Mangifera indica</i>        | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 221 | 215   | Peru           | <i>Psidium guajava</i>         | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 222 | 216   | Shewga         | <i>Moringa oleifera</i>        | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 223 | 217   | Subabul        | <i>Leucaena leucocephala</i>   | 1-2  | 20-25 | To be Removed | Falling within excavation line |
| 224 | 218   | Subabul        | <i>Leucaena leucocephala</i>   | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 225 | 219   | Amba           | <i>Mangifera indica</i>        | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 226 | 220   | Subabul        | <i>Leucaena leucocephala</i>   | 3-4  | 25-30 | To be Removed | Falling within excavation line |
| 227 | 221   | Vavla          | <i>holoptelea integrifolia</i> | 3-4  | 15-20 | To be Removed | Falling within excavation line |
| 228 | 222   | Giripushpa     | <i>Gliricidia sepium</i>       | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 229 | 223   | Subabul        | <i>Leucaena leucocephala</i>   | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 230 | 224   | Subabul        | <i>Leucaena leucocephala</i>   | 1-2  | 25-30 | To be Removed | Falling within excavation line |
| 231 | 225   | Subabul        | <i>Leucaena leucocephala</i>   | 7"-1 | 20-25 | To be Removed | Falling within excavation line |
| 232 | 226   | Giripushpa     | <i>Gliricidia sepium</i>       | 7"-1 | 15-20 | To be Removed | Falling within excavation line |
| 233 | 227   | Subabul        | <i>Leucaena leucocephala</i>   | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 234 | 228   | Amba           | <i>Mangifera indica</i>        | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 235 | 229   | Dhaman         | <i>Grewia tiliaefolia</i>      | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 236 | 230   | Charcoal Tree  | <i>Trema orientalis</i>        | 3-4  | 18-20 | To be Removed | Falling within excavation line |
| 237 | 230 A | Amba           | <i>Mangifera indica</i>        | 7"-1 | 12-15 | To be Removed | Falling within excavation line |
| 238 | 231   | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 5-6  | 25-30 | To be Removed | Falling within excavation line |
| 239 | 232   | Subabul        | <i>Leucaena leucocephala</i>   | 7"-1 | 15-20 | To be Removed | Falling within excavation line |
| 240 | 233   | Shemat         | <i>Lannea coromandelica</i>    | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 241 | 234   | Apta           | <i>Bauhinia racemosa</i>       | 3-4  | 25-30 | To be Removed | Falling within excavation line |
| 242 | 235   | karanj         | <i>Pongamia pinnata</i>        | 3-4  | 30-35 | To be Removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                               |      |       |               |                                |
|-----|-----|----------------|-------------------------------|------|-------|---------------|--------------------------------|
| 243 | 236 | Subabul        | <i>Leucaena leucocephala</i>  | 7"-1 | 15-20 | To be Removed | Falling within excavation line |
| 244 | 237 | Atrun          | <i>Flacourtia montana</i>     | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 245 | 238 | Subabul        | <i>Leucaena leucocephala</i>  | 1-2  | 10-12 | To be Removed | Falling within excavation line |
| 246 | 239 | Desi Badam     | <i>Terminalia catappa</i>     | 7"-1 | 10-12 | To be Removed | Falling within excavation line |
| 247 | 240 | Subabul (Dead) | <i>Leucaena leucocephala</i>  | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 248 | 241 | Kharoti        | <i>Streblus asper</i>         | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 249 | 242 | Giripushpa     | <i>Gliricidia sepium</i>      | 2-3  | 20-25 | To be Removed | Falling within excavation line |
| 250 | 243 | Shewga         | <i>Moringa oleifera</i>       | 2-3  | 15-20 | To be Removed | Falling within excavation line |
| 251 | 244 | Shemat         | <i>Lannea coromandelica</i>   | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 252 | 245 | Umber          | <i>Ficus racemosa</i>         | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 253 | 246 | Shewga         | <i>Moringa oleifera</i>       | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 254 | 247 | Shewga         | <i>Moringa oleifera</i>       | 7"-1 | 10-15 | To be Removed | Falling within excavation line |
| 255 | 248 | Kaju           | <i>Anacardium occidentale</i> | 2-3  | 15-20 | To be Removed | Falling within excavation line |
| 256 | 249 | Subabul        | <i>Leucaena leucocephala</i>  | 1-2  | 20-25 | To be Removed | Falling within excavation line |
| 257 | 250 | Tuti           | <i>Morus alba</i>             | 2-3  | 10-15 | To be Removed | Falling within excavation line |
| 258 | 251 | Subabul        | <i>Leucaena leucocephala</i>  | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 259 | 252 | Subabul        | <i>Leucaena leucocephala</i>  | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 260 | 253 | Giripushpa     | <i>Gliricidia sepium</i>      | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 261 | 254 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 262 | 255 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 263 | 256 | Asana          | <i>Pterocarpus marsupium</i>  | 2-3  | 20-25 | To be Removed | Falling within excavation line |
| 264 | 257 | Amba           | <i>Mangifera indica</i>       | 5-6  | 30-35 | To be Removed | Falling within excavation line |
| 265 | 258 | Amba           | <i>Mangifera indica</i>       | 1-2  | 10-15 | To be Removed | Falling within excavation line |
| 266 | 259 | Amba           | <i>Mangifera indica</i>       | 3-4  | 25-30 | To be Removed | Falling within excavation line |
| 267 | 260 | Naral          | <i>Cocos nucifera</i>         | 3-4  | 25-30 | To be Removed | Falling within excavation line |
| 268 | 261 | Naral          | <i>Cocos nucifera</i>         | 2-3  | 20-25 | To be Removed | Falling within excavation line |
| 269 | 262 | Shewga         | <i>Moringa oleifera</i>       | 1-2  | 15-20 | To be Removed | Falling within excavation line |
| 270 | 263 | Asupalav       | <i>Polyalthia langifolia</i>  | 3-4  | 35-40 | To be Removed | Falling within excavation line |
| 271 | 264 | Amba           | <i>Mangifera indica</i>       | 2-3  | 25-30 | To be Removed | Falling within excavation line |
| 272 | 265 | Amba           | <i>Mangifera indica</i>       | 3-4  | 15-20 | To be Removed | Falling within excavation line |
| 273 | 266 | Amba           | <i>Mangifera indica</i>       | 3-4  | 15-20 | To be Removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |             |                              |      |       |               |                                 |
|-----|-----|-------------|------------------------------|------|-------|---------------|---------------------------------|
| 274 | 267 | Desi Badam  | <i>Terminalia catappa</i>    | 3-4  | 25-30 | To be Removed | Falling within excavation line  |
| 275 | 268 | Desi Badam  | <i>Terminalia catappa</i>    | 3-4  | 15-20 | To be Removed | Falling within excavation line  |
| 276 | 269 | Amba        | <i>Mangifera indica</i>      | 3-4  | 15-20 | To be Removed | Falling within excavation line  |
| 277 | 270 | Amba        | <i>Mangifera indica</i>      | 3-4  | 15-20 | To be Removed | Falling within excavation line  |
| 278 | 271 | Amba        | <i>Mangifera indica</i>      | 3-4  | 15-20 | To be Removed | Falling within excavation line  |
| 279 | 272 | Dead        | -                            | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 280 | 273 | Amba        | <i>Mangifera indica</i>      | 3-4  | 20-25 | To be Removed | Falling within excavation line  |
| 281 | 274 | Amba        | <i>Mangifera indica</i>      | 7"-1 | 10-15 | To be Removed | Falling within excavation line  |
| 282 | 275 | Desi Badam  | <i>Terminalia catappa</i>    | 3-4  | 30-35 | To be Removed | Falling within excavation line  |
| 283 | 276 | Desi Badam  | <i>Terminalia catappa</i>    | 1-2  | 25-30 | To be Removed | Falling within excavation line  |
| 284 | 277 | Amba        | <i>Mangifera indica</i>      | 8-10 | 35-40 | To be Removed | Falling within excavation line  |
| 285 | 278 | Amba        | <i>Mangifera indica</i>      | 7-8  | 35-40 | To be Removed | Falling within excavation line  |
| 286 | 279 | Amba        | <i>Mangifera indica</i>      | 3-4  | 15-18 | To be Removed | Falling within excavation line  |
| 287 | 280 | Naral       | <i>Cocos nucifera</i>        | 3-4  | 35-40 | To be Removed | Falling within excavation line  |
| 288 | 281 | Naral       | <i>Cocos nucifera</i>        | 3-4  | 35-40 | To be Removed | Falling within excavation line  |
| 289 | 282 | Naral       | <i>Cocos nucifera</i>        | 3-4  | 35-40 | To be Removed | Falling within excavation line  |
| 290 | 283 | Amba        | <i>Mangifera indica</i>      | 6-7  | 35-40 | To be Removed | Falling within excavation line  |
| 291 | 284 | Fern Tree   | <i>Filicum decipiens</i>     | 3-4  | 15-20 | To be Removed | Falling within excavation line  |
| 292 | 285 | Fern Tree   | <i>Filicum decipiens</i>     | 3-4  | 10-15 | To be Removed | Falling within excavation line  |
| 293 | 286 | Amba        | <i>Mangifera indica</i>      | 7-8  | 35-40 | To be Removed | Falling within excavation line  |
| 294 | 287 | Jambhul     | <i>Syzygium cumini</i>       | 6-7  | 35-40 | To be Removed | Falling within excavation line  |
| 295 | 288 | Naral       | <i>Cocos nucifera</i>        | 3-4  | 10-15 | To be Removed | Falling within excavation line  |
| 296 | 289 | Amba (Dead) | <i>Mangifera indica</i>      | 4-5  | 10-15 | To be Removed | Falling within excavation line  |
| 297 | 290 | Amba        | <i>Mangifera indica</i>      | 4-5  | 25-30 | To be Removed | Falling within excavation line  |
| 298 | 291 | Amba        | <i>Mangifera indica</i>      | 8-9  | 40-45 | To be Removed | Falling within excavation line  |
| 299 | 292 | Subabul     | <i>Leucaena leucocephala</i> | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 300 | 293 | Subabul     | <i>Leucaena leucocephala</i> | 1-2  | 10-15 | To be Removed | Falling within excavation line  |
| 301 | 294 | Umber       | <i>Ficus racemosa</i>        | 1-2  | 10-12 | To be Retaine | Falling outside excavation line |
| 302 | 295 | Kala Umber  | <i>Ficus hispida</i>         | 1-2  | 10-15 | To be Retaine | Falling outside excavation line |
| 303 | 296 | Tuti        | <i>Morus alba</i>            | 1-2  | 10-12 | To be Retaine | Falling outside excavation line |
| 304 | 297 | Naral       | <i>Cocos nucifera</i>        | 3-4  | 30-35 | To be Retaine | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                               |     |       |               |                                 |
|-----|-----|----------------|-------------------------------|-----|-------|---------------|---------------------------------|
| 305 | 298 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 30-35 | To be Retaine | Falling outside excavation line |
| 306 | 299 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 30-35 | To be Retaine | Falling outside excavation line |
| 307 | 300 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 30-35 | To be Retaine | Falling outside excavation line |
| 308 | 301 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 30-35 | To be Retaine | Falling outside excavation line |
| 309 | 302 | Naral (Dead)   | <i>Cocos nucifera</i>         | 2-3 | 20-25 | To be Retaine | Falling outside excavation line |
| 310 | 303 | Naral          | <i>Cocos nucifera</i>         | 2-3 | 30-35 | To be Retaine | Falling outside excavation line |
| 311 | 304 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 30-35 | To be Retaine | Falling outside excavation line |
| 312 | 305 | Desi Badam     | <i>Terminalia catappa</i>     | 6-8 | 30-35 | To be Retaine | Falling outside excavation line |
| 313 | 306 | Amba           | <i>Mangifera indica</i>       | 1-2 | 10-15 | To be Retaine | Falling outside excavation line |
| 314 | 307 | Amba           | <i>Mangifera indica</i>       | 3-4 | 20-25 | To be Retaine | Falling outside excavation line |
| 315 | 308 | Tad            | <i>Borassus flabellifer</i>   | 4-5 | 30-35 | To be Retaine | Falling outside excavation line |
| 316 | 309 | Amba           | <i>Mangifera indica</i>       | 6-7 | 30-35 | To be Retaine | Falling outside excavation line |
| 317 | 310 | Amba           | <i>Mangifera indica</i>       | 4-5 | 20-25 | To be Retaine | Falling outside excavation line |
| 318 | 311 | Amba           | <i>Mangifera indica</i>       | 2-3 | 25-30 | To be Removed | Falling within excavation line  |
| 319 | 312 | Supari         | <i>Areca catechu</i>          | 1-2 | 10-15 | To be Removed | Falling within excavation line  |
| 320 | 313 | Desi Badam     | <i>Terminalia catappa</i>     | 3-5 | 35-40 | To be Removed | Falling within excavation line  |
| 321 | 314 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 3-4 | 20-25 | To be Removed | Falling within excavation line  |
| 322 | 315 | RanChiku       | <i>Diospyros embryopteris</i> | 3-4 | 25-30 | To be Removed | Falling within excavation line  |
| 323 | 316 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 35-40 | To be Removed | Falling within excavation line  |
| 324 | 317 | Amba           | <i>Mangifera indica</i>       | 7-9 | 35-40 | To be Removed | Falling within excavation line  |
| 325 | 318 | Amba           | <i>Mangifera indica</i>       | 7-9 | 35-40 | To be Removed | Falling within excavation line  |
| 326 | 319 | Naral          | <i>Cocos nucifera</i>         | 4-5 | 35-40 | To be Removed | Falling within excavation line  |
| 327 | 320 | Naral (Dead)   | <i>Cocos nucifera</i>         | 3-4 | 30-35 | To be Removed | Falling within excavation line  |
| 328 | 321 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 20-25 | To be Removed | Falling within excavation line  |
| 329 | 322 | Desi Badam     | <i>Terminalia catappa</i>     | 4-5 | 30-35 | To be Removed | Falling within excavation line  |
| 330 | 323 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 5-6 | 20-25 | To be Removed | Falling within excavation line  |
| 331 | 324 | Amba           | <i>Mangifera indica</i>       | 6-8 | 30-35 | To be Removed | Falling within excavation line  |
| 332 | 325 | Asupalav       | <i>Polyalthia langifolia</i>  | 1-2 | 15-20 | To be Removed | Falling within excavation line  |
| 333 | 326 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 40-45 | To be Removed | Falling within excavation line  |
| 334 | 327 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 35-40 | To be Removed | Falling within excavation line  |
| 335 | 328 | Naral          | <i>Cocos nucifera</i>         | 3-4 | 35-40 | To be Removed | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                 |       |       |               |                                |
|-----|-----|---------------|---------------------------------|-------|-------|---------------|--------------------------------|
| 336 | 329 | Naral         | <i>Cocos nucifera</i>           | 3-4   | 25-30 | To be Removed | Falling within excavation line |
| 337 | 330 | Naral         | <i>Cocos nucifera</i>           | 3-4   | 35-40 | To be Removed | Falling within excavation line |
| 338 | 331 | Naral         | <i>Cocos nucifera</i>           | 3-4   | 35-40 | To be Removed | Falling within excavation line |
| 339 | 332 | Naral         | <i>Cocos nucifera</i>           | 3-4   | 35-40 | To be Removed | Falling within excavation line |
| 340 | 333 | Naral         | <i>Cocos nucifera</i>           | 3-4   | 35-40 | To be Removed | Falling within excavation line |
| 341 | 334 | Naral         | <i>Cocos nucifera</i>           | 3-4   | 30-35 | To be Removed | Falling within excavation line |
| 342 | 335 | Amba          | <i>Mangifera indica</i>         | 8-10  | 25-30 | To be Removed | Falling within excavation line |
| 343 | 336 | Asupalav      | <i>Polyalthia langifolia</i>    | 1-2   | 20-25 | To be Removed | Falling within excavation line |
| 344 | 337 | Jambhul       | <i>Syzygium cumini</i>          | 10-15 | 40-45 | To be Removed | Falling within excavation line |
| 345 | 338 | Naral         | <i>Cocos nucifera</i>           | 2-3   | 10-15 | To be Removed | Falling within excavation line |
| 346 | 339 | Deshi Badam   | <i>Terminalia catappa</i>       | 3-4   | 25-30 | To be Removed | Falling within excavation line |
| 347 | 340 | Vad           | <i>Ficus benghalensis</i>       | 15-20 | 30-35 | To be Removed | Falling within excavation line |
| 348 | 341 | Deshi Badam   | <i>Terminalia catappa</i>       | 2-3   | 25-30 | To be Removed | Falling within excavation line |
| 349 | 342 | Pimpal        | <i>Ficus religiosa</i>          | 15-20 | 60-70 | To be Removed | Falling within excavation line |
| 350 | 343 | Shewga        | <i>Moringa oleifera</i>         | 2-3   | 20-25 | To be Removed | Falling within excavation line |
| 351 | 344 | Asupalav      | <i>Polyalthia langifolia</i>    | 1-2   | 25-30 | To be Removed | Falling within excavation line |
| 352 | 345 | Deshi Badam   | <i>Terminalia catappa</i>       | 2-3   | 25-30 | To be Removed | Falling within excavation line |
| 353 | 346 | Asupalav      | <i>Polyalthia langifolia</i>    | 1-2   | 20-25 | To be Removed | Falling within excavation line |
| 354 | 347 | Asupalav      | <i>Polyalthia langifolia</i>    | 7"-1  | 20-25 | To be Removed | Falling within excavation line |
| 355 | 348 | Deshi Badam   | <i>Terminalia catappa</i>       | 1-2   | 20-25 | To be Removed | Falling within excavation line |
| 356 | 349 | Phanas        | <i>Artocarpus heterophyllus</i> | 2-3   | 20-25 | To be Removed | Falling within excavation line |
| 357 | 350 | Dhaman (Dead) | <i>Grewia tiliaefolia</i>       | 1-2   | 15-20 | To be Removed | Falling within excavation line |
| 358 | 351 | Vad           | <i>Ficus benghalensis</i>       | 20-25 | 40-45 | To be Removed | Falling within excavation line |
| 359 | 352 | Pimpal        | <i>Ficus religiosa</i>          | 15-20 | 40-45 | To be Removed | Falling within excavation line |
| 360 | 353 | Rain Tree     | <i>Samanea saman</i>            | 12-15 | 50-55 | To be Removed | Falling within excavation line |
| 361 | 354 | Deshi Badam   | <i>Terminalia catappa</i>       | 1-2   | 20-25 | To be Removed | Falling within excavation line |
| 362 | 355 | Peru          | <i>Psidium guajava</i>          | 1-2   | 20-25 | To be Removed | Falling within excavation line |
| 363 | 356 | Kadamb        | <i>Neolamarckia cadamba</i>     | 1-2   | 20-25 | To be Removed | Falling within excavation line |
| 364 | 357 | Naral         | <i>Cocos nucifera</i>           | 2-3   | 20-25 | To be Removed | Falling within excavation line |
| 365 | 358 | Phanas        | <i>Artocarpus heterophyllus</i> | 1-2   | 20-25 | To be Removed | Falling within excavation line |
| 366 | 359 | Deshi Badam   | <i>Terminalia catappa</i>       | 2-3   | 30-35 | To be Removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |       |            |                              |       |       |               |                                |
|-----|-------|------------|------------------------------|-------|-------|---------------|--------------------------------|
| 367 | 360   | Umber      | <i>Ficus racemosa</i>        | 2-3   | 25-30 | To be Removed | Falling within excavation line |
| 368 | 361   | Naral      | <i>Cocos nucifera</i>        | 2-3   | 10-15 | To be Removed | Falling within excavation line |
| 369 | 362   | Naral      | <i>Cocos nucifera</i>        | 2-4   | 15-20 | To be Removed | Falling within excavation line |
| 370 | 362 A | Naral      | <i>Cocos nucifera</i>        | 1-2   | 15-20 | To be Removed | Falling within excavation line |
| 371 | 362 B | Amba       | <i>Mangifera indica</i>      | 10-15 | 10-15 | To be Removed | Falling within excavation line |
| 372 | 363   | Kala Umber | <i>Ficus hispida</i>         | 7"-1  | 10-15 | To be Removed | Falling within excavation line |
| 373 | 364   | Naral      | <i>Cocos nucifera</i>        | 2-3   | 30-35 | To be Removed | Falling within excavation line |
| 374 | 365   | Subabul    | <i>Leucaena leucocephala</i> | 7"-1  | 10-15 | To be Removed | Falling within excavation line |
| 375 | 366   | Tetu       | <i>Oroxylum indicum</i>      | 7"-1  | 10-15 | To be Removed | Falling within excavation line |
| 376 | 367   | Tetu       | <i>Oroxylum indicum</i>      | 7"-1  | 10-15 | To be Removed | Falling within excavation line |
| 377 | 368   | Tetu       | <i>Oroxylum indicum</i>      | 7"-1  | 15-20 | To be Removed | Falling within excavation line |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 47         |
| Trees to be removed  | 330        |
| <b>Total Trees</b>   | <b>377</b> |



| Summary of Tree Survey at Launching Shaft at Pali Ground |          |             |                                |                     |                      |                     |                                 |
|--|----------|-------------|--------------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.  | Tree no. | Common Name | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1  | 1        | Shewaga     | <i>Moringa oleifera</i>        | 2                   | 25                   | To be Retain        | Falling outside excavation line |
| 2  | 2        | Pichkari    | <i>Spathodea campanulata</i>   | 8"                  | 10                   | To be Retain        | Falling outside excavation line |
| 3  | 3        | Sonmohar    | <i>Peltophorum pterocarpum</i> | 4                   | 25                   | To be Retain        | Falling outside excavation line |
| 4  | 4        | Pichkari    | <i>Spathodea campanulata</i>   | 8"                  | 10                   | To be removed       | Falling outside excavation line |
| 5  | 5        | Peru        | <i>Psidium guajava</i>         | 8"                  | 10                   | To be removed       | Falling outside excavation line |
| 6  | 6        | Naral       | <i>Cocos nucifera</i>          | 3                   | 30                   | To be Retain        | Falling outside excavation line |
| 7  | 7        | Naral       | <i>Cocos nucifera</i>          | 3                   | 22                   | To be Retain        | Falling outside excavation line |
| 8  | 8        | Sonmohar    | <i>Peltophorum pterocarpum</i> | 4                   | 25                   | To be Retain        | Falling outside excavation line |
| 9  | 9        | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3                   | 25                   | To be Retain        | Falling outside excavation line |
| 10   | 10       | Sonmohar    | <i>Peltophorum pterocarpum</i> | 2                   | 25                   | To be Retain        | Falling outside excavation line |
| 11   | 11       | Sonmohar    | <i>Peltophorum pterocarpum</i> | 3                   | 25                   | To be Retain        | Falling outside excavation line |
| 12   | 12       | Dead        | -                              | 1                   | 20                   | To be removed       | Falling outside excavation line |
| 13   | 13       | Naral       | <i>Cocos nucifera</i>          | 2                   | 25                   | To be Retain        | Falling outside excavation line |
| 14   | 14       | Naral       | <i>Cocos nucifera</i>          | 3                   | 28                   | To be Retain        | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |           |                                |   |    |               |                                 |
|----|-----|-----------|--------------------------------|---|----|---------------|---------------------------------|
| 15 | 14A | Pimpal    | <i>Ficus religiosa</i>         | 4 | 30 | To be Retain  | Falling outside excavation line |
| 16 | 15  | Rain tree | <i>Samanea saman</i>           | 4 | 30 | To be Retain  | Falling outside excavation line |
| 17 | 16  | Naral     | <i>Cocos nucifera</i>          | 2 | 30 | To be Retain  | Falling outside excavation line |
| 18 | 17  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3 | 30 | To be Retain  | Falling outside excavation line |
| 19 | 18  | Dead      | -                              | 4 | 25 | To be removed | Falling outside excavation line |
| 20 | 19  | Giripushp | <i>Gliricidia sepium</i>       | 1 | 15 | To be removed | Falling outside excavation line |
| 21 | 20  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3 | 25 | To be removed | Falling outside excavation line |
| 22 | 21  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3 | 25 | To be removed | Falling outside excavation line |
| 23 | 22  | Giripushp | <i>Gliricidia sepium</i>       | 1 | 20 | To be removed | Falling outside excavation line |
| 24 | 23  | Rain tree | <i>Samanea saman</i>           | 6 | 25 | To be removed | Falling outside excavation line |
| 25 | 24  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3 | 35 | To be Retain  | Falling outside excavation line |
| 26 | 25  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3 | 35 | To be Retain  | Falling outside excavation line |
| 27 | 26  | Jambhul   | <i>Syzygium cumini</i>         | 3 | 35 | To be Retain  | Falling outside excavation line |
| 28 | 27  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 3 | 30 | To be Retain  | Falling outside excavation line |
| 29 | 28  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 2 | 20 | To be Retain  | Falling outside excavation line |
| 30 | 29  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 2 | 30 | To be Retain  | Falling outside excavation line |
| 31 | 30  | Sonmohar  | <i>Peltophorum pterocarpum</i> | 1 | 25 | To be Retain  | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |              |                                |    |    |              |                                 |
|----|----|--------------|--------------------------------|----|----|--------------|---------------------------------|
| 32 | 31 | Rain tree    | <i>Samanea saman</i>           | 10 | 30 | To be Retain | Falling outside excavation line |
| 33 | 32 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2  | 25 | To be Retain | Falling outside excavation line |
| 34 | 33 | Rain tree    | <i>Samanea saman</i>           | 8" | 18 | To be Retain | Falling outside excavation line |
| 35 | 34 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 2  | 25 | To be Retain | Falling outside excavation line |
| 36 | 35 | Jungli Badam | <i>Sterculia foetida</i>       | 1  | 18 | To be Retain | Falling outside excavation line |
| 37 | 36 | Bhend        | <i>Thespesia populnea</i>      | 3  | 20 | To be Retain | Falling outside excavation line |
| 38 | 37 | Naral        | <i>Cocos nucifera</i>          | 2  | 35 | To be Retain | Falling outside excavation line |
| 39 | 38 | Naral        | <i>Cocos nucifera</i>          | 2  | 35 | To be Retain | Falling outside excavation line |
| 40 | 39 | Naral        | <i>Cocos nucifera</i>          | 2  | 35 | To be Retain | Falling outside excavation line |
| 41 | 40 | Jungli Badam | <i>Sterculia foetida</i>       | 8" | 20 | To be Retain | Falling outside excavation line |
| 42 | 41 | Naral        | <i>Cocos nucifera</i>          | 2  | 25 | To be Retain | Falling outside excavation line |
| 43 | 42 | Naral        | <i>Cocos nucifera</i>          | 3  | 25 | To be Retain | Falling outside excavation line |
| 44 | 43 | Naral        | <i>Cocos nucifera</i>          | 2  | 25 | To be Retain | Falling outside excavation line |
| 45 | 44 | Naral        | <i>Cocos nucifera</i>          | 3  | 20 | To be Retain | Falling outside excavation line |
| 46 | 45 | Amba         | <i>Mangifera indica</i>        | 8" | 8  | To be Retain | Falling outside excavation line |
| 47 | 46 | Naral        | <i>Cocos nucifera</i>          | 2  | 20 | To be Retain | Falling outside excavation line |
| 48 | 47 | Naral        | <i>Cocos nucifera</i>          | 2  | 20 | To be Retain | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |              |                                |    |    |               |                                 |
|----|----|--------------|--------------------------------|----|----|---------------|---------------------------------|
| 49 | 48 | Naral        | <i>Cocos nucifera</i>          | 3  | 20 | To be Retain  | Falling outside excavation line |
| 50 | 49 | Jungli Badam | <i>Sterculia foetida</i>       | 8" | 15 | To be Retain  | Falling outside excavation line |
| 51 | 50 | Pichkari     | <i>Spathodea campanulata</i>   | 8" | 10 | To be Retain  | Falling outside excavation line |
| 52 | 51 | kashid       | <i>cassia fistula</i>          | 2  | 25 | To be removed | Falling outside excavation line |
| 53 | 52 | Shewaga      | <i>Moringa oleifera</i>        | 3  | 30 | To be Retain  | Falling outside excavation line |
| 54 | 53 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3  | 25 | To be Retain  | Falling outside excavation line |
| 55 | 54 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3  | 25 | To be Retain  | Falling outside excavation line |
| 56 | 55 | Sonmohar     | <i>Peltophorum pterocarpum</i> | 3  | 20 | To be removed | Falling outside excavation line |
| 57 | 56 | Jungli Badam | <i>Sterculia foetida</i>       | 8" | 8  | To be Retain  | Falling outside excavation line |
| 58 | 57 | Jungli Badam | <i>Sterculia foetida</i>       | 1  | 20 | To be removed | Falling outside excavation line |
| 59 | 58 | Rain tree    | <i>Samanea saman</i>           | 1  | 20 | To be removed | Falling outside excavation line |
| 60 | 59 | Pimpal       | <i>Ficus religiosa</i>         | 1  | 15 | To be Retain  | Falling outside excavation line |
| 61 | 60 | Bhend        | <i>Thespesia populnea</i>      | 5  | 25 | To be removed | Falling outside excavation line |
| 62 | 61 | Wad          | <i>Ficus benghalensis</i>      | 2  | 15 | To be Retain  | Falling outside excavation line |
| 63 | 62 | Bhend        | <i>Thespesia populnea</i>      | 10 | 25 | To be Retain  | Falling outside excavation line |
| 64 | 63 | kala umbar   | <i>ficus hispida</i>           | 3  | 25 | To be removed | Falling outside excavation line |
| 65 | 64 | Kashid       | <i>cassia fistula</i>          | 2  | 25 | To be removed | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |             |                              |   |    |               |                                 |
|----|-----|-------------|------------------------------|---|----|---------------|---------------------------------|
| 66 | 64A | Kashid      | <i>cassia fistula</i>        | 3 | 35 | To be removed | Falling outside excavation line |
| 67 | 64B | Kashid      | <i>cassia fistula</i>        | 3 | 35 | To be removed | Falling outside excavation line |
| 68 | 65  | Amba        | <i>Mangifera indica</i>      | 3 | 20 | To be Retain  | Falling outside excavation line |
| 69 | 66  | Asupalav    | <i>Polyalthia longifolia</i> | 1 | 10 | To be Retain  | Falling outside excavation line |
| 70 | 67  | Deshi Badam | <i>Terminalia catappa</i>    | 3 | 32 | To be Retain  | Falling outside excavation line |
| 71 | 68  | Kashid      | <i>cassia fistula</i>        | 2 | 20 | To be removed | Falling outside excavation line |
| 72 | 69  | Asupalav    | <i>Polyalthia longifolia</i> | 1 | 10 | To be Retain  | Falling outside excavation line |
| 73 | 70  | Naral       | <i>Cocos nucifera</i>        | 3 | 18 | To be Retain  | Falling outside excavation line |
| 74 | 71  | Deshi Badam | <i>Terminalia catappa</i>    | 3 | 20 | To be Retain  | Falling outside excavation line |
| 75 | 72  | Asupalav    | <i>Polyalthia longifolia</i> | 1 | 10 | To be Retain  | Falling outside excavation line |
| 76 | 73  | Asupalav    | <i>Polyalthia longifolia</i> | 3 | 15 | To be Retain  | Falling outside excavation line |
| 77 | 74  | Safed jam   | <i>Syzygium samarangense</i> | 1 | 12 | To be Retain  | Falling outside excavation line |

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 58        |
| Trees to be removed  | 19        |
| <b>Total Trees</b>   | <b>77</b> |

| Summary of Tree Survey at Casting Yard at JVL R |          |                 |                                |                     |                      |                     |                                   |
|---|----------|-----------------|--------------------------------|---------------------|----------------------|---------------------|-----------------------------------|
| Sr. no.   | Tree no. | Common Name     | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                            |
| 1   | 1        | Subabul         | <i>Leucaena leucocephala</i>   | 2                   | 18                   | To be Removed       | Falling within excavation line    |
| 2   | 2        | Sag             | <i>Tectona grandis</i>         | 1                   | 12                   | To be Removed       | Falling within excavation line    |
| 3   | 3        | Bartend         | <i>Morinda pubescens</i>       | 4                   | 15                   | To be retained      | Falling outside construction line |
| 4   | 4        | Vilayti Chinch  | <i>Pithecellobium dulce</i>    | 2                   | 25                   | To be Removed       | Falling within excavation line    |
| 5   | 5        | Vilayti Chinch  | <i>Pithecellobium dulce</i>    | 1                   | 22                   | To be Removed       | Falling within excavation line    |
| 6   | 6        | Vilayti Chinch  | <i>Pithecellobium dulce</i>    | 1                   | 22                   | To be Removed       | Falling within excavation line    |
| 7   | 7        | Vavla           | <i>Holoptelea integrifolia</i> | 2                   | 20                   | To be Removed       | Falling within excavation line    |
| 8   | 8        | Bor             | <i>Zizyphus mauritiana</i>     | 1                   | 25                   | To be Removed       | Falling within excavation line    |
| 9   | 9        | Subabul         | <i>Leucaena leucocephala</i>   | 2                   | 35                   | To be Removed       | Falling within excavation line    |
| 10  | 10       | Vavla           | <i>Holoptelea integrifolia</i> | 1                   | 20                   | To be Removed       | Falling within excavation line    |
| 11  | 11       | Vavla           | <i>Holoptelea integrifolia</i> | 1                   | 20                   | To be Removed       | Falling within excavation line    |
| 12  | 12       | Subabul         | <i>Leucaena leucocephala</i>   | 2                   | 25                   | To be retained      | Falling outside construction line |
| 13  | 13       | Vaval           | <i>Holoptelea integrifolia</i> | 3                   | 20                   | To be retained      | Falling outside construction line |
| 14  | 14       | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 3                   | 25                   | To be retained      | Falling outside construction line |
| 15  | 15       | Vilayti chinch  | <i>Pithecellobium dulce</i>    | 2                   | 25                   | To be retained      | Falling outside construction line |
| 16  | 16       | Khair           | <i>Acacia nilotica</i>         | 2                   | 23                   | To be retained      | Falling outside construction line |
| 17  | 17       | Khair           | <i>Acacia nilotica</i>         | 2                   | 23                   | To be retained      | Falling outside construction line |
| 18  | 18       | Savar           | <i>Bombax ceiba</i>            | 4                   | 30                   | To be Removed       | Falling within excavation line    |
| 19  | 19       | Vavla           | <i>Holoptelea integrifolia</i> | 2                   | 20                   | To be Removed       | Falling within excavation line    |
| 20  | 20       | Rain Tree       | <i>Samanea saman</i>           | 3                   | 25                   | To be Removed       | Falling within excavation line    |
| 21  | 21       | Rain Tree       | <i>Samanea saman</i>           | 3                   | 25                   | To be Removed       | Falling within excavation line    |
| 22  | 22       | Rain Tree       | <i>Samanea saman</i>           | 4                   | 23                   | To be Removed       | Falling within excavation line    |
| 23  | 23       | Rain Tree       | <i>Samanea saman</i>           | 4                   | 20                   | To be Removed       | Falling within excavation line    |
| 24  | 24       | Singapur Cherry | <i>Muntingia calabura</i>      | 8"                  | 10                   | To be Removed       | Falling within excavation line    |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |                |                                |    |    |                |                                   |
|----|----|----------------|--------------------------------|----|----|----------------|-----------------------------------|
| 25 | 25 | Savar          | <i>Bombax ceiba</i>            | 2  | 30 | To be Removed  | Falling within excavation line    |
| 26 | 26 | Savar          | <i>Bombax ceiba</i>            | 2  | 30 | To be Removed  | Falling within excavation line    |
| 27 | 27 | Katesavar      | <i>Bombax cieba</i>            | 3  | 25 | To be Removed  | Falling within excavation line    |
| 28 | 28 | Subabul        | <i>Leucaena leucocephala</i>   | 1  | 30 | To be Removed  | Falling within excavation line    |
| 29 | 29 | Vavla          | <i>holoptelea integrifolia</i> | 2  | 25 | To be Removed  | Falling within excavation line    |
| 30 | 30 | Shemat         | <i>Lannea coromandelica</i>    | 2  | 25 | To be Removed  | Falling within excavation line    |
| 31 | 31 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 1  | 20 | To be Removed  | Falling within excavation line    |
| 32 | 32 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 3  | 20 | To be Removed  | Falling within excavation line    |
| 33 | 33 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 2  | 20 | To be Removed  | Falling within excavation line    |
| 34 | 34 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 3  | 20 | To be Removed  | Falling within excavation line    |
| 35 | 35 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 3  | 20 | To be Removed  | Falling within excavation line    |
| 36 | 36 | Bor            | <i>Zizyphus mairitiana</i>     | 3  | 20 | To be retained | Falling outside construction line |
| 37 | 37 | Subabul        | <i>Leucaena leucocephala</i>   | 1  | 25 | To be retained | Falling outside construction line |
| 38 | 38 | Subabul        | <i>Leucaena leucocephala</i>   | 1  | 25 | To be retained | Falling outside construction line |
| 39 | 39 | Katesavar      | <i>Bombax cieba</i>            | 1  | 20 | To be retained | Falling outside construction line |
| 40 | 40 | Tad            | <i>Borassus flabellifer</i>    | 2  | 35 | To be Removed  | Falling within excavation line    |
| 41 | 41 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 2  | 30 | To be Removed  | Falling within excavation line    |
| 42 | 42 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 1  | 25 | To be Removed  | Falling within excavation line    |
| 43 | 43 | Wad            | <i>Ficus benghalensis</i>      | 8" | 10 | To be Removed  | Falling within excavation line    |
| 44 | 44 | Asupalv        | <i>Polyalthia longifolia</i>   | 8" | 11 | To be Removed  | Falling within excavation line    |
| 45 | 45 | Asupalv        | <i>Polyalthia longifolia</i>   | 1  | 25 | To be Removed  | Falling within excavation line    |
| 46 | 46 | Subabul        | <i>Leucaena leucocephala</i>   | 1  | 25 | To be Removed  | Falling within excavation line    |
| 47 | 47 | Subabul        | <i>Leucaena leucocephala</i>   | 2  | 30 | To be Removed  | Falling within excavation line    |
| 48 | 48 | Subabul        | <i>Leucaena leucocephala</i>   | 1  | 10 | To be Removed  | Falling within excavation line    |
| 49 | 49 | Dead           | -                              |    |    | To be Removed  | Falling within excavation line    |
| 50 | 50 | Subabul        | <i>Leucaena leucocephala</i>   | 8" | 12 | To be Removed  | Falling within excavation line    |
| 51 | 51 | Subabul        | <i>Leucaena leucocephala</i>   | 1  | 15 | To be Removed  | Falling within excavation line    |
| 52 | 52 | Subabul        | <i>Leucaena leucocephala</i>   | 8" | 10 | To be retained | Falling outside construction line |
| 53 | 53 | Desi Badam     | <i>Treminaliya catappa</i>     | 1  | 20 | To be retained | Falling outside construction line |
| 54 | 54 | Desi Badam     | <i>Treminaliya catappa</i>     | 8" | 10 | To be retained | Falling outside construction line |
| 55 | 55 | Katesavar      | <i>Bombax cieba</i>            | 1  | 20 | To be retained | Falling outside construction line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |               |                              |        |    |                |                                   |
|----|----|---------------|------------------------------|--------|----|----------------|-----------------------------------|
| 56 | 56 | Subabul       | <i>Leucaena leucocephala</i> | 8"     | 10 | To be retained | Falling outside construction line |
| 57 | 57 | Desi Badam    | <i>Treminaliya catappa</i>   | 1      | 20 | To be retained | Falling outside construction line |
| 58 | 58 | Desi Badam    | <i>Treminaliya catappa</i>   | 8"     | 10 | To be retained | Falling outside construction line |
| 59 | 59 | Katesavar     | <i>Bombax cieba</i>          | 1      | 20 | To be retained | Falling outside construction line |
| 60 | 60 | Subabul       | <i>Leucaena leucocephala</i> | 8"     | 10 | To be retained | Falling outside construction line |
| 61 | 61 | Desi Badam    | <i>Treminaliya catappa</i>   | 1      | 20 | To be retained | Falling outside construction line |
| 62 | 62 | Desi Badam    | <i>Treminaliya catappa</i>   | 8"     | 10 | To be retained | Falling outside construction line |
| 63 | 63 | Katesavar     | <i>Bombax cieba</i>          | 1      | 20 | To be retained | Falling outside construction line |
| 64 | 64 | Subabul       | <i>Leucaena leucocephala</i> | 8"     | 10 | To be retained | Falling outside construction line |
| 65 | 65 | Subabul       | <i>Leucaena leucocephala</i> | 2      | 25 | To be Removed  | Falling within excavation line    |
| 66 | 66 | Charcoal tree | <i>Trema orientalis</i>      | 8"     | 10 | To be Removed  | Falling within excavation line    |
| 67 | 67 | Desi Badam    | <i>Treminaliya catappa</i>   | 1      | 20 | To be retained | Falling outside construction line |
| 68 | 68 | Subabul       | <i>Leucaena leucocephala</i> | 2      | 25 | To be Removed  | Falling within excavation line    |
| 69 | 69 | Desi Badam    | <i>Treminaliya catappa</i>   | 8"     | 10 | To be retained | Falling outside construction line |
| 70 | 70 | Katesavar     | <i>Bombax cieba</i>          | 1      | 20 | To be retained | Falling outside construction line |
| 71 | 71 | Subabul       | <i>Leucaena leucocephala</i> | 8"     | 10 | To be retained | Falling outside construction line |
| 72 | 72 | Desi Badam    | <i>Treminaliya catappa</i>   | 1      | 20 | To be retained | Falling outside construction line |
| 73 | 73 | Subabul       | <i>Leucaena leucocephala</i> | 2      | 25 | To be retained | Falling outside construction line |
| 74 | 74 | Katesavar     | <i>Bombax cieba</i>          | 1      | 20 | To be retained | Falling outside construction line |
| 75 | 75 | Khair         | <i>Acacia nilotica</i>       | 1      | 15 | To be retained | Falling outside construction line |
| 76 | 76 | Subabul       | <i>Leucaena leucocephala</i> | 2      | 25 | To be Removed  | Falling within excavation line    |
| 77 | 77 | Subabul       | <i>Leucaena leucocephala</i> | 1      | 20 | To be retained | Falling outside construction line |
| 78 | 78 | Kaduneem      | <i>Azadirachta indica</i>    | 0.5576 | 9  | To be retained | Falling outside construction line |
| 79 | 79 | Subabul       | <i>Leucaena leucocephala</i> | 3      | 25 | To be Removed  | Falling within excavation line    |
| 80 | 80 | Kashid        | <i>Cassia siamea</i>         | 2      | 26 | To be retained | Falling outside construction line |
| 81 | 81 | Subabul       | <i>Leucaena leucocephala</i> | 2      | 25 | To be Removed  | Falling within excavation line    |
| 82 | 82 | Subabul       | <i>Leucaena leucocephala</i> | 3      | 30 | To be retained | Falling outside construction line |
| 83 | 83 | Subabul       | <i>Leucaena leucocephala</i> | 8"     | 15 | To be retained | Falling outside construction line |
| 84 | 84 | Subabul       | <i>Leucaena leucocephala</i> | 3      | 20 | To be retained | Falling outside construction line |
| 85 | 85 | Subabul       | <i>Leucaena leucocephala</i> | 2      | 25 | To be retained | Falling outside construction line |
| 86 | 86 | Subabul       | <i>Leucaena leucocephala</i> | 2      | 25 | To be retained | Falling outside construction line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |            |                              |    |       |                |                                   |
|----|----|------------|------------------------------|----|-------|----------------|-----------------------------------|
| 87 | 87 | Subabul    | <i>Leucaena leucocephala</i> | 2  | 25    | To be retained | Falling outside construction line |
| 88 | 88 | Subabul    | <i>Leucaena leucocephala</i> | 2  | 20    | To be retained | Falling outside construction line |
| 89 | 89 | Asupalav   | <i>Polyalthia longifolia</i> | 8" | 13.12 | To be retained | Falling outside construction line |
| 90 | 90 | Subabul    | <i>Leucaena leucocephala</i> | 1  | 20    | To be Removed  | Falling within excavation line    |
| 91 | 91 | Khair      | <i>Acacia nilotica</i>       | 1  | 20    | To be retained | Falling outside construction line |
| 92 | 92 | Subabul    | <i>Leucaena leucocephala</i> | 3  | 25    | To be retained | Falling outside construction line |
| 93 | 93 | Subabul    | <i>Leucaena leucocephala</i> | 2  | 25    | To be retained | Falling outside construction line |
| 94 | 94 | Subabul    | <i>Leucaena leucocephala</i> | 2  | 20    | To be retained | Falling outside construction line |
| 95 | 95 | Subabul    | <i>Leucaena leucocephala</i> | 1  | 20    | To be retained | Falling outside construction line |
| 96 | 96 | Subabul    | <i>Leucaena leucocephala</i> | 1  | 25    | To be Removed  | Falling within excavation line    |
| 97 | 97 | Kala Umber | <i>Ficus hispida</i>         | 1  | 20    | To be Removed  | Falling within excavation line    |

|                      |           |
|----------------------|-----------|
| Trees to be Retained | 48        |
| Trees to be removed  | 49        |
| <b>Total Trees</b>   | <b>97</b> |

**8. PYLON TERMINATION AT AAREY COLONY**

| Summary of Tree Survey at Pylon Termination, Aarey Colony |          |                  |                              |                      |                       |                     |                            |
|---|----------|------------------|------------------------------|----------------------|-----------------------|---------------------|----------------------------|
| Sr. no.   | Tree no. | Common Name      | Botanical Name               | Approx . Girth (ft.) | Approx . Height (ft.) | Proposed suggestion | Remark                     |
| 1   | 1        | Subabhul         | <i>Leucaena leucocephala</i> | 3-4                  | 20-30                 | To be removed       | Affected in Road diversion |
| 2   | 2        | Subabhul         | <i>Leucaena leucocephala</i> | 1-2                  | 10-20                 | To be removed       | Affected in Road diversion |
| 3   | 3        | Dead             | -                            | 2-3                  | 15-25                 | To be removed       | Affected in Road diversion |
| 4   | 4        | Subabhul         | <i>Leucaena leucocephala</i> | 1-2                  | 25-35                 | To be removed       | Affected in Road diversion |
| 5   | 5        | Subabhul         | <i>Leucaena leucocephala</i> | 1-2                  | 20-30                 | To be removed       | Affected in Road diversion |
| 6   | 6        | Rain tree        | <i>Samanea saman</i>         | 7-8                  | 30-40                 | To be removed       | Affected in Road diversion |
| 7   | 7        | Giripushpa       | <i>Gliricidia sepium</i>     | 3-4                  | 15-25                 | To be removed       | Affected in Road diversion |
| 8   | 8        | Subabhul         | <i>Leucaena leucocephala</i> | 3-4                  | 20-30                 | To be removed       | Affected in Road diversion |
| 9   | 9        | Subabhul         | <i>Leucaena leucocephala</i> | 2-3                  | 15-25                 | To be removed       | Affected in Road diversion |
| 10  | 10       | Singapore cherry | <i>Muntingia calabura</i>    | 1-2                  | 10-20                 | To be removed       | Affected in Road diversion |
| 11  | 11       | Subabhul         | <i>Leucaena leucocephala</i> | 1-2                  | 10-20                 | To be removed       | Affected in Road diversion |
| 12  | 12       | Dhaman           | <i>Grewia tiliaefolia</i>    | 2-3                  | 10-20                 | To be removed       | Affected in Road diversion |
| 13  | 13       | Dhaman           | <i>Grewia tiliaefolia</i>    | 1-2                  | 10-20                 | To be removed       | Affected in Road diversion |
| 14  | 14       | Dhaman           | <i>Grewia tiliaefolia</i>    | 3-4                  | 15-25                 | To be removed       | Affected in Road diversion |
| 15  | 15       | Subabhul         | <i>Leucaena leucocephala</i> | 1-2                  | 10-20                 | To be removed       | Affected in Road diversion |
| 16  | 16       | Kala UMBER       | <i>Ficus hispida</i>         | 1-2                  | 10-15                 | To be removed       | Affected in Road diversion |
| 17  | 17       | Dhaman           | <i>Grewia tiliaefolia</i>    | 1-2                  | 10-20                 | To be removed       | Affected in Road diversion |
| 18  | 18       | Dhaman           | <i>Grewia tiliaefolia</i>    | 2-3                  | 10-20                 | To be removed       | Affected in Road diversion |
| 19  | 19       | Subabhul         | <i>Leucaena leucocephala</i> | 2-3                  | 20-30                 | To be removed       | Affected in Road diversion |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |               |                              |       |       |               |                            |
|----|----|---------------|------------------------------|-------|-------|---------------|----------------------------|
| 20 | 20 | Subabhul      | <i>Leucaena leucocephala</i> | 3-4   | 20-30 | To be removed | Affected in Road diversion |
| 21 | 21 | Subabhul      | <i>Leucaena leucocephala</i> | 3-4   | 20-30 | To be removed | Affected in Road diversion |
| 22 | 22 | Charcoal tree | <i>Trema orientalis</i>      | 2-3   | 20-30 | To be removed | Affected in Road diversion |
| 23 | 23 | Subabhul      | <i>Leucaena leucocephala</i> | 3-4   | 10-20 | To be removed | Affected in Road diversion |
| 24 | 24 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1-2   | 15-25 | To be removed | Affected in Road diversion |
| 25 | 25 | Dhaman        | <i>Grewia tiliaefolia</i>    | 5-6   | 10-20 | To be removed | Affected in Road diversion |
| 26 | 26 | Subabhul      | <i>Leucaena leucocephala</i> | 6-7   | 15-20 | To be removed | Affected in Road diversion |
| 27 | 27 | Amba          | <i>Mangifera indica</i>      | 12-13 | 30-40 | To be removed | Affected in Road diversion |
| 28 | 28 | Dhaman        | <i>Grewia tiliaefolia</i>    | 3-4   | 10-20 | To be removed | Affected in Road diversion |
| 29 | 29 | Dhaman        | <i>Grewia tiliaefolia</i>    | 2-3   | 15-25 | To be removed | Affected in Road diversion |
| 30 | 30 | Dhaman        | <i>Grewia tiliaefolia</i>    | 3-4   | 15-25 | To be removed | Affected in Road diversion |
| 31 | 31 | Asana         | <i>Bridelia retusa</i>       | 2-3   | 10-20 | To be removed | Affected in Pylon shifting |
| 32 | 32 | Bhokar        | <i>Cordia dichotoma</i>      | 2-3   | 10-20 | To be removed | Affected in Pylon shifting |
| 33 | 33 | Dhaman        | <i>Grewia tiliaefolia</i>    | 3-4   | 15-25 | To be removed | Affected in Pylon shifting |
| 34 | 34 | Tetu          | <i>Oroxylum indicum</i>      | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 35 | 35 | Tetu          | <i>Oroxylum indicum</i>      | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 36 | 36 | Tetu          | <i>Oroxylum indicum</i>      | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 37 | 37 | Tetu          | <i>Oroxylum indicum</i>      | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 38 | 38 | Dhaman        | <i>Grewia tiliaefolia</i>    | 2-3   | 10-20 | To be removed | Affected in Pylon shifting |
| 39 | 39 | Bhokar        | <i>Cordia dichotoma</i>      | 3-4   | 10-20 | To be removed | Affected in Pylon shifting |
| 40 | 40 | Kala Umber    | <i>Ficus hispida</i>         | 3-4   | 15-25 | To be removed | Affected in Pylon shifting |
| 41 | 41 | Kala Umber    | <i>Ficus hispida</i>         | 2-3   | 15-25 | To be removed | Affected in Pylon shifting |
| 42 | 42 | Petari        | <i>Trewia nudiflora</i>      | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 43 | 43 | Kala Umber    | <i>Ficus hispida</i>         | 2-3   | 15-25 | To be removed | Affected in Pylon shifting |
| 44 | 44 | Kala Umber    | <i>Ficus hispida</i>         | 1-2   | 15-25 | To be removed | Affected in Pylon shifting |
| 45 | 45 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1-2   | 15-25 | To be removed | Affected in Pylon shifting |
| 46 | 46 | Desi badam    | <i>Terminalia catappa</i>    | 1-2   | 20-30 | To be removed | Affected in Pylon shifting |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                |                                 |      |       |               |                            |
|----|-----|----------------|---------------------------------|------|-------|---------------|----------------------------|
| 47 | 47  | Tad            | <i>Borassus flabellifer</i>     | 5-6  | 35-45 | To be removed | Affected in Pylon shifting |
| 48 | 48  | Vilayti chinch | <i>Pithecellobium dulce</i>     | 2-3  | 15-25 | To be removed | Affected in Pylon shifting |
| 49 | 49  | Subabhul       | <i>Leucaena leucocephala</i>    | 4-5  | 40-50 | To be removed | Affected in Pylon shifting |
| 50 | 50  | Subabhul       | <i>Leucaena leucocephala</i>    | 3-4  | 25-35 | To be removed | Affected in Pylon shifting |
| 51 | 50A | Subabhul       | <i>Leucaena leucocephala</i>    | 2-3  | 30-40 | To be removed | Affected in Pylon shifting |
| 52 | 51  | Subabhul       | <i>Leucaena leucocephala</i>    | 4-5  | 30-40 | To be removed | Affected in Pylon shifting |
| 53 | 52  | Subabhul       | <i>Leucaena leucocephala</i>    | 1-2  | 25-35 | To be removed | Affected in Pylon shifting |
| 54 | 53  | Tuti           | <i>Morus alba</i>               | 1-2  | 15-25 | To be removed | Affected in Pylon shifting |
| 55 | 54  | Tuti           | <i>Morus alba</i>               | 1-2  | 15-25 | To be removed | Affected in Pylon shifting |
| 56 | 55  | Dhaman         | <i>Grewia tiliaefolia</i>       | 1-2  | 15-25 | To be removed | Affected in Pylon shifting |
| 57 | 56  | Dead           | -                               | 1-2  | 10-20 | To be removed | Affected in Pylon shifting |
| 58 | 57  | Subabhul       | <i>Leucaena leucocephala</i>    | 6-7  | 40-50 | To be removed | Affected in Pylon shifting |
| 59 | 58  | Subabhul       | <i>Leucaena leucocephala</i>    | 3-4  | 30-40 | To be removed | Affected in Pylon shifting |
| 60 | 59  | Asana          | <i>Bridelia retusa</i>          | 1-2  | 15-25 | To be removed | Affected in Pylon shifting |
| 61 | 60  | Shevga         | <i>Moringa oleifera</i>         | 1-2  | 15-25 | To be removed | Affected in Pylon shifting |
| 62 | 61  | Naral          | <i>Cocos nucifera</i>           | 4-5  | 30-40 | To be removed | Affected in Pylon shifting |
| 63 | 62  | Phanas         | <i>Artocarpus heterophyllus</i> | 4-5  | 30-40 | To be removed | Affected in Pylon shifting |
| 64 | 63  | Sitaphal       | <i>Annona squamosa</i>          | 1-2  | 10-20 | To be removed | Affected in Pylon shifting |
| 65 | 64  | Limbu          | <i>Citrus aurantifolia</i>      | 1-2  | 15-25 | To be removed | Affected in Pylon shifting |
| 66 | 65  | Amba           | <i>Mangifera indica</i>         | 8"-1 | 10-20 | To be removed | Affected in Pylon shifting |
| 67 | 66  | Phanas         | <i>Artocarpus heterophyllus</i> | 1-2  | 10-20 | To be removed | Affected in Pylon shifting |
| 68 | 67  | Shevga         | <i>Moringa oleifera</i>         | 2-3  | 20-30 | To be removed | Affected in Pylon shifting |
| 69 | 68  | Kaduneem       | <i>Azadirachta indica</i>       | 8"-1 | 10-20 | To be removed | Affected in Pylon shifting |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |    |               |                              |      |       |               |                            |
|----|----|---------------|------------------------------|------|-------|---------------|----------------------------|
| 70 | 69 | Tuti          | <i>Morus alba</i>            | 3-4  | 15-25 | To be removed | Affected in Pylon shifting |
| 71 | 70 | Subabhul      | <i>Leucaena leucocephala</i> | 1-2  | 25-35 | To be removed | Affected in Pylon shifting |
| 72 | 71 | Bherli mad    | <i>Caryota urens</i>         | 1-2  | 10-15 | To be removed | Affected in Pylon shifting |
| 73 | 72 | Tuti          | <i>Morus alba</i>            | 1-2  | 10-20 | To be removed | Affected in Pylon shifting |
| 74 | 73 | Charcoal tree | <i>Trema orientalis</i>      | 2-3  | 30-40 | To be removed | Affected in Pylon shifting |
| 75 | 74 | Desi badam    | <i>Terminalia catappa</i>    | 3-4  | 35-45 | To be removed | Affected in Pylon shifting |
| 76 | 75 | Subabhul      | <i>Leucaena leucocephala</i> | 1-2  | 15-25 | To be removed | Affected in Pylon shifting |
| 77 | 76 | Dhaman        | <i>Grewia tiliaefolia</i>    | 4-5  | 15-25 | To be removed | Affected in Pylon shifting |
| 78 | 77 | Subabhul      | <i>Leucaena leucocephala</i> | 1-2  | 10-15 | To be removed | Affected in Pylon shifting |
| 79 | 78 | Subabhul      | <i>Leucaena leucocephala</i> | 1-2  | 20-30 | To be removed | Affected in Pylon shifting |
| 80 | 79 | Subabhul      | <i>Leucaena leucocephala</i> | 1-2  | 20-30 | To be removed | Affected in Pylon shifting |
| 81 | 80 | Dhaman        | <i>Grewia tiliaefolia</i>    | 6-7  | 20-30 | To be removed | Affected in Pylon shifting |
| 82 | 81 | Dhaman        | <i>Grewia tiliaefolia</i>    | 2-3  | 15-25 | To be removed | Affected in Pylon shifting |
| 83 | 82 | Karanj        | <i>Pongamia pinnata</i>      | 1-2  | 10-20 | To be removed | Affected in Pylon shifting |
| 84 | 83 | Dhaman        | <i>Grewia tiliaefolia</i>    | 3-4  | 15-25 | To be removed | Affected in Pylon shifting |
| 85 | 84 | Dhaman        | <i>Grewia tiliaefolia</i>    | 3-4  | 15-25 | To be removed | Affected in Pylon shifting |
| 86 | 85 | Subabhul      | <i>Leucaena leucocephala</i> | 2-3  | 30-40 | To be removed | Affected in Pylon shifting |
| 87 | 86 | Karanj        | <i>Pongamia pinnata</i>      | 2-3  | 15-25 | To be removed | Affected in Pylon shifting |
| 88 | 87 | Subabhul      | <i>Leucaena leucocephala</i> | 1-2  | 20-30 | To be removed | Affected in Pylon shifting |
| 89 | 88 | Dhaman        | <i>Grewia tiliaefolia</i>    | 3-4  | 15-25 | To be removed | Affected in Pylon shifting |
| 90 | 89 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1-2  | 20-30 | To be removed | Affected in Pylon shifting |
| 91 | 90 | Dhaman        | <i>Grewia tiliaefolia</i>    | 8"-1 | 10-20 | To be removed | Affected in Pylon shifting |
| 92 | 91 | Dhaman        | <i>Grewia tiliaefolia</i>    | 2-3  | 10-20 | To be removed | Affected in Pylon shifting |
| 93 | 92 | Dhaman        | <i>Grewia tiliaefolia</i>    | 2-3  | 10-20 | To be removed | Affected in Pylon shifting |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                              |       |       |               |                            |
|-----|-----|------------|------------------------------|-------|-------|---------------|----------------------------|
| 94  | 93  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-15 | To be removed | Affected in Pylon shifting |
| 95  | 94  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 96  | 95  | Dhaman     | <i>Grewia tiliaefolia</i>    | 8"-1  | 10-15 | To be removed | Affected in Pylon shifting |
| 97  | 96  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 98  | 97  | Rain tree  | <i>Samanea saman</i>         | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 99  | 98  | Kate savar | <i>Bombax ceiba</i>          | 5-6   | 25-35 | To be removed | Affected in Pylon shifting |
| 100 | 99  | Asana      | <i>Bridelia retusa</i>       | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 101 | 100 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-15 | To be removed | Affected in Pylon shifting |
| 102 | 101 | Apta       | <i>Bauhinia racemosa</i>     | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 103 | 102 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-15 | To be removed | Affected in Pylon shifting |
| 104 | 103 | Khajur     | <i>Phoenix dactylifera</i>   | 3-4   | 15-25 | To be removed | Affected in Pylon shifting |
| 105 | 104 | Kala Umber | <i>Ficus hispida</i>         | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 106 | 105 | Asana      | <i>Bridelia retusa</i>       | 1-2   | 10-15 | To be removed | Affected in Pylon shifting |
| 107 | 106 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2-3   | 10-15 | To be removed | Affected in Pylon shifting |
| 108 | 107 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-15 | To be removed | Affected in Pylon shifting |
| 109 | 108 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2-3   | 10-15 | To be removed | Affected in Pylon shifting |
| 110 | 109 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 15-25 | To be removed | Affected in Pylon shifting |
| 111 | 110 | Kate savar | <i>Bombax ceiba</i>          | 2-3   | 15-25 | To be removed | Affected in Pylon shifting |
| 112 | 111 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-20 | To be removed | Affected in Pylon shifting |
| 113 | 112 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 15-25 | To be removed | Affected in Pylon shifting |
| 114 | 113 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2-3   | 10-15 | To be removed | Affected in Pylon shifting |
| 115 | 114 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-15 | To be removed | Affected in Pylon shifting |
| 116 | 115 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-15 | To be removed | Affected in Pylon shifting |
| 117 | 116 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-15 | To be removed | Affected in Pylon shifting |
| 118 | 117 | Vad        | <i>Ficus benghalensis</i>    | 17-18 | 40-50 | To be removed | Affected in Pylon shifting |
| 119 | 118 | Vad        | <i>Ficus benghalensis</i>    | 17-18 | 40-50 | To be removed | Affected in Pylon shifting |
| 120 | 119 | Dhaman     | <i>Grewia tiliaefolia</i>    | 4-5   | 15-25 | To be removed | Affected in Pylon shifting |
| 121 | 120 | Subabhul   | <i>Leucaena leucocephala</i> | 1-2   | 15-25 | To be removed | Affected in Pylon shifting |
| 122 | 121 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1-2   | 10-15 | To be removed | Affected in Road diversion |
| 123 | 122 | Arjun      | <i>Terminalia arjuna</i>     | 6"-1  | 10-15 | To be removed | Affected in Road diversion |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                              |      |       |               |                            |
|-----|-----|------------|------------------------------|------|-------|---------------|----------------------------|
| 124 | 123 | Kadamb     | <i>Neolamarkiana cadamba</i> | 6"-1 | 10-15 | To be removed | Affected in Road diversion |
| 125 | 124 | Kadamb     | <i>Neolamarkiana cadamba</i> | 1-2  | 10-15 | To be removed | Affected in Road diversion |
| 126 | 125 | Kadamb     | <i>Neolamarkiana cadamba</i> | 1-2  | 10-15 | To be removed | Affected in Road diversion |
| 127 | 126 | Dead       | -                            | 1-2  | 5-10  | To be removed | Affected in Road diversion |
| 128 | 127 | Tabebuia   | <i>Tabebuia pentaphylla</i>  | 1-2  | 10-20 | To be removed | Affected in Road diversion |
| 129 | 128 | Mahogani   | <i>Swetinia macrophylla</i>  | 6"-1 | 10-20 | To be removed | Affected in Road diversion |
| 130 | 129 | Mahogani   | <i>Swetinia macrophylla</i>  | 6"-1 | 10-20 | To be removed | Affected in Road diversion |
| 131 | 130 | Kadamb     | <i>Neolamarkiana cadamba</i> | 6"-1 | 10-15 | To be removed | Affected in Road diversion |
| 132 | 131 | Karanj     | <i>Pongamia pinnata</i>      | 1-2  | 10-15 | To be removed | Affected in Road diversion |
| 133 | 132 | Umber      | <i>Ficus glomerata</i>       | 6"-1 | 10-15 | To be removed | Affected in Road diversion |
| 134 | 133 | Subabhul   | <i>Leucaena leucocephala</i> | 6"-1 | 10-20 | To be removed | Affected in Road diversion |
| 135 | 134 | Desi badam | <i>Terminalia catappa</i>    | 3-4  | 25-35 | To be removed | Affected in Road diversion |
| 136 | 135 | Kala Umber | <i>Ficus hispida</i>         | 2-3  | 20-30 | To be removed | Affected in Road diversion |
| 137 | 136 | Karanj     | <i>Pongamia pinnata</i>      | 2-3  | 25-35 | To be removed | Affected in Road diversion |

|                      |            |
|----------------------|------------|
| Trees to be Retained | 0          |
| Trees to be removed  | 137        |
| <b>Total Trees</b>   | <b>137</b> |



**9. CAR-SHED DEPOT AT AAREY COLONY**

| Summary of Tree Survey at Car Shed Depot at Aarey Colony, as per tree survey carried out on May 2017 |          |                  |                                |                     |                      |                     |                                 |
|--|----------|------------------|--------------------------------|---------------------|----------------------|---------------------|---------------------------------|
| Sr. no.  | Tree no. | Common Name      | Botanical Name                 | Approx. Girth (ft.) | Approx. Height (ft.) | Proposed suggestion | Remark                          |
| 1  | 1        | Rain tree        | <i>Samanea saman</i>           | 8                   | 35                   | To be removed       | Falling within excavation line  |
| 2  | 2        | Rain tree        | <i>Samanea saman</i>           | 10                  | 45                   | To be removed       | Falling within excavation line  |
| 3  | 3        | Rain tree        | <i>Samanea saman</i>           | 8                   | 35                   | To be removed       | Falling within excavation line  |
| 4  | 3A       | Charcoal tree    | <i>Trema orientalis</i>        | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 5  | 3B       | Subabhul         | <i>Leucaena leucocephala</i>   | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 6  | 3C       | Subabhul         | <i>Leucaena leucocephala</i>   | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 7  | 3D       | Gulmohar         | <i>Delonix regia</i>           | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 8  | 4        | Rain tree        | <i>Samanea saman</i>           | 5                   | 45                   | To be removed       | Falling within excavation line  |
| 9  | 5        | Umber            | <i>Ficus glomerata</i>         | 2                   | 20                   | To be retained      | Falling outside excavation line |
| 10   | 6        | Gulmohar         | <i>Delonix regia</i>           | 5                   | 45                   | To be retained      | Falling outside excavation line |
| 11   | 6A       | Subabhul         | <i>Leucaena leucocephala</i>   | 1                   | 15                   | To be retained      | Falling outside excavation line |
| 12   | 6B       | Subabhul         | <i>Leucaena leucocephala</i>   | 1.5                 | 20                   | To be retained      | Falling outside excavation line |
| 13   | 7        | Vilayti Chinch   | <i>Pithecellobium dulce</i>    | 2                   | 25                   | To be retained      | Falling outside excavation line |
| 14   | 8        | Amba             | <i>Mangifera indica</i>        | 5                   | 45                   | To be retained      | Falling outside excavation line |
| 15   | 9        | Umber            | <i>Ficus glomerata</i>         | 2                   | 30                   | To be retained      | Falling outside excavation line |
| 16   | 10       | Pipri            | <i>Ficus amplissima</i>        | 5                   | 35                   | To be removed       | Falling within excavation line  |
| 17   | 10A      | Subabhul         | <i>Leucaena leucocephala</i>   | 1.5                 | 20                   | To be removed       | Falling within excavation line  |
| 18   | 10B      | Charcoal tree    | <i>Trema orientalis</i>        | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 19   | 10C      | Singapore cherry | <i>Muntingia calabura</i>      | 1                   | 15                   | To be removed       | Falling within excavation line  |
| 20   | 11       | Jambhul          | <i>Syzygium cumini</i>         | 8                   | 45                   | To be retained      | Falling outside excavation line |
| 21   | 12       | Karanj           | <i>Pongamia pinnata</i>        | 5                   | 25                   | To be retained      | Falling outside excavation line |
| 22   | 13       | Rain tree        | <i>Samanea saman</i>           | 8                   | 35                   | To be removed       | Falling within excavation line  |
| 23   | 14       | Rain tree        | <i>Samanea saman</i>           | 8                   | 35                   | To be removed       | Falling within excavation line  |
| 4  | 15       | Sonmohar         | <i>Peltophorum pterocarpum</i> | 1.5                 | 20                   | To be removed       | Falling within excavation line  |
| 25   | 16       | Rain tree        | <i>Samanea saman</i>           | 5                   | 30                   | To be removed       | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |               |                                |     |    |                |                                 |
|----|-----|---------------|--------------------------------|-----|----|----------------|---------------------------------|
| 26 | 17  | Sonmohar      | <i>Peltophorum pterocarpum</i> | 2   | 30 | To be retained | Falling outside excavation line |
| 27 | 18  | Jambhul       | <i>Syzygium cumini</i>         | 2   | 20 | To be retained | Falling outside excavation line |
| 28 | 19  | Sonmohar      | <i>Peltophorum pterocarpum</i> | 2   | 15 | To be retained | Falling outside excavation line |
| 29 | 20  | Vad           | <i>Ficus benghalensis</i>      | 10  | 45 | To be retained | Falling outside excavation line |
| 30 | 20A | Tad           | <i>Borassus flabellifer</i>    | 2   | 35 | To be removed  | Falling within excavation line  |
| 31 | 21  | Jambhul       | <i>Syzygium cumini</i>         | 5   | 45 | To be removed  | Falling within excavation line  |
| 32 | 22  | Sonmohar      | <i>Peltophorum pterocarpum</i> | 10  | 35 | To be removed  | Falling within excavation line  |
| 33 | 22A | Karanj        | <i>Pongamia pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 34 | 22B | Subabhul      | <i>Leucaena leucocephala</i>   | 1   | 15 | To be retained | Falling outside excavation line |
| 35 | 22C | Subabhul      | <i>Leucaena leucocephala</i>   | 1   | 15 | To be removed  | Falling within excavation line  |
| 36 | 23  | Gulmohar      | <i>Delonix regia</i>           | 8   | 35 | To be removed  | Falling within excavation line  |
| 37 | 24  | Rain tree     | <i>Samanea saman</i>           | 10  | 45 | To be removed  | Falling within excavation line  |
| 38 | 25  | Rain tree     | <i>Samanea saman</i>           | 5   | 25 | To be removed  | Falling within excavation line  |
| 39 | 26  | Jambhul       | <i>Syzygium cumini</i>         | 8   | 35 | To be retained | Falling outside excavation line |
| 40 | 27  | Vad           | <i>Ficus benghalensis</i>      | 5   | 30 | To be retained | Falling outside excavation line |
| 41 | 28  | Rain tree     | <i>Samanea saman</i>           | 10  | 35 | To be removed  | Falling within excavation line  |
| 42 | 28A | Subabhul      | <i>Leucaena leucocephala</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 43 | 28B | Charcoal tree | <i>Trema orientalis</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 44 | 29  | Sonmohar      | <i>Peltophorum pterocarpum</i> | 8   | 35 | To be retained | Falling outside excavation line |
| 45 | 29A | Rain tree     | <i>Samanea saman</i>           | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 46 | 29B | Kadamb        | <i>Neolamarckia cadamba</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 47 | 29C | Kadamb        | <i>Neolamarckia cadamba</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 48 | 29D | Kadamb        | <i>Neolamarckia cadamba</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 49 | 30  | Vad           | <i>Ficus benghalensis</i>      | 8   | 30 | To be retained | Falling outside excavation line |
| 50 | 30A | Subabhul      | <i>Leucaena leucocephala</i>   | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 51 | 31  | Rain tree     | <i>Samanea saman</i>           | 10  | 30 | To be retained | Falling outside excavation line |
| 52 | 31A | Sonmohar      | <i>Peltophorum pterocarpum</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 53 | 31B | Rain tree     | <i>Samanea saman</i>           | 1.5 | 15 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|    |     |                |                                |     |    |                |                                 |
|----|-----|----------------|--------------------------------|-----|----|----------------|---------------------------------|
| 54 | 32  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 10  | 45 | To be retained | Falling outside excavation line |
| 55 | 33  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 25 | To be removed  | Falling within excavation line  |
| 56 | 33A | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 57 | 33B | Subabhul       | <i>Leucaena leucocephala</i>   | 1   | 15 | To be removed  | Falling within excavation line  |
| 58 | 34  | Subabhul       | <i>Leucaena leucocephala</i>   | 5   | 30 | To be removed  | Falling within excavation line  |
| 59 | 34A | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 60 | 34B | Subabhul       | <i>Leucaena leucocephala</i>   | 1   | 15 | To be removed  | Falling within excavation line  |
| 61 | 35  | Subabhul       | <i>Leucaena leucocephala</i>   | 5   | 30 | To be removed  | Falling within excavation line  |
| 62 | 36  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 10  | 30 | To be removed  | Falling within excavation line  |
| 63 | 37  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed  | Falling within excavation line  |
| 64 | 38  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 10  | 30 | To be removed  | Falling within excavation line  |
| 65 | 39  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 10  | 30 | To be removed  | Falling within excavation line  |
| 66 | 40  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 8   | 35 | To be removed  | Falling within excavation line  |
| 67 | 41  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed  | Falling within excavation line  |
| 68 | 42  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 8   | 35 | To be removed  | Falling within excavation line  |
| 69 | 43  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed  | Falling within excavation line  |
| 70 | 44  | Gulmohar       | <i>Delonix regia</i>           | 5   | 30 | To be removed  | Falling within excavation line  |
| 71 | 45  | Rain tree      | <i>Samanea saman</i>           | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 72 | 45A | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 73 | 46  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 8   | 45 | To be removed  | Falling within excavation line  |
| 74 | 47  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 10  | 45 | To be removed  | Falling within excavation line  |
| 75 | 47A | Dhaman         | <i>Grewia tiliaefolia</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 76 | 47B | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 77 | 48  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 10  | 45 | To be removed  | Falling within excavation line  |
| 78 | 49  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 10  | 45 | To be removed  | Falling within excavation line  |
| 79 | 49A | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 80 | 50  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 8   | 45 | To be removed  | Falling within excavation line  |
| 81 | 51  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 10  | 50 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                |     |    |               |                                |
|-----|-----|----------------|--------------------------------|-----|----|---------------|--------------------------------|
| 82  | 52  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 35 | To be removed | Falling within excavation line |
| 83  | 52A | Rain tree      | <i>Samanea saman</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 84  | 53  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 8   | 35 | To be removed | Falling within excavation line |
| 85  | 54  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 35 | To be removed | Falling within excavation line |
| 86  | 55  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 35 | To be removed | Falling within excavation line |
| 87  | 56  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed | Falling within excavation line |
| 88  | 56A | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 30 | To be removed | Falling within excavation line |
| 89  | 57  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 8   | 30 | To be removed | Falling within excavation line |
| 90  | 57A | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 91  | 58  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 92  | 59  | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 93  | 60  | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 30 | To be removed | Falling within excavation line |
| 94  | 61  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 35 | To be removed | Falling within excavation line |
| 95  | 62  | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 35 | To be removed | Falling within excavation line |
| 96  | 63  | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 35 | To be removed | Falling within excavation line |
| 97  | 64  | Subabhul       | <i>Leucaena leucocephala</i>   | 2   | 35 | To be removed | Falling within excavation line |
| 98  | 65  | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 99  | 66  | Vavla          | <i>Holoptela integrifolia</i>  | 1   | 15 | To be removed | Falling within excavation line |
| 100 | 67  | Vavla          | <i>Holoptela integrifolia</i>  | 1   | 15 | To be removed | Falling within excavation line |
| 101 | 68  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 35 | To be removed | Falling within excavation line |
| 102 | 69  | Sonmohar       | <i>Peltophorum pterocarpum</i> | 5   | 35 | To be removed | Falling within excavation line |
| 103 | 70  | Charcoal tree  | <i>Trema orientalis</i>        | 1.5 | 20 | To be removed | Falling within excavation line |
| 104 | 71  | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 105 | 72  | Charcoal tree  | <i>Trema orientalis</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 106 | 73  | Charcoal tree  | <i>Trema orientalis</i>        | 1.5 | 10 | To be removed | Falling within excavation line |
| 107 | 74  | Charcoal tree  | <i>Trema orientalis</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 108 | 75  | Rain tree      | <i>Samanea saman</i>           | 1   | 15 | To be removed | Falling within excavation line |
| 109 | 76  | Rain tree      | <i>Samanea saman</i>           | 1   | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                  |                                |     |    |                |                                 |
|-----|-----|------------------|--------------------------------|-----|----|----------------|---------------------------------|
| 110 | 77  | Singapore cherry | <i>Muntingia calabura</i>      | 1   | 20 | To be removed  | Falling within excavation line  |
| 111 | 78  | Charcoal tree    | <i>Trema orientalis</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 112 | 79  | Singapore cherry | <i>Muntingia calabura</i>      | 1   | 15 | To be removed  | Falling within excavation line  |
| 113 | 80  | Singapore cherry | <i>Muntingia calabura</i>      | 1   | 15 | To be removed  | Falling within excavation line  |
| 114 | 81  | Pimparni         | <i>Ficus virens</i>            | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 115 | 82  | Sonmohar         | <i>Peltophorum pterocarpum</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 116 | 83  | Kala umber       | <i>Ficus hispida</i>           | 1   | 15 | To be removed  | Falling within excavation line  |
| 117 | 84  | Subabhul         | <i>Leucaena leucocephala</i>   | 1   | 15 | To be removed  | Falling within excavation line  |
| 118 | 85  | Rain tree        | <i>Samanea saman</i>           | 10  | 50 | To be retained | Falling outside excavation line |
| 119 | 86  | Rain tree        | <i>Samanea saman</i>           | 5   | 50 | To be retained | Falling outside excavation line |
| 120 | 87  | Kharoti          | <i>Streblus asper</i>          | 1   | 10 | To be retained | Falling outside excavation line |
| 121 | 88  | Jambhul          | <i>Syzygium cumini</i>         | 1.5 | 30 | To be retained | Falling outside excavation line |
| 122 | 89  | Rain tree        | <i>Samanea saman</i>           | 5   | 50 | To be retained | Falling outside excavation line |
| 123 | 90  | Rain tree        | <i>Samanea saman</i>           | 8   | 50 | To be retained | Falling outside excavation line |
| 124 | 91  | Rain tree        | <i>Samanea saman</i>           | 10  | 50 | To be retained | Falling outside excavation line |
| 125 | 92  | Narikel          | <i>Pterygota alata</i>         | 10  | 50 | To be retained | Falling outside excavation line |
| 126 | 93  | Narikel          | <i>Pterygota alata</i>         | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 127 | 94  | Subabhul         | <i>Leucaena leucocephala</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 128 | 95  | Dhaman           | <i>Grewia tiliaefolia</i>      | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 129 | 96  | Bhokar           | <i>Cordia dichotoma</i>        | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 130 | 97  | Pimpal           | <i>Ficus religiosa</i>         | 10  | 50 | To be removed  | Falling within excavation line  |
| 131 | 98  | Kate savar       | <i>Bombax ceiba</i>            | 2   | 50 | To be removed  | Falling within excavation line  |
| 132 | 99  | Kala umber       | <i>Ficus hispida</i>           | 1   | 15 | To be removed  | Falling within excavation line  |
| 133 | 100 | Narikel          | <i>Pterygota alata</i>         | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 134 | 101 | Rain tree        | <i>Samanea saman</i>           | 1   | 15 | To be removed  | Falling within excavation line  |
| 135 | 102 | Narikel          | <i>Pterygota alata</i>         | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 136 | 103 | Narikel          | <i>Pterygota alata</i>         | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 137 | 104 | Narikel          | <i>Pterygota alata</i>         | 1.5 | 30 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                   |                              |     |    |               |                                |
|-----|------|-------------------|------------------------------|-----|----|---------------|--------------------------------|
| 138 | 105  | Narikel           | <i>Pterygota alata</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 139 | 106  | Narikel           | <i>Pterygota alata</i>       | 1   | 15 | To be removed | Falling within excavation line |
| 140 | 107  | Rain tree         | <i>Samanea saman</i>         | 8   | 50 | To be removed | Falling within excavation line |
| 141 | 108  | Shemat            | <i>Lannea coromandelica</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 142 | 109  | Asana             | <i>Bridelia retusa</i>       | 1.5 | 35 | To be removed | Falling within excavation line |
| 143 | 110  | Rain tree         | <i>Samanea saman</i>         | 1.5 | 35 | To be removed | Falling within excavation line |
| 144 | 111  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 145 | 112  | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 146 | 113  | Bor               | <i>Ziziphus mauritiana</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 147 | 114  | Bor               | <i>Ziziphus mauritiana</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 148 | 115  | Shemat            | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 149 | 116  | Shemat            | <i>Lannea coromandelica</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 150 | 117  | Charcoal tree     | <i>Trema orientalis</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 151 | 118  | Charcoal tree     | <i>Trema orientalis</i>      | 1   | 10 | To be removed | Falling within excavation line |
| 152 | 118A | Charcoal tree     | <i>Trema orientalis</i>      | 1   | 15 | To be removed | Falling within excavation line |
| 153 | 118B | Subabhul          | <i>Leucaena leucocephala</i> | 1   | 15 | To be removed | Falling within excavation line |
| 154 | 119  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 155 | 120  | Rain tree         | <i>Samanea saman</i>         | 8   | 45 | To be removed | Falling within excavation line |
| 156 | 121  | Amba              | <i>Mangifera indica</i>      | 5   | 15 | To be removed | Falling within excavation line |
| 157 | 122  | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 158 | 123  | Charcoal tree     | <i>Trema orientalis</i>      | 8   | 10 | To be removed | Falling within excavation line |
| 159 | 124  | Australian Babbul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed | Falling within excavation line |
| 160 | 125  | Atrun             | <i>Flacourtia montana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 161 | 126  | Atrun             | <i>Flacourtia montana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 162 | 127  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 163 | 128  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1   | 25 | To be removed | Falling within excavation line |
| 164 | 129  | Amba              | <i>Mangifera indica</i>      | 8   | 50 | To be removed | Falling within excavation line |
| 165 | 130  | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                              |     |    |                |                                 |
|-----|-----|------------|------------------------------|-----|----|----------------|---------------------------------|
| 166 | 131 | Rain tree  | <i>Samanea saman</i>         | 2   | 50 | To be removed  | Falling within excavation line  |
| 167 | 132 | Rain tree  | <i>Samanea saman</i>         | 2   | 50 | To be removed  | Falling within excavation line  |
| 168 | 133 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 169 | 134 | Rain tree  | <i>Samanea saman</i>         | 8   | 50 | To be removed  | Falling within excavation line  |
| 170 | 135 | Rain tree  | <i>Samanea saman</i>         | 2   | 35 | To be removed  | Falling within excavation line  |
| 171 | 136 | Amba       | <i>Mangifera indica</i>      | 5   | 35 | To be removed  | Falling within excavation line  |
| 172 | 137 | Umber      | <i>Ficus glomerata</i>       | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 173 | 138 | Rain tree  | <i>Samanea saman</i>         | 2   | 50 | To be removed  | Falling within excavation line  |
| 174 | 139 | Amba       | <i>Mangifera indica</i>      | 5   | 35 | To be removed  | Falling within excavation line  |
| 175 | 140 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 176 | 141 | Narikel    | <i>Pterygota alata</i>       | 5   | 50 | To be retained | Falling outside excavation line |
| 177 | 142 | Narikel    | <i>Pterygota alata</i>       | 8   | 50 | To be removed  | Falling within excavation line  |
| 178 | 143 | Bhokar     | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 179 | 144 | Rain tree  | <i>Samanea saman</i>         | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 180 | 145 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 181 | 146 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 182 | 147 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be removed  | Falling within excavation line  |
| 183 | 148 | Bartondi   | <i>Morinda pubescens</i>     | 1   | 15 | To be removed  | Falling within excavation line  |
| 184 | 149 | Narikel    | <i>Pterygota alata</i>       | 8   | 50 | To be removed  | Falling within excavation line  |
| 185 | 150 | Narikel    | <i>Pterygota alata</i>       | 5   | 50 | To be retained | Falling outside excavation line |
| 186 | 151 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 187 | 152 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 188 | 153 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 189 | 154 | Narikel    | <i>Pterygota alata</i>       | 2   | 50 | To be retained | Falling outside excavation line |
| 190 | 155 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 191 | 156 | Narikel    | <i>Pterygota alata</i>       | 2   | 50 | To be removed  | Falling within excavation line  |
| 192 | 157 | Kanchan    | <i>Bauhinia purpurea</i>     | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 193 | 158 | Rain tree  | <i>Samanea saman</i>         | 2   | 50 | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |            |                           |     |    |               |                                |
|-----|------|------------|---------------------------|-----|----|---------------|--------------------------------|
| 194 | 159  | Rain tree  | <i>Samanea saman</i>      | 2   | 50 | To be removed | Falling within excavation line |
| 195 | 160  | Rain tree  | <i>Samanea saman</i>      | 2   | 50 | To be removed | Falling within excavation line |
| 196 | 161  | Rain tree  | <i>Samanea saman</i>      | 5   | 50 | To be removed | Falling within excavation line |
| 197 | 162  | Kate savar | <i>Bombax ceiba</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 198 | 163  | Umber      | <i>Ficus glomerata</i>    | 5   | 35 | To be removed | Falling within excavation line |
| 199 | 163A | Kharoti    | <i>Streblus asper</i>     | 1   | 10 | To be removed | Falling within excavation line |
| 200 | 164  | Dhaman     | <i>Grewia tiliaefolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 201 | 165  | Dhaman     | <i>Grewia tiliaefolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 202 | 166  | Amba       | <i>Mangifera indica</i>   | 8   | 45 | To be removed | Falling within excavation line |
| 203 | 167  | Kharoti    | <i>Streblus asper</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 204 | 168  | Dhaman     | <i>Grewia tiliaefolia</i> | 1   | 10 | To be removed | Falling within excavation line |
| 205 | 169  | Amba       | <i>Mangifera indica</i>   | 5   | 50 | To be removed | Falling within excavation line |
| 206 | 170  | Kharoti    | <i>Streblus asper</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 207 | 171  | Kharoti    | <i>Streblus asper</i>     | 1   | 10 | To be removed | Falling within excavation line |
| 208 | 172  | Kharoti    | <i>Streblus asper</i>     | 2   | 15 | To be removed | Falling within excavation line |
| 209 | 173  | Kharoti    | <i>Streblus asper</i>     | 1.5 | 10 | To be removed | Falling within excavation line |
| 210 | 174  | Dhaman     | <i>Grewia tiliaefolia</i> | 1.5 | 10 | To be removed | Falling within excavation line |
| 211 | 175  | Rain tree  | <i>Samanea saman</i>      | 1.5 | 35 | To be removed | Falling within excavation line |
| 212 | 176  | Rain tree  | <i>Samanea saman</i>      | 1   | 10 | To be removed | Falling within excavation line |
| 213 | 177  | Amba       | <i>Mangifera indica</i>   | 10  | 45 | To be removed | Falling within excavation line |
| 214 | 178  | Dhaman     | <i>Grewia tiliaefolia</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 215 | 179  | Rain tree  | <i>Samanea saman</i>      | 2   | 50 | To be removed | Falling within excavation line |
| 216 | 180  | Rain tree  | <i>Samanea saman</i>      | 2   | 50 | To be removed | Falling within excavation line |
| 217 | 181  | Rain tree  | <i>Samanea saman</i>      | 2   | 50 | To be removed | Falling within excavation line |
| 218 | 182  | Rain tree  | <i>Samanea saman</i>      | 2   | 50 | To be removed | Falling within excavation line |
| 219 | 183  | Rain tree  | <i>Samanea saman</i>      | 5   | 50 | To be removed | Falling within excavation line |
| 220 | 184  | Rain tree  | <i>Samanea saman</i>      | 2   | 50 | To be removed | Falling within excavation line |
| 221 | 185  | Rain tree  | <i>Samanea saman</i>      | 1.5 | 50 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                                |     |    |                |                                 |
|-----|-----|---------------|--------------------------------|-----|----|----------------|---------------------------------|
| 222 | 186 | Rain tree     | <i>Samanea saman</i>           | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 223 | 187 | Dhaman        | <i>Grewia tiliaefolia</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 224 | 188 | Narikel       | <i>Pterygota alata</i>         | 5   | 50 | To be retained | Falling outside excavation line |
| 225 | 189 | Narikel       | <i>Pterygota alata</i>         | 5   | 50 | To be retained | Falling outside excavation line |
| 226 | 190 | Rain tree     | <i>Samanea saman</i>           | 2   | 50 | To be removed  | Falling within excavation line  |
| 227 | 191 | Narikel       | <i>Pterygota alata</i>         | 5   | 50 | To be removed  | Falling within excavation line  |
| 228 | 192 | Rain tree     | <i>Samanea saman</i>           | 2   | 50 | To be removed  | Falling within excavation line  |
| 229 | 193 | Rain tree     | <i>Samanea saman</i>           | 2   | 50 | To be removed  | Falling within excavation line  |
| 230 | 194 | Narikel       | <i>Pterygota alata</i>         | 5   | 50 | To be removed  | Falling within excavation line  |
| 231 | 195 | Subabhul      | <i>Leucaena leucocephala</i>   | 5   | 50 | To be removed  | Falling within excavation line  |
| 232 | 196 | Rain tree     | <i>Samanea saman</i>           | 5   | 50 | To be removed  | Falling within excavation line  |
| 233 | 197 | Rain tree     | <i>Samanea saman</i>           | 2   | 50 | To be removed  | Falling within excavation line  |
| 234 | 198 | Rain tree     | <i>Samanea saman</i>           | 1.5 | 50 | To be removed  | Falling within excavation line  |
| 235 | 199 | Rain tree     | <i>Samanea saman</i>           | 5   | 50 | To be removed  | Falling within excavation line  |
| 236 | 200 | Rain tree     | <i>Samanea saman</i>           | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 237 | 201 | Rain tree     | <i>Samanea saman</i>           | 2   | 50 | To be removed  | Falling within excavation line  |
| 238 | 202 | Rain tree     | <i>Samanea saman</i>           | 2   | 50 | To be removed  | Falling within excavation line  |
| 239 | 203 | Rain tree     | <i>Samanea saman</i>           | 2   | 50 | To be removed  | Falling within excavation line  |
| 240 | 204 | Rain tree     | <i>Samanea saman</i>           | 5   | 50 | To be removed  | Falling within excavation line  |
| 241 | 205 | Bhokar        | <i>Cordia dichotoma</i>        | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 242 | 206 | Narikel       | <i>Pterygota alata</i>         | 8   | 50 | To be retained | Falling outside excavation line |
| 243 | 207 | Amba (Dead)   | <i>Mangifera indica</i>        | 5   | 35 | To be removed  | Falling within excavation line  |
| 244 | 208 | Dhaman (Dead) | <i>Grewia tiliaefolia</i>      | 1   | 10 | To be removed  | Falling within excavation line  |
| 245 | 209 | Bhokar        | <i>Cordia dichotoma</i>        | 2   | 40 | To be removed  | Falling within excavation line  |
| 246 | 210 | Gulmohar      | <i>Delonix regia</i>           | 5   | 50 | To be removed  | Falling within excavation line  |
| 247 | 211 | Sonmohar      | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 248 | 212 | Rain tree     | <i>Samanea saman</i>           | 5   | 50 | To be removed  | Falling within excavation line  |
| 249 | 213 | Gulmohar      | <i>Delonix regia</i>           | 3   | 45 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                |                              |     |    |               |                                |
|-----|------|----------------|------------------------------|-----|----|---------------|--------------------------------|
| 250 | 214  | Umber (Dead)   | <i>Ficus glomerata</i>       | 1   | 10 | To be removed | Falling within excavation line |
| 251 | 215  | Rain tree      | <i>Samanea saman</i>         | 1.5 | 35 | To be removed | Falling within excavation line |
| 252 | 216  | Rain tree      | <i>Samanea saman</i>         | 5   | 50 | To be removed | Falling within excavation line |
| 253 | 217  | Rain tree      | <i>Samanea saman</i>         | 2   | 50 | To be removed | Falling within excavation line |
| 254 | 218  | Rain tree      | <i>Samanea saman</i>         | 5   | 50 | To be removed | Falling within excavation line |
| 255 | 219  | Rain tree      | <i>Samanea saman</i>         | 1.5 | 45 | To be removed | Falling within excavation line |
| 256 | 220  | Rain tree      | <i>Samanea saman</i>         | 5   | 50 | To be removed | Falling within excavation line |
| 257 | 221  | Rain tree      | <i>Samanea saman</i>         | 1.5 | 35 | To be removed | Falling within excavation line |
| 258 | 222  | Rain tree      | <i>Samanea saman</i>         | 5   | 50 | To be removed | Falling within excavation line |
| 259 | 223  | Amba           | <i>Mangifera indica</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 260 | 224  | Amba           | <i>Mangifera indica</i>      | 5   | 45 | To be removed | Falling within excavation line |
| 261 | 225  | Gulmohar       | <i>Delonix regia</i>         | 3   | 45 | To be removed | Falling within excavation line |
| 262 | 226  | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 263 | 227  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be removed | Falling within excavation line |
| 264 | 228  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be removed | Falling within excavation line |
| 265 | 229  | Amba           | <i>Mangifera indica</i>      | 10  | 45 | To be removed | Falling within excavation line |
| 266 | 229A | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1   | 10 | To be removed | Falling within excavation line |
| 267 | 230  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 268 | 231  | Asana          | <i>Pterocarpus marsupium</i> | 2   | 35 | To be removed | Falling within excavation line |
| 269 | 232  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 270 | 233  | Bor            | <i>Ziziphus mauritiana</i>   | 1   | 10 | To be removed | Falling within excavation line |
| 271 | 234  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 272 | 235  | Jambhul        | <i>Syzygium cumini</i>       | 2   | 35 | To be removed | Falling within excavation line |
| 273 | 236  | Rain tree      | <i>Samanea saman</i>         | 1   | 15 | To be removed | Falling within excavation line |
| 274 | 237  | Shemat         | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 275 | 238  | Kate savar     | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 276 | 239  | Shemat         | <i>Lannea coromandelica</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 277 | 240  | Kate savar     | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                               |     |    |                |                                 |
|-----|-----|----------------|-------------------------------|-----|----|----------------|---------------------------------|
| 278 | 241 | Semat          | <i>Lannea coromandelica</i>   | 2   | 35 | To be removed  | Falling within excavation line  |
| 279 | 242 | Bor            | <i>Ziziphus mauritiana</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 280 | 243 | Safed Shirish  | <i>Albizia procera</i>        | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 281 | 244 | Apta           | <i>Bauhinia racemosa</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 282 | 245 | Amba           | <i>Mangifera indica</i>       | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 283 | 246 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 2   | 25 | To be removed  | Falling within excavation line  |
| 284 | 247 | Kharoti        | <i>Streblus asper</i>         | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 285 | 248 | Kharoti        | <i>Streblus asper</i>         | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 286 | 249 | Amba           | <i>Mangifera indica</i>       | 5   | 35 | To be removed  | Falling within excavation line  |
| 287 | 250 | Amba           | <i>Mangifera indica</i>       | 5   | 35 | To be removed  | Falling within excavation line  |
| 288 | 251 | Bartondi       | <i>Morinda pubescens</i>      | 1   | 10 | To be removed  | Falling within excavation line  |
| 289 | 252 | Amba (Dead)    | <i>Mangifera indica</i>       | 8   | 35 | To be removed  | Falling within excavation line  |
| 290 | 253 | Asana          | <i>Pterocarpus marsupium</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 291 | 254 | Amba (Dead)    | <i>Mangifera indica</i>       | 8   | 15 | To be removed  | Falling within excavation line  |
| 292 | 255 | Dhaman         | <i>Grewia tiliaefolia</i>     | 2   | 35 | To be removed  | Falling within excavation line  |
| 293 | 256 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 294 | 257 | Moha           | <i>Madhuca indica</i>         | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 295 | 258 | Narikel        | <i>Pterygota alata</i>        | 5   | 60 | To be retained | Falling outside excavation line |
| 296 | 259 | Narikel        | <i>Pterygota alata</i>        | 5   | 60 | To be retained | Falling outside excavation line |
| 297 | 260 | Narikel        | <i>Pterygota alata</i>        | 8   | 60 | To be retained | Falling outside excavation line |
| 298 | 261 | Amba           | <i>Mangifera indica</i>       | 5   | 45 | To be removed  | Falling within excavation line  |
| 299 | 262 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 300 | 263 | Amba (Dead)    | <i>Mangifera indica</i>       | 10  | 15 | To be removed  | Falling within excavation line  |
| 301 | 264 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1   | 15 | To be removed  | Falling within excavation line  |
| 302 | 265 | Moha           | <i>Madhuca indica</i>         | 1   | 10 | To be removed  | Falling within excavation line  |
| 303 | 266 | Moha           | <i>Madhuca indica</i>         | 1   | 10 | To be removed  | Falling within excavation line  |
| 304 | 267 | Kate savar     | <i>Bombax ceiba</i>           | 1   | 15 | To be removed  | Falling within excavation line  |
| 305 | 268 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                              |     |    |                |                                 |
|-----|-----|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 306 | 269 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 307 | 270 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 308 | 271 | Moha              | <i>Madhuca indica</i>        | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 309 | 272 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 35 | To be removed  | Falling within excavation line  |
| 310 | 273 | Bhokar            | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 311 | 274 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 312 | 275 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 35 | To be removed  | Falling within excavation line  |
| 313 | 276 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 314 | 277 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 315 | 278 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 35 | To be removed  | Falling within excavation line  |
| 316 | 279 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be removed  | Falling within excavation line  |
| 317 | 280 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 318 | 281 | Australian Babhul | <i>Acacia auriculiformis</i> | 3   | 35 | To be removed  | Falling within excavation line  |
| 319 | 282 | Shemat            | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 320 | 283 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 321 | 284 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 322 | 285 | Shemat            | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 323 | 286 | Palas             | <i>Butea monosperma</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 324 | 287 | Palas             | <i>Butea monosperma</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 325 | 288 | Pipri             | <i>Ficus amplissima</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 326 | 289 | Narikel           | <i>Pterygota alata</i>       | 5   | 60 | To be retained | Falling outside excavation line |
| 327 | 290 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 328 | 291 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 329 | 292 | Rain tree         | <i>Samanea saman</i>         | 5   | 35 | To be removed  | Falling within excavation line  |
| 330 | 293 | Bhokar            | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 331 | 294 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 332 | 295 | Palas             | <i>Butea monosperma</i>      | 2   | 35 | To be removed  | Falling within excavation line  |
| 333 | 296 | Palas             | <i>Butea monosperma</i>      | 1.5 | 10 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                              |     |    |               |                                |
|-----|-----|-------------------|------------------------------|-----|----|---------------|--------------------------------|
| 334 | 297 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 335 | 298 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 336 | 299 | Bhokar            | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 337 | 300 | Australian Babbul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed | Falling within excavation line |
| 338 | 301 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 339 | 302 | Bhokar            | <i>Cordia dichotoma</i>      | 2   | 35 | To be removed | Falling within excavation line |
| 340 | 303 | Gulmohar          | <i>Delonix regia</i>         | 1   | 10 | To be removed | Falling within excavation line |
| 341 | 304 | Shemat            | <i>Lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 342 | 305 | Rain tree         | <i>Samanea saman</i>         | 2   | 45 | To be removed | Falling within excavation line |
| 343 | 306 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 344 | 307 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 345 | 308 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 346 | 309 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 347 | 310 | Amba (Dead)       | <i>Mangifera indica</i>      | 8   | 25 | To be removed | Falling within excavation line |
| 348 | 311 | Rain tree         | <i>Samanea saman</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 349 | 312 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 350 | 313 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 351 | 314 | Amba              | <i>Mangifera indica</i>      | 2   | 35 | To be removed | Falling within excavation line |
| 352 | 315 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 353 | 316 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 354 | 317 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be removed | Falling within excavation line |
| 355 | 318 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 356 | 319 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 357 | 320 | Shemat            | <i>Lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 358 | 321 | Bhokar            | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 359 | 322 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 10 | To be removed | Falling within excavation line |
| 360 | 323 | Shemat            | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 361 | 324 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                              |     |    |                |                                 |
|-----|-----|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 362 | 325 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 363 | 326 | Gulmohar          | <i>Delonix regia</i>         | 2   | 35 | To be removed  | Falling within excavation line  |
| 364 | 327 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be removed  | Falling within excavation line  |
| 365 | 328 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 366 | 329 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 367 | 330 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 368 | 331 | Gulmohar          | <i>Delonix regia</i>         | 2   | 35 | To be removed  | Falling within excavation line  |
| 369 | 332 | Bivla             | <i>Pterocarpus marsupium</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 370 | 333 | Kukar             | <i>Sterculia guttata</i>     | 2   | 35 | To be removed  | Falling within excavation line  |
| 371 | 334 | Shemat            | <i>Lannea coromandelica</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 372 | 335 | Shemat            | <i>Lannea coromandelica</i>  | 5   | 35 | To be removed  | Falling within excavation line  |
| 373 | 336 | Atrun             | <i>Flacourtia montana</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 374 | 337 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 375 | 338 | Australian Babhul | <i>Acacia auriculiformis</i> | 3   | 35 | To be removed  | Falling within excavation line  |
| 376 | 339 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 35 | To be removed  | Falling within excavation line  |
| 377 | 340 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 378 | 341 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 379 | 342 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 380 | 343 | Amba              | <i>Mangifera indica</i>      | 5   | 35 | To be removed  | Falling within excavation line  |
| 381 | 344 | Amba              | <i>Mangifera indica</i>      | 5   | 35 | To be removed  | Falling within excavation line  |
| 382 | 345 | Amba (Dead)       | <i>Mangifera indica</i>      | 5   | 15 | To be removed  | Falling within excavation line  |
| 383 | 346 | Australian Babhul | <i>Acacia auriculiformis</i> | 1   | 15 | To be removed  | Falling within excavation line  |
| 384 | 347 | Amba              | <i>Mangifera indica</i>      | 5   | 45 | To be removed  | Falling within excavation line  |
| 385 | 348 | Amba              | <i>Mangifera indica</i>      | 5   | 45 | To be removed  | Falling within excavation line  |
| 386 | 349 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1   | 10 | To be removed  | Falling within excavation line  |
| 387 | 350 | Rain tree         | <i>Samanea saman</i>         | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 388 | 351 | Rain tree         | <i>Samanea saman</i>         | 1.5 | 25 | To be retained | Falling outside excavation line |
| 389 | 352 | Amba              | <i>Mangifera indica</i>      | 5   | 45 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                                |     |    |                |                                 |
|-----|-----|----------------|--------------------------------|-----|----|----------------|---------------------------------|
| 390 | 353 | Kate savar     | <i>Bombax ceiba</i>            | 2   | 45 | To be retained | Falling outside excavation line |
| 391 | 354 | Karanj         | <i>Pongamia pinnata</i>        | 1   | 10 | To be removed  | Falling within excavation line  |
| 392 | 355 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1   | 10 | To be removed  | Falling within excavation line  |
| 393 | 356 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 394 | 357 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 395 | 358 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1   | 15 | To be retained | Falling outside excavation line |
| 396 | 359 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 397 | 360 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1   | 15 | To be retained | Falling outside excavation line |
| 398 | 361 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 399 | 362 | Shivan         | <i>Gmelina arborea</i>         | 1.5 | 25 | To be retained | Falling outside excavation line |
| 400 | 363 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 401 | 364 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1.5 | 10 | To be retained | Falling outside excavation line |
| 402 | 365 | Kamala         | <i>Mallotus philippines</i>    | 1   | 10 | To be retained | Falling outside excavation line |
| 403 | 366 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 404 | 367 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 405 | 368 | Vavla          | <i>Holoptela integrifolia</i>  | 1   | 10 | To be retained | Falling outside excavation line |
| 406 | 369 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 407 | 370 | Karanj         | <i>Pongamia pinnata</i>        | 2   | 35 | To be retained | Falling outside excavation line |
| 408 | 371 | Kate savar     | <i>Bombax ceiba</i>            | 2   | 25 | To be retained | Falling outside excavation line |
| 409 | 372 | Kumkum         | <i>Mallotus philippinensis</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 410 | 373 | Shemat         | <i>Lannea coromandelica</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 411 | 374 | Kahandol       | <i>Sterculia urens</i>         | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 412 | 375 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 413 | 376 | Amba           | <i>Mangifera indica</i>        | 10  | 45 | To be removed  | Falling within excavation line  |
| 414 | 377 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 415 | 378 | Tendu          | <i>Diospyros melanoxylon</i>   | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 416 | 379 | Rain tree      | <i>Samanea saman</i>           | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 417 | 380 | Amba           | <i>Mangifera indica</i>        | 5   | 35 | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                              |     |    |               |                                |
|-----|-----|---------------|------------------------------|-----|----|---------------|--------------------------------|
| 418 | 381 | Kate savar    | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 419 | 382 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 420 | 383 | Kate savar    | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 421 | 384 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 422 | 385 | Bhokar        | <i>Cordia dichotoma</i>      | 1   | 10 | To be removed | Falling within excavation line |
| 423 | 386 | Kate savar    | <i>Bombax ceiba</i>          | 2   | 25 | To be removed | Falling within excavation line |
| 424 | 387 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 425 | 388 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 426 | 389 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 427 | 390 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 428 | 391 | Asana         | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 429 | 392 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 430 | 393 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 431 | 394 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 432 | 395 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 433 | 396 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 434 | 397 | Asana         | <i>Pterocarpus marsupium</i> | 2   | 15 | To be removed | Falling within excavation line |
| 435 | 398 | Charcoal tree | <i>Trema orientalis</i>      | 1   | 10 | To be removed | Falling within excavation line |
| 436 | 399 | Karanj        | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 437 | 400 | Kate savar    | <i>Bombax ceiba</i>          | 1   | 10 | To be removed | Falling within excavation line |
| 438 | 401 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be removed | Falling within excavation line |
| 439 | 402 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be removed | Falling within excavation line |
| 440 | 403 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 441 | 404 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 442 | 405 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 443 | 406 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 444 | 407 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 445 | 408 | Shemat        | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |             |                              |     |    |               |                                |
|-----|-----|-------------|------------------------------|-----|----|---------------|--------------------------------|
| 446 | 409 | Shemat      | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 447 | 410 | Shemat      | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 448 | 411 | Shemat      | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 449 | 412 | Shemat      | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 450 | 413 | Shemat      | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 451 | 414 | Shemat      | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 452 | 415 | Shemat      | <i>Lannea coromandelica</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 453 | 416 | Asana       | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 454 | 417 | Shemat      | <i>Lannea coromandelica</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 455 | 418 | Amba (Dead) | <i>Mangifera indica</i>      | 2   | 10 | To be removed | Falling within excavation line |
| 456 | 419 | Kate savar  | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 457 | 420 | Amba        | <i>Mangifera indica</i>      | 5   | 35 | To be removed | Falling within excavation line |
| 458 | 421 | Kate savar  | <i>Bombax ceiba</i>          | 2   | 15 | To be removed | Falling within excavation line |
| 459 | 422 | Amba        | <i>Mangifera indica</i>      | 5   | 35 | To be removed | Falling within excavation line |
| 460 | 423 | Kate savar  | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 461 | 424 | Kahandol    | <i>Sterculia urens</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 462 | 425 | Kahandol    | <i>Sterculia urens</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 463 | 426 | Dhaman      | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 464 | 427 | Amba        | <i>Mangifera indica</i>      | 5   | 35 | To be removed | Falling within excavation line |
| 465 | 428 | Bhokar      | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 466 | 429 | Amba (Dead) | <i>Mangifera indica</i>      | 2   | 35 | To be removed | Falling within excavation line |
| 467 | 430 | Kahandol    | <i>Sterculia urens</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 468 | 431 | Dhaman      | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 469 | 432 | Asana       | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 470 | 433 | Kate savar  | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 471 | 434 | Dhaman      | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed | Falling within excavation line |
| 472 | 435 | Kate savar  | <i>Bombax ceiba</i>          | 5   | 45 | To be removed | Falling within excavation line |
| 473 | 436 | Shemat      | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                              |     |    |               |                                |
|-----|-----|------------|------------------------------|-----|----|---------------|--------------------------------|
| 474 | 437 | Shemat     | <i>Lannea coromandelica</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 475 | 438 | Shemat     | <i>Lannea coromandelica</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 476 | 439 | Shemat     | <i>Lannea coromandelica</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 477 | 440 | Shemat     | <i>Lannea coromandelica</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 478 | 441 | Shemat     | <i>Lannea coromandelica</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 479 | 442 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 480 | 443 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 481 | 444 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 482 | 445 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 483 | 446 | Bhokar     | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 484 | 447 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 485 | 448 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 486 | 449 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 487 | 450 | Bhokar     | <i>Cordia dichotoma</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 488 | 451 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 489 | 452 | Shemat     | <i>Lannea coromandelica</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 490 | 453 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 491 | 454 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 492 | 455 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 493 | 456 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 494 | 457 | Kate savar | <i>Bombax ceiba</i>          | 5   | 45 | To be removed | Falling within excavation line |
| 495 | 458 | Shemat     | <i>Lannea coromandelica</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 496 | 459 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 497 | 460 | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 498 | 461 | Bhokar     | <i>Cordia dichotoma</i>      | 1   | 10 | To be removed | Falling within excavation line |
| 499 | 462 | Bor        | <i>Ziziphus mauritiana</i>   | 1   | 10 | To be removed | Falling within excavation line |
| 500 | 463 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 10 | To be removed | Falling within excavation line |
| 501 | 464 | Rain tree  | <i>Samanea saman</i>         | 1   | 10 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |               |                           |     |    |                |                                 |
|-----|-----|---------------|---------------------------|-----|----|----------------|---------------------------------|
| 502 | 465 | Narikel       | <i>Pterygota alata</i>    | 2   | 35 | To be removed  | Falling within excavation line  |
| 503 | 466 | Karanj        | <i>Pongamia pinnata</i>   | 2   | 25 | To be removed  | Falling within excavation line  |
| 504 | 467 | Charcoal tree | <i>Trema orientalis</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 505 | 468 | Narikel       | <i>Pterygota alata</i>    | 8   | 50 | To be retained | Falling outside excavation line |
| 506 | 469 | Narikel       | <i>Pterygota alata</i>    | 8   | 50 | To be retained | Falling outside excavation line |
| 507 | 470 | Rain tree     | <i>Samanea saman</i>      | 10  | 50 | To be removed  | Falling within excavation line  |
| 508 | 471 | Narikel       | <i>Pterygota alata</i>    | 1   | 15 | To be removed  | Falling within excavation line  |
| 509 | 472 | Kate savar    | <i>Bombax ceiba</i>       | 2   | 25 | To be removed  | Falling within excavation line  |
| 510 | 473 | Vaivarna      | <i>Crataeva religiosa</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 511 | 474 | Vaivarna      | <i>Crataeva religiosa</i> | 1   | 10 | To be removed  | Falling within excavation line  |
| 512 | 475 | Narikel       | <i>Pterygota alata</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 513 | 476 | Rain tree     | <i>Samanea saman</i>      | 5   | 50 | To be removed  | Falling within excavation line  |
| 514 | 477 | Dhaman        | <i>Grewia tiliaefolia</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 515 | 478 | Dhaman        | <i>Grewia tiliaefolia</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 516 | 479 | Narikel       | <i>Pterygota alata</i>    | 8   | 10 | To be retained | Falling outside excavation line |
| 517 | 480 | Dhaman        | <i>Grewia tiliaefolia</i> | 1   | 10 | To be removed  | Falling within excavation line  |
| 518 | 481 | Apta          | <i>Bauhinia racemosa</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 519 | 482 | Kate savar    | <i>Bombax ceiba</i>       | 1   | 10 | To be removed  | Falling within excavation line  |
| 520 | 483 | Rain tree     | <i>Samanea saman</i>      | 5   | 50 | To be removed  | Falling within excavation line  |
| 521 | 484 | Vaivarna      | <i>Crataeva religiosa</i> | 1   | 10 | To be removed  | Falling within excavation line  |
| 522 | 485 | Dhaman        | <i>Grewia tiliaefolia</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 523 | 486 | Vaivarna      | <i>Crataeva religiosa</i> | 1   | 10 | To be removed  | Falling within excavation line  |
| 524 | 487 | Dhaman        | <i>Grewia tiliaefolia</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 525 | 488 | Dhaman        | <i>Grewia tiliaefolia</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 526 | 489 | Dhaman        | <i>Grewia tiliaefolia</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 527 | 490 | Dhaman        | <i>Grewia tiliaefolia</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 528 | 491 | Dhaman        | <i>Grewia tiliaefolia</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 529 | 492 | Narikel       | <i>Pterygota alata</i>    | 1   | 15 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                        |                             |     |    |               |                                |
|-----|-----|------------------------|-----------------------------|-----|----|---------------|--------------------------------|
| 530 | 493 | Dhaman                 | <i>Grewia tiliaefolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 531 | 494 | Dhaman                 | <i>Grewia tiliaefolia</i>   | 2   | 35 | To be removed | Falling within excavation line |
| 532 | 495 | Charcoal tree          | <i>Trema orientalis</i>     | 1   | 10 | To be removed | Falling within excavation line |
| 533 | 496 | Tad                    | <i>Borassus flabellifer</i> | 8   | 15 | To be removed | Falling within excavation line |
| 534 | 497 | Dhaman                 | <i>Grewia tiliaefolia</i>   | 8   | 35 | To be removed | Falling within excavation line |
| 535 | 498 | Bhokar                 | <i>Cordia dichotoma</i>     | 5   | 25 | To be removed | Falling within excavation line |
| 536 | 499 | Kate savar             | <i>Bombax ceiba</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 537 | 500 | Jambhul (Dead)         | <i>Syzygium cumini</i>      | 2   | 15 | To be removed | Falling within excavation line |
| 538 | 501 | Kakad                  | <i>Garuga pinnata</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 539 | 502 | Kakad                  | <i>Garuga pinnata</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 540 | 503 | Dhaman                 | <i>Grewia tiliaefolia</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 541 | 504 | Karanj                 | <i>Pongamia pinnata</i>     | 5   | 25 | To be removed | Falling within excavation line |
| 542 | 505 | Karanj                 | <i>Pongamia pinnata</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 543 | 506 | Kakad                  | <i>Garuga pinnata</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 544 | 507 | Shemat                 | <i>Lannea coromandelica</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 545 | 508 | Dhaman                 | <i>Grewia tiliaefolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 546 | 509 | Dhaman                 | <i>Grewia tiliaefolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 547 | 510 | Shemat                 | <i>Lannea coromandelica</i> | 2   | 35 | To be removed | Falling within excavation line |
| 548 | 511 | Shemat                 | <i>Lannea coromandelica</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 549 | 512 | Vaivarna               | <i>Crataeva religiosa</i>   | 1   | 10 | To be removed | Falling within excavation line |
| 550 | 513 | Shirish                | <i>Albizzia lebbek</i>      | 1.5 | 35 | To be removed | Falling within excavation line |
| 551 | 514 | Vaivarna               | <i>Crataeva religiosa</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 552 | 515 | Kate savar             | <i>Bombax ceiba</i>         | 1.5 | 35 | To be removed | Falling within excavation line |
| 553 | 516 | Dhaman                 | <i>Grewia tiliaefolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 554 | 517 | Kate savar             | <i>Bombax ceiba</i>         | 10  | 45 | To be removed | Falling within excavation line |
| 555 | 518 | Kakad                  | <i>Garuga pinnata</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 556 | 519 | Kakad                  | <i>Garuga pinnata</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 557 | 520 | Singapore Chery (Dead) | <i>Muntingia calabura</i>   | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                             |     |     |                |                                 |
|-----|-----|----------------|-----------------------------|-----|-----|----------------|---------------------------------|
| 558 | 521 | Kate savar     | <i>Bombax ceiba</i>         | 1.5 | 15  | To be retained | Falling outside excavation line |
| 559 | 522 | Kate savar     | <i>Bombax ceiba</i>         | 1.5 | 15  | To be retained | Falling outside excavation line |
| 560 | 523 | Umber          | <i>Ficus glomerata</i>      | 1.5 | 15  | To be retained | Falling outside excavation line |
| 561 | 524 | Dhaman         | <i>Grewia tiliaefolia</i>   | 2   | 35  | To be retained | Falling outside excavation line |
| 562 | 525 | Vilayti Chinch | <i>Pithecellobium dulce</i> | 2   | 25  | To be retained | Falling outside excavation line |
| 563 | 526 | Vilayti Chinch | <i>Pithecellobium dulce</i> | 2   | 35  | To be retained | Falling outside excavation line |
| 564 | 527 | Shemat         | <i>Lannea coromandelica</i> | 2   | 35  | To be retained | Falling outside excavation line |
| 565 | 528 | Dhaman         | <i>Grewia tiliaefolia</i>   | 1.5 | 35  | To be retained | Falling outside excavation line |
| 566 | 529 | Dhaman         | <i>Grewia tiliaefolia</i>   | 1.5 | 25  | To be retained | Falling outside excavation line |
| 567 | 530 | Kate savar     | <i>Bombax ceiba</i>         | 1.5 | 25  | To be retained | Falling outside excavation line |
| 568 | 531 | Kate savar     | <i>Bombax ceiba</i>         | 1.5 | 10  | To be removed  | Falling within excavation line  |
| 569 | 532 | Bor            | <i>Ziziphus mauritiana</i>  | 1.5 | 15  | To be removed  | Falling within excavation line  |
| 570 | 533 | Kate savar     | <i>Bombax ceiba</i>         | 2   | 25  | To be removed  | Falling within excavation line  |
| 571 | 534 | Toran          | <i>Toran</i>                | 2   | 25  | To be removed  | Falling within excavation line  |
| 572 | 535 | Chinch         | <i>Chinch</i>               | 8   | 35  | To be removed  | Falling within excavation line  |
| 573 | 536 | Karanj         | <i>Karanj</i>               | 1.5 | 15  | To be removed  | Falling within excavation line  |
| 574 | 537 | Dhaman         | <i>Grewia tiliaefolia</i>   | 1.5 | 25  | To be removed  | Falling within excavation line  |
| 575 | 538 | Dhaman         | <i>Grewia tiliaefolia</i>   | 1.5 | 25  | To be removed  | Falling within excavation line  |
| 576 | 539 | Bhokar         | <i>Cordia dichotoma</i>     | 2   | 25  | To be removed  | Falling within excavation line  |
| 577 | 540 | Dhaman         | <i>Grewia tiliaefolia</i>   | 2   | 35  | To be removed  | Falling within excavation line  |
| 578 | 541 | Kate savar     | <i>Bombax ceiba</i>         | 1.5 | 25  | To be removed  | Falling within excavation line  |
| 579 | 542 | Charcoal tree  | <i>Trema orientalis</i>     | 2   | 2-3 | To be removed  | Falling within excavation line  |
| 580 | 543 | Kate savar     | <i>Bombax ceiba</i>         | 2   | 35  | To be removed  | Falling within excavation line  |
| 581 | 544 | Dhaman         | <i>Grewia tiliaefolia</i>   | 2   | 35  | To be removed  | Falling within excavation line  |
| 582 | 545 | Shivan         | <i>Gmelina arborea</i>      | 1.5 | 25  | To be removed  | Falling within excavation line  |
| 583 | 546 | Dhaman         | <i>Grewia tiliaefolia</i>   | 1.5 | 25  | To be removed  | Falling within excavation line  |
| 584 | 547 | Shivan         | <i>Gmelina arborea</i>      | 1.5 | 25  | To be removed  | Falling within excavation line  |
| 585 | 548 | Dhaman         | <i>Grewia tiliaefolia</i>   | 1.5 | 25  | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |            |                               |     |    |               |                                |
|-----|-----|------------|-------------------------------|-----|----|---------------|--------------------------------|
| 586 | 549 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 587 | 550 | Palas      | <i>Butea monosperma</i>       | 2   | 35 | To be removed | Falling within excavation line |
| 588 | 551 | Kate savar | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |
| 589 | 552 | Apta       | <i>Bauhinia racemosa</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 590 | 553 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 10 | To be removed | Falling within excavation line |
| 591 | 554 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 592 | 555 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 593 | 556 | Kate savar | <i>Bombax ceiba</i>           | 5   | 35 | To be removed | Falling within excavation line |
| 594 | 557 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 595 | 558 | Bhokar     | <i>Cordia dichotoma</i>       | 2   | 35 | To be removed | Falling within excavation line |
| 596 | 559 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed | Falling within excavation line |
| 597 | 560 | Shemat     | <i>Lannea coromandelica</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 598 | 561 | Kate savar | <i>Bombax ceiba</i>           | 5   | 45 | To be removed | Falling within excavation line |
| 599 | 562 | Kahandol   | <i>Sterculia urens</i>        | 2   | 35 | To be removed | Falling within excavation line |
| 600 | 563 | Vavla      | <i>Holoptela integrifolia</i> | 5   | 45 | To be removed | Falling within excavation line |
| 601 | 564 | Kate savar | <i>Bombax ceiba</i>           | 8   | 45 | To be removed | Falling within excavation line |
| 602 | 565 | Shemat     | <i>Lannea coromandelica</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 603 | 566 | Kate savar | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |
| 604 | 567 | Moha       | <i>Madhuca indica</i>         | 1.5 | 25 | To be removed | Falling within excavation line |
| 605 | 568 | Shemat     | <i>Lannea coromandelica</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 606 | 569 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 607 | 570 | Shemat     | <i>Lannea coromandelica</i>   | 2   | 35 | To be removed | Falling within excavation line |
| 608 | 571 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 35 | To be removed | Falling within excavation line |
| 609 | 572 | Vaivarna   | <i>Crataeva religiosa</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 610 | 573 | Shemat     | <i>Lannea coromandelica</i>   | 2   | 35 | To be removed | Falling within excavation line |
| 611 | 574 | Kate savar | <i>Bombax ceiba</i>           | 2   | 45 | To be removed | Falling within excavation line |
| 612 | 575 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 45 | To be removed | Falling within excavation line |
| 613 | 576 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                        |                              |     |    |               |                                |
|-----|-----|------------------------|------------------------------|-----|----|---------------|--------------------------------|
| 614 | 577 | Asana                  | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 615 | 578 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 616 | 579 | Pimpal                 | <i>Ficus religiosa</i>       | 5   | 45 | To be removed | Falling within excavation line |
| 617 | 580 | Amba                   | <i>Mangifera indica</i>      | 10  | 45 | To be removed | Falling within excavation line |
| 618 | 581 | Amba                   | <i>Mangifera indica</i>      | 8   | 45 | To be removed | Falling within excavation line |
| 619 | 582 | Singapore Chery (Dead) | <i>Muntingia calabura</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 620 | 583 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 621 | 584 | Shemat                 | <i>Lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 622 | 585 | Kahandol               | <i>Sterculia urens</i>       | 2   | 35 | To be removed | Falling within excavation line |
| 623 | 586 | Kate savar             | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 624 | 587 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 625 | 588 | Asana                  | <i>Pterocarpus marsupium</i> | 2   | 35 | To be removed | Falling within excavation line |
| 626 | 589 | Dhaman (Dead)          | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 627 | 590 | Kate savar             | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 628 | 591 | Shemat                 | <i>Lannea coromandelica</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 629 | 592 | Not ID                 | Not ID                       | 2   | 35 | To be removed | Falling within excavation line |
| 630 | 593 | Kate savar             | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 631 | 594 | Palas                  | <i>Butea monosperma</i>      | 5   | 35 | To be removed | Falling within excavation line |
| 632 | 595 | Singapore Chery (Dead) | <i>Muntingia calabura</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 633 | 596 | Not ID                 | Not ID                       | 2   | 35 | To be removed | Falling within excavation line |
| 634 | 597 | Singapore Chery (Dead) | <i>Muntingia calabura</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 635 | 598 | Shemat                 | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 636 | 599 | Rain tree              | <i>Samanea saman</i>         | 5   | 35 | To be removed | Falling within excavation line |
| 637 | 600 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed | Falling within excavation line |
| 638 | 601 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 639 | 602 | Umber                  | <i>Ficus glomerata</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 640 | 603 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 641 | 604 | Asana                  | <i>Pterocarpus marsupium</i> | 2   | 35 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                              |     |    |                |                                 |
|-----|-----|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 642 | 605 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed  | Falling within excavation line  |
| 643 | 606 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed  | Falling within excavation line  |
| 644 | 607 | Bhokar            | <i>Cordia dichotoma</i>      | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 645 | 608 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 646 | 609 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 647 | 610 | Rain tree         | <i>Samanea saman</i>         | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 648 | 611 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 649 | 612 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed  | Falling within excavation line  |
| 650 | 613 | Narikel           | <i>Pterygota alata</i>       | 8   | 50 | To be retained | Falling outside excavation line |
| 651 | 614 | Narikel           | <i>Pterygota alata</i>       | 5   | 50 | To be retained | Falling outside excavation line |
| 652 | 615 | Narikel           | <i>Pterygota alata</i>       | 5   | 50 | To be retained | Falling outside excavation line |
| 653 | 616 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 654 | 617 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 655 | 618 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 656 | 619 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 657 | 620 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 658 | 621 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 659 | 622 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 660 | 623 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 661 | 624 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 662 | 625 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 663 | 626 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 664 | 627 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 665 | 628 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 666 | 629 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 667 | 630 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 668 | 631 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 669 | 632 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                              |     |    |               |                                |
|-----|-----|-------------------|------------------------------|-----|----|---------------|--------------------------------|
| 670 | 633 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed | Falling within excavation line |
| 671 | 634 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed | Falling within excavation line |
| 672 | 635 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed | Falling within excavation line |
| 673 | 636 | Bartondi          | <i>Morinda pubescens</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 674 | 637 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed | Falling within excavation line |
| 675 | 638 | Acacia mangium    | <i>Acacia mangium</i>        | 1.5 | 35 | To be removed | Falling within excavation line |
| 676 | 639 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed | Falling within excavation line |
| 677 | 640 | Tad               | <i>Borassus flabellifer</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 678 | 641 | Acacia mangium    | <i>Acacia mangium</i>        | 5   | 45 | To be removed | Falling within excavation line |
| 679 | 642 | Vilayti Chinch    | <i>Pithecellobium dulce</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 680 | 643 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 681 | 644 | Khair             | <i>Acacia catechuoides</i>   | 5   | 35 | To be removed | Falling within excavation line |
| 682 | 645 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed | Falling within excavation line |
| 683 | 646 | Rain tree         | <i>Samanea saman</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 684 | 647 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed | Falling within excavation line |
| 685 | 648 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed | Falling within excavation line |
| 686 | 649 | Acacia mangium    | <i>Acacia mangium</i>        | 2   | 45 | To be removed | Falling within excavation line |
| 687 | 650 | Acacia mangium    | <i>Acacia mangium</i>        | 2   | 35 | To be removed | Falling within excavation line |
| 688 | 651 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 689 | 652 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed | Falling within excavation line |
| 690 | 653 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 691 | 654 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 692 | 655 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 693 | 656 | Dhaman (Dead)     | <i>Grewia tiliaefolia</i>    | 5   | 25 | To be removed | Falling within excavation line |
| 694 | 657 | Acacia mangium    | <i>Acacia mangium</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 695 | 658 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 696 | 659 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed | Falling within excavation line |
| 697 | 660 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                              |     |    |                |                                 |
|-----|-----|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 698 | 661 | Australian Babbul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 699 | 662 | Australian Babbul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 700 | 663 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 701 | 664 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 702 | 665 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 703 | 666 | Australian Babbul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 704 | 667 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 705 | 668 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 706 | 669 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed  | Falling within excavation line  |
| 707 | 670 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 708 | 671 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 709 | 672 | Kumbh             | <i>Careya arborea</i>        | 2   | 35 | To be removed  | Falling within excavation line  |
| 710 | 673 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 45 | To be removed  | Falling within excavation line  |
| 711 | 674 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 712 | 675 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 713 | 676 | Subabhul          | <i>Leucaena leucocephala</i> | 5   | 45 | To be removed  | Falling within excavation line  |
| 714 | 677 | Vilayti Chinch    | <i>Pithecellobium dulce</i>  | 8   | 45 | To be removed  | Falling within excavation line  |
| 715 | 678 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 716 | 679 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 717 | 680 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 718 | 681 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 719 | 682 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be removed  | Falling within excavation line  |
| 720 | 683 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 721 | 684 | Kate savar        | <i>Bombax ceiba</i>          | 5   | 35 | To be removed  | Falling within excavation line  |
| 722 | 685 | Rain tree         | <i>Samanea saman</i>         | 2   | 35 | To be removed  | Falling within excavation line  |
| 723 | 686 | Kahandol          | <i>Sterculia urens</i>       | 1.5 | 25 | To be retained | Falling outside excavation line |
| 724 | 687 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be retained | Falling outside excavation line |
| 725 | 688 | Karvat            | <i>Ficus asperrima</i>       | 1.5 | 25 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                        |                              |     |    |                |                                 |
|-----|-----|------------------------|------------------------------|-----|----|----------------|---------------------------------|
| 726 | 689 | Karanj                 | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be retained | Falling outside excavation line |
| 727 | 690 | Kate savar             | <i>Bombax ceiba</i>          | 2   | 35 | To be removed  | Falling within excavation line  |
| 728 | 691 | Amba                   | <i>Mangifera indica</i>      | 8   | 35 | To be removed  | Falling within excavation line  |
| 729 | 692 | Kahandol               | <i>Sterculia urens</i>       | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 730 | 693 | Shemat                 | <i>Lannea coromandelica</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 731 | 694 | Asana                  | <i>Pterocarpus marsupium</i> | 5   | 35 | To be removed  | Falling within excavation line  |
| 732 | 695 | Kate savar             | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 733 | 696 | Subabhul               | <i>Leucaena leucocephala</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 734 | 697 | Asana                  | <i>Pterocarpus marsupium</i> | 2   | 25 | To be removed  | Falling within excavation line  |
| 735 | 698 | Asana                  | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 736 | 699 | Subabhul               | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 737 | 700 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 738 | 701 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 739 | 702 | Subabhul               | <i>Leucaena leucocephala</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 740 | 703 | Subabhul               | <i>Leucaena leucocephala</i> | 5   | 45 | To be removed  | Falling within excavation line  |
| 741 | 704 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 742 | 705 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 743 | 706 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 744 | 707 | Australian Babbul      | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 745 | 708 | Asana                  | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 746 | 709 | Asana                  | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 747 | 710 | Singapore Chery (Dead) | <i>Muntingia calabura</i>    | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 748 | 711 | Karanj                 | <i>Pongamia pinnata</i>      | 1   | 15 | To be removed  | Falling within excavation line  |
| 749 | 712 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 750 | 713 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 751 | 714 | Asana                  | <i>Pterocarpus marsupium</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 752 | 715 | Asana                  | <i>Pterocarpus marsupium</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 753 | 716 | Bhokar                 | <i>Cordia dichotoma</i>      | 2   | 45 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                              |     |    |                |                                 |
|-----|-----|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 754 | 717 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 755 | 718 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 756 | 719 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 757 | 720 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 758 | 721 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 759 | 722 | Vilayti Chinch    | <i>Pithecellobium dulce</i>  | 2   | 45 | To be removed  | Falling within excavation line  |
| 760 | 723 | Karanj            | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 761 | 724 | Karanj            | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 762 | 725 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 763 | 726 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 764 | 727 | Australian Babhul | <i>Acacia auriculiformis</i> | 1   | 35 | To be retained | Falling outside excavation line |
| 765 | 728 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 766 | 729 | Karanj            | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be retained | Falling outside excavation line |
| 767 | 730 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 768 | 731 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 769 | 732 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 770 | 733 | Amba              | <i>Mangifera indica</i>      | 5   | 35 | To be retained | Falling outside excavation line |
| 771 | 734 | Karanj            | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be retained | Falling outside excavation line |
| 772 | 735 | Narikel           | <i>Pterygota alata</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 773 | 736 | Amba (Dead)       | <i>Mangifera indica</i>      | 5   | 15 | To be retained | Falling outside excavation line |
| 774 | 737 | Karanj            | <i>Pongamia pinnata</i>      | 2   | 45 | To be retained | Falling outside excavation line |
| 775 | 738 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 776 | 739 | Karanj            | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be retained | Falling outside excavation line |
| 777 | 740 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 778 | 741 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be retained | Falling outside excavation line |
| 779 | 742 | Karanj            | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 780 | 743 | Amba              | <i>Mangifera indica</i>      | 2   | 35 | To be retained | Falling outside excavation line |
| 781 | 744 | Kharoti           | <i>Streblus asper</i>        | 2   | 45 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                              |     |    |                |                                 |
|-----|-----|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 782 | 745 | Narikel           | <i>Pterygota alata</i>       | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 783 | 746 | Amba              | <i>Mangifera indica</i>      | 5   | 35 | To be removed  | Falling within excavation line  |
| 784 | 747 | Narikel           | <i>Pterygota alata</i>       | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 785 | 748 | Karvat            | <i>Ficus asperrima</i>       | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 786 | 749 | Amba              | <i>Mangifera indica</i>      | 10  | 45 | To be removed  | Falling within excavation line  |
| 787 | 750 | Kharoti           | <i>Streblus asper</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 788 | 751 | Amba              | <i>Mangifera indica</i>      | 10  | 35 | To be removed  | Falling within excavation line  |
| 789 | 752 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 790 | 753 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 791 | 754 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 792 | 755 | Vilayti Chinch    | <i>Pithecellobium dulce</i>  | 2   | 35 | To be removed  | Falling within excavation line  |
| 793 | 756 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 794 | 757 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 795 | 758 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 796 | 759 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 797 | 760 | Amba (Dead)       | <i>Mangifera indica</i>      | 5   | 25 | To be removed  | Falling within excavation line  |
| 798 | 761 | Amba (Dead)       | <i>Mangifera indica</i>      | 10  | 45 | To be removed  | Falling within excavation line  |
| 799 | 762 | Narikel           | <i>Pterygota alata</i>       | 5   | 50 | To be retained | Falling outside excavation line |
| 800 | 763 | Narikel           | <i>Pterygota alata</i>       | 5   | 50 | To be retained | Falling outside excavation line |
| 801 | 764 | Narikel           | <i>Pterygota alata</i>       | 5   | 50 | To be retained | Falling outside excavation line |
| 802 | 765 | Narikel           | <i>Pterygota alata</i>       | 2   | 50 | To be removed  | Falling within excavation line  |
| 803 | 766 | Amba              | <i>Mangifera indica</i>      | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 804 | 767 | Tad               | <i>Borassus flabellifer</i>  | 2   | 45 | To be removed  | Falling within excavation line  |
| 805 | 768 | Amba              | <i>Mangifera indica</i>      | 8   | 45 | To be removed  | Falling within excavation line  |
| 806 | 769 | Narikel           | <i>Pterygota alata</i>       | 8   | 50 | To be retained | Falling outside excavation line |
| 807 | 770 | Narikel           | <i>Pterygota alata</i>       | 5   | 50 | To be retained | Falling outside excavation line |
| 808 | 771 | Amba              | <i>Mangifera indica</i>      | 10  | 45 | To be removed  | Falling within excavation line  |
| 809 | 772 | Australian Babhul | <i>Acacia auriculiformis</i> | 1   | 10 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                 |                                |     |    |                |                                 |
|-----|------|-----------------|--------------------------------|-----|----|----------------|---------------------------------|
| 810 | 773  | Narikel         | <i>Pterygota alata</i>         | 8   | 50 | To be retained | Falling outside excavation line |
| 811 | 774  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 5   | 35 | To be retained | Falling outside excavation line |
| 812 | 774A | Toran           | <i>Ziziphus rugosa</i>         | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 813 | 775  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 8   | 35 | To be retained | Falling outside excavation line |
| 814 | 776  | Bhokar          | <i>Cordia dichotoma</i>        | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 815 | 777  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 5   | 45 | To be retained | Falling outside excavation line |
| 816 | 778  | Narikel         | <i>Pterygota alata</i>         | 10  | 50 | To be retained | Falling outside excavation line |
| 817 | 779  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 818 | 780  | Gunj            | <i>Adenantha pavonina</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 819 | 781  | Gulmohar        | <i>Delonix regia</i>           | 2   | 45 | To be removed  | Falling within excavation line  |
| 820 | 782  | Narikel         | <i>Pterygota alata</i>         | 8   | 50 | To be removed  | Falling within excavation line  |
| 821 | 783  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 822 | 784  | Rain tree       | <i>Samanea saman</i>           | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 823 | 785  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 824 | 786  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 825 | 787  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 826 | 788  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 827 | 789  | Narikel         | <i>Pterygota alata</i>         | 8   | 50 | To be removed  | Falling within excavation line  |
| 828 | 790  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 829 | 791  | Gulmohar        | <i>Delonix regia</i>           | 5   | 35 | To be removed  | Falling within excavation line  |
| 830 | 792  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 831 | 793  | Rain tree       | <i>Samanea saman</i>           | 5   | 45 | To be removed  | Falling within excavation line  |
| 832 | 794  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 833 | 795  | Rain tree       | <i>Samanea saman</i>           | 5   | 45 | To be removed  | Falling within excavation line  |
| 834 | 796  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 835 | 797  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 836 | 798  | Sonmohar        | <i>Peltophorum pterocarpum</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 837 | 799  | Gulmohar (Dead) | <i>Delonix regia</i>           | 5   | 35 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |                   |                                |     |    |                |                                 |
|-----|------|-------------------|--------------------------------|-----|----|----------------|---------------------------------|
| 838 | 800  | Narikel           | <i>Pterygota alata</i>         | 8   | 50 | To be removed  | Falling within excavation line  |
| 839 | 801  | Gulmohar          | <i>Delonix regia</i>           | 2   | 35 | To be removed  | Falling within excavation line  |
| 840 | 802  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 841 | 802A | Sonmohar          | <i>Peltophorum pterocarpum</i> | 2   | 15 | To be removed  | Falling within excavation line  |
| 842 | 803  | Dhaman            | <i>Grewia tiliaefolia</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 843 | 804  | Gulmohar          | <i>Delonix regia</i>           | 2   | 35 | To be removed  | Falling within excavation line  |
| 844 | 805  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 845 | 806  | Gulmohar          | <i>Delonix regia</i>           | 5   | 35 | To be removed  | Falling within excavation line  |
| 846 | 807  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 847 | 808  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 848 | 809  | Gulmohar          | <i>Delonix regia</i>           | 2   | 35 | To be removed  | Falling within excavation line  |
| 849 | 810  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 850 | 811  | Sonmohar          | <i>Peltophorum pterocarpum</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 851 | 812  | Rain tree         | <i>Samanea saman</i>           | 5   | 45 | To be removed  | Falling within excavation line  |
| 852 | 813  | Subabhul          | <i>Leucaena leucocephala</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 853 | 814  | Narikel           | <i>Pterygota alata</i>         | 10  | 50 | To be removed  | Falling within excavation line  |
| 854 | 815  | Kate savar        | <i>Bombax ceiba</i>            | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 855 | 816  | Narikel           | <i>Pterygota alata</i>         | 8   | 50 | To be removed  | Falling within excavation line  |
| 856 | 817  | Vilayti Chinch    | <i>Pithecellobium dulce</i>    | 5   | 35 | To be removed  | Falling within excavation line  |
| 857 | 818  | Tad               | <i>Borassus flabellifer</i>    | 5   | 50 | To be removed  | Falling within excavation line  |
| 858 | 819  | Kumbh             | <i>Careya arborea</i>          | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 859 | 820  | Australian Babhul | <i>Acacia auriculiformis</i>   | 1.5 | 35 | To be retained | Falling outside excavation line |
| 860 | 821  | Subabhul          | <i>Leucaena leucocephala</i>   | 2   | 35 | To be retained | Falling outside excavation line |
| 861 | 822  | Kate savar        | <i>Bombax ceiba</i>            | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 862 | 823  | Subabhul          | <i>Leucaena leucocephala</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 863 | 824  | Shemat            | <i>Lannea coromandelica</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 864 | 825  | Bor               | <i>Ziziphus mauritiana</i>     | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 865 | 826  | Amba              | <i>Mangifera indica</i>        | 10  | 45 | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                   |                               |     |    |                |                                 |
|-----|-----|-------------------|-------------------------------|-----|----|----------------|---------------------------------|
| 866 | 827 | Vavla             | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 867 | 828 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 868 | 829 | Shemat            | <i>Lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 869 | 830 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 870 | 831 | Karvat            | <i>Ficus asperrima</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 871 | 832 | Amba (Dead)       | <i>Mangifera indica</i>       | 10  | 45 | To be removed  | Falling within excavation line  |
| 872 | 833 | Amba              | <i>Mangifera indica</i>       | 5   | 45 | To be removed  | Falling within excavation line  |
| 873 | 834 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 25 | To be removed  | Falling within excavation line  |
| 874 | 835 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 45 | To be removed  | Falling within excavation line  |
| 875 | 836 | Kakad             | <i>Garuga pinnata</i>         | 2   | 35 | To be retained | Falling outside excavation line |
| 876 | 837 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 877 | 838 | Kahandol          | <i>Sterculia urens</i>        | 5   | 35 | To be retained | Falling outside excavation line |
| 878 | 839 | Amba (Dead)       | <i>Mangifera indica</i>       | 5   | 25 | To be removed  | Falling within excavation line  |
| 879 | 840 | Kakad             | <i>Garuga pinnata</i>         | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 880 | 841 | Kahandol          | <i>Sterculia urens</i>        | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 881 | 842 | Bhokar            | <i>Cordia dichotoma</i>       | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 882 | 843 | Kakad             | <i>Garuga pinnata</i>         | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 883 | 844 | Kakad             | <i>Garuga pinnata</i>         | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 884 | 845 | Kakad             | <i>Garuga pinnata</i>         | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 885 | 846 | Shemat            | <i>Lannea coromandelica</i>   | 1   | 15 | To be removed  | Falling within excavation line  |
| 886 | 847 | Vavla             | <i>Holoptela integrifolia</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 887 | 848 | Kumbh             | <i>Careya arborea</i>         | 2   | 25 | To be removed  | Falling within excavation line  |
| 888 | 849 | Kakad             | <i>Garuga pinnata</i>         | 2   | 25 | To be removed  | Falling within excavation line  |
| 889 | 850 | Kakad             | <i>Garuga pinnata</i>         | 2   | 15 | To be removed  | Falling within excavation line  |
| 890 | 851 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 891 | 852 | Dhaman            | <i>Grewia tiliaefolia</i>     | 2   | 35 | To be removed  | Falling within excavation line  |
| 892 | 853 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 893 | 854 | Dhaman            | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |      |            |                              |     |    |                |                                 |
|-----|------|------------|------------------------------|-----|----|----------------|---------------------------------|
| 894 | 855  | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 895 | 856  | Shemat     | <i>Lannea coromandelica</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 896 | 857  | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 897 | 858  | Amba       | <i>Mangifera indica</i>      | 5   | 45 | To be removed  | Falling within excavation line  |
| 898 | 859  | Tad        | <i>Borassus flabellifer</i>  | 5   | 60 | To be retained | Falling outside excavation line |
| 899 | 860  | Tetu       | <i>Oroxylum indicum</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 900 | 861  | Tetu       | <i>Oroxylum indicum</i>      | 1.5 | 20 | To be retained | Falling outside excavation line |
| 901 | 862  | Tetu       | <i>Oroxylum indicum</i>      | 1.5 | 10 | To be retained | Falling outside excavation line |
| 902 | 863  | Tad        | <i>Borassus flabellifer</i>  | 5   | 45 | To be retained | Falling outside excavation line |
| 903 | 864  | Asana      | <i>Pterocarpus marsupium</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 904 | 865  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 905 | 866  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 906 | 867  | Kate savar | <i>Bombax ceiba</i>          | 2   | 45 | To be removed  | Falling within excavation line  |
| 907 | 868  | Amba       | <i>Mangifera indica</i>      | 5   | 45 | To be removed  | Falling within excavation line  |
| 908 | 869  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 909 | 870  | Amba       | <i>Mangifera indica</i>      | 10  | 45 | To be retained | Falling outside excavation line |
| 910 | 870A | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 911 | 871  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 912 | 872  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 913 | 873  | Vaivarna   | <i>Crataeva religiosa</i>    | 1   | 10 | To be retained | Falling outside excavation line |
| 914 | 874  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be retained | Falling outside excavation line |
| 915 | 875  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 916 | 876  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be retained | Falling outside excavation line |
| 917 | 877  | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 918 | 878  | Vaivarna   | <i>Crataeva religiosa</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 919 | 879  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 920 | 880  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 921 | 881  | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |                |                              |     |    |                |                                 |
|-----|-----|----------------|------------------------------|-----|----|----------------|---------------------------------|
| 922 | 882 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 923 | 883 | Vaivarna       | <i>Crataeva religiosa</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 924 | 884 | Vaivarna       | <i>Crataeva religiosa</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 925 | 885 | Kala umber     | <i>Ficus hispida</i>         | 1.5 | 15 | To be retained | Falling outside excavation line |
| 926 | 886 | Subabhul       | <i>Leucaena leucocephala</i> | 5   | 45 | To be removed  | Falling within excavation line  |
| 927 | 887 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 928 | 888 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 929 | 889 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |
| 930 | 890 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 931 | 891 | Charcoal tree  | <i>Trema orientalis</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 932 | 892 | Charcoal tree  | <i>Trema orientalis</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 933 | 893 | Karvat         | <i>Ficus asperrima</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 934 | 894 | Karvat         | <i>Ficus asperrima</i>       | 2   | 20 | To be retained | Falling outside excavation line |
| 935 | 895 | Karvat         | <i>Ficus asperrima</i>       | 1.5 | 20 | To be retained | Falling outside excavation line |
| 936 | 896 | Charcoal tree  | <i>Trema orientalis</i>      | 2   | 35 | To be removed  | Falling within excavation line  |
| 937 | 897 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 938 | 898 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 939 | 899 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 940 | 900 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 941 | 901 | Kakad          | <i>Garuga pinnata</i>        | 2   | 25 | To be retained | Falling outside excavation line |
| 942 | 902 | Kakad          | <i>Garuga pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 943 | 903 | Kakad          | <i>Garuga pinnata</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 944 | 904 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 945 | 905 | Kakad          | <i>Garuga pinnata</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 946 | 906 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 947 | 907 | Karvat         | <i>Ficus asperrima</i>       | 1   | 10 | To be retained | Falling outside excavation line |
| 948 | 908 | Amba           | <i>Mangifera indica</i>      | 10  | 45 | To be retained | Falling outside excavation line |
| 949 | 909 | Kahandol       | <i>Sterculia urens</i>       | 1.5 | 20 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|     |     |              |                              |     |    |                |                                 |
|-----|-----|--------------|------------------------------|-----|----|----------------|---------------------------------|
| 950 | 910 | Kahandol     | <i>Sterculia urens</i>       | 1.5 | 20 | To be retained | Falling outside excavation line |
| 951 | 911 | Dhaman       | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 952 | 912 | Tambada kuda | <i>Wrightia arborea</i>      | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 953 | 913 | Dhaman       | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be removed  | Falling within excavation line  |
| 954 | 914 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 955 | 915 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 956 | 916 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 957 | 917 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 958 | 918 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 959 | 919 | Bherli Mad   | <i>Caryota urens</i>         | 2   | 45 | To be retained | Falling outside excavation line |
| 960 | 920 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 961 | 921 | shemat       | <i>lannea coromandelica</i>  | 1.5 | 10 | To be retained | Falling outside excavation line |
| 962 | 922 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 963 | 923 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 964 | 924 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 965 | 925 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 966 | 926 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 967 | 927 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 968 | 928 | Shemat       | <i>lannea coromandelica</i>  | 1   | 15 | To be removed  | Falling within excavation line  |
| 969 | 929 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 970 | 930 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 971 | 931 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 972 | 932 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 973 | 933 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 974 | 934 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 975 | 935 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 976 | 936 | Shemat       | <i>lannea coromandelica</i>  | 2   | 20 | To be removed  | Falling within excavation line  |
| 977 | 937 | Shemat       | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |     |          |                             |     |    |                |                                 |
|------|-----|----------|-----------------------------|-----|----|----------------|---------------------------------|
| 978  | 938 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 979  | 939 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 980  | 940 | Kahandol | <i>Sterculia urens</i>      | 1.5 | 20 | To be retained | Falling outside excavation line |
| 981  | 941 | Amba     | <i>Mangifera indica</i>     | 2   | 25 | To be retained | Falling outside excavation line |
| 982  | 942 | Shemat   | <i>lannea coromandelica</i> | 1   | 10 | To be retained | Falling outside excavation line |
| 983  | 943 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 984  | 944 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 985  | 945 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 986  | 946 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 987  | 947 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 988  | 948 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 989  | 949 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 990  | 950 | Shemat   | <i>lannea coromandelica</i> | 2   | 30 | To be removed  | Falling within excavation line  |
| 991  | 951 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 992  | 952 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 993  | 953 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 994  | 954 | Shemat   | <i>lannea coromandelica</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 995  | 955 | Shemat   | <i>lannea coromandelica</i> | 1   | 10 | To be retained | Falling outside excavation line |
| 996  | 956 | Karvat   | <i>Ficus asperrima</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 997  | 957 | Dhaman   | <i>Grewia tiliaefolia</i>   | 2   | 25 | To be retained | Falling outside excavation line |
| 998  | 958 | Amba     | <i>Mangifera indica</i>     | 5   | 35 | To be retained | Falling outside excavation line |
| 999  | 959 | Dhaman   | <i>Grewia tiliaefolia</i>   | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1000 | 960 | Dhaman   | <i>Grewia tiliaefolia</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1001 | 961 | Dhaman   | <i>Grewia tiliaefolia</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1002 | 962 | Amba     | <i>Mangifera indica</i>     | 10  | 45 | To be retained | Falling outside excavation line |
| 1003 | 963 | Dhaman   | <i>Grewia tiliaefolia</i>   | 2   | 20 | To be retained | Falling outside excavation line |
| 1004 | 964 | Dhaman   | <i>Grewia tiliaefolia</i>   | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1005 | 965 | Dhaman   | <i>Grewia tiliaefolia</i>   | 1.5 | 10 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |     |                |                               |     |    |                |                                 |
|------|-----|----------------|-------------------------------|-----|----|----------------|---------------------------------|
| 1006 | 966 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1007 | 967 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1008 | 968 | Vaivarna       | <i>Crataeva religiosa</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1009 | 969 | Bor            | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1010 | 970 | Charcoal tree  | <i>Trema orientalis</i>       | 2   | 10 | To be retained | Falling outside excavation line |
| 1011 | 971 | Dhaman         | <i>Grewia tiliaefolia</i>     | 2   | 25 | To be retained | Falling outside excavation line |
| 1012 | 972 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1013 | 973 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1014 | 974 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1015 | 975 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1016 | 976 | Kumbh          | <i>Careya arborea</i>         | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1017 | 977 | Kate savar     | <i>Bombax ceiba</i>           | 2   | 15 | To be removed  | Falling within excavation line  |
| 1018 | 978 | Asana          | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1019 | 979 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1020 | 980 | Vavla          | <i>Holoptela integrifolia</i> | 5   | 35 | To be removed  | Falling within excavation line  |
| 1021 | 981 | Kahandol       | <i>Sterculia urens</i>        | 2   | 35 | To be removed  | Falling within excavation line  |
| 1022 | 982 | Kate savar     | <i>Bombax ceiba</i>           | 5   | 45 | To be removed  | Falling within excavation line  |
| 1023 | 983 | Kate savar     | <i>Bombax ceiba</i>           | 2   | 45 | To be removed  | Falling within excavation line  |
| 1024 | 984 | Shemat         | <i>lannea coromandelica</i>   | 5   | 45 | To be removed  | Falling within excavation line  |
| 1025 | 985 | Vavla          | <i>Holoptela integrifolia</i> | 5   | 25 | To be removed  | Falling within excavation line  |
| 1026 | 986 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1027 | 987 | Kahandol       | <i>Sterculia urens</i>        | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1028 | 988 | Bartondi       | <i>Morinda pubescens</i>      | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 1029 | 989 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1030 | 990 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 1031 | 991 | Kahandol       | <i>Sterculia urens</i>        | 2   | 35 | To be removed  | Falling within excavation line  |
| 1032 | 992 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 1033 | 993 | Shemat         | <i>lannea coromandelica</i>   | 2   | 35 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |               |                                |
|------|------|------------|------------------------------|-----|----|---------------|--------------------------------|
| 1034 | 994  | Shemat     | <i>lannea coromandelica</i>  | 1   | 15 | To be removed | Falling within excavation line |
| 1035 | 995  | Kahandol   | <i>Sterculia urens</i>       | 5   | 35 | To be removed | Falling within excavation line |
| 1036 | 996  | Bartondi   | <i>Morinda pubescens</i>     | 1   | 10 | To be removed | Falling within excavation line |
| 1037 | 997  | Shemat     | <i>lannea coromandelica</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 1038 | 998  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1039 | 999  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1040 | 1000 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1041 | 1001 | Asana      | <i>Pterocarpus marsupium</i> | 1   | 10 | To be removed | Falling within excavation line |
| 1042 | 1002 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 1043 | 1003 | Kate savar | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1044 | 1004 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 1045 | 1005 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1046 | 1006 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1047 | 1007 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1048 | 1008 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 1049 | 1009 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 1050 | 1010 | Shivan     | <i>Gmelina arborea</i>       | 1   | 10 | To be removed | Falling within excavation line |
| 1051 | 1011 | Shemat     | <i>lannea coromandelica</i>  | 2   | 20 | To be removed | Falling within excavation line |
| 1052 | 1012 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1053 | 1013 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1054 | 1014 | Shemat     | <i>lannea coromandelica</i>  | 1   | 10 | To be removed | Falling within excavation line |
| 1055 | 1015 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1056 | 1016 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1057 | 1017 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1058 | 1018 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1059 | 1019 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1060 | 1020 | Shemat     | <i>lannea coromandelica</i>  | 1   | 15 | To be removed | Falling within excavation line |
| 1061 | 1021 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |               |                                |
|------|------|------------|------------------------------|-----|----|---------------|--------------------------------|
| 1062 | 1022 | Shemat     | <i>lannea coromandelica</i>  | 1   | 15 | To be removed | Falling within excavation line |
| 1063 | 1023 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1064 | 1024 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1065 | 1025 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1066 | 1026 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1067 | 1027 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1068 | 1028 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1069 | 1029 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1070 | 1030 | Shemat     | <i>lannea coromandelica</i>  | 2   | 20 | To be removed | Falling within excavation line |
| 1071 | 1031 | Shemat     | <i>lannea coromandelica</i>  | 2   | 20 | To be removed | Falling within excavation line |
| 1072 | 1032 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1073 | 1033 | Shemat     | <i>lannea coromandelica</i>  | 2   | 20 | To be removed | Falling within excavation line |
| 1074 | 1034 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1075 | 1035 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 1076 | 1036 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1077 | 1037 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 1078 | 1038 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1079 | 1039 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1080 | 1040 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1081 | 1041 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 10 | To be removed | Falling within excavation line |
| 1082 | 1042 | Kahandol   | <i>Sterculia urens</i>       | 2   | 30 | To be removed | Falling within excavation line |
| 1083 | 1043 | Subabhul   | <i>Leucaena leucocephala</i> | 8   | 35 | To be removed | Falling within excavation line |
| 1084 | 1044 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1085 | 1045 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 1086 | 1046 | Amba       | <i>Mangifera indica</i>      | 5   | 35 | To be removed | Falling within excavation line |
| 1087 | 1047 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 1088 | 1048 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 1089 | 1049 | Amba       | <i>Mangifera indica</i>      | 5   | 35 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |             |                               |     |    |               |                                |
|------|------|-------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1090 | 1050 | Dhaman      | <i>Grewia tiliaefolia</i>     | 1.5 | 10 | To be removed | Falling within excavation line |
| 1091 | 1051 | Kate savar  | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1092 | 1052 | Dhaman      | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1093 | 1053 | Subabhul    | <i>Leucaena leucocephala</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 1094 | 1054 | Subabhul    | <i>Leucaena leucocephala</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 1095 | 1055 | Dhaman      | <i>Grewia tiliaefolia</i>     | 1.5 | 10 | To be removed | Falling within excavation line |
| 1096 | 1056 | Kate savar  | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 1097 | 1057 | Kahandol    | <i>Sterculia urens</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 1098 | 1058 | Amba (Dead) | <i>Mangifera indica</i>       | 5   | 10 | To be removed | Falling within excavation line |
| 1099 | 1059 | Asana       | <i>Pterocarpus marsupium</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1100 | 1060 | Kate savar  | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |
| 1101 | 1061 | Kahandol    | <i>Sterculia urens</i>        | 2   | 25 | To be removed | Falling within excavation line |
| 1102 | 1062 | Bivla       | <i>Pterocarpus marsupium</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1103 | 1063 | Kaju        | <i>Anacardium occidentale</i> | 5   | 45 | To be removed | Falling within excavation line |
| 1104 | 1064 | Dhaman      | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 1105 | 1065 | Kahandol    | <i>Sterculia urens</i>        | 1   | 10 | To be removed | Falling within excavation line |
| 1106 | 1066 | Tad         | <i>Borassus flabellifer</i>   | 2   | 50 | To be removed | Falling within excavation line |
| 1107 | 1067 | Dhaman      | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed | Falling within excavation line |
| 1108 | 1068 | Apta        | <i>Bauhinia racemosa</i>      | 2   | 30 | To be removed | Falling within excavation line |
| 1109 | 1069 | Asana       | <i>Pterocarpus marsupium</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 1110 | 1070 | Amba        | <i>Mangifera indica</i>       | 5   | 35 | To be removed | Falling within excavation line |
| 1111 | 1071 | Tad         | <i>Borassus flabellifer</i>   | 2   | 50 | To be removed | Falling within excavation line |
| 1112 | 1072 | Kate savar  | <i>Bombax ceiba</i>           | 2   | 30 | To be removed | Falling within excavation line |
| 1113 | 1073 | Kaju        | <i>Anacardium occidentale</i> | 5   | 35 | To be removed | Falling within excavation line |
| 1114 | 1074 | Bhokar      | <i>Cordia dichotoma</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 1115 | 1075 | Kahandol    | <i>Sterculia urens</i>        | 1.5 | 20 | To be removed | Falling within excavation line |
| 1116 | 1076 | Tad         | <i>Borassus flabellifer</i>   | 2   | 50 | To be removed | Falling within excavation line |
| 1117 | 1077 | Dhaman      | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                                |     |    |               |                                |
|------|------|------------|--------------------------------|-----|----|---------------|--------------------------------|
| 1118 | 1078 | Tad        | <i>Borassus flabellifer</i>    | 2   | 50 | To be removed | Falling within excavation line |
| 1119 | 1079 | Tad        | <i>Borassus flabellifer</i>    | 2   | 50 | To be removed | Falling within excavation line |
| 1120 | 1080 | Vavla      | <i>Holoptela integrifolia</i>  | 2   | 15 | To be removed | Falling within excavation line |
| 1121 | 1081 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 1.5 | 10 | To be removed | Falling within excavation line |
| 1122 | 1082 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 2   | 25 | To be removed | Falling within excavation line |
| 1123 | 1083 | Narikel    | <i>Pterygota alata</i>         | 10  | 65 | To be removed | Falling within excavation line |
| 1124 | 1084 | Rain tree  | <i>Samanea saman</i>           | 5   | 35 | To be removed | Falling within excavation line |
| 1125 | 1085 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1126 | 1086 | Dhaman     | <i>Grewia tiliaefolia</i>      | 2   | 45 | To be removed | Falling within excavation line |
| 1127 | 1087 | Tetu       | <i>Oroxylum indicum</i>        | 1.5 | 10 | To be removed | Falling within excavation line |
| 1128 | 1088 | Dhaman     | <i>Grewia tiliaefolia</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 1129 | 1089 | Dhaman     | <i>Grewia tiliaefolia</i>      | 1.5 | 35 | To be removed | Falling within excavation line |
| 1130 | 1090 | Shemat     | <i>lannea coromandelica</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 1131 | 1091 | Kate savar | <i>Bombax ceiba</i>            | 1   | 10 | To be removed | Falling within excavation line |
| 1132 | 1092 | Shivan     | <i>Gmelina arborea</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 1133 | 1093 | Asana      | <i>Pterocarpus marsupium</i>   | 1.5 | 10 | To be removed | Falling within excavation line |
| 1134 | 1094 | Asana      | <i>Pterocarpus marsupium</i>   | 1   | 15 | To be removed | Falling within excavation line |
| 1135 | 1095 | Asana      | <i>Pterocarpus marsupium</i>   | 1.5 | 10 | To be removed | Falling within excavation line |
| 1136 | 1096 | Shemat     | <i>lannea coromandelica</i>    | 2   | 35 | To be removed | Falling within excavation line |
| 1137 | 1097 | Asana      | <i>Pterocarpus marsupium</i>   | 5   | 35 | To be removed | Falling within excavation line |
| 1138 | 1098 | Asana      | <i>Pterocarpus marsupium</i>   | 1.5 | 10 | To be removed | Falling within excavation line |
| 1139 | 1099 | Shemat     | <i>lannea coromandelica</i>    | 2   | 35 | To be removed | Falling within excavation line |
| 1140 | 1100 | Shemat     | <i>lannea coromandelica</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 1141 | 1101 | Shemat     | <i>lannea coromandelica</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 1142 | 1102 | Kate savar | <i>Bombax ceiba</i>            | 1.5 | 15 | To be removed | Falling within excavation line |
| 1143 | 1103 | Shemat     | <i>lannea coromandelica</i>    | 1   | 10 | To be removed | Falling within excavation line |
| 1144 | 1104 | Kate savar | <i>Bombax ceiba</i>            | 2   | 35 | To be removed | Falling within excavation line |
| 1145 | 1105 | Asana      | <i>Pterocarpus marsupium</i>   | 1.5 | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                                |     |    |               |                                |
|------|------|------------|--------------------------------|-----|----|---------------|--------------------------------|
| 1146 | 1106 | Kate savar | <i>Bombax ceiba</i>            | 1.5 | 20 | To be removed | Falling within excavation line |
| 1147 | 1107 | Bhokar     | <i>Cordia dichotoma</i>        | 2   | 15 | To be removed | Falling within excavation line |
| 1148 | 1108 | Asana      | <i>Pterocarpus marsupium</i>   | 2   | 35 | To be removed | Falling within excavation line |
| 1149 | 1109 | Kharoti    | <i>Streblus asper</i>          | 5   | 15 | To be removed | Falling within excavation line |
| 1150 | 1110 | Kate savar | <i>Bombax ceiba</i>            | 2   | 30 | To be removed | Falling within excavation line |
| 1151 | 1111 | Bhokar     | <i>Cordia dichotoma</i>        | 1.5 | 30 | To be removed | Falling within excavation line |
| 1152 | 1112 | Asana      | <i>Pterocarpus marsupium</i>   | 2   | 20 | To be removed | Falling within excavation line |
| 1153 | 1113 | Dhaman     | <i>Grewia tiliaefolia</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 1154 | 1114 | Vavla      | <i>Holoptela integrifolia</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 1155 | 1115 | Bhokar     | <i>Cordia dichotoma</i>        | 1.5 | 30 | To be removed | Falling within excavation line |
| 1156 | 1116 | Karvat     | <i>Ficus asperrima</i>         | 1.5 | 20 | To be removed | Falling within excavation line |
| 1157 | 1117 | Rain tree  | <i>Samanea saman</i>           | 1.5 | 30 | To be removed | Falling within excavation line |
| 1158 | 1118 | Dhaman     | <i>Grewia tiliaefolia</i>      | 1   | 10 | To be removed | Falling within excavation line |
| 1159 | 1119 | Rain tree  | <i>Samanea saman</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1160 | 1120 | Sonmohar   | <i>Peltophorum pterocarpum</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 1161 | 1121 | Kaju       | <i>Anacardium occidentale</i>  | 5   | 35 | To be removed | Falling within excavation line |
| 1162 | 1122 | Kaju       | <i>Anacardium occidentale</i>  | 8   | 35 | To be removed | Falling within excavation line |
| 1163 | 1123 | Kumbh      | <i>Careya arborea</i>          | 2   | 15 | To be removed | Falling within excavation line |
| 1164 | 1124 | Bhokar     | <i>Cordia dichotoma</i>        | 1.5 | 35 | To be removed | Falling within excavation line |
| 1165 | 1125 | Dhaman     | <i>Grewia tiliaefolia</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 1166 | 1126 | Asana      | <i>Pterocarpus marsupium</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 1167 | 1127 | Asana      | <i>Pterocarpus marsupium</i>   | 2   | 35 | To be removed | Falling within excavation line |
| 1168 | 1128 | Kahandol   | <i>Sterculia urens</i>         | 1.5 | 35 | To be removed | Falling within excavation line |
| 1169 | 1129 | Asana      | <i>Pterocarpus marsupium</i>   | 5   | 35 | To be removed | Falling within excavation line |
| 1170 | 1130 | Bivla      | <i>Pterocarpus marsupium</i>   | 2   | 45 | To be removed | Falling within excavation line |
| 1171 | 1131 | Bor        | <i>Ziziphus mauritiana</i>     | 1.5 | 10 | To be removed | Falling within excavation line |
| 1172 | 1132 | Dhaman     | <i>Grewia tiliaefolia</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 1173 | 1133 | Dhaman     | <i>Grewia tiliaefolia</i>      | 1.5 | 30 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                               |     |    |               |                                |
|------|------|----------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1174 | 1134 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1175 | 1135 | Rain tree      | <i>Samanea saman</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 1176 | 1136 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1177 | 1137 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1178 | 1138 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1179 | 1139 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 1180 | 1140 | Asana          | <i>Pterocarpus marsupium</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 1181 | 1141 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 10 | To be removed | Falling within excavation line |
| 1182 | 1142 | Bhokar         | <i>Cordia dichotoma</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 1183 | 1143 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 10 | To be removed | Falling within excavation line |
| 1184 | 1144 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 1185 | 1145 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1186 | 1146 | Gulmohar       | <i>Delonix regia</i>          | 2   | 50 | To be removed | Falling within excavation line |
| 1187 | 1147 | Rain tree      | <i>Samanea saman</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 1188 | 1148 | Amba           | <i>Mangifera indica</i>       | 5   | 45 | To be removed | Falling within excavation line |
| 1189 | 1149 | Amba           | <i>Mangifera indica</i>       | 10  | 35 | To be removed | Falling within excavation line |
| 1190 | 1150 | Amba           | <i>Mangifera indica</i>       | 5   | 35 | To be removed | Falling within excavation line |
| 1191 | 1151 | Tad            | <i>Borassus flabellifer</i>   | 5   | 50 | To be removed | Falling within excavation line |
| 1192 | 1152 | Dhaman         | <i>Grewia tiliaefolia</i>     | 2   | 35 | To be removed | Falling within excavation line |
| 1193 | 1153 | Asana          | <i>Pterocarpus marsupium</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 1194 | 1154 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1195 | 1155 | Bhokar         | <i>Cordia dichotoma</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 1196 | 1156 | Bhokar         | <i>Cordia dichotoma</i>       | 2   | 25 | To be removed | Falling within excavation line |
| 1197 | 1157 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1198 | 1158 | Amba           | <i>Mangifera indica</i>       | 8   | 45 | To be removed | Falling within excavation line |
| 1199 | 1159 | Asana          | <i>Pterocarpus marsupium</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1200 | 1160 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 8   | 35 | To be removed | Falling within excavation line |
| 1201 | 1161 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                               |     |    |               |                                |
|------|------|------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1202 | 1162 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1203 | 1163 | Amba       | <i>Mangifera indica</i>       | 2   | 35 | To be removed | Falling within excavation line |
| 1204 | 1164 | Kate savar | <i>Bombax ceiba</i>           | 2   | 25 | To be removed | Falling within excavation line |
| 1205 | 1165 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1206 | 1166 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1207 | 1167 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 1208 | 1168 | Bhokar     | <i>Cordia dichotoma</i>       | 2   | 45 | To be removed | Falling within excavation line |
| 1209 | 1169 | Amba       | <i>Mangifera indica</i>       | 5   | 45 | To be removed | Falling within excavation line |
| 1210 | 1170 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1211 | 1171 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1212 | 1172 | Gulmohar   | <i>Delonix regia</i>          | 2   | 45 | To be removed | Falling within excavation line |
| 1213 | 1173 | Amba       | <i>Mangifera indica</i>       | 10  | 35 | To be removed | Falling within excavation line |
| 1214 | 1174 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 1215 | 1175 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 25 | To be removed | Falling within excavation line |
| 1216 | 1176 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1217 | 1177 | Rain tree  | <i>Samanea saman</i>          | 5   | 45 | To be removed | Falling within excavation line |
| 1218 | 1178 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1219 | 1179 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed | Falling within excavation line |
| 1220 | 1180 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 1221 | 1181 | Bor        | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 1222 | 1182 | Rain tree  | <i>Samanea saman</i>          | 2   | 15 | To be removed | Falling within excavation line |
| 1223 | 1183 | Bartondi   | <i>Morinda pubescens</i>      | 1   | 10 | To be removed | Falling within excavation line |
| 1224 | 1184 | Kumbh      | <i>Careya arborea</i>         | 2   | 15 | To be removed | Falling within excavation line |
| 1225 | 1185 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 35 | To be removed | Falling within excavation line |
| 1226 | 1186 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1227 | 1187 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1228 | 1188 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1229 | 1189 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                               |     |    |               |                                |
|------|------|---------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1230 | 1190 | Shemat        | <i>lannea coromandelica</i>   | 2   | 35 | To be removed | Falling within excavation line |
| 1231 | 1191 | Kate savar    | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |
| 1232 | 1192 | Shemat        | <i>lannea coromandelica</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 1233 | 1193 | Dhaman        | <i>Grewia tiliaefolia</i>     | 5   | 35 | To be removed | Falling within excavation line |
| 1234 | 1194 | Kate savar    | <i>Bombax ceiba</i>           | 2   | 25 | To be removed | Falling within excavation line |
| 1235 | 1195 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1236 | 1196 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1237 | 1197 | Dhaman        | <i>Grewia tiliaefolia</i>     | 2   | 25 | To be removed | Falling within excavation line |
| 1238 | 1198 | Vavla         | <i>Holoptela integrifolia</i> | 5   | 35 | To be removed | Falling within excavation line |
| 1239 | 1199 | Dhaman        | <i>Grewia tiliaefolia</i>     | 2   | 25 | To be removed | Falling within excavation line |
| 1240 | 1200 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1241 | 1201 | Charcoal tree | <i>Trema orientalis</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 1242 | 1202 | Kahandol      | <i>Sterculia urens</i>        | 2   | 35 | To be removed | Falling within excavation line |
| 1243 | 1203 | Kaduneem      | <i>Azadirachta indica</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1244 | 1204 | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 30 | To be removed | Falling within excavation line |
| 1245 | 1205 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 1246 | 1206 | Shemat        | <i>lannea coromandelica</i>   | 2   | 30 | To be removed | Falling within excavation line |
| 1247 | 1207 | Kate savar    | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |
| 1248 | 1208 | Kate savar    | <i>Bombax ceiba</i>           | 2   | 20 | To be removed | Falling within excavation line |
| 1249 | 1209 | Asana         | <i>Pterocarpus marsupium</i>  | 2   | 20 | To be removed | Falling within excavation line |
| 1250 | 1210 | Asana         | <i>Pterocarpus marsupium</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1251 | 1211 | Asana         | <i>Pterocarpus marsupium</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 1252 | 1212 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 1253 | 1213 | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1254 | 1214 | Bhokar        | <i>Cordia dichotoma</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 1255 | 1215 | Amba          | <i>Mangifera indica</i>       | 5   | 35 | To be removed | Falling within excavation line |
| 1256 | 1216 | Kahandol      | <i>Sterculia urens</i>        | 2   | 35 | To be removed | Falling within excavation line |
| 1257 | 1217 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                               |     |    |               |                                |
|------|------|------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1258 | 1218 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 30 | To be removed | Falling within excavation line |
| 1259 | 1219 | Rain tree  | <i>Samanea saman</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 1260 | 1220 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed | Falling within excavation line |
| 1261 | 1221 | Tad        | <i>Borassus flabellifer</i>   | 2   | 45 | To be removed | Falling within excavation line |
| 1262 | 1222 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1263 | 1223 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1264 | 1224 | Bhokar     | <i>Cordia dichotoma</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 1265 | 1225 | Kahandol   | <i>Sterculia urens</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 1266 | 1226 | Toran      | <i>Ziziphus rugosa</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 1267 | 1227 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1268 | 1228 | Sisvi      | <i>Dalbergia latifolia</i>    | 1.5 | 30 | To be removed | Falling within excavation line |
| 1269 | 1229 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 30 | To be removed | Falling within excavation line |
| 1270 | 1230 | Bivla      | <i>Pterocarpus marsupium</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1271 | 1231 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1272 | 1232 | Kate savar | <i>Bombax ceiba</i>           | 5   | 35 | To be removed | Falling within excavation line |
| 1273 | 1233 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1274 | 1234 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 1275 | 1235 | Bhokar     | <i>Cordia dichotoma</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 1276 | 1236 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1277 | 1237 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 1278 | 1238 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 1279 | 1239 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 20 | To be removed | Falling within excavation line |
| 1280 | 1240 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 1281 | 1241 | Vavla      | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 1282 | 1242 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 30 | To be removed | Falling within excavation line |
| 1283 | 1243 | Kate savar | <i>Bombax ceiba</i>           | 2   | 30 | To be removed | Falling within excavation line |
| 1284 | 1244 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1285 | 1245 | Apta       | <i>Bauhinia racemosa</i>      | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                               |     |    |               |                                |
|------|------|----------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1286 | 1246 | Asana          | <i>Pterocarpus marsupium</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 1287 | 1247 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 1288 | 1248 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1289 | 1249 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 30 | To be removed | Falling within excavation line |
| 1290 | 1250 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1291 | 1251 | Vavla          | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 1292 | 1252 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1293 | 1253 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 30 | To be removed | Falling within excavation line |
| 1294 | 1254 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 30 | To be removed | Falling within excavation line |
| 1295 | 1255 | Asana          | <i>Pterocarpus marsupium</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 1296 | 1256 | Shemat         | <i>lannea coromandelica</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 1297 | 1257 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 30 | To be removed | Falling within excavation line |
| 1298 | 1258 | Asana          | <i>Pterocarpus marsupium</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1299 | 1259 | Kaju           | <i>Anacardium occidentale</i> | 5   | 35 | To be removed | Falling within excavation line |
| 1300 | 1260 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1301 | 1261 | Bor            | <i>Ziziphus mauritiana</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 1302 | 1262 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 30 | To be removed | Falling within excavation line |
| 1303 | 1263 | Rain tree      | <i>Samanea saman</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 1304 | 1264 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 1305 | 1265 | Rain tree      | <i>Samanea saman</i>          | 2   | 45 | To be removed | Falling within excavation line |
| 1306 | 1266 | Rain tree      | <i>Samanea saman</i>          | 2   | 45 | To be removed | Falling within excavation line |
| 1307 | 1267 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 45 | To be removed | Falling within excavation line |
| 1308 | 1268 | Amba           | <i>Mangifera indica</i>       | 5   | 35 | To be removed | Falling within excavation line |
| 1309 | 1269 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 1310 | 1270 | Rain tree      | <i>Samanea saman</i>          | 1.5 | 30 | To be removed | Falling within excavation line |
| 1311 | 1271 | Rain tree      | <i>Samanea saman</i>          | 2   | 45 | To be removed | Falling within excavation line |
| 1312 | 1272 | Rain tree      | <i>Samanea saman</i>          | 5   | 45 | To be removed | Falling within excavation line |
| 1313 | 1273 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 2   | 25 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                        |                                |     |    |               |                                |
|------|------|------------------------|--------------------------------|-----|----|---------------|--------------------------------|
| 1314 | 1274 | Bhokar                 | <i>Cordia dichotoma</i>        | 1.5 | 35 | To be removed | Falling within excavation line |
| 1315 | 1275 | Kaju                   | <i>Anacardium occidentale</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1316 | 1276 | Bor                    | <i>Ziziphus mauritiana</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1317 | 1277 | Umber                  | <i>Ficus glomerata</i>         | 3   | 40 | To be removed | Falling within excavation line |
| 1318 | 1278 | Pimpal                 | <i>Ficus religiosa</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 1319 | 1279 | Shemat                 | <i>lannea coromandelica</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 1320 | 1280 | Kaduneem               | <i>Azadirachta indica</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 1321 | 1281 | Pimpal                 | <i>Ficus religiosa</i>         | 10  | 45 | To be removed | Falling within excavation line |
| 1322 | 1282 | Pimpal                 | <i>Ficus religiosa</i>         | 10  | 45 | To be removed | Falling within excavation line |
| 1323 | 1283 | Kate savar             | <i>Bombax ceiba</i>            | 2   | 35 | To be removed | Falling within excavation line |
| 1324 | 1284 | Kate savar             | <i>Bombax ceiba</i>            | 1.5 | 35 | To be removed | Falling within excavation line |
| 1325 | 1285 | Kate savar             | <i>Bombax ceiba</i>            | 5   | 35 | To be removed | Falling within excavation line |
| 1326 | 1286 | Rain tree              | <i>Samanea saman</i>           | 5   | 45 | To be removed | Falling within excavation line |
| 1327 | 1287 | Rain tree              | <i>Samanea saman</i>           | 5   | 45 | To be removed | Falling within excavation line |
| 1328 | 1288 | Sonmohar               | <i>Peltophorum pterocarpum</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1329 | 1289 | Rain tree              | <i>Samanea saman</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1330 | 1290 | Rain tree              | <i>Samanea saman</i>           | 5   | 45 | To be removed | Falling within excavation line |
| 1331 | 1291 | Australian Babhul      | <i>Acacia auriculiformis</i>   | 2   | 45 | To be removed | Falling within excavation line |
| 1332 | 1292 | Rain tree              | <i>Samanea saman</i>           | 2   | 25 | To be removed | Falling within excavation line |
| 1333 | 1293 | Asana                  | <i>Pterocarpus marsupium</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 1334 | 1294 | Gulmohar               | <i>Delonix regia</i>           | 5   | 45 | To be removed | Falling within excavation line |
| 1335 | 1295 | Pimpal                 | <i>Ficus religiosa</i>         | 2   | 45 | To be removed | Falling within excavation line |
| 1336 | 1296 | Kumbh                  | <i>Careya arborea</i>          | 5   | 45 | To be removed | Falling within excavation line |
| 1337 | 1297 | Kate savar             | <i>Bombax ceiba</i>            | 5   | 50 | To be removed | Falling within excavation line |
| 1338 | 1298 | Rain tree              | <i>Samanea saman</i>           | 5   | 45 | To be removed | Falling within excavation line |
| 1339 | 1299 | Dhaman                 | <i>Grewia tiliaefolia</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 1340 | 1300 | Singapore Chery (Dead) | <i>Muntingia calabura</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 1341 | 1301 | Singapore Chery (Dead) | <i>Muntingia calabura</i>      | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |               |                                |
|------|------|----------------|------------------------------|-----|----|---------------|--------------------------------|
| 1342 | 1302 | Asana          | <i>Pterocarpus marsupium</i> | 2   | 30 | To be removed | Falling within excavation line |
| 1343 | 1303 | Rain tree      | <i>Samanea saman</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 1344 | 1304 | Rain tree      | <i>Samanea saman</i>         | 5   | 35 | To be removed | Falling within excavation line |
| 1345 | 1305 | Rain tree      | <i>Samanea saman</i>         | 5   | 35 | To be removed | Falling within excavation line |
| 1346 | 1306 | Rain tree      | <i>Samanea saman</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 1347 | 1307 | Kate savar     | <i>Bombax ceiba</i>          | 5   | 45 | To be removed | Falling within excavation line |
| 1348 | 1308 | Amba           | <i>Mangifera indica</i>      | 5   | 35 | To be removed | Falling within excavation line |
| 1349 | 1309 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1350 | 1310 | Amba           | <i>Mangifera indica</i>      | 5   | 45 | To be removed | Falling within excavation line |
| 1351 | 1311 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 1352 | 1312 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 1353 | 1313 | Dhaman         | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed | Falling within excavation line |
| 1354 | 1314 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 1355 | 1315 | Dhaman         | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed | Falling within excavation line |
| 1356 | 1316 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 1357 | 1317 | Amba (Dead)    | <i>Mangifera indica</i>      | 8   | 20 | To be removed | Falling within excavation line |
| 1358 | 1318 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 5   | 20 | To be removed | Falling within excavation line |
| 1359 | 1319 | Rain tree      | <i>Samanea saman</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 1360 | 1320 | Rain tree      | <i>Samanea saman</i>         | 5   | 35 | To be removed | Falling within excavation line |
| 1361 | 1321 | Kate savar     | <i>Bombax ceiba</i>          | 5   | 35 | To be removed | Falling within excavation line |
| 1362 | 1322 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 1363 | 1323 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1364 | 1324 | Charcoal tree  | <i>Trema orientalis</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 1365 | 1325 | Subabhul       | <i>Leucaena leucocephala</i> | 8   | 20 | To be removed | Falling within excavation line |
| 1366 | 1326 | Rain tree      | <i>Samanea saman</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 1367 | 1327 | Rain tree      | <i>Samanea saman</i>         | 1.5 | 35 | To be removed | Falling within excavation line |
| 1368 | 1328 | Rain tree      | <i>Samanea saman</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 1369 | 1329 | Rain tree      | <i>Samanea saman</i>         | 2   | 30 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |               |                                |
|------|------|-------------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1370 | 1330 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1371 | 1331 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1372 | 1332 | Gulmohar          | <i>Delonix regia</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 1373 | 1333 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1374 | 1334 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed | Falling within excavation line |
| 1375 | 1335 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1376 | 1336 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1377 | 1337 | Gulmohar          | <i>Delonix regia</i>          | 5   | 45 | To be removed | Falling within excavation line |
| 1378 | 1338 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1379 | 1339 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1380 | 1340 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |
| 1381 | 1341 | Kaju              | <i>Anacardium occidentale</i> | 2   | 30 | To be removed | Falling within excavation line |
| 1382 | 1342 | Gulmohar          | <i>Delonix regia</i>          | 1.5 | 30 | To be removed | Falling within excavation line |
| 1383 | 1343 | Rain tree         | <i>Samanea saman</i>          | 5   | 35 | To be removed | Falling within excavation line |
| 1384 | 1344 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1385 | 1345 | Charcoal tree     | <i>Trema orientalis</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 1386 | 1346 | Charcoal tree     | <i>Trema orientalis</i>       | 1   | 15 | To be removed | Falling within excavation line |
| 1387 | 1347 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |
| 1388 | 1348 | Kakad             | <i>Garuga pinnata</i>         | 2   | 30 | To be removed | Falling within excavation line |
| 1389 | 1349 | Vavla             | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 1390 | 1350 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 1391 | 1351 | Dhaman            | <i>Grewia tiliaefolia</i>     | 10  | 15 | To be removed | Falling within excavation line |
| 1392 | 1352 | Amba              | <i>Mangifera indica</i>       | 2   | 30 | To be removed | Falling within excavation line |
| 1393 | 1353 | Rain tree         | <i>Samanea saman</i>          | 5   | 50 | To be removed | Falling within excavation line |
| 1394 | 1354 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 1395 | 1355 | Gulmohar          | <i>Delonix regia</i>          | 8   | 35 | To be removed | Falling within excavation line |
| 1396 | 1356 | Dhaman            | <i>Grewia tiliaefolia</i>     | 5   | 30 | To be removed | Falling within excavation line |
| 1397 | 1357 | Shemat            | <i>lannea coromandelica</i>   | 2   | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                               |     |    |                |                                 |
|------|------|---------------|-------------------------------|-----|----|----------------|---------------------------------|
| 1398 | 1358 | Asana         | <i>Pterocarpus marsupium</i>  | 5   | 30 | To be removed  | Falling within excavation line  |
| 1399 | 1359 | Dhaman        | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed  | Falling within excavation line  |
| 1400 | 1360 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 1401 | 1361 | Dhaman (Dead) | <i>Grewia tiliaefolia</i>     | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 1402 | 1362 | Gulmohar      | <i>Delonix regia</i>          | 2   | 45 | To be removed  | Falling within excavation line  |
| 1403 | 1363 | Gulmohar      | <i>Delonix regia</i>          | 2   | 45 | To be removed  | Falling within excavation line  |
| 1404 | 1364 | Vavla         | <i>Holoptela integrifolia</i> | 1   | 10 | To be removed  | Falling within excavation line  |
| 1405 | 1365 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1406 | 1366 | Charcoal tree | <i>Trema orientalis</i>       | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1407 | 1367 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1408 | 1368 | Dhaman        | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed  | Falling within excavation line  |
| 1409 | 1369 | Kate savar    | <i>Bombax ceiba</i>           | 2   | 15 | To be removed  | Falling within excavation line  |
| 1410 | 1370 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1411 | 1371 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 1412 | 1372 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1413 | 1373 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1414 | 1374 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 1415 | 1375 | Shemat        | <i>lannea coromandelica</i>   | 2   | 20 | To be retained | Falling outside excavation line |
| 1416 | 1376 | Subabhul      | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1417 | 1377 | Subabhul      | <i>Leucaena leucocephala</i>  | 5   | 35 | To be retained | Falling outside excavation line |
| 1418 | 1378 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1419 | 1379 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1420 | 1380 | Subabhul      | <i>Leucaena leucocephala</i>  | 2   | 30 | To be retained | Falling outside excavation line |
| 1421 | 1381 | Jambhul       | <i>Syzygium cumini</i>        | 10  | 50 | To be removed  | Falling within excavation line  |
| 1422 | 1382 | Kate savar    | <i>Bombax ceiba</i>           | 10  | 45 | To be removed  | Falling within excavation line  |
| 1423 | 1383 | Kate savar    | <i>Bombax ceiba</i>           | 2   | 35 | To be removed  | Falling within excavation line  |
| 1424 | 1384 | Tad (Dead)    | <i>Borassus flabellifer</i>   | 5   | 60 | To be removed  | Falling within excavation line  |
| 1425 | 1385 | Bhokar        | <i>Cordia dichotoma</i>       | 5   | 35 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |                |                                 |
|------|------|------------|------------------------------|-----|----|----------------|---------------------------------|
| 1426 | 1386 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1427 | 1387 | Asana      | <i>Bridelia retusa</i>       | 2   | 35 | To be removed  | Falling within excavation line  |
| 1428 | 1388 | Kate savar | <i>Bombax ceiba</i>          | 5   | 45 | To be removed  | Falling within excavation line  |
| 1429 | 1389 | Kate savar | <i>Bombax ceiba</i>          | 5   | 45 | To be removed  | Falling within excavation line  |
| 1430 | 1390 | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1431 | 1391 | Asana      | <i>Pterocarpus marsupium</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 1432 | 1392 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1433 | 1393 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1434 | 1394 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1435 | 1395 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1436 | 1396 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1437 | 1397 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1438 | 1398 | Asana      | <i>Pterocarpus marsupium</i> | 2   | 25 | To be retained | Falling outside excavation line |
| 1439 | 1399 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 30 | To be retained | Falling outside excavation line |
| 1440 | 1400 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1441 | 1401 | Kate savar | <i>Bombax ceiba</i>          | 2   | 25 | To be retained | Falling outside excavation line |
| 1442 | 1402 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1443 | 1403 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1444 | 1404 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1445 | 1405 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1446 | 1406 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1447 | 1407 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1448 | 1408 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1449 | 1409 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 30 | To be retained | Falling outside excavation line |
| 1450 | 1410 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be retained | Falling outside excavation line |
| 1451 | 1411 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1452 | 1412 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1453 | 1413 | Apta       | <i>Bauhinia racemosa</i>     | 1.5 | 10 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |                |                                 |
|------|------|------------|------------------------------|-----|----|----------------|---------------------------------|
| 1454 | 1414 | Subabhul   | <i>Leucaena leucocephala</i> | 8   | 45 | To be retained | Falling outside excavation line |
| 1455 | 1415 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 1456 | 1416 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1457 | 1417 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1458 | 1418 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1459 | 1419 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 30 | To be removed  | Falling within excavation line  |
| 1460 | 1420 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 30 | To be removed  | Falling within excavation line  |
| 1461 | 1421 | Moha       | <i>Garuga pinnata</i>        | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1462 | 1422 | Subabhul   | <i>Garuga pinnata</i>        | 5   | 35 | To be removed  | Falling within excavation line  |
| 1463 | 1423 | Subabhul   | <i>Sterculia urens</i>       | 5   | 35 | To be removed  | Falling within excavation line  |
| 1464 | 1424 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 1465 | 1425 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1466 | 1426 | Kakad      | <i>Garuga pinnata</i>        | 2   | 35 | To be removed  | Falling within excavation line  |
| 1467 | 1427 | Kakad      | <i>Garuga pinnata</i>        | 5   | 30 | To be removed  | Falling within excavation line  |
| 1468 | 1428 | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1469 | 1429 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1470 | 1430 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1471 | 1431 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1472 | 1432 | Kamala     | <i>Mallotus philippines</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1473 | 1433 | Kamala     | <i>Mallotus philippines</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1474 | 1434 | Kate savar | <i>Bombax ceiba</i>          | 2   | 35 | To be removed  | Falling within excavation line  |
| 1475 | 1435 | Kakad      | <i>Garuga pinnata</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1476 | 1436 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1477 | 1437 | Kate savar | <i>Bombax ceiba</i>          | 5   | 35 | To be removed  | Falling within excavation line  |
| 1478 | 1438 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 1479 | 1439 | Kahandol   | <i>Sterculia urens</i>       | 5   | 35 | To be removed  | Falling within excavation line  |
| 1480 | 1440 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 1481 | 1441 | Asana      | <i>Pterocarpus marsupium</i> | 5   | 35 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |                |                                 |
|------|------|----------------|------------------------------|-----|----|----------------|---------------------------------|
| 1482 | 1442 | Subabhul       | <i>Leucaena leucocephala</i> | 5   | 25 | To be removed  | Falling within excavation line  |
| 1483 | 1443 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 35 | To be retained | Falling outside excavation line |
| 1484 | 1444 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1485 | 1445 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1486 | 1446 | Bhokar         | <i>Cordia dichotoma</i>      | 2   | 45 | To be removed  | Falling within excavation line  |
| 1487 | 1447 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1488 | 1448 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1489 | 1449 | Subabhul       | <i>leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1490 | 1450 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1491 | 1451 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1492 | 1452 | Jambhul        | <i>Syzygium cumini</i>       | 1   | 20 | To be retained | Falling outside excavation line |
| 1493 | 1453 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1494 | 1454 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1495 | 1455 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1496 | 1456 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1497 | 1457 | Subabhul       | <i>Leucaena leucocephala</i> | 5   | 35 | To be retained | Falling outside excavation line |
| 1498 | 1458 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1499 | 1459 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1500 | 1460 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1501 | 1461 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1502 | 1462 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1503 | 1463 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1504 | 1464 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1505 | 1465 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1506 | 1466 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1507 | 1467 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1508 | 1468 | Shemat         | <i>lannea coromandelica</i>  | 2   | 30 | To be retained | Falling outside excavation line |
| 1509 | 1469 | Kakad          | <i>Garuga pinnata</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |          |                                 |     |    |                |                                 |
|------|------|----------|---------------------------------|-----|----|----------------|---------------------------------|
| 1510 | 1470 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1511 | 1471 | Dhaman   | <i>Grewia tiliaefolia</i>       | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1512 | 1472 | Kakad    | <i>Garuga pinnata</i>           | 2   | 25 | To be retained | Falling outside excavation line |
| 1513 | 1473 | Dhaman   | <i>Grewia tiliaefolia</i>       | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1514 | 1474 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1515 | 1475 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1516 | 1476 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1517 | 1477 | Karvat   | <i>Ficus asperrima</i>          | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1518 | 1478 | Karvat   | <i>Ficus asperrima</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1519 | 1479 | Dhaman   | <i>Grewia tiliaefolia</i>       | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1520 | 1480 | Dhaman   | <i>Grewia tiliaefolia</i>       | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1521 | 1481 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1522 | 1482 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1523 | 1483 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1524 | 1484 | Moha     | <i>Madhuca indica</i>           | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1525 | 1485 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1526 | 1486 | Kakad    | <i>Garuga pinnata</i>           | 2   | 30 | To be retained | Falling outside excavation line |
| 1527 | 1487 | Dhaman   | <i>Grewia tiliaefolia</i>       | 1   | 10 | To be retained | Falling outside excavation line |
| 1528 | 1488 | Subabhul | <i>Leucaena leucocephala</i>    | 2   | 35 | To be retained | Falling outside excavation line |
| 1529 | 1489 | Kakad    | <i>Garuga pinnata</i>           | 2   | 35 | To be retained | Falling outside excavation line |
| 1530 | 1490 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1531 | 1491 | Asana    | <i>Pterocarpus marsupium</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1532 | 1492 | Dhaman   | <i>Grewia tiliaefolia</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1533 | 1493 | Kakad    | <i>Garuga pinnata</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1534 | 1494 | Kumbh    | <i>Careya arborea</i>           | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1535 | 1495 | Shemat   | <i>lannea coromandelica</i>     | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1536 | 1496 | Shemat   | <i>lannea coromandelica</i>     | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1537 | 1497 | Paroli   | <i>Stereospermum tetragonum</i> | 2   | 35 | To be retained | Falling outside excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |          |                              |     |    |                |                                 |
|------|------|----------|------------------------------|-----|----|----------------|---------------------------------|
| 1538 | 1498 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1539 | 1499 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1540 | 1500 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1541 | 1501 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1542 | 1502 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1543 | 1503 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1544 | 1504 | Dhaman   | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1545 | 1505 | Dhaman   | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 1546 | 1506 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1547 | 1507 | Asana    | <i>Pterocarpus marsupium</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1548 | 1508 | Dhaman   | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1549 | 1509 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1550 | 1510 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1551 | 1511 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1552 | 1512 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1553 | 1513 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1554 | 1514 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1555 | 1515 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1556 | 1516 | Kakad    | <i>Garuga pinnata</i>        | 1   | 20 | To be retained | Falling outside excavation line |
| 1557 | 1517 | Dhaman   | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1558 | 1518 | Kakad    | <i>Garuga pinnata</i>        | 2   | 25 | To be retained | Falling outside excavation line |
| 1559 | 1519 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1560 | 1520 | Kakad    | <i>Garuga pinnata</i>        | 5   | 20 | To be retained | Falling outside excavation line |
| 1561 | 1521 | Bartondi | <i>Morinda pubescens</i>     | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1562 | 1522 | Dhaman   | <i>Grewia tiliaefolia</i>    | 5   | 20 | To be retained | Falling outside excavation line |
| 1563 | 1523 | Dhaman   | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1564 | 1524 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1565 | 1525 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                               |     |    |                |                                 |
|------|------|------------|-------------------------------|-----|----|----------------|---------------------------------|
| 1566 | 1526 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1567 | 1527 | Kakad      | <i>Garuga pinnata</i>         | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1568 | 1528 | Kakad      | <i>Garuga pinnata</i>         | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1569 | 1529 | Kakad      | <i>Garuga pinnata</i>         | 2   | 35 | To be retained | Falling outside excavation line |
| 1570 | 1530 | Kakad      | <i>Garuga pinnata</i>         | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1571 | 1531 | Subabhul   | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1572 | 1532 | Karvat     | <i>Ficus asperrima</i>        | 2   | 35 | To be retained | Falling outside excavation line |
| 1573 | 1533 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1574 | 1534 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1575 | 1535 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1576 | 1536 | Kakad      | <i>Garuga pinnata</i>         | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1577 | 1537 | Kakad      | <i>Garuga pinnata</i>         | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1578 | 1538 | Kakad      | <i>Garuga pinnata</i>         | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1579 | 1539 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1580 | 1540 | Subabhul   | <i>Leucaena leucocephala</i>  | 2   | 45 | To be retained | Falling outside excavation line |
| 1581 | 1541 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1582 | 1542 | Bivla      | <i>Pterocarpus marsupium</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1583 | 1543 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1584 | 1544 | Subabhul   | <i>Leucaena leucocephala</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1585 | 1545 | Subabhul   | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1586 | 1546 | Subabhul   | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1587 | 1547 | Subabhul   | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1588 | 1548 | Subabhul   | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1589 | 1549 | Subabhul   | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1590 | 1550 | Subabhul   | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1591 | 1551 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1592 | 1552 | Subabhul   | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1593 | 1553 | Subabhul   | <i>Leucaena leucocephala</i>  | 2   | 45 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |              |                               |     |    |                |                                 |
|------|------|--------------|-------------------------------|-----|----|----------------|---------------------------------|
| 1594 | 1554 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1595 | 1555 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1596 | 1556 | Subabhul     | <i>Leucaena leucocephala</i>  | 2   | 45 | To be retained | Falling outside excavation line |
| 1597 | 1557 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1598 | 1558 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1599 | 1559 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1600 | 1560 | Dhaman       | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1601 | 1561 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1602 | 1562 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1603 | 1563 | Vavla        | <i>Holoptela integrifolia</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1604 | 1564 | Tambada kuda | <i>Wrightia arborea</i>       | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1605 | 1565 | Kate savar   | <i>Bombax ceiba</i>           | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1606 | 1566 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1607 | 1567 | Umber        | <i>Ficus glomerata</i>        | 2   | 25 | To be retained | Falling outside excavation line |
| 1608 | 1568 | Subabhul     | <i>Leucaena leucocephala</i>  | 2   | 45 | To be retained | Falling outside excavation line |
| 1609 | 1569 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1610 | 1570 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1611 | 1571 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1612 | 1572 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1613 | 1573 | Umber        | <i>Ficus glomerata</i>        | 2   | 20 | To be retained | Falling outside excavation line |
| 1614 | 1574 | Dhaman       | <i>Grewia tiliaefolia</i>     | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1615 | 1575 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1616 | 1576 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1617 | 1577 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1618 | 1578 | Subabhul     | <i>Leucaena leucocephala</i>  | 5   | 35 | To be retained | Falling outside excavation line |
| 1619 | 1579 | Subabhul     | <i>Leucaena leucocephala</i>  | 2   | 25 | To be retained | Falling outside excavation line |
| 1620 | 1580 | Tendu        | <i>Diospyros melanoxylon</i>  | 1   | 10 | To be retained | Falling outside excavation line |
| 1621 | 1581 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |              |                              |     |    |                |                                 |
|------|------|--------------|------------------------------|-----|----|----------------|---------------------------------|
| 1622 | 1582 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1623 | 1583 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1624 | 1584 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1625 | 1585 | Kakad        | <i>Garuga pinnata</i>        | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1626 | 1586 | Asana        | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1627 | 1587 | Kakad        | <i>Garuga pinnata</i>        | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1628 | 1588 | Tambada kuda | <i>Wrightia arborea</i>      | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1629 | 1589 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1630 | 1590 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1631 | 1591 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 1632 | 1592 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1633 | 1593 | Asana        | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1634 | 1594 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed  | Falling within excavation line  |
| 1635 | 1595 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 1636 | 1596 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 30 | To be retained | Falling outside excavation line |
| 1637 | 1597 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 30 | To be retained | Falling outside excavation line |
| 1638 | 1598 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1639 | 1599 | Subabhul     | <i>Leucaena leucocephala</i> | 2   | 45 | To be removed  | Falling within excavation line  |
| 1640 | 1600 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1641 | 1601 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1642 | 1602 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1643 | 1603 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1644 | 1604 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1645 | 1605 | Asana        | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1646 | 1606 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1647 | 1607 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1648 | 1608 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1649 | 1609 | Subabhul     | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                        |                              |     |    |                |                                 |
|------|------|------------------------|------------------------------|-----|----|----------------|---------------------------------|
| 1650 | 1610 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1651 | 1611 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1652 | 1612 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1653 | 1613 | Apta                   | <i>Bauhinia racemosa</i>     | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1654 | 1614 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1655 | 1615 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1656 | 1616 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1657 | 1617 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1658 | 1618 | Subabhul               | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1659 | 1619 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1660 | 1620 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1661 | 1621 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1662 | 1622 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1663 | 1623 | Subabhul               | <i>Leucaena leucocephala</i> | 5   | 45 | To be retained | Falling outside excavation line |
| 1664 | 1624 | Asana                  | <i>Pterocarpus marsupium</i> | 2   | 15 | To be retained | Falling outside excavation line |
| 1665 | 1625 | Kate savar             | <i>Bombax ceiba</i>          | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1666 | 1626 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1667 | 1627 | Subabhul               | <i>Leucaena leucocephala</i> | 2   | 10 | To be retained | Falling outside excavation line |
| 1668 | 1628 | Asana                  | <i>Pterocarpus marsupium</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1669 | 1629 | Kumbh                  | <i>Careya arborea</i>        | 2   | 30 | To be retained | Falling outside excavation line |
| 1670 | 1630 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1671 | 1631 | Subabhul               | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1672 | 1632 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1673 | 1633 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1674 | 1634 | Singapore Chery (Dead) | <i>Muntingia calabura</i>    | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1675 | 1635 | Asana                  | <i>Pterocarpus marsupium</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1676 | 1636 | Dhaman                 | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1677 | 1637 | Subabhul               | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |              |                               |     |    |                |                                 |
|------|------|--------------|-------------------------------|-----|----|----------------|---------------------------------|
| 1678 | 1638 | Subabhul     | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1679 | 1639 | Subabhul     | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1680 | 1640 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1681 | 1641 | Vavla        | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1682 | 1642 | Subabhul     | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1683 | 1643 | Dhaman       | <i>Grewia tiliaefolia</i>     | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1684 | 1644 | Tetu         | <i>Oroxylum indicum</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1685 | 1645 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1686 | 1646 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1687 | 1647 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1688 | 1648 | Kahandol     | <i>Sterculia urens</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1689 | 1649 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1690 | 1650 | Vavla        | <i>Holoptela integrifolia</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1691 | 1651 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1692 | 1652 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1693 | 1653 | Subabhul     | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1694 | 1654 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1695 | 1655 | Vavla        | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1696 | 1656 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1697 | 1657 | Kate savar   | <i>Bombax ceiba</i>           | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1698 | 1658 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1699 | 1659 | Vavla        | <i>Holoptela integrifolia</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1700 | 1660 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1701 | 1661 | Subabhul     | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1702 | 1662 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1703 | 1663 | Shemat       | <i>lannea coromandelica</i>   | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1704 | 1664 | Subabhul     | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1705 | 1665 | Tambada kuda | <i>Wrightia arborea</i>       | 1.5 | 25 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |       |                   |                              |     |    |               |                                |
|------|-------|-------------------|------------------------------|-----|----|---------------|--------------------------------|
| 1706 | 1666  | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1707 | 1667  | Tambada kuda      | <i>Wrightia arborea</i>      | 1.5 | 30 | To be removed | Falling within excavation line |
| 1708 | 1668  | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1709 | 1669  | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1710 | 1670  | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 1711 | 1671  | Tetu              | <i>Oroxylum indicum</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 1712 | 1672  | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1713 | 1673  | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1714 | 1674  | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1715 | 1675  | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 10 | To be removed | Falling within excavation line |
| 1716 | 1676  | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 1717 | 1677  | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1718 | 1678  | Kumbh             | <i>Careya arborea</i>        | 1.5 | 20 | To be removed | Falling within excavation line |
| 1719 | 1679  | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 20 | To be removed | Falling within excavation line |
| 1720 | 1680  | Kahandol          | <i>Sterculia urens</i>       | 2   | 30 | To be removed | Falling within excavation line |
| 1721 | 1680A | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 25 | To be removed | Falling within excavation line |
| 1722 | 1681  | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 1723 | 1682  | Tambada kuda      | <i>Wrightia arborea</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 1724 | 1683  | Tetu              | <i>Oroxylum indicum</i>      | 1.5 | 30 | To be removed | Falling within excavation line |
| 1725 | 1684  | Shemat            | <i>lannea coromandelica</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1726 | 1685  | Tambada kuda      | <i>Wrightia arborea</i>      | 1.5 | 10 | To be removed | Falling within excavation line |
| 1727 | 1686  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be removed | Falling within excavation line |
| 1728 | 1687  | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 10 | To be removed | Falling within excavation line |
| 1729 | 1688  | Teak              | <i>Tectona grandis</i>       | 1.5 | 10 | To be removed | Falling within excavation line |
| 1730 | 1689  | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 1731 | 1690  | Kumbh             | <i>Careya arborea</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 1732 | 1691  | Shivan            | <i>Gmelina arborea</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 1733 | 1692  | Shivan            | <i>Gmelina arborea</i>       | 2   | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |               |                                |
|------|------|-------------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1734 | 1693 | Kharoti           | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 1735 | 1694 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 10 | To be removed | Falling within excavation line |
| 1736 | 1695 | Bael              | <i>Aegle marmelos</i>         | 1.5 | 10 | To be removed | Falling within excavation line |
| 1737 | 1696 | Bael              | <i>Aegle marmelos</i>         | 1.5 | 10 | To be removed | Falling within excavation line |
| 1738 | 1697 | Tambada kuda      | <i>Wrightia arborea</i>       | 1.5 | 10 | To be removed | Falling within excavation line |
| 1739 | 1698 | Tambada kuda      | <i>Wrightia arborea</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 1740 | 1699 | Vavla             | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 1741 | 1700 | Shemat            | <i>lannea coromandelica</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 1742 | 1701 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1743 | 1702 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1744 | 1703 | Shemat            | <i>lannea coromandelica</i>   | 2   | 20 | To be removed | Falling within excavation line |
| 1745 | 1704 | Shemat            | <i>lannea coromandelica</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 1746 | 1705 | Tambada kuda      | <i>Wrightia arborea</i>       | 1.5 | 10 | To be removed | Falling within excavation line |
| 1747 | 1706 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1748 | 1707 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1749 | 1708 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1750 | 1709 | Shemat            | <i>lannea coromandelica</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 1751 | 1710 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 1752 | 1711 | Vavla             | <i>Holoptela integrifolia</i> | 2   | 25 | To be removed | Falling within excavation line |
| 1753 | 1712 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1754 | 1713 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1755 | 1714 | Rain tree         | <i>Samanea saman</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 1756 | 1715 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 1757 | 1716 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1758 | 1717 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1759 | 1718 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1760 | 1719 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 1761 | 1720 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |               |                                |
|------|------|-------------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1762 | 1721 | Charcoal tree     | <i>Trema orientalis</i>       | 2   | 30 | To be removed | Falling within excavation line |
| 1763 | 1722 | Subabhul          | <i>Leucaena leucocephala</i>  | 2   | 15 | To be removed | Falling within excavation line |
| 1764 | 1723 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 1765 | 1724 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 1766 | 1725 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1767 | 1726 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1768 | 1727 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 1769 | 1728 | Dhaman            | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed | Falling within excavation line |
| 1770 | 1729 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1771 | 1730 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 1772 | 1731 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1773 | 1732 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1774 | 1733 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 10 | To be removed | Falling within excavation line |
| 1775 | 1734 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 10 | To be removed | Falling within excavation line |
| 1776 | 1735 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1777 | 1736 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 1778 | 1737 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 30 | To be removed | Falling within excavation line |
| 1779 | 1738 | Dhaman            | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed | Falling within excavation line |
| 1780 | 1739 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1781 | 1740 | Jambhul           | <i>Syzygium cumini</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 1782 | 1741 | Jambhul           | <i>Syzygium cumini</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 1783 | 1742 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 1784 | 1743 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |
| 1785 | 1744 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1786 | 1745 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1787 | 1746 | Vavla             | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 1788 | 1747 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed | Falling within excavation line |
| 1789 | 1748 | Kahandol          | <i>Sterculia urens</i>        | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |               |                                |
|------|------|-------------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1790 | 1749 | Australian Babbul | <i>Acacia auriculiformis</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 1791 | 1750 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 1792 | 1751 | Australian Babbul | <i>Acacia auriculiformis</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 1793 | 1752 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 1794 | 1753 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1795 | 1754 | Australian Babbul | <i>Acacia auriculiformis</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 1796 | 1755 | Dhaman            | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed | Falling within excavation line |
| 1797 | 1756 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1798 | 1757 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 1799 | 1758 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1800 | 1759 | Vavla             | <i>Holoptela integrifolia</i> | 2   | 25 | To be removed | Falling within excavation line |
| 1801 | 1760 | Rain tree         | <i>Samanea saman</i>          | 8   | 50 | To be removed | Falling within excavation line |
| 1802 | 1761 | Tambada kuda      | <i>Wrightia arborea</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 1803 | 1762 | Vavla             | <i>Holoptela integrifolia</i> | 2   | 45 | To be removed | Falling within excavation line |
| 1804 | 1763 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1805 | 1764 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 1806 | 1765 | Vavla             | <i>Holoptela integrifolia</i> | 5   | 45 | To be removed | Falling within excavation line |
| 1807 | 1766 | Gulmohar          | <i>Delonix regia</i>          | 2   | 45 | To be removed | Falling within excavation line |
| 1808 | 1767 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1809 | 1768 | Charcoal tree     | <i>Trema orientalis</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 1810 | 1769 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1811 | 1770 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 1812 | 1771 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 45 | To be removed | Falling within excavation line |
| 1813 | 1772 | Shemat            | <i>lannea coromandelica</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 1814 | 1773 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1815 | 1774 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1816 | 1775 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1817 | 1776 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |           |                               |     |    |                |                                 |
|------|------|-----------|-------------------------------|-----|----|----------------|---------------------------------|
| 1818 | 1777 | Dhaman    | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1819 | 1778 | Subabhul  | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1820 | 1779 | Rain tree | <i>Samanea saman</i>          | 5   | 45 | To be removed  | Falling within excavation line  |
| 1821 | 1780 | Rain tree | <i>Samanea saman</i>          | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1822 | 1781 | Rain tree | <i>Samanea saman</i>          | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 1823 | 1782 | Tetu      | <i>Oroxylum indicum</i>       | 5   | 25 | To be removed  | Falling within excavation line  |
| 1824 | 1783 | Tetu      | <i>Oroxylum indicum</i>       | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1825 | 1784 | Subabhul  | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1826 | 1785 | Rain tree | <i>Samanea saman</i>          | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1827 | 1786 | Subabhul  | <i>Leucaena leucocephala</i>  | 2   | 45 | To be removed  | Falling within excavation line  |
| 1828 | 1787 | Kahandol  | <i>Sterculia urens</i>        | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1829 | 1788 | Jambhul   | <i>Syzygium cumini</i>        | 5   | 45 | To be removed  | Falling within excavation line  |
| 1830 | 1789 | Kahandol  | <i>Sterculia urens</i>        | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1831 | 1790 | Vavla     | <i>holoptela integrifolia</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1832 | 1791 | Rain tree | <i>Samanea saman</i>          | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1833 | 1792 | Karanj    | <i>Pongamia pinnata</i>       | 2   | 20 | To be removed  | Falling within excavation line  |
| 1834 | 1793 | Subabhul  | <i>Leucaena leucocephala</i>  | 2   | 45 | To be removed  | Falling within excavation line  |
| 1835 | 1794 | Subabhul  | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1836 | 1795 | Subabhul  | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1837 | 1796 | Subabhul  | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1838 | 1797 | Rain tree | <i>Samanea saman</i>          | 1.5 | 10 | To be retained | Falling outside excavation line |
| 1839 | 1798 | Rain tree | <i>Samanea saman</i>          | 2   | 35 | To be retained | Falling outside excavation line |
| 1840 | 1799 | Shemat    | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1841 | 1800 | Dhaman    | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1842 | 1801 | Vavla     | <i>Holoptela integrifolia</i> | 5   | 50 | To be retained | Falling outside excavation line |
| 1843 | 1802 | Vavla     | <i>Holoptela integrifolia</i> | 8   | 50 | To be retained | Falling outside excavation line |
| 1844 | 1803 | Subabhul  | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1845 | 1804 | Vavla     | <i>Holoptela integrifolia</i> | 8   | 50 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |          |                               |     |    |                |                                 |
|------|------|----------|-------------------------------|-----|----|----------------|---------------------------------|
| 1846 | 1805 | Pimpal   | <i>Ficus religiosa</i>        | 10  | 50 | To be retained | Falling outside excavation line |
| 1847 | 1806 | Vavla    | <i>Holoptela integrifolia</i> | 5   | 50 | To be retained | Falling outside excavation line |
| 1848 | 1807 | Karanj   | <i>Pongamia pinnata</i>       | 5   | 45 | To be removed  | Falling within excavation line  |
| 1849 | 1808 | Vavla    | <i>Holoptela integrifolia</i> | 5   | 50 | To be retained | Falling outside excavation line |
| 1850 | 1809 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1851 | 1810 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1852 | 1811 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1853 | 1812 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1854 | 1813 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1855 | 1814 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1856 | 1815 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1857 | 1816 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1858 | 1817 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1859 | 1818 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1860 | 1819 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1861 | 1820 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 1862 | 1821 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1863 | 1822 | Bartondi | <i>Morinda pubescens</i>      | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1864 | 1823 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1865 | 1824 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1866 | 1825 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1867 | 1826 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1868 | 1827 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1869 | 1828 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1870 | 1829 | Subabhul | <i>Leucaena leucocephala</i>  | 2   | 45 | To be retained | Falling outside excavation line |
| 1871 | 1830 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1872 | 1831 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1873 | 1832 | Subabhul | <i>Leucaena leucocephala</i>  | 2   | 45 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |          |                               |     |    |                |                                 |
|------|------|----------|-------------------------------|-----|----|----------------|---------------------------------|
| 1874 | 1833 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1875 | 1834 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1876 | 1835 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1877 | 1836 | Vavla    | <i>holoptela integrifolia</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1878 | 1837 | Karanj   | <i>Pongamia pinnata</i>       | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1879 | 1838 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1880 | 1839 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1881 | 1840 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1882 | 1841 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1883 | 1842 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1884 | 1843 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1885 | 1844 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1886 | 1845 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1887 | 1846 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 1888 | 1847 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1889 | 1848 | Subabhul | <i>Leucaena leucocephala</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 1890 | 1849 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1891 | 1850 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1892 | 1851 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1893 | 1852 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1894 | 1853 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1895 | 1854 | Subabhul | <i>Leucaena leucocephala</i>  | 2   | 45 | To be retained | Falling outside excavation line |
| 1896 | 1855 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1897 | 1856 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1898 | 1857 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1899 | 1858 | Subabhul | <i>Leucaena leucocephala</i>  | 2   | 35 | To be removed  | Falling within excavation line  |
| 1900 | 1859 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1901 | 1860 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 45 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                              |     |    |                |                                 |
|------|------|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 1902 | 1861 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1903 | 1862 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1904 | 1863 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 45 | To be retained | Falling outside excavation line |
| 1905 | 1864 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1906 | 1865 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1907 | 1866 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1908 | 1867 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 45 | To be removed  | Falling within excavation line  |
| 1909 | 1868 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1910 | 1869 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1911 | 1870 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1912 | 1871 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 1913 | 1872 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1914 | 1873 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1915 | 1874 | Jambhul           | <i>Syzygium cumini</i>       | 2   | 35 | To be retained | Falling outside excavation line |
| 1916 | 1875 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1917 | 1876 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1918 | 1877 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1919 | 1878 | Jambhul           | <i>Syzygium cumini</i>       | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1920 | 1879 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1921 | 1880 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1922 | 1881 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be removed  | Falling within excavation line  |
| 1923 | 1882 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1924 | 1883 | Kahandol          | <i>Sterculia urens</i>       | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1925 | 1884 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1926 | 1885 | Apta              | <i>Bauhinia racemosa</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1927 | 1886 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1928 | 1887 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1929 | 1888 | Umber             | <i>Ficus glomerata</i>       | 1.5 | 15 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |               |                                |
|------|------|-------------------|-------------------------------|-----|----|---------------|--------------------------------|
| 1930 | 1889 | Vavla             | <i>holoptela integrifolia</i> | 2   | 35 | To be removed | Falling within excavation line |
| 1931 | 1890 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1932 | 1891 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1933 | 1892 | Australian Babbul | <i>Acacia auriculiformis</i>  | 2   | 45 | To be removed | Falling within excavation line |
| 1934 | 1893 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 1935 | 1894 | Rain tree         | <i>Samanea saman</i>          | 2   | 45 | To be removed | Falling within excavation line |
| 1936 | 1895 | Amba              | <i>Mangifera indica</i>       | 2   | 45 | To be removed | Falling within excavation line |
| 1937 | 1896 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 1938 | 1897 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 45 | To be removed | Falling within excavation line |
| 1939 | 1898 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 1940 | 1899 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 35 | To be removed | Falling within excavation line |
| 1941 | 1900 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 45 | To be removed | Falling within excavation line |
| 1942 | 1901 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 1943 | 1902 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 1944 | 1903 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1945 | 1904 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 1946 | 1905 | Subabhul          | <i>Leucaena leucocephala</i>  | 2   | 45 | To be removed | Falling within excavation line |
| 1947 | 1906 | Vilayti Chinch    | <i>Pithecellobium dulce</i>   | 1.5 | 45 | To be removed | Falling within excavation line |
| 1948 | 1907 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 1949 | 1908 | Subabhul          | <i>Leucaena leucocephala</i>  | 2   | 20 | To be removed | Falling within excavation line |
| 1950 | 1909 | Kate savar        | <i>Bombax ceiba</i>           | 1   | 15 | To be removed | Falling within excavation line |
| 1951 | 1910 | Bhokar            | <i>Cordia dichotoma</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 1952 | 1911 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed | Falling within excavation line |
| 1953 | 1912 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed | Falling within excavation line |
| 1954 | 1913 | Kahandol          | <i>Sterculia urens</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 1955 | 1914 | Amba              | <i>Mangifera indica</i>       | 8   | 45 | To be removed | Falling within excavation line |
| 1956 | 1915 | Pandhari          | <i>Tamilnadia uliginosa</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 1957 | 1916 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |                |                                 |
|------|------|-------------------|-------------------------------|-----|----|----------------|---------------------------------|
| 1958 | 1917 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1959 | 1918 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 1960 | 1919 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 1961 | 1920 | Amba              | <i>Mangifera indica</i>       | 8   | 45 | To be removed  | Falling within excavation line  |
| 1962 | 1921 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed  | Falling within excavation line  |
| 1963 | 1922 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 1964 | 1923 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1965 | 1924 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 1966 | 1925 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1967 | 1926 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1968 | 1927 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1969 | 1928 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1970 | 1929 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1971 | 1930 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1972 | 1931 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1973 | 1932 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1974 | 1933 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1975 | 1934 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1976 | 1935 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1977 | 1936 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1978 | 1937 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 1979 | 1938 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1980 | 1939 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1981 | 1940 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1982 | 1941 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1983 | 1942 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 1984 | 1943 | Subabhul          | <i>Leucaena leucocephala</i>  | 2   | 15 | To be removed  | Falling within excavation line  |
| 1985 | 1944 | Subabhul          | <i>Leucaena leucocephala</i>  | 2   | 20 | To be retained | Falling outside excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                              |     |    |                |                                 |
|------|------|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 1986 | 1945 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1987 | 1946 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 1988 | 1947 | Amba              | <i>Mangifera indica</i>      | 8   | 45 | To be retained | Falling outside excavation line |
| 1989 | 1948 | Amba              | <i>Mangifera indica</i>      | 2   | 45 | To be retained | Falling outside excavation line |
| 1990 | 1949 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 1991 | 1950 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1992 | 1951 | Shemat            | <i>lannea coromandelica</i>  | 2   | 45 | To be retained | Falling outside excavation line |
| 1993 | 1952 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1994 | 1953 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1995 | 1954 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be retained | Falling outside excavation line |
| 1996 | 1955 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 50 | To be retained | Falling outside excavation line |
| 1997 | 1956 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 1998 | 1957 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 1999 | 1958 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2000 | 1959 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2001 | 1960 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 35 | To be retained | Falling outside excavation line |
| 2002 | 1961 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2003 | 1962 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2004 | 1963 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 45 | To be retained | Falling outside excavation line |
| 2005 | 1964 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 2006 | 1965 | Moha              | <i>Madhuca indica</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2007 | 1966 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2008 | 1967 | Australian Babbul | <i>Acacia auriculiformis</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2009 | 1968 | Pimpal            | <i>Ficus religiosa</i>       | 10  | 50 | To be retained | Falling outside excavation line |
| 2010 | 1969 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2011 | 1970 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 45 | To be retained | Falling outside excavation line |
| 2012 | 1971 | Subabhul          | <i>Leucaena leucocephala</i> | 5   | 45 | To be retained | Falling outside excavation line |
| 2013 | 1972 | Subabhul          | <i>Leucaena leucocephala</i> | 2   | 45 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                               |     |    |                |                                 |
|------|------|------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2014 | 1973 | Amba       | <i>Mangifera indica</i>       | 5   | 35 | To be retained | Falling outside excavation line |
| 2015 | 1974 | Kharoti    | <i>Streblus asper</i>         | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2016 | 1975 | Vavla      | <i>holoptela integrifolia</i> | 2   | 45 | To be retained | Falling outside excavation line |
| 2017 | 1976 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2018 | 1977 | Subabhul   | <i>Leucaena leucocephala</i>  | 2   | 30 | To be retained | Falling outside excavation line |
| 2019 | 1978 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2020 | 1979 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2021 | 1980 | Kate savar | <i>Bombax ceiba</i>           | 1   | 20 | To be retained | Falling outside excavation line |
| 2022 | 1981 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2023 | 1982 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2024 | 1983 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2025 | 1984 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2026 | 1985 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 30 | To be removed  | Falling within excavation line  |
| 2027 | 1986 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 2028 | 1987 | Shemat     | <i>lannea coromandelica</i>   | 2   | 30 | To be removed  | Falling within excavation line  |
| 2029 | 1988 | Shemat     | <i>lannea coromandelica</i>   | 2   | 30 | To be removed  | Falling within excavation line  |
| 2030 | 1989 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 2031 | 1990 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 2032 | 1991 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2033 | 1992 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 2034 | 1993 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 2035 | 1994 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2036 | 1995 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 2037 | 1996 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 2038 | 1997 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 2039 | 1998 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 2040 | 1999 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 2041 | 2000 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 35 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |              |                             |     |    |               |                                |
|------|------|--------------|-----------------------------|-----|----|---------------|--------------------------------|
| 2042 | 2001 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 2043 | 2002 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 2044 | 2003 | Kahandol     | <i>Sterculia urens</i>      | 2   | 45 | To be removed | Falling within excavation line |
| 2045 | 2004 | Shemat       | <i>lannea coromandelica</i> | 2   | 35 | To be removed | Falling within excavation line |
| 2046 | 2005 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 2047 | 2006 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 2048 | 2007 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 2049 | 2008 | Shemat       | <i>lannea coromandelica</i> | 2   | 35 | To be removed | Falling within excavation line |
| 2050 | 2009 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2051 | 2010 | Dhaman       | <i>Grewia tiliaefolia</i>   | 1.5 | 35 | To be removed | Falling within excavation line |
| 2052 | 2011 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2053 | 2012 | Shemat       | <i>lannea coromandelica</i> | 2   | 35 | To be removed | Falling within excavation line |
| 2054 | 2013 | Kate savar   | <i>Bombax ceiba</i>         | 1.5 | 25 | To be removed | Falling within excavation line |
| 2055 | 2014 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 2056 | 2015 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 2057 | 2016 | Dhaman       | <i>Grewia tiliaefolia</i>   | 1   | 15 | To be removed | Falling within excavation line |
| 2058 | 2017 | Tambada kuda | <i>Wrightia arborea</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 2059 | 2018 | Kahandol     | <i>Sterculia urens</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 2060 | 2019 | Kate savar   | <i>Bombax ceiba</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 2061 | 2020 | Dhaman       | <i>Grewia tiliaefolia</i>   | 1.5 | 35 | To be removed | Falling within excavation line |
| 2062 | 2021 | Dhaman       | <i>Grewia tiliaefolia</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 2063 | 2022 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2064 | 2023 | Kate savar   | <i>Bombax ceiba</i>         | 2   | 35 | To be removed | Falling within excavation line |
| 2065 | 2024 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2066 | 2025 | Shemat       | <i>lannea coromandelica</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2067 | 2026 | Dhaman       | <i>grewia tiliaefolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 2068 | 2027 | Kahandol     | <i>Sterculia urens</i>      | 2   | 35 | To be removed | Falling within excavation line |
| 2069 | 2028 | Dhaman       | <i>Grewia tiliaefolia</i>   | 1.5 | 30 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                              |     |    |               |                                |
|------|------|-------------------|------------------------------|-----|----|---------------|--------------------------------|
| 2070 | 2029 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 2071 | 2030 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 2072 | 2031 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 2073 | 2032 | Gulmohar          | <i>Delonix regia</i>         | 1.5 | 30 | To be removed | Falling within excavation line |
| 2074 | 2033 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be removed | Falling within excavation line |
| 2075 | 2034 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be removed | Falling within excavation line |
| 2076 | 2035 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 2077 | 2036 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2078 | 2037 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 2079 | 2038 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 2080 | 2039 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 20 | To be removed | Falling within excavation line |
| 2081 | 2040 | Kahandol          | <i>Sterculia urens</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 2082 | 2041 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2083 | 2042 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2084 | 2043 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2085 | 2044 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 2086 | 2045 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2087 | 2046 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 30 | To be removed | Falling within excavation line |
| 2088 | 2047 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2089 | 2048 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 2090 | 2049 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 25 | To be removed | Falling within excavation line |
| 2091 | 2050 | Vilayti Chinch    | <i>Pithecellobium dulce</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 2092 | 2051 | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2093 | 2052 | Vilayti Chinch    | <i>Pithecellobium dulce</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2094 | 2053 | Charcoal tree     | <i>Trema orientalis</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2095 | 2054 | Vilayti Chinch    | <i>Pithecellobium dulce</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 2096 | 2055 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 2097 | 2056 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |               |                                |
|------|------|-------------------|-------------------------------|-----|----|---------------|--------------------------------|
| 2098 | 2057 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2099 | 2058 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 2100 | 2059 | Vilayti Chinch    | <i>Pithecellobium dulce</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2101 | 2060 | Bor               | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2102 | 2061 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2103 | 2062 | Kahandol          | <i>Sterculia urens</i>        | 5   | 25 | To be removed | Falling within excavation line |
| 2104 | 2063 | Charcoal tree     | <i>Trema orientalis</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2105 | 2064 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 2106 | 2065 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2107 | 2066 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 2108 | 2067 | Kate savar        | <i>Bombax ceiba</i>           | 1   | 25 | To be removed | Falling within excavation line |
| 2109 | 2068 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 2110 | 2069 | Kate savar        | <i>Bombax ceiba</i>           | 1   | 15 | To be removed | Falling within excavation line |
| 2111 | 2070 | Atrun             | <i>Flacourtia montana</i>     | 1.5 | 10 | To be removed | Falling within excavation line |
| 2112 | 2071 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 2113 | 2072 | Asana             | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2114 | 2073 | kate savar        | <i>Bombax ceiba</i>           | 8   | 35 | To be removed | Falling within excavation line |
| 2115 | 2074 | Kahandol          | <i>Sterculia urens</i>        | 2   | 15 | To be removed | Falling within excavation line |
| 2116 | 2075 | Kumbh             | <i>Careya arborea</i>         | 1.5 | 10 | To be removed | Falling within excavation line |
| 2117 | 2076 | Moha              | <i>Madhuca indica</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2118 | 2077 | kahandol          | <i>Sterculia urens</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2119 | 2078 | Vavla             | <i>holoptela integrifolia</i> | 1   | 15 | To be removed | Falling within excavation line |
| 2120 | 2079 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2121 | 2080 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2122 | 2081 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2123 | 2082 | Vavla             | <i>holoptela integrifolia</i> | 1   | 15 | To be removed | Falling within excavation line |
| 2124 | 2083 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 2125 | 2084 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |               |                                |
|------|------|-------------------|-------------------------------|-----|----|---------------|--------------------------------|
| 2126 | 2085 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 2127 | 2086 | Australian Babbul | <i>Acacia auriculiformis</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 2128 | 2087 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 2129 | 2088 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 2130 | 2089 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 2131 | 2090 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 35 | To be removed | Falling within excavation line |
| 2132 | 2091 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 2133 | 2092 | kahandol          | <i>Sterculia urens</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2134 | 2093 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 2135 | 2094 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 2136 | 2095 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2137 | 2096 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2138 | 2097 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2139 | 2098 | Australian Babbul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 2140 | 2099 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2141 | 2100 | Kahandol          | <i>Sterculia urens</i>        | 2   | 30 | To be removed | Falling within excavation line |
| 2142 | 2101 | Vavla             | <i>holoptela integrifolia</i> | 5   | 45 | To be removed | Falling within excavation line |
| 2143 | 2102 | Subabhul          | <i>Leucaena leucocephala</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 2144 | 2103 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2145 | 2104 | Kharoti           | <i>Streblus asper</i>         | 1   | 15 | To be removed | Falling within excavation line |
| 2146 | 2105 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 2147 | 2106 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 2148 | 2107 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 2149 | 2108 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 25 | To be removed | Falling within excavation line |
| 2150 | 2109 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 2151 | 2110 | Vavla             | <i>holoptela integrifolia</i> | 3   | 35 | To be removed | Falling within excavation line |
| 2152 | 2111 | Asana             | <i>Pterocarpus marsupium</i>  | 2   | 15 | To be removed | Falling within excavation line |
| 2153 | 2112 | Kate savar(Dead)  | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |                |                                 |
|------|------|-------------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2154 | 2113 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2155 | 2114 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2156 | 2115 | Vilayti Chinch    | <i>Pithecellobium dulce</i>   | 2   | 25 | To be removed  | Falling within excavation line  |
| 2157 | 2116 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2158 | 2117 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2159 | 2118 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2160 | 2119 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2161 | 2120 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2162 | 2121 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2163 | 2122 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 45 | To be retained | Falling outside excavation line |
| 2164 | 2123 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2165 | 2124 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2166 | 2125 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2167 | 2126 | Subabhul          | <i>Leucaena leucocephala</i>  | 2   | 30 | To be retained | Falling outside excavation line |
| 2168 | 2127 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2169 | 2128 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2170 | 2129 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 35 | To be retained | Falling outside excavation line |
| 2171 | 2130 | Asana             | <i>Pterocarpus marsupium</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2172 | 2131 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2173 | 2132 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2174 | 2133 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2175 | 2134 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2176 | 2135 | Kahandol          | <i>Sterculia urens</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2177 | 2136 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2178 | 2137 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2179 | 2138 | kakad             | <i>Garuga pinnata</i>         | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2180 | 2139 | kamala            | <i>Mallotus philippines</i>   | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2181 | 2140 | kamala            | <i>Mallotus philippines</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                               |     |    |                |                                 |
|------|------|---------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2182 | 2141 | Charcoal tree | <i>Trema orientalis</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2183 | 2142 | Amba          | <i>Mangifera indica</i>       | 2   | 25 | To be retained | Falling outside excavation line |
| 2184 | 2143 | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2185 | 2144 | Kahandol      | <i>Sterculia urens</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2186 | 2145 | Asana         | <i>Pterocarpus marsupium</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2187 | 2146 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2188 | 2147 | Kate savar    | <i>Bombax ceiba</i>           | 2   | 30 | To be retained | Falling outside excavation line |
| 2189 | 2148 | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2190 | 2149 | Shemat        | <i>lannea coromandelica</i>   | 5   | 25 | To be retained | Falling outside excavation line |
| 2191 | 2150 | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2192 | 2151 | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2193 | 2152 | Kahandol      | <i>Sterculia urens</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2194 | 2153 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2195 | 2154 | Shemat        | <i>lannea coromandelica</i>   | 2   | 25 | To be retained | Falling outside excavation line |
| 2196 | 2155 | Shemat        | <i>lannea coromandelica</i>   | 2   | 25 | To be retained | Falling outside excavation line |
| 2197 | 2156 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2198 | 2157 | Kahandol      | <i>Sterculia urens</i>        | 5   | 30 | To be retained | Falling outside excavation line |
| 2199 | 2158 | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2200 | 2159 | Vavla         | <i>holoptela integrifolia</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2201 | 2160 | Kukar         | <i>Sterculia guttata</i>      | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2202 | 2161 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2203 | 2162 | Asana         | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2204 | 2163 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2205 | 2164 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2206 | 2165 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2207 | 2166 | Shemat        | <i>lannea coromandelica</i>   | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2208 | 2167 | Asana         | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2209 | 2168 | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 15 | To be retained | Falling outside excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |                |                                 |
|------|------|-------------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2210 | 2169 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2211 | 2170 | Moha              | <i>Madhuca indica</i>         | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2212 | 2171 | Rain tree         | <i>Samanea saman</i>          | 2   | 25 | To be retained | Falling outside excavation line |
| 2213 | 2172 | Shemat            | <i>lannea coromandelica</i>   | 2   | 25 | To be retained | Falling outside excavation line |
| 2214 | 2173 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2215 | 2174 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2216 | 2175 | Shemat            | <i>lannea coromandelica</i>   | 2   | 15 | To be retained | Falling outside excavation line |
| 2217 | 2176 | Kumbh             | <i>Careya arborea</i>         | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2218 | 2177 | Shemat            | <i>lannea coromandelica</i>   | 2   | 10 | To be retained | Falling outside excavation line |
| 2219 | 2178 | Shemat            | <i>lannea coromandelica</i>   | 2   | 30 | To be retained | Falling outside excavation line |
| 2220 | 2179 | Shemat            | <i>lannea coromandelica</i>   | 2   | 25 | To be retained | Falling outside excavation line |
| 2221 | 2180 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2222 | 2181 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2223 | 2182 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2224 | 2183 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2225 | 2184 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2226 | 2185 | kate savar        | <i>Bombax ceiba</i>           | 2   | 35 | To be retained | Falling outside excavation line |
| 2227 | 2186 | Jambhul           | <i>Syzygium cumini</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2228 | 2187 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2229 | 2188 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2230 | 2189 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2231 | 2190 | Toran             | <i>Ziziphus rugosa</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2232 | 2191 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2233 | 2192 | Moha              | <i>Madhuca indica</i>         | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2234 | 2193 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2235 | 2194 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2236 | 2195 | Asana             | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2237 | 2196 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |                |                                 |
|------|------|-------------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2238 | 2197 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 30 | To be retained | Falling outside excavation line |
| 2239 | 2198 | Asana             | <i>Pterocarpus marsupium</i>  | 2   | 15 | To be retained | Falling outside excavation line |
| 2240 | 2199 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2241 | 2200 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2242 | 2201 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2243 | 2202 | Rain tree         | <i>Samanea saman</i>          | 1.5 | 45 | To be retained | Falling outside excavation line |
| 2244 | 2203 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2245 | 2204 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2246 | 2205 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2247 | 2206 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2248 | 2207 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2249 | 2208 | Rain tree         | <i>Samanea saman</i>          | 2   | 25 | To be retained | Falling outside excavation line |
| 2250 | 2209 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2251 | 2210 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2252 | 2211 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2253 | 2212 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2254 | 2213 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2255 | 2214 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 30 | To be retained | Falling outside excavation line |
| 2256 | 2215 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2257 | 2216 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2258 | 2217 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2259 | 2218 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2260 | 2219 | Jambhul           | <i>Syzygium cumini</i>        | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2261 | 2220 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2262 | 2221 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 35 | To be removed  | Falling within excavation line  |
| 2263 | 2222 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2264 | 2223 | Rain tree         | <i>Samanea saman</i>          | 2   | 35 | To be removed  | Falling within excavation line  |
| 2265 | 2224 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |                |                                 |
|------|------|------------|------------------------------|-----|----|----------------|---------------------------------|
| 2266 | 2225 | Petari     | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2267 | 2226 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be removed  | Falling within excavation line  |
| 2268 | 2227 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2269 | 2228 | Petari     | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2270 | 2229 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2271 | 2230 | Apta       | <i>Bauhinia racemosa</i>     | 1   | 10 | To be removed  | Falling within excavation line  |
| 2272 | 2231 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 2273 | 2232 | Not ID     | Not ID                       | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2274 | 2233 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 2275 | 2234 | Shemat     | <i>lannea coromandelica</i>  | 2   | 20 | To be retained | Falling outside excavation line |
| 2276 | 2235 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2277 | 2236 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2278 | 2237 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2279 | 2238 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2280 | 2239 | Rain tree  | <i>Samanea saman</i>         | 2   | 35 | To be removed  | Falling within excavation line  |
| 2281 | 2240 | Pandhari   | <i>Tamilnadia uliginosa</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2282 | 2241 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2283 | 2242 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2284 | 2243 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2285 | 2244 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2286 | 2245 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2287 | 2246 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2288 | 2247 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2289 | 2248 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2290 | 2249 | Shemat     | <i>lannea coromandelica</i>  | 1   | 15 | To be retained | Falling outside excavation line |
| 2291 | 2250 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2292 | 2251 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2293 | 2252 | Tendu      | <i>Diospyros melanoxylon</i> | 1.5 | 15 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                              |     |    |                |                                 |
|------|------|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 2294 | 2253 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2295 | 2254 | Kate savar        | <i>Bombax ceiba</i>          | 2   | 35 | To be retained | Falling outside excavation line |
| 2296 | 2255 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2297 | 2256 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2298 | 2257 | Petari            | <i>Trewia nudiflora</i>      | 1   | 15 | To be retained | Falling outside excavation line |
| 2299 | 2258 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2300 | 2259 | Asana             | <i>Pterocarpus marsupium</i> | 2   | 25 | To be retained | Falling outside excavation line |
| 2301 | 2260 | Shemat            | <i>lannea coromandelica</i>  | 2   | 25 | To be retained | Falling outside excavation line |
| 2302 | 2261 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2303 | 2262 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2304 | 2263 | Shemat            | <i>lannea coromandelica</i>  | 2   | 25 | To be retained | Falling outside excavation line |
| 2305 | 2264 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2306 | 2265 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2307 | 2266 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2308 | 2267 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2309 | 2268 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2310 | 2269 | Tambada kuda      | <i>Wrightia arborea</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 2311 | 2270 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2312 | 2271 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2313 | 2272 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2314 | 2273 | Tambada kuda      | <i>Wrightia arborea</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2315 | 2274 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2316 | 2275 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2317 | 2276 | Bor               | <i>Ziziphus mauritiana</i>   | 2   | 25 | To be retained | Falling outside excavation line |
| 2318 | 2277 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2319 | 2278 | Asana             | <i>Pterocarpus marsupium</i> | 5   | 20 | To be retained | Falling outside excavation line |
| 2320 | 2279 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2321 | 2280 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 10 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |       |            |                              |     |    |                |                                 |
|------|-------|------------|------------------------------|-----|----|----------------|---------------------------------|
| 2322 | 2281  | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2323 | 2282  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2324 | 2283  | Moha       | <i>Madhuca indica</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2325 | 2284  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2326 | 2285  | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 25 | To be retained | Falling outside excavation line |
| 2327 | 2286  | Moha       | <i>Madhuca indica</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2328 | 2287  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2329 | 2288  | Kumbh      | <i>Careya arborea</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2330 | 2289  | Petari     | <i>Trewia nudiflora</i>      | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2331 | 2290  | Shemat     | <i>lannea coromandelica</i>  | 2   | 25 | To be retained | Falling outside excavation line |
| 2332 | 2291  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2333 | 2292  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2334 | 2293  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2335 | 2294  | Petari     | <i>Trewia nudiflora</i>      | 1   | 15 | To be retained | Falling outside excavation line |
| 2336 | 2295  | Petari     | <i>Trewia nudiflora</i>      | 1   | 15 | To be retained | Falling outside excavation line |
| 2337 | 2296  | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2338 | 2297  | Kate savar | <i>Bombax ceiba</i>          | 2   | 25 | To be retained | Falling outside excavation line |
| 2339 | 2297A | Petari     | <i>Trewia nudiflora</i>      | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2340 | 2298  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2341 | 2299  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2342 | 2300  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2343 | 2301  | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2344 | 2302  | Kate savar | <i>Bombax ceiba</i>          | 2   | 30 | To be retained | Falling outside excavation line |
| 2345 | 2303  | Petari     | <i>Trewia nudiflora</i>      | 1   | 15 | To be retained | Falling outside excavation line |
| 2346 | 2304  | Petari     | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2347 | 2305  | Dhaman     | <i>Grewia tiliaefolia</i>    | 1   | 10 | To be retained | Falling outside excavation line |
| 2348 | 2306  | Kate savar | <i>Bombax ceiba</i>          | 2   | 15 | To be retained | Falling outside excavation line |
| 2349 | 2307  | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |                |                                 |
|------|------|----------------|------------------------------|-----|----|----------------|---------------------------------|
| 2350 | 2308 | Shemat         | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2351 | 2309 | Shemat         | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2352 | 2310 | Shemat         | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2353 | 2311 | Atrun          | <i>Flacourtia montana</i>    | 1   | 10 | To be retained | Falling outside excavation line |
| 2354 | 2312 | Bhokar         | <i>Cordia dichotoma</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 2355 | 2313 | Asana          | <i>Pterocarpus marsupium</i> | 1   | 15 | To be retained | Falling outside excavation line |
| 2356 | 2314 | Shemat         | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2357 | 2315 | Shemat         | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2358 | 2316 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 25 | To be retained | Falling outside excavation line |
| 2359 | 2317 | Bor            | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2360 | 2318 | Petari         | <i>Trewia nudiflora</i>      | 1   | 15 | To be retained | Falling outside excavation line |
| 2361 | 2319 | Petari         | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2362 | 2320 | Petari         | <i>Trewia nudiflora</i>      | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2363 | 2321 | Kate savar     | <i>Bombax ceiba</i>          | 1   | 15 | To be retained | Falling outside excavation line |
| 2364 | 2322 | Asana          | <i>Pterocarpus marsupium</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2365 | 2323 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2366 | 2324 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 25 | To be retained | Falling outside excavation line |
| 2367 | 2325 | Asana          | <i>Pterocarpus marsupium</i> | 2   | 25 | To be retained | Falling outside excavation line |
| 2368 | 2326 | Shemat         | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2369 | 2327 | Shemat         | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2370 | 2328 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2371 | 2329 | Dhaman         | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be retained | Falling outside excavation line |
| 2372 | 2330 | Rain tree      | <i>Samanea saman</i>         | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2373 | 2331 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 5   | 20 | To be retained | Falling outside excavation line |
| 2374 | 2332 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2375 | 2333 | Moha           | <i>Madhuca indica</i>        | 1   | 15 | To be retained | Falling outside excavation line |
| 2376 | 2334 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2377 | 2335 | Petari         | <i>Trewia nudiflora</i>      | 1.5 | 20 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                              |     |    |                |                                 |
|------|------|-------------------|------------------------------|-----|----|----------------|---------------------------------|
| 2378 | 2336 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2379 | 2337 | Kahandol          | <i>Sterculia urens</i>       | 2   | 25 | To be retained | Falling outside excavation line |
| 2380 | 2338 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2381 | 2339 | Bor               | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2382 | 2340 | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2383 | 2341 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2384 | 2342 | Shemat            | <i>lannea coromandelica</i>  | 1   | 15 | To be retained | Falling outside excavation line |
| 2385 | 2343 | Atrun             | <i>Flacourtia montana</i>    | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2386 | 2344 | Kahandol          | <i>Sterculia urens</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2387 | 2345 | Kahandol          | <i>Sterculia urens</i>       | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2388 | 2346 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2389 | 2347 | Moha              | <i>Madhuca indica</i>        | 1   | 10 | To be retained | Falling outside excavation line |
| 2390 | 2348 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2391 | 2349 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2392 | 2350 | Rain tree         | <i>Samanea saman</i>         | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2393 | 2351 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2394 | 2352 | Rain tree         | <i>Samanea saman</i>         | 2   | 25 | To be retained | Falling outside excavation line |
| 2395 | 2353 | Australian Babhul | <i>Acacia auriculiformis</i> | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2396 | 2354 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 30 | To be retained | Falling outside excavation line |
| 2397 | 2355 | Australian Babhul | <i>Acacia auriculiformis</i> | 5   | 45 | To be retained | Falling outside excavation line |
| 2398 | 2356 | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be retained | Falling outside excavation line |
| 2399 | 2357 | Australian Babhul | <i>Acacia auriculiformis</i> | 2   | 30 | To be retained | Falling outside excavation line |
| 2400 | 2358 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2401 | 2359 | Kate savar        | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2402 | 2360 | Shemat            | <i>lannea coromandelica</i>  | 1   | 10 | To be retained | Falling outside excavation line |
| 2403 | 2361 | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2404 | 2362 | Asana             | <i>Pterocarpus marsupium</i> | 2   | 15 | To be retained | Falling outside excavation line |
| 2405 | 2363 | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |         |                              |     |    |                |                                 |
|------|------|---------|------------------------------|-----|----|----------------|---------------------------------|
| 2406 | 2364 | Asana   | <i>Pterocarpus marsupium</i> | 2   | 15 | To be retained | Falling outside excavation line |
| 2407 | 2365 | Petari  | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2408 | 2366 | Petari  | <i>Trewia nudiflora</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 2409 | 2367 | Petari  | <i>Trewia nudiflora</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 2410 | 2368 | Petari  | <i>Trewia nudiflora</i>      | 1   | 10 | To be retained | Falling outside excavation line |
| 2411 | 2369 | Petari  | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2412 | 2370 | Dhaman  | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2413 | 2371 | Asana   | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2414 | 2372 | Dhaman  | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2415 | 2373 | Petari  | <i>Trewia nudiflora</i>      | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2416 | 2374 | Kharoti | <i>Streblus asper</i>        | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2417 | 2375 | Kharoti | <i>Streblus asper</i>        | 1   | 15 | To be removed  | Falling within excavation line  |
| 2418 | 2376 | Kharoti | <i>Streblus asper</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2419 | 2377 | Shemat  | <i>lannea coromandelica</i>  | 2   | 25 | To be retained | Falling outside excavation line |
| 2420 | 2378 | Dhaman  | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2421 | 2379 | Dhaman  | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2422 | 2380 | Karanj  | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2423 | 2381 | Amba    | <i>Mangifera indica</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2424 | 2382 | Shemat  | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2425 | 2383 | Dhaman  | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2426 | 2384 | Dhaman  | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be retained | Falling outside excavation line |
| 2427 | 2385 | Kumbh   | <i>careya arborea</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2428 | 2386 | Petari  | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2429 | 2387 | Kumbh   | <i>careya arborea</i>        | 1   | 10 | To be retained | Falling outside excavation line |
| 2430 | 2388 | Kumbh   | <i>careya arborea</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2431 | 2389 | Shemat  | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2432 | 2390 | Shemat  | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2433 | 2391 | Petari  | <i>Trewia nudiflora</i>      | 1   | 15 | To be retained | Falling outside excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                               |     |    |                |                                 |
|------|------|------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2434 | 2392 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 2435 | 2393 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 15 | To be retained | Falling outside excavation line |
| 2436 | 2394 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 15 | To be retained | Falling outside excavation line |
| 2437 | 2395 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2438 | 2396 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2439 | 2397 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 2440 | 2398 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 2441 | 2399 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 2442 | 2400 | Petari     | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2443 | 2401 | Petari     | <i>Trewia nudiflora</i>       | 8   | 10 | To be retained | Falling outside excavation line |
| 2444 | 2402 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 15 | To be retained | Falling outside excavation line |
| 2445 | 2403 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2446 | 2404 | Vavla      | <i>holoptela integrifolia</i> | 1   | 15 | To be retained | Falling outside excavation line |
| 2447 | 2405 | Petari     | <i>Trewia nudiflora</i>       | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2448 | 2406 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2449 | 2407 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 2450 | 2408 | Petari     | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2451 | 2409 | Petari     | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2452 | 2410 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1   | 15 | To be retained | Falling outside excavation line |
| 2453 | 2411 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1   | 15 | To be retained | Falling outside excavation line |
| 2454 | 2412 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 2455 | 2413 | Shemat     | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2456 | 2414 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2457 | 2415 | Kahandol   | <i>Sterculia urens</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2458 | 2416 | Petari     | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2459 | 2417 | Petari     | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2460 | 2418 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2461 | 2419 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                              |     |    |                |                                 |
|------|------|---------------|------------------------------|-----|----|----------------|---------------------------------|
| 2462 | 2420 | Kate savar    | <i>Bombax ceiba</i>          | 1   | 15 | To be retained | Falling outside excavation line |
| 2463 | 2421 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2464 | 2422 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2465 | 2423 | Asana         | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2466 | 2424 | Asana         | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2467 | 2425 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2468 | 2426 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2469 | 2427 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2470 | 2428 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 2471 | 2429 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2472 | 2430 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2473 | 2431 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2474 | 2432 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2475 | 2433 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2476 | 2434 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2477 | 2435 | Dhaman        | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be retained | Falling outside excavation line |
| 2478 | 2436 | Bor           | <i>Ziziphus mauritiana</i>   | 1   | 10 | To be retained | Falling outside excavation line |
| 2479 | 2437 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2480 | 2438 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2481 | 2439 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2482 | 2440 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2483 | 2441 | Karanj        | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2484 | 2442 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2485 | 2443 | Dhaman (Dead) | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2486 | 2444 | Jambhul       | <i>Syzygium cumini</i>       | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2487 | 2445 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2488 | 2446 | Kakad         | <i>Garuga pinnata</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2489 | 2447 | Asana         | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                              |     |    |                |                                 |
|------|------|---------------|------------------------------|-----|----|----------------|---------------------------------|
| 2490 | 2448 | Kakad         | <i>Garuga pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2491 | 2449 | Kakad         | <i>Garuga pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2492 | 2450 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2493 | 2451 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2494 | 2452 | Bor           | <i>Ziziphus mauritiana</i>   | 1   | 15 | To be retained | Falling outside excavation line |
| 2495 | 2453 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2496 | 2454 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2497 | 2455 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2498 | 2456 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2499 | 2457 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2500 | 2458 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2501 | 2459 | Shemat        | <i>lannea coromandolica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2502 | 2460 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2503 | 2461 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2504 | 2462 | Shemat        | <i>lannea coromandolica</i>  | 1.5 | 30 | To be retained | Falling outside excavation line |
| 2505 | 2463 | Shemat        | <i>lannea coromandolica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2506 | 2464 | Shemat        | <i>lannea coromandolica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2507 | 2465 | Asana         | <i>Pterocarpus marsupium</i> | 2   | 20 | To be retained | Falling outside excavation line |
| 2508 | 2466 | Shemat        | <i>lannea coromandolica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2509 | 2467 | Safed Shirish | <i>Albizia procera</i>       | 2   | 35 | To be retained | Falling outside excavation line |
| 2510 | 2468 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2511 | 2469 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2512 | 2470 | Asana         | <i>Pterocarpus marsupium</i> | 2   | 20 | To be retained | Falling outside excavation line |
| 2513 | 2471 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2514 | 2472 | Moha          | <i>Madhuca indica</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2515 | 2473 | Tendu         | <i>Diospyros melanoxylon</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2516 | 2474 | Shemat        | <i>lannea coromandolica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2517 | 2475 | Tendu         | <i>Diospyros melanoxylon</i> | 1   | 10 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |          |                              |     |    |                |                                 |
|------|------|----------|------------------------------|-----|----|----------------|---------------------------------|
| 2518 | 2476 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2519 | 2477 | Dhaman   | <i>Grewia tiliaefolia</i>    | 1   | 10 | To be retained | Falling outside excavation line |
| 2520 | 2478 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2521 | 2479 | Tendu    | <i>Diospyros melanoxylon</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2522 | 2480 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2523 | 2481 | Tendu    | <i>Diospyros melanoxylon</i> | 1   | 10 | To be retained | Falling outside excavation line |
| 2524 | 2482 | Tendu    | <i>Diospyros melanoxylon</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2525 | 2483 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2526 | 2484 | Kakad    | <i>Garuga pinnata</i>        | 2   | 15 | To be retained | Falling outside excavation line |
| 2527 | 2485 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2528 | 2486 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2529 | 2487 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2530 | 2488 | Karanj   | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2531 | 2489 | Subabhul | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be retained | Falling outside excavation line |
| 2532 | 2490 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2533 | 2491 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2534 | 2492 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2535 | 2493 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2536 | 2494 | Shemat   | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2537 | 2495 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2538 | 2496 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2539 | 2497 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2540 | 2498 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2541 | 2499 | Kakad    | <i>Garuga pinnata</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2542 | 2500 | Asana    | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2543 | 2501 | Chinch   | <i>Tamarindus indica</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2544 | 2502 | Shemat   | <i>lannea coromandelica</i>  | 2   | 20 | To be retained | Falling outside excavation line |
| 2545 | 2503 | Kahandol | <i>Sterculia urens</i>       | 1.5 | 20 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |                |                                 |
|------|------|------------|------------------------------|-----|----|----------------|---------------------------------|
| 2546 | 2504 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2547 | 2505 | Asana      | <i>Pterocarpus marsupium</i> | 2   | 15 | To be retained | Falling outside excavation line |
| 2548 | 2506 | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2549 | 2507 | Bahava     | <i>Cassia fistula</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2550 | 2508 | Kahandol   | <i>Sterculia urens</i>       | 1   | 10 | To be retained | Falling outside excavation line |
| 2551 | 2509 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 2552 | 2510 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2553 | 2511 | Asana      | <i>Pterocarpus marsupium</i> | 2   | 20 | To be retained | Falling outside excavation line |
| 2554 | 2512 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2555 | 2513 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2556 | 2514 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2557 | 2515 | Shemat     | <i>lannea coromandelica</i>  | 2   | 20 | To be retained | Falling outside excavation line |
| 2558 | 2516 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2559 | 2517 | Atrun      | <i>Flacourtia montana</i>    | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2560 | 2518 | Kahandol   | <i>Sterculia urens</i>       | 2   | 25 | To be retained | Falling outside excavation line |
| 2561 | 2519 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2562 | 2520 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2563 | 2521 | shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2564 | 2522 | shemat     | <i>lannea coromandelica</i>  | 2   | 15 | To be retained | Falling outside excavation line |
| 2565 | 2523 | shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2566 | 2524 | shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2567 | 2525 | shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2568 | 2526 | shemat     | <i>lannea coromandelica</i>  | 2   | 15 | To be retained | Falling outside excavation line |
| 2569 | 2527 | shemat     | <i>lannea coromandelica</i>  | 1   | 15 | To be retained | Falling outside excavation line |
| 2570 | 2528 | shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2571 | 2529 | shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2572 | 2530 | shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2573 | 2531 | shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |                |                                 |
|------|------|------------|------------------------------|-----|----|----------------|---------------------------------|
| 2574 | 2532 | shemat     | <i>lannea coromandelica</i>  | 2   | 20 | To be retained | Falling outside excavation line |
| 2575 | 2533 | shemat     | <i>lannea coromandelica</i>  | 2   | 20 | To be retained | Falling outside excavation line |
| 2576 | 2534 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 20 | To be removed  | Falling within excavation line  |
| 2577 | 2535 | Kate savar | <i>Bombax ceiba</i>          | 2   | 15 | To be retained | Falling outside excavation line |
| 2578 | 2536 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2579 | 2537 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2580 | 2538 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be retained | Falling outside excavation line |
| 2581 | 2539 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2582 | 2540 | Dhaman     | <i>grewia tiliaefolia</i>    | 2   | 15 | To be retained | Falling outside excavation line |
| 2583 | 2541 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2584 | 2542 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2585 | 2543 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2586 | 2544 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2587 | 2545 | Kate savar | <i>Bombax ceiba</i>          | 2   | 25 | To be retained | Falling outside excavation line |
| 2588 | 2546 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2589 | 2547 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2590 | 2548 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2591 | 2549 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 2592 | 2550 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2593 | 2551 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2594 | 2552 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2595 | 2553 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2596 | 2554 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2597 | 2555 | Asana      | <i>Pterocarpus marsupium</i> | 2   | 20 | To be retained | Falling outside excavation line |
| 2598 | 2556 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2599 | 2557 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2600 | 2558 | Dhaman     | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be removed  | Falling within excavation line  |
| 2601 | 2559 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                   |                               |     |    |                |                                 |
|------|------|-------------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2602 | 2560 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2603 | 2561 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2604 | 2562 | Shemat            | <i>lannea coromandelica</i>   | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2605 | 2563 | Kate savar        | <i>Bombax ceiba</i>           | 10  | 15 | To be retained | Falling outside excavation line |
| 2606 | 2564 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2607 | 2565 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2608 | 2566 | Kate savar        | <i>Bombax ceiba</i>           | 2   | 15 | To be removed  | Falling within excavation line  |
| 2609 | 2567 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2610 | 2568 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2611 | 2569 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 25 | To be removed  | Falling within excavation line  |
| 2612 | 2570 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2613 | 2571 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2614 | 2572 | Australian Babhul | <i>Acacia auriculiformis</i>  | 2   | 30 | To be removed  | Falling within excavation line  |
| 2615 | 2573 | Vavla             | <i>holoptela integrifolia</i> | 1   | 15 | To be removed  | Falling within excavation line  |
| 2616 | 2574 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2617 | 2575 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2618 | 2576 | Australian Babhul | <i>Acacia auriculiformis</i>  | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 2619 | 2577 | Kharoti           | <i>Streblus asper</i>         | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2620 | 2578 | Subabhul          | <i>Leucaena leucocephala</i>  | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 2621 | 2579 | Bor               | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2622 | 2580 | Vavla             | <i>holoptela integrifolia</i> | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2623 | 2581 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2624 | 2582 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2625 | 2583 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2626 | 2584 | Bor               | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2627 | 2585 | Kate savar        | <i>Bombax ceiba</i>           | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 2628 | 2586 | Subabhul          | <i>Leucaena leucocephala</i>  | 2   | 35 | To be removed  | Falling within excavation line  |
| 2629 | 2587 | Dhaman            | <i>Grewia tiliaefolia</i>     | 1   | 15 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                    |                              |     |    |               |                                |
|------|------|--------------------|------------------------------|-----|----|---------------|--------------------------------|
| 2630 | 2588 | Bor                | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2631 | 2589 | Bor                | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2632 | 2590 | Tambda kuda        | <i>Wrightia arborea</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2633 | 2591 | Bor                | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2634 | 2592 | Dhaman             | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 2635 | 2593 | Bor                | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2636 | 2594 | Subabhul           | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2637 | 2595 | <i>Citrus spp.</i> | <i>Citrus spp.</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 2638 | 2596 | Bor                | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2639 | 2597 | Bor                | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2640 | 2598 | Dhaman             | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 2641 | 2599 | Bhokar             | <i>Cordia dichotoma</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 2642 | 2600 | Dhaman             | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2643 | 2601 | Australian Babhul  | <i>Acacia auriculiformis</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 2644 | 2602 | Australian Babhul  | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed | Falling within excavation line |
| 2645 | 2603 | Bor                | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2646 | 2604 | Subabhul           | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2647 | 2605 | Dhaman             | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2648 | 2606 | Dhaman             | <i>Grewia tiliaefolia</i>    | 1   | 10 | To be removed | Falling within excavation line |
| 2649 | 2607 | Kahandol           | <i>Sterculia urens</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2650 | 2608 | Kate savar         | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 2651 | 2609 | Kate savar         | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2652 | 2610 | Kate savar         | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 2653 | 2611 | Dhaman             | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 2654 | 2612 | Dhaman             | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 2655 | 2613 | Asana              | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 2656 | 2614 | Dhaman             | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 2657 | 2615 | Kate savar         | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |               |                                |
|------|------|------------|------------------------------|-----|----|---------------|--------------------------------|
| 2658 | 2616 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 2659 | 2617 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2660 | 2618 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2661 | 2619 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 2662 | 2620 | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 2663 | 2621 | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 2664 | 2622 | Shemat     | <i>lannea coromandelica</i>  | 1   | 15 | To be removed | Falling within excavation line |
| 2665 | 2623 | Shemat     | <i>lannea coromandelica</i>  | 1   | 15 | To be removed | Falling within excavation line |
| 2666 | 2624 | Shemat     | <i>lannea coromandelica</i>  | 2   | 15 | To be removed | Falling within excavation line |
| 2667 | 2625 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2668 | 2626 | Kahandol   | <i>Sterculia urens</i>       | 5   | 30 | To be removed | Falling within excavation line |
| 2669 | 2627 | Shemat     | <i>lannea coromandelica</i>  | 1   | 15 | To be removed | Falling within excavation line |
| 2670 | 2628 | Kahandol   | <i>Sterculia urens</i>       | 2   | 30 | To be removed | Falling within excavation line |
| 2671 | 2629 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2672 | 2630 | Kate savar | <i>Bombax ceiba</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 2673 | 2631 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 2674 | 2632 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 2675 | 2633 | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 35 | To be removed | Falling within excavation line |
| 2676 | 2634 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2677 | 2635 | Asana      | <i>Pterocarpus marsupium</i> | 1   | 10 | To be removed | Falling within excavation line |
| 2678 | 2636 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2679 | 2637 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2680 | 2638 | Moha       | <i>Madhuca indica</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2681 | 2639 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2682 | 2640 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 2683 | 2641 | Kahandol   | <i>Sterculia urens</i>       | 2   | 30 | To be removed | Falling within excavation line |
| 2684 | 2642 | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2685 | 2643 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                              |     |    |               |                                |
|------|------|---------------|------------------------------|-----|----|---------------|--------------------------------|
| 2686 | 2644 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 2687 | 2645 | Dhaman        | <i>Grewia tiliaefolia</i>    | 2   | 20 | To be removed | Falling within excavation line |
| 2688 | 2646 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 2689 | 2647 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 2690 | 2648 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 2691 | 2649 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 2692 | 2650 | Petari        | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2693 | 2651 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 2694 | 2652 | Kharoti       | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2695 | 2653 | Apta          | <i>Bauhinia racemosa</i>     | 2   | 15 | To be removed | Falling within excavation line |
| 2696 | 2654 | Kakad         | <i>Garuga pinnata</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 2697 | 2655 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2698 | 2656 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 2699 | 2657 | Kahandol      | <i>Sterculia urens</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2700 | 2658 | Kahandol      | <i>Sterculia urens</i>       | 2   | 25 | To be removed | Falling within excavation line |
| 2701 | 2659 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 2702 | 2660 | Asana         | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2703 | 2661 | Kahandol      | <i>Sterculia urens</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2704 | 2662 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2705 | 2663 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2706 | 2664 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2707 | 2665 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2708 | 2666 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2709 | 2667 | Palas         | <i>Butea monosperma</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 2710 | 2668 | Bhokar        | <i>Cordia dichotoma</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 2711 | 2669 | Kahandol      | <i>Sterculia urens</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 2712 | 2670 | Bhokar        | <i>Cordia dichotoma</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2713 | 2671 | Bhokar        | <i>Cordia dichotoma</i>      | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |          |                              |     |    |               |                                |
|------|------|----------|------------------------------|-----|----|---------------|--------------------------------|
| 2714 | 2672 | Subabhul | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 2715 | 2673 | Subabhul | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 2716 | 2674 | Subabhul | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 2717 | 2675 | Subabhul | <i>Leucaena leucocephala</i> | 2   | 45 | To be removed | Falling within excavation line |
| 2718 | 2676 | Subabhul | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 2719 | 2677 | Subabhul | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 2720 | 2678 | Subabhul | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 2721 | 2679 | Vaivarna | <i>Crataeva religiosa</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2722 | 2680 | Subabhul | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 2723 | 2681 | Kharoti  | <i>Streblus asper</i>        | 1   | 15 | To be removed | Falling within excavation line |
| 2724 | 2682 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 2725 | 2683 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 2726 | 2684 | Karanj   | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 2727 | 2685 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 20 | To be removed | Falling within excavation line |
| 2728 | 2686 | Dhaman   | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2729 | 2687 | Kharoti  | <i>Streblus asper</i>        | 5   | 30 | To be removed | Falling within excavation line |
| 2730 | 2688 | Asana    | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 2731 | 2689 | Kharoti  | <i>Streblus asper</i>        | 5   | 30 | To be removed | Falling within excavation line |
| 2732 | 2690 | Kahandol | <i>Sterculia urens</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 2733 | 2691 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 10 | To be removed | Falling within excavation line |
| 2734 | 2692 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2735 | 2693 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2736 | 2694 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 20 | To be removed | Falling within excavation line |
| 2737 | 2695 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2738 | 2696 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2739 | 2697 | Karanj   | <i>Pongamia pinnata</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 2740 | 2698 | Dhaman   | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 2741 | 2699 | Kharoti  | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |       |               |                               |     |    |               |                                |
|------|-------|---------------|-------------------------------|-----|----|---------------|--------------------------------|
| 2742 | 2700  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2743 | 2701  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2744 | 2702  | Kate savar    | <i>Bombax ceiba</i>           | 2   | 30 | To be removed | Falling within excavation line |
| 2745 | 2703  | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 2746 | 2704  | Charcoal tree | <i>Trema orientalis</i>       | 1.5 | 35 | To be removed | Falling within excavation line |
| 2747 | 2705  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2748 | 2706  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2749 | 2707  | Bor           | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2750 | 2708  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 20 | To be removed | Falling within excavation line |
| 2751 | 2708A | Vavla         | <i>holoptela integrifolia</i> | 6   | 45 | To be removed | Falling within excavation line |
| 2752 | 2709  | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 2753 | 2710  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2754 | 2711  | Karanj        | <i>Pongamia pinnata</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2755 | 2711A | Bor           | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2756 | 2711B | Bor           | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2757 | 2712  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2758 | 2713  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2759 | 2714  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2760 | 2715  | Kharoti       | <i>Streblus asper</i>         | 1.5 | 20 | To be removed | Falling within excavation line |
| 2761 | 2716  | Apta          | <i>Bauhinia racemosa</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2762 | 2717  | Apta          | <i>Bauhinia racemosa</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 2763 | 2718  | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 2764 | 2719  | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 2765 | 2720  | Bor           | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2766 | 2721  | Karanj        | <i>Pongamia pinnata</i>       | 5   | 45 | To be removed | Falling within excavation line |
| 2767 | 2722  | Karanj        | <i>Pongamia pinnata</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2768 | 2723  | Kate savar    | <i>Bombax ceiba</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 2769 | 2724  | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                             |     |    |               |                                |
|------|------|------------|-----------------------------|-----|----|---------------|--------------------------------|
| 2770 | 2725 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2771 | 2726 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 2772 | 2727 | Dhaman     | <i>Grewia tiliaefolia</i>   | 5   | 25 | To be removed | Falling within excavation line |
| 2773 | 2728 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2774 | 2729 | Karanj     | <i>Pongamia pinnata</i>     | 2   | 15 | To be removed | Falling within excavation line |
| 2775 | 2730 | Dhaman     | <i>Grewia tiliaefolia</i>   | 2   | 15 | To be removed | Falling within excavation line |
| 2776 | 2731 | Kharoti    | <i>Streblus asper</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2777 | 2732 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2778 | 2733 | Kate savar | <i>Bombax ceiba</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2779 | 2734 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 2780 | 2735 | Kate savar | <i>Bombax ceiba</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2781 | 2736 | Kate savar | <i>Bombax ceiba</i>         | 2   | 30 | To be removed | Falling within excavation line |
| 2782 | 2737 | Kahandol   | <i>Sterculia urens</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2783 | 2738 | Kate savar | <i>Bombax ceiba</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2784 | 2739 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1   | 15 | To be removed | Falling within excavation line |
| 2785 | 2740 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2786 | 2741 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2787 | 2742 | Kate savar | <i>Bombax ceiba</i>         | 2   | 20 | To be removed | Falling within excavation line |
| 2788 | 2743 | Kate savar | <i>Bombax ceiba</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2789 | 2744 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 2790 | 2745 | Kate savar | <i>Bombax ceiba</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2791 | 2746 | Dhaman     | <i>Grewia tiliaefolia</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 2792 | 2747 | Kate savar | <i>Bombax ceiba</i>         | 1.5 | 25 | To be removed | Falling within excavation line |
| 2793 | 2748 | Kharoti    | <i>Streblus asper</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2794 | 2749 | Kate savar | <i>Bombax ceiba</i>         | 1   | 15 | To be removed | Falling within excavation line |
| 2795 | 2750 | Kate savar | <i>Bombax ceiba</i>         | 1.5 | 20 | To be removed | Falling within excavation line |
| 2796 | 2751 | Shemat     | <i>lannea coromandelica</i> | 2   | 25 | To be removed | Falling within excavation line |
| 2797 | 2752 | Kahandol   | <i>Sterculia urens</i>      | 2   | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                               |     |    |                |                                 |
|------|------|------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2798 | 2753 | Kaju       | <i>Anacardium occidentale</i> | 5   | 25 | To be removed  | Falling within excavation line  |
| 2799 | 2754 | Kahandol   | <i>Sterculia urens</i>        | 2   | 25 | To be removed  | Falling within excavation line  |
| 2800 | 2755 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2801 | 2756 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2802 | 2757 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2803 | 2758 | Karanj     | <i>Pongamia pinnata</i>       | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2804 | 2759 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 35 | To be removed  | Falling within excavation line  |
| 2805 | 2760 | Petari     | <i>Trewia nudiflora</i>       | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2806 | 2761 | Dhaman     | <i>Grewia tiliaefolia</i>     | 2   | 35 | To be removed  | Falling within excavation line  |
| 2807 | 2762 | Kala umber | <i>Ficus hispida</i>          | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2808 | 2763 | Kala umber | <i>Ficus hispida</i>          | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2809 | 2764 | Karanj     | <i>Pongamia pinnata</i>       | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2810 | 2765 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2811 | 2766 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2812 | 2767 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2813 | 2768 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2814 | 2769 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 2815 | 2770 | Petari     | <i>Trewia nudiflora</i>       | 1   | 15 | To be retained | Falling outside excavation line |
| 2816 | 2771 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2817 | 2772 | Kate savar | <i>Bombax ceiba</i>           | 5   | 30 | To be retained | Falling outside excavation line |
| 2818 | 2773 | Asana      | <i>Pterocarpus marsupium</i>  | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2819 | 2774 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2820 | 2775 | Kate savar | <i>Bombax ceiba</i>           | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2821 | 2776 | Petari     | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2822 | 2777 | Kumbh      | <i>careya arborea</i>         | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2823 | 2778 | Shemat     | <i>lannea coromandelica</i>   | 5   | 25 | To be retained | Falling outside excavation line |
| 2824 | 2779 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1   | 15 | To be retained | Falling outside excavation line |
| 2825 | 2780 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |                |                                 |
|------|------|------------|------------------------------|-----|----|----------------|---------------------------------|
| 2826 | 2781 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2827 | 2782 | Apta       | <i>Bauhinia racemosa</i>     | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2828 | 2783 | Kahandol   | <i>Sterculia urens</i>       | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2829 | 2784 | Kate savar | <i>Bombax ceiba</i>          | 2   | 30 | To be retained | Falling outside excavation line |
| 2830 | 2785 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2831 | 2786 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2832 | 2787 | Asana      | <i>Pterocarpus marsupium</i> | 2   | 25 | To be retained | Falling outside excavation line |
| 2833 | 2788 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2834 | 2789 | Moha       | <i>Madhuca indica</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2835 | 2790 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2836 | 2791 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2837 | 2792 | Shemat     | <i>lannea coromandelica</i>  | 2   | 25 | To be retained | Falling outside excavation line |
| 2838 | 2793 | Karanj     | <i>Pongamia pinnata</i>      | 2   | 20 | To be retained | Falling outside excavation line |
| 2839 | 2794 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2840 | 2795 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2841 | 2796 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2842 | 2797 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2843 | 2798 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be retained | Falling outside excavation line |
| 2844 | 2799 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2845 | 2800 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2846 | 2801 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2847 | 2802 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 2848 | 2803 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2849 | 2804 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2850 | 2805 | Asana      | <i>Pterocarpus marsupium</i> | 2   | 20 | To be retained | Falling outside excavation line |
| 2851 | 2806 | Asana      | <i>Pterocarpus marsupium</i> | 1   | 15 | To be retained | Falling outside excavation line |
| 2852 | 2807 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2853 | 2808 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 30 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                              |     |    |                |                                 |
|------|------|---------------|------------------------------|-----|----|----------------|---------------------------------|
| 2854 | 2809 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 2855 | 2810 | Karanj        | <i>Pongamia pinnata</i>      | 1   | 20 | To be retained | Falling outside excavation line |
| 2856 | 2811 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 2857 | 2812 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2858 | 2813 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2859 | 2814 | Asana         | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2860 | 2815 | Shemat        | <i>lannea coromandelica</i>  | 2   | 20 | To be retained | Falling outside excavation line |
| 2861 | 2816 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2862 | 2817 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2863 | 2818 | Bartondi      | <i>Morinda pubescens</i>     | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2864 | 2819 | Shemat        | <i>lannea coromandelica</i>  | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2865 | 2820 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2866 | 2821 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2867 | 2822 | Kumbh         | <i>careya arborea</i>        | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2868 | 2823 | Kate savar    | <i>Bombax ceiba</i>          | 1   | 10 | To be retained | Falling outside excavation line |
| 2869 | 2824 | Petari        | <i>Trewia nudiflora</i>      | 1   | 15 | To be retained | Falling outside excavation line |
| 2870 | 2825 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be retained | Falling outside excavation line |
| 2871 | 2826 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be retained | Falling outside excavation line |
| 2872 | 2827 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2873 | 2828 | Kate savar    | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2874 | 2829 | Karanj        | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2875 | 2830 | Petari        | <i>Trewia nudiflora</i>      | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2876 | 2831 | Petari        | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2877 | 2832 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2878 | 2833 | Shemat        | <i>lannea coromandelica</i>  | 2   | 20 | To be removed  | Falling within excavation line  |
| 2879 | 2834 | shivan        | <i>Gmelina arborea</i>       | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2880 | 2835 | Karanj        | <i>pongamia pinnata</i>      | 2   | 20 | To be removed  | Falling within excavation line  |
| 2881 | 2836 | Gorakh Chinch | <i>Adansonia digitata</i>    | 10  | 45 | To be removed  | Falling within excavation line  |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |                |                                 |
|------|------|----------------|------------------------------|-----|----|----------------|---------------------------------|
| 2882 | 2837 | Karanj         | <i>pongamia pinnata</i>      | 5   | 30 | To be removed  | Falling within excavation line  |
| 2883 | 2838 | Karanj         | <i>pongamia pinnata</i>      | 2   | 25 | To be removed  | Falling within excavation line  |
| 2884 | 2839 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2885 | 2840 | Kala umber     | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2886 | 2841 | Rain tree      | <i>Samanea saman</i>         | 8   | 35 | To be removed  | Falling within excavation line  |
| 2887 | 2842 | Petari         | <i>Trewia nudiflora</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2888 | 2843 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2889 | 2844 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2890 | 2845 | Karanj         | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2891 | 2846 | Karanj         | <i>Pongamia pinnata</i>      | 2   | 25 | To be removed  | Falling within excavation line  |
| 2892 | 2847 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2893 | 2848 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2894 | 2849 | Karanj         | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2895 | 2850 | Karanj         | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2896 | 2851 | Dhaman         | <i>grewia tiliaefolia</i>    | 2   | 30 | To be removed  | Falling within excavation line  |
| 2897 | 2852 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2898 | 2853 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 30 | To be removed  | Falling within excavation line  |
| 2899 | 2854 | Karanj         | <i>Pongamia pinnata</i>      | 1.5 | 10 | To be removed  | Falling within excavation line  |
| 2900 | 2855 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2901 | 2856 | Rain tree      | <i>Samanea saman</i>         | 5   | 30 | To be removed  | Falling within excavation line  |
| 2902 | 2857 | Asana          | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2903 | 2858 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2904 | 2859 | Dhaman         | <i>Grewia tiliaefolia</i>    | 2   | 25 | To be removed  | Falling within excavation line  |
| 2905 | 2860 | Karanj         | <i>Pongamia pinnata</i>      | 2   | 25 | To be removed  | Falling within excavation line  |
| 2906 | 2861 | Shemat         | <i>lannea coromandelica</i>  | 1.5 | 20 | To be retained | Falling outside excavation line |
| 2907 | 2862 | Shemat         | <i>lannea coromandelica</i>  | 2   | 25 | To be removed  | Falling within excavation line  |
| 2908 | 2863 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 30 | To be retained | Falling outside excavation line |
| 2909 | 2864 | Behada         | <i>Terminalia bellerica</i>  | 8   | 35 | To be retained | Falling outside excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                               |     |    |                |                                 |
|------|------|----------------|-------------------------------|-----|----|----------------|---------------------------------|
| 2910 | 2865 | Kate savar     | <i>Bombax ceiba</i>           | 5   | 35 | To be retained | Falling outside excavation line |
| 2911 | 2866 | Charcoal tree  | <i>Trema orientalis</i>       | 1.5 | 15 | To be retained | Falling outside excavation line |
| 2912 | 2867 | shivan         | <i>Gmelina arborea</i>        | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2913 | 2868 | Kahandol       | <i>Sterculia urens</i>        | 5   | 25 | To be removed  | Falling within excavation line  |
| 2914 | 2869 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2915 | 2870 | Chinch         | <i>Tamarindus indica</i>      | 5   | 20 | To be removed  | Falling within excavation line  |
| 2916 | 2871 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2917 | 2872 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2918 | 2873 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2919 | 2874 | Karanj         | <i>Pongamia pinnata</i>       | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2920 | 2875 | Kharoti        | <i>Streblus asper</i>         | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2921 | 2876 | Kharoti        | <i>Streblus asper</i>         | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2922 | 2877 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2923 | 2878 | Kate savar     | <i>Bombax ceiba</i>           | 5   | 35 | To be removed  | Falling within excavation line  |
| 2924 | 2879 | Karanj         | <i>Pongamia pinnata</i>       | 1   | 15 | To be removed  | Falling within excavation line  |
| 2925 | 2880 | Karanj         | <i>pongamia pinnata</i>       | 1   | 10 | To be removed  | Falling within excavation line  |
| 2926 | 2881 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2927 | 2882 | bor            | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2928 | 2883 | Dhaman         | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2929 | 2884 | Karanj         | <i>pongamia pinnata</i>       | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2930 | 2885 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 2   | 35 | To be removed  | Falling within excavation line  |
| 2931 | 2886 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2932 | 2887 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 1.5 | 20 | To be removed  | Falling within excavation line  |
| 2933 | 2888 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 8   | 25 | To be removed  | Falling within excavation line  |
| 2934 | 2889 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2935 | 2890 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 1.5 | 25 | To be removed  | Falling within excavation line  |
| 2936 | 2891 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed  | Falling within excavation line  |
| 2937 | 2892 | Rain tree      | <i>Samanea saman</i>          | 5   | 45 | To be removed  | Falling within excavation line  |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |       |                   |                              |     |    |               |                                |
|------|-------|-------------------|------------------------------|-----|----|---------------|--------------------------------|
| 2938 | 2893  | Dhaman            | <i>grewia tiliaefolia</i>    | 1   | 10 | To be removed | Falling within excavation line |
| 2939 | 2894  | Shemat            | <i>lannea coromandelica</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 2940 | 2895  | Kala umber        | <i>Ficus hispida</i>         | 1   | 15 | To be removed | Falling within excavation line |
| 2941 | 2896  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2942 | 2897  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 20 | To be removed | Falling within excavation line |
| 2943 | 2898  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be removed | Falling within excavation line |
| 2944 | 2899  | Karanj            | <i>Pongamia pinnata</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 2945 | 2900  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2946 | 2901  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2947 | 2902  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2948 | 2903  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2949 | 2904  | Asana             | <i>Pterocarpus marsupium</i> | 5   | 20 | To be removed | Falling within excavation line |
| 2950 | 2905  | Apta              | <i>Bauhinia racemosa</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 2951 | 2905A | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be removed | Falling within excavation line |
| 2952 | 2906  | Karanj            | <i>Pongamia pinnata</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 2953 | 2907  | Asana             | <i>Pterocarpus marsupium</i> | 2   | 20 | To be removed | Falling within excavation line |
| 2954 | 2908  | Dhaman            | <i>Grewia tiliaefolia</i>    | 5   | 30 | To be removed | Falling within excavation line |
| 2955 | 2909  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2956 | 2910  | Australian Babhul | <i>Acacia auriculiformis</i> | 5   | 45 | To be removed | Falling within excavation line |
| 2957 | 2911  | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2958 | 2912  | Kate savar        | <i>Bombax ceiba</i>          | 5   | 30 | To be removed | Falling within excavation line |
| 2959 | 2913  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 2960 | 2914  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 2961 | 2915  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2962 | 2916  | Australian Babhul | <i>Acacia auriculiformis</i> | 4   | 45 | To be removed | Falling within excavation line |
| 2963 | 2917  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2964 | 2918  | Kala umber        | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2965 | 2919  | Asana             | <i>Pterocarpus marsupium</i> | 2   | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |               |                                |
|------|------|------------|------------------------------|-----|----|---------------|--------------------------------|
| 2966 | 2920 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 2967 | 2921 | Bartondi   | <i>Morinda pubescens</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 2968 | 2922 | Kahandol   | <i>Sterculia urens</i>       | 5   | 30 | To be removed | Falling within excavation line |
| 2969 | 2923 | Kate savar | <i>Bombax ceiba</i>          | 5   | 30 | To be removed | Falling within excavation line |
| 2970 | 2924 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 2971 | 2925 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 2972 | 2926 | Apta       | <i>Bauhinia racemosa</i>     | 1   | 15 | To be removed | Falling within excavation line |
| 2973 | 2927 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2974 | 2928 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2975 | 2929 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 2976 | 2930 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 2977 | 2931 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 10 | To be removed | Falling within excavation line |
| 2978 | 2932 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 2979 | 2933 | Karanj     | <i>pongamia pinnata</i>      | 1   | 15 | To be removed | Falling within excavation line |
| 2980 | 2934 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 2981 | 2935 | Apta       | <i>Bauhinia racemosa</i>     | 1   | 15 | To be removed | Falling within excavation line |
| 2982 | 2936 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2983 | 2937 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 2984 | 2938 | Kala umber | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 2985 | 2939 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 2986 | 2940 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2987 | 2941 | Moha       | <i>Madhuca indica</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2988 | 2942 | Dhaman     | <i>grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 2989 | 2943 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 2990 | 2944 | shivan     | <i>Gmelina arborea</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 2991 | 2945 | shivan     | <i>Gmelina arborea</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 2992 | 2946 | Kharoti    | <i>Streblus asper</i>        | 2   | 15 | To be removed | Falling within excavation line |
| 2993 | 2947 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |               |                                |
|------|------|------------|------------------------------|-----|----|---------------|--------------------------------|
| 2994 | 2948 | Kharoti    | <i>Streblus asper</i>        | 1   | 15 | To be removed | Falling within excavation line |
| 2995 | 2949 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2996 | 2950 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2997 | 2951 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2998 | 2952 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 2999 | 2953 | Toran      | <i>Ziziphus rugosa</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3000 | 2954 | shivan     | <i>Gmelina arborea</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3001 | 2955 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 20 | To be removed | Falling within excavation line |
| 3002 | 2956 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3003 | 2957 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 20 | To be removed | Falling within excavation line |
| 3004 | 2958 | shivan     | <i>Gmelina arborea</i>       | 1   | 15 | To be removed | Falling within excavation line |
| 3005 | 2959 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3006 | 2960 | shivan     | <i>Gmelina arborea</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3007 | 2961 | Shemat     | <i>lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 3008 | 2962 | shivan     | <i>Gmelina arborea</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3009 | 2963 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3010 | 2964 | shivan     | <i>Gmelina arborea</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3011 | 2965 | shivan     | <i>Gmelina arborea</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3012 | 2966 | shivan     | <i>Gmelina arborea</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3013 | 2967 | Asana      | <i>Pterocarpus marsupium</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3014 | 2968 | Vaivarna   | <i>Crataeva religiosa</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3015 | 2969 | shivan     | <i>Gmelina arborea</i>       | 1   | 15 | To be removed | Falling within excavation line |
| 3016 | 2970 | shivan     | <i>Gmelina arborea</i>       | 1   | 15 | To be removed | Falling within excavation line |
| 3017 | 2971 | Bor        | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 3018 | 2972 | Karanj     | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3019 | 2973 | Not ID     | Not ID                       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3020 | 2974 | Kharoti    | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3021 | 2975 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |               |                                |
|------|------|----------------|------------------------------|-----|----|---------------|--------------------------------|
| 3022 | 2976 | Dhaman         | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be removed | Falling within excavation line |
| 3023 | 2977 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3024 | 2978 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3025 | 2979 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3026 | 2980 | Karanj         | <i>pongamia pinnata</i>      | 2   | 15 | To be removed | Falling within excavation line |
| 3027 | 2981 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 10 | To be removed | Falling within excavation line |
| 3028 | 2982 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3029 | 2983 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3030 | 2984 | Kharoti        | <i>Streblus asper</i>        | 2   | 15 | To be removed | Falling within excavation line |
| 3031 | 2985 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 3032 | 2986 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 3033 | 2987 | Dhaman         | <i>grewia tiliaefolia</i>    | 2   | 15 | To be removed | Falling within excavation line |
| 3034 | 2988 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 3035 | 2989 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 10 | To be removed | Falling within excavation line |
| 3036 | 2990 | Dhaman         | <i>grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3037 | 2991 | Bor            | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 3038 | 2992 | Apta           | <i>Bauhinia racemosa</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3039 | 2993 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 3040 | 2994 | Kahandol       | <i>Sterculia urens</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 3041 | 2995 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3042 | 2996 | Apta           | <i>Bauhinia racemosa</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 3043 | 2997 | Kahandol       | <i>Sterculia urens</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3044 | 2998 | Kahandol       | <i>Sterculia urens</i>       | 2   | 25 | To be removed | Falling within excavation line |
| 3045 | 2999 | Kahandol       | <i>Sterculia urens</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3046 | 3000 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 10 | To be removed | Falling within excavation line |
| 3047 | 3001 | Kate savar     | <i>Bombax ceiba</i>          | 5   | 35 | To be removed | Falling within excavation line |
| 3048 | 3002 | Moha           | <i>Madhuca indica</i>        | 1.5 | 10 | To be removed | Falling within excavation line |
| 3049 | 3003 | Dhaman         | <i>Grewia tiliaefolia</i>    | 2   | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |               |                                |
|------|------|------------|------------------------------|-----|----|---------------|--------------------------------|
| 3050 | 3004 | Karanj     | <i>Pongamia pinnata</i>      | 2   | 35 | To be removed | Falling within excavation line |
| 3051 | 3005 | Apta       | <i>Bauhinia racemosa</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 3052 | 3006 | Shemat     | <i>lannea coromandelica</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 3053 | 3007 | Apta       | <i>Bauhinia racemosa</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 3054 | 3008 | Apta       | <i>Bauhinia racemosa</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3055 | 3009 | Apta       | <i>Bauhinia racemosa</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3056 | 3010 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3057 | 3011 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 3058 | 3012 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3059 | 3013 | Asana      | <i>Pterocarpus marsupium</i> | 1   | 15 | To be removed | Falling within excavation line |
| 3060 | 3014 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3061 | 3015 | Asana      | <i>Pterocarpus marsupium</i> | 2   | 20 | To be removed | Falling within excavation line |
| 3062 | 3016 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 3063 | 3017 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3064 | 3018 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3065 | 3019 | Chinch     | <i>Tamarindus indica</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 3066 | 3020 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3067 | 3021 | Bor        | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 3068 | 3022 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3069 | 3023 | Apta       | <i>Bauhinia racemosa</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3070 | 3024 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3071 | 3025 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3072 | 3026 | Kate savar | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 3073 | 3027 | Apta       | <i>Bauhinia racemosa</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3074 | 3028 | Rain tree  | <i>Samanea saman</i>         | 8   | 45 | To be removed | Falling within excavation line |
| 3075 | 3029 | Kate savar | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 3076 | 3030 | Dhaman     | <i>grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3077 | 3031 | Rain tree  | <i>Samanea saman</i>         | 10  | 45 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |               |                                |
|------|------|----------------|------------------------------|-----|----|---------------|--------------------------------|
| 3078 | 3032 | Rain tree      | <i>Samanea saman</i>         | 8   | 45 | To be removed | Falling within excavation line |
| 3079 | 3033 | Kharoti        | <i>Streblus asper</i>        | 2   | 15 | To be removed | Falling within excavation line |
| 3080 | 3034 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3081 | 3035 | Kala umber     | <i>Ficus hispida</i>         | 1.5 | 10 | To be removed | Falling within excavation line |
| 3082 | 3036 | Bor            | <i>Ziziphus mauritiana</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 3083 | 3037 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 3084 | 3038 | Karanj         | <i>Pongamia pinnata</i>      | 5   | 20 | To be removed | Falling within excavation line |
| 3085 | 3039 | Rain tree      | <i>Samanea saman</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 3086 | 3040 | Rain tree      | <i>Samanea saman</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 3087 | 3041 | Rain tree      | <i>Samanea saman</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 3088 | 3042 | Karanj         | <i>Pongamia pinnata</i>      | 3   | 35 | To be removed | Falling within excavation line |
| 3089 | 3043 | Rain tree      | <i>Samanea saman</i>         | 5   | 35 | To be removed | Falling within excavation line |
| 3090 | 3044 | Rain tree      | <i>Samanea saman</i>         | 2   | 45 | To be removed | Falling within excavation line |
| 3091 | 3045 | Rain tree      | <i>Samanea saman</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 3092 | 3046 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 5   | 25 | To be removed | Falling within excavation line |
| 3093 | 3047 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3094 | 3048 | Asana          | <i>Pterocarpus marsupium</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3095 | 3049 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 3096 | 3050 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be removed | Falling within excavation line |
| 3097 | 3051 | Asana          | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3098 | 3052 | Asana          | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3099 | 3053 | Rain tree      | <i>Samanea saman</i>         | 1.5 | 10 | To be removed | Falling within excavation line |
| 3100 | 3054 | Rain tree      | <i>Samanea saman</i>         | 1.5 | 30 | To be removed | Falling within excavation line |
| 3101 | 3055 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3102 | 3056 | Pilkhan        | <i>Ficus tsjakela</i>        | 2   | 20 | To be removed | Falling within excavation line |
| 3103 | 3057 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3104 | 3058 | Palas          | <i>Butea monosperma</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 3105 | 3059 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 25 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |       |                   |                              |     |    |               |                                |
|------|-------|-------------------|------------------------------|-----|----|---------------|--------------------------------|
| 3106 | 3060  | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3107 | 3061  | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3108 | 3062  | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 10 | To be removed | Falling within excavation line |
| 3109 | 3063  | Bhokar            | <i>Cordia dichotoma</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 3110 | 3064  | Kate savar        | <i>Bombax ceiba</i>          | 8   | 30 | To be removed | Falling within excavation line |
| 3111 | 3065  | Kumbh             | <i>careya arborea</i>        | 2   | 25 | To be removed | Falling within excavation line |
| 3112 | 3065A | Kahandol          | <i>Sterculia urens</i>       | 2   | 20 | To be removed | Falling within excavation line |
| 3113 | 3065B | Subabhul          | <i>Leucaena leucocephala</i> | 5   | 35 | To be removed | Falling within excavation line |
| 3114 | 3065C | Subabhul          | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3115 | 3066  | Kaim              | <i>Mitragyna parvifolia</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 3116 | 3067  | Kate savar        | <i>Bombax ceiba</i>          | 8   | 35 | To be removed | Falling within excavation line |
| 3117 | 3068  | Dhaman            | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be removed | Falling within excavation line |
| 3118 | 3069  | Kate savar        | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 3119 | 3070  | Asana             | <i>Pterocarpus marsupium</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3120 | 3071  | Kate savar        | <i>Bombax ceiba</i>          | 2   | 25 | To be removed | Falling within excavation line |
| 3121 | 3072  | Kate savar        | <i>Bombax ceiba</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 3122 | 3073  | Australian Babbul | <i>Acacia auriculiformis</i> | 2   | 35 | To be removed | Falling within excavation line |
| 3123 | 3073A | Rain tree         | <i>Samanea saman</i>         | 7   | 35 | To be removed | Falling within excavation line |
| 3124 | 3073B | Australian Babbul | <i>Acacia auriculiformis</i> | 5   | 35 | To be removed | Falling within excavation line |
| 3125 | 3073C | Karanj            | <i>Pongamia pinnata</i>      | 5   | 35 | To be removed | Falling within excavation line |
| 3126 | 3073D | Asana             | <i>Pterocarpus marsupium</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3127 | 3073E | Vilayti Chinch    | <i>Pithecellobium dulce</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3128 | 3074  | Dhaman            | <i>grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3129 | 3075  | Dhaman            | <i>grewia tiliaefolia</i>    | 2   | 30 | To be removed | Falling within excavation line |
| 3130 | 3076  | Kharoti           | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3131 | 3077  | Kharoti           | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3132 | 3078  | Dhaman            | <i>Grewia tiliaefolia</i>    | 2   | 15 | To be removed | Falling within excavation line |
| 3133 | 3079  | Shemat            | <i>lannea coromandelica</i>  | 1.5 | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |       |                |                              |     |    |               |                                |
|------|-------|----------------|------------------------------|-----|----|---------------|--------------------------------|
| 3134 | 3080  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3135 | 3081  | Shemat         | <i>lannea coromandelica</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 3136 | 3082  | Kahandol       | <i>Sterculia urens</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 3137 | 3083  | Asana          | <i>Pterocarpus marsupium</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3138 | 3084  | Kharoti        | <i>Streblus asper</i>        | 2   | 15 | To be removed | Falling within excavation line |
| 3139 | 3085  | Kate savar     | <i>Bombax ceiba</i>          | 5   | 30 | To be removed | Falling within excavation line |
| 3140 | 3086  | Kahandol       | <i>Sterculia urens</i>       | 2   | 20 | To be removed | Falling within excavation line |
| 3141 | 3087  | Apta           | <i>Bauhinia racemosa</i>     | 1.5 | 10 | To be removed | Falling within excavation line |
| 3142 | 3088  | Apta           | <i>Bauhinia racemosa</i>     | 1.5 | 10 | To be removed | Falling within excavation line |
| 3143 | 3089  | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 3144 | 3090  | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3145 | 3091  | Karanj         | <i>Pongamia pinnata</i>      | 1.5 | 10 | To be removed | Falling within excavation line |
| 3146 | 3092  | Jambhul        | <i>Syzygium cumini</i>       | 5   | 35 | To be removed | Falling within excavation line |
| 3147 | 3093  | Kate savar     | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 3148 | 3093A | Kala umber     | <i>Ficus hispida</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 3149 | 3093B | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 3150 | 3094  | Rain tree      | <i>Samanea saman</i>         | 10  | 35 | To be removed | Falling within excavation line |
| 3151 | 3095  | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 3152 | 3096  | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3153 | 3097  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3154 | 3097A | Karanj         | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3155 | 3098  | Bhokar         | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 3156 | 3099  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 10 | To be removed | Falling within excavation line |
| 3157 | 3100  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3158 | 3101  | Kharoti        | <i>Streblus asper</i>        | 2   | 15 | To be removed | Falling within excavation line |
| 3159 | 3102  | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3160 | 3103  | Kumbh          | <i>careya arborea</i>        | 8   | 30 | To be removed | Falling within excavation line |
| 3161 | 3104  | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                                |     |    |               |                                |
|------|------|----------------|--------------------------------|-----|----|---------------|--------------------------------|
| 3162 | 3105 | Tambada kuda   | <i>Wrightia arborea</i>        | 1.5 | 10 | To be removed | Falling within excavation line |
| 3163 | 3106 | Tambada kuda   | <i>Wrightia arborea</i>        | 1.5 | 10 | To be removed | Falling within excavation line |
| 3164 | 3107 | Tambada kuda   | <i>Wrightia arborea</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3165 | 3108 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 3166 | 3109 | Charcoal tree  | <i>Trema orientalis</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3167 | 3110 | Petari         | <i>Trewia nudiflora</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3168 | 3111 | Karanj         | <i>Pongamia pinnata</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3169 | 3112 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 5   | 25 | To be removed | Falling within excavation line |
| 3170 | 3113 | Vavla          | <i>Holoptela integrifolia</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3171 | 3114 | Charcoal tree  | <i>Trema orientalis</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 3172 | 3115 | Vavla          | <i>Holoptela integrifolia</i>  | 1.5 | 10 | To be removed | Falling within excavation line |
| 3173 | 3116 | Subabhul       | <i>Leucaena leucocephala</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 3174 | 3117 | Kate savar     | <i>Bombax ceiba</i>            | 1.5 | 25 | To be removed | Falling within excavation line |
| 3175 | 3118 | Vavla          | <i>Holoptela integrifolia</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 3176 | 3119 | Vavla          | <i>Holoptela integrifolia</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 3177 | 3120 | Subabhul       | <i>Leucaena leucocephala</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 3178 | 3121 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3179 | 3122 | Sonmohar       | <i>Peltophorum pterocarpum</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3180 | 3123 | Charcoal tree  | <i>Trema orientalis</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3181 | 3124 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 3182 | 3125 | Subabhul       | <i>Leucaena leucocephala</i>   | 2   | 20 | To be removed | Falling within excavation line |
| 3183 | 3126 | Kala umber     | <i>Ficus hispida</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 3184 | 3127 | Kala umber     | <i>Ficus hispida</i>           | 1.5 | 10 | To be removed | Falling within excavation line |
| 3185 | 3128 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 3186 | 3129 | Kharoti        | <i>Streblus asper</i>          | 5   | 15 | To be removed | Falling within excavation line |
| 3187 | 3130 | Kharoti        | <i>Streblus asper</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 3188 | 3131 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 3189 | 3132 | Karanj         | <i>Pongamia pinnata</i>        | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                               |     |    |               |                                |
|------|------|---------------|-------------------------------|-----|----|---------------|--------------------------------|
| 3190 | 3133 | Bhokar        | <i>Cordia dichotoma</i>       | 2   | 25 | To be removed | Falling within excavation line |
| 3191 | 3134 | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 3192 | 3135 | Dhaman        | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3193 | 3136 | Kharoti       | <i>Streblus asper</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 3194 | 3137 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3195 | 3138 | Asana         | <i>Pterocarpus marsupium</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3196 | 3139 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3197 | 3140 | Kala umber    | <i>Ficus hispida</i>          | 1.5 | 25 | To be removed | Falling within excavation line |
| 3198 | 3141 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 3199 | 3142 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3200 | 3143 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3201 | 3144 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3202 | 3145 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3203 | 3146 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3204 | 3147 | Subabhul      | <i>Leucaena leucocephala</i>  | 5   | 15 | To be removed | Falling within excavation line |
| 3205 | 3148 | Charcoal tree | <i>Trema orientalis</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3206 | 3149 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3207 | 3150 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 3208 | 3151 | Subabhul      | <i>Leucaena leucocephala</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 3209 | 3152 | Karvat        | <i>Ficus asperrima</i>        | 2   | 15 | To be removed | Falling within excavation line |
| 3210 | 3153 | Vavla         | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3211 | 3154 | Subabhul      | <i>Leucaena leucocephala</i>  | 1.5 | 35 | To be removed | Falling within excavation line |
| 3212 | 3155 | Subabhul      | <i>Leucaena leucocephala</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 3213 | 3156 | Bor           | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3214 | 3157 | Bor           | <i>Ziziphus mauritiana</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3215 | 3158 | Bor           | <i>ziziphus mauritiana</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3216 | 3159 | Vavla         | <i>Holoptela integrifolia</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3217 | 3160 | Bor           | <i>Ziziphus mauritiana</i>    | 1.5 | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                               |     |    |               |                                |
|------|------|----------------|-------------------------------|-----|----|---------------|--------------------------------|
| 3218 | 3161 | Babhul         | <i>Acacia nilotica</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3219 | 3162 | Bor            | <i>Ziziphus mauritiana</i>    | 2   | 25 | To be removed | Falling within excavation line |
| 3220 | 3163 | Vavla          | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 3221 | 3164 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3222 | 3165 | Vavla          | <i>Holoptela integrifolia</i> | 1   | 10 | To be removed | Falling within excavation line |
| 3223 | 3166 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3224 | 3167 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3225 | 3168 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3226 | 3169 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3227 | 3170 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3228 | 3171 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3229 | 3172 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3230 | 3173 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3231 | 3174 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3232 | 3175 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3233 | 3176 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3234 | 3177 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3235 | 3178 | Vavla          | <i>Holoptela integrifolia</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3236 | 3179 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3237 | 3180 | Bor            | <i>Ziziphus mauritiana</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 3238 | 3181 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 2   | 25 | To be removed | Falling within excavation line |
| 3239 | 3182 | Vavla          | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 3240 | 3183 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3241 | 3184 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3242 | 3185 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3243 | 3186 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3244 | 3187 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3245 | 3188 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |          |                               |     |    |               |                                |
|------|------|----------|-------------------------------|-----|----|---------------|--------------------------------|
| 3246 | 3189 | Vavla    | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 3247 | 3190 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3248 | 3191 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3249 | 3192 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3250 | 3193 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3251 | 3194 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3252 | 3195 | Vavla    | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 3253 | 3196 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3254 | 3197 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3255 | 3198 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3256 | 3199 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3257 | 3200 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3258 | 3201 | Dhaman   | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 3259 | 3202 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3260 | 3203 | Bor      | <i>Ziziphus mauritiana</i>    | 2   | 20 | To be removed | Falling within excavation line |
| 3261 | 3204 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3262 | 3205 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3263 | 3206 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3264 | 3207 | Dhaman   | <i>Grewia tiliaefolia</i>     | 1   | 15 | To be removed | Falling within excavation line |
| 3265 | 3208 | Dhaman   | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3266 | 3209 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3267 | 3210 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3268 | 3211 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 20 | To be removed | Falling within excavation line |
| 3269 | 3212 | Dhaman   | <i>Grewia tiliaefolia</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 3270 | 3213 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3271 | 3214 | Subabhul | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 3272 | 3215 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3273 | 3216 | Vavla    | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                               |     |    |               |                                |
|------|------|------------|-------------------------------|-----|----|---------------|--------------------------------|
| 3274 | 3217 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3275 | 3218 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3276 | 3219 | Subabhul   | <i>Leucaena leucocephala</i>  | 1.5 | 25 | To be removed | Falling within excavation line |
| 3277 | 3220 | Vavla      | <i>Holoptela integrifolia</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3278 | 3221 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3279 | 3222 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3280 | 3223 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3281 | 3224 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3282 | 3225 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3283 | 3226 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3284 | 3227 | Vavla      | <i>Holoptela integrifolia</i> | 1   | 15 | To be removed | Falling within excavation line |
| 3285 | 3228 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3286 | 3229 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3287 | 3230 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3288 | 3231 | Umber      | <i>Ficus glomerata</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3289 | 3232 | Umber      | <i>Ficus glomerata</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3290 | 3233 | Umber      | <i>Ficus glomerata</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3291 | 3234 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3292 | 3235 | Subabhul   | <i>Leucaena leucocephala</i>  | 1   | 20 | To be removed | Falling within excavation line |
| 3293 | 3236 | Dhaman     | <i>Grewia tiliaefolia</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3294 | 3237 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3295 | 3238 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3296 | 3239 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3297 | 3240 | Subabhul   | <i>Leucaena leucocephala</i>  | 2   | 35 | To be removed | Falling within excavation line |
| 3298 | 3241 | Karanj     | <i>Pongamia pinnata</i>       | 2   | 25 | To be removed | Falling within excavation line |
| 3299 | 3242 | Kate savar | <i>Bombax ceiba</i>           | 5   | 45 | To be removed | Falling within excavation line |
| 3300 | 3243 | Umber      | <i>Ficus glomerata</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3301 | 3244 | Vavla      | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                               |     |    |               |                                |
|------|------|----------------|-------------------------------|-----|----|---------------|--------------------------------|
| 3302 | 3245 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3303 | 3246 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3304 | 3247 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3305 | 3248 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3306 | 3249 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3307 | 3250 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3308 | 3251 | Petari         | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3309 | 3252 | Petari         | <i>Trewia nudiflora</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 3310 | 3253 | Petari         | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3311 | 3254 | Karanj         | <i>Pongamia pinnata</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3312 | 3255 | Kate savar     | <i>Bombax ceiba</i>           | 2   | 15 | To be removed | Falling within excavation line |
| 3313 | 3256 | Petari         | <i>Trewia nudiflora</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3314 | 3257 | Karanj         | <i>Pongamia pinnata</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3315 | 3258 | Vavla          | <i>Holoptela integrifolia</i> | 5   | 35 | To be removed | Falling within excavation line |
| 3316 | 3259 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3317 | 3260 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3318 | 3261 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3319 | 3262 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 1.5 | 25 | To be removed | Falling within excavation line |
| 3320 | 3263 | Vavla          | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 3321 | 3264 | Vavla          | <i>Holoptela integrifolia</i> | 2   | 30 | To be removed | Falling within excavation line |
| 3322 | 3265 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3323 | 3266 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3324 | 3267 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3325 | 3268 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3326 | 3269 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3327 | 3270 | Kala umber     | <i>Ficus hispida</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3328 | 3271 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3329 | 3272 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                               |     |    |               |                                |
|------|------|----------------|-------------------------------|-----|----|---------------|--------------------------------|
| 3330 | 3273 | Kate savar     | <i>Bombax ceiba</i>           | 1.5 | 20 | To be removed | Falling within excavation line |
| 3331 | 3274 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3332 | 3275 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3333 | 3276 | Kala umber     | <i>Ficus hispida</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3334 | 3277 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3335 | 3278 | Charcoal tree  | <i>Trema orientalis</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 3336 | 3279 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3337 | 3280 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3338 | 3281 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3339 | 3282 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3340 | 3283 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3341 | 3284 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3342 | 3285 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3343 | 3286 | Vilayti Chinch | <i>Pithecellobium dulce</i>   | 1   | 20 | To be removed | Falling within excavation line |
| 3344 | 3287 | Charcoal tree  | <i>Trema orientalis</i>       | 1   | 20 | To be removed | Falling within excavation line |
| 3345 | 3288 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 25 | To be removed | Falling within excavation line |
| 3346 | 3289 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 25 | To be removed | Falling within excavation line |
| 3347 | 3290 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 25 | To be removed | Falling within excavation line |
| 3348 | 3291 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 20 | To be removed | Falling within excavation line |
| 3349 | 3292 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 20 | To be removed | Falling within excavation line |
| 3350 | 3293 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3351 | 3294 | Vavla          | <i>Holoptela integrifolia</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3352 | 3295 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 20 | To be removed | Falling within excavation line |
| 3353 | 3296 | Subabhul       | <i>Leucaena leucocephala</i>  | 1.5 | 15 | To be removed | Falling within excavation line |
| 3354 | 3297 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 25 | To be removed | Falling within excavation line |
| 3355 | 3298 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 25 | To be removed | Falling within excavation line |
| 3356 | 3299 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 25 | To be removed | Falling within excavation line |
| 3357 | 3300 | Subabhul       | <i>Leucaena leucocephala</i>  | 1   | 30 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                  |                              |     |    |               |                                |
|------|------|------------------|------------------------------|-----|----|---------------|--------------------------------|
| 3358 | 3301 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3359 | 3302 | Chinch           | <i>Tamarindus indica</i>     | 2   | 15 | To be removed | Falling within excavation line |
| 3360 | 3303 | Kate savar       | <i>Bombax ceiba</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 3361 | 3304 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3362 | 3305 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3363 | 3306 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3364 | 3307 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3365 | 3308 | Charcoal tree    | <i>Trema orientalis</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 3366 | 3309 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3367 | 3310 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3368 | 3311 | Charcoal tree    | <i>Trema orientalis</i>      | 1   | 15 | To be removed | Falling within excavation line |
| 3369 | 3312 | Subabhul         | <i>Leucaena leucocephala</i> | 1   | 20 | To be removed | Falling within excavation line |
| 3370 | 3313 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3371 | 3314 | Charcoal tree    | <i>Trema orientalis</i>      | 1.5 | 30 | To be removed | Falling within excavation line |
| 3372 | 3315 | Charcoal tree    | <i>Trema orientalis</i>      | 1.5 | 30 | To be removed | Falling within excavation line |
| 3373 | 3316 | Charcoal tree    | <i>Trema orientalis</i>      | 1.5 | 30 | To be removed | Falling within excavation line |
| 3374 | 3317 | Kumbh            | <i>careya arborea</i>        | 2   | 25 | To be removed | Falling within excavation line |
| 3375 | 3318 | Charcoal tree    | <i>Trema orientalis</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 3376 | 3319 | Charcoal tree    | <i>Trema orientalis</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 3377 | 3320 | Singapore cherry | <i>Muntingia calabura</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3378 | 3321 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3379 | 3322 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3380 | 3323 | Kate savar       | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3381 | 3324 | Vaivarna         | <i>Crataeva religiosa</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3382 | 3325 | Subabhul         | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3383 | 3326 | Vaivarna         | <i>Crataeva religiosa</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3384 | 3327 | Kate savar       | <i>Bombax ceiba</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3385 | 3328 | Dhaman           | <i>Grewia tiliaefolia</i>    | 1.5 | 30 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |               |                                |
|------|------|----------------|------------------------------|-----|----|---------------|--------------------------------|
| 3386 | 3329 | Kaduneem       | <i>Azadirachta indica</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3387 | 3330 | Shemat         | <i>Lannea coromandelica</i>  | 1.5 | 30 | To be removed | Falling within excavation line |
| 3388 | 3331 | Shemat         | <i>Lannea coromandelica</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 3389 | 3332 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3390 | 3333 | Kakad          | <i>Garuga pinnata</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 3391 | 3334 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3392 | 3335 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 3393 | 3336 | Vaivarna       | <i>Crataeva religiosa</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3394 | 3337 | Bhokar         | <i>Cordia dichotoma</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 3395 | 3338 | Kate savar     | <i>Bombax ceiba</i>          | 10  | 50 | To be removed | Falling within excavation line |
| 3396 | 3339 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3397 | 3340 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 35 | To be removed | Falling within excavation line |
| 3398 | 3341 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3399 | 3342 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3400 | 3343 | Charcoal tree  | <i>Trema orientalis</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3401 | 3344 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3402 | 3345 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3403 | 3346 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3404 | 3347 | Kate savar     | <i>Bombax ceiba</i>          | 2   | 15 | To be removed | Falling within excavation line |
| 3405 | 3348 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3406 | 3349 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3407 | 3350 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3408 | 3351 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3409 | 3352 | Subabhul       | <i>Leucaena leucocephala</i> | 1   | 15 | To be removed | Falling within excavation line |
| 3410 | 3353 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3411 | 3354 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3412 | 3355 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 3413 | 3356 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                              |     |    |               |                                |
|------|------|---------------|------------------------------|-----|----|---------------|--------------------------------|
| 3414 | 3357 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3415 | 3358 | Subabhul      | <i>Leucaena leucocephala</i> | 1   | 15 | To be removed | Falling within excavation line |
| 3416 | 3359 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3417 | 3360 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3418 | 3361 | Subabhul      | <i>Leucaena leucocephala</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3419 | 3362 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3420 | 3363 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 3421 | 3364 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3422 | 3365 | Kate savar    | <i>Bombax ceiba</i>          | 5   | 25 | To be removed | Falling within excavation line |
| 3423 | 3366 | Shemat        | <i>Lannea coromandelica</i>  | 2   | 20 | To be removed | Falling within excavation line |
| 3424 | 3367 | Bor           | <i>Ziziphus mauritiana</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 3425 | 3368 | Chinch        | <i>Tamarindus indica</i>     | 2   | 30 | To be removed | Falling within excavation line |
| 3426 | 3369 | Jambhul       | <i>Syzygium cumini</i>       | 8   | 25 | To be removed | Falling within excavation line |
| 3427 | 3370 | Bhokar        | <i>Cordia dichotoma</i>      | 5   | 25 | To be removed | Falling within excavation line |
| 3428 | 3371 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3429 | 3372 | Kate savar    | <i>Bombax ceiba</i>          | 5   | 30 | To be removed | Falling within excavation line |
| 3430 | 3373 | Amba          | <i>Mangifera indica</i>      | 5   | 30 | To be removed | Falling within excavation line |
| 3431 | 3374 | Dhaman        | <i>Grewia tiliaefolia</i>    | 1   | 10 | To be removed | Falling within excavation line |
| 3432 | 3375 | Kharoti       | <i>Streblus asper</i>        | 5   | 25 | To be removed | Falling within excavation line |
| 3433 | 3376 | Asana         | <i>Pterocarpus marsupium</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3434 | 3377 | Charcoal tree | <i>Trema orientalis</i>      | 1   | 10 | To be removed | Falling within excavation line |
| 3435 | 3378 | Dhaman        | <i>Grewia tiliaefolia</i>    | 2   | 20 | To be removed | Falling within excavation line |
| 3436 | 3379 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3437 | 3380 | Asana         | <i>Pterocarpus marsupium</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3438 | 3381 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3439 | 3382 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3440 | 3383 | Asana         | <i>Pterocarpus marsupium</i> | 5   | 20 | To be removed | Falling within excavation line |
| 3441 | 3384 | Karanj        | <i>Pongamia pinnata</i>      | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |               |                                |
|------|------|----------------|------------------------------|-----|----|---------------|--------------------------------|
| 3442 | 3385 | Pimpal         | <i>Ficus religiosa</i>       | 10  | 25 | To be removed | Falling within excavation line |
| 3443 | 3386 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 5   | 25 | To be removed | Falling within excavation line |
| 3444 | 3387 | Kharoti        | <i>Streblus asper</i>        | 2   | 20 | To be removed | Falling within excavation line |
| 3445 | 3388 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 2   | 30 | To be removed | Falling within excavation line |
| 3446 | 3389 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3447 | 3390 | Charcoal tree  | <i>Trema orientalis</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3448 | 3391 | Dhaman         | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3449 | 3392 | Charcoal tree  | <i>Trema orientalis</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3450 | 3393 | Kate savar     | <i>Bombax ceiba</i>          | 1.5 | 10 | To be removed | Falling within excavation line |
| 3451 | 3394 | Charcoal tree  | <i>Trema orientalis</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 3452 | 3395 | Charcoal tree  | <i>Trema orientalis</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 3453 | 3396 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3454 | 3397 | Charcoal tree  | <i>Trema orientalis</i>      | 2   | 20 | To be removed | Falling within excavation line |
| 3455 | 3398 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3456 | 3399 | Charcoal tree  | <i>Trema orientalis</i>      | 2   | 20 | To be removed | Falling within excavation line |
| 3457 | 3400 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3458 | 3401 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3459 | 3402 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3460 | 3403 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3461 | 3404 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3462 | 3405 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3463 | 3406 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3464 | 3407 | Subabhul       | <i>leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3465 | 3408 | Subabhul       | <i>Leucaena leucocephala</i> | 1   | 20 | To be removed | Falling within excavation line |
| 3466 | 3409 | Charcoal tree  | <i>Trema orientalis</i>      | 1   | 15 | To be removed | Falling within excavation line |
| 3467 | 3410 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3468 | 3411 | Subabhul       | <i>Leucaena leucocephala</i> | 1   | 15 | To be removed | Falling within excavation line |
| 3469 | 3412 | Subabhul       | <i>Leucaena leucocephala</i> | 1   | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |               |                              |     |    |               |                                |
|------|------|---------------|------------------------------|-----|----|---------------|--------------------------------|
| 3470 | 3413 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3471 | 3414 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3472 | 3415 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3473 | 3416 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3474 | 3417 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3475 | 3418 | Subabhul      | <i>leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3476 | 3419 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3477 | 3420 | Pimpal        | <i>Ficus religiosa</i>       | 2   | 40 | To be removed | Falling within excavation line |
| 3478 | 3421 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3479 | 3422 | Jambhul       | <i>Syzygium cumini</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 3480 | 3423 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 3481 | 3424 | Charcoal tree | <i>Trema orientalis</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3482 | 3425 | Subabhul      | <i>Leucaena leucocephala</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3483 | 3426 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3484 | 3427 | Subabhul      | <i>Leucaena leucocephala</i> | 2   | 35 | To be removed | Falling within excavation line |
| 3485 | 3428 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 35 | To be removed | Falling within excavation line |
| 3486 | 3429 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3487 | 3430 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3488 | 3431 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3489 | 3432 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3490 | 3433 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3491 | 3434 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3492 | 3435 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3493 | 3436 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3394 | 3437 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3395 | 3438 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3496 | 3439 | Subabhul      | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3497 | 3440 | Charcoal tree | <i>Trema orientalis</i>      | 2   | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                              |     |    |               |                                |
|------|------|----------------|------------------------------|-----|----|---------------|--------------------------------|
| 3498 | 3441 | Bhokar         | <i>Cordia dichotoma</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 3499 | 3442 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3500 | 3443 | Amba (Dead)    | <i>Mangifera indica</i>      | 2   | 20 | To be removed | Falling within excavation line |
| 3501 | 3444 | Subabhul       | <i>Leucaena leucocephala</i> | 8   | 35 | To be removed | Falling within excavation line |
| 3502 | 3445 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3503 | 3446 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 30 | To be removed | Falling within excavation line |
| 3504 | 3447 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3505 | 3448 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3506 | 3449 | Kharoti        | <i>Streblus asper</i>        | 1.5 | 15 | To be removed | Falling within excavation line |
| 3507 | 3450 | Subabhul       | <i>Leucaena leucocephala</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3508 | 3451 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3509 | 3452 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3510 | 3453 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3511 | 3454 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3512 | 3455 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3513 | 3456 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3514 | 3457 | Asana          | <i>Pterocarpus marsupium</i> | 1   | 15 | To be removed | Falling within excavation line |
| 3515 | 3458 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3516 | 3459 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3517 | 3460 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3518 | 3461 | Charcoal tree  | <i>Trema orientalis</i>      | 2   | 20 | To be removed | Falling within excavation line |
| 3519 | 3462 | Subabhul       | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3520 | 3463 | Subabhul       | <i>Leucaena leucocephala</i> | 1   | 15 | To be removed | Falling within excavation line |
| 3521 | 3464 | Shemat         | <i>Lannea coromandelica</i>  | 5   | 20 | To be removed | Falling within excavation line |
| 3522 | 3465 | Vilayti Chinch | <i>Pithecellobium dulce</i>  | 2   | 25 | To be removed | Falling within excavation line |
| 3523 | 3466 | Dhaman         | <i>Grewia tiliaefolia</i>    | 2   | 30 | To be removed | Falling within excavation line |
| 3524 | 3467 | Kaduneem       | <i>Azadirachta indica</i>    | 2   | 30 | To be removed | Falling within excavation line |
| 3525 | 3468 | Toran          | <i>Ziziphus rugosa</i>       | 1.5 | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                                 |     |    |               |                                |
|------|------|----------------|---------------------------------|-----|----|---------------|--------------------------------|
| 3526 | 3469 | Amba           | <i>Mangifera indica</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 3527 | 3470 | Amba           | <i>Mangifera indica</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 3528 | 3471 | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 1.5 | 25 | To be removed | Falling within excavation line |
| 3529 | 3472 | Naral          | <i>Cocus nucifera</i>           | 2   | 50 | To be removed | Falling within excavation line |
| 3530 | 3473 | Pimpal         | <i>Ficus religiosa</i>          | 10  | 45 | To be removed | Falling within excavation line |
| 3531 | 3474 | Not ID         | Not ID                          | 2   | 20 | To be removed | Falling within excavation line |
| 3532 | 3475 | Naral          | <i>Cocus nucifera</i>           | 2   | 45 | To be removed | Falling within excavation line |
| 3533 | 3476 | Phanas         | <i>Artocarpus heteroohyllus</i> | 2   | 30 | To be removed | Falling within excavation line |
| 3534 | 3477 | Naral          | <i>Cocus nucifera</i>           | 2   | 45 | To be removed | Falling within excavation line |
| 3535 | 3478 | Moha           | <i>Madhuca indica</i>           | 1.5 | 25 | To be removed | Falling within excavation line |
| 3536 | 3479 | Amba           | <i>Mangifera indica</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 3537 | 3480 | Naral          | <i>Cocus nucifera</i>           | 2   | 45 | To be removed | Falling within excavation line |
| 3538 | 3481 | Amba           | <i>Mangifera indica</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 3539 | 3482 | Desi Badam     | <i>Terminalia catappa</i>       | 2   | 30 | To be removed | Falling within excavation line |
| 3540 | 3483 | Amba           | <i>Mangifera indica</i>         | 1.5 | 20 | To be removed | Falling within excavation line |
| 3541 | 3484 | Amba           | <i>Mangifera indica</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 3542 | 3485 | Desi Badam     | <i>Terminalia catappa</i>       | 5   | 35 | To be removed | Falling within excavation line |
| 3543 | 3486 | Kala umber     | <i>Ficus hispida</i>            | 1.5 | 15 | To be removed | Falling within excavation line |
| 3544 | 3487 | Desi Badam     | <i>Terminalia catappa</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3545 | 3488 | Naral          | <i>Cocus nucifera</i>           | 2   | 45 | To be removed | Falling within excavation line |
| 3546 | 3489 | Amba           | <i>Mangifera indica</i>         | 10  | 45 | To be removed | Falling within excavation line |
| 3547 | 3490 | Asupalav       | <i>Polyalthia longifolia</i>    | 2   | 35 | To be removed | Falling within excavation line |
| 3548 | 3491 | Naral          | <i>Cocus nucifera</i>           | 2   | 45 | To be removed | Falling within excavation line |
| 3549 | 3492 | Jambhul        | <i>Syzygium cumini</i>          | 1.5 | 30 | To be removed | Falling within excavation line |
| 3550 | 3493 | Naral          | <i>Cocus nucifera</i>           | 2   | 45 | To be removed | Falling within excavation line |
| 3551 | 3494 | Amba           | <i>Mangifera indica</i>         | 8   | 35 | To be removed | Falling within excavation line |
| 3552 | 3495 | Kate savar     | <i>Bombax ceiba</i>             | 2   | 25 | To be removed | Falling within excavation line |
| 3553 | 3496 | Dhaman         | <i>Grewia tiliaefolia</i>       | 2   | 30 | To be removed | Falling within excavation line |



## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                                 |     |    |               |                                |
|------|------|----------------|---------------------------------|-----|----|---------------|--------------------------------|
| 3554 | 3497 | Desi Badam     | <i>Terminalia catappa</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 3555 | 3498 | Amba           | <i>Mangifera indica</i>         | 2   | 45 | To be removed | Falling within excavation line |
| 3556 | 3499 | Naral          | <i>Cocus nucifera</i>           | 2   | 45 | To be removed | Falling within excavation line |
| 3557 | 3500 | Chinch         | <i>Tamarindus indica</i>        | 5   | 35 | To be removed | Falling within excavation line |
| 3558 | 3501 | Phanas         | <i>Artocarpus heteroohyllus</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3559 | 3502 | Bhend          | <i>Thespesia populnea</i>       | 1.5 | 30 | To be removed | Falling within excavation line |
| 3560 | 3503 | Phanas         | <i>Artocarpus heteroohyllus</i> | 2   | 35 | To be removed | Falling within excavation line |
| 3561 | 3504 | Pimpal         | <i>Ficus religiosa</i>          | 10  | 45 | To be removed | Falling within excavation line |
| 3562 | 3505 | Chafa          | <i>Plumeria alba</i>            | 2   | 30 | To be removed | Falling within excavation line |
| 3563 | 3506 | Amba           | <i>Mangifera indica</i>         | 5   | 45 | To be removed | Falling within excavation line |
| 3564 | 3507 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 30 | To be removed | Falling within excavation line |
| 3565 | 3508 | Chafa          | <i>Plumeria alba</i>            | 1.5 | 20 | To be removed | Falling within excavation line |
| 3566 | 3509 | Chinch         | <i>Tamarindus indica</i>        | 1.5 | 20 | To be removed | Falling within excavation line |
| 3567 | 3510 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 3568 | 3511 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 3569 | 3512 | Subabhul       | <i>Leucaena leucocephala</i>    | 2   | 15 | To be removed | Falling within excavation line |
| 3570 | 3513 | Vavla          | <i>Holoptela integrifolia</i>   | 5   | 35 | To be removed | Falling within excavation line |
| 3571 | 3514 | Desi Badam     | <i>Terminalia catappa</i>       | 2   | 45 | To be removed | Falling within excavation line |
| 3572 | 3515 | Bhend          | <i>Thespesia populnea</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 3573 | 3516 | Bhend          | <i>Thespesia populnea</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 3574 | 3517 | Bhend          | <i>Thespesia populnea</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 3575 | 3518 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3576 | 3519 | Subabhul       | <i>Leucaena leucocephala</i>    | 1   | 15 | To be removed | Falling within excavation line |
| 3577 | 3520 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3578 | 3521 | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 1.5 | 20 | To be removed | Falling within excavation line |
| 3579 | 3522 | Vavla          | <i>Holoptela integrifolia</i>   | 1   | 15 | To be removed | Falling within excavation line |
| 3580 | 3523 | Charcoal tree  | <i>Trema orientalis</i>         | 1   | 15 | To be removed | Falling within excavation line |
| 3581 | 3524 | Shewga         | <i>Moringa oleifera</i>         | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                                 |     |    |               |                                |
|------|------|------------|---------------------------------|-----|----|---------------|--------------------------------|
| 3582 | 3525 | Peru       | <i>Psidium guajava</i>          | 1.5 | 20 | To be removed | Falling within excavation line |
| 3583 | 3526 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3584 | 3527 | Subabhul   | <i>Leucaena leucocephala</i>    | 5   | 50 | To be removed | Falling within excavation line |
| 3585 | 3528 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 45 | To be removed | Falling within excavation line |
| 3586 | 3529 | Subabhul   | <i>Leucaena leucocephala</i>    | 2   | 30 | To be removed | Falling within excavation line |
| 3587 | 3530 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 3588 | 3531 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3589 | 3532 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3590 | 3533 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3591 | 3534 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 3592 | 3535 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 35 | To be removed | Falling within excavation line |
| 3593 | 3536 | Phanas     | <i>Artocarpus heteroohyllus</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3594 | 3537 | Peru       | <i>Psidium guajava</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 3595 | 3538 | Subabhul   | <i>Leucaena leucocephala</i>    | 2   | 30 | To be removed | Falling within excavation line |
| 3596 | 3539 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 45 | To be removed | Falling within excavation line |
| 3597 | 3540 | Peru       | <i>Psidium guajava</i>          | 1   | 15 | To be removed | Falling within excavation line |
| 3598 | 3541 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 30 | To be removed | Falling within excavation line |
| 3599 | 3542 | Jamb tree  | <i>Syzygium samarangens</i>     | 1.5 | 30 | To be removed | Falling within excavation line |
| 3600 | 3543 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 30 | To be removed | Falling within excavation line |
| 3601 | 3544 | Subabhul   | <i>Leucaena leucocephala</i>    | 5   | 20 | To be removed | Falling within excavation line |
| 3602 | 3545 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3603 | 3546 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3604 | 3547 | Desi Badam | <i>Terminalia catappa</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 3605 | 3548 | Tad (Dead) | <i>Borassus flabellifer</i>     | 2   | 35 | To be removed | Falling within excavation line |
| 3606 | 3549 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3607 | 3550 | Desi Badam | <i>Terminalia catappa</i>       | 1.5 | 25 | To be removed | Falling within excavation line |
| 3608 | 3551 | Subabhul   | <i>Leucaena leucocephala</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3609 | 3552 | Desi Badam | <i>Terminalia catappa</i>       | 2   | 35 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                                |     |    |               |                                |
|------|------|----------------|--------------------------------|-----|----|---------------|--------------------------------|
| 3610 | 3553 | Subabhul       | <i>Leucaena leucocephala</i>   | 1   | 30 | To be removed | Falling within excavation line |
| 3611 | 3554 | Subabhul       | <i>Leucaena leucocephala</i>   | 2   | 15 | To be removed | Falling within excavation line |
| 3612 | 3555 | Kala umber     | <i>Ficus hispida</i>           | 1.5 | 15 | To be removed | Falling within excavation line |
| 3613 | 3556 | Desi Badam     | <i>Terminalia catappa</i>      | 1.5 | 25 | To be removed | Falling within excavation line |
| 3614 | 3557 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 30 | To be removed | Falling within excavation line |
| 3615 | 3558 | Desi Badam     | <i>Terminalia catappa</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3616 | 3559 | Desi Badam     | <i>Terminalia catappa</i>      | 5   | 45 | To be removed | Falling within excavation line |
| 3617 | 3560 | Desi Badam     | <i>Terminalia catappa</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3618 | 3561 | Naral          | <i>Cocus nucifera</i>          | 1.5 | 35 | To be removed | Falling within excavation line |
| 3619 | 3562 | Phanas         | <i>Artocarpus heterohyllus</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3620 | 3563 | Amba           | <i>Mangifera indica</i>        | 5   | 35 | To be removed | Falling within excavation line |
| 3621 | 3564 | Kadi Patta     | <i>Murraya koenigii</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 3622 | 3565 | Chikoo         | <i>Manilkara zapota</i>        | 2   | 30 | To be removed | Falling within excavation line |
| 3623 | 3566 | Amba           | <i>Mangifera indica</i>        | 5   | 35 | To be removed | Falling within excavation line |
| 3624 | 3567 | Jamb tree      | <i>Syzygium samarangens</i>    | 2   | 20 | To be removed | Falling within excavation line |
| 3625 | 3568 | Subabhul       | <i>Leucaena leucocephala</i>   | 2   | 15 | To be removed | Falling within excavation line |
| 3626 | 3569 | Charcoal tree  | <i>Trema orientalis</i>        | 1.5 | 25 | To be removed | Falling within excavation line |
| 3627 | 3570 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 3628 | 3571 | Dhaman         | <i>Grewia tiliaefolia</i>      | 1.5 | 15 | To be removed | Falling within excavation line |
| 3629 | 3572 | Vilayti Chinch | <i>Pithecellobium dulce</i>    | 5   | 20 | To be removed | Falling within excavation line |
| 3630 | 3573 | Desi Badam     | <i>Terminalia catappa</i>      | 5   | 45 | To be removed | Falling within excavation line |
| 3631 | 3574 | Khajur         | <i>Phoenix sylvestris</i>      | 2   | 45 | To be removed | Falling within excavation line |
| 3632 | 3575 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 15 | To be removed | Falling within excavation line |
| 3633 | 3576 | Tuti           | <i>Morus alba</i>              | 1.5 | 20 | To be removed | Falling within excavation line |
| 3634 | 3577 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 3635 | 3578 | Subabhul       | <i>Leucaena leucocephala</i>   | 1.5 | 20 | To be removed | Falling within excavation line |
| 3636 | 3579 | Tuti           | <i>Morus alba</i>              | 1.5 | 15 | To be removed | Falling within excavation line |
| 3637 | 3580 | Tuti           | <i>Morus alba</i>              | 1.5 | 15 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |            |                              |     |    |               |                                |
|------|------|------------|------------------------------|-----|----|---------------|--------------------------------|
| 3638 | 3581 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 20 | To be removed | Falling within excavation line |
| 3639 | 3582 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3640 | 3583 | Umber      | <i>Ficus glomerata</i>       | 2   | 35 | To be removed | Falling within excavation line |
| 3641 | 3584 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 30 | To be removed | Falling within excavation line |
| 3642 | 3585 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3643 | 3586 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3644 | 3587 | Dhaman     | <i>Grewia tiliaefolia</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3645 | 3588 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3646 | 3589 | Umber      | <i>Ficus glomerata</i>       | 2   | 45 | To be removed | Falling within excavation line |
| 3647 | 3590 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 15 | To be removed | Falling within excavation line |
| 3648 | 3591 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 25 | To be removed | Falling within excavation line |
| 3649 | 3592 | Subabhul   | <i>Leucaena leucocephala</i> | 2   | 15 | To be removed | Falling within excavation line |
| 3650 | 3593 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3651 | 3594 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3652 | 3595 | Kala umber | <i>Ficus hispida</i>         | 1   | 15 | To be removed | Falling within excavation line |
| 3653 | 3596 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |
| 3654 | 3597 | Naral      | <i>Cocos nucifera</i>        | 2   | 10 | To be removed | Falling within excavation line |
| 3655 | 3598 | Peru       | <i>Psidium guajava</i>       | 1.5 | 20 | To be removed | Falling within excavation line |
| 3656 | 3599 | Jambhul    | <i>Syzygium cumini</i>       | 2   | 35 | To be removed | Falling within excavation line |
| 3657 | 3600 | Amba       | <i>Mangifera indica</i>      | 1.5 | 20 | To be removed | Falling within excavation line |
| 3658 | 3601 | Amba       | <i>Mangifera indica</i>      | 2   | 25 | To be removed | Falling within excavation line |
| 3659 | 3602 | Peru       | <i>Psidium guajava</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3660 | 3603 | Peru       | <i>Psidium guajava</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3661 | 3604 | Kaduneem   | <i>Azadirachta indica</i>    | 2   | 30 | To be removed | Falling within excavation line |
| 3662 | 3605 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3663 | 3606 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3664 | 3607 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 25 | To be removed | Falling within excavation line |
| 3665 | 3608 | Subabhul   | <i>Leucaena leucocephala</i> | 1.5 | 20 | To be removed | Falling within excavation line |

## PART-II: TREE INVENTORY DETAILS

## GENERAL CONSULTANT FOR MUMBAI METRO LINE 3

|      |      |                |                                 |     |    |               |                                |
|------|------|----------------|---------------------------------|-----|----|---------------|--------------------------------|
| 3666 | 3609 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 30 | To be removed | Falling within excavation line |
| 3667 | 3610 | Kahandol       | <i>Sterculia urens</i>          | 2   | 30 | To be removed | Falling within excavation line |
| 3668 | 3611 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 30 | To be removed | Falling within excavation line |
| 3669 | 3612 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3670 | 3613 | Subabhul       | <i>Leucaena leucocephala</i>    | 2   | 15 | To be removed | Falling within excavation line |
| 3671 | 3614 | Kala umber     | <i>Ficus hispida</i>            | 1.5 | 20 | To be removed | Falling within excavation line |
| 3672 | 3615 | Dhaman         | <i>Grewia tiliaefolia</i>       | 1.5 | 15 | To be removed | Falling within excavation line |
| 3673 | 3616 | Kala umber     | <i>Ficus hispida</i>            | 1.5 | 15 | To be removed | Falling within excavation line |
| 3674 | 3617 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 25 | To be removed | Falling within excavation line |
| 3675 | 3618 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3676 | 3619 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 20 | To be removed | Falling within excavation line |
| 3677 | 3620 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 45 | To be removed | Falling within excavation line |
| 3678 | 3621 | Pimpal         | <i>Ficus religiosa</i>          | 5   | 15 | To be removed | Falling within excavation line |
| 3679 | 3622 | Tuti           | <i>Morus alba</i>               | 1.5 | 15 | To be removed | Falling within excavation line |
| 3680 | 3623 | Phanas         | <i>Artocarpus heterophyllus</i> | 1   | 25 | To be removed | Falling within excavation line |
| 3681 | 3624 | Charcoal tree  | <i>Trema orientalis</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 3682 | 3625 | Umbur          | <i>Ficus glomerata</i>          | 1.5 | 15 | To be removed | Falling within excavation line |
| 3683 | 3626 | Kala umber     | <i>Ficus hispida</i>            | 1.5 | 15 | To be removed | Falling within excavation line |
| 3684 | 3627 | Kala umber     | <i>Ficus hispida</i>            | 1.5 | 15 | To be removed | Falling within excavation line |
| 3685 | 3628 | Kala umber     | <i>Ficus hispida</i>            | 1.5 | 15 | To be removed | Falling within excavation line |
| 3686 | 3629 | Shewga         | <i>Moringa oleifera</i>         | 1.5 | 15 | To be removed | Falling within excavation line |
| 3687 | 3630 | Subabhul       | <i>Leucaena leucocephala</i>    | 1.5 | 15 | To be removed | Falling within excavation line |
| 3688 | 3631 | Subabhul       | <i>Leucaena leucocephala</i>    | 5   | 35 | To be removed | Falling within excavation line |
| 3689 | 3632 | Khajur         | <i>Phoenix sylvestris</i>       | 2   | 20 | To be removed | Falling within excavation line |
| 3690 | 3633 | Vilayti Chinch | <i>Pithecellobium dulce</i>     | 1.5 | 15 | To be removed | Falling within excavation line |
| 3691 | 3634 | Bartondi       | <i>Morinda pubescens</i>        | 5   | 25 | To be removed | Falling within excavation line |

**PART-II: TREE INVENTORY DETAILS**

**GENERAL CONSULTANT FOR MUMBAI METRO LINE 3**

|                      |             |
|----------------------|-------------|
| Trees to be Retained | 1045        |
| Trees to be removed  | 2646        |
| <b>Total Trees</b>   | <b>3691</b> |